

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1961	2	42,620
Campus Total			42,620

Category: Exterior **Building: Main** Recommend Replacement Comments Item - Type Location Quantity **UOM** Rank Group Entrance Entrance Control - Audio and Video #1 - Main - W EΑ 7 10+ years 1 Exterior Doors - Store Front #1 - Main - W 3 EΑ 7 10+ years LF Exterior Stairs - Concrete #1 - Main - W 20 5 6-10 years 3 FΑ Exterior Doors - Store Front 6-10 years #2 - N 6 20 LF 7 Exterior Stairs - Concrete #2 - N 10+ years Exterior Doors - Exterior Steel Door #3 - NF 1 EΑ 6 6-10 years Exterior Doors - Transom Lite #3 - NE 7 1 EΑ 10+ years New 1 F Exterior Stairs - Concrete #3 - NE 4 5 6-10 years Concrete is not broken. It is spalled underside Exterior Doors - Exterior Steel Door #4 - SE 1 FΑ 6 6-10 years #4 - SE 7 LF 2-5 years Exterior Stairs - Concrete 5 #5 - SE Exterior Doors - Exterior Steel Door 1 FΑ 5 1-2 years Damaged frame #5 - SE 6-10 years Exterior Doors - Transom Lite FΑ 6 1 7 Exterior Doors - Store Front #6 - S 3 FΑ 10+ years LF Exterior Stairs - Concrete #6 - S 20 5 2-5 years Cracks in the concrete Exterior Stairs - Stone 10 1 F 5 2-5 years #6 - S Foundation Foundation - Concrete **Entire Building** 745 LF 7 10+ years LF Foundation - Concrete **Entire Building** 5 10+ years SF Superstructure - Concrete **Entire Building** 38,705 10+ years _Liahtina

Campus Name: Brownell Page: 1 of 20 Assessment Date: 03/09/2022



E	Item - Type Exterior Lighting - Parapet or Roof Mounted	Location					
E E		Lagation				Recommend	
E	Exterior Lighting Daranet or Doof Mounted	Location	Quantity	UOM	Rank	Replacement	Comments
		Entire Building	11	EΑ	6	6-10 years	
D (O)	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	6-10 years	
Roof Syste	em						
(Coping - Stone	Low E roof	46	LF	6	6-10 years	
Γ	Downspouts - Interior Downspouts	Low E roof	13	LF	6	6-10 years	
F	Parapet - 16" - 30" Height	Low E roof	46	LF	5	10+ years	
	Roof - Modified Bitumen	Low E roof	561	SF	5	2-5 years	
ſ	Roof Structure - Concrete	Low E roof	561	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	26	LF	5	10+ years	
(Coping - Stone	Main Roof	744	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	104	LF	6	2-5 years	
	Parapet - 16" - 30" Height	Main Roof	516	LF	4	6-10 years	Spalled, broken, loose bricks, open
	Roof - Modified Bitumen	Main Roof	21,168	SF	3	2-5 years	joints, deteriorated mortar at entire exterior or parapet wal perimeter Soft spots, worn out roofing
	Noon Woulled Bramen	Wall Roof	21,100	O.	Ū	2 o youro	membrane
F	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
F	Roof Structure - Concrete	Main Roof	21,168	SF	7	10+ years	
Walls							
(Canopy - Concrete/ Stucco	Entire Building	234	SF	6	6-10 years	Peeling paint only
F	Exterior Walls - Brick	Entire Building	15,876	SF	6	6-10 years	3 .
	Exterior Walls - Brick	Entire Building	2,500	SF	4	1-2 years	Open joints, deteriorated mortar, damaged and loose brick above lintels& exterior of parapet walls. Also, Open joints in general throughout walls
	Exterior Walls - Stone-Cast	Entire Building	520	SF	6	10+ years	
F	Exterior Walls - Stone-Cast	Entire Building	200	SF	5	10+ years	
Windows							
(Clerestory - Glass Double-Pane	Entire Building	165	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	5,157	SF	6	10+ years	
	Lintels - Steel	Entire Building	741	LF	6	10+ years	
	Lintels - Stone	Entire Building	38	LF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	5,157	SF	6	10+ years	

Campus Name: Brownell Page : 2 of 20 Assessment Date: 03/09/2022



Catego	ry : Electrical		В	uilding	: Main		
	Name Tame	1 ()	0	11014	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Emerge</u> i	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,402	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,424	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,210	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	2	0-1 year	Fixtures damage
	Exit Signs - Corridors and Stairs	Entire Building	9	ΕA	2	0-1 year	No battery backup power
	Exit Signs - Lunchroom	Entire Building	2	ĒĀ	2	0-1 year	New item added per current observation No battery backup power
	Exit Signs - Lunchroom	Entire Building	4	EA	2	0-1 year	No battery backup power
	Security System - CCTV	Entire Building	42,620	SF	5	6-10 years	Al system installed
	Security System - Intrusion Detection	J	42,620	SF	5	6-10 years	Covered only few areas
	Security System - Intrusion Detection	Entire Building	42,020	SF	3	6-10 years	Covered only lew areas
Main Se		FL (LD					
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	42,620	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Boiler Room	1	EA	3	2-5 years	Older system

Campus Name: Brownell Page : 3 of 20 Assessment Date: 03/09/2022



Catego	ry : Fire Protection			Buildi	ng : Main		
0	Name Trans	Lasatian	•		M D :	Recommend	2
Group	Item - Type	Location	Quantity	OO.		Replacement	Comments
	Fire Alarm System	Boiler Room Boiler Room	42,620			0-1 year	No strobe light and older system
	Fire Alarm_System	Doller Room	42,620	ان ر	F 4	2-5 years	Older system
Catego	ry : Mechanical			Buildi	ng : Main		
Group	Itam - Typo	Location	Quantity	UO	M Rank	Recommend	Comments
Group	Item - Type Iling Systems	Location	Quantity	00	IVI Kalik	Replacement	Comments
All Hall	Air Handling Unit- Package Single Zone-	Entire Building	,	2 E/	A 5	6-10 years	Control needs to be adjusted
	Indoor- Steam Coils - 4000-8000 cfm	· ·				•	,
	Air Intake	Entire Building	2	2 E/		6-10 years	Shaft needs some seals
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Entire Building	2	2 E/	A 5	6-10 years	Belts needs some repair
Boiler Sy	ystems						
·	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	2 E/	A 6	10+ years	
	Chemical Feed System	Boiler Room		E/	A 6	10+ years	
	Chemical Feeder	Boiler Room	•	E/	٩ 6	10+ years	
	Combustion Dampers	Boiler Room	2	2 E/	٩ 6	10+ years	
	Condensate Pump	Boiler Room	2	2 E/	Α 5	10+ years	Need some repair
	Feed Water Pumps and Tank	Boiler Room	•			6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	2 E/	٩ 6	10+ years	
	Piping - Condensate Pipe- Steel	Boiler Room	300) LF	- 6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	300) LF	- 6	10+ years	
	Steam Traps	Boiler Room	12	2 E/	A 5	6-10 years	Need some cleaning
	Vacuum Pump	Boiler Room	2			6-10 years	Need some repair
Gas Boo	oster						
	Gas Booster	Boiler Room	;	3 E/	A 6	10+ years	Only one booster pump working Perbuilding engineer
Heating	Devices Fin Tube - Steam	Entire Building	80) LF	= 6	6-10 years	
	Wall Heater - Electric	Entire Building Entire Building	0(6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building Entire Building	12			6-10 years	Control needs to be adjusted
	Capitiet Heaters - With Steam Con	Little building	12	. []	٦ ٥	0-10 years	Control fieeds to be adjusted
Tempera	ature Control						
	Electric Thermostat	Entire Building	(10+ years	
	Hybrid Pneumatic/DDC System	Entire Building	42,620) SI	F 3	0-1 year	Pneumatic system is not working Ai compressor not working per building engineer
	Thermostats - Pneumatic	Entire Building	24	l E	A 6	6-10 years	onginoor
Campus	Name: Brownell		Page : 4 of 20				Assessment Date: 03/09/20

Campus Name: Brownell Page: 4 of 20 Assessment Date: 03/09/2022



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jnit Ver	itilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	24	EA	5	6-10 years	Control needs to be adjusted
entilati	on						
	Exhaust Fans- Indoor - Less than 500 CFM	1st floor and Roof	1	EA	5	6-10 years	Need some repair
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	1	EA	7	10+ years	New item added per current observation Installed new in 2020
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	1	EA	4	2-5 years	Rusty and vibrating
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st floor and Roof	1	EA	4	2-5 years	Quantity per current observation Rusty and vibrating
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st floor and Roof	1	EA	3	0-1 year	Remove from the curb
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st floor and Roof	1	EA	3	0-1 year	Not working per building engineer
Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	42,620	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	42,620	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,620	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,620	SF	6	10+ years	
					c	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,620	SF	6	101 youro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	42,620 42,620	SF SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	· ·		SF SF		•	
	Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	42,620	SF	6	10+ years	



atego	ategory : Room			uilding	: Main		
	Itam Tuna	Location	Oventity	HOM	Donk	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices	A + 0				0.40	
	AC Unit	1st flr main office suite	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr main office suite	613	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr main office suite	2	EA	6	10+ years	
	Floor - Carpet	1st flr main office suite	298	SF	6	6-10 years	
	Floor - Tile/Sheet	1st flr main office suite	315	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr main office suite	10	EA	7	10+ years	
	Power Distribution	1st flr main office suite	13	EA	6	6-10 years	
	Storage/ Closet	1st flr main office suite	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st flr main office suite	1,796	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	105	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office	2	EA	7	10+ years	
	Power Distribution	Gym Office	2	EA	6	10+ years	
	Walls - Concrete Block	Gym Office	152	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Principal's Office - 1 FL	155	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Principal's Office - 1 FL	20	SF	6	1-2 years	Peeling paint
	Doors - Wood Doors inclu hw	Principal's Office - 1 FL	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office - 1 FL	175	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office - 1 FL	2	EA	7	10+ years	
	Power Distribution	Principal's Office - 1 FL	4	EA	6	6-10 years	
	Storage/ Closet	Principal's Office - 1 FL	10	SF	7	10+ years	
	Walls - Concrete Block	Principal's Office - 1 FL	280	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office - 1 FL	22	SF	7	10+ years	
	AC Unit	Room 105, Adjustment Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 105, Adjustment Room	360	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 105, Adjustment Room	10	SF	4	0-1 year	Water Stain ceiling. Peeling pai
	Doors - Wood Doors inclu hw	Room 105, Adjustment Room	1	EA	6	10+ years	· · · · · · · · · · · · · · · · · · ·
	Floor - Tile	Room 105, Adjustment Room	367	SF	6	10+ years	
	Floor - Tile	Room 105, Adjustment Room	3	SF	4	0-1 year	Cracked 9x9 tile
	Lighting - Pendent/Surface	Room 105, Adjustment Room	6	EA	7	10+ years	
	Power Distribution	Room 105, Adjustment Room	6	EA	6	10+ years	
	Walls - Concrete Block	Room 105, Adjustment Room	784	SF	6	10+ years	
	Work SInk	Room 105, Adjustment Room	1	ĒΑ	7	10+ years	
	AC Unit	Teacher's Lounge 2 FL	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Teacher's Lounge 2 FL	323	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge 2 FL	1	ĒΑ	6	10+ years	
	Floor - Tile	Teacher's Lounge 2 FL	323	SF	6	10+ years	
	Lighting - Pendent/Surface	Teacher's Lounge 2 FL	6	EA	7	10+ years	
	Power Distribution	Teacher's Lounge 2 FL	8	EΑ	6	6-10 years	
	Walls - Concrete Block	Teacher's Lounge 2 FL	734	SF	7	10+ years	

Gymnasia

Campus Name: Brownell Page : 6 of 20 Assessment Date: 03/09/2022



Catego	ry : Room		R	uilding	· Main	07-	41 3 Michigan Avenue, Chicago, iL 60637
Calego	i y . 1300iii		В	unung	. iviaiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о пр	Ceiling - Plaster/Drywall	1st Floor	3,424	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	3,424	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	12	EA	7	10+ years	
	Sound System	1st Floor	1	ΕA	7	10+ years	
	Stage	1st Floor	710	SF	6	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	95	SF	7	10+ years	Updated to match current
	Grerage, Greece	10111001		O.	•	io. youro	observations
	Walls - Concrete Block	1st Floor	2,295	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,295	SF	6	10+ years	
	Walle Gracial Glazea File	16(1.166)	2,200	O.	Ü	.o. youro	
_Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	657	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	657	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years	
	Serving Line	1st Floor	18	LF	7	10+ years	
	Storage/ Closet	1st Floor	38	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	317	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	739	SF	6	10+ years	
MDF_ID	E						
<u> </u>	Doors - Wood Doors inclu hw	2nd flr inside #208	1	EA	6	10+ years	
	Finishes	2nd flr inside #208	147	SF	7	10+ years	
	Other Cooling Unit	2nd flr inside #208	1	EA	7	6-10 years	New Cooling unit
_Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	942	SF	7	10+ years	
	Janitor's Closet	1st Floor	43	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	135	SF	7	10+ years	
	Storage Room	1st Floor	58	SF	7	10+ years	
	Vaults	1st Floor	82	SF	7	10+ years	
	Janitor's Closet	2nd Floor	43	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	195	SF	7	10+ years	
	Storage Room	2nd Floor	58	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	42,300	SF	7	10+ years	
_Restroor	m						
	Accessories	1st Floor	339	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	324	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	5	6-10 years	Repaired
	, , , ,			-	-	,	•

Campus Name: Brownell Page: 7 of 20 Assessment Date: 03/09/2022



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	339	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	5	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	188	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	525	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	6	10+ years	
	Accessories	1st Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	266	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	266	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	6	10+ years	
	Partitions	1st Floor	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	196	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	458	SF	6	10+ years	
	Water Closet	1st Floor	7	EA	6	10+ years	
	Accessories	1st flr inside #108 library	26	SF	7	6-10 years	Updated to match current observations
	Ceiling - Plaster/Drywall	1st flr inside #108 library	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside #108 library	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st flr inside #108 library	26	SF	5	1-2 years	Some water stains
	Lavatory	1st flr inside #108 library	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st flr inside #108 library	1	EA	6	1-2 years	Extremely dim
	Walls - Concrete Block	1st flr inside #108 library	165	SF	6	10+ years	•
	Water Closet	1st flr inside #108 library	1	EA	6	10+ years	
	Accessories	1st flr inside principal's office	41	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside principal's office	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st flr inside principal's office	41	SF	7	10+ years	
	Lavatory	1st flr inside principal's office	1	ĒΑ	6	10+ years	
	Lighting - Lay-in	1st flr inside principal's office	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st flr inside principal's office	1	EA	7	10+ years	
	Partitions	1st flr inside principal's office	1	EA	7	10+ years	
	Walls - Concrete Block	1st flr inside principal's office	234	SF	7	10+ years	
	Water Closet	1st flr inside principal's office	1	ĒΑ	7	10+ years	
	Accessories	2nd Floor	339	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	339	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Water damage/peeling paint
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
			•		ŭ	,	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	2nd Floor	339	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	188	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	525	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	236	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	6	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	4	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	266	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	2	EΑ	7	10+ years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	176	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	20	SF	5	0-1 year	Crack in wall
	Walls - Structural Glazed Tile	2nd Floor	458	SF	7	10+ years	Crack iii waii
	Water Closet	2nd Floor	7	EA	7	10+ years	
	Accessories	In Kitchen Area	33	SF	7	•	
	Ceiling - Plaster/Drywall	In Kitchen Area	33	SF SF	6	6-10 years	
	Doors - Wood Doors inclu hw			EA	6	10+ years	
		In Kitchen Area	1		-	10+ years	
	Floor - Tile	In Kitchen Area	33	SF	6	2-5 years	
	Lavatory	In Kitchen Area	1	EΑ	6	10+ years	
	Lighting - Lay-in	In Kitchen Area	1	EΑ	6	10+ years	
	Lighting - Wall Mounted	In Kitchen Area	1	EA	6	10+ years	
	Walls - Masonry	In Kitchen Area	170	SF	6	10+ years	
	Water Closet	In Kitchen Area	1	EA	6	10+ years	
	Accessories	In Room 110	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 110	29	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 110	1	EA	6	10+ years	
	Floor - Tile	In Room 110	27	SF	6	10+ years	
	Floor - Tile	In Room 110	2	SF	5	1-2 years	Chipping and loose tile
	Lavatory	In Room 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 110		EA	6	1-2 years	Very dim light
	Walls - Concrete Block	In Room 110	124	SF	6	10+ years	
	Water Closet	In Room 110	1	EA	6	10+ years	
	Accessories	Men's Room, 2nd Floor	66	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Room, 2nd Floor	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men's Room, 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Men's Room, 2nd Floor	66	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		TO Michigan AVENUE, Officago, IE 00007
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Men's Room, 2nd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	Men's Room, 2nd Floor	1	EA	7	10+ years	
	Partitions	Men's Room, 2nd Floor	1	EA	7	10+ years	
	Urinals	Men's Room, 2nd Floor	1	EA	6	10+ years	
	Walls - Concrete Block	Men's Room, 2nd Floor	274	SF	7	10+ years	
	Water Closet	Men's Room, 2nd Floor	1	ĒΑ	7	10+ years	
	Accessories	Women's Room, 2nd Floor	91	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Room, 2nd Floor	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's Room, 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Women's Room, 2nd Floor	91	SF	6	10+ years	
	Lavatory	Women's Room, 2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's Room, 2nd Floor	1	EA	4	0-1 year	Missing cover
	Lighting - Wall Mounted	Women's Room, 2nd Floor	2	EA	4	0-1 year	Light fixture malfunction
	Partitions	Women's Room, 2nd Floor	2	EA	7	10+ years	Light lixture mailunction
	Walls - Concrete Block	Women's Room, 2nd Floor	308	SF	7 7	10+ years 10+ years	
	Water Closet	Women's Room, 2nd Floor	2	EA	7		
	Water Closet	Women's Room, 2nd Floor	2	EA	1	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	787	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	10+ years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	Work Clink	1001	·		•	101 youro	
Classroo	m #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	813	SF	6	10+ years	Updated to match current observations
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Loose cover
	Walls - Concrete Block	1st Floor	943	SF	6	10+ years	
	om #102 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	787	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	1-2 years	Not functioning
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	C
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Cover missing
	Walls - Concrete Block	1st Floor	894	SF	6	10+ years	3
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	813	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF	5	1-2 years	Seal wearing out
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	Ocal wearing out
	Lighting - Pendent/Surface	1st Floor	2	EA	6	1-2 years	Not functioning
	Lighting - Pendent/Surface	1st Floor	2	EA	5	1-2 years	Loose and missing cover
	Walls - Concrete Block	1st Floor	1,160	SF	6	6-10 years	Very strong mold smell in entire room
Classes	one #404 (Demiller Classicans)						
_Classroo	om #104 (Regular Classroom)	4 . =		·		0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	779	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	894	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	787	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Hardware	1st Floor	1	EA	6	0-1 year	Loose hardware
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	8	SF	6	1-2 years	Rust stain
	Floor - Tile	1st Floor	774	SF	6	10+ years	
						,	



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Chipping edges
	Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	1-2 years	Not functioning
	Lighting - Pendent/Surface	1st Floor	2	EΑ	5	1-2 years	Missing cover
	Walls - Concrete Block	1st Floor	894	SF	6	10+ years	9
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroc	om #108 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	85	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,121	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,121	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,411	SF	6	•	
						10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #110 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,080	SF	6	10+ years	Quantity changed
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,080	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	10+ years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	5	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	1st Floor	1,445	SF	6	10+ years	observations
	Work Sink	1st Floor	1,443	EA	7	10+ years	
	WOIR SIIIR	151 11001	1	LA	1	10+ years	
Classroc	om #200 (Regular Classroom)	0.151		-		0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	934	SF	7	10+ years	
Classroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
					•	,	

Campus Name: Brownell Page : 12 of 20 Assessment Date: 03/09/2022



atego	ry : Classroom		В	uilding	: Main					
						Recommend				
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile	2nd Floor	801	SF	6	10+ years				
	Floor - Tile	2nd Floor	12	SF	5	1-2 years	Missing and broken tiles			
	Lighting - Pendent/Surface	2nd Floor	13	EΑ	7	10+ years	ee			
	Lighting - Pendent/Surface	2nd Floor	2	EΑ	6	1-2 years	Not functioning			
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Cover missing			
	Storage/ Closet	2nd Floor 2nd Floor	14	SF	7		Cover missing			
	Storage/ Closet					10+ years				
	Walls - Concrete Block	2nd Floor	1,160	SF	7	10+ years				
assroc	om #202 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	35	LF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile	2nd Floor	782	SF	6	10+ years				
	Floor - Tile			SF	5		Missing tile			
		2nd Floor	5			1-2 years	Missing tile			
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	No. of the control of			
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	1-2 years	Not functioning			
	Lighting - Pendent/Surface	2nd Floor	9	EA	5	1-2 years	Missing covers			
	Marker Board	2nd Floor	8	LF	6	6-10 years				
	Walls - Concrete Block	2nd Floor	934	SF	7	10+ years				
ssroc	m #203 (Play Room)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	24	LF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	813	SF	7	10+ years	Updated to match current			
	Centrig - Flaster/Drywan	2110 1 1001	013	Oi	,		observations			
	Chalk Board	2nd Floor	36	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile	2nd Floor	813	SF	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor	10	ĒΑ	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor	3	EΑ	5	1-2 years	Missing and loose covers			
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	Wildshing and loose covers			
	Walls - Concrete Block	2nd Floor	1,160	SF	7	•				
						10+ years	Tiles encelies			
	Walls - Concrete Block	2nd Floor	10	SF	5	0-1 year	Tiles cracking			
ssroc	m #204 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	35	LF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years				
	Floor - Tile	2nd Floor	787	SF	6	10+ years				
	1 1001 - 1 11 0	Z110 1 1001	101	OF-	O	IUT years				

Campus Name: Brownell Page: 13 of 20 Assessment Date: 03/09/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	1-2 years	Not functioning
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Switch cover loose
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	934	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7		
	Lighting - Pendent/Surface		3	EA		10+ years	Missing sover
		2nd Floor			4	1-2 years	Missing cover
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	934	SF	7	10+ years	
Classroo	om #207 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	808	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	36	LF	4	2-5 years	· ·
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	1-2 years	Cover missing
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Cover loose
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	30.0
	Walls - Concrete Block	2nd Floor	943	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	653	SF	7	10+ years	
	Chalk Board	2nd Floor	34	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	633	SF	6	10+ years	
	Floor - Tile	2nd Floor	20	SF	5	1-2 years	Missing tiles
	Lighting - Pendent/Surface	2nd Floor	10	EA	5 7		wissing tiles
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	2	EA	4	10+ years	Missing cover
				SF		1-2 years	Missing cover
	Walls - Concrete Block	2nd Floor	934		7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	

Campus Name: Brownell Page : 14 of 20 Assessment Date: 03/09/2022



Catego	ry : Classroom		В	Building : Main			
			<u> </u>			Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	#200 /P						
lassro	om #209 (Regular Classroom)	0.15				0.40	
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	801	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	12	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	1-2 years	Not functioning
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	-
	Walls - Concrete Block	2nd Floor	1,174	SF	7	10+ years	Updated to match current
			,			, , , , , ,	observations
lassro	om #210 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	787	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	4	1-2 years	Missing cover
	Marker Board	2nd Floor	8	LF	6	6-10 years	Missing Cover
		2nd Floor 2nd Floor		SF	7	•	
	Walls - Concrete Block		934			10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	om #212 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years	
	Chalk Board	2nd Floor	48	LF	4	2-5 years	Chalkboard still in use
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Chamboard Still III dec
	Floor - Tile	2nd Floor	777	SF	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	10	SF	5		Small cracks forming
						1-2 years	Small cracks forming
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	934	SF	7	10+ years	
lassroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	787	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Doors - Wood Doors Inclu IIW	2110 1 1001	'	LA	U	TOT years	

Campus Name: Brownell Page : 15 of 20 Assessment Date: 03/09/2022



Catego	ry : Classroom	Building : Main							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	2nd Floor	782	SF	6	10+ years			
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Chipping tile		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	2	EA	5	1-2 years	Missing cover		
	Storage/ Closet	2nd Floor	14	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	905	SF	6	10+ years			
Catego	ry : Interior		В	uilding	: Main				
J						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	1st Floor	1,826	SF	7	10+ years			
	Ceiling - Splined	1st Floor	748	SF	7	10+ years			
	Doors - Wood Doors include hw	1st Floor	7	EA	6	10+ years			
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	10+ years			
	Floor - Terrazzo	1st Floor	748	SF	6	10+ years			
	Floor - Tile/Sheet	1st Floor	1,821	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	5	SF	5	1-2 years	Chipping and loose tiles		
	Lighting - Lay-in	1st Floor	8	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	28	EA	6	10+ years			
	Lighting - Wall Mounted	1st Floor	2	EA	5	1-2 years	Cover missing		
	Student Lockers - One Tier	1st Floor	156	EA	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	2,864	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	2,530	SF	7	10+ years			
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	2,530	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	35	EΑ	7	10+ years			
	Student Lockers - One Tier	2nd Floor	199	EΑ	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,222	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	5	SF	6	1-2 years	Cracking		
	Walls - Structural Glazed Tile	2nd Floor	2,453	SF	7	10+ years			
Safety									
,	Camera Viewing Station	Entire building	1	EA	7	6-10 years			
	Security Cameras	Entire building	3	EA	7	6-10 years			
	Security Cameras	Entire building	5	EA	7	6-10 years			
Stairs									
	Ceiling - Plaster/Drywall	Middle of corridor	768	SF	7	10+ years			
	Floor - Terrazzo	Middle of corridor	668	SF	6	10+ years			
	Handrails	Middle of corridor	128	LF	7	10+ years			
	Lighting - Lay-in	Middle of corridor	1	EA	7	10+ years			

Campus Name: Brownell Page : 16 of 20 Assessment Date: 03/09/2022



Catego	ry : Interior	·	В	uilding	: Main	·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Middle of corridor	4	EA	7	10+ years	
	Stairs - Terrazzo	Middle of corridor	60	LF	6	10+ years	
	Walls - Structural Glazed Tile	Middle of corridor	1,950	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North	367	SF	7	10+ years	
	Floor - Terrazzo	North	340	SF	6	10+ years	
	Handrails	North	64	LF	7	10+ years	
	Lighting - Pendent/Surface	North	3	EΑ	7	10+ years	
	Stairs - Terrazzo	North	30	LF	6	10+ years	
	Walls - Concrete Block	North	767	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	767	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	367	SF	7	10+ years	
	Floor - Terrazzo	South	340	SF	6	10+ years	
	Handrails	South	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South	3	EA	7	10+ years	
	Stairs - Terrazzo	South	30	LF	6	10+ years	
	Walls - Concrete Block	South	767	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	767	SF	7	10+ years	



Building · Site

Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic	Surface - Asphalt	North	6,532	SF	5	6-10 years	
_Civil/Drai	nage						
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site Entire Site	2 2	EA EA	7 7	10+ years 10+ years	
Fencing							
·	Fencing - Chain Link Fencing - Chain Link	Entire Site Entire Site	46 1,198	LF LF	6 6	2-5 years 6-10 years	Most of the chain-link is in good shape
	Fencing - Chain Link	Entire Site	100	LF	5	1-2 years	Leaning fence
_Landsca	De .						
,	Landscape - Grass Parkway trees Play Area - Hardscape- Asphalt	Entire Site Entire Site Entire Site	5,445 13 20,012	SF EA SF	6 7 4	6-10 years 10+ years 2-5 years	Alligatored surface, Large cracks and potholes
Parking I	ot						
	Surface - Asphalt Surface - Asphalt Surface - Concrete Trash Enclosure - Chain Links	Parking Lot- East Parking Lot- East Parking Lot- East Parking Lot- East	11,326 4,000 800 20	SF SF SF	6 5 7 5	6-10 years 1-2 years 10+ years 2-5 years	Potholes, Alligatored surface,
Playgrou	nd						
, ,	Equipment - School Age 5-12 Surface - Poured Surface	North North	1 2,298	EA SF	5 6	1-2 years 2-5 years	Wear and tear
_Sidewalk	s						
	Sidewalks - Internal Walks Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site Entire Site	41 20 5,588	LF LF SF	6 4 6	6-10 years 1-2 years 6-10 years	Broken sidewalks at entries
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	5	1-2 years	Cracked concrete sidewalks
Signage	Flori Polo Flori Polo	Fasting City	4			0.5	
	Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Sign	Entire Site Entire Site Entire Site	1 1 3	EA EA EA	6 6 6	2-5 years 10+ years 10+ years	



Charles S Brownell Elementary School

6741 S Michigan AVENUE, Chicago, IL 60637

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Brownell Page: 19 of 20 Assessment Date: 03/09/2022



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intended Osage	Room Location	Number	Number	(31)	Alta	Alea	Stop	Doard
Computer Lab	Regular Classroom	2nd Floor	210	210	787	210	72	Y	Υ
Kindergarten	Regular Classroom	1st Floor	103	103	813	136	37	N	Υ
Library	Kindergarten	1st Floor	108	108	1,121	315	108	Υ	N
Office	Regular Classroom	1st Floor	106	106	787	210	72	N	Υ
Play Room	Regular Classroom	2nd Floor	203	203	813	136	37	N	Υ
Pre School	Kindergarten	1st Floor	110	110	1,080	175	56	N	N
Regular Classroom	Computer Lab	2nd Floor	208	208	653	210	72	Y	N
Regular Classroom	Regular Classroom	1st Floor	100	100	787	210	72	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	787	136	37	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	787	210	72	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	787	210	72	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	787	210	72	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	813	136	37	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	787	210	72	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	787	210	72	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	787	210	72	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	813	136	37	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	787	136	37	N	Υ
Vacant	Regular Classroom	2nd Floor	207	207	787	136	37	N	N
Vacant	Regular Classroom	2nd Floor	212	212	787	210	72	Υ	Υ