

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	2	55,812
Field House	1924	1	2,715
Campus Total			58,527

Catego	ry : Exterior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	pment						
	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	3	EA	7	10+ years	
	Cell Equipment - Generator	Entire Building	1	EA	7	10+ years	
Entrance							
	Entrance Control - Audio and Video	#1 SE	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#1 SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 SE	1	EA	6	10+ years	
	Power Door Operator and Controls	#1 SE	2	EA	7	10+ years	
	Ramps - Concrete	#1 SE	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2 S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 S	3	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#3 SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 SW	7	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#4 NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 NW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#4 NW	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.5 N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#5.5 N	10	LF	5	10+ years	Hairline crack in concrete



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	#6 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 N	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 E	5	LF	7	10+ years	
	Entrance Control - Audio and Video	#8 NE	1	ĒΑ	6	10+ years	
	Exterior Doors - Exterior AMP Door	#8 NE	2	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	#8 NE	1	EA	6	10+ years	
ire Esc	ape						
	Fire Escape	North Façade	90	LF	6	10+ years	
oundat	ion						
	Foundation - Concrete	Entire Building	20	LF	7	10+ years	No settlement or seepage was
							reported or seen at this location. A new ramp has been installed here
	Foundation - Concrete	Entiro Building	640	LF	7	10 L Vooro	new ramp has been installed here
		Entire Building	640	SF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	51,472		6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	4,340	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
Roof Sys							
	Coping - Stone	#1	61	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#1	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#1	61	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#1	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#1	386	SF	7	10+ years	
	Access Ladder - Metal	#2	1	EA	5	2-5 years	Pipe and rebar ladder
	Access Ladder - Wood	#2	1	EA	5	2-5 years	Difficult to climb this ladder
	Coping - Clay Tile	#2	167	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#2	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	#2	167	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#2	3,200	SF	6	10+ years	
	Roof Hatch - Metal	#2	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#2	3,200	SF	7	10+ years	
	Access Ladder - Metal	#3	3,200	EA	5	2-5 years	Obsolete metal ladder uses rebar
	Access Ladder - Wedan Access Ladder - Wood	#3 #3	1	EA	4	1-2 years	Old wood ladder that is not safe to
	Access Laudel - Wood	πJ	1		4	1-2 years	climb
	Chimney - Brick Chimney- Concrete/ Mortar Liner	#3	40	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chimney - Brick Chimney- Concrete/ Mortar Liner	#3	10	LF	5	1-2 years	Cracked brick
	Coping - Clay Tile	#3	366	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#3	84	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	83	LF	5	1-2 years	Deteriorated mortar and open joints
	Parapet - Parapet > 30"	#3	143	LF	6	10+ years	
	Parapet - Parapet > 30"	#3	40	LF	5	1-2 years	Deteriorated mortar and open joints
	Roof - Asphalt Gravel Ballast	#3	6,678	SF	6	10+ years	
	Roof Hatch - Metal	#3	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#3	6,678	SF	7	10+ years	
	Access Ladder - Metal	#4	1	EA	5	2-5 years	Old metal galvanized pipe and rebar ladder
	Access Ladder - Wood	#4	1	EA	4	2-5 years	
	Coping - Clay Tile	#4	5	LF	6	10+ years	
	Coping - Clay Tile	#4	130	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#4	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4	135	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#4	3,608	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#4	10	SF	4	0-1 year	Open seams in the roofing
	Roof Hatch - Metal	#4	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#4	3,618	SF	7	10+ years	
	Coping - Stone	#5	63	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#5	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#5	63	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#5	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#5	386	SF	7	10+ years	
	Coping - Clay Tile	#6	339	LF	6	10+ years	
	Coping - Clay Tile	#6	3	LF	5	1-2 years	Cracked tile, deteriorated sealant at counter flashing
	Downspouts - Exterior Downspouts	#6	52	LF	6	10+ years	<b>U</b>
	Parapet - 16" - 30" Height	#6	10	LF	5	1-2 years	Open joints
	Parapet - Parapet < 16" Height	#6	332	LF	6	10+ years	•
	Roof - Asphalt Gravel Ballast	#6	3,477	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#6	300	SF	4	1-2 years	Large mound of ballast with growing vegetation, areas of asphalt with no ballast
	Roof - Modified Bitumen	#6	200	SF	6	10+ years	Electrical equipment roof
	Roof Structure - Steel with Clay Tile Arch	#6 #6	3,977	SF	7	10+ years	Lieutiluai equipinent 1001
	Noor Structure - Steel with Glay The Alch	π <b>O</b>	3,977	J.	,	TOT YEARS	
Walls	Cornice - Masonry Projecting Limestone	Entire Building	252	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,166	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	50	LF	4	0-1 years	Open joints, deteriorated sealant,
	Connice - Metal i Tojecting	Entire Dunding	30	LI	7	o-i y <del>c</del> ai	open joints, deteriorated secialit,

Campus Name: Burley Page: 3 of 30 Assessment Date: 12/09/2021



#### Augustus H Burley Elementary School

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Some pieces are coming apart
	Exterior Walls - Brick	Entire Building	16,365	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,888	SF	4	0-1 year	Open joints, cracks in brick
	Exterior Walls - Precast Panel Wall	Entire Building	480	SF	6	10+ years	Concrete precast panel at roof number six electrical enclosure
	Exterior Walls - Stone-Cut	Entire Building	3,332	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	100	SF	5	10+ years	
Vindow	S						
	Guard - Guards perforated	Entire Building	2,185	SF	6	10+ years	
	Lintels - Brick	Entire Building	145	LF	6	10+ years	
	Lintels - Brick	Entire Building	12	LF	5	1-2 years	Arched window lintels in Boiler House
		-				-	are failing
	Lintels - Brick	Entire Building	4	LF	4	1-2 years	Arch lintel is failing, brick is displace
	Lintels - Steel	Entire Building	9	LF	6	10+ years	Corrosion is minor
	Lintels - Stone	Entire Building	715	LF	6	10+ years	
	Windows - Decorative	Entire Building	528	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,321	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System						
	Automatic Transfer Switch	Boiler Room	1	EA	4	2-5 years	Installed new in 2020 - not connected per building engineer
	Security System - CCTV	Entire Building	55,812	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	55,812	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	6	EA	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	2	EA	7	10+ years	North side
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	South side
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	36	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	7	10+ years	Combination of battery packs and exist sign
	Emergency Battery Packs - Multipurpose Room	Entire Building	5	EA	6	6-10 years	·
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,330	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	6,207	SF	6	6-10 years	No EM A/C power in the Gym
	Emergency A/C Power - Lunchrooms	Entire Building	870	SF	6	6-10 years	North side
	Emergency A/C Power - Students Toilets	Entire Building	1,546	SF	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Main office	55,812	SF	3	0-1 year	Not functional
_Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Room 302 closet
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Room 202 closet
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Room 102 closet
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	

**Category: Fire Protection Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Fire Ala	rm					'	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Process for renovation installed in 2021 and connect to new system in 2022. Per building engineer
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Per building engineer existing system still working
	Fire Alarm Strobe Lights	Entire Building	18,000	SF	6	6-10 years	Installed new in Process for renovation - 2021
	Fire Alarm_System	Entire Building	55,812	SF	4	2-5 years	Process for renovation installed in 2021 and connect to new system in 2022. Per building engineer
	Fire Pump Controller	Entire Building	1	EA	4	2-5 years	
Pump R	oom Assembly						
·	Fire Pump - 25-50 hp	Sprinkler	1	EA	5	2-5 years	

Campus Name: Burley Page : 5 of 30 Assessment Date: 12/09/2021



Catego	ry : Fire Protection		Е	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sprinkler	System						
	Dry Sprinkler System	Electrical Room	55,812	SF	6	6-10 years	
	Sprinkler Heads	Electrical Room	55,812		4	2-5 years	
	Sprinkler Piping	Electrical Room	55,812		5	6-10 years	
	Spirition i iping	Elootiloai (toolii	00,012	O.	Ŭ	o ro youro	
Catego	ry : Mechanical		E	Building	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ling Systems		•				
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Entire Building	1	EA	5	6-10 years	
	Air Intake	Entire Building	1	EA	6	6-10 years	
	Auxiliaries - 30001 - 45000 cfm	Entire Building	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts-	Entire Building	100	LF	5	6-10 years	
	Missing or Existing Shaft	Zikiio Ballanig	.00		Ü	o lo youlo	
	Zone Dampers	Entire Building	15	EA	6	6-10 years	
	Zone Dampers	Entire Building	12	EΑ	5	6-10 years	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Not exist - per building engineer Condensate pipes connected to feed water and pumps - per building engineer
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	Installed new in 2005
	Non Condensing - Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Steam Traps	Boiler Room	45	ĒΑ	5	6-10 years	
Hacting	Davisas					-	
Heating	Radiators - Steam	Basement	2	EA	5	6-10 years	Not leaking- fixed per building engineer
	Unit Heater - Electric	Entire Building	1	EA	5	0-1 year	Not working-per building engineer
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	1401 Working per building engineer
	Unit Heater - Steam	Entire Building	1	EA	7	2-5 years	Room 005
	Wall Heater - Electric	Entire Building	16	EA	5	6-10 years	KOOM OOS
	vvali i icaici - Licotiio	Little building	10	LA	5	0-10 years	

Campus Name: Burley Page : 6 of 30 Assessment Date: 12/09/2021



Catego	ry : Mechanical		В	uilding	: Main		-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<b>T</b>	tura Caratasi						
Tempera	ture Control  Electric Thermostat	Entire Building	2	EA	7	10+ years	Served exhaust fan Served electrica
	Electric Triefmostat	Entire Building	۷	EA	,	10+ years	unit heater
	Pneumatic System	Entire Building	55,912	SF	7	10+ years	Fixed per building engineer
	Thermostats - Pneumatic	Entire Building	27	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	North facing
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	10+ years	Engineer bathroom
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Lower roof
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	2-5 years	High roof New motor installed in 2006
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	2-5 years	Lower roof
Catego	ry : Plumbing		В	uilding	: Main		
	·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	Installed new in renovation process summer 2021
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	55,812	SF	4	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	55,812	SF	4	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	55,812	SF	4	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	55,812	SF	7	10+ years	Copper pipes - installed new water heater and new pipes - connect to existing pipes
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	55,812	SF	4	2-5 years	317
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	55,812	SF	4	2-5 years	
	Sanitary Piping	Entire Building	55,812	SF	5	6-10 years	
	Storm Piping	Entire Building	55,812	SF	5	6-10 years	
	Vent Piping	Entire Building	55,812	SF	5	6-10 years	
Pumps							

Campus Name: Burley Page: 7 of 30 Assessment Date: 12/09/2021



atego	ry : Room		В	uilding	: Main		
_						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices						
	AC Unit	1st Floor-clerk space 103	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor-clerk space 103	389	SF	7	10+ years	
	Doors - Side-lite	1st Floor-clerk space 103	70	SF	7	10+ years	
	Doors - Transom Window	1st Floor-clerk space 103	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-clerk space 103	1	EA	6	10+ years	
	Floor - Wood	1st Floor-clerk space 103	389	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-clerk space 103	7	EA	6	10+ years	
	Power Distribution	1st Floor-clerk space 103	8	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-clerk space 103	400	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-clerk space 103	450	SF	6	10+ years	
	AC Unit	1st a Floor-Meeting room	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st a Floor-Meeting room	264	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st a Floor-Meeting room	1	EA	6	10+ years	
	Floor - Wood	1st a Floor-Meeting room	264	SF	7	10+ years	
	Lighting - Lay-in	1st a Floor-Meeting room	4	EA	7	10+ years	
	Power Distribution	1st a Floor-Meeting room	8	EA	7	10+ years	
	Storage/ Closet	1st a Floor-Meeting room	78	SF	7	10+ years	
	Storage/ Closet	1st a Floor-Meeting room	95	SF	7	10+ years	
	Walls - Plaster/Drywall	1st a Floor-Meeting room	646	SF	6	10+ years	
	AC Unit	1st floor Principal office	1	ĒA	7	6-10 years	
	Ceiling - Lay-in	1st floor Principal office	350	SF	7	10+ years	
	Doors - Transom Window	1st floor Principal office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor Principal office	2	ĒΑ	6	10+ years	
	Floor - Wood	1st floor Principal office	350	SF	7	10+ years	
	Lighting - Lay-in	1st floor Principal office	8	EA	7	6-10 years	
	Power Distribution	1st floor Principal office	6	EA	7	10+ years	
	Storage/ Closet	1st floor Principal office	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor Principal office	820	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor- Office 209	170	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor- Office 209	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor- Office 209	170	SF	7	10+ years	Changed to match current observations
	Lighting - Pendent/Surface	2nd Floor- Office 209	2	EA	7	6-10 years	Changed to match current observations
	Power Distribution	2nd Floor- Office 209	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor- Office 209	461	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor- Office 209	282	SF	7	10+ years	
	AC Unit	Basement 002A counselor office	1	EA	7	6-10 years	
	Ceiling - Exposed	Basement 002A counselor office	350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement 002A counselor office	1	EA	6	10+ years	
	Floor - Tile	Basement 002A counselor office	350	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement 002A counselor office	6	EA	7	6-10 years	
	Power Distribution	Basement 002A counselor office	3	EA	7	10+ years	

Campus Name: Burley Page: 8 of 30 Assessment Date: 12/09/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement 002A counselor office	710	SF	7	10+ years	
	Work SInk	Basement 002A counselor office	1	EA	7	6-10 years	
	AC Unit	Basement-004 Teacher's Lounge	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-004 Teacher's Lounge	285	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-004 Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement-004 Teacher's Lounge	285	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement-004 Teacher's Lounge	6	EA	6	10+ years	
	Power Distribution	Basement-004 Teacher's Lounge	18	EΑ	6	10+ years	
	Walls - Plaster/Drywall	Basement-004 Teacher's Lounge	720	SF	6	10+ years	
	Work SInk	Basement-004 Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement-Engineer's Office	151	SF	6	10+ years	
	Ceiling - Lay-in	Basement-Engineer's Office	24	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Basement-Engineer's Office	1	EΑ	6	10+ years	
	Floor - Tile	Basement-Engineer's Office	175	SF	6	10+ years	
	Lighting - Lay-in	Basement-Engineer's Office	2	EA	6	10+ years	
	Power Distribution	Basement-Engineer's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement-Engineer's Office	425	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Engineer's Office	10	SF	5	1-2 years	Wall paint is cracked
	Ceiling - Exposed	Basement-Lunchroom Office	125	SF	6	10+ years	Changed to match current observations
	Doors - Wood Doors inclu hw	Basement-Lunchroom Office	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-Lunchroom Office	125	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Lunchroom Office	2	ĒΑ	6	10+ years	
	Power Distribution	Basement-Lunchroom Office	6	EA	6	10+ years	
	Walls - Masonry	Basement-Lunchroom Office	240	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Lunchroom Office	240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Speech Therapist Office	52	SF	6	10+ years	Ceiling paint is peeling
	Doors - Wood Doors inclu hw	Basement-Speech Therapist Office	1	ĒΑ	6	10+ years	31 - 31 - 3
	Floor - Concrete	Basement-Speech Therapist Office	52	SF	5	1-2 years	Floor paint is cracked and peeling
	Lighting - Pendent/Surface	Basement-Speech Therapist Office	1	ĒΑ	6	10+ years	3
	Power Distribution	Basement-Speech Therapist Office	2	EA	6	10+ years	
	Walls - Metal Panel	Basement-Speech Therapist Office	170	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Speech Therapist Office	145	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Speech Therapist Office	25	SF	5	1-2 years	Wall paint is cracked
	,	·				,	•
_Gymnas							
	Ceiling - Plaster/Drywall	3rd Floor	3,255	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	7	10+ years	
	Floor - Wood	3rd Floor	3,255	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	6-10 years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	-					-	

Campus Name: Burley Page: 9 of 30 Assessment Date: 12/09/2021



ge Curtain ge Lighting System ge-Stairs - Asphalt s - Plaster/Drywall  burpose Room  Unit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry is - Plaster/Drywall  Unit ing - Lay-in rs - Wood Doors inclu hw	Location  3rd Floor  Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen	Quantity  550 3 1 10 4,965  2 870 4 870 19 65 1,212 200 2 1,210	UOM SF EA LF SF EA SF EA SF EA SF EA SF SF SF SF EA	Rank           7           7           7           7           6           6           7           6           7           6           7           6           7           7	Recommend Replacement  10+ years 10+ years 6-10 years 10+ years	Comments
ge Curtain ge Lighting System ge-Stairs - Asphalt s - Plaster/Drywall  burpose Room  Unit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry s - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor  Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	550 3 1 10 4,965 2 870 4 870 19 65 1,212 200 2	SF EA LF SF EA SF EA SF SF EA	7 7 7 7 6 6 5 6 7 6	10+ years 10+ years 6-10 years 10+ years	Comments
ge Curtain ge Lighting System ge-Stairs - Asphalt gs - Plaster/Drywall gurpose Room Unit gr - Plaster/Drywall gr - Wood Doors inclu hw gr - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet gs - Masonry gs - Plaster/Drywall Unit gr - Lay-in gr - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor  Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	3 1 10 4,965 2 870 4 870 19 65 1,212 200 2	EA LF SF EA SF EA SF SF EA	7 7 7 7 6 6 5 6 7 6 7	10+ years 6-10 years 10+ years	
ge Lighting System ge-Stairs - Asphalt s - Plaster/Drywall  purpose Room  Unit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry s - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	1 10 4,965 2 870 4 870 19 65 1,212 200 2	EA SF EA SF EA SF SF SF EA	7 7 7 6 6 5 6 7 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
pe-Stairs - Asphalt s - Plaster/Drywall  purpose Room  Jnit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry s - Plaster/Drywall  Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	10 4,965 2 870 4 870 19 65 1,212 200 2	EA SF EA SF EA SF SF SF EA	7 7 6 6 5 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
pe-Stairs - Asphalt s - Plaster/Drywall  purpose Room  Jnit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry s - Plaster/Drywall  Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	4,965 2 870 4 870 19 65 1,212 200 2 1,210	EA SF EA SF EA SF SF EA	7 6 6 5 6 7 6 7	6-10 years 10+ years	
s - Plaster/Drywall  purpose Room  Jnit ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet s - Masonry s - Plaster/Drywall  Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	2 870 4 870 19 65 1,212 200 2	EA SF EA SF SF SF SF EA	7 6 6 5 6 7 6 7	6-10 years 10+ years	
Unit Ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet ls - Masonry ls - Plaster/Drywall Unit ling - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	870 4 870 19 65 1,212 200 2	SF EA SF EA SF SF EA	6 5 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
Unit Ing - Plaster/Drywall rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet ls - Masonry ls - Plaster/Drywall Unit ling - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	870 4 870 19 65 1,212 200 2	SF EA SF EA SF SF EA	6 5 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
ing - Plaster/Drywall rs - Wood Doors inclu hw r - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet ls - Masonry ls - Plaster/Drywall Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	870 4 870 19 65 1,212 200 2	SF EA SF EA SF SF EA	6 5 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
rs - Wood Doors inclu hw or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet ls - Masonry ls - Plaster/Drywall Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	4 870 19 65 1,212 200 2	EA SF EA SF SF SF EA	6 5 6 7 6 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
or - Concrete Epoxy/ Painted ting - Pendent/Surface age/ Closet is - Masonry is - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	870 19 65 1,212 200 2	SF EA SF SF SF EA	5 6 7 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	
ting - Pendent/Surface age/ Closet ls - Masonry ls - Plaster/Drywall Jnit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	19 65 1,212 200 2 1,210	EA SF SF SF EA	6 7 6 7 7	10+ years 10+ years 10+ years 10+ years	
age/ Closet ls - Masonry ls - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-N Lunchroom Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	65 1,212 200 2 1,210	SF SF SF EA	7 6 7 7	10+ years 10+ years 10+ years	
is - Masonry is - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	1,212 200 2 1,210	SF SF EA	6 7 7	10+ years 10+ years	
s - Plaster/Drywall Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-N Lunchroom Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	200 2 1,210	SF EA	7 7	10+ years	
Unit ing - Lay-in rs - Wood Doors inclu hw	Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	1,210	EA	7		
ing - Lay-in rs - Wood Doors inclu hw	kitchen Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming	1,210			6-10 years	
rs - Wood Doors inclu hw	Basement-S Lunchroom/warming kitchen Basement-S Lunchroom/warming		SF	_		
	Basement-S Lunchroom/warming	2		6	10+ years	
r - Concrete Epoxy/ Painted		2	EA	6	10+ years	
. Control Epony/ Fairtou	Basement-S Lunchroom/warming kitchen	1,210	SF	7	10+ years	
ting - Pendent/Surface	Basement-S Lunchroom/warming kitchen	27	EA	6	10+ years	
ving Line	Basement-S Lunchroom/warming kitchen	13	LF	6	6-10 years	
s - Masonry	Basement-S Lunchroom/warming kitchen	750	SF	6	10+ years	
s - Plaster/Drywall	Basement-S Lunchroom/warming kitchen	1,083	SF	6	10+ years	
rs - Wood Doors inclu hw	2nd Floor	1	FΑ	7	10+ vears	
					•	
dow AC Offic	ZHU FIOOI	1	LA	,	0-10 years	
ervice Rooms						
					•	
tor's Closet		14		5	10+ years	Wall and ceiling paint is cracking
	3rd Floor	15	SF	7	10+ years	<b>3</b> .
tor's Closet			SF	7	•	
tor's Closet	3rd Floor				10+ years	
sh do e to	or's Closet or's Closet or's Closet	nes 2nd Floor ow AC Unit 2nd Floor  rvice Rooms  or's Closet 1st Floor or's Closet 2nd Floor or's Closet 3rd Floor ge Room 3rd Floor	nes         2nd Floor         143           ow AC Unit         2nd Floor         1    rvice Rooms  or's Closet  1st Floor  14  or's Closet  2nd Floor  14  or's Closet  3rd Floor  3rd Floor  75	nes         2nd Floor         143         SF           ow AC Unit         2nd Floor         1         EA    rvice Rooms           or's Closet         1st Floor         14         SF           or's Closet         2nd Floor         14         SF           or's Closet         3rd Floor         15         SF	nes       2nd Floor       143       SF       7         ow AC Unit       2nd Floor       1       EA       7         rvice Rooms         or's Closet       1st Floor       14       SF       7         or's Closet       2nd Floor       14       SF       5         or's Closet       3rd Floor       15       SF       7         ge Room       3rd Floor       75       SF       7	nes       2nd Floor       143       SF       7       10+ years         row AC Unit       2nd Floor       1       EA       7       6-10 years    rvice Rooms         rvice Rooms         or's Closet       1st Floor       14       SF       7       10+ years         or's Closet       2nd Floor       14       SF       5       10+ years         or's Closet       3rd Floor       15       SF       7       10+ years         ge Room       3rd Floor       75       SF       7       10+ years

Campus Name: Burley Page : 10 of 30 Assessment Date: 12/09/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake Plenums	Basement	320	SF	7	10+ years	
	Air Tunnel	Basement	340	SF	7	10+ years	
	Boiler Room	Basement	1,798	SF	5	1-2 years	Wall and floor paint is peeling
	Janitor's Closet	Basement	20	SF	7	10+ years	• • • •
	Mechanical/ Service Rooms	Basement	145	SF	5	1-2 years	Ceiling plaster is spalling
	Mechanical/ Service Rooms	Basement	75	SF	5	1-2 years	Masonry wall is spalling
	Mechanical/ Service Rooms	Basement	250	SF	5	1-2 years	Masonry is spalling and paint is
						,	peeling
	Storage Room	Basement	172	SF	7	10+ years	Y
	Storage Room	Basement	455	SF	5	10+ years	
	Storage Room	Basement	180	SF	5	1-2 years	Ceiling and floor paint is peeling
	Storage Room	Basement	100	SF	5	1-2 years	Wall and ceiling paint is peeling
	Glorage Room	Basement	100	Oi.	J	1 Z years	vvali and ceiling paint is peciling
Restroo	m						
	Accessories	1st Floor-Men's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Men's Staff Restroom	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Men's Staff Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Men's Staff Restroom	162	SF	6	6-10 years	
	Hand Dryer	1st Floor-Men's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Men's Staff Restroom	2	EΑ	6	10+ years	
	Partitions	1st Floor-Men's Staff Restroom	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Men's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor-Men's Staff Restroom	2	EA	6	6-10 years	
	Accessories	1st Floor-Women's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom	162	SF	6	10+ years	
	Doors - Transom Window	1st Floor-Women's Staff Restroom		SF	6	•	
			8 1	SF EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom	=		6	10+ years	
	Floor - Tile	1st Floor-Women's Staff Restroom	162	SF	6	10+ years	
	Hand Dryer	1st Floor-Women's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Women's Staff Restroom	2	EA	6	10+ years	
	Partitions	1st Floor-Women's Staff Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Women's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor-Women's Staff Restroom	2	EΑ	6	6-10 years	
	Accessories	2nd Floor-Boys Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Boys Restroom	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Boys Restroom	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor-Boys Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Boys Restroom	2	EA	7	10+ years	
	Hand Dryer	2nd Floor-Boys Restroom	1	ĒΑ	7	6-10 years	
	Lavatory	2nd Floor-Boys Restroom	2	EΑ	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Boys Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Boys Restroom	3	EA	7	10+ years	
	i didiono	Zila i looi boys (testilooili	3		,	TOT years	

Campus Name: Burley Page : 11 of 30 Assessment Date: 12/09/2021



Catego	ry : Room		В	uilding	: Main		•
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	2nd Floor-Boys Restroom	7	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Boys Restroom	267	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Boys Restroom	534	SF	6	10+ years	
	Water Closet	2nd Floor-Boys Restroom	3	EA	6	6-10 years	
	Accessories	2nd Floor-Girls Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Girls Restroom	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Girls Restroom	2	EA	7	10+ years	
	Hand Dryer	2nd Floor-Girls Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Girls Restroom	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Girls Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Girls Restroom	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	534	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	2	SF	5	1-2 years	Wall tiles spalling
	Water Closet	2nd Floor-Girls Restroom	9	EA	6	6-10 years	. •
	Accessories	2nd Floor-Unisex Restroom	123	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Unisex Restroom	123	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Unisex Restroom	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor-Unisex Restroom	123	SF	7	10+ years	
	Hand Dryer	2nd Floor-Unisex Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Unisex Restroom	2	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor-Unisex Restroom	2	EA	7	10+ years	
	Partitions	2nd Floor-Unisex Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Unisex Restroom	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Unisex Restroom	173	SF	7	10+ years	
	Water Closet	2nd Floor-Unisex Restroom	2	EA	6	6-10 years	
	Accessories	Basement-Boy's Restroom	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Boy's Restroom	152	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Boy's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	152	SF	7	10+ years	
	Floor Drain	Basement-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Boy's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement-Boy's Restroom	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Boy's Restroom	3	EA	6	10+ years	
	Partitions	Basement-Boy's Restroom	4	EA	7	10+ years	
	Urinals	Basement-Boy's Restroom	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement-Boy's Restroom	5	SF	6	1-2 years	Wall paint peeling
	Walls - Plaster/Drywall	Basement-Boy's Restroom	160	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	425	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	5	SF	5	1-2 years	Wall tiles chipped
	Water Closet	Basement-Boy's Restroom	4	ĒΑ	6	6-10 years	• •
	Accessories	Basement-Engineer's Restroom	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Engineer's Restroom	50	SF	6	10+ years	Ceiling paint is cracking
	,	Ŭ ·				,	· · · · · · · · · · · · · · · · · · ·

Campus Name: Burley Page: 12 of 30 Assessment Date: 12/09/2021



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement-Engineer's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Engineer's Restroom	50	SF	6	10+ years	
	Floor Drain	Basement-Engineer's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Engineer's Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Engineer's Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement-Engineer's Restroom	1	EA	6	10+ years	
	Showers	Basement-Engineer's Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Engineer's Restroom	285	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Engineer's Restroom	30	SF	5	1-2 years	Wall paint is cracking
	Walls - Tile Ceramic/ Porcelain	Basement-Engineer's Restroom	65	SF	6	10+ years	
	Water Closet	Basement-Engineer's Restroom	1	EA	6	6-10 years	
	Accessories	Basement-Girl's Restroom	510	SF	7	6-10 years	<b>-</b>
	Ceiling - Plaster/Drywall	Basement-Girl's Restroom	50	SF	6	1-2 years	Ceiling paint peeling
	Ceiling - Plaster/Drywall	Basement-Girl's Restroom	460	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Girl's Restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	510	SF	6	10+ years	
	Floor Drain	Basement-Girl's Restroom	2	EA	7	10+ years	
	Hand Dryer	Basement-Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement-Girl's Restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement-Girl's Restroom	7	EA	6	10+ years	
	Partitions	Basement-Girl's Restroom	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement-Girl's Restroom	365	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	800	SF	6	10+ years	
	Water Closet	Basement-Girl's Restroom	10	EA	6	6-10 years	
	Accessories	Basement-Men's Staff Restroom	155	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Men's Staff Restroom	155	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Men's Staff Restroom	2	EA	6	10+ years	
	Floor - Tile	Basement-Men's Staff Restroom	70	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Men's Staff Restroom	85	SF	6	10+ years	
	Floor Drain	Basement-Men's Staff Restroom	1	EΑ	7	10+ years	
	Hand Dryer	Basement-Men's Staff Restroom	1	EΑ	7	6-10 years	
	Lavatory	Basement-Men's Staff Restroom	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Men's Staff Restroom	2	EΑ	6	10+ years	
	Lighting - Wall Mounted	Basement-Men's Staff Restroom	1	EΑ	6	10+ years	
	Partitions	Basement-Men's Staff Restroom	2	EΑ	7	10+ years	
	Urinals	Basement-Men's Staff Restroom	1	EA SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Men's Staff Restroom	365		6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Men's Staff Restroom	225	SF	6	10+ years	
	Water Closet	Basement-Men's Staff Restroom	2	EA SF	6	6-10 years	
	Accessories	Basement-Women's Staff Restroom	145	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Women's Staff Restroom	145		6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Women's Staff Restroom	2	EA SF	6	10+ years	
	Floor - Tile Coromic/ Percelain	Basement-Women's Staff Restroom	60	SF SF	6 6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Women's Staff Restroom	85	ЭF	О	10+ years	

Campus Name: Burley Page: 13 of 30 Assessment Date: 12/09/2021



Catego	ry : Room		В	uilding	: Main		,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	Basement-Women's Staff Restroom	1	EΑ	7	6-10 years	
	Lavatory	Basement-Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Women's Staff Restroom	2	EA	7	10+ years	
	Lighting - Wall Mounted	Basement-Women's Staff Restroom	1	EA	7	10+ years	
	Partitions	Basement-Women's Staff Restroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement-Women's Staff Restroom	345	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Women's Staff Restroom	255	SF	6	10+ years	
	Water Closet	Basement-Women's Staff Restroom	2	EA	6	6-10 years	
	Accessories	Main Office	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	51	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	51	SF	7	10+ years	
	Lavatory	Main Office	1	ĒΑ	6	6-10 years	
	Lighting - Wall Mounted	Main Office	1	ΕA	7	10+ years	Changed to match current
	Lighting Trail Modified	Main Ollios	·	_, `	•	io. youro	observations
	Walls - Plaster/Drywall	Main Office	310	SF	6	10+ years	oboot valions
	Water Closet	Main Office	1	EΑ	6	6-10 years	
	Accessories	Restroom 001	24	SF	7	6-10 years	
	Ceiling - Exposed	Restroom 001	24	SF	6	10+ years	Changed to match current
	Coming Expected	110011001111001		O.	Ŭ	ioi youro	observations
	Doors - Wood Doors inclu hw	Restroom 001	1	EA	6	10+ years	oboot valions
	Floor - Tile	Restroom 001	24	SF	6	10+ years	
	Lavatory	Restroom 001	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	Restroom 001	1	ĒΑ	6	10+ years	
	Walls - Masonry	Restroom 001	60	SF	6	10+ years	
	Walls - Plaster/Drywall	Restroom 001	100	SF	7	10+ years	
	Water Closet	Restroom 001	1	EΑ	6	6-10 years	
	Accessories	Restroom 002A inside counselor	30	SF	7	6-10 years	
		office		-	•	- · · · · · · · · · · · · · · · · · · ·	
	Ceiling - Lay-in	Restroom 002A inside counselor	30	SF	6	10+ years	
		office		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	Restroom 002A inside counselor	1	EΑ	6	10+ years	
		office			-	, , , , , , , , , , , , , , , , , , , ,	
	Floor - Tile	Restroom 002A inside counselor	30	SF	6	10+ years	
		office	-	О.	ŭ	. o · you.o	
	Lavatory	Restroom 002A inside counselor	1	EΑ	6	6-10 years	
	<b>,</b>	office				,	
	Lighting - Lay-in	Restroom 002A inside counselor	1	EA	6	10+ years	
	gg,	office			-	, , , , , , , , , , , , , , , , , , , ,	
	Walls - Plaster/Drywall	Restroom 002A inside counselor	175	SF	6	10+ years	
		office		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Walls - Vinyl Coated Gypsum Panel	Restroom 002A inside counselor	43	SF	6	10+ years	
		office	.0	٥.	ū	,	
	Water Closet	Restroom 002A inside counselor	1	EA	6	6-10 years	
					-	<b>,</b>	

Campus Name: Burley Page: 14 of 30 Assessment Date: 12/09/2021



**Building: Main** Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments office

Cotogony . Classroom Duilding . Main

Catego	ry : Classroom		Building : Main						
	_					Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classroo	m #001 (Kindergarten)								
	AC Units	Basement	1	EA	7	6-10 years			
	Ceiling - Exposed	Basement	765	SF	6	10+ years	Changed to match current observations		
	Chalk Board	Basement	4	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years			
	Floor - Wood	Basement	765	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement	14	EA	6	10+ years			
	Walls - Masonry	Basement	1,054	SF	6	10+ years			
	Work Sink	Basement	1	EA	7	6-10 years			
Classroc	m #002 (Pre School)								
	AC Units	Basement	1	EA	7	6-10 years	Quantity changed to match current observations		
	Casework	Basement	5	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	Basement	1,039	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years			
	Floor - Wood	Basement	1,039	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement	<sup>'</sup> 12	EA	7	10+ years			
	Marker Board	Basement	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	Basement	1,260	SF	6	10+ years			
_Classroo	m #003 (Kindergarten)								
	AC Units	Basement	1	EA	7	6-10 years			
	Ceiling - Lay-in	Basement	822	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	ĒΑ	6	10+ years			
	Floor - Tile	Basement	822	SF	6	10+ years			
	Lighting - Lay-in	Basement	14	EA	6	10+ years			
	Marker Board	Basement	8	LF	6	6-10 years			
	Walls - Plaster/Drywall	Basement	960	SF	7	10+ years			
Classroo	m #005 (Special Program)								
	AC Units	Basement	1	EA	7	6-10 years			
	Ceiling - Lay-in	Basement	339	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years			
	Floor - Tile	Basement	335	SF	6	10+ years			
	Floor - Tile	Basement	4	SF	4	1-2 years	Chipped		
	Lighting - Lay-in	Basement	6	EA	6	10+ years	- · · ·           - · · ·		
	5 5 -7		-		-	- <b>,</b>			

Campus Name: Burley Page: 15 of 30 Assessment Date: 12/09/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	663	SF	6	10+ years	
Classroo	om #101 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	Quantity changed to match current observations
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	7	10+ years	Newly refinished
	Walls - Vinyl Coated Gypsum Panel	1st Floor	262	SF	6	10+ years	rtomy romnonou
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	nm #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	743	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5	SF	6	10+ years	Peeling paint
	Chalk Board	1st Floor	8	LF	4	2-5 years	r eemig pamit
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Books includition	1st Floor	748	SF	7	•	
		1st Floor				10+ years	
	Lighting - Pendent/Surface		14	EA	6	10+ years	
	Marker Board	1st Floor	20	LF 0F	7	6-10 years	
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	830	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	Quantity changed to match current observations
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years	

Campus Name: Burley Page : 16 of 30 Assessment Date: 12/09/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #105 (Regular Classroom)						
Classiu	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Bools inclu hw	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
			12				
	Marker Board	1st Floor		LF CF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,085	SF	7	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
						•	
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,075	SF	7	10+ years	NA/ 4 1
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage
Classro	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Quantity changed to match current observations
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	object various
	Floor - Wood	1st Floor	748	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
	walls - Flaster/Drywall	151 11001	1,040	SF	O	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Quantity changed to match current observations
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
						,	

Campus Name: Burley Page: 17 of 30 Assessment Date: 12/09/2021



Category : Classroom			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
lassroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board		20	LF	7	-	
		2nd Floor				6-10 years	Lighto do not turn on with switch
	Storage/ Closet	2nd Floor	125	SF	5	10+ years	Lights do not turn on with switch
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
lassroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	92	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
	Work Sink	2nd Floor	1,040	EA	7	10+ years	
						,	
lassroc	om #202A (Special Education)  Ceiling - Plaster/Drywall	2nd Floor	253	SF	7	10+ years	
	Doors - Wood Doors inclu hw			EA		•	
		2nd Floor	1		7	10+ years	
	Floor - Wood	2nd Floor	253	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	560	SF	7	10+ years	
lassroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Bools inclu hw	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Lighting - I chacil/Sulface	ZIIU I IUUI	14	LA	,	0-10 years	

Campus Name: Burley Page: 18 of 30 Assessment Date: 12/09/2021



Group	/ : Classroom Item - Type Marker Board	Location		uilding		Recommend	
•		oup Item - Type Location				Necommend	
•		Location	Quantity	UOM	Rank	Replacement	Comments
		2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,310	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroom	n #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	375	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	70	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	375	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	655	SF	7	10+ years	
Classroom	n #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years	
Classroom	n #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years	
Classroom	n #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	

Campus Name: Burley Page: 19 of 30 Assessment Date: 12/09/2021



Categor	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
Classroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
	Walls - Flastel/Drywall	2110 11001	1,046	SF	,	10+ years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	5	10+ years	Wall paint peeling
	Walls - Plaster/Drywall	3rd Floor	1,385	SF	7	10+ years	1 1 3
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	795	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Wood Bools med TW	3rd Floor	795	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	130	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,485	SF	6	10+ years	
	vvalis - i lastei/Diywali	314 F1001	1,400	SI	U	10+ years	
Classroo	m #303 (Regular Classroom)						

Campus Name: Burley Page : 20 of 30 Assessment Date: 12/09/2021



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	170	SF	5	1-2 years	Wall paint is peeling
	Walls - Plaster/Drywall	3rd Floor	1,568	SF	7	10+ years	vvaii pairit is pooliing
assroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	875	SF	7	10+ years	
	Doors - Transom Window		30	SF	7	•	
		3rd Floor				10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	95	SF	5	10+ years	Wall and ceiling paint is damaged
	Walls - Plaster/Drywall	3rd Floor	1,325	SF	7	10+ years	
assroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	26	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,565	SF	7	10+ years	
assroc	om #308 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Wood Doors inclu riw	3rd Floor	775	SF	7	10+ years	
						-	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	

Campus Name: Burley Page : 21 of 30 Assessment Date: 12/09/2021



Catego	Category : Classroom			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	5	1-2 years	Floor boards missing
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	7	10+ years	
	•					•	

Category : Interior **Building** · Main

Catego	Category : Interior		В	uilding			
0	Name Trans	Landin	0 !!!	LIONS	D/	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor_							
	Ceiling - Plaster/Drywall	1st Floor	2,065	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	2,065	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,065	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	85	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	8	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	Changed to match current observations
	Floor - Wood	2nd Floor	2,065	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,465	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	40	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	196	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,465	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Stairs - Wood	3rd Floor	12	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,085	SF	7	10+ years	
	Ceiling - Exposed	Basement	1,756	SF	6	10+ years	
	Ceiling - Exposed	Basement	200	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	Basement	858	SF	6	10+ years	•
	Doors - Transom Window	Basement	80	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	12	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	Inside lunchroom room
	Floor - Concrete Epoxy/ Painted	Basement	2,120	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	32	EA	6	10+ years	
	Lighting - Wall Mounted	Basement	8	EA	6	10+ years	
	Stairs - Concrete Stairs	Basement	48	LF	6	10+ years	
	Student Lockers - Two Tiers	Basement	5	EA	7	10+ years	
	Walls - Masonry	Basement	2,100	SF	6	10+ years	

Campus Name: Burley Page : 22 of 30 Assessment Date: 12/09/2021



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	Basement	5,445	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	50	SF	5	1-2 years	Water damage
Safety							
-	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Camera Viewing Station	1st Floor	2	EΑ	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	E Stairs	432	SF	7	10+ years	
	Floor - Asphalt	E Stairs	612	SF	5	2-5 years	Cracking
	Handrails	E Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	E Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	E Stairs	518	LF	5	2-5 years	Cracks
	Walls - Plaster/Drywall	E Stairs	3,696	SF	7	10+ years	
	Ceiling - Plaster/Drywall	W Stairs	432	SF	7	10+ years	
	Floor - Asphalt	W Stairs	612	SF	7	10+ years	
	Handrails .	W Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	W Stairs	10	EΑ	7	6-10 years	
	Stairs - Asphalt	W Stairs	518	LF	5	1-2 years	Cracking
	Walls - Plaster/Drywall	W Stairs	3,681	SF	7	10+ years	-
	Walls - Plaster/Drywall	W Stairs	15	SF	6	1-2 years	Flaking

Campus Name: Burley Page : 23 of 30 Assessment Date: 12/09/2021



Category : Exterior **Building: Field House** 

beyond its serv
ooyona no con
at entry
beyond its serv
boyona no conv
beyond its serv
w any signs of
ii aii, oigiio oi
beyond its serv
uts
k
es, and broken
•
vindows.
ng

Campus Name: Burley Page : 24 of 30 Assessment Date: 12/09/2021



y : Exterior Item - Type y : Electrical Item - Type	Location	B Quantity	uilding UOM	: Field F	House Recommend Replacement	Comments
y : Electrical	Location				Recommend	Comments
y : Electrical	Location	Quantity	UOM	Rank	Replacement	Comments
					op.aoomont	Commicing
Item - Tyne	ategory : Electrical			: Field F	louse	
Item - Tyne					Recommend	
nem Type	Location	Quantity	UOM	Rank	Replacement	Comments
vice					-	
Independent Electrical Service for emergency power	1st Floor	1	EA	7	10+ years	
atribution						
Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	6-10 years	Per building engineer- panel is more than 40 years old but not has any issues
v · Fire Protection		В	uildina	· Field F	łouse	
y : i iic i roteotion			ananig	. I leia i		
Item - Type	Location	Quantity	UOM	Rank		Comments
· ·	2004	Quantity	<b>J J J J J J J J J J</b>	Hann	rtopiacomont	Comments
Fire Alarm Strobe Lights	Entire Building	3	SF	7	10+ years	Process for renovation work 2021- construction finish in 2022
Fire Alarm_System	Entire Building	2,715	SF	7	10+ years	Served from main building Process for renovation work 2021-construction finish in 2022
y : Mechanical		В	uilding			
		Recommend				
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					_	
Gas/ Natural Draft Furnace - 101 - 200 MBH	Mechanical Room	1	EA	5	6-10 years	
ure Control						
	1st Floor	1	FA	6	6-10 years	
Ziodilo Momodiai	1001	·	_, 、	Ŭ	o io youro	
n						
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	3	0-1 year	Per building engineer - fan not exist
v : Plumbina		В	uildina			
<u> </u>					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
,		•				
Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	2-5 years	
ע טפּיים ע	/: Fire Protection  Item - Type  Fire Alarm Strobe Lights  Fire Alarm_System  /: Mechanical  Item - Type  evices  Gas/ Natural Draft Furnace - 101 - 200  MBH  ure Control  Electric Thermostat  Exhaust Fans- Indoor - Less than 500 CFM  /: Plumbing  Item - Type	Lighting and Power Panels - Above 100 A  Mechanical Room  /: Fire Protection  Item - Type  Location  Fire Alarm Strobe Lights  Fire Alarm_System  Entire Building  /: Mechanical  Item - Type  evices  Gas/ Natural Draft Furnace - 101 - 200  MBH  Mechanical Room  MBH  Inc Control  Electric Thermostat  1st Floor  Exhaust Fans- Indoor - Less than 500 CFM  Entire Building  /: Plumbing  Item - Type  Location	Lighting and Power Panels - Above 100 A Mechanical Room 1  /: Fire Protection B  Item - Type Location Quantity  Fire Alarm Strobe Lights Entire Building 3  Fire Alarm_System Entire Building 2,715  /: Mechanical B  Item - Type Location Quantity  evices  Gas/ Natural Draft Furnace - 101 - 200 Mechanical Room 1  MBH  III Control  Electric Thermostat 1st Floor 1  Exhaust Fans- Indoor - Less than 500 CFM Entire Building 2  /: Plumbing B  Item - Type Location Quantity  B  Item - Type Location Quantity	Lighting and Power Panels - Above 100 A Mechanical Room 1 EA  /: Fire Protection Building  Item - Type Location Quantity UOM  Fire Alarm Strobe Lights Entire Building 3 SF  Fire Alarm_System Entire Building 2,715 SF  /: Mechanical Building  Item - Type Location Quantity UOM  evices  Gas/ Natural Draft Furnace - 101 - 200 Mechanical Room 1 EA  MBH  ITE Control  Electric Thermostat 1st Floor 1 EA  Exhaust Fans- Indoor - Less than 500 CFM Entire Building 2 EA  /: Plumbing Building  Item - Type Location Quantity UOM  Electric Thermostat Ust Floor 1 EA	Lighting and Power Panels - Above 100 A Mechanical Room 1 EA 4  /: Fire Protection Building : Field Fittem - Type Location Quantity UOM Rank  Fire Alarm Strobe Lights Entire Building 3 SF 7  Fire Alarm_System Entire Building 2,715 SF 7  /: Mechanical Building : Field Fittem - Type Location Quantity UOM Rank  evices  Gas/ Natural Draft Furnace - 101 - 200 Mechanical Room 1 EA 5  MBH  Ira Control Electric Thermostat 1st Floor 1 EA 6  Exhaust Fans- Indoor - Less than 500 CFM Entire Building 2 EA 3  /: Plumbing Building : Field Fittem - Type Location Quantity UOM Rank	Lighting and Power Panels - Above 100 A Mechanical Room 1 EA 4 6-10 years  7: Fire Protection    Building : Field House Recommend Replacement

Campus Name: Burley Page : 25 of 30 Assessment Date: 12/09/2021



	Category : Plumbing			uilding	: Field F		
			Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
iping							
	Domestic Piping-Hot Water Return Lines	Entire Building	2,717	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	2,715	SF	6	6-10 years	
	(Horizontal Lines)						
	Sanitary Piping	Entire Building	2,715	SF	6	6-10 years	
	Vent Piping	Entire Building	2,715	SF	6	6-10 years	
			_			_	
Catego	ry : Classroom		В	uilding	: Field I		
_						Recommend	
<b>3</b> roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #109E (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Walls - Masonry	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	7	10+ years	
Classroo	m #109W (Art Room)						
<u> </u>	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	41	SF	7	10+ years	
	Walls - Masonry	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	7	10+ years	
	·					•	
Catego	ry : Room		В	uilding	: Field h		
	Name Time	1	0	1101	D/	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
/lechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Storage Room	1st Floor	70	SF	7	10+ years	
Restroor	1						
	Accessories	1st Floor-109E Restroom	38	SF	7	6-10 years	

Campus Name: Burley Page : 26 of 30 Assessment Date: 12/09/2021



Catego	Category : Room			uilding	: Field I	louse	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor-109E Restroom	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-109E Restroom	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-109E Restroom	38	SF	7	6-10 years	
	Floor Drain	1st Floor-109E Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-109E Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-109E Restroom	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-109E Restroom	242	SF	7	10+ years	
	Water Closet	1st Floor-109E Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-109W Restroom	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-109W Restroom	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-109W Restroom	1	EΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-109W Restroom	38	SF	5	10+ years	
	Floor Drain	1st Floor-109W Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-109W Restroom	1	EΑ	7	10+ years	
	Lighting - Wall Mounted	1st Floor-109W Restroom	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-109W Restroom	242	SF	6	10+ years	
	Water Closet	1st Floor-109W Restroom	1	EA	7	10+ years	

Category : Interior **Building: Field House** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	175	SF	5	1-2 years	Cracking throughout
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	-
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	173	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	460	SF	7	10+ years	



Puilding : Sito

Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic							
	Lighting	North Courtyard	2	EA SF	6	10+ years	
	Surface - Asphalt Surface - Synthetic	North Courtyard North Courtyard	4,000 4,894	SF SF	6 6	10+ years 10+ years	
	Surface - Synthetic	North Courtyard	4,094	SF	5	1-2 years	Add to surface is broken and is being
	Surface - Synthetic	North Courtyard	10	Sir	3	1-2 years	undermined by a growing hole under it
Civil/Dra	inage						
OIVIII DIG	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
Fencing							
J	Fencing - Chain Link	Entire Site	384	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	80	LF	5	1-2 years	Damaged, bent, corroded
	Fencing - Chain Link	Entire Site	400	LF	4	2-5 years	Broken, rusted, bent out of shape chain-link fence, pieces missing
	Fencing - New Standard Ornamental	Entire Site	287	LF	6	10+ years	Gram marteries, process missing
Landsca	De .						
	Benches	Entire Site	10	EA	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	20,286	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	2,050	SF	4	1-2 years	Large cracks, potholes, alligatored surfaces, uneven surfaces, trip hazards
	Landscape - Hardscape- Concrete	Entire Site	2,010	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	750	SF	4	1-2 years	Shattered, broken concrete
	Lighting - Pole Mounted	Entire Site	3	EA	6	10+ years	
	Parkway trees	Entire Site	5	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,200	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	7,660	SF	6	10+ years	The surfaces in good shape, starting to show signs of wear and tear
	Trash Receptacles	Entire Site	2	EA	6	10+ years	Ç
Parking I	ot						
	Surface - Asphalt	E Parking Lot	3,620	SF	6	10+ years	
	Trash Compactor	E Parking Lot	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	E Parking Lot	400	SF	7	10+ years	
Playgrou	nd						
, ,							

Campus Name: Burley Page : 28 of 30 Assessment Date: 12/09/2021



Catego	Category : Site			uilding	•		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - School Age 5-12	NE Playground	1	EA	4	2-5 years	Play ground equipment has lost much of its paint, much metal exposed
	Surface - Square Rubber Mats	NE Playground	2,358	SF	4	2-5 years	Curling at edges, large gaps, trip hazards
	Equipment - Pre K 3-5	NW Playground	1	EA	6	10+ years	
	Surface - Poured Surface	NW Playground	1,600	SF	6	6-10 years	
Sidewalk	KS .						
	Sidewalks - Internal Walks	Entire Site	50	LF	5	1-2 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	5,035	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	5	1-2 years	Broken sidewalks
Signage							
0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Burley Page: 29 of 30 Assessment Date: 12/09/2021

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	<del>_</del>	<del>_</del>			,				
Computer Lab	Library	1st Floor	101	101	748	140	58	N	N
Kindergarten	Kindergarten	Basement	003	003	822	62	28	N	N
Kindergarten	Regular Classroom	Basement	001	001	765	62	28	N	N
Pre School	Pre School	Basement	002	002	1,039	34	12	N	N
Regular Classroom	Office	2nd Floor	204	204	375	15	15		1
Regular Classroom	Regular Classroom	1st Floor	102	102	748	140	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	748	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	748	140	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	748	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	748	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	830	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	748	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	748	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	760	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	795	140	58	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	865	140	58	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	880	140	58	Y	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	775	140	58	Y	N
Regular Classroom	Special Education	2nd Floor	202	202	748	140	58	Υ	N
Regular Classroom	Special Education	2nd Floor	206	206	830	140	58	Υ	N
Special Education	Regular Classroom	3rd Floor	308	308	775	140	58	Υ	N
Special Education	Store Room	2nd Floor	202A	202A	253	15	15		
Special Program	Kindergarten	Basement	005	005	339	124	40	N	N
Building : Field House									
Art Room	Regular Classroom	1st Floor	109W	109W	686	72	30	N	N
Kindergarten	Kindergarten	1st Floor	109E	109E	686	84	40	N	N

Campus Name: Burley	Page : 30 of 30	Assessment Date: 12/09/2021