

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1893	4	49,191
Modular 1 (4-Classroom)	2008	1	4,060
Campus Total			53,251

Catego	ry : Exterior Building :						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Main Roof	6	EA	7	6-10 years	
	Cell Equipment - Cabinets	Main Roof	6	EA	7	10+ years	
Entrance	2						
	Entrance Control - Audio and Video	1 - Main Door	1	EA	7	6-10 years	
	Exterior Doors - Exterior AMP Door	1 - Main Door	3	EA	6	6-10 years	Paint required.
	Exterior Doors - Transom Lite	1 - Main Door	3	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	2 - East	2	EA	6	6-10 years	Paint required.
	Exterior Doors - Transom Lite	2 - East	2	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	3 - North	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 - North	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 - South	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	6 - South	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	6 - South	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	7 - North	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7 - North	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	8 - West	1	EA	5	0-1 year	Dented, starting to corrode.
	Exterior Doors - Exterior Steel Door	9 - West	2	EA	5	0-1 year	Dented, starting to corrode.
	Exterior Doors - Exterior Steel Door	Fire Escape 1st Floor - South	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Fire Escape 1st Floor - South	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Fire Escape 2nd Floor - West	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Fire Escape 2nd Floor - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Fire Escape 3rd Floor - West	1	EA	6	6-10 years	



John C Burroughs Elementary School 3542 S Washtenaw AVENUE, Chicago, IL 60632

Catego	ry : Exterior		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	Fire Escape 3rd Floor - West	1	EA	6	6-10 years	
Fire Esca	•						
	Fire Escape	South and West	80	LF	6	6-10 years	
E a considerati							
Foundati	on Foundation - Masonry	Entire Building	652	LF	7	10	
	Superstructure - Heavy Timber	Entire Building	45,765	SF	7	10+ years 10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	3,426	SF	7	10+ years	
	Superstructure - Steel with Clay The Arch		3,420	36	'	IU+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Site	9	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Site	1	EA	7	6-10 years	Fixed.
	Exterior Lighting - Wall Mounted	Entire Site	17	EA	6	6-10 years	
Roof Sys	tem						
RUUI Sys	Access Ladder - Metal	A	1	EA	4	0-1 year	Ladder has a bounce, some of the
			-		-	- · · · ·	planking leading to it and around it it
							unsecure.
	Chimney - Brick Chimney- Concrete/ Mortar	A	72	LF	7	10+ years	Repaired
	Liner					2	•
	Coping - Terra Cotta	A	16	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	342	LF	5	0-1 year	Broken at bottom/rusting.
	Parapet - Parapet < 16" Height	А	12	LF	5	0-1 year	Open joints in masonry
	Roof - Asphalt Shingle	А	7,581	SF	6	6-10 years	
	Roof - Modified Bitumen	A	3,848	SF	6	6-10 years	
	Roof Hatch - Metal	A	0,040	EA	7	6-10 years	
		A	11,429	SF	7	10+ years	
	Roof Structure - Heavy Timber		,	LF			
	Coping - Stone	В	47		6	10+ years	
	Downspouts - Exterior Downspouts	В	10	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	В	47	LF	6	10+ years	
	Roof - Modified Bitumen	В	847	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	В	847	SF	7	10+ years	
	Coping - Stone	С	98	LF	6	10+ years	
	Parapet - Parapet < 16" Height	С	98	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	С	900	SF	6	2-5 years	
	Roof - Asphalt Gravel Ballast	С	300	SF	4	0-1 year	Soft spots in this area of the roof
	Roof Structure - Steel with Clay Tile Arch	C	1,200	SF	7	10+ years	
	Coping - Terra Cotta	D	7	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	D	7	LF	6	10+ years	
	Roof - Modified Bitumen	D	203	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	D	203	SF	7	10+ years	
	Coping - Terra Cotta	E	87	LF	6	6-10 years	



Catego	ry : Exterior		R	uilding	· Main		
Calego			J	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Downspouts - Exterior Downspouts	E	19	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	E	87	LF	6	10+ years	
	Roof - Modified Bitumen	E	1,225	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	E	1,225	SF	7	10+ years	
	Rooi Structure - Steel with Clay The Arch	L	1,225	51	1	TOF years	
Valls							
	Exterior Walls - Brick	Entire Building	19,007	SF	5	10+ years	Tuckpointing throughout.
	Exterior Walls - Brick	Entire Building	300	SF	4	0-1 year	Open joints at boiler house
	Exterior Walls - Stone-Cut	Entire Building	3,210	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	100	SF	4	0-1 year	Cracking and open joints.
	Exterior Walls - Terra Cotta	Entire Building	1,283	SF	6	10+ years	
Vindows	、 、						
VITICOWS	Guard - Guards perforated	Entire Building	903	SF	6	6-10 years	
	Lintels - Brick	Entire Building	362	LF	6	10+ years	
	Lintels - Steel	Entire Building	8	LF	6	10+ years	
	Lintels - Stone	Entire Building	173	LF	6		
			979	SF		10+ years	
	Windows - Insulated Panel	Entire Building			6	6-10 years	
	Windows - Louver	Entire Building	30	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,211	SF	7	6-10 years	Seals are in good condition
Catego	ry : Electrical	Entire Building		SF uilding		6-10 years	Seals are in good condition
	ry : Electrical	-	В	uilding	: Main	Recommend	-
Group	ry : Electrical Item - Type	Location					Comments
Group	ry : Electrical Item - Type ncy System	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	-
Group	ry : Electrical Item - Type ncy System Security System - CCTV	Location Entire Building	B Quantity 49,191	uilding UOM SF	: Main Rank	Recommend Replacement 6-10 years	-
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection	Location Entire Building Entire Building	Quantity 49,191 49,191	UOM SF SF	: Main Rank	Recommend Replacement 6-10 years 6-10 years	Comments
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs	Location Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21	UOM SF SF EA	5 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most.
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym	Location Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3	UOM SF SF EA EA EA	: Main Rank 5 5 5 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one.
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom	Location Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2	UOM SF SF EA EA EA EA	5 5 5 5 5 5 5 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most.
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and	Location Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3	UOM SF SF EA EA EA	: Main Rank 5 5 5 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one.
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom	Location Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2	UOM SF SF EA EA EA EA	5 5 5 5 5 5 5 5 5	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been
Group	ry : Electrical Item - Type ncy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs	Location Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2 21	UOM SF SF EA EA EA EA EA	5 5 5 5 5 5 5 6	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been divided/aggregated. Units and/or their protective cages
Group	ry : Electrical Item - Type Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Location Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2 21 1	UOM SF SF EA EA EA EA EA	5 5 5 5 5 6 6	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been divided/aggregated.
roup	ry : Electrical Item - Type nov System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Gym	Location Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2 21 1 4	UOM SF SF EA EA EA EA EA EA	Main Rank 5 5 5 5 5 6 6 6 2	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been divided/aggregated. Units and/or their protective cages are damaged.
iroup	ry : Electrical Item - Type nov System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Gym	Location Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2 21 1 4 2 21	UOM SF SF EA EA EA EA EA EA	Main Rank 5 5 5 5 5 6 6 2 6	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been divided/aggregated. Units and/or their protective cages are damaged. Quantity changed to match current
Group	ry : Electrical Item - Type Decy System Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and	Location Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 49,191 49,191 21 3 2 21 1 4 2 1 4 2 4	UOM UOM SF EA EA EA EA EA EA EA	Main Rank 5 5 5 5 5 6 6 2 6 6 6	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 6-10 years 6-10 years 6-10 years	Comments Lighting dimmed on most. Lighting dimmed on one. Lighting dimmed on one. Quantity changed as total has been divided/aggregated. Units and/or their protective cages are damaged. Quantity changed to match current



	Schools						S Washtenaw AVENUE, Chicago, IL 6063
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lain Se							
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	49,191	SF	5	6-10 years	Serves Main and Modular
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Quantity changed to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	6	6-10 years	Quantity set to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Panels are Above 100 A. Rank and RUL adjusted to match current observations.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	5	0-1 year	Step-up transformer serves air handler. Rusting.
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	6	10+ years	Serves Main only.
	Fire Alarm Strobe Lights	Mechanical Room	49,191	SF	6	10+ years	
	Fire Alarm_System	Mechanical Room	49,191	SF	6	10+ years	
	Fire Pump Controller	Mechanical Room	1	EA	6	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Basement	1	EA	6	10+ years	Corrosion caused by previous leaks
Sprinkle	System						
	Dry Sprinkler System	Entire Building	49,191	SF	6	10+ years	
	Sprinkler Heads	Entire Building	49,191	SF	7	10+ years	
	Sprinkler Piping	Entire Building	49,191	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Entire Building	1	EA	5	6-10 years	Serves main building.
				– •	-	0.40	

Air Intake

Auxiliaries - 25001 - 35000 cfm

Entire Building Entire Building

6-10 years 6-10 years

ΕA

ΕA

1

1

5

5



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Entire Building	100	LF	5	6-10 years	
	Zone Dampers	Entire Building	23	EA	6	6-10 years	Pneumatic system has been upgraded since last assessment and is fully operational.
Boiler Sy	/stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	10+ years	
	Chemical Feed System	Boiler Room	1	EA	5	10+ years	
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	Replaced since last assessment
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	10+ years	Both boilers have had repairs made.
	Steam- Low Pressure Boiler - 76 - 100 HP		E	L/\	U	lot youro	No leaks, fully operational.
	Piping - Condensate Pipe- Steel	Boiler Room	200	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	200	LF	5	10+ years	
	Steam Traps	Boiler Room	15	EA	5	6-10 years	
Heating	Devices						
	Fin Tube - Electric	Basement	24	LF	6	10+ years	Room 001, controlled by wall- mounted electric thermostat
	Fin Tube - Electric	Basement	24	LF	6	10+ years	Room 005, has integral thermostats
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	22	EA	5	10+ years	All units are fully operational. Quantity changed as total has been divided/aggregated.
	Wall Heater - Electric	Rooms LL Boys Toilert/2 of 3 in 002 and 2 in Engr Office and Toilet	4	EA	5	6-10 years	All units are fully operational.
	Wall Heater - Electric	Rooms LL Boys Toilert/2 of 3 in 002 and 2 in Engr Office and Toilet	4	EA	4	0-1 year	Covers missing.
	Radiators - Steam	Yard Storage	1	EA	5	6-10 years	
Tempera	ature Control						
-	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls fin tube
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls unit heater; missing its housing but still fully operational.
	Pneumatic System	Entire Building	49,191	SF	7	10+ years	Pneumatic system has been upgraded since last assessment and is fully operational.
	Thermostats - Pneumatic	Entire Building	21	EA	7	10+ years	Replaced since last assessment. Now fully operational with upgraded



Group

Category : Mechanical

Item - Type

Thermostats - Pneumatic

			3542	S Washtenaw AVENUE, Chicago, IL 60632
B	uilding	: Main		
Quantity	UOM	Rank	Recommend Replacement	Comments
2	EA	7	10+ years	pneumatic system. Replaced since last assessment. Now fully operational with upgraded pneumatic system.
1	EA	5	6-10 years	Above MDF Room door. Disabled

Building : Main

Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	Above MDF Room door. Disabled and blocked.
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	Above stove in break room. No fire suppression. Residential style.
Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	

Location

Entire Building

Category : Plumbing

	. ,						
_			• • • •			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	49,191	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	49,191	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	49,191	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	49,191	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	49,191	SF	6	10+ years	
	(Risers)			~-	-		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	49,191	SF	6	10+ years	
	(from Risers to Fixtures)		10.101	05	0	10	
	Sanitary Piping	Entire Building	49,191	SF	6	10+ years	
	Storm Piping	Entire Building	49,191	SF	5	6-10 years	
	Vent Piping	Entire Building	49,191	SF	6	10+ years	
_							
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	6-10 years	



Catego	ory : Room		В	uilding	: Main		
Ū						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	1st Floor Teachers Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Teachers Room	336	SF	6	10+ years	
	Doors - Transom Window	1st Floor Teachers Room	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Teachers Room	1	EA	6	10+ years	
	Floor - Tile	1st Floor Teachers Room	332	SF	6	10+ years	
	Floor - Tile	1st Floor Teachers Room	4	SF	4	0-1 year	Cracked.
	Lighting - Pendent/Surface	1st Floor Teachers Room	5	EA	7	6-10 years	
	Power Distribution	1st Floor Teachers Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Teachers Room	1,040	SF	6	10+ years	
	Work SInk	1st Floor Teachers Room	, 1	EA	7	10+ years	
	Ceiling - Exposed	Engineers Office	392	SF	6	10+ years	Paint peeling on vents.
	Doors - Wood Doors inclu hw	Engineers Office	1	EA	6	10+ years	5
	Floor - Tile/Sheet	Engineers Office	392	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineers Office	3	EA	7	6-10 years	
	Power Distribution	Engineers Office	8	EA	7	10+ years	
	Storage/ Closet	Engineers Office	196	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineers Office	840	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym office / 303	360	SF	6	10+ years	
	Doors - Transom Window	Gym office / 303	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym office / 303	2	ĒA	6	10+ years	
	Floor - Wood	Gym office / 303	360	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym office / 303	5	EA	7	6-10 years	
	Power Distribution	Gym office / 303	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym office / 303	1,092	SF	6	10+ years	
	AC Unit	Main office - room 107	· 1	EA	7	6-10 years	
	Ceiling - Lay-in	Main office - room 107	406	SF	7	10+ years	
	Doors - Transom Window	Main office - room 107	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main office - room 107	2	EA	6	10+ years	
	Floor - Wood	Main office - room 107	406	SF	6	10+ years	
	Lighting - Lay-in	Main office - room 107	6	EA	7	6-10 years	
	Power Distribution	Main office - room 107	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Main office - room 107	946	SF	6	10+ years	
	AC Unit	Principals Office - Room 108	1	EA	7	6-10 years	
	Ceiling - Splined	Principals Office - Room 108	1,938	SF	6	10+ years	
	Doors - Transom Window	Principals Office - Room 108	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principals Office - Room 108	1	ĒA	6	10+ years	
	Floor - Wood	Principals Office - Room 108	1,938	SF	6	10+ years	
	Lighting - Pendent/Surface	Principals Office - Room 108	4	EA	7	6-10 years	
	Power Distribution	Principals Office - Room 108	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals Office - Room 108	504	SF	7	10+ years	
	Ceiling - Exposed	Room 005 - A	297	SF	6	10+ years	
	Dears Transam Mindaw			0	7	10	

Doors - Transom Window

Floor - Tile/Sheet

3

297

SF

SF

7

5

Room 005 - A

Room 005 - A

10+ years

6-10 years



			_			3542	S Washtenaw AVENUE, Chicago, IL 60632
Catego	ry : Room		В	Building : Main			
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Room 005 - A	3	EA	7	6-10 years	
	Power Distribution	Room 005 - A	4	EA	7	6-10 years	
	Walls - Masonry	Room 005 - A	490	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 005 - A	270	SF	6	10+ years	
	Ceiling - Exposed	Room 005 B	140	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Room 005 B	140	SF	5	6-10 years	
	Lighting - Pendent/Surface	Room 005 B	2	EA	7	6-10 years	
	Power Distribution	Room 005 B	4	EA	7	10+ years	
	Walls - Masonry	Room 005 B	140	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 005 B	350	SF	6	10+ years	Paint/wallpaper peeling off.
	AC Unit	Room 103 / Storage	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 103 / Storage	382	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Room 103 / Storage	10	SF	5	0-1 year	Water damage.
	Doors - Transom Window	Room 103 / Storage	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 103 / Storage	1	EA	6	10+ years	
	Floor - Wood	Room 103 / Storage	392	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 103 / Storage	5	EA	7	6-10 years	
	Power Distribution	Room 103 / Storage	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 103 / Storage	474	SF	6	6-10 years	
	Walls - Plaster/Drywall	Room 103 / Storage	10	SF	5	0-1 year	Water damage.
Cumpoo	io						
Gymnas	Ceiling - Plaster/Drywall	3rd Floor	3,346	SF	6	101 years	
	Ceiling - Plaster/Drywall	3rd Floor	3,340	SF	6 4	10+ years	Water demoge
	Doors - Transom Window	3rd Floor	36	SF	4	0-1 year 10+ years	Water damage.
	Doors - Wood Doors inclu hw	3rd Floor	5	EA	6	10+ years	
	Floor - Wood	3rd Floor	3,354	SF	6	10+ years	
		3rd Floor		EA	7		
	Lighting - Metal Halide/ High Pressure Sodium	310 F1001	13	EA	1	6-10 years	
	Stage	3rd Floor	860	SF	7	10+ years	
	Stage Curtain	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,324	SF	6	10+ years	
	Walls - Flaster/Drywall	310 11001	5,524	36	0	10+ years	
Library							
,	AC Unit	Room 305	2	EA	7	6-10 years	
	Casework	Room 305	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 305	1,008	SF	6	10+ years	Paint cracking and peeling.
	Doors - Steel Doors incl hw	Room 305	1	EA	6	10+ years	6 1 1 2
	Doors - Transom Window	Room 305	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 305	2	EA	6	10+ years	
	Floor - Wood	Room 305	1,008	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 305	15	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 305	1,664	SF	6	10+ years	Paint cracking and peeling.
	· · · · · · · · · · · · · · · · · · ·		.,	2.	-	, , , , , , , , , , , , , , , , , , , ,	



atego	ry : Room		В	uilding	: Main			
						Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
unch &	Multipurpose Room							
	Ceiling - Plaster/Drywall	102	1,087	SF	6	10+ years		
	Doors - Transom Window	102	1	SF	7	10+ years		
	Doors - Wood Doors inclu hw	102	2	EA	7	10+ years		
	Floor - Tile	102	561	SF	7	10+ years		
	Floor - Tile	102	163	SF	4	0-1 year	Missing/damaged.	
	Floor - Tile Quarry	102	363	SF	6	10+ years	6 6	
	Lighting - Pendent/Surface	102	15	EA	7	6-10 years		
	Serving Line	102	18	LF	7	10+ years		
	Walls - Plaster/Drywall	102	1,560	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Public Room-Social Work (in	445	SF	6	10+ years		
	Centrig - Flaster/Drywall	basement/girls' play room)		01	0	TO+ years		
	Ceiling - Plaster/Drywall	Public Room-Social Work (in	80	SF	5	0-1 year	Water damage.	
	Cenning - Flaster/Drywan	basement/girls' play room)	00	36	5	0-1 year	Water Gamage.	
	Doors - Wood Doors inclu hw		2	EA	7	10		
	Doors - wood Doors Inclu nw	Public Room-Social Work (in	2	EA	7	10+ years		
		basement/girls' play room)	505	05	0	0.40		
	Floor - Tile	Public Room-Social Work (in	525	SF	6	6-10 years		
		basement/girls' play room)	-		-			
	Lighting - Pendent/Surface	Public Room-Social Work (in	6	EA	6	6-10 years		
		basement/girls' play room)			_			
	Walls - Masonry	Public Room-Social Work (in	460	SF	7	6-10 years		
		basement/girls' play room)						
	Walls - Plaster/Drywall	Public Room-Social Work (in	460	SF	6	6-10 years		
		basement/girls' play room)						
1DF ID	E							
שו_וש	Doors - Steel Doors incl hw	3rd Next to library	1	EA	6	10+ years		
	Finishes	3rd Next to library	138	SF	7	10+ years		
	Window AC Unit	3rd Next to library	1	EA	7	6-10 years		
		Sid Next to library	I	LA	1	0-10 years		
1echani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	24	SF	7	10+ years		
	Air Tunnel	Basement	606	SF	7	10+ years		
	Boiler Room	Basement	1,248	SF	5	10+ years	Flooring worn, paint cracking and peeling on masonry wall.	
	Janitor's Closet	Basement	72	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	64	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	170	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	630	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	624	SF	5	10+ years		
	Storage Room	Basement	1,083	SF	5	10+ years		

Restroom



Catego	ry : Room		B	uilding	· Main	0072	S Washtenaw AVENUE, Chicago, IL 60632
oalego				unung	. Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cicup	Accessories	2nd floor boys	112	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys	112	SF	6	10+ years	Paint chipping and peeling.
	Doors - Wood Doors inclu hw	2nd floor boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	112	SF	7	10+ years	
	Floor Drain	2nd floor boys	1	ĒA	7	10+ years	
	Hand Dryer	2nd floor boys	1	EA	7	6-10 years	
	Lavatory	2nd floor boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor boys	3	EA	7	6-10 years	
	Partitions	2nd floor boys	1	EA	7	10+ years	
	Urinals	2nd floor boys	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor boys	396	SF	7	10+ years	
	Water Closet	2nd floor boys	1	EA	7	10+ years	
	Accessories	2nd floor girls	136	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls	136	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls	136	SF	7	10+ years	
	Floor Drain	2nd floor girls	1	EA	7	10+ years	
	Hand Dryer	2nd floor girls	1	EA	7	6-10 years	
	Lavatory	2nd floor girls	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor girls	3	EA	7	6-10 years	
	Partitions	2nd floor girls	3	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor girls	450	SF	7	10+ years	
	Water Closet	2nd floor girls	3	EA	7	10+ years	
	Accessories	2nd floor men's	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor men's	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor men's	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor men's	25	SF	7	10+ years	
	Lavatory	2nd floor men's	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor men's	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor men's	45	SF	5	0-1 year	Wall pushed in/dented near water closet.
	Water Closet	2nd floor men's	1	EA	7	10+ years	
	Accessories	2nd floor teachers	324	SF	7	6-10 years	
		restroom/Teacher's lounge toilet					
	Ceiling - Plaster/Drywall	2nd floor teachers	324	SF	7	10+ years	
		restroom/Teacher's lounge toilet					
	Doors - Transom Window	2nd floor teachers	9	SF	7	10+ years	
		restroom/Teacher's lounge toilet					
	Doors - Wood Doors inclu hw	2nd floor teachers	2	EA	7	10+ years	
		restroom/Teacher's lounge toilet					
	Floor - Tile	2nd floor teachers	324	SF	4	0-1 year	Cracking throughout.
		restroom/Teacher's lounge toilet					
	Lavatory	2nd floor teachers	1	EA	7	10+ years	
		restroom/Teacher's lounge toilet					



Catego	ory : Room		В	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd floor teachers	4	EA	6	6-10 years	
		restroom/Teacher's lounge toilet					
	Partitions	2nd floor teachers	2	EA	7	10+ years	
		restroom/Teacher's lounge toilet			_		
	Walls - Plaster/Drywall	2nd floor teachers	1,326	SF	7	10+ years	
		restroom/Teacher's lounge toilet	0	Ξ.	-	40	
	Water Closet	2nd floor teachers	2	EA	7	10+ years	
	Accessories	restroom/Teacher's lounge toilet	C / F	SF	7	6 10 10000	
	Accessories	Boys Restroom - Basement	645	SF		6-10 years	Daint abinning and pooling
	Ceiling - Exposed Doors - Wood Doors inclu hw	Boys Restroom - Basement Boys Restroom - Basement	645 1	EA	6 7	10+ years 10+ years	Paint chipping and peeling.
	Floor - Concrete Epoxy/ Painted	Boys Restroom - Basement	645	SF	7	10+ years	
	Floor Drain	Boys Restroom - Basement	1	EA	7	10+ years	
	Hand Dryer	Boys Restroom - Basement	2	EA	7	6-10 years	
	Lavatory	Boys Restroom - Basement	3	EA	6	10+ years	
	Lavatory	Boys Restroom - Basement	1	EA	5	1-2 years	
	Lighting - Pendent/Surface	Boys Restroom - Basement	12	EA	6	6-10 years	
	Partitions	Boys Restroom - Basement	4	EA	5	6-10 years	
	Urinals	Boys Restroom - Basement	10	EA	7	10+ years	
	Walls - Masonry	Boys Restroom - Basement	768	SF	7	10+ years	
	Walls - Plaster/Drywall	Boys Restroom - Basement	512	SF	6	6-10 years	
	Water Closet	Boys Restroom - Basement	4	EA	6	10+ years	
	Accessories	Engineers Office	42	SF	7	6-10 years	
	Ceiling - Exposed	Engineers Office	42	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Engineers Office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Engineers Office	42	SF	5	10+ years	
	Lavatory	Engineers Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineers Office	1	EA	7	6-10 years	
	Walls - Masonry	Engineers Office	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineers Office	60	SF	6	10+ years	
	Water Closet	Engineers Office	1	EA	7	10+ years	
	Accessories	Girls Restroom - Basement	590	SF	7	6-10 years	
	Ceiling - Exposed	Girls Restroom - Basement	590	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Restroom - Basement	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Girls Restroom - Basement	590	SF	5	10+ years	
	Floor Drain	Girls Restroom - Basement	1 2	EA	7 7	10+ years 6-10 years	
	Hand Dryer	Girls Restroom - Basement	2	EA EA	7	6-10 years 6-10 years	
	Lavatory Lighting - Pendent/Surface	Girls Restroom - Basement Girls Restroom - Basement	4	EA	6	6-10 years	
	Partitions	Girls Restroom - Basement	12	EA	7	10+ years	
	Walls - Concrete Block	Girls Restroom - Basement	768	SF	7	10+ years	
	Walls - Plaster/Drywall	Girls Restroom - Basement	512	SF	6	10+ years	
	Water Closet	Girls Restroom - Basement	12	EA	7	10+ years	
	Accessories	Janitor's Restroom	28	SF	7	6-10 years	
	7.00000100		20	51	'	o io youis	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	Janitor's Restroom	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Janitor's Restroom	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Janitor's Restroom	28	SF	5	10+ years	
	Lavatory	Janitor's Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Janitor's Restroom	1	EA	6	6-10 years	
	Walls - Masonry	Janitor's Restroom	110	SF	5	0-1 year	Chipping/cracking, paint chipping and peeling.
	Walls - Plaster/Drywall	Janitor's Restroom	110	SF	6	10+ years	Paint cracking and peeling.
	Water Closet	Janitor's Restroom	1	EA	7	10+ years	
	Accessories	RR in 104 (Wardrobe)	40	SF	7	10+ years	
	Ceiling - Plaster/Drywall	RR in 104 (Wardrobe)	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	RR in 104 (Wardrobe)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	RR in 104 (Wardrobe)	40	SF	6	10+ years	
	Lavatory	RR in 104 (Wardrobe)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	RR in 104 (Wardrobe)	1	EA	5	6-10 years	
	Partitions	RR in 104 (Wardrobe)	1	EA	7	10+ years	
	Walls - Plaster/Drywall	RR in 104 (Wardrobe)	250	SF	6	10+ years	
	Water Closet	RR in 104 (Wardrobe)	1	EA	6	10+ years	
	Accessories	RR inside 101 (Wardrobe)	20	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	RR inside 101 (Wardrobe)	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	RR inside 101 (Wardrobe)	1	EA	6	10+ years	
	Floor - Tile	RR inside 101 (Wardrobe)	20	SF	6	10+ years	
	Lavatory	RR inside 101 (Wardrobe)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	RR inside 101 (Wardrobe)	1	EA	6	6-10 years	
	Partitions	RR inside 101 (Wardrobe)	1	EA	7	10+ years	
	Walls - Plaster/Drywall	RR inside 101 (Wardrobe)	100	SF	6	10+ years	
	Water Closet	RR inside 101 (Wardrobe)	1	EA	6	10+ years	

Catego	Category : Classroom			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	om #001 (Pre School)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,015	SF	6	6-10 years	Paint peeling pretty bad on vents.
	Chalk Board	Basement	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	1,015	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	18	EA	7	6-10 years	
	Walls - Masonry	Basement	988	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	312	SF	6	10+ years	Paint clumping near marker board - needs to be sanded.

Classroom #005 (Special Education)



Catego	ry : Classroom		В	uilding	: Main		
Ŭ				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	500	SF	6	10+ years	Paint cracking and peeling.
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	500	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Masonry	Basement	510	SF	6	6-10 years	Paint cracking and peeling at lowe portion of walls.
	Walls - Plaster/Drywall	Basement	210	SF	6	6-10 years	Paint cracking and peeling at lowe portion of walls.
	Work Sink	Basement	1	EA	7	6-10 years	
assroc	om #006 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	650	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	15	SF	5	0-1 year	Water damage along edges.
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	665	SF	4	0-1 year	Separating and chipping.
	Lighting - Pendent/Surface	Basement	8	EA	6	6-10 years	
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Masonry	Basement	750	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	350	SF	6	10+ years	
assroc	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,295	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	Repaired
	Floor - Wood	1st Floor	1,295	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	196	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,612	SF	7	10+ years	
assroc	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,176	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



αισχυ	ry : Classroom		P	uilding	• Main		S Washtenaw AVENUE, Chicago, IL 606
	iy. Glassi Oolii		D	unung		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oup	Floor - Wood	1st Floor	1,176	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	168	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,664	SF	7	10+ years	
	Work Sink	1st Floor	1,001	EA	7	10+ years	
assroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,038	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	5	0-1 year	Water damage.
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	1.053	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	132	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,545	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	15	SF	5	0-1 year	Water damage.
assroo	m #106 (Regular Classroom) AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6		6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor		SF	6	6-10 years	Detabling throughout point poodos
		1st Floor	1,054	SF			Patching throughout, paint needed
	Ceiling - Plaster/Drywall Chalk Board	1st Floor	10 28	LF	5 4	0-1 year	Cracking.
	Doors - Transom Window			SF		2-5 years	
		1st Floor 1st Floor	9	EA	6	10+ years	
	Doors - Wood Doors inclu hw		3		6	10+ years	
	Floor - Wood	1st Floor 1st Floor	1,064	SF EA	6 7	10+ years	
	Lighting - Pendent/Surface		15 168	SF		6-10 years	
	Storage/ Closet	1st Floor		SF	7 7	10+ years	Doint prophing and popling
	Walls - Plaster/Drywall	1st Floor	1,560	ЪГ	/	10+ years	Paint cracking and peeling throughout.
assroc	m #201 (Pre School)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,189	SF	6	10+ years	
			18	LF	4	2-5 years	
	Chalk Board	2nd Floor	10				
		2nd Floor 2nd Floor				•	
	Chalk Board	2nd Floor 2nd Floor 2nd Floor	9	SF EA	6 6	10+ years 10+ years	



	ory : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,280	SF	7	10+ years	
Classroo	om #202 (Science Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	31	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,185	SF	6	10+ years	Paint cracking and peeling throughout.
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	5
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	6	10+ years	
	Floor - Wood	2nd Floor	1,189	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,664	SF	7	10+ years	Minor paint chipping and peeling
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
		2nd Floor 2nd Floor	6 1,189	LF SF	6 7	10+ years 10+ years	
	Casework Ceiling - Lay-in Chalk Board					10+ years	
	Ceiling - Lay-in	2nd Floor	1,189 34	SF LF	7	10+ years 2-5 years	
	Ceiling - Lay-in Chalk Board	2nd Floor 2nd Floor	1,189	SF	7 4	10+ years 2-5 years 10+ years	
	Ceiling - Lay-in Chalk Board Doors - Transom Window	2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2	SF LF SF	7 4 6	10+ years 2-5 years 10+ years 10+ years	
	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189	SF LF SF EA SF	7 4 6 6	10+ years 2-5 years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2	SF LF SF EA SF EA	7 4 6 6 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	
	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4	SF LF SF EA SF EA LF	7 4 6 6 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15	SF LF SF EA SF EA	7 4 6 6 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	Minor paint chipping and peeling.
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139	SF LF EA SF EA LF SF	7 6 6 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Minor paint chipping and peeling.
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139	SF LF EA SF EA LF SF	7 6 6 7 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Minor paint chipping and peeling
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280	SF LF EA SF EA LF SF SF	7 4 6 6 7 7 6	10+ years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Minor paint chipping and peeling.
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall om #204 (Special Education) AC Units Casework	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280	SF LF EA SF EA LF SF SF EA	7 4 6 6 7 7 6 7	10+ years 2-5 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall Dm #204 (Special Education) AC Units	2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280	SF LF SF EA LF SF SF EA LF	7 4 6 6 7 7 6 7 6	10+ years 2-5 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Minor paint chipping and peeling.
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall Dom #204 (Special Education) AC Units Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280	SF LF SF EF SF EA LF SF LF LF	7 4 6 6 7 7 6 7 6 4	10+ years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 2-5 years	
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall Dom #204 (Special Education) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280 1,280	SF LF SA LF SF EA LF SF LF SF	7 4 6 6 7 7 6 7 6 4 6	10+ years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 2-5 years 10+ years	
Classro	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall om #204 (Special Education) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280 1,280	SF LF EA LF SF EA LF SF LF SF LF SF	7 4 6 6 7 7 6 7 6 4 6 4 6 6	10+ years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years	
Classroo	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall Dom #204 (Special Education) AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	1,189 34 70 2 1,189 15 4 139 1,280 1,280 1,280	SF LF SA LF SF EA LF SF LF SF	7 4 6 6 7 7 6 7 6 4 6	10+ years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years 2-5 years 10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,664	SF	6	10+ years	Paint cracking and peeling.
lassroo	om #205 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,062	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,280	SF	7	10+ years	Paint cracking and peeling.
	Walls - Plaster/Drywall	2nd Floor	4	SF	4	0-1 year	Water damage.
lassroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,189	SF	6	10+ years	One ceiling tile pushed up.
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,189	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,280	SF	6	10+ years	
lassroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,146	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,146	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,664	SF	6	10+ years	

Classroom #302 (Regular Classroom)



Catego	ry : Classroom			3542 S Washtenaw AVENU Building : Main				
Jaleyo				unung	. wam	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
noup	AC Units	3rd Floor	2	EA	7	6-10 years	Commente	
	Casework	3rd Floor	5	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	1,146	SF	6	10+ years		
	Chalk Board	3rd Floor	20	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	20	EA	6	10+ years		
	Floor - Wood	3rd Floor	1,146	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years		
	Marker Board	3rd Floor	16		6	6-10 years		
	Storage/ Closet	3rd Floor	138	SF	7	10+ years		
		3rd Floor		SF	6			
	Walls - Plaster/Drywall	310 FI001	1,664	55	0	10+ years		
assroo	om #306 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	5	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	1,146	SF	6	10+ years		
	Chalk Board	3rd Floor	28	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Wood	3rd Floor	1,146	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	6	6-10 years		
	Storage/ Closet	3rd Floor	138	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,664	SF	6	10+ years		
aterro	ry : Interior		B	uilding	• Main			
alogo				anang	. mann	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
orridor								
	Ceiling - Plaster/Drywall	1st floor, #1	1,460	SF	6	10+ years		
	Doors - Transom Window	1st floor, #1	64	SF	7	10+ years		
	Doors - Wood Doors include hw	1st floor, #1	4	EA	6	10+ years		
	Floor - Wood	1st floor, #1	1,460	SF	7	10+ years		
	Lighting - Pendent/Surface	1st floor, #1	24	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st floor, #1	1,950	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor, #2	1,060	SF	7	10+ years		
	Doors - Transom Window	2nd Floor, #2	96	SF	7	10+ years		
	Doors - Wood Doors include hw	2nd Floor, #2	6	EA	6	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor, #2	2	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor, #2	1,060	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor, #2	22	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor, #2	2,150	SF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor #3	400	SF	7	10+ years		
	Doors Transom Window	3rd Floor #3	19	SE.	6	101 years		

Doors - Transom Window

Doors - Wood Doors include hw

3rd Floor #3

3rd Floor #3

18

2

SF

ΕA

6

6

10+ years

10+ years



Category : Interior			В	uildina	Building : Main				
j-	· · · · · · · · · · · · · · · · · · ·				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Concrete Epoxy/ Painted	3rd Floor #3	400	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor #3	5	EA	6	6-10 years			
	Walls - Plaster/Drywall	3rd Floor #3	1,014	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd floor, #4	224	SF	6	10+ years			
	Doors - Transom Window	3rd floor, #4	1	SF	7	10+ years			
	Doors - Wood Doors include hw	3rd floor, #4	2	EA	7	10+ years			
	Floor - Tile/Sheet	3rd floor, #4	224	SF	5	10+ years			
	Lighting - Pendent/Surface	3rd floor, #4	4	EA	6	6-10 years			
	Walls - Plaster/Drywall	3rd floor, #4	715	SF	6	10+ years			
	Ceiling - Exposed	Basement 1	812	SF	6	10+ years			
	Doors - Wood Doors include hw	Basement 1	2	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement 1	812	SF	5	10+ years			
	Lighting - Pendent/Surface	Basement 1	7	EA	7	6-10 years			
	Walls - Masonry	Basement 1	1,600	SF	6	10+ years			
	Ceiling - Exposed	Basement 2	282	SF	6	10+ years			
	Ceiling - Exposed	Basement 2	30	SF	4	0-1 year	Water damage.		
	Drinking Fountains - Double Fountain	Basement 2	2	EA	4 7	10+ years	Water damage.		
	Floor - Concrete Epoxy/ Painted		312	SF	7				
		Basement 2	5	EA	6	10+ years 6-10 years			
	Lighting - Pendent/Surface Walls - Masonry	Basement 2 Basement 2	550	SF	6	•			
	Walls - Masonry Walls - Plaster/Drywall			SF	6	10+ years			
		Basement 2	700			10+ years			
	Ceiling - Exposed	Vestibule #1	24	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Vestibule #1	24	SF	5	10+ years			
	Lighting - Pendent/Surface	Vestibule #1	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Vestibule #1	56	SF	6	6-10 years			
	Ceiling - Exposed	Vestibule #2	24	SF	6	10+ years			
	Doors - Wood Doors include hw	Vestibule #2	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Vestibule #2	24	SF	6	10+ years			
	Lighting - Pendent/Surface	Vestibule #2	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	Vestibule #2	56	SF	7	10+ years			
	Ceiling - Exposed	Vestibule #3	48	SF	7	10+ years			
	Doors - Steel Doors incl hw	Vestibule #3	120	EA	6	6-10 years			
	Doors - Wood Doors include hw	Vestibule #3	3	EA	7	10+ years			
	Floor - Concrete	Vestibule #3	48	SF	5	6-10 years			
	Lighting - Pendent/Surface	Vestibule #3	1	EA	6	6-10 years			
	Walls - Concrete Block	Vestibule #3	48	SF	7	10+ years			
	Walls - Masonry	Vestibule #3	88	SF	6	10+ years			
afety									
<u></u>	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	3	EA	7	6-10 years			
tairs									
	Ceiling - Plaster/Drywall	#1	325	SF	6	10+ years			



Catego	ry : Interior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	#1	26	SF	7	10+ years	
	Handrails	#1	28	LF	7	10+ years	
	Lighting - Pendent/Surface	#1	4	EA	7	6-10 years	
	Stairs - Rubber	#1	338	LF	6	10+ years	
	Walls - Plaster/Drywall	#1	650	SF	6	10+ years	
	Ceiling - Exposed	#2	180	SF	6	10+ years	
	Ceiling - Plaster/Drywall	#2	360	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	#2	80	SF	7	10+ years	
	Floor - Epoxy/ Painted	#2	180	SF	7	10+ years	
	Handrails	#2	99	LF	7	10+ years	
	Lighting - Pendent/Surface	#2	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	#2	3	EA	5	6-10 years	
	Stairs - Rubber	#2	360	LF	6	10+ years	
	Walls - Plaster/Drywall	#2	3,888	SF	6	10+ years	
	Ceiling - Exposed	#3	180	SF	7	10+ years	
	Ceiling - Plaster/Drywall	#3	360	SF	6	10+ years	
	Floor - Tile	#3	80	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	#3	360	SF	7	10+ years	
	Handrails	#3	99	LF	7	10+ years	
	Lighting - Pendent/Surface	#3	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	#3	3	EA	5	6-10 years	
	Stairs - Rubber	#3	180	LF	7	10+ years	
	Walls - Plaster/Drywall	#3	3,888	SF	6	10+ years	



Catego	ry : Exterior	В	Building : Modular 1 (4-Classroom)					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group		LUCATION	Quantity		Rank	Replacement	Comments	
Entrance	Exterior Doors - Exterior Steel Door	4 - East	2	EA	5	0-1 year	Doors and frame are rusting	
	Exterior Doors - Exterior Steel Door	5 - West	2	EA	5 5	0-1 year	Doors and frame are rusting	
	Ramps - Concrete	5 - West	40	LF	7	10+ years	Doors and frame are rusting	
	Namps - Obliciete	5 - West	-0		'	TO+ years		
Foundati	ion							
	Foundation - Concrete	Entire Building	246	LF	7	10+ years		
	Foundation - Concrete	Entire Building	10	LF	5	0-1 year	Cracking.	
	Superstructure - Metal Deck/ Concrete	Entire Building	4,060	SF	7	10+ years		
	Topping							
Lighting								
-0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	6-10 years		
Roof Sys	stem							
,	Coping - Metal	F	256	LF	6	2-5 years		
	Downspouts - Exterior Downspouts	F	84	LF	6	10+ years		
	Roof - EPDM/ Synthetic Rubber	F	4,060	SF	4	0-1 year	Roof shows areas of ponding.	
	Roof Structure - Steel / Metal Deck/	F	4,060	SF	7	10+ years		
	Concrete Topping							
Walls								
	Exterior Walls - Hardie Board	Entire Building	2,356	SF	6	6-10 years		
	Exterior Walls - Hardie Board	Entire Building	300	SF	4	0-1 year	Trim is decayed or missing at bottom	
							of the walls.	
Windows	3							
	Guard - Guards wire guard	Entire Building	288	SF	6	2-5 years	Needs scrape and paint, parts of the guard are rusting.	
	Lintels - Steel	Entire Building	48	LF	6	10+ years	guard are rusting.	
	Windows - Sash Aluminum Double-pane	Entire Building	288	SF	6	6-10 years		
Catego	ry : Electrical		В	uildina	: Modul	ar 1 (4-Classro	om)	
	· · · · · · · · · · · · · · · · · · ·			_		Recommend	·	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System							
Ũ	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years		
	Emergency Battery Packs - Corridors and	Entire Building	2	EA	6	6-10 years		
	Stairs	5						



Catego	ry : Electrical	Building : Modular 1 (4-Classroom)						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lain Se								
	PA System Main Electrical Service - 800 A and 120/208/3PH	Entire Building Outside Facade	4,060 1	SF EA	5 6	6-10 years 10+ years	Served by Main	
Power D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years		
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	oom)	
Ŭ				Ŭ		Recommend	,	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m							
	Fire Alarm_System	1st Floor	4,060	SF	5	1-2 years	No pull stations; activation of the sprinkler system triggers horns and alarm bells per Building Engineer.	
Sprinkler	System							
-	Sprinkler Heads	Entire Building	4,060	SF	7	10+ years		
	Sprinkler Piping	Entire Building	4,060	SF	6	10+ years		
	Wet Sprinkler System	Entire Building	4,060	SF	6	10+ years		
- note	ry : Mechanical		в	uilding	· Modul	ar 1 (A-Classro	oom)	
Jalego	ry . Mechanical		Building : Modular 1 (4-Classroom) Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	ture Control		· · · · · · · · · · · · · · · · · · ·					
I	Electric Thermostat	Entire Building	4	EA	6	6-10 years	Controls Unit Ventilator	
		-				-		
Jnit Ven								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	4	EA	5	6-10 years		
/entilatio	n							
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	6	EA	6	6-10 years		
Category : Plumbing		В	uilding	: Modul	ar 1 (4-Classro	om)		
	Hanna Tama	Leastlen	0 11		D . 1	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate		Machanical Deem	A	۲ ۸		6 10		
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years		



Group

Piping

Category : Plumbing

Item - Type

 Building : Modular 1 (4-Classroom)

 Recommend

 Quantity
 UOM
 Rank
 Replacement
 Comments

 4,060
 SF
 6
 10+ years

0	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building Entire Building	4,060 4,060	SF SF	6 6	10+ years 10+ years
	Sanitary Piping	Entire Building	4,060	SF	6	10+ years
	Storm Piping	Entire Building	4,060	SF	6	10+ years
	Vent Piping	Entire Building	4,060	SF	6	10+ years

Location

Catego	ry : Classroom		Building : Modular 1 (4-Classroom)							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroo	m #995 (Regular Classroom)									
	Ceiling - Lay-in	1st Floor	621	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
	Floor - Tile	1st Floor	621	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	49	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	800	SF	6	10+ years				
Classroo	m #996 (Regular Classroom)									
	Ceiling - Lay-in	1st Floor	621	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	7	10+ years				
	Floor - Tile	1st Floor	621	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	49	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	800	SF	6	10+ years				
Classroo	m #997 (Regular Classroom)									
	Ceiling - Lay-in	1st Floor	621	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
	Floor - Tile	1st Floor	621	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	ĒA	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	49	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	800	SF	7	10+ years				
Classroo	m #998 (Regular Classroom)									
	Ceiling - Lay-in	1st Floor	621	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years				
	Floor - Tile	1st Floor		SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years				
	0 0 -9				-					



Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	49	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	800	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	om)
Ū				Ū		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	Sprinkler/Janitor Room	52	SF	5	10+ years	2 SF of floor tile missing.
Restroor	n						
	Accessories	Boys	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys	192	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys	1	ĒA	7	10+ years	
	Floor - Tile	Boys	192	SF	6	10+ years	
	Hand Dryer	Boys	1	EA	7	6-10 years	
	Lavatory	Boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys	2	EA	7	6-10 years	
	Partitions	Boys	1	EA	7	10+ years	
	Urinals	Boys	3	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Boys	608	SF	7	10+ years	
	Water Closet	Boys	1	EA	7	10+ years	
	Accessories	Girls	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls	192	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls	1	EA	7	10+ years	
	Floor - Tile	Girls	192	SF	6	10+ years	
	Hand Dryer	Girls	1	EA	7	6-10 years	
	Lavatory	Girls	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls	2	EA	7	6-10 years	
	Partitions	Girls	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Girls	608	SF	7	10+ years	
	Water Closet	Girls	4	EA	7	10+ years	

Category : Interior

Building : Modular 1 (4-Classroom)

Group Corridor	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	Corridor - Modular	548	SF	7	10+ years	
	Drinking Fountains - Single Fountain	Corridor - Modular	2	EA	7	10+ years	
	Floor - Tile/Sheet	Corridor - Modular	548	SF	7	10+ years	
	Lighting - Lay-in	Corridor - Modular	8	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Corridor - Modular	1,168	SF	7	10+ years	



Category : Site			В	uilding			
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	4	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	6-10 years	
Fencina							
0	Fencing - New Standard Ornamental	Entire Site	1,014	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	48	LF	4	0-1 year	Pieces missing.
andsca	De						
	Benches	Entire Site	6	EA	5	0-1 year	Rusting.
	Irrigation	Entire Site	6,058	SF	4	0-1 year	Not working.
	Landscape - Grass	Entire Site	100	SF	7	10+ years	Repaired
	Landscape - Grass	Entire Site	5,958	SF	6	10+ years	-
	Landscape - Hardscape- Concrete	Entire Site	13,150	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	9	ĒA	6	10+ years	
	Parkway trees	Entire Site	19	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	3,302	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	14,850	SF	7	6-10 years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
			Ŭ	2/1	0	o to youro	
Parking							
	Concrete Curbs	Entire Site	554	LF	6	10+ years	
	Interior Plantings	Entire Site	18	LF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	3	EA	6	6-10 years	
	Surface - Asphalt	Entire Site	8,276	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	300	SF	4	0-1 year	Potholes, alligator surface.
	Trash Compactor	Entire Site	1	EA	6	6-10 years	
	Trash Enclosure - Chain Links	Entire Site	286	SF	6	6-10 years	
	Vehicular Screening	Entire Site	265	LF	6	10+ years	Prune bushes
Playgrou	nd						
	Equipment - Combo 3-12	Northwest	1	EA	7	10+ years	Repaired 2020.
	Surface - Poured Surface	Northwest	3,256	SF	7	10+ years	Repaired 2020.
Sidewalk	S						
	Sidewalks - Perimeter Sidewalks	Entire Site	11,053	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	25	SF	4	0-1 year	Cracking.
Signage							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	5	6-10 years	Missing flag.



Category : Site			В					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	· · · · · · · · · · · · · · · · · · ·	1							
Computer Lab	Computer Lab	2nd Floor	205	205	1,062	270	82	Y	
Kindergarten	Kindergarten	1st Floor	101	101	1,295	270	82	Y	
Kindergarten	Play Room	Basement	006	Boys Play Rm	665	78	48	N	N
Pre School	Regular Classroom	2nd Floor	201	201	1,189	49	115	Y	
Pre School	Regular Classroom	Basement	001	NA	1,015	117	56	Y	
Regular Classroom	Library	2nd Floor	206	206	1,189	270	82	Y	
Regular Classroom	Regular Classroom	1st Floor	104	104	1,176	145	45	Y	
Regular Classroom	Regular Classroom	1st Floor	105	105	1,053	270	82	Y	
Regular Classroom	Regular Classroom	1st Floor	106	106	1,064	270	82	Y	
Regular Classroom	Regular Classroom	2nd Floor	203	203	1,189	145	45	Y	
Regular Classroom	Regular Classroom	3rd Floor	301	301	1,146	247	78	Y	
Regular Classroom	Regular Classroom	3rd Floor	302	302	1,146	247	78	Y	
Regular Classroom	Regular Classroom	3rd Floor	306	306	1,146	247	78	Y	
Science Classroom	Regular Classroom	2nd Floor	202	202	1,189	570	82	Y	
Special Education	Office	Basement	005	office	500	58	28	N	N
Special Education	Regular Classroom	2nd Floor	204	204	1,189	145	45	Y	
Building : Modular 1 (4-Classr	room)								
Regular Classroom	Regular Classroom	1st Floor	995	995	621	48	24	N	Ν
Regular Classroom	Regular Classroom	1st Floor	996	996	621	48	24	N	Ν
Regular Classroom	Regular Classroom	1st Floor	997	997	621	48	24	N	Ν
Regular Classroom	Regular Classroom	1st Floor	998	998	621	48	24	N	Ν