

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition1. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1897	4	120,281
Annex	1905	1	17,053
Campus Total			137,334

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Entire Building	9	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	3	EA	7	10+ years	
ntrance	1						
	Exterior Doors - Exterior FRP Door	#1 - SE	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - SE	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - SE	20	LF	5	2-5 years	
	Entrance Control - Audio and Video	#2 - E	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#2 - E	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - E	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - E	20	LF	5	2-5 years	
	Entrance Control - Audio and Video	#3 - Main - NE	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - Main - NE	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - Main - NE	3	EA	6	10+ years	
	Power Door Operator and Controls	#3 - Main - NE	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#4 - N	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - N	3	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - N	20	LF	5	2-5 years	
	Exterior Doors - Exterior FRP Door	#5 - NW	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - NW	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - NW	52	LF	5	2-5 years	
	Ramp Handrail - Steel_Ramp Handrail	#5 - NW	60	LF	6	10+ years	
	Ramps - Concrete	#5 - NW	25	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior FRP Door	#6 - NW	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7 - W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7.1 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7.2 - SW	1	EA	6	10+ years	
	Entrance Control - Audio and Video	#8 - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#8 - SW	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - SW	6	LF	6	10+ years	
oundati	ion						
	Foundation - Masonry	Entire Building	1,160	LF	7	10+ years	
	Foundation - Masonry	Entire Building	10	LF	5	2-5 years	Cracked/Open joints
	Superstructure - Heavy Timber	Entire Building	120,041	SF	7	10+ years	,
	Superstructure - Slab on Grade	Entire Building	240	SF	4	0-1 year	Concrete slab buckled and
		3	_			, , , , ,	deteriorating at Sprinkler pump room
							and adjacent areas at lower level.
ighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	10 L VOORS	
	Exterior Lighting - Parapet of Roof Mounted	Entire building	9	EA	б	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	#1 - SE	2	EA	7	10+ years	
	Access Ladder - Metal	#1 - SE	1	EA	7	10+ years	
	Coping - Terra Cotta	#1 - SE	416	LF	6	10+ years	
	Downspouts - Interior Downspouts	#1 - SE	244	LF	6	10+ years	
	Parapet - Parapet > 30"	#1 - SE	416	LF	6	10+ years	Cracked masonry
	Roof - Modified Bitumen	#1 - SE	9,048	SF	6	10+ years	
	Roof - Modified Bitumen	#1 - SE	20	SF	6	2-5 years	
	Roof Hatch - Metal	#1 - SE	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#1 - SE	9,068	SF	7	10+ years	
	Coping - Terra Cotta	#10 - Low SSE	26	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#10 - Low SSE	14	LF	6	10+ years	
	Parapet - Parapet > 30"	#10 - Low SSE	26	LF	6	10+ years	
	Roof - Modified Bitumen	#10 - Low SSE	845	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#10 - Low SSE	845	SF	7	10+ years	
	Coping - Stone	#11 - Low Door #8	23	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#11 - Low Door #8	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#11 - Low Door #8	23	LF	6	10+ years	
	Roof - Modified Bitumen	#11 - Low Door #8	208	SF	5	2-5 years	Dead bird remains/bird feces - Sea
	Roof Structure - Steel with Clay Tile Arch	#11 - Low Door #8	208	SF	7	10+ years	Deterioration
	Coping - Stone	#12 - N Entrance	30	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#12 - N Entrance	15	LF	6	10+ years	

Campus Name: Cameron Page : 2 of 47 Assessment Date: 06/08/2022



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	#12 - N Entrance	30	LF	6	10+ years	
	Roof - Metal	#12 - N Entrance	125	SF	6	10+ years	
	Roof Structure - Heavy Timber	#12 - N Entrance	125	SF	7	10+ years	
	Access Ladder - Metal	#2 - Middle	1	EA	7	10+ years	
	Coping - Terra Cotta	#2 - Middle	421	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#2 - Middle	183	LF	6	10+ years	
	Parapet - 16" - 30" Height	#2 - Middle	391	LF	6	10+ years	
	Parapet - Parapet > 30"	#2 - Middle	30	LF	6	10+ years	
	Roof - Modified Bitumen	#2 - Middle	8,599	SF	6	10+ years	
	Roof Structure - Heavy Timber	#2 - Middle	8,599	SF	7	10+ years	
	Access Ladder - Metal	#3 - NE	1	EA	7	10+ years	
	Coping - Terra Cotta	#3 - NE	272	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#3 - NE	65	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3 - NE	40	LF	6	10+ years	
	Parapet - Parapet > 30"	#3 - NE	232	LF	6	10+ years	
	Roof - Modified Bitumen	#3 - NE	4,148	SF	6	10+ years	
	Roof Structure - Heavy Timber	#3 - NE	4,148	SF	7	10+ years	
	Access Ladder - Metal	#4 - N	, 1	ĒΑ	7	10+ years	
	Coping - Terra Cotta	#4 - N	60	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#4 - N	61	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4 - N	60	LF	6	10+ years	
	Roof - Modified Bitumen	#4 - N	1,580	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#4 - N	1,580	SF	7	10+ years	
	Access Ladder - Metal	#5 - NW	2	ĒΑ	7	10+ years	
	Coping - Terra Cotta	#5 - NW	375	LF	6	10+ years	
	Downspouts - Interior Downspouts	#5 - NW	252	LF	6	10+ years	
	Parapet - 16" - 30" Height	#5 - NW	375	LF	6	10+ years	
	Roof - Modified Bitumen	#5 - NW	7,342	SF	6	10+ years	
	Roof Hatch - Metal	#5 - NW	1	ĒΑ	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#5 - NW	7,342	SF	7	10+ years	
	Access Ladder - Metal	#6 - Low N Courtyard	1	ĒΑ	7	10+ years	
	Coping - Terra Cotta	#6 - Low N Courtyard	8	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#6 - Low N Courtyard	13	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#6 - Low N Courtyard	8	LF	6	10+ years	
	Roof - Modified Bitumen	#6 - Low N Courtyard	1,123	SF	6	10+ years	
	Roof Structure - Heavy Timber	#6 - Low N Courtyard	1,123	SF	7	10+ years	
	Access Ladder - Metal	#7 - W	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	#7 - W	120	LF	6	10+ years	
	Liner		-			•	
	Coping - Terra Cotta	#7 - W	135	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#7 - W	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	#7 - W	135	LF	6	10+ years	
	Roof - Modified Bitumen	#7 - W	1,017	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	#7 - W	1,017	SF	7	10+ years	



	Catego	ry : Exterior		В	uilding	: Main		+ N Monticello AVENOE, Chicago, IL 60631
Access Ladder - Metal #8 - Low SE		,		_			Recommend	
Coping - Terra Cotta	Group		Location	Quantity	UOM	Rank	Replacement	Comments
Downspouts - Exterior Downspouts		Access Ladder - Metal	#8 - Low SE	1	EΑ	7	10+ years	
Parapet 1-16" - 30" Helight		Coping - Terra Cotta	#8 - Low SE	20	LF	6	10+ years	
Roof - Modified Bitumen		Downspouts - Exterior Downspouts	#8 - Low SE	13	LF	6	10+ years	
Roof - Modified Bitumen		Parapet - 16" - 30" Height	#8 - Low SE	20	LF	6	10+ years	
Roof Structure - Steel with Clay Tile Arch   #8 - Low SE   20			#8 - Low SE	384	SF	6	10+ years	
Coping - Terra Cotta			#8 - Low SE	384	SF	7	10+ years	
Downspouts			#9 - Low SW	96	LF	6	6-10 years	
Parapet - Parapet > 30"			#9 - Low SW		LF	6		
Roof - Modified Bitumen					LF		-	Item type Changed
Roof Structure - Concrete #9 - Low SW 532 SF 7 10+ ýears  Valls  Cornice - Masonry Projecting Limestone Comice - Masonry Projecting Entire Building 1,160 LF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 4 0-1 year Walls - Brick Exterior Walls - Brick Entire Building 70,000 SF 4 0-1 year Walls - Brick Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 1,188 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 4 1-2 years Exterior Walls - Stone-Cut Entire Building 8 SF 0 10+ years Exterior Walls - Stone-Cut Entire Building 8 SF 0 10+ years Exterior Walls - Stone-Cut Entire Building 8 SF 0 10+ years Exterior Walls - Stone-Cut Entire Building 8 SF 0 10+ years Ouanity Adjusted Spall, cracked and broken Exterior Walls - Stone-Cut Entire Building 8 SF 0 10+ years Uniform Wall - Louver Entire Building 1,562 SF 0 10+ years Uniform Wall - Louver Entire Building 1,562 SF 0 10+ years Uniform Wall - Louver Entire Building 1,562 SF 0 10+ years Uniform Wall - Louver Entire Building 1,562 SF 0 10+ years Uniform Wall - Louver Entire Building 1,562 SF 0 10+ years Uniform Wall - Stone Entire Building 1,562 SF 0 10+ years Windows - Sash Aluminum Entire Building 1,562 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Double-pane Entire Building 1,564 SF 0 10+ years Windows - Wood- Dou					SF			3,1 1 1 3 1
Cornice - Masonry Projecting Limestone Cornice - Metal Projecting Entire Building 1,160 LF 6 10+ years 10+ years Exterior Walls - Brick Entire Building 529 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from mair wall.  ***Unindows**  ***Curtain wall - Louver Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane							•	
Cornice - Masonry Projecting Limestone Cornice - Metal Projecting Entire Building 1,160 LF 6 10+ years 10+ years Exterior Walls - Brick Entire Building 529 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Brick Entire Building 70,000 SF 6 10+ years Exterior Walls - Stone-Cast Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from mair wall.  ***Unindows**  ***Curtain wall - Louver Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane	Walls							
Exterior Walls - Brick Entire Building 7,000 SF 6 10+ years Cuantity Adjusted Throughout building, stepped cracket work and the sterior Walls - Brick Entire Building 7,000 SF 6 10+ years Countity Adjusted Throughout building, stepped cracket work and the sterior Walls - Brick Entire Building 400 SF 4 0-1 year Throughout building, stepped cracket work and the sterior Walls - Brick Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cust Entire Building 1,186 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 1,186 SF 6 10+ years Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver Entire Building 3,00 SF 6 6-10 years Stone-Cut Entire Building 3,692 SF 6 10+ years Stone-Cut Entire Building 3,458 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 3,884 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Sash Aluminum Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building								
Exterior Walls - Brick Entire Building 71,000 SF 6 10+ years Unantity Adjusted Throughout building, stepped cracke wortar joints, major mortar joints deterioration and open joints in interior courtyard and behind downspouts in interior courtyard and behind downspouts in interior courtyard.  Exterior Walls - Stone-Cast Entire Building 1,186 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 4 1-2 years Spall, cracked and broken Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from mair wall.  Curtain wall - Louver Entire Building 3,692 SF 6 10+ years Guard - Guards perforated Entire Building 3,692 SF 6 10+ years Lintels - Stone Entire Building 13,2 LF 6 10+ years Lintels - Stone Entire Building 1416 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entire Building 140 SF 6 10+ years Windows - Wood- Double-pane Entir		Cornice - Metal Projecting	Entire Building	1,160		6	10+ years	
Exterior Walls - Brick  Entire Building  A00 SF 4 0-1 year  Throughout building, stepped cracke mortar joints interior courtyard and behind downspouts in interior courtyard and behind downspouts in interior courtyard.  Exterior Walls - Stone-Cast Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 1,186 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 4 1-2 years Spall, cracked and broken Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver Guard - Guards perforated Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 3,692 SF 6 10+ years Lintels - Steel Lintels - Steel Entire Building 3,458 LF 6 10+ years Lintels - Stone Windows - Sash Aluminum Entire Building 416 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,848 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Exterior Walls - Stone Location Quantity UOM Rank Replacement Comments		Exterior Walls - Brick	Entire Building	529		6	10+ years	
mortar joints, major mortar joints deterioration and open joints in interior courtyard and behind downspouts in interior courtyard.  Exterior Walls - Stone-Cut Entire Building 1,360 SF 6 10+ years Exterior Walls - Stone-Cut Entire Building 6 SF 4 1-2 years Spall, cracked and broken Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver Entire Building 3,692 SF 6 10+ years Guard - Guards perforated Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 66 LF 6 10+ years Lintels - Stone Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,488 LF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Sash Aluminum Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane		Exterior Walls - Brick		71,000		6	10+ years	
Exterior Walls - Stone-Cut Entire Building 1,186 SF 6 10+ years Spall, cracked and broken Exterior Walls - Stone-Cut Entire Building 8 SF 3 0-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 13,84 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,84 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,84 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 Comments		Exterior Walls - Brick	-			4	0-1 year	mortar joints. major mortar joints deterioration and open joints in interior courtyard and behind
Exterior Walls - Stone-Cut Entire Building 6 SF 4 1-2 years O-1 year Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver Entire Building 30 SF 6 6-10 years Guard - Guards perforated Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 66 LF 6 10+ years Lintels - Steel Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,498 LF 6 10+ years Lintels - Stone Entire Building 3,498 LF 6 10+ years Lintels - Stone Entire Building 13,498 LF 6 10+ years Windows - Sash Aluminum Entire Building 416 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Windows - Wood- Double-pane Windows - Wood- Do		Exterior Walls - Stone-Cast		1,360		6	10+ years	
Exterior Walls - Stone-Cut  Entire Building  8 SF 3 0-1 year  Asset Added: Fresh air in-take cut stone enclosure detaching from main wall.  Vindows  Curtain wall - Louver  Guard - Guards perforated  Entire Building  3,692 SF 6 10+ years  Lintels - Brick  Entire Building  66 LF 6 10+ years  Lintels - Stoel  Entire Building  132 LF 6 10+ years  Lintels - Stone  Entire Building  3,458 LF 6 10+ years  Windows - Sash Aluminum  Entire Building  416 SF 6 10+ years  Windows - Sash Aluminum Double-pane  Windows - Wood- Double-pane  Entire Building  13,884 SF 6 10+ years  Windows - Wood- Double-pane  Entire Building  40 SF 6 10+ years  Category : Electrical  Building : Main  Recommend		Exterior Walls - Stone-Cut	Entire Building	1,186		6	10+ years	Quantity Adjusted
Stone enclosure detaching from main wall.    Vindows		Exterior Walls - Stone-Cut	Entire Building	6		4	1-2 years	Spall, cracked and broken
Curtain wall - Louver Entire Building 30 SF 6 6-10 years Guard - Guards perforated Entire Building 3,692 SF 6 10+ years Lintels - Brick Entire Building 66 LF 6 10+ years Lintels - Steel Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 416 SF 6 10+ years Windows - Wood- Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years		Exterior Walls - Stone-Cut	Entire Building	8	SF	3	0-1 year	stone enclosure detaching from main
Guard - Guards perforated  Entire Building  3,692  SF 6 10+ years Lintels - Brick Entire Building 66  LF 6 10+ years Lintels - Steel Lintels - Steel Entire Building 132  LF 6 10+ years Lintels - Stone Entire Building 3,458  LF 6 10+ years Windows - Sash Aluminum Entire Building 416  SF 6 10+ years Windows - Sash Aluminum Double-pane Windows - Wood- Double-pane Entire Building 40  SF 6 10+ years  Horizonal  Building: Main  Recommend	Windows							
Lintels - Brick Entire Building 66 LF 6 10+ years Lintels - Steel Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 416 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical  Building : Main  Recommend  Recommend  Group Item - Type Location Quantity UOM Rank Replacement Comments		Curtain wall - Louver	Entire Building	30	SF	6	6-10 years	
Lintels - Brick Entire Building 66 LF 6 10+ years Lintels - Steel Entire Building 132 LF 6 10+ years Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 416 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical  Building : Main  Recommend  Recommend  Group Item - Type Location Quantity UOM Rank Replacement Comments		Guard - Guards perforated	•	3,692	SF			
Lintels - Steel Lintels - Stone Lintels - Stone Entire Building Stroup Item - Type  Entire Building Entire Building Stroup Item - Type  Entire Building Stroup Item - Type  Entire Building Stroup Item - Type  Entire Building Stroup Item - Stone Entire Building Stroup Item - Strone Entire Building Stroup Item - Strone Entire Building Strone Strone Strone Entire Building Strone Strone Strone Strone Strone Strone Entire Building Strone St			Entire Building	66	LF	6	•	
Lintels - Stone Entire Building 3,458 LF 6 10+ years Windows - Sash Aluminum Entire Building 416 SF 6 10+ years Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical  Building : Main  Recommend Froup Item - Type Location Quantity UOM Rank Replacement Comments		Lintels - Steel		132			10+ years	
Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical Building : Main  Recommend  Froup Item - Type Location Quantity UOM Rank Replacement Comments			•				•	
Windows - Sash Aluminum Double-pane Entire Building 13,884 SF 6 10+ years Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical Building : Main  Recommend Froup Item - Type Location Quantity UOM Rank Replacement Comments		Windows - Sash Aluminum		416			•	
Windows - Wood- Double-pane Entire Building 40 SF 6 10+ years  Category : Electrical  Recommend  Froup Item - Type Location Quantity UOM Rank Replacement Comments		Windows - Sash Aluminum Double-pane	•	13,884	SF	6		
Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments			Entire Building	40	SF	6		
Group Item - Type Location Quantity UOM Rank Replacement Comments	Catego	ry : Electrical		В	uilding	: Main		
· · · · · · · · · · · · · · · · · · ·	Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	•							



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Auditoium and Aisle Lighting	Basement	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Basement	7	EA	6	6-10 years	Building has an emergency AC generator for emergency lighting
	Exit Signs - Auditoium	Entire Building	17	EA	6	6-10 years	Cleaned, functional. Glare from light causes iPad camera to show blurred photo
	Exit Signs - Corridors and Stairs	Entire Building	31	EA	6	6-10 years	•
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Functional, cleaned
	Exit Signs - Lunchroom	Entire Building	5	EA	6	6-10 years	Building has an AC generator
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,376	SF	6	10+ years	Ç Ç
	Emergency A/C Power - Corridors and Stairs	Entire Building	27,741	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	4,418	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,119	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	3,103	SF	6	10+ years	
	Security System - CCTV	Entire Building	120,281	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	120,281	SF	5	6-10 years	
	Emergency Generator- Outdoor- Diesel - 101 - 150 KW	Site South	1	EA	6	10+ years	Serves main building
	Automatic Transfer Switch	Storage Room, Electrical Room	3	EA	6	6-10 years	Serve AC generator
Main Se	rvice						
	Main Electrical Service - 1600 A 120/240/3PH	Electrical Room	1	EA	6	6-10 years	Serves main building
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	120,281	SF	6	6-10 years	A few speakers failed were replaced recently. Connected to annex
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	2-5 years	Frequently trips, not reliable, EM panel
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	7	10+ years	
	J J -	Entire Building				- <i>j</i>	

Campus Name: Cameron Page : 5 of 47 Assessment Date: 06/08/2022



						120-	N Monticello AVENUE, Chicago, IL 60651
Catego	ry : Electrical		В	uilding	: Main		<u>.</u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels, rated 7, have 10+
		9				•	years of expected life
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	•
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	7	10+ years	Functional panels, rated 7, have 10+
	·	-				-	years of expected life
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EΑ	7	10+ years	
	amp	· ·				•	
	·						
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
			Qualitity	00111		replacement	Comments
Fire Alar	m		Quantity	O O III	rtaint	rtopiacomont	Comments
Fire Alar		1.11.1	1			·	
Fire Alar	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
_Fire Alar	Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Entire Building	1 120,281	EA SF	6 6	6-10 years 6-10 years	Serves main building
Fire Alar	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building Entire Building	1	EA	6	6-10 years 6-10 years 6-10 years	
Fire Alar	Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Entire Building	1 120,281 120,281	EA SF SF	6 6 6	6-10 years 6-10 years	Serves main building
	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building Entire Building	1 120,281 120,281	EA SF SF	6 6 6	6-10 years 6-10 years 6-10 years	Serves main building
	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller	Entire Building Entire Building Entire Building	1 120,281 120,281	EA SF SF	6 6 6	6-10 years 6-10 years 6-10 years	Serves main building
	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  poom Assembly	Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1	EA SF SF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building
	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  pom Assembly Fire Pump - 25-50 hp	Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1	EA SF SF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building
_Pump Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  pom Assembly Fire Pump - 25-50 hp	Entire Building Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1	EA SF SF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building Serves main building
_Pump Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp	Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1	EA SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building
_Pump Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp	Entire Building Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1	EA SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building Serves main building Serves main building
_Pump Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  com Assembly Fire Pump - 25-50 hp  CSystem Dry Sprinkler System	Entire Building Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building	1 120,281 120,281 1 1	EA SF SF EA	6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Serves main building Serves main building Serves main building Serves main building
_Pump Ro _Sprinkled	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  com Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building	1 120,281 120,281 1 1 120,281 120,281 120,281	EA SF SF EA SF SF	6 6 6 6 7 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	Serves main building Serves main building Serves main building Serves main building
_Pump Ro _Sprinkled	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp  System  Dry Sprinkler System  Sprinkler Heads	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building	1 120,281 120,281 1 1 120,281 120,281 120,281	EA SF SF EA SF	6 6 6 6 7 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	Serves main building Serves main building Serves main building Serves main building
_Pump Ro _Sprinkled	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  com Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping  ry: Mechanical	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building Entire Building Entire Building	1 120,281 120,281 1 1 1 120,281 120,281 120,281	EA SF SF EA SF SF SF	6 6 6 6 7 6 : Main	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years  10+ years 10+ years 10+ years	Serves main building  Serves main building  Serves main building  Serves main building, building uses an air compressor
_Pump Ro _Sprinkled	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  com Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building	1 120,281 120,281 1 1 120,281 120,281 120,281	EA SF SF EA SF SF	6 6 6 6 7 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Serves main building Serves main building Serves main building Serves main building
_Pump Ro _Sprinkled	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping  ry: Mechanical  Item - Type	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building Entire Building Entire Building	1 120,281 120,281 1 1 1 120,281 120,281 120,281	EA SF SF EA SF SF SF	6 6 6 6 7 6 : Main	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years  10+ years 10+ years 10+ years	Serves main building  Serves main building  Serves main building  Serves main building, building uses an air compressor
_Pump_Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping  ry: Mechanical  Item - Type	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building  Entire Building Entire Building Entire Building	1 120,281 120,281 1 1 1 120,281 120,281 120,281	EA SF SF EA SF SF SF	6 6 6 6 7 6 : Main	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years  10+ years 10+ years 10+ years	Serves main building  Serves main building  Serves main building  Serves main building, building uses an air compressor
_Pump_Ro	Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller  Dom Assembly Fire Pump - 25-50 hp  System Dry Sprinkler System  Sprinkler Heads Sprinkler Piping  ry: Mechanical  Item - Type  itioning	Entire Building Entire Building Entire Building Entire Building  Sprinkler Room  Entire Building Entire Building Entire Building Entire Building Entire Building	1 120,281 120,281 1 1 120,281 120,281 120,281 B Quantity	EA SF SF EA SF SF SF UIIding	6 6 6 7 6 : Main	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years Recommend Replacement	Serves main building Serves main building Serves main building Serves main building, building uses an air compressor  Comments



atego	ry : Mechanical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
loup	nem - Type	Location	Quantity	OOW	Naiik	Replacement	Comments
· Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	Serves gym and auditorium
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	Functional, painted
	Zone Dampers	Basement	3	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Basement	1	EA	5	10+ years	Serves north and south portion of building, classrooms and offices
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 30001 - 45000 cfm	Basement	1	EΑ	5	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	550	LF	6	10+ years	
	Zone Dampers	Basement	40	EA	5	6-10 years	Many dampers are manually controlled
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves dining area, classrooms
	Air Intake	Mechanical Room	1	EA	5	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	500	LF	6	10+ years	
	Zone Dampers	Mechanical Room	28	EA	5	6-10 years	Many dampers are manually controlled
ler Sy	stems						
-	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	Lubricated, functional
	Condensate Pump	Boiler Room	3	EA	6	6-10 years	·
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Boiler Room	2	EA	5	6-10 years	Serves main building, recently retubed
	Piping - Condensate Pipe- Steel	Boiler Room	750	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	750	LF	5	6-10 years	
	Steam Traps	Boiler Room	45	ĒΑ	5	6-10 years	
	Steam Traps	Boiler Room	20	EA	4	2-5 years	Steam traps have internal leaks
as Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	Serve boilers



Catego	ry : Mechanical		E	uilding	: Main		
	<del>.</del>	•	0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Unit Heater - Electric	Basement	2	EA	5	6-10 years	
	Unit Heater - Steam	Basement	2	EΑ	5	6-10 years	
	Wall Heater - Electric	Entire Building	15	EΑ	6	10+ years	
	Wall Heater - Electric	Entire Building	5	EΑ	5	6-10 years	Recently cleaned and inspected
	Radiators - Steam	Entire Building	15	EΑ	5	6-10 years	reconney clouriou and mopeolou
	Radiators - Steam	Entire Building	5	EA	4	2-5 years	Deteriorated, difficult to control
	Nadiators - dteam	Littile ballaling	3	LA	7	2-5 years	temperature
	Fin Tube - Steam	Entire Building	12	LF	5	6-10 years	•
Tempera	ture Control						
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves fan coil in IDF room
	Pneumatic System	Entire Building	120,281	SF	5	6-10 years	Mostly manually operated
	Thermostats - Pneumatic	Entire Building	61	EA	6	6-10 years	, , ,
	Thermostats - Pneumatic	Entire Building	10	EA	5	6-10 years	Not calibrated well
Ventilatio	nn.						
Verman	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof	7	EA	6	6-10 years	Serve restrooms, above ceilings
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	7	EΑ	6	6-10 years	corre recardenne, above cominge
	CFM		•	_, `	Ū	o to youro	
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	6	10+ years	In kitchen
Catego	ry : Plumbing		В	uilding	: Main		
Janogo	. y		_	·		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	2012 installation
	Electric Heater - Less than 20 KW	Kitchen	1	EA	5	6-10 years	Functional, serves kitchen
Dining							
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	120,281	SF	6	6-10 years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	120,281	SF	6	6-10 years	Pressure at third floor is good
	Domestic Piping-Hot Water from Risers to	Entire Building	120,281	SF	6	6-10 years	r ressure at time noor is good
	Fixtures	Little ballaling	120,201	01	U	0-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	120,281	SF	6	6-10 years	1897 installation
	(Horizontal Lines)	Entire Duilding	400.004	C.	^	6.40	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	120,281	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	120,281	SF	6	6-10 years	No active leaks
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	120,281	SF	6	6-10 years	
	Storm Piping	Entire Building	120,281	SF	6	6-10 years	
C	Jame: Cameron		Page : 8 of 47				Assessment Date: 06/08/202



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Vent Piping	Entire Building	120,281	SF	6	6-10 years	
_Pumps_							
	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	6-10 years	Serves main building. Seals have been recently repacked
	Pumps - Sump-Simplex	Coal Room (Basement)	1	EΑ	5	6-10 years	Seal has been recently repacked
	Pumps - Sump-Simplex	Elevator pit	1	EA	5	6-10 years	Functional, recently inspected by elevator inspector, under elevator

Category: Room **Building: Main** 

	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	105 Teacher's lounge	900	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105 Teacher's lounge	1	EA	7	10+ years	
	Floor - Carpet	105 Teacher's lounge	900	SF	7	10+ years	
	Lighting - Pendent/Surface	105 Teacher's lounge	8	EA	7	6-10 years	
	Power Distribution	105 Teacher's lounge	6	EA	7	10+ years	
	Walls - Plaster/Drywall	105 Teacher's lounge	1,400	SF	7	10+ years	
	AC Unit	108 Counselor's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	108 Counselor's Office	610	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108 Counselor's Office	2	EA	7	10+ years	
	Floor - Tile	108 Counselor's Office	605	SF	7	10+ years	
	Floor - Tile	108 Counselor's Office	5	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	108 Counselor's Office	10	EA	7	6-10 years	
	Power Distribution	108 Counselor's Office	6	EA	7	10+ years	
	Storage/ Closet	108 Counselor's Office	250	SF	7	10+ years	
	Walls - Plaster/Drywall	108 Counselor's Office	1,300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	111A Nurse's Office	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111A Nurse's Office	1	EA	7	10+ years	
	Floor - Tile	111A Nurse's Office	190	SF	7	10+ years	
	Floor - Tile	111A Nurse's Office	5	SF	5	0-1 year	Broken tiles
	Lighting - Pendent/Surface	111A Nurse's Office	2	EA	7	6-10 years	
	Power Distribution	111A Nurse's Office	4	EA	7	10+ years	
	Storage/ Closet	111A Nurse's Office	6	SF	7	10+ years	
	Walls - Metal Panel	111A Nurse's Office	323	SF	7	10+ years	
	Walls - Plaster/Drywall	111A Nurse's Office	496	SF	7	10+ years	
	Ceiling - Plaster/Drywall	112A Attendance Office	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112A Attendance Office	1	EA	7	10+ years	
	Floor - Tile	112A Attendance Office	195	SF	6	10+ years	
	Lighting - Pendent/Surface	112A Attendance Office	2	EA	7	6-10 years	
	Power Distribution	112A Attendance Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	112A Attendance Office	496	SF	7	10+ years	
	Ceiling - Plaster/Drywall	116 Auditorium balcony Office north	216	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	116 Auditorium balcony Office north	2	EA	7	10+ years	
	Floor - Terrazzo	116 Auditorium balcony Office north	216	SF	7	10+ years	
	Lighting - Pendent/Surface	116 Auditorium balcony Office north	2	EA	6	6-10 years	
	Power Distribution	116 Auditorium balcony Office north	4	EA	7	10+ years	
	Walls - Plaster/Drywall	116 Auditorium balcony Office north	496	SF	7	10+ years	
	Ceiling - Plaster/Drywall	118 Auditorium balcony Office south	216	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118 Auditorium balcony Office south	2	EA	7	10+ years	
	Floor - Terrazzo	118 Auditorium balcony Office south	216	SF	7	10+ years	
	Lighting - Pendent/Surface	118 Auditorium balcony Office south	2	EA	7	6-10 years	
	Power Distribution	118 Auditorium balcony Office south	4	EA	7	10+ years	
	Walls - Plaster/Drywall	118 Auditorium balcony Office south	496	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor C/CM Office	286	SF	7	10+ years	
	Doors - Transom Window	1st Floor C/CM Office	54	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor C/CM Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor C/CM Office	286	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor C/CM Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor C/CM Office	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor C/CM Office	1,016	SF	7	10+ years	
	Work SInk	1st Floor C/CM Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	213 - Copy Room	410	SF	7	10+ years	
	Doors - Wood Doors inclu hw	213 - Copy Room	1	EA	7	10+ years	
	Floor - Carpet	213 - Copy Room	205	SF	7	6-10 years	
	Floor - Tile	213 - Copy Room	199	SF	7	10+ years	
	Floor - Tile	213 - Copy Room	6	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	213 - Copy Room	7	EA	7	10+ years	
	Power Distribution	213 - Copy Room	10	EA	7	10+ years	
	Storage/ Closet	213 - Copy Room	170	SF	7	10+ years	
	Walls - Metal Panel	213 - Copy Room	643	SF	7	10+ years	
	Walls - Plaster/Drywall	213 - Copy Room	663	SF	7	10+ years	
	AC Unit	3rd floor - 305 Social Worker	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor - 305 Social Worker	478	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor - 305 Social Worker	1	EA	7	10+ years	
	Floor - Tile	3rd floor - 305 Social Worker	473	SF	7	6-10 years	
	Floor - Tile	3rd floor - 305 Social Worker	5	SF	4	0-1 year	Damaged and missing tiles
	Lighting - Pendent/Surface	3rd floor - 305 Social Worker	6	EA	7	6-10 years	
	Power Distribution	3rd floor - 305 Social Worker	12	EA	7	10+ years	
	Storage/ Closet	3rd floor - 305 Social Worker	30	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd floor - 305 Social Worker	1,105	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor - 305 Social Worker	5	SF	4	0-1 year	Holes in wall
	AC Unit	3rd floor - 313 Assistant Principle	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor - 313 Assistant Principle	428	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor - 313 Assistant Principle	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd floor - 313 Assistant Principle	408	SF	6	10+ years	
	Floor - Tile	3rd floor - 313 Assistant Principle	20	SF	4	0-1 year	Damaged tiles
		•				•	<u>-</u>

Campus Name: Cameron Page : 10 of 47 Assessment Date: 06/08/2022



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd floor - 313 Assistant Principle	6	EA	7	6-10 years	
	Power Distribution	3rd floor - 313 Assistant Principle	12	EA	7	10+ years	
	Storage/ Closet	3rd floor - 313 Assistant Principle	30	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd floor - 313 Assistant Principle	1,110	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd floor - office inside gym	337	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor - office inside gym	1	EA	7	10+ years	
	Floor - Tile	3rd floor - office inside gym	337	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd floor - office inside gym	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd floor - office inside gym	1	EA	6	2-5 years	
	Power Distribution	3rd floor - office inside gym	2	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd floor - office inside gym	1,532	SF	7	10+ years	
	AC Unit	Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	310	SF	7	10+ years	
	Doors - Transom Window	Engineer's Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	Engineer's Office	298	SF	7	10+ years	
	Floor - Tile	Engineer's Office	12	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	Engineer's Office	6	EA	7	6-10 years	
	Power Distribution	Engineer's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	696	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	50	SF	4	0-1 year	Damaged plaster falling to the floor
	AC Unit	Main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office	464	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office	1	EA	7	10+ years	
	Floor - Tile	Main office	464	SF	7	10+ years	
	Lighting - Pendent/Surface	Main office	10	EA	7	6-10 years	
	Power Distribution	Main office	4	EA	7	10+ years	
	Storage/ Closet	Main office	74	SF	7	10+ years	
	Walls - Plaster/Drywall	Main office	1,158	SF	7	10+ years	
	AC Unit	Principal's Office	. 1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	325	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	7	10+ years	
	Floor - Carpet	Principal's Office	325	SF	7	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	3	EA	7	6-10 years	
	Power Distribution	Principal's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	745	SF	7	10+ years	
	AC Unit	Room 101 Book Room Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 101 Book Room Office	364	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 101 Book Room Office	1	ĒA	7	10+ years	
	Floor - Tile	Room 101 Book Room Office	364	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 101 Book Room Office	7	ĒΑ	6	6-10 years	
	Power Distribution	Room 101 Book Room Office	4	EΑ	7	10+ years	
	Storage/ Closet	Room 101 Book Room Office	50	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 101 Book Room Office	1,280	SF	7	10+ years	
			.,_50	٠.	•	,	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work SInk	Room 101 Book Room Office	1	EA	7	10+ years	
	AC Unit	Room 113	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 113	612	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 113	1	EA	7	10+ years	
	Floor - Tile	Room 113	607	SF	7	6-10 years	
	Floor - Tile	Room 113	5	SF	4	0-1 year	Missing tiles
	Lighting - Pendent/Surface	Room 113	10	EA	6	6-10 years	
	Power Distribution	Room 113	20	EA	7	10+ years	
	Storage/ Closet	Room 113	176	SF	7	10+ years	
	Walls - Metal Panel	Room 113	226	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 113	1,343	SF	7	10+ years	
_Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	372	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,366	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	8	EA	7	10+ years	
	Floor - Carpet	1st Floor	764	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor	2,612	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	57	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	16	EA	7	10+ years	
	Main Floor Seating	1st Floor	400	EA	7	10+ years	
	Main Floor Seating	1st Floor	5	EA	5	0-1 year	Delaminating wood on seats
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	725	SF	7	10+ years	
	Stage Curtain	1st Floor	5	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	2	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	20	LF	7	10+ years	
	Walls - Masonry	1st Floor	346	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,900	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	57	SF	4	0-1 year	Water damage
_Gymnas	ia						
	Ceiling - Plaster/Drywall	3rd Floor	4,418	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	4,418	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	3rd Floor	20	EA	6	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,528	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,982	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen							
	Ceiling - Lay-in	Basement	624	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile Quarry	Basement	624	SF	7	10+ years	
	Lighting - Lay-in	Basement	9	EA	7	6-10 years	
	Storage/ Closet	Basement	158	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	405	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement	405	SF	7	10+ years	
Library							
	AC Unit	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	117	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,670	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	1,670	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,120	SF	7	10+ years	
Lunch 8	Multipurpose Room						
LUITOITA	Ceiling - Plaster/Drywall	Ond floor avaight recordingle grows	672	SF	7	40	
	Doors - Wood Doors inclu hw	3rd floor - weight room inside gym 3rd floor - weight room inside gym		SF EA	7 7	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	3rd floor - weight room inside gym	1 672	SF	7	10+ years	
		3rd floor - weight room inside gym	3	SF EA	7	10+ years	
	Lighting - Pendent/Surface Lighting - Pendent/Surface	3rd floor - weight room inside gym	3 1	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd floor - weight room inside gym	2,353	SF	7	2-5 years	
	Ceiling - Lay-in	Basement - Lunchroom A	2,333 1,984	SF SF	7 7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Lunchroom A	1,964	EA	7	10+ years	
	Floor - Tile		1,984	SF	7 7	10+ years 10+ years	
	Lighting - Lay-in	Basement - Lunchroom A Basement - Lunchroom A	33	SF EA	7	6-10 years	
	Serving Line	Basement - Lunchroom A	28	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Lunchroom A	26 946	SF	7		
	Walls - Vinyl Coated Gypsum Panel	Basement - Lunchroom A	940	SF	7	10+ years	
	Ceiling - Lay-in	Basement- Lunchroom B	1,135	SF	7	10+ years 10+ years	
	Doors - Steel Doors incl hw	Basement- Lunchroom B	1,133	EA	7	10+ years	
	Floor - Tile	Basement- Lunchroom B	1,135	SF	7	10+ years 10+ years	
	Lighting - Lay-in	Basement- Lunchroom B	1,135	EA	7	•	
	Serving Line	Basement- Lunchroom B	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement- Lunchroom B	474	SF	7	10+ years 10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement- Lunchroom B	616	SF	7	10+ years	
	•		0.0	<b>J</b> .	•	, care	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	107	SF	7	10+ years	
	Janitor's Closet	2nd Floor	24	SF	7	10+ years	

Campus Name: Cameron Page : 13 of 47 Assessment Date: 06/08/2022



Catego	ry : Room		В	uilding	: Main	.20	TWININGTHEERIO AVENUE, Officago, IE 00001
2 2 2 3 4			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage Room	2nd Floor	70	SF	7	10+ years	
	Janitor's Closet	3rd Floor	83	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Air Intake Plenums	Basement	160	SF	7	10+ years	
	Air Intake Plenums	Basement	600	SF	7	10+ years	
	Air Tunnel	Basement	200	SF	7	10+ years	
	Auditorium Plenums	Basement	4,000	SF	7	10+ years	
	Boiler Room	Basement	2,016	SF	7	10+ years	
	Coal Room	Basement	944	SF	7	10+ years	
	Janitor's Closet	Basement	12	SF	7	10+ years	
	Janitor's Closet	Basement	12	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	980	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	770	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	830	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	415	SF	4	1-2 years	Floor cracking
	Storage Room	Basement	106	SF	7	10+ years	•
	Storage Room	Basement	888	SF	7	10+ years	
	Storage Room	Basement	291	SF	7	10+ years	
	Storage Room	Basement	360	SF	5	1-2 years	Peeling paint falling to the floor
	Storage Room	Basement	290	SF	4	0-1 year	Floor concrete caved in tripping hazard
	Vaults	Basement	400	SF	7	10+ years	nazaru
Prep Ro	om						
	Ceiling - Plaster/Drywall	Room 101 Kiln former restroom	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 101 Kiln former restroom	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	Room 101 Kiln former restroom	176	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 101 Kiln former restroom	1	ĒΑ	7	6-10 years	
	Partitions	Room 101 Kiln former restroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 101 Kiln former restroom	702	SF	7	10+ years	
Restroor	n						
	Accessories	013	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	013	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	013	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	013	120	SF	7	10+ years	
	Floor Drain	013	1	EA	7	10+ years	
	Lavatory	013	1	EA	7	10+ years	
	Lighting - Pendent/Surface	013	1	EA	7	10+ years	
	Walls - Plaster/Drywall	013	80	SF	7	10+ years	Quantity changed to match current observation
	Walls - Tile Ceramic/ Porcelain	013	320	SF	7	10+ years	555517441011
	Water Closet	013	1	EA	7	10+ years	
		- 10	•		•	,	

Campus Name: Cameron Page : 14 of 47 Assessment Date: 06/08/2022



Catego	ategory : Room		В	uilding	: Main			
J						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	1st Floor	650	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	650	SF	7	10+ years	Rank changed to match current observation	
	Floor - Tile Ceramic/ Porcelain	1st Floor	650	SF	7	10+ years		
	Floor Drain	1st Floor	2	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	6-10 years		
	Lavatory	1st Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years		
	Partitions	1st Floor	5	EA	7	10+ years		
	Urinals	1st Floor	8	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	328	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	1,076	SF	7	10+ years		
	Water Closet	1st Floor	5	EA	7	10+ years		
	Accessories	1st Floor	300	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	300	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	300	SF	7	10+ years		
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years		
	Hand Dryer	1st Floor	2	EA	7	10+ years		
	Lavatory	1st Floor	3	ĒΑ	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years		
	Partitions	1st Floor	5	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	500	SF	7	10+ years		
	Water Closet	1st Floor	5	EΑ	7	10+ years		
	Accessories	1st floor Unisex next to boys	80	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st floor Unisex next to boys	80	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st floor Unisex next to boys	1	EΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor Unisex next to boys	80	SF	7	10+ years		
	Floor Drain	1st floor Unisex next to boys	1	EA	7	10+ years		
	Hand Dryer	1st floor Unisex next to boys	1	EA	7	6-10 years		
	Lavatory	1st floor Unisex next to boys	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	1st floor Unisex next to boys	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st floor Unisex next to boys	96	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st floor Unisex next to boys	192	SF	7	10+ years		
	Water Closet	1st floor Unisex next to boys	132	EA	7	10+ years		
	Accessories	2nd Floor	387	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	382	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	vator damage	
	Floor - Terrazzo	2nd Floor	382	SF	7	10+ years		
	Floor - Terrazzo	2nd Floor	502	SF	4	0-1 years	Cracking	
	Floor Drain	2nd Floor	1	EA	7	10+ years	Cracking	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years		
	Hallu Diyel	ZIIU FIUUI	2	EA	,	0-10 years		



Catego	Category : Room		В	uilding	: Main		-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	10+ years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	566	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Wall damage
	Walls - Structural Glazed Tile	2nd Floor	531	SF	7	10+ years	· ·
	Water Closet	2nd Floor	7	EA	7	10+ years	
	Accessories	2nd Floor	697	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	697	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	19	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	597	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	100	SF	4	0-1 year	Cracking
	Floor Drain	2nd Floor	2	EΑ	7	10+ years	G. 35g
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	10+ years	
	Partitions	2nd Floor	4	EA	7	10+ years	
	Urinals	2nd Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	360	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	1,050	SF	7	•	
	Water Closet	2nd Floor	*	EA	7	10+ years	
			4	SF		10+ years	Not in use
	Accessories	2nd Floor	90	SF SF	7	6-10 years	Not in use
	Ceiling - Plaster/Drywall	2nd Floor	90	SF EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1		7	10+ years	
	Floor - Terrazzo	2nd Floor	90	SF	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Partitions	2nd Floor	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	430	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	40	SF	4	0-1 year	Cracks
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	3rd Floor	330	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	330	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	19	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	330	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years	
	Partitions	3rd Floor	7	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	468	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	528	SF	7	10+ years	
	Water Closet	3rd Floor	7	EA	7	10+ years	
						•	



•	Item - Type Accessories	Location				Recommend	
•	Accessories	Location					
			Quantity	UOM	Rank	Replacement	Comments
	0 "	3rd Floor	697	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	697	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	19	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	697	SF	7	10+ years	
	Floor Drain	3rd Floor	2	ĒΑ	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	9	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EΑ	6	6-10 years	
	Partitions	3rd Floor	4	EA	7	10+ years	
	Urinals			EA	7	•	
		3rd Floor	10 360	SF		10+ years	
	Walls - Plaster/Drywall	3rd Floor			7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	1,050	SF	7	10+ years	
	Water Closet	3rd Floor	4	EA	7	10+ years	
	Accessories	3rd floor - inside 305 social worker office	89	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor - inside 305 social worker office	89	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor - inside 305 social worker office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor - inside 305 social worker office	89	SF	7	10+ years	
	Floor Drain	3rd floor - inside 305 social worker	1	EA	7	10+ years	
	Hand Dryer	office 3rd floor - inside 305 social worker	1	EA	7	10+ years	
	Lavatory	office 3rd floor - inside 305 social worker	1	EA	7	10+ years	
	Lighting - Pendent/Surface	office 3rd floor - inside 305 social worker	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	office 3rd floor - inside 305 social worker	400	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	office 3rd floor - inside 305 social worker	106	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	office 3rd floor - inside 305 social worker office	1	SF	5	1-2 years	Damaged tile
	Water Closet	3rd floor - inside 305 social worker office	1	EA	7	10+ years	
	Accessories	Auditorium - Men	168	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium - Men	168	SF	7	10+ years	
	Doors - Wood Doors inclu hw			EA	7 7		
		Auditorium - Men	1			10+ years	
	Floor - Terrazzo	Auditorium - Men	168	SF	7	10+ years	
	Floor - Terrazzo	Auditorium - Men	6	SF	5	0-1 year	Floor all broken up
	Lavatory	Auditorium - Men	1	EA	6	6-10 years	

Campus Name: Cameron Page : 17 of 47 Assessment Date: 06/08/2022



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Auditorium - Men	1	EA	7	10+ years	
	Partitions	Auditorium - Men	1	EA	7	10+ years	
	Partitions	Auditorium - Men	1	EA	4	0-1 year	Glass partition is broken
	Urinals	Auditorium - Men	1	EA	7	10+ years	•
	Walls - Plaster/Drywall	Auditorium - Men	625	SF	7	10+ years	
	Water Closet	Auditorium - Men	1	EA	7	10+ years	
	Accessories	Auditorium - Women	91	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium - Women	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium - Women	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	Auditorium - Women	91	SF	7	10+ years	
	Lavatory	Auditorium - Women	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Auditorium - Women	1	EA	6	10+ years	
	Partitions	Auditorium - Women	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Auditorium - Women	423	SF	7	10+ years	
	Water Closet	Auditorium - Women	2	EA	6	10+ years	
	Accessories	Basement	397	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	397	SF	7	6-10 years	
	Doors - Wood Doors inclu hw			EA	7	•	
		Basement	1	SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	397		7	10+ years	
	Floor Drain	Basement	2	EΑ	7	10+ years	
	Hand Dryer	Basement	2	EΑ	7	10+ years	
	Lavatory	Basement	3	EA	7	10+ years	
	Lighting - Lay-in	Basement	5	EA	7	6-10 years	
	Partitions	Basement	4	EA	7	10+ years	
	Urinals	Basement	3	EA	7	10+ years	
	Walls - Concrete Block	Basement	656	SF	7	10+ years	
	Water Closet	Basement	4	EA	7	10+ years	
	Accessories	Basement	652	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	652	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Terrazzo	Basement	652	SF	7	10+ years	
	Floor - Terrazzo	Basement	20	SF	5	1-2 years	Cracks in the floor
	Floor Drain	Basement	2	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Partitions	Basement	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	328	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	1,076	SF	6	10+ years	
	Water Closet	Basement	7	ĒΑ	7	10+ years	
	Accessories	Engineer's Restroom	66	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Restroom	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Restroom	1	EA	6	1-2 years	Missing hardware
	Floor - Terrazzo	Engineer's Restroom	66	SF	7	10+ years	
	TIOST TOTALLO	2119111001 0 11001100111	00	0.	•	ioi youio	

Campus Name: Cameron Page : 18 of 47 Assessment Date: 06/08/2022



·	Item - Type Lavatory Lighting - Pendent/Surface Partitions	Location Engineer's Restroom	Quantity	HOM		Recommend	
•	Lavatory Lighting - Pendent/Surface		Quantity	1101			
	Lighting - Pendent/Surface	Engineer's Restroom	•	UOM	Rank	Replacement	Comments
	• •		1	EA	7	10+ years	
	Partitions	Engineer's Restroom	1	EA	7	6-10 years	
		Engineer's Restroom	1	EA	7	6-10 years	
	Walls - Masonry	Engineer's Restroom	24	SF	7	10+ years	
	Walls - Masonry	Engineer's Restroom	16	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Restroom	300	SF	7	10+ years	Rank changed to match current observation
	Water Closet	Engineer's Restroom	1	EA	7	10+ years	
	Accessories	Main Office Restroom	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Restroom	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Restroom	1	ĒΑ	7	10+ years	
	Floor - Tile	Main Office Restroom	55	SF	6	10+ years	
	Floor - Tile	Main Office Restroom	5	SF	4	0-1 year	Damaged tiles
	Lavatory	Main Office Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office Restroom	1	EA	7	6-10 years	
	Partitions	Main Office Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office Restroom	390	SF	6	10+ years	
	Water Closet	Main Office Restroom	1	EA	7	10+ years	
	Accessories		10	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in teachers lounge	110	SF	7	•	
		Restroom in teachers lounge	_			10+ years	
	Doors - Wood Doors inclu hw	Restroom in teachers lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in teachers lounge	110	SF	7	10+ years	
	Hand Dryer	Restroom in teachers lounge	1	EA	7	10+ years	
	Lavatory	Restroom in teachers lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Restroom in teachers lounge	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom in teachers lounge	300	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in teachers lounge	240	SF	7	10+ years	
	Water Closet	Restroom in teachers lounge	1	EA	4	0-1 year	Not working
	Accessories	Room 008	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 008	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 008	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 008	120	SF	7	10+ years	
	Floor Drain	Room 008	1	EA	7	10+ years	
	Hand Dryer	Room 008	1	EA	7	10+ years	
	Lavatory	Room 008	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 008	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 008	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Room 008	280	SF	7	10+ years	
	Water Closet	Room 008	1	EA	7	10+ years	
Categor	y : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Campus Name: Cameron Page : 19 of 47 Assessment Date: 06/08/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,048	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	1,048	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	13	EA	7	6-10 years	
	Marker Board	Basement	20	LF	7	6-10 years	
	Storage/ Closet	Basement	42	SF	7	10+ years	
	Walls - Masonry	Basement	816	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	540	SF	7	10+ years	
	Work Sink	Basement	2	EA	7	10+ years	
Classroo	om #011 (Pre School)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	800	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	EA	7	10+ years	
	Marker Board	Basement	5	LF	7	6-10 years	
	Walls - Masonry	Basement	263	SF	7	10+ years	
	Walls - Masority Walls - Plaster/Drywall	Basement	874	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classro	om #013 (Pre School)						
Ciassion	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	7	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall		950	SF	7	-	
	Doors - Wood Doors inclu hw	Basement Basement	950	EA		10+ years	
				SF	7 7	10+ years	Quantity and rank abanged to match
	Floor - Tile	Basement	950	5F	/	10+ years	Quantity and rank changed to match current observation
	Lighting - Pendent/Surface	Basement	16	EA	7	10+ years	
	Marker Board	Basement	24	LF	7	6-10 years	
	Storage/ Closet	Basement	278	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,067	SF	7	10+ years	
	Work Sink	Basement	2	EA	7	10+ years	
Classroo	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	921	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
						,	

Campus Name: Cameron Page : 20 of 47 Assessment Date: 06/08/2022



Catego	ry : Classroom		В	uilding	: Main		TV Montteello AVENOE, Officago, ie 00051
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	921	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,473	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	6	6-10 years	
Classro	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,434	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,434	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1,434	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
		1st Floor		SF	7		
	Walls - Plaster/Drywall	181 11001	1,740	SF	1	10+ years	
Classro	om #102 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	921	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	921	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	7	10+ years	
Classro	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	921	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	921	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	7	10+ years	
Classra	om #106 (Regular Classroom)						
_Cia55100		4 at Flace			7	0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	7	10+ years	



atego	ry : Classroom		B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	830	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Broken tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	190	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	312	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,040	SF	7	10+ years	
assroc	m #107 (Store Room)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	836	SF	7	10+ years	
	Floor - Tile	1st Floor	4	SF	4	0-1 year	Broken tiles tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Dioken tiles tiles
	Marker Board	1st Floor	5	LF	7	6-10 years	
	Storage/ Closet	1st Floor	156	SF	7	•	
	Walls - Metal Panel	1st Floor	316	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,030	SF	7	10+ years 10+ years	
oceroo	om #109 (Regular Classroom)						
a55100		4 of Elean	4	ΓΛ	7	C 40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	825	SF	7	10+ years	
	Floor - Tile	1st Floor	5	SF	4	0-1 year	Broken and missing tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	152	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	316	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,030	SF	7	10+ years	
assroc	om #111 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	880	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	880	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	

Campus Name: Cameron Page : 22 of 47 Assessment Date: 06/08/2022



Catego	ry : Classroom		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	1st Floor	372	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	7	10+ years	
Classro	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	826	SF	7	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	826	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	152	SF	7	10+ years	Attendance office
	Walls - Metal Panel	1st Floor	316	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,030	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	920	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	921	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,460	SF	6	10+ years	
Classro	om #201 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	920	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Bools Inclu IIW	2nd Floor	920	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,450	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Damaged wall
Classro	om #203 (Regular Classroom)						
J1400100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7		
	Casework	ZHU FIOUI	9	LF	,	10+ years	



Catego	Category : Classroom		В	uilding	: Main		· <u> </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	920	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	920	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,440	SF	6	10+ years	
Classro	om #205 (Computer Lab)						
<u> </u>	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	938	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor		SF	7		
			938			10+ years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,824	SF	7	10+ years	<b>B</b> . II
	Walls - Plaster/Drywall	2nd Floor	15	SF	6	2-5 years	Peeling paint
	Wireless System	2nd Floor	1	EA	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	807	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracked
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	807	SF	7	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	g
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	420	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	970	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
Classroo	om #207 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	840	SF	7 7	10+ years	
				SF LF			
	Chalk Board	2nd Floor	64		4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor	840	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	189	SF	7	10+ years	

Campus Name: Cameron Page : 24 of 47 Assessment Date: 06/08/2022



Catego	ory : Classroom		В	uilding	: Main		4 N MONICEILO AVENDE, CHICAGO, IL 6063 I
3 g c	<b>,</b>		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	2nd Floor	495	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	6	10+ years	
	,		,			, , , , , ,	
Classro	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	856	SF	7	10+ years	
	Floor - Tile	2nd Floor	6	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	185	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	339	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,251	SF	7	10+ years	
Classro	om #209 (Regular Classroom)						
Classio	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	828	SF	7	10+ years	
	Floor - Tile	2nd Floor	12	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	Damagoa moo
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	495	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,155	SF	7	10+ years	
	valie i lactor/Drywan	2110 1 1001	1,100	O.	•	101 youro	
Classro	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	6	2-5 years	Peeling paint
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	840	SF	7	10+ years	
	Floor - Tile	2nd Floor	22	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	339	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,251	SF	7	10+ years	
	•					-	



Categor	y : Classroom		В	uilding	: Main		
C===	Name Time	Location	Quantity	UOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Classroo	m #211 (Regular Classroom)	0 15				0.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	5 1.0
	Floor - Tile	2nd Floor	20	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	200	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	339	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,251	SF	7	10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	826	SF	7	10+ years	
	Chalk Board	2nd Floor	5	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	808	SF	7	10+ years	
	Floor - Tile	2nd Floor	18	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	3
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	420	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroo	m #300 (Regular Classroom)						
Olassioo	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	805	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	805	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,319	SF	7	10+ years	
Classroo	m #301 (Regular Classroom)						
CIA55100		Ord Floor	4	ΓΛ	7	0.40.40.55	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor 3rd Floor	9 812	LF SF	7 7	10+ years 10+ years	
	= Piasiai/i If\/\/aii	310 F100F	812	.>-	/	TO+ VEATS	



Catego	ry : Classroom		В	uilding	: Main		THE WISHINGS IN A VENUE, Officago, IE 00001
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	812	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,322	SF	6	10+ years	
_Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	799	SF	7	10+ years	
	Chalk Board	3rd Floor	57	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	799	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	7	10+ years	
_Classroc	om #303A (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	688	SF	7	10+ years	
	Chalk Board	3rd Floor	41	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	688	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,227	SF	7	10+ years	
_Classroo	om #303B (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	563	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	563	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,102	SF	6	2-5 years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	AC SIMO	0.4 1.001	ı	_/ \	,	o io years	



Catego	ry : Classroom		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	811	SF	6	10+ years	peeling paint
	Chalk Board	3rd Floor	42	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	811	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,315	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	867	SF	7	10+ years	
	Chalk Board	3rd Floor	34	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	817	SF	7	6-10 years	
		3rd Floor		SF			Domogod tilos
	Floor - Tile		50		4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	207	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,409	SF	7	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Splined	3rd Floor	855	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	10	SF	4	0-1 year	Damaged tiles
	Chalk Board	3rd Floor	10	LF	4	2-5 years	•
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	g
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,368	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	nm #308 (Regular Classroom)						
CIUSSIUC	AC Units	3rd Floor	4	EA	7	6.10 years	
			1	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	872		7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	

Campus Name: Cameron Page : 28 of 47 Assessment Date: 06/08/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	772	SF	7	10+ years	
	Floor - Tile	3rd Floor	100	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	ŭ
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	204	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,419	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	878	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	838	SF	6	-	
				SF	-	10+ years	Domagad tiles
	Floor - Tile	3rd Floor	40		4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	17	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	190	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,462	SF	7	10+ years	
Classroc	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	863	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	813	SF	6	10+ years	
	Floor - Tile	3rd Floor	50	SF	4	0-1 vear	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	3.1.1
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	7	10+ years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	929	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	899	SF	7	10+ years	
	Floor - Tile Floor - Tile			SF SF			Damaged tiles
		3rd Floor	30		5 7	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	1	6-10 years	

Campus Name: Cameron Page : 29 of 47 Assessment Date: 06/08/2022



Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	249	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,304	SF	7	10+ years	
Classroc	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	868	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	868	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	194	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,343	SF	7	10+ years	

Category : Interior **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	6,096	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	Rank changed to match current observation
	Floor - Terrazzo	1st Floor	2,515	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	189	SF	7	10+ years	
	Floor - Wood	1st Floor	3,176	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	41	EA	7	10+ years	
	Stairs - Terrazzo	1st Floor	3	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	11,504	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5,716	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	12	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	2,541	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	10	SF	4	0-1 year	Cracked
	Floor - Tile/Sheet	2nd Floor	39	SF	7	10+ years	
	Floor - Wood	2nd Floor	3,176	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	39	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	11,033	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	215	SF	7	10+ years	

Campus Name: Cameron Page : 30 of 47 Assessment Date: 06/08/2022



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	5,766	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	6	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	5	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	2,592	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	10	SF	7	0-1 year	Cracked
	Floor - Wood	3rd Floor	3,176	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	40	EΑ	7	10+ years	
	Lighting - Wall Mounted	3rd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	12,481	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	15	SF	6	2-5 years	
	Ceiling - Lay-in	Basement	1,060	SF	7	10+ years	
	Ceiling - Lay-in	Basement	30	SF	4	0-1 year	Missing tiles
	Ceiling - Plaster/Drywall	Basement	5,626	SF	7	10+ years	•
	Doors - Steel Doors incl hw	Basement	8	EA	7	10+ years	
	Doors - Transom Window	Basement	59	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	7	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	5	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	3,938	SF	7	10+ years	
	Floor - Asphalt Floor	Basement	100	SF	5	1-2 years	Floor is deteriorating
	Floor - Terrazzo	Basement	853	SF	7	10+ years	ŭ
	Floor - Tile Ceramic/ Porcelain	Basement	348	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	1,427	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	50	SF	4	0-1 year	Broken and missing tiles
	Lighting - Lay-in	Basement	7	ĒΑ	7	10+ years	3
	Lighting - Pendent/Surface	Basement	46	EΑ	7	10+ years	
	Stairs - Concrete Stairs	Basement	7	LF	7	10+ years	
	Stairs - Terrazzo	Basement	17	LF	7	10+ years	
	Student Lockers - One Tier	Basement	6	ĒΑ	7	10+ years	
	Walls - Masonry	Basement	598	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	6,127	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	592	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement	2,375	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North Corridor of Auditorium	133	SF	7	10+ years	
	coming industry was	Platform	.00	٠.	•	,	
	Doors - Steel Doors incl hw	North Corridor of Auditorium Platform	2	EA	7	10+ years	
	Doors - Wood Doors include hw	North Corridor of Auditorium Platform	1	EA	7	10+ years	
	Floor - Terrazzo	North Corridor of Auditorium Platform	81	SF	7	10+ years	
	Floor - Tile/Sheet	North Corridor of Auditorium	48	SF	7	10+ years	



Catego	ry : Interior		В	uilding	: Main		<u> </u>
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	Platform North Corridor of Auditorium	4	SF	4	0-1 year	Missing tiles
	1 loor - Tile/Offeet	Platform	7	Oi	7	0-1 year	ivilosing tiles
	Lighting - Pendent/Surface	North Corridor of Auditorium	2	EA	7	10+ years	
	3 8	Platform				,	
	Stairs - Terrazzo	North Corridor of Auditorium	16	LF	7	10+ years	
		Platform					
	Walls - Plaster/Drywall	North Corridor of Auditorium	558	SF	7	10+ years	
	Cailing Diagtor/Drawall	Platform	227	C.E.	7	10	
	Ceiling - Plaster/Drywall	South Corridor of Auditorium Platform	327	SF	7	10+ years	
	Doors - Wood Doors include hw	South Corridor of Auditorium	4	EA	7	10+ years	
	Boole Wood Boole moldae iiw	Platform	•		•	101 youro	
	Floor - Terrazzo	South Corridor of Auditorium	277	SF	7	10+ years	
		Platform				j	
	Lighting - Pendent/Surface	South Corridor of Auditorium	2	EA	7	10+ years	
		Platform			_		
	Stairs - Terrazzo	South Corridor of Auditorium	33	LF	7	10+ years	
	Malla Diagtor/Drawall	Platform	E00	SF	7	10	
	Walls - Plaster/Drywall	South Corridor of Auditorium Platform	508	5F	/	10+ years	
	Ceiling - Plaster/Drywall	West Vestibule of Auditorium	390	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West Vestibule of Auditorium	20	SF	7	10+ years	
	Doors - Wood Doors include hw	West Vestibule of Auditorium	6	ĒΑ	7	10+ years	
	Floor - Tile Quarry	West Vestibule of Auditorium	410	SF	7	10+ years	
	Lighting - Pendent/Surface	West Vestibule of Auditorium	3	EA	7	10+ years	
	Walls - Concrete Block	West Vestibule of Auditorium	716	SF	7	10+ years	
	Walls - Plaster/Drywall	West Vestibule of Auditorium	457	SF	7	10+ years	
_Safety_							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	11 4	EA EA	7 7	6-10 years	
	Security Cameras	Entire Building	4	EA	,	6-10 years	
Stairs							
<u> </u>	Ceiling - Plaster/Drywall	East - Center of N-S corridor	700	SF	7	10+ years	
	Floor - Terrazzo	East - Center of N-S corridor	478	SF	7	10+ years	
	Handrails	East - Center of N-S corridor	168	LF	7	10+ years	
	Lighting - Pendent/Surface	East - Center of N-S corridor	6	EA	7	10+ years	
	Stairs - Terrazzo	East - Center of N-S corridor	444	LF	7	10+ years	
	Walls - Plaster/Drywall	East - Center of N-S corridor	3,063	SF	7	10+ years	
	Walls - Plaster/Drywall	East - Center of N-S corridor	20	SF	5	2-5 years	Peeling paint
	Ceiling - Plaster/Drywall	NE of Gym	81	SF	7	10+ years	
	Handrails	NE of Gym	36	LF	7	10+ years	



Category : Interior		Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_	Lighting - Pendent/Surface	NE of Gym	1	EΑ	7	10+ years		
	Stairs - Terrazzo	NE of Gym	108	LF	7	10+ years		
	Walls - Plaster/Drywall	NE of Gym	540	SF	7	10+ years		
	Ceiling - Plaster/Drywall	North - Éast of Elevator	676	SF	7	10+ years		
	Floor - Asphalt	North - East of Elevator	440	SF	7	10+ years		
	Floor - Wood	North - East of Elevator	62	SF	7	10+ years		
	Handrails	North - East of Elevator	155	LF	7	10+ years		
	Handrails	North - East of Elevator	1	LF	4	0-1 year	Broken handrail	
	Lighting - Pendent/Surface	North - East of Elevator	4	EA	7	10+ years		
	Stairs - Asphalt	North - East of Elevator	392	LF	7	10+ years		
	Stairs - Terrazzo	North - East of Elevator	133	LF	7	10+ years		
	Walls - Plaster/Drywall	North - East of Elevator	1,921	SF	7	10+ years		
	Ceiling - Plaster/Drywall	SW Corner of Assembly Hall	73	SF	7	10+ years		
	Floor - Terrazzo	SW Corner of Assembly Hall	27	SF	7	10+ years		
	Handrails	SW Corner of Assembly Hall	44	LF	7	10+ years		
	Lighting - Pendent/Surface	SW Corner of Assembly Hall	1	EA	7	10+ years		
	Stairs - Terrazzo	SW Corner of Assembly Hall	130	LF	7	10+ years		
	Walls - Plaster/Drywall	SW Corner of Assembly Hall	486	SF	6	10+ years		
	Ceiling - Plaster/Drywall	South	700	SF	7	10+ years		
	Floor - Terrazzo	South	478	SF	7	10+ years		
	Handrails	South	168	LF	7	10+ years		
	Lighting - Pendent/Surface	South	4	EA	7	6-10 years		
	Stairs - Terrazzo	South	70	LF	6	10+ years		
	Stairs - Terrazzo	South	4	LF	4	0-1 year	Damaged	
	Walls - Plaster/Drywall	South	3,083	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair SE of Gym from 3rd to 1st (stair #3)	584	SF	6	10+ years		
	Floor - Terrazzo	Stair SE of Gym from 3rd to 1st (stair #3)	323	SF	7	10+ years		
	Handrails	Stair SE of Gym from 3rd to 1st (stair #3)	186	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair SE of Gym from 3rd to 1st (stair #3)	3	EA	7	6-10 years		
	Stairs - Terrazzo	Stair SE of Gym from 3rd to 1st (stair #3)	93	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair SE of Gym from 3rd to 1st (stair #3)	3,756	SF	6	6-10 years		
Vertical (	Conveyance							
	Elevator - Hydraulic Elevator	West	1	EA	7	10+ years		

Campus Name: Cameron Page : 33 of 47 Assessment Date: 06/08/2022



Categor	ry : Exterior		В	uilding	: Annex		
0	Ham. Time	Lagation	O	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	#10 - S	1	EA	6	10+ years	
	Entrance Control - Audio	#11 - W	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#11 - W	2	EA	6	10+ years	
	Entrance Control - Audio and Video	#9 - E	1	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	#9 - E	2	EA	6	10+ years	
oundati							
	Foundation - Concrete	Entire Building	605	LF	7	10+ years	
	Superstructure - Steel	Entire Building	17,053	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	6-10 years	Quantity Adjusted
Roof Sys	stem						
	Chimney - Metal Flue	Entire Building	36	LF	6	10+ years	
	Coping - Metal	Entire Building	605	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Entire Building	72	LF	6	10+ years	
	Roof - Metal	Entire Building	16,650	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	16,650	SF	7	10+ years	
Valls							
	Canopy - Metal	Entire Building	216	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	605	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	7,001	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	259	SF	6	10+ years	
Vindows							
	Curtain wall - Louver	Entire Building	288	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	259	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,850	SF	6	10+ years	
ategoi	ry : Electrical		В	uilding	: Annex		
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
meraen	ncy System		•				
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Serves independent service, functional
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	2	0-1 year	Cleaned, functional. Glare from fixture causes iPad camera to show

Page : 34 of 47 Campus Name: Cameron Assessment Date: 06/08/2022



Catego	ry : Electrical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							glared photo, no battery, no AC
							generator
	Emergency A/C Power - Corridors and	Entire Building	2,064	SF	6	10+ years	Functional
	Stairs	· ·				•	
	Emergency A/C Power - Students Toilets	Entire Building	767	SF	6	10+ years	Functional
	Security System - CCTV	Entire Building	17,053	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	17,053	SF	6	6-10 years	
	• •	· ·				·	
ain Se	rvice						
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	ATS and a second meter, serves
	emergency power					,	annex
	Main Electrical Service - 800 A and	Electrical Room	1	EA	6	10+ years	Serves annex building, 800 Amp
	120/208/3PH					, , , , , ,	3, 111
	PA System	Entire Building	17,053	SF	6	6-10 years	Connected to main building
	·	-				-	_
ower D	istribution						
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	10+ years	2005 installation
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	7	10+ years	
	Main Distribution Panels - Less than 400	Electrical Room	1	EA	7	10+ years	
	amp					•	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	10+ years	
						-	
atego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Ala	•	Location	Quantity	OO!!!	Rum	Ropidocinoni	Commente
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	Connected to main building, serves annex, not connected to city. Passes fire marshal inspection
	Fire Alarm Strobe Lights	Electrical Room	17,053	SF	6	10+ years	Functional
	Fire Alarm_System	Electrical Room	17,053	SF	6	10+ years	Connected to main building, serves annex
Sprinkle	r System						
•	Sprinkler Heads	Entire Building	17,053	SF	7	10+ years	Functional
	Sprinkler Piping	Entire Building	17,053	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	17,053	SF	6	10+ years	2005 installation, using city water

Campus Name: Cameron Page : 35 of 47 Assessment Date: 06/08/2022



**Building: Annex Category : Fire Protection** 

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments

pressure

Duilding . Annov

Category : Mechanical			В	uilding	: Annex		
Group I	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	oning Condensing Unit- Ground Mounted - Less than 5 tons	MDF/Communication Room 126	1	EA	6	10+ years	Serves fan coil in MDF room, mounted to an exterior wall
Air Handlin	ng Systems						
<i>,</i> I	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000	Mechanical Room	1	EA	6	6-10 years	Serves annex, corridor
	cfm Air Intake	Mechanical Room	1	EA	6	10+ years	
Boiler Syst	tems						
·	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Mechanical Room	2	EA	5	10+ years	
	Chemical Pot Feeder	Mechanical Room	1	EA	5	6-10 years	Manually fed, previously not assessed, not painted
	Combustion Dampers	Mechanical Room	2	EA	6	10+ years	
	Glycol Feed System	Mechanical Room	1	EA	6	6-10 years	Functional, manually fed
	Hot Water Pump	Mechanical Room	2	EA	5	6-10 years	Previously not assessed
-	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Mechanical Room	2	EA	5	10+ years	Serve annex building
	Piping - Chilled Water Pipes- Steel	Mechanical Room	100	LF	5	10+ years	Hot water pipes, hydronic, no chiller
	Water Fill System	Mechanical Room	1	EA	5	6-10 years	, , , , ,
Heating De	evices						
•	Unit Heater - Hot Water	Entire Building	2	EA	5	6-10 years	Recently cleaned
(	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	10+ years	Ceiling mounted
Temperatu	ire Control						
· I	Electric Controls	Entire Building	17,053	SF	5	6-10 years	No DDC, no pneumatics, local electrical controls, serves univents
I	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve unit heaters, previously not assessed
Unit Ventila	ation						
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self	1st Floor	13	EA	6	6-10 years	Hot water

Page : 36 of 47 Campus Name: Cameron Assessment Date: 06/08/2022



		Building : Annex						
y . Miechanicai		<u> </u>	unung	. Alliex				
Item - Type	Location	Quantity	UOM	Rank		Comments		
ın								
	Roof	2	FΔ	6	6-10 years	Sloped metal roof not accessed		
	11001	_	L/\	U	o to years	Cioped metal roof not accessed		
- · · · ·	Roof	1	FA	6	6-10 years			
CFM	. 100.	•		Ū	0 .0 ,00.0			
y : Plumbing		В	uilding	: Annex				
,					Recommend			
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		•			•			
	Mechanical Room	1	FΔ	-5	6-10 years	Serves annex, functional		
Cas ricater 100000 000000 BTO/TIK	Weenamear Room		L/\	J	o io years	Cerves armex, ranellorial		
Domestic Pining-Hot Water Return Lines	Entire Building	17 053	SF	6	10+ vears	No leaks		
					•	No leaks		
. •	Entire Building	17,000	O.	Ū	Tot youro			
	Entire Building	17.053	SF	6	6-10 years	2005 installation		
	g	,	-	-	,			
Domestic Piping-Hot/Cold Water Supply	Entire Building	17,053	SF	6	10+ years	2005 installation		
(from Risers to Fixtures)	•				•			
	Entire Building	17,053	SF	6	10+ years			
	Entire Building	17,053		6	10+ years	Sloped metal roof not accessed		
Vent Piping	Entire Building	17,053	SF	6	10+ years	Sloped metal roof not accessed		
_		_		_				
ry:Room		В	uilding	: Annex				
	Location	Quantity	UOM	Rank	Replacement	Comments		
			_					
					-			
					•			
					•			
Walls - Plaster/Drywall	110	590	SF SF	7	-			
vvana * Ligalei/Divvali	-	182	SF	7	10+ years 10+ years			
	128 Storage				IUT VEGIS			
Ceiling - Lay-in	128 Storage					Water damage tiles		
Ceiling - Lay-in Ceiling - Lay-in	128 Storage	8	SF	4	0-1 year	Water damage tiles		
Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw	128 Storage 128 Storage	8 1	SF EA	4 7	0-1 year 10+ years	Water damage tiles		
Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile	128 Storage 128 Storage 128 Storage	8 1 190	SF EA SF	4 7 7	0-1 year 10+ years 10+ years	Water damage tiles		
Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw	128 Storage 128 Storage	8 1	SF EA	4 7	0-1 year 10+ years	Water damage tiles		
	Item - Type  Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	tem - Type Contained Compressor  Exhaust Fans- Roof Mounted - 1501 - 8000 CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM  Exhaust Fans- Roof Mounted - 500 - 1500 CFM  Ty: Plumbing  Item - Type Location  If Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping Storm Piping Storm Piping Entire Building Entire Building Entire Building Fixer	tem - Type Location Quantity  Exhaust Fans- Roof Mounted - 1501 - 8000 Roof 2  CFM Exhaust Fans- Roof Mounted - 500 - 1500 Roof 1  Ty: Plumbing Butem - Type Location Quantity  Tig Gas Heater - 150000 - 300000 BTU/HR Mechanical Room 1  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Sanitary Piping Entire Building 17,053  Sanitary Piping Entire Building 17,053  Vent Piping Entire Building 17,053  Vent Piping Entire Building 17,053  Ty: Room Butem - Type Location Quantity  Item - Type Location Quantity  Entire Building 17,053  Ty: Room Butem - Type Location Quantity  Entire Suilding 17,053  Ty: Room Butem - Type Location Quantity  Entire Suilding - Lay-in 110 352  Lighting - Lay-in 110 352	tem - Type Location Quantity UOM Contained Compressor  Exhaust Fans- Roof Mounted - 1501 - 8000 CFM Exhaust Fans- Roof Mounted - 500 - 1500 Roof 2 EA CFM Exhaust Fans- Roof Mounted - 500 - 1500 Roof 2 EA Exhaust Fans- Roof Mounted - 500 - 1500 Roof 1 EA  Ty: Plumbing Building  Item - Type Location Quantity UOM  IT  Gas Heater - 150000 - 300000 BTU/HR Mechanical Room 1 EA  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply Entire Building 17,053 SF Fixtures Domestic Piping-Hot/Cold Water Supply Entire Building 17,053 SF (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 17,053 SF (Sanitary Piping Entire Building 17,053 SF Storm Piping Entire Building 17,053 SF Vent Piping Entire Building 17,053 SF (Ty: Room Building 17,053 SF  Ty: Room Building  Item - Type Location Quantity UOM  Tative Suites/Offices  Ceiling - Lay-in 110 352 SF Lighting - Lay-in 110 352 SF Lighting - Lay-in 110 4 EA  Power Distribution 10 EA		Name		

Campus Name: Cameron Page : 37 of 47 Assessment Date: 06/08/2022



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	128 Storage	413	SF	7	10+ years	
	Walls - Plaster/Drywall	128 Storage	288	SF	7	10+ years	
MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	80	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Split unit
/lechani	ical/ Service Rooms						
noonan	Boiler Room	1st Floor	412	SF	7	10+ years	
	Janitor's Closet	1st Floor	33	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	197	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	62	SF	7	10+ years	
Restroor	m						
<u>KOOH OOI</u>	Accessories	1st Floor	227	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	227	SF	7	10+ years	
	Floor - Concrete	1st Floor	216	SF	5	1-2 years	Peeling paint
	Floor - Tile	1st Floor	11	SF	7	10+ years	. Journal barret
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	4	0-1 year	Does not work
	Lavatory	1st Floor	4	EA	7	10+ years	Does not work
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	5	1-2 years	No cover
	Partitions	1st Floor	3	EA	7	10+ years	NO COVE
	Urinals	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	605	SF	7	10+ years	
	Water Closet	1st Floor	3		7	10+ years 10+ years	
	Accessories	1st Floor	540	EA SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	540	SF	7	10+ years	
	Floor - Concrete	1st Floor	540	SF			Decling point
	Floor - Concrete Floor Drain	1st Floor		EA	5	1-2 years	Peeling paint
			2		7	10+ years	
	Hand Dryer	1st Floor 1st Floor	1	EΑ	7	6-10 years	
	Lavatory		4	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	10+ years	Deint headly, deteriors to d
	Partitions	1st Floor	11	EA	5	1-2 years	Paint badly deteriorated
	Walls - Concrete Block	1st Floor	1,340	SF	7	10+ years	
	Water Closet	1st Floor	11	EA	7	10+ years	
	Accessories	Men	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men	45	SF	7	10+ years	
	Doors - Steel Doors incl hw	Men	1	EA	7	10+ years	
	Floor - Tile	Men	45	SF	7	10+ years	
	Floor Drain	Men	1	EΑ	7	10+ years	



Catego	ry : Room		В	uilding	: Annex		THINISTREE NO AVENUE, Officago, IE 00001
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Men	2	EA	7	10+ years	
	Walls - Concrete Block	Men	262	SF	7	10+ years	
	Water Closet	Men	1	EΑ	7	10+ years	
	Accessories	Women	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	Women	1	EA	7	10+ years	
	Floor - Tile	Women	42	SF	7	10+ years	
	Floor - Tile	Women	2	SF	5	1-2 years	Broken tiles
	Floor Drain	Women	1	EA	7	10+ years	
	Lavatory	Women	1	EΑ	7	10+ years	
	Lighting - Lay-in	Women	1	EA	7	10+ years	
	Walls - Concrete Block	Women	252	SF	7	10+ years	
	Water Closet	Women	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Annex		
_				_		Recommend	
Group	<b>7</b> 1	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #400 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	835	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	4	0-1 year	Water damage tiles
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	855	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	932	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
Classroo	om #401 (Computer Lab)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	865	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	865	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	932	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
OI-	1/400 /B						
Classroo	om #402 (Regular Classroom)	4 a t 🗆 c - :-	40			40	
	Casework	1st Floor	19	LF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		TV Monticello AVENOE, Onicago, ie 00007
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	855	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	855	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	687	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	490	SF	7	10+ years	
Classroo	m #403 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	674	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	480	SF	7	10+ years	
	walls - Flastel/Drywall	ist Floor	400	SF	,	10+ years	
_Classroo	m #404 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	855	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	853	SF	7	10+ years	
	Floor - Tile	1st Floor	2	SF	4	0-1 year	Broken tiles
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	937	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
Classroo	m #405 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	11	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	500	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	674	SF	7	10+ years	
_Classroo	m #406 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Annex	(	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	855	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	855	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	500	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	627	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	7	10+ years	
Classroo	om #407 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	880	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	7	•	
					7	6-10 years	
	Walls - Concrete Block	1st Floor	590	SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	554	SF	7	10+ years	
Classroo	om #408 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	855	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	855	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	637	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	500	SF	7	10+ years	
Classroo	om #409 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	11	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	11	LF	7		
			674	SF	7 7	6-10 years	
	Walls - Concrete Block	1st Floor	6/4	<b>3</b> F	1	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	470	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	30	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #410 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	855	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	855	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	637	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	500	SF	7	10+ years	
Classroo	m #411 (Regular Classroom)						
	Casework	1st Floor	19	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	11	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	Quantity and rank changed to mate
	Marker Board	1st Floor	12	LF	7	6-10 years	current observation
	Walls - Concrete Block	1st Floor	674	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	490	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,961	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	Water damage tiles
	Ceiling - Plaster/Drywall	1st Floor	158	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	9	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Tile Quarry	1st Floor	79	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,985	SF	7	10+ years	
		1st Floor	22	EA	7	6-10 years	
	Lighting - Lay-in	151 11001	22	EA	1	0-10 years	



Category : Interior			Building : Annex					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Safety								
,	Security Cameras	1st Floor	1	EA	7	6-10 years		

Campus Name: Cameron Page: 43 of 47 Assessment Date: 06/08/2022





Category : Site **Building: Site** 

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	South	1,285	SF	4	1-2 years	Broken/Cracked/Uneven - Trip
							hazards
Civil/Dra	inaga						
CIVII/DIa	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Catch Basin	Entire Site	1	EA	, 5	2-5 years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Catch Basin	Entire Site	2	EA	5	2-5 years 2-5 years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site	15	EA	5 7	10+ years	
	Civil/ Drainage - Site Marinole	chille Site	15	EA	,	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	640	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	60	LF	4	1-2 years	Bent/broken/Ripped/Leaning
	Fencing - New Standard Ornamental	Entire Site	490	LF	6	10+ years	
Landsca	pe						
	Benches	Entire Site	1	EA	6	10+ years	
	Landscape - Grass	Entire Site	7,424	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,188	SF	4	0-1 year	Cracked/Broken
	Lighting - Pole Mounted	Entire Site	2	ĒΑ	7	10+ years	Site lighting - Behind/South of Annex
	Parkway trees	Entire Site	20	EA	6	10+ years	3 . 3
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing tree
	Planting Beds/ Area	Entire Site	410	SF	6	10+ years	3
	Play Area - Hardscape- Asphalt	Entire Site	2,000	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	595	SF	4	1-2 years	Disjointed/Misaligned/Broken and
	.,					,	cracked
	Play Area - Hardscape- Asphalt	Entire Site	3,030	SF	4	0-1 year	Trip Hazards:
	,		2,223			· , , · · · ·	Uneven/Cracked/Broken/vegetative
							growth in cracks and material
							deterioration at edges
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
Parking	Lot						
_r arking_	Concrete Curbs	SW	340	LF	6	10+ years	
	Interior Plantings	SW	60	LF	6	10+ years	
	Lighting - Pole Mounted	SW	2	EA	6	10+ years	Quantity Adjusted: 2 pole lights are
	Lighting - Pole Mounted	SVV	2	LA	Ü	10+ years	behind/south of annex, annotated in
	Curfo o Aordo de	CVA	45.000	C.E.	0	40	"Landscaping".
	Surface - Asphalt	SW	15,080	SF	6	10+ years	
	Trash Enclosure - Chain Links	SW	400	SF	6	10+ years	



Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Playgrou	und						
	Equipment - Combo 3-12	NW	1	EA	6	10+ years	
	Surface - Poured Surface	NW	2,438	SF	6	10+ years	
	Equipment - Pre K 3-5	South	1	EA	7	10+ years	
	Surface - Poured Surface	South	1,250	SF	4	0-1 year	Section ripped away, adherence to substrate deteriorating, holes and gashes.
	Surface - Poured Surface	South	2,440	SF	4	0-1 year	Holes/ripped with gashes. Deteriorating edges, deteriorating from substrate.
	Surface - Poured Surface	South	1,250	SF	4	0-1 year	Holes and gaps/Missing section of material
	Surface - Square Rubber Mats	South	383	SF	4	0-1 year	Gaps/Vegetative growth between tiles/ with missing mats/tiles.
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	110	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	60	LF	4	1-2 years	Cracked/Broken/Deterioration
	Sidewalks - Perimeter Sidewalks	Entire Site	14,747	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	125	SF	4	1-2 years	Cracked/Broken
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	4	1-2 years	Cracked/Broken
	Sidewalks - Perimeter Sidewalks	Entire Site	125	SF	4	1-2 years	Cracked/Broken
Signage							
	Flag Pole - Flag Pole	NW, East and North	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	NW, East and North	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	NW, East and North	3	EA	6	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Cameron Page: 45 of 47 Assessment Date: 06/08/2022

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classiconi Summary			_	Floor Plan	_	Glazed	Operable		
0	1.4. 1.11	5	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main Computer Lab	Regular Classroom	2nd Floor	205	Teacher's	938	208	84	Υ	N
Computer Lab	Regular Classicom	Zilu Flooi	205	Lunch	936	208	04	r	IN
Kindergarten	Regular Classroom	1st Floor	111	107	880	260	105	Υ	N
Music Room	Regular Classroom	2nd Floor	207	207	840	208	84	Y	N
Pre School	Pre School	Basement	008	201	1,048	80	40	Y	N
Pre School	Pre School	Basement	011	011	800	80	40	N	Y
Pre School	Pre School	Basement	013	013	950	80	40	N	Y
				013				Y	
Regular Classroom	Library	1st Floor	101	404	1,434	208	84		N
Regular Classroom	Regular Classroom	1st Floor	100	101	921	208	84	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	921	208	84	Y	N
Regular Classroom	Regular Classroom	1st Floor	104	104	921	208	84	Y	N
Regular Classroom	Regular Classroom	1st Floor	106	104	840	208	84	Y	N
Regular Classroom	Regular Classroom	1st Floor	109	106	830	208	84	Y	Y
Regular Classroom	Regular Classroom	1st Floor	112	108	826	208	84	Y	N
Regular Classroom	Regular Classroom	2nd Floor	200	202	920	208	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	204	920	208	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	827	84	12	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	862	208	84	Y	N
Regular Classroom	Regular Classroom	2nd Floor	209	210	840	208	84	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210	208A	862	208	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	900	208	84	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	826	208	84	Y	N
Regular Classroom	Regular Classroom	3rd Floor	300	302	805	192	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	812	204	102	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	303	799	212	106	N	N
Regular Classroom	Regular Classroom	3rd Floor	303A	Home Mech	688	153	77	N	N
				room					
Regular Classroom	Regular Classroom	3rd Floor	303B	Home Mech	563	153	77	N	N
				Room					
Regular Classroom	Regular Classroom	3rd Floor	304	304	811	212	106	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	867	144	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	305	865	194	97	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	307	872	144	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	308	878	114	57	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	309	863	144	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	310	929	294	147	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	311	868	204	102	N	N
Store Room	Regular Classroom	1st Floor	107	105	840	228	94	Y	N



**Classroom Summary** 

Oursell Heave	lates de dille and	Barra Laradian	Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Store Room	Regular Classroom	2nd Floor	201	201	920	208	84	Υ	N
Building : Annex									
Computer Lab	Regular Classroom	1st Floor	401	123	865	147	74	Υ	N
Regular Classroom	Regular Classroom	1st Floor	400	124	855	144	60	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	402	122	855	144	60	Υ	N
Regular Classroom	Regular Classroom	1st Floor	403	121	870	147	74	Υ	N
Regular Classroom	Regular Classroom	1st Floor	404	108	855	144	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	405	104	870	147	74	N	N
Regular Classroom	Regular Classroom	1st Floor	406	107	855	144	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	407	103	880	147	74	Y	N
Regular Classroom	Regular Classroom	1st Floor	408	106	855	144	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	409	102	870	147	74	Y	N
Regular Classroom	Regular Classroom	1st Floor	410	105	855	144	60	Υ	N
Regular Classroom	Regular Classroom	1st Floor	411	101	870	147	74	Y	N