

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1959	2	56,732
Addition	1963	2	11,452
Campus Total			68,184

Category : Exterior Building : Main

	.y . =xto.i.e.			uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	•						
	Entrance Control - Audio and Video	#1- Main Accessible- NE	1	EA	6	10+ years	
	Exterior Doors - Side lite	#1- Main Accessible- NE	2	EA	6	10+ years	
	Exterior Doors - Store Front	#1- Main Accessible- NE	2	EA	6	10+ years	
	Exterior Doors - Side lite	#10- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Store Front	#10- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Side lite	#11- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Store Front	#11- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11- SW-courtyard	1	EA	6	10+ years	
	Exterior Doors - Side lite	#2- NW	2	EA	6	10+ years	
	Exterior Doors - Store Front	#2- NW	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#2- NW	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	#3- SW	2	EΑ	6	10+ years	
	Exterior Doors - Store Front	#3- SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3- SW	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	#4- SW	2	EA	6	10+ years	
	Exterior Doors - Store Front	#4- SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4- SW	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4.1- Boiler Room- SW	2	EA	4	1-2 years	Severe rust on bottom of door, right leaf
	Exterior Stairs - Concrete	#4.1- Boiler Room- SW	80	LF	4	1-2 years	Chipped throughout
	Stair Handrail - Steel_Stair Handrail	#4.1- Boiler Room- SW	27	LF	6	6-10 years	5
	Stair Handrail - Steel_Stair Handrail	#4.1- Boiler Room- SW	20	LF	3	0-1 year	No handrail or guardrail on west side

Campus Name: Chalmers Page : 1 of 31 Assessment Date: 07/12/2021



Category : Exterior		В	uilding		<u> </u>		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	#5- SW	2	EA	6	10+ years	
	Exterior Doors - Store Front	#5- SW	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#5- SW	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#5- SW	25	LF	5	1-2 years	Spalling, holes throughout
	Entrance Control - Audio and Video	#6 - SE	1	EA	6	10+ years	
	Exterior Doors - Side lite	#6 - SE	2	EA	6	10+ years	
	Exterior Doors - Store Front	#6 - SE	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9- NE	2	EA	6	10+ years	
Foundati	on						
	Foundation - Concrete	Entire Building	931	LF	7	10+ years	
	Foundation - Concrete	Entire Building	23	LF	6	10+ years	Quantities combined
	Foundation - Concrete	Entire Building	10	LF	6	10+ years	
	Superstructure - Concrete	Entire Building	56,732	SF	7	10+ years	
Lighting							
- 5 - 5	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	1-2 years	Not working according to engineer
Roof Svs	tem						
,	Access Ladder - Metal	Main	1	EA	7	6-10 years	
	Chimney - Metal Flue	Main	42	LF	6	10+ years	
	Coping - Metal	Main	860	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main	144	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Main	29,206	SF	5	2-5 years	
	Roof Hatch - Metal	Main	1	ĒΑ	7	10+ years	
	Roof Structure - Concrete	Main	29,206	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	7,832	SF	6	10+ years	
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	7,924	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	3,976	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	2,808	SF	6	10+ years	
	Lintels - Steel	Entire Building	6	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	60	SF	6	6-10 years	
	pane	3		•	-	,	
	Windows - Casement Aluminum Double- pane	Entire Building	980	SF	6	6-10 years	
Catego	ry : Electrical		R	uilding	· Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	item - Type	Location	Quantity	OOM	Nank	Necommend	Comments



						Replacement	
morgor	ncy System					rtopiacomont	
merger	UPS - Less than 30 KW	2nd Floor	1	EA	6	2 F voors	
			1		6 7	2-5 years	The building engineer was not
	Automatic Transfer Switch	Electrical Room	1	EA	,	6-10 years	The building engineer was not present- I couldn't determine what this ATS doing since the school doesn't have a generator.
	Security System - CCTV	Entire Building	56,732	SF	7	6-10 years	3
	Security System - Intrusion Detection	Entire Building	56,732	SF	6	2-5 years	
	Emergency A/C Power - Corridors and	Entire Building	2	SF	7	6-10 years	
	Stairs	Entire Ballating	_	O.	•	o ro youro	
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building	7	ΕA	7	6-10 years	
	3 - 3,	3				,	
/lain Se							
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	7	6-10 years	
	120/208/3PH				_		
	PA System	Entire Building	56,732	SF	5	2-5 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	2nd floor, no access inside
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	. 1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 2777400 - 120/200	Littile building	·	LA	,	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Alar		Location	Quantity	COM	Rain	Replacement	Comments
	Fire Alarm Panel	Mechanical Room	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Mechanical Room	56,732	SF	7	6-10 years	
	Fire Alarm_System	Mechanical Room	56,732	SF	7	6-10 years	
:atego	ry : Mechanical		В	uilding	: Main		
go	. y					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments



Catego	ry : Mechanical		В	uilding	: Main		, <u>, , , , , , , , , , , , , , , , , , </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chemical Pot Feeder	Roof	1	EA	7	6-10 years	
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Roof	1	EA	7	6-10 years	
	- 50 - 100 tons				_		
	Glycol Feed	Roof	1	EA	7	6-10 years	
	Pipes - Chilled Water Pipe- Copper	Roof	200	LF.	6	10+ years	
	Chemical Pot Feeder	Roof	1	EΑ	7	6-10 years	
	Chiller-Air Cooled-Scroll Type-Roof Mounted - Less than 50 tons	Roof	2	EA	7	10+ years	
	Glycol Feed	Roof	1	EA	7	6-10 years	
	Pipes - Chilled Water Pipe- Copper	Roof	200	LF	7	10+ years	
	Fipes - Crillied Water Fipe- Copper	Kool	200	LF	,	10+ years	
_Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	2nd floor MDF Room	1	EA	7	6-10 years	
	Air Handling Unit-Package Single Zone-	Boiler Room	1	EA	6	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	20001-30000 cfm						
	Air Intake	Boiler Room	1	EA	6	10+ years	
	Zone Dampers	Boiler Room	30	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	
	Indoor- Hot Water and Chilled Water Coils -						
	12001-20000 cfm	Mechanical Room	4	EA	6	10	
	Air Intake Zone Dampers	Mechanical Room	1 30	EA EA	6 7	10+ years 6-10 years	
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	
	Cage - Greater than 20000 CFM	Wechanical Room	ı	LA	U	0-10 years	
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	10+ years	
	Cage - 10001 - 20000 CFM	Modrialisal Room	·		J	101 youro	
_Boiler Sy							
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	7	10+ years	
	Glycol Feed System	Boiler Room	1	EA	7	6-10 years	
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	6	10+ years	
	Tube- Force Draft- Hot Water Boiler - 2001						
	- 3000 MBH						
_Heat Exc	phongore						
_ I I Cal EXI	Heat Exchanger - Water to Water Plate	Mechanical Room	1	EA	6	6-10 years	
	Type	WEGIAIIIGAI KOOIII	ı	EA	U	0-10 years	
	1,750						
Heating	Devices						
3							



	SCHOOIS					21	745 W Roosevelt ROAD, Chicago, IL 60608
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cabinet Heaters - With Electric Coil	1st Floor	2	EA	6	6-10 years	
	Unit Heater - Electric	2nd Floor	1	EA	6	2-5 years	
	Unit Heater - Electric	2nd Floor	1	EA	5	2-5 years	
Mechani	cal Plumbing						
	Chilled Water Pump - Less than 10	Boiler and Mechancial Rooms	4	EA	7	2-5 years	
	Chilled Water Pump - Less than 10	Boiler and Mechancial Rooms	2	EA	7	2-5 years	
	Hot Water Pump - Less than 10	Boiler and Mechanical Rooms	2	EA	7	2-5 years	
	Hot Water Pump - Less than 10	Boiler and Mechanical Rooms	2	EA	7	2-5 years	
	Hot Water Pump - Less than 10	Boiler and Mechanical Rooms	2	ĒΑ	7	2-5 years	
	Hydronic Supply and Return - Copper	Entire Building	400	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	6-10 years	
	Trydromo duppry and Notari Otoci	Entire Ballating	100		J	o ro youro	
_Tempera	ature Control						
	DDC System	Entire Building	56,732	SF	7	6-10 years	
	Thermostats - DDC	Entire Building	64	ĒΑ	7	6-10 years	
	Thermostats - DDC	Entire Building	1	EA	7	2-5 years	
		g	•		•	7 - 5	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Electric-	Entire Building	52	EA	6	6-10 years	
	Electric Heating & DX Cooling Coil W/	3			-	, , , , , , , , , , , , , , , , , , ,	
	Remote Mounted Compressor						
	•						
_Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	6	6-10 years	
	CFM					•	
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	2	EA	6	6-10 years	
	CFM					•	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	-	LUCALIUII	Quantity	UOW	Kalik	Replacement	Comments
Hot Wate		D :					
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	
Piping							
 	Domestic Piping-Hot Water Return Lines	Entire Building	56,732	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	56,732	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	56,732	SF	6	10+ years	
	Fixtures	0 Danaing	00,702	٥.	J	io. youro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	56,732	SF	6	10+ years	
	2 s sollo i iping i lot sollo trator suppry	0 Danaing	00,702	٥.	J	io. youro	



Catego	ry : Plumbing		В	uilding				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	(Horizontal Lines)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	56,732	SF	6	10+ years		
	(Risers)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	56,732	SF	6	10+ years		
	(from Risers to Fixtures)							
	Sanitary Piping	Entire Building	56,732	SF	6	10+ years		
	Storm Piping	Entire Building	56,732	SF	6	10+ years		
	Vent Piping	Entire Building	56,732	SF	6	10+ years		
Pumps								
	Pumps - Ejector-Duplex	Boiler and Mechancial Rooms	1	EA	6	2-5 years		
	Pumps - Sump-Duplex	Boiler and Mechancial Rooms	1	EA	7	6-10 years		

Category: Room **Building: Main**

Quantity	UOM	Rank	Recommend Replacement	Comments
1, 355	SF	6	10+ years	Incorrect quantity previously
1, 40	SF	6	10+ years	
1, 12	SF	6	10+ years	
1, 1	EA	6	10+ years	
1, 275	SF	6	6-10 years	Incorrect quantity previously
1, 80	SF	7	10+ years	Asset not previously assessed
1, 9	EA	6	6-10 years	
1, 12	EA	6	10+ years	
1, 131	SF	5	10+ years	
1, 348	SF	5	10+ years	
2 942	SF	6	10+ years	
2 4	EA	6	10+ years	
2 942	SF	6	10+ years	
2 8	EA	6	6-10 years	
2 12	EA	6		
2 107	SF	5	10+ years	
2 1,620	SF	6	10+ years	
	1, 355 1, 40 1, 12 1, 1 1, 275 1, 80 1, 9 1, 12 1, 131 1, 348 2 942 2 4 2 942 2 942 2 8 2 12 2 107	1, 355 SF 1, 40 SF 1, 12 SF 1, 1 EA 1, 275 SF 1, 80 SF 1, 9 EA 1, 12 EA 1, 131 SF 1, 348 SF 2 942 SF 4 EA 2 942 SF 2 942 SF 4 EA 2 942 SF 2 8 EA 2 12 EA 107 SF	1, 355 SF 6 1, 40 SF 6 1, 12 SF 6 1, 1 EA 6 1, 275 SF 6 1, 80 SF 7 1, 9 EA 6 1, 12 EA 6 1, 131 SF 5 1, 348 SF 5 2 942 SF 6 3 EA 6 2 12 EA 6	1, 355 SF 6 10+ years 1, 40 SF 6 10+ years 1, 12 SF 6 10+ years 1, 1 EA 6 10+ years 1, 275 SF 6 6-10 years 1, 80 SF 7 10+ years 1, 9 EA 6 6-10 years 1, 12 EA 6 10+ years 1, 131 SF 5 10+ years 1, 348 SF 5 10+ years 2 942 SF 6 10+ years 3 EA 6 6-10 years 3 EA 6 6-10 years 4 EA 6 10+ years 5 10+ years

Campus Name: Chalmers Page : 6 of 31 Assessment Date: 07/12/2021



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work SInk	1st flr south of classroom #102	1	EA	7	10+ years	Not previously assessed
	Ceiling - Splined	2nd flr north of library	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr north of library	1	EA	6	10+ years	
	Floor - Tile	2nd flr north of library	230	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd flr north of library	4	EA	6	6-10 years	
	Power Distribution	2nd flr north of library	6	EA	6	10+ years	
	Walls - Concrete Block	2nd flr north of library	594	SF	6	10+ years	
	Ceiling - Splined	Assistant principal (across from 201)	550	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant principal (across from 201)	1	EA	7	10+ years	
	Floor - Tile	Assistant principal (across from 201)	550	SF	7	10+ years	
	Lighting - Pendent/Surface	Assistant principal (across from 201)	8	EA	7	6-10 years	
	Power Distribution	Assistant principal (across from 201)	2	EA	7	10+ years	
	Walls - Concrete Block	Assistant principal (across from 201)	550	SF	7	10+ years	
	Ceiling - Exposed	Basement engineer's office	280	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement engineer's office	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement engineer's office	280	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement engineer's office	6	ĒΑ	6	10+ years	
	Power Distribution	Basement engineer's office	6	EA	6	10+ years	
	Walls - Concrete Block	Basement engineer's office	612	SF	6	10+ years	
	Ceiling - Splined	First floor principal office	340	SF	7	10+ years	
	Doors - Transom Window	First floor principal office	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor principal office	3	EA	7	10+ years	
	Floor - Carpet	First floor principal office	340	SF	7	6-10 years	
	Lighting - Pendent/Surface	First floor principal office	4	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	First floor principal office	1	EΑ	5	2-5 years	
	Power Distribution	First floor principal office	4	EA	7	10+ years	
	Storage/ Closet	First floor principal office	20	SF	7	10+ years	
	Walls - Concrete Block	First floor principal office	580	SF	7	10+ years	
	Walle Collecte Blook	r not neer principal emee	000	O.	•	ro. youro	
_Gymnas	ia						
	Ceiling - Splined	1st Floor	3,768	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Floor - Sport Flooring	1st Floor	3,768	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	38	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	504	SF	6	10+ years	
	Stage Curtain	1st Floor	2	EA	7	6-10 years	Not previously assessed
	Stage Lift	1st Floor	1	EA	5	10+ years	-
	Stage Lighting System	1st Floor	1	EA	5	6-10 years	
	Stage-Stairs - Wood	1st Floor	6	LF	7	10+ years	Not previously assessed
	Storage/ Closet	1st Floor	20	SF	7	10+ years	Not previously assessed
	Storage/ Closet	1st Floor	20	SF	5	10+ years	Not previously assessed
	Walls - Concrete Block	1st Floor	5,386	SF	7	10+ years	
						-	



Category : Room		В	uilding	: Main	-		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ibrary		- .					
	Casework	2nd Floor	67	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,326	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	1,326	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,721	SF	6	10+ years	
MDF ID	F.						
_	Doors - Steel Doors incl hw	2nd flr south of Rm #210	1	EA	6	10+ years	
	Finishes	2nd flr south of Rm #210	225	SF	7	10+ years	
	Other Cooling Unit	2nd flr south of Rm #210	1	EA	7	6-10 years	
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	65	SF	5	10+ years	
	Storage Room	1st Floor	100	SF	7	10+ years	
	Storage Room	1st Floor	140	SF	5	10+ years	
	Vaults	1st Floor	120	SF	7	10+ years	Not previously assessed
	Janitor's Closet	2nd Floor	85	SF	7	10+ years	The provided of the provided o
	Boiler Room	Basement	2,466	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,691	SF	7	10+ years	
	Storage Room	Basement	455	SF	7	10+ years	
Restroor	_						
estroor	Accessories	1st flr inside principal's office	48	SF	5	6-10 years	
	Ceiling - Exposed	1st flr inside principal's office	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	45	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	3	SF	4	0-1 year	Missing tiles
	Lavatory	1st flr inside principal's office	1	EA	6	6-10 years	Wilson'ig tiles
	Lighting - Wall Mounted	1st flr inside principal's office	1	EA	6	10+ years	
	Partitions	1st fir inside principal's office	1	EA	7	10+ years	
	Walls - Concrete Block	1st flr inside principal's office	103	SF	6	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	1st fir inside principal's office	206	SF SF	6	10+ years 10+ years	
	Water Closet	1st fir inside principal's office		SF EA	6	-	
			1	SF		10+ years	
	Accessories	1st fir next to main office suite	48	SF SF	5	6-10 years	
	Ceiling - Exposed Doors - Wood Doors inclu hw	1st fir next to main office suite	48		6	10+ years	
		1st flr next to main office suite	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr next to main office suite	48	SF	6	10+ years	
	Lavatory	1st flr next to main office suite	1	EΑ	6	10+ years	
	Lighting - Wall Mounted	1st flr next to main office suite	1	EΑ	6	10+ years	
	Partitions	1st flr next to main office suite	1	EA	5	10+ years	



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st flr next to main office suite	103	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st flr next to main office suite	206	SF	6	10+ years	
	Water Closet	1st flr next to main office suite	1	EA	6	10+ years	
	Accessories	1st flr north of classroom #107	251	SF	5	6-10 years	
	Ceiling - Splined	1st flr north of classroom #107	251	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr north of classroom #107	251	SF	6	10+ years	
	Floor Drain	1st flr north of classroom #107	1	EΑ	7	10+ years	
	Hand Dryer	1st flr north of classroom #107	2	EΑ	5	6-10 years	
	Lavatory	1st flr north of classroom #107	3	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st flr north of classroom #107	3	EA	6	6-10 years	
	Partitions	1st flr north of classroom #107	5	EA	5	10+ years	
	Walls - Concrete Block	1st flr north of classroom #107	235	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st flr north of classroom #107	469	SF	6	10+ years	
	Water Closet	1st flr north of classroom #107	5	EA	6	10+ years	
	Accessories	1st flr north of classroom #109	251	SF	5	6-10 years	
	Ceiling - Splined	1st flr north of classroom #109	251	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr north of classroom #109	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr north of classroom #109	251	SF	6	10+ years	
	Floor Drain	1st flr north of classroom #109	1	ĒΑ	7	10+ years	
	Hand Dryer	1st flr north of classroom #109	2	EA	7	6-10 years	
	Lavatory	1st flr north of classroom #109	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st flr north of classroom #109	2	EΑ	6	6-10 years	
	Partitions	1st flr north of classroom #109	3	EA	5	10+ years	
	Urinals	1st flr north of classroom #109	4	EA	6	10+ years	
	Walls - Concrete Block	1st flr north of classroom #109	235	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st flr north of classroom #109	469	SF	6	10+ years	
	Water Closet	1st flr north of classroom #109	3	ĒΑ	6	10+ years	
	Accessories	2nd flr female to north of library	99	SF	7	10+ years	
	Ceiling - Exposed	2nd flr female to north of library	99	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr female to north of library	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr female to north of library	99	SF	6	10+ years	
	Lavatory	2nd flr female to north of library	1	ĒΑ	6	10+ years	
	Lighting - Wall Mounted	2nd flr female to north of library	2	EA	6	10+ years	
	Partitions	2nd flr female to north of library	2	EA	7	10+ years	
	Walls - Concrete Block	2nd flr female to north of library	148	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd flr female to north of library	296	SF	6	10+ years	
	Water Closet	2nd flr female to north of library	2	ĒΑ	6	10+ years	
	Accessories	2nd flr male to north of library	47	SF	7	6-10 years	
	Ceiling - Exposed	2nd flr male to north of library	47	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd flr male to north of library	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr male to north of library	47	SF	6	10+ years	
	Lavatory	2nd fir male to north of library	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd fir male to north of library	1	EA	6	10+ years	
	Partitions	2nd flr male to north of library	1	EA	7	6-10 years	
			•		•	3 .0 ,00.0	



Category : Room			Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	2nd flr male to north of library	105	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd flr male to north of library	210	SF	6	10+ years			
	Water Closet	2nd flr male to north of library	1	EA	6	10+ years			
	Accessories	2nd flr north of classroom #208	382	SF	7	10+ years			
	Ceiling - Exposed	2nd flr north of classroom #208	382	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd flr north of classroom #208	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd flr north of classroom #208	382	SF	6	10+ years			
	Floor Drain	2nd flr north of classroom #208	1	EA	7	10+ years			
	Hand Dryer	2nd flr north of classroom #208	2	EA	7	10+ years			
	Lavatory	2nd flr north of classroom #208	4	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd flr north of classroom #208	3	EA	6	10+ years			
	Partitions	2nd flr north of classroom #208	8	EA	7	10+ years			
	Walls - Concrete Block	2nd flr north of classroom #208	298	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd flr north of classroom #208	597	SF	6	10+ years			
	Water Closet	2nd flr north of classroom #208	8	EA	6	10+ years			
	Accessories	2nd flr north of classroom #208	251	SF	7	6-10 years			
	Ceiling - Exposed	2nd flr north of classroom #208	251	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd flr north of classroom #208	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd flr north of classroom #208	251	SF	6	10+ years			
	Floor Drain	2nd flr north of classroom #208	1	EA	7	10+ years			
	Hand Dryer	2nd flr north of classroom #208	2	EA	5	10+ years			
	Lavatory	2nd flr north of classroom #208	3	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd flr north of classroom #208	2	EA	6	6-10 years			
	Partitions	2nd flr north of classroom #208	3	EA	7	10+ years			
	Urinals	2nd flr north of classroom #208	4	EA	6	10+ years			
	Walls - Concrete Block	2nd flr north of classroom #208	235	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd flr north of classroom #208	469	SF	6	10+ years			
	Water Closet	2nd flr north of classroom #208	3	EA	6	10+ years			
	Accessories	Basement	69	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Basement	69	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement	69	SF	7	10+ years			
	Floor Drain	Basement	1	EA	7	10+ years			
	Lavatory	Basement	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Basement	2	EA	6	10+ years			
	Partitions	Basement	1	EA	5	10+ years	_		
	Showers	Basement	1	EA	5	1-2 years	Does not work.		
	Urinals	Basement	1	EA	6	10+ years			
	Walls - Concrete Block	Basement	320	SF	6	10+ years			
	Water Closet	Basement	1	EA	6	10+ years			
	Accessories	In Room 106	42	SF	5	6-10 years			
	Ceiling - Lay-in	In Room 106	42	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Room 106	1	EA	6	10+ years			
	Floor - Tile	In Room 106	42	SF	5	6-10 years			

Campus Name: Chalmers Page : 10 of 31 Assessment Date: 07/12/2021



Catego	ry : Room		Building : Main							
				J		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	In Room 106	1	EΑ	7	6-10 years				
	Lavatory	In Room 106	1	EA	6	10+ years				
	Lighting - Lay-in	In Room 106	1	EA	7	10+ years				
	Walls - Vinyl Coated Gypsum Panel	In Room 106	212	SF	6	10+ years				
	Water Closet	In Room 106	1	EA	6	10+ years				
	Accessories	In Room 107 toilet 126	35	SF	7	6-10 years				
	Ceiling - Splined	In Room 107 toilet 126	35	SF	6	10+ years				
	Doors - Wood Doors inclu hw	In Room 107 toilet 126	1	EA	7	10+ years				
	Floor - Tile	In Room 107 toilet 126	35	SF	7	10+ years	RESTROOM UNDER RENOVATION.			
	Floor Drain	In Room 107 toilet 126	1	EA	7	10+ years	Not previously assessed			
	Lighting - Wall Mounted	In Room 107 toilet 126	1	EA	7	6-10 years				
	Walls - Concrete Block	In Room 107 toilet 126	94	SF	6	10+ years				
	Accessories	In Room 109	35	SF	7	10+ years				
	Ceiling - Splined	In Room 109	35	SF	7	10+ years				
	Doors - Wood Doors inclu hw	In Room 109	1	EA	6	10+ years				
	Floor - Tile	In Room 109	35	SF	7	10+ years	RESTROOM UNDER RENOVATION.			
	Floor Drain	In Room 109	1	EA	7	10+ years	Not previously assessed			
	Lighting - Wall Mounted	In Room 109	1	EA	6	10+ years				
	Walls - Concrete Block	In Room 109	94	SF	6	10+ years				
	Accessories	Inside nurse room(south of CR 101, main office suit)	17	SF	7	6-10 years				
	Ceiling - Splined	Inside nurse room(south of CR 101, main office suit)	17	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Inside nurse room(south of CR 101, main office suit)	1	EA	7	10+ years				
	Floor - Tile	Inside nurse room(south of CR 101, main office suit)	17	SF	6	10+ years				
	Lighting - Wall Mounted	Inside nurse room(south of CR 101, main office suit)	1	EA	6	6-10 years				
	Walls - Concrete Block	Inside nurse room(south of CR 101, main office suit)	162	SF	7	10+ years				
	Water Closet	Inside nurse room(south of CR 101, main office suit)	1	EA	6	6-10 years				

Category: Classroom

Building: Main

<u> </u>			Ŭ		Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom #101 (Regular Classroom)						
Casework	1st Floor	26	LF	6	10+ years	
Ceiling - Splined	1st Floor	858	SF	6	10+ years	
Doors - Side-lite	1st Floor	18	SF	6	10+ years	
Doors - Transom Window	1st Floor	12	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	858	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Pendent/Surface	1st Floor	21	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,148	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Splined	1st Floor	858	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,716	SF	6	10+ years	Asset was missed in prior assessment
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Splined	1st Floor	858	SF	6	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,148	SF	6	10+ years	
Classroo	om #104 (Computer Lab)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	856	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	856	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,029	SF	6	10+ years	
			,	ĒΑ		,	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #105 (Regular Classroom)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	856	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	856	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,029	SF	6	10+ years	
	Wallo Controlo Block	10111001	1,020	O.	Ü	101 youro	
lassroo	m #106 (Kindergarten)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	805	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	805	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,029	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	536	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	1-2 years	Hole in the wall
lassroo	m #107 (Kindergarten)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Splined	1st Floor	1,144	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,144	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	•	Draviously inserrest quantity
						6-10 years	Previously incorrect quantity
	Marker Board	1st Floor 1st Floor	12 80	LF SF	6	6-10 years	
	Storage/ Closet				5	10+ years	
	Walls - Concrete Block	1st Floor	1,450	SF	6	10+ years	
lassroo	m #109 (Kindergarten)						
	Ceiling - Splined	1st Floor	1,144	SF	7	10+ years	
	Doors - Side-lite	1st Floor	[′] 18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Hansoni Window	13(1100)	12	01	U	IUT years	

Campus Name: Chalmers Page: 13 of 31 Assessment Date: 07/12/2021



Group	y : Classroom Item - Type		_	uilding			
Group	Item - Type					Recommend	
		Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,144	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	[^] 21	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	80	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,450	SF	6	10+ years	
Classroo	m #110 (Art Room)						
Oldssiddi	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	856	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	15	EA	6		
	Floor - Tile	1st Floor		SF		10+ years	
	Instructional Surface		1,029	SF LF	6	6-10 years	
		1st Floor	8	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21		6	6-10 years	
	Marker Board	1st Floor	32	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,029	SF	6	10+ years	
Classroor	m #111 (Regular Classroom)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Splined	1st Floor	856	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	856	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,029	SF	6	10+ years	
Classroo	m #113 (Regular Classroom)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Splined	1st Floor	910	SF	6	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,160	SF	6	10+ years	

Campus Name: Chalmers Page : 14 of 31 Assessment Date: 07/12/2021



Catego	ry : Classroom		В	uilding	: Main		743 W ROOSEVEIL ROAD, CHICAGO, IL 60606
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #114 (Art Room)						
	Casework	1st Floor	26	LF	5	6-10 years	
	Ceiling - Splined	1st Floor	910	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,160	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	910	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,160	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
_01033100	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	858	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	1,148	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
_CIG55100	Casework	2nd Floor	26	LF	6	10+ years	
	Casework Ceiling - Splined	2nd Floor 2nd Floor	910	SF	6	10+ years 10+ years	
	Doors - Side-lite	2nd Floor 2nd Floor	18	SF SF	6	10+ years 10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	12	EA	6	10+ years	
	20010 WOOD 20013 IIIOID IIW	2110 1 1001	'	LA	J	TOT years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	1,160	SF	6	10+ years	
N	1004 (Danielas Olanasas)						
Jassroc	om #204 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	990	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,056	SF	6	10+ years	
						-	
Classroc	om #205 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	856	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	6	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,029	SF	6	10+ years	
			,			,	
Classroc	om #206 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	990	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,056	SF	6	10+ years	
			,			,	
lassroc	om #207 (Regular Classroom)						

Campus Name: Chalmers Page : 16 of 31 Assessment Date: 07/12/2021



Catego	ry : Classroom		В	uilding	: Main		45 W ROUSEVEIL ROAD, Chicago, IL 60606
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,148	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EΑ	6	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,148	SF	6	10+ years	
_Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	858	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,148	SF	6	10+ years	
Classroo	om #209 (Science Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	858	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,148	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	856	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	7	10+ years	
						-	

Campus Name: Chalmers Page : 17 of 31 Assessment Date: 07/12/2021



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,029	SF	6	10+ years	
Classroo	om #211 (Library)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	1,176	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	960	SF	6	10+ years	
Classroo	om #212 (Computer Lab)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	858	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Carpet	2nd Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	78	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,029	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #213 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	AC Units	2nd Floor	1	EA	5	0-1 year	Cover missing.
	Casework	2nd Floor	6	LF	6	10+ years	-
	Ceiling - Splined	2nd Floor	910	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,160	SF	6	10+ years	
	Wireless System	2nd Floor	1	EΑ	7	10+ years	



Category : Classroom			В				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #214 (Music Room)						
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	910	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	910	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,160	SF	6	10+ years	
			,			.o. yeare	
Catego	ry : Interior		В	uilding	: Main	Decemmend	
2	Itama Tuma	Location	Our matitus	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	0.111.						
	Ceiling - Splined	1st Floor	4,619	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,297	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,322	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	44	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	4,140	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	8,150	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	5,476	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	5,476	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	40	EA	6	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	30	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	3,980	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	7,960	SF	6	10+ years	
	Ceiling - Exposed	Basement	282	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	282	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	4	EA	6	10+ years	
	Walls - Concrete Block	Basement	720	SF	6	10+ years	
	vvalis - Collete Diock	Dascilletit	720	SF	O	TOT years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	Previously not assessed
	Security Cameras	Entire Building	1	EA	7	6-10 years	
Stairs							



Catego	ry : Interior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	North	319	SF	6	10+ years	
	Floor - Tile/Sheet	North	260	SF	7	10+ years	
	Handrails	North	64	LF	7	10+ years	
	Lighting - Pendent/Surface	North	1	EA	6	6-10 years	
	Lighting - Wall Mounted	North	2	EA	6	10+ years	
	Stairs - Concrete	North	30	LF	6	10+ years	
	Walls - Concrete Block	North	424	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	1,272	SF	6	10+ years	
	Ceiling - Splined	South	319	SF	6	10+ years	
	Floor - Tile/Sheet	South	260	SF	7	10+ years	
	Handrails	South	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South	1	EA	6	6-10 years	
	Lighting - Wall Mounted	South	2	EA	6	6-10 years	
	Stairs - Concrete	South	30	LF	6	10+ years	
	Walls - Concrete Block	South	424	SF	6	10+ years	
	Walls - Structural Glazed Tile	South	1,272	SF	6	10+ years	



Category : Exterior **Building: Addition**

Categor	y . Exterior		<u> </u>	unung	. Additi		
0	Ham. Toma	Location	O. antitu	LIOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Entrance Control - Audio and Video	#7- SE	1	EA	6	10+ years	
	Exterior Doors - Side lite	#7- SE	2	EA	6	10+ years	
	Exterior Doors - Store Front	#7- SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7- SE	3	EA	6	10+ years	
	Exterior Doors - Side lite	#8- NE	2	EA	6	10+ years	
	Exterior Doors - Store Front	#8- NE	2	EA	6	10+ years	
						, , , , ,	
Foundati	on						
Odnodu	Foundation - Concrete	Entire Building	239	LF	7	10+ years	
	Foundation - Concrete	Entire Building	5	LF	6	2-5 years	
	Superstructure - Concrete	Entire Building	11,452	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	11,402	Si	,	10+ years	
Lighting							
Lighting	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	2-5 years	Not working according to engineer
	Exterior Lighting - Wall Mounted	Littile building	2	LA	3	2-5 years	Not working according to engineer
Roof Sys	tom						
_Koor Sys	Coping - Metal	Elevator tower roof	77	LF	6	10+ years	
	Roof - Modified Bitumen	Elevator tower roof	375	SF	6	10+ years	
				SF	7		
	Roof Structure - Steel / Metal Deck/	Elevator tower roof	375	SF	/	10+ years	
	Concrete Topping	Main Danf	400		^	40	
	Coping - Metal	Main Roof	198	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	48	LF	6	10+ years	D
	Roof - Asphalt Gravel Ballast	Main Roof	5,351	SF	5	2-5 years	Ponding issues
	Roof Structure - Concrete	Main Roof	5,351	SF	7	10+ years	
Malla							
_Walls	Exterior Walls - Prefabricated Metal Panel	Entire Building	3,591	SF	6	6-10 years	
	Wall	Entire Building	3,391	SF	О	6-10 years	
	vvali						
_Windows							
vviiiuOvva	Curtain wall - Glazed Double Pane	Entire Building	1,110	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	1,089	SF	6	6-10 years	Quantities consolidated from several
	Cartain mail initiation i anoi	E. M. O Danding	1,000	0.	J	5 10 yours	line items.
	Curtain wall - Louver	Entire Building	64	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	544	SF	6	10+ years	
	Lintels - Steel	Entire Building	6	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	320	SF	6	10+ years	
	pane	Little Dallaling	520	5 1	J	ioi youis	
	Paris						



Catego	ry : Electrical		Building : Addition				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerge	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	7	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	7	6-10 years	
	Security System - CCTV	Entire Building	11,452	SF	5	2-5 years	Manu units have holes
	Security System - Intrusion Detection	Entire Building	11,452	SF	7	6-10 years	
Main Se	rvice						
	PA System	Entire Building	11,452	SF	5	2-5 years	
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alaı	m						
	Fire Alarm Strobe Lights	Entire Building	11,452	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	11,452	SF	7	6-10 years	
Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Wall Heater - Electric	Elevator equipment room and elect closet on 2nd floor	1	EA	6	6-10 years	It might be another unit on the 2nd floor but the room was locked, the
	Cabinet Heaters - With Hot Water Coil	Entire Building	9	EA	6	6-10 years	custodian didn't have the key
	Cabillet neaters - with not water con	Entire building	9	EA	O	6-10 years	
Tempera	ature Control						
	Thermostats - DDC	Entire Building	10	EA	7	6-10 years	
Unit Ver							
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	8	EA	6	6-10 years	
Ventilati	on						

Campus Name: Chalmers Page : 22 of 31 Assessment Date: 07/12/2021



Category : Mechanical				Building : Addition						
		Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Kitchen and elevator equipment room and Roof	1	EA	7	6-10 years				
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Kitchen and elevator equipment room and Roof	1	EA	6	6-10 years				
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Kitchen and elevator equipment room and Roof	1	EA	6	6-10 years				
_			_							

Category: Plumbing Building: Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wate	er		•			•	
	Electric Heater - 20 - 50 KW	1st Floor	1	EA	7	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	11,452	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	11,452	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	11,452	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	11,452	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	11,452	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	11,452	SF	6	10+ years	
	Sanitary Piping	Entire Building	11,452	SF	6	10+ years	
	Storm Piping	Entire Building	11,452	SF	6	10+ years	

Building: Addition Category: Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Splined	Kitchen Manager's Office	172	SF	6	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager's Office	1	EA	6	10+ years	Missed on previous assessment
	Floor - Tile	Kitchen Manager's Office	172	SF	6	10+ years	•
	Lighting - Pendent/Surface	Kitchen Manager's Office	4	EA	7	6-10 years	
	Power Distribution	Kitchen Manager's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Manager's Office	283	SF	6	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	690	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Missed last assessment
	Floor - Tile	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	

Campus Name: Chalmers Page : 23 of 31 Assessment Date: 07/12/2021



Catego	ry : Room		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Serving Line	1st Floor	8	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	845	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	1st Floor	1,599	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Tile	1st Floor	1,599	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,630	SF	6	10+ years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	70	SF	5	10+ years	Not assessed previously
	Storage Room	1st Floor	62	SF	5	10+ years	. ,
	Storage Room	2nd Floor	135	SF	7	6-10 years	
Restroor	m.						
	Accessories	1st Floor	142	SF	7	6-10 years	RESTROOM UNDER RENOVATION
	Ceiling - Splined	1st Floor	142	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	142	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	210	SF	6	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	137	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	137	SF	7	10+ years	RESTROOM UNDER RENOVATION
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	137	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	2	ΕA	5	6-10 years	
	Urinals	1st Floor	2	ΕA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	204	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	96	SF	7	6-10 years	Missed asset previous assessment
	Ceiling - Splined	1st Floor	96	SF	7	10+ years	Missed asset previous assessment
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	96	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	



			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lavatory	1st Floor	1	EΑ	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years			
	Walls - Structural Glazed Tile	1st Floor	280	SF	6	10+ years			
	Water Closet	1st Floor	1	EA	6	10+ years			
	Accessories	2nd Floor	142	SF	7	6-10 years			
	Ceiling - Splined	2nd Floor	142	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	142	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years			
	Partitions	2nd Floor	3	EA	7	6-10 years			
	Walls - Structural Glazed Tile	2nd Floor	210	SF	6	10+ years			
	Water Closet	2nd Floor	3	EA	6	10+ years			
	Accessories	2nd Floor	137	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	137	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	147	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	10+ years			
	Partitions	2nd Floor	1	EA	7	6-10 years			
	Urinals	2nd Floor	2	EA	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	204	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	6	10+ years			

Category : Classroom **Building: Addition**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	m #118 (Regular Classroom)		•				
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Splined	1st Floor	805	SF	6	10+ years	
	Doors - Side-lite	1st Floor	18	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	805	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,142	SF	6	10+ years	

Classroom #213 (Computer Lab)



Catego	ry : Classroom		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	5	1-2 years	Cover missing.
	AC Units	2nd Floor	1	EA	5	1-2 years	
	Casework	2nd Floor	32	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	768	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	768	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,056	SF	6	10+ years	
lassroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	32	LF	6	10+ years	
	Casework Ceiling - Splined	2nd Floor	768	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	•	
						10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,056	SF	6	10+ years	
lassroc	om #215 (Store Room)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	805	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	805	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,142	SF	6	10+ years	
lassroo	om #216 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	805	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw			SF EA	6		
		2nd Floor	1		-	10+ years	
	Floor - Tile	2nd Floor	805	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	

Campus Name: Chalmers Page : 26 of 31 Assessment Date: 07/12/2021



Catego	ry : Classroom		В	uildina	: Additi		45 W ROOSEVER ROAD, Officago, IE 0000
outogo.			_	uug	. , (Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Concrete Block	2nd Floor	1,142	SF	6	10+ years	
Classroo	m #217 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	805	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	805	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	1,142	SF	6	10+ years	
	Work Sink	2nd Floor	, 1	EA	7	10+ years	
Classroo	m #218 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	805	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	800	SF	6	10+ years	
				SF	_	•	Missing
	Floor - Tile	2nd Floor	5		4	0-1 year	Missing.
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,142	SF	6	10+ years	
ategoi	ry : Interior		В	uilding	: Additi	on	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Calling Lawin	4 at Flace	400			40	
	Ceiling - Lay-in	1st Floor	190	SF	6	10+ years	
	Ceiling - Splined	1st Floor	1,048	SF	6	10+ years	
	Doors - Store Front	1st Floor	4	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	5	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	320	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	918	SF	5	10+ years	
	Lighting Lovin	1st Floor	2	EA	6	6-10 years	
	Lighting - Lay-in Lighting - Pendent/Surface	13(1100)	8		U	0-10 years	



Catego	ry : Interior		В	uilding	: Additi		TO W Hoosevelt Horle, emeage, in ecoco
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Structural Glazed Tile	1st Floor	2,338	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	190	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,048	SF	6	10+ years	
	Doors - Store Front	2nd Floor	4	EA	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	320	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	918	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,338	SF	6	10+ years	
Safety							
	Security Cameras	Entire Building	1	EA	7	6-10 years	
_Stairs							
	Ceiling - Splined	North	108	SF	6	10+ years	
	Ceiling - Splined	North	5	SF	4	1-2 years	Missing.
	Floor - Tile	North	50	SF	6	10+ years	•
	Handrails	North	64	LF	5	10+ years	
	Lighting - Pendent/Surface	North	2	EA	6	10+ years	
	Lighting - Wall Mounted	North	1	EA	6	6-10 years	
	Stairs - Tile	North	30	LF	6	10+ years	
	Walls - Structural Glazed Tile	North	950	SF	6	10+ years	
	Ceiling - Splined	South	113	SF	6	10+ years	
	Floor - Tile	South	50	SF	6	10+ years	
	Handrails	South	64	LF	5	10+ years	
	Lighting - Pendent/Surface	South	2	EA	6	6-10 years	
	Lighting - Wall Mounted	South	1	EA	6	6-10 years	
	Stairs - Tile	South	30	LF	6	10+ years	
	Walls - Structural Glazed Tile	South	950	SF	6	10+ years	
Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	2nd Floor	1	EA	6	10+ years	



Category : Site **Building: Site**

oup	Item - Type					Recommend	
			O	LION	Dank	Danissans	Cammanta
		Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	6	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	7	10+ years	
encing							
	Fencing - Chain Link	Entire Site	700	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	384	LF	6	6-10 years	
	S						
andscap		Fasting Oits				0.40	
	Benches	Entire Site	1	EA	6	6-10 years	
	Landscape - Grass	Entire Site	9,929	SF	6	2-5 years	
	Landscape - Hardscape- Asphalt	Entire Site	640	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	735	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	90	SF	4	1-2 years	Cracked, spalling
	Landscape - Hardscape- Pavers	Entire Site	1,000	SF	5	2-5 years	
	Landscape - Mulch	Entire Site	1,800	SF	6	6-10 years	
	Parkway trees	Entire Site	9	EA	7	6-10 years	
	Planting Beds/ Area	Entire Site	440	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	9,018	SF	4	1-2 years	Uneven pavement, spalling throughout
	Retaining Wall - Concrete	Entire Site	250	SF	6	2-5 years	aougout
	Trash Receptacles	Entire Site	1	EA	6	2-5 years	
Parking L	ot						
arking L	Concrete Curbs	Parking Lot- South	30	LF	6	6-10 years	
				SF			
	Surface - Asphalt	Parking Lot- South	8,800		6	2-5 years	
	Trash Enclosure - Chain Links	Parking Lot- South	288	SF	6	6-10 years	
	Vehicular Screening	Parking Lot- South	191	LF	6	6-10 years	
Playgroui	nd						
	Equipment - School Age 5-12	SE site	1	EA	6	2-5 years	
	Surface - Poured Surface	SE site	2,609	SF	6	2-5 years	
	Equipment - Pre K 3-5	SW site	. 2	EA	6	2-5 years	
	Surface - Poured Surface	SW site	2,045	SF	6	2-5 years	
			, -			,	
Sidewalk		Finting City	404	1.5		0.5	
	Sidewalks - Internal Walks	Entire Site	131	LF	6	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site Entire Site	12,251 2,180	SF SF	6 5	2-5 years 2-5 years	Spalling
	Sidewalks - Perimeter Sidewalks						



Catego	ry : Site		В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Chalmers Page: 30 of 31 Assessment Date: 07/12/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	mionaca ecago	100m Eddalon	Hamboi	Italiiboi	(0.)	Alou	Allou	Сюр	Doura
Art Room	Art Room	1st Floor	110	110	856	219	48	Υ	N
Art Room	Regular Classroom	1st Floor	114	114	910	219	10	N	N
Computer Lab	Computer Lab	1st Floor	104	104	856	219	48	Y	N
Computer Lab	Computer Lab	2nd Floor	212	212	858	219	48	N	N
Computer Lab	Computer Lab	2nd Floor	213	213	910	219	10	N	Y
Kindergarten	Kindergarten	1st Floor	106	106	805	219	56	Y	N
Kindergarten	Kindergarten	1st Floor	107	107	1,144	281	10	Y	N
Kindergarten	Kindergarten	1st Floor	109	109	1,144	281	10	Y	N
Library	Library	2nd Floor	211	211	1,176	300	12	Y	N
Music Room	Regular Classroom	2nd Floor	214	214	910	219	10	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	858	219	10	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	858	219	10	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	858	219	10	Y	N
Regular Classroom	Regular Classroom	1st Floor	105	105	856	219	48	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	856	219	48	Y	N
Regular Classroom	Regular Classroom	1st Floor	113	113	910	219	10	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	858	219	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	858	219	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	910	219	10	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	990	281	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	856	219	10	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	990	281	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	858	219	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	858	219	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	856	219	48	N	N
Science Classroom	Regular Classroom	2nd Floor	209	209	858	219	10	Υ	N
Building : Addition									
Computer Lab	Computer Lab	2nd Floor	213	213	768	216	12	N	N
Office	Regular Classroom	2nd Floor	218	218	805	157	10	Υ	N
Regular Classroom	Regular Classroom	1st Floor	118	118	805	157	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	768	216	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	805	157	10	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	805	157	10	Υ	N
Store Room	Regular Classroom	2nd Floor	215	215	805	157	10	N	N