

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Field House 1	1955	1	3,250
Field House 2 - Leased	1955	1	320
Field House 3	1980	1	600
Field House 4	1955	1	3,100
Field House 5 - Leased	1990	1	320
Field House 6	1997	1	320
Field House 7 - East	1955	1	600
Grandstand East	1955	1	0
Grandstand West	1955	1	0
Campus Total			8,510

Category : Exterior						Building : Field House 1					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments				
Entrance	9										
	Exterior Doors - Exterior Steel Door	1	2	EA	6	10+ years	On steel door, one storm door				
	Exterior Stairs - Concrete	1	4	LF	6	10+ years					
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years					
	Exterior Doors - Exterior Steel Door	3	1	EA	6	6-10 years					
	Exterior Doors - Exterior Steel Door	4	1	EA	6	6-10 years					
	Exterior Stairs - Concrete	4	4	LF	6	10+ years					
_Foundat	ion										
	Foundation - Concrete	Entire Building	222	LF	7	10+ years					
	Superstructure - Concrete	Entire Building	3,100	SF	7	10+ years					
Lighting											
0-0	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	10+ years					
Roof Sys	stem										



							810 E 103rd STREET, Chicago, IL 60628
Catego	ry : Exterior	B	uilding	House 1			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Roof - Metal	Canopy	48	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Canopy	48	SF	7	10+ years	
	Concrete Topping					-	
	Chimney - Brick Chimney- Concrete/ Mortar	Entire Building	12	LF	6	10+ years	
	Liner	-				-	
	Chimney - Brick Chimney- Concrete/ Mortar	Entire Building	8	LF	5	1-2 years	
	Liner	C C				•	
	Chimney - Metal Flue	Entire Building	3	LF	6	2-5 years	
	Coping - Metal	Entire Building	222	LF	5	1-2 years	Gutter is bent with leaks at all joints.
		6					Damage to a brick walls below
	Downspouts - Exterior Downspouts	Entire Building	36	LF	6	6-10 years	5
	Downspouts - Exterior Downspouts	Entire Building	12	LF	4	1-2 years	Missing downspouts
	Roof - Asphalt Gravel Ballast	Entire Building	3,100	SF	4	1-2 years	Soft spots, deteriorated sealant
	Roof Structure - Concrete	Entire Building	222	SF	7	10+ years	
						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Walls							
	Canopy - Metal	Entire Building	36	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	1,837	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	4	1-2 years	Open joints, cracks
	Exterior Walls - Stone-Cast	Entire Building	32	SF	5	10+ years	
				•	Ũ	let jeale	
Windows							
	Guard - Guards perforated	Entire Building	134	SF	7	10+ years	
	Lintels - Steel	Entire Building	97	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	142	SF	6	10+ years	
	pane						
	Windows - Decorative	Entire Building	16	SF	6	10+ years	Ticket window
Catego	ry : Electrical		в	uilding	· Field I	House 1	
Oulego				unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System						
Lineiger	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No battery backup nor backup
		Entro Banang	L	<b>L</b> /\	2	o i your	generator
							generator
Main Se	rvice						
	Main Electrical Service - 800 A and Less	1st Floor	1	EA	7	10+ years	
	than 277/480/3PH					-	
	PA System	1st Floor	3,500	SF	6	6-10 years	
						-	
Power D	istribution						
	Lighting and Power Panels - 100 A	1st Floor	4	EA	4	2-5 years	Corroded
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	10+ years	



810 E 103rd STREET, Chicago, IL 60628 **Building : Field House 1 Category : Electrical** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Main Distribution Panels - 400 - 600 amp 1st Floor 3 ΕA 6 10+ vears Transformers - 277/480 - 120/240 1st Floor 2 ΕA 7 10+ years **Category : Mechanical Building : Field House 1** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Boiler Systems Non Condensing- Water Tube- Flexible Mechanical Room 1 ΕA 6 10+ years Packaged boiler Tube- Force Draft- Hot Water Boiler - Less than 500 MBH Piping - Dual Temperature Pipes- Steel Mechanical Room 3,250 LF 4 6-10 years Heating Devices Unit Heater - Hot Water 1st Floor 1 EA 6 6-10 years LF Fin Tube - Hot Water 1st Floor 80 6 6-10 years Mechanical Plumbing Hydronic Supply and Return - Steel Entire Building 3.250 LF 6 6-10 years Temperature Control Electric Thermostat 1st Floor ΕA 7 1 6-10 years Ventilation Exhaust Fans- Indoor - 500 - 1500 CFM Entire Building 2 ΕA 6 2-5 years **Category : Plumbing Building : Field House 1** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR ΕA 6 1st Floor 1 6-10 years Hot Water Storage Tank\_Gas - 201 - 500 1st Floor FΑ 3 0-1 year 1 Decommissioned Gallons Piping Domestic Piping-Hot/Cold Water Supply 1st Floor 3,250 SF 4 2-5 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply 1st Floor 3,250 SF 4 2-5 years (from Risers to Fixtures) Sanitary Piping 1st Floor 3.250 SF 6 6-10 vears Storm Piping SF 6-10 years 1st Floor 3.250 6 Vent Piping 3.250 SF 6 6-10 years 1st Floor



XICA .	Schools						810 E 103rd STREET, Chicago, IL 60628	
Catego	ory : Room		B	uilding	: Field I	House 1		
-				5		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Adminis	trative Suites/Offices							
	AC Unit	Office inside north locker room	1	EA	7	6-10 years		
	Ceiling - Exposed	Office inside north locker room	300	SF	7	10+ years		
	Doors - Steel Doors incl hw	Office inside north locker room	1	EA	7	10+ years		
	Floor - Tile	Office inside north locker room	300	SF	6	2-5 years		
	Lighting - Pendent/Surface	Office inside north locker room	3	EA	7	6-10 years		
	Power Distribution	Office inside north locker room	3	EA	7	10+ years		
	Storage/ Closet	Office inside north locker room	110	SF	7	10+ years		
	Walls - Masonry	Office inside north locker room	810	SF	6	10+ years	Peeling paint	
	AC Unit	Stadium Manager Office	1	EA	7	10+ years		
	Ceiling - Exposed	Stadium Manager Office	135	SF	7	10+ years		
	Doors - Steel Doors incl hw	Stadium Manager Office	2	EA	6	10+ years		
	Floor - Tile	Stadium Manager Office	135	SF	6	10+ years		
	Lighting - Pendent/Surface	Stadium Manager Office	3	EA	7	10+ years		
	Walls - Masonry	Stadium Manager Office	528	SF	7	10+ years		
	Ceiling - Exposed	Ticket Office	100	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Ticket Office	100	EA	6	10+ years		
	Floor - Tile	Ticket Office	100	SF	6	10+ years		
	Lighting - Pendent/Surface	Ticket Office	3	EA	7	10+ years		
	Walls - Masonry	Ticket Office	550	SF	7	10+ years		
Lockor/9	Shower Room					·		
LUCKEI/C	Accessories	Home Team Locker Room	1,085	SF	5	10+ years		
	Benches, ped mounted	Home Team Locker Room	24	LF	6	6-10 years	Quantity: 4, Rank: 6	
	Benches, ped mounted	Home Team Locker Room	24	LF	5	1-2 years	Splitting wood seat	
	Ceiling - Exposed		-	SF	6	6-10 years	Spinning wood sear	
	Doors - Steel Doors incl hw	Home Team Locker Room Home Team Locker Room	1,085 2	EA	6	10+ years		
	Floor - Concrete	Home Team Locker Room		SF	7	•		
	Floor Drain	Home Team Locker Room	1,085 6	EA	7	10+ years		
			18	EA	7	10+ years	Item Type: Pendent/Surface,	
	Lighting - Pendent/Surface	Home Team Locker Room	10	EA	1	10+ years	Quantity: 18, Rank: 7	
	Student Lockers - One Tier	Home Team Locker Room	16	EA	7	10+ years		
	Student Lockers - Two Tier	Home Team Locker Room	28	EA	6	6-10 years		
	Student Lockers - Two Tier	Home Team Locker Room	2	EA	5	1-2 years	Missing doors	
	Walls - Masonry	Home Team Locker Room	1,452	SF	7	10+ years	Item Type: Masonry, Quantity: 1452 Rank: 7	
	Accessories	Visiting team locker room (north)	1,580	SF	5	6-10 years	· · · · · · ·	
	Benches, ped mounted	Visiting team locker room (north)	24	LF	6	2-5 years		
	Benches, ped mounted	Visiting team locker room (north)	6	LF	5	1-2 years	Damaged/chipped bench	
	Ceiling - Exposed	Visiting team locker room (north)	1,580	SF	6	10+ years	<b>C</b>	
	Doors - Steel Doors incl hw	Visiting team locker room (north)	1	EA	7	6-10 years		
	Floor - Concrete	Visiting team locker room (north)	1,580	SF	7	10+ years		
	Floor Drain	Visiting team locker room (north)	13	ĒA	7	10+ years		
	Lavatory	Visiting team locker room (north)	1	EA	6	6-10 years		
	,	<b>U</b>	-		-	,		



							810 E 103rd STREET, Chicago, IL 60628
Catego	ry : Room		В	uilding	: Field I		
0	line Truck	Location	Owently		David	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Visiting team locker room (north)	22	EA	7	6-10 years	
	Partitions	Visiting team locker room (north)	1	EA	7	6-10 years	
	Partitions	Visiting team locker room (north)	1	EA	5	1-2 years	Missing door
	Showers	Visiting team locker room (north)	12	EA	7	10+ years	
	Student Lockers - One Tier	Visiting team locker room (north)	36	EA	6	2-5 years	••• • • • • • •
	Student Lockers - One Tier	Visiting team locker room (north)	10	EA	5	1-2 years	Missing locker door handle
	Urinals	Visiting team locker room (north)	3	EA	5	2-5 years	
	Walls - Masonry	Visiting team locker room (north)	2,620	SF	6	10+ years	
	Water Closet	Visiting team locker room (north)	2	EA	3	2-5 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	234	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years	
	Storage Room	1st Floor	190	SF	7	10+ years	
	Mechanical/ Service Rooms	Mechanical room inside north	280	SF	7	10+ years	
		building				,	
Restroor	n						
	Accessories	Home Team Locker Room Toilets	190	SF	7	10+ years	
	Ceiling - Exposed	Home Team Locker Room Toilets	190	SF	7	10+ years	
	Floor - Concrete	Home Team Locker Room Toilets	190	SF	7	10+ years	
	Floor Drain	Home Team Locker Room Toilets	1	EA	7	10+ years	
	Lavatory	Home Team Locker Room Toilets	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Home Team Locker Room Toilets	2	EA	7	10+ years	
	Partitions	Home Team Locker Room Toilets	2	EA	7	10+ years	
	Student Lockers - One Tier	Home Team Locker Room Toilets	7	EA	7	10+ years	
	Urinals	Home Team Locker Room Toilets	3	EA	7	10+ years	
	Walls - Masonry	Home Team Locker Room Toilets	638	SF	7	10+ years	
	Water Closet	Home Team Locker Room Toilets	2	EA	7	10+ years	
	Accessories	Home team locker room mens	220	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Home team locker room mens	220	SF	7	10+ years	
	Doors - Steel Doors incl hw	Home team locker room mens		EA	7	10+ years	
	Floor - Concrete	Home team locker room mens	220	SF	7	10+ years	
	Floor Drain	Home team locker room mens	1	EA	7	10+ years	
	Hand Dryer	Home team locker room mens	1	EA	7	6-10 years	
	Lavatory	Home team locker room mens	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Home team locker room mens	2	EA	7	6-10 years	
	Partitions	Home team locker room mens	2	EA	5	6-10 years	
	Partitions	Home team locker room mens	2	EA	4	1-2 years	Partition not securely bolted to
	Faituons	TIOME learn locker room mens	1	LA	4	1-2 years	ground causing swaying
	Urinals	Home team locker room mens	3	EA	6	6-10 years	ground oddonig swaying
	Walls - Masonry	Home team locker room mens	630	SF	7	10+ years	
	Water Closet	Home team locker room mens	2	EA	6	6-10 years	
	Accessories	Home team locker room womens	220	SF	5	2-5 years	
	70003301103		220	0	5	2-0 years	



Category : Room Building : Field House 1							810 E 10310 STREET, Chicago, IL 60628
Calego	IY. ROOM		D	unung	. Field r	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Ceiling - Exposed	Home team locker room womens	220	SF	7	10+ years	Comments
	Doors - Steel Doors incl hw		220	EA	7		
	Floor - Concrete	Home team locker room womens		SF	7	10+ years	
		Home team locker room womens	220	EA	7	10+ years	
	Floor Drain	Home team locker room womens	1			10+ years	
	Hand Dryer	Home team locker room womens	1	EA	7	6-10 years	
	Lavatory	Home team locker room womens	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Home team locker room womens	2	EA	7	6-10 years	
	Partitions	Home team locker room womens	3	EA	7	6-10 years	
	Walls - Masonry	Home team locker room womens	630	SF	7	10+ years	
	Water Closet	Home team locker room womens	3	EA	3	2-5 years	
	Accessories	North mens locker room restroom	220	SF	5	6-10 years	
	Ceiling - Exposed	North mens locker room restroom	220	SF	7	10+ years	
	Doors - Steel Doors incl hw	North mens locker room restroom	1	EA	7	10+ years	
	Floor - Concrete	North mens locker room restroom	220	SF	7	10+ years	
	Floor Drain	North mens locker room restroom	1	EA	7	10+ years	
	Lavatory	North mens locker room restroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	North mens locker room restroom	2	EA	7	6-10 years	
	Partitions	North mens locker room restroom	1	EA	7	10+ years	
	Partitions	North mens locker room restroom	3	EA	5	0-1 year	Missing door
	Urinals	North mens locker room restroom	1	EA	6	6-10 years	5
	Urinals	North mens locker room restroom	2	EA	4	1-2 years	Doesn't flush
	Walls - Masonry	North mens locker room restroom	630	SF	7	10+ years	
	Water Closet	North mens locker room restroom	1	EA	7	6-10 years	
	Water Closet	North mens locker room restroom	2	EA	3	0-1 year	Hole inside toilet water constantly
			_		-		running/inoperable
	Accessories	Stadium Manager Restroom	135	SF	7	10+ years	Quantity: 135, Rank: 7
	Ceiling - Exposed	Stadium Manager Restroom	135	SF	6	10+ years	Item Type: Exposed, Quantity: 135,
			100	01	0	Tor youro	Rank: 7
	Doors - Steel Doors incl hw	Stadium Manager Restroom	1	EA	7	10+ years	Item Type: Steel Doors incl hw,
							Quantity: 1085, Rank: 7
	Floor - Concrete	Stadium Manager Restroom	135	SF	7	10+ years	Item Type: Concrete, Quantity: 135,
		Ota diana Managana Dagtasana	4	<b>–</b> ^	-	10	Rank: 7
	Floor Drain	Stadium Manager Restroom	1	EA	7	10+ years	Item Type: Floor Drain, Quantity: 1, Rank: 7
	Lavatory	Stadium Manager Restroom	1	EA	6	10+ years	Quantity: 1, Rank: 7
	Lighting - Pendent/Surface	Stadium Manager Restroom	2	EA	7	10+ years	Item Type: Pendent/Surface,
		-	_			, ,	Quantity: 2, Rank: 7
	Showers	Stadium Manager Restroom	1	EA	5	6-10 years	Unused, storage Quantity: 1, Rank: 5
	Student Lockers - One Tier	Stadium Manager Restroom	6	EA	7	10+ years	Item Type: One Tier, Quantity: 6,
		-				2	Rank: 7
	Walls - Masonry	Stadium Manager Restroom	528	SF	6	10+ years	Item Type: Masonry, Quantity: 528,
							Rank: 7
	Water Closet	Stadium Manager Restroom	1	EA	7	10+ years	Quantity: 1, Rank: 7
	Accessories	Womens restroom north locker room	220	SF	7	6-10 years	
						-	



**Building : Field House 1 Category : Room** Recommend Location UOM Group Item - Type Quantity Rank Replacement Comments Ceiling - Exposed Womens restroom north locker room SF 10+ years 220 7 Doors - Steel Doors incl hw Womens restroom north locker room ΕA 7 6-10 years 1 10+ years Floor - Concrete Womens restroom north locker room 220 SF 7 Floor Drain Womens restroom north locker room ΕA 7 1 10+ years 3 ΕA Lavatory Womens restroom north locker room 6 10+ years Lighting - Pendent/Surface 2 Womens restroom north locker room ΕA 7 6-10 years Partitions Womens restroom north locker room 4 ΕA 7 10+ years Walls - Masonry 630 SF Womens restroom north locker room 7 10+ years Water Closet ΕA 2-5 years Womens restroom north locker room 4 3



**Category : Exterior Building : Field House 2 - Leased** Recommend Location **Replacement** Comments Item - Type Quantity UOM Rank Group Entrance Exterior Doors - Exterior Steel Door ΕA 6 1 1 6-10 years 2 ΕA Exterior Doors - Exterior Steel Door 1 6 10+ years Foundation LF 7 Foundation - Concrete Entire Building 72 10+ years SF Superstructure - Concrete **Entire Building** 320 7 10+ years Roof System Coping - Metal Entire Building 72 LF 6 10+ years SF Roof - Asphalt Gravel Ballast Entire Building 320 6 10+ years Roof Structure - Concrete SF Entire Building 320 7 10+ years Walls Exterior Walls - Brick Entire Building 660 SF 6 10+ years SF Open joints, cracked brick Exterior Walls - Brick Entire Building 50 4 1-2 years Windows Guard - Guards wire guard Entire Building 12 SF 6 10+ years Lintels - Steel Entire Building 13 LF 6 6-10 years Windows - Louver Entire Building 12 SF 6 10+ years **Category : Room Building : Field House 2 - Leased** Recommend Location **Replacement** Comments Group Item - Type Quantity UOM Rank Mechanical/ Service Rooms Mechanical/ Service Rooms SF 7 Electrical Room 105 10+ years



**Category : Exterior Building : Field House 3** Recommend Location Replacement Comments Group Item - Type Quantity UOM Rank Entrance Exterior Doors - Exterior Wood Door 1 ΕA 6 1 10+ years 2 2 ΕA 6 Exterior Doors - Exterior Wood Door 2-5 years **Exterior Stairs - Concrete** 2 7 LF 5 6-10 years Foundation Superstructure - Slab on Grade SF 5 **Entire Building** 320 2-5 years Large cracks in the concrete, evidence of rotted trusses Roof System SF Roof - Asphalt Shingle Entire Building 320 2 0-1 year Holes in the roof and eaves, rotted wood Roof Structure - Heavy Timber Entire Building 320 SF 5 1-2 years Light wood truss construction. Rotting wood Walls Exterior Walls - Wood Siding Entire Building 448 SF 5 6-10 years Exterior Walls - Wood Siding SF Entire Building 128 4 1-2 years Patched walls, Rotted walls Windows Windows - Louver 5 SF 6 Entire Building 2-5 years **Category : Room Building : Field House 3** Recommend Location Rank **Replacement** Comments Group Item - Type Quantity UOM Mechanical/ Service Rooms Storage Room SF 5 Green building 600 10+ years



**Category : Exterior Building : Field House 4** Recommend Item - Type Location Quantity UOM Replacement **Comments** Group Rank Entrance FΑ Exterior Doors - Exterior Steel Door 1 1 6 10+ years LF 7 Exterior Stairs - Concrete 4 10+ years 1 2 Exterior Doors - Exterior Steel Door 1 EΑ 6 10+ years **Exterior Stairs - Concrete** 2 5 LF 7 10+ years 3 Exterior Doors - Exterior Steel Door 1 ΕA 6 10+ years Exterior Stairs - Concrete 3 LF 10+ years 4 6 Exterior Doors - Exterior Steel Door 4 1 ΕA 6 6-10 years Exterior Stairs - Concrete 4 4 LF 6 10+ vears Exterior Doors - Exterior Steel Door 5 1 EΑ 6 6-10 years Foundation Foundation - Concrete Entire Building 222 LF 7 10+ years SF Superstructure - Concrete Entire Building 3.100 7 10+ years Lighting Exterior Lighting - Wall Mounted 4 ΕA 6 Entire Building 10+ years Roof System LF Chimney - Brick Chimney- Concrete/ Mortar Entire Building 12 6 10+ years Liner Chimney - Brick Chimney- Concrete/ Mortar Entire Building 8 1 F 5 1-2 years Open joints, cracks in masonry Liner Chimney - Metal Flue LF Corroded metal chimney Entire Building 3 4 1-2 years LF Coping - Metal Entire Building 222 5 1-2 years Bent gutter, disconnected joints throughout. Leaks and damage to brick below **Downspouts - Exterior Downspouts** Entire Building 36 LF 6 10+ vears Downspouts - Exterior Downspouts 12 LF Entire Building 4 1-2 years Broken, displaced/missing downspout. Damage to brick wall Roof - Asphalt Gravel Ballast Entire Building 3,100 SF 4 1-2 years Blistering, deteriorated sealant, soft spots SF 7 Roof Structure - Concrete Entire Building 3,100 10+ years Walls Exterior Walls - Brick Entire Building 2,081 SF 6 10+ years Exterior Walls - Brick Entire Building SF 5 10+ years 50 SF Exterior Walls - Brick Entire Building 150 4 1-2 years Open joints, Cracked brick Exterior Walls - Stone-Cast Entire Building 10 SF 5 10+ vears Windows



· · · · · · ·
imend
ement Comments
/ears
/ears
/ears
/ears
2



**Category : Exterior Building : Field House 5 - Leased** Recommend Location **Replacement** Comments Item - Type Quantity UOM Rank Group Entrance Exterior Doors - Exterior Wood Door 2 ΕA 6 1 10+ years 2 ΕA Exterior Doors - Exterior Wood Door 1 6 2-5 years Foundation SF 7 Superstructure - Slab on Grade Entire Building 320 10+ years Lighting Exterior Lighting - Wall Mounted Entire Building 1 ΕA 6 2-5 years Roof System Roof - Asphalt Shingle 320 SF Entire Building 6 6-10 years SF Roof Structure - Heavy Timber Entire Building 320 7 10+ years Unable to gain access to the building. Chicago park district has keys to Gates Walls Exterior Walls - Wood Siding Entire Building 503 SF 6 6-10 years Unable to get access to this building, only park district has keys to the gates SF Exterior Walls - Wood Siding Entire Building 20 4 1-2 years Burnt section of siding, Damage to the fascia Windows SF Guard - Guards wire guard Entire Building 10 6 2-5 years Windows - Wood- Single-pane Entire Building 10 SF 6 2-5 years **Category : Room Building : Field House 5 - Leased** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Mechanical/ Service Rooms Storage Room Red building 300 SF 5 Building is inaccessible. POC did not 2-5 years have keys.



Catego	ry : Exterior		В				
0	Here Town	Less ten	Overstites		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance				<b>F</b> A	0	0.40	
	Exterior Doors - Overhead Rolling/ Garage Door	1	1	EA	6	6-10 years	
	Power Door Operator and Controls	1	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	5	1-2 years	Door is corroding
_Foundati	on						
	Foundation - Concrete	Entire Building	72	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	320	SF	7	10+ years	
_Roof Sys	stem						
	Coping - Metal	Entire Building	72	LF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	320	SF	6	10+ years	Tarred over roof
	Roof Structure - Concrete	Entire Building	320	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	503	SF	6	10+ years	
Windows							
	Lintels - Steel	Entire Building	20	LF	6	10+ years	
	Windows - Louver	Entire Building	8	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Field H	louse 6	
	-			U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Storage Room	Garage storage	300	SF	7	10+ years	



**Category : Exterior Building : Field House 7 - East** Recommend Location Replacement Item - Type Quantity UOM **Comments** Group Rank Entrance Exterior Doors - Exterior Steel Door FΑ 6 1 1 10+ years FΑ Exterior Doors - Transom Lite 6 10+ years 1 1 Exterior Stairs - Concrete LF 7 1 4 10+ years Exterior Doors - Exterior Steel Door 2 1 ΕA 6 10+ years 2 Exterior Doors - Transom Lite 1 EA 6 10+ years Exterior Stairs - Concrete 2 LF 10+ years 4 6 3 Exterior Doors - Exterior Steel Door 1 ΕA 6 10+ years Exterior Doors - Transom Lite 3 1 ΕA 6 10+ years LF Exterior Stairs - Concrete 3 4 6 10+ years Exterior Doors - Exterior Steel Door FΑ 4 1 6 10+ years Exterior Doors - Transom Lite 4 1 EΑ 6 10+ years Exterior Stairs - Concrete LF 6 4 10+ years 4 Foundation Foundation - Concrete LF 7 Entire Building 80 10+ years 400 SF Superstructure - Concrete Entire Building 7 10+ years Lighting Exterior Lighting - Wall Mounted 2 FΑ 6 Entire Building 10+ years Roof System Chimney - Brick Chimney- Concrete/ Mortar LF Entire Building 15 6 10+ years Liner LF Coping - Metal 68 6 10+ years Entire Building Coping - Metal Entire Building 12 LF 5 1-2 years Bent coping LF **Downspouts - Interior Downspouts** Entire Building 12 6 10+ years SF Roof - Asphalt Gravel Ballast Entire Building 400 6 6-10 years Asphalt only, no gravel Roof Structure - Concrete SF 7 10+ years Entire Building 400 Walls Exterior Walls - Brick 676 SF 6 Entire Building 10+ years SF Exterior Walls - Brick Entire Building 100 4 1-2 years Spalled, cracked, concrete Windows Lintels - Steel 8 LF 6 Entire Building 10+ years SF Windows - Louver Entire Building 24 6 10+ years



NCA S							810 E 103rd STREET, Chicago, IL 6062	
Catego	ry : Electrical		B	uilding	: Field H	House 7 - East		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Power Di	istribution							
	Lighting and Power Panels - 100 A	1st Floor	1	EA	4	1-2 years	Corroded	
Catego	ry : Mechanical		В	uilding	: Field I	House 7 - East		
_			• • • •			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Boiler Sy								
	Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH	1st Floor	1	EA	6	6-10 years		
	Combustion Dampers	1st Floor	1	EA	6	6-10 years		
	Hot Water Pump	1st Floor	1	EA	6	2-5 years		
	Non Condensing- Water Tube- Flexible	1st Floor	1	EA	6	10+ years		
	Tube- Force Draft- Hot Water Boiler - Less than 500 MBH							
	Piping - Chilled Water Pipes- Steel	1st Floor	150	LF	4	6-10 years		
	Water Fill System	1st Floor	1	EA	6	6-10 years		
Heating I	Devices							
	Fin Tube - Hot Water	1st Floor	120	LF	6	6-10 years		
Tempera	ture Control		0.000	~-		0.40		
	Electric Controls	Entire Building	3,250	SF	6	6-10 years		
	Electric Thermostat	Entire Building	1	EA	5	1-2 years		
Ventilatio								
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	3	EA	6	6-10 years		
Catago	ry · Plumbing		D	uilding	· Field I	House 7 - East		
Calego	ry : Plumbing			unung	. rieid r	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate			Quantity	0.0111				
	Gas Heater - 150000 - 300000 BTU/HR	1st Floor	1	EA	6	6-10 years		
	Hot Water Storage Tank_Gas - 201 - 500	1st Floor	1	EA	2	1-2 years	Decommissioned	
	Gallons	13(1100)	I	ĽA	2	1-2 years	Decommissioned	
Piping								
	Domestic Piping-Hot Water Return Lines	1st Floor	3,250	SF	4	2-5 years	Piping is more than 50 years old	
	Domestic Piping-Hot/Cold Water Supply	1st Floor	3,250	SF	4	2-5 years	Piping is more than 50 years old	
	(Horizontal Lines)		-,		-			
	Domestic Piping-Hot/Cold Water Supply	1st Floor	3,250	SF	4	2-5 years	Piping is more than 50 years old	
	(from Risers to Fixtures)		-,			,		
	Sanitary Piping	1st Floor	3,250	SF	5	2-5 years	Piping is more than 50 years old	



# George H Corliss High School 810 E 103rd STREET, Chicago, IL 60628

Category : Plumbing		Building : Field House 7 - East						
					Recommend			
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Storm Piping	1st Floor	3,250	SF	5	2-5 years	Piping is more than 50 years old		
Vent Piping	1st Floor	3,250	SF	6	6-10 years	Piping is more than 50 years old		


## Category : Room

Building : Field House 7 - East

	, , , , , , , , , , , , , , , , , , ,		Recommend				
)	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oor	n						
	Accessories	Mens restroom (south)	220	SF	5	2-5 years	
	Ceiling - Exposed	Mens restroom (south)	220	SF	7	10+ years	
	Doors - Steel Doors incl hw	Mens restroom (south)	1	EA	6	10+ years	
	Floor - Concrete	Mens restroom (south)	220	SF	7	10+ years	
	Floor Drain	Mens restroom (south)	1	EA	7	10+ years	
	Hand Dryer	Mens restroom (south)	1	EA	7	6-10 years	
	Lavatory	Mens restroom (south)	1	EA	6	2-5 years	
	Lighting - Pendent/Surface	Mens restroom (south)	2	EA	7	6-10 years	
	Partitions	Mens restroom (south)	3	EA	7	10+ years	
	Urinals	Mens restroom (south)	3	EA	7	6-10 years	
	Walls - Masonry	Mens restroom (south)	630	SF	6	10+ years	
	Water Closet	Mens restroom (south)	2	EA	6	6-10 years	
	Accessories	Unisex	48	SF	7	6-10 years	
	Ceiling - Exposed	Unisex	48	SF	7	10+ years	
	Doors - Steel Doors incl hw	Unisex	1	EA	7	6-10 years	
	Floor - Concrete	Unisex	220	SF	7	10+ years	
	Hand Dryer	Unisex	1	EA	5	1-2 years	Doesn't power on
	Lavatory	Unisex	1	EA	6	2-5 years	
	Lighting - Pendent/Surface	Unisex	1	EA	7	6-10 years	
	Walls - Concrete Block	Unisex	260	SF	6	10+ years	
	Water Closet	Unisex	1	EA	7	10+ years	
	Accessories	Womens restroom	220	SF	5	6-10 years	
	Ceiling - Exposed	Womens restroom	220	SF	7	10+ years	
	Doors - Steel Doors incl hw	Womens restroom	1	EA	6	6-10 years	
	Floor - Concrete	Womens restroom	220	SF	7	10+ years	
	Floor Drain	Womens restroom	1	EA	7	10+ years	
	Hand Dryer	Womens restroom	1	EA	7	6-10 years	
	Lavatory	Womens restroom	3	EA	5	2-5 years	
	Lighting - Pendent/Surface	Womens restroom	2	EA	7	6-10 years	
	Partitions	Womens restroom	3	EA	5	2-5 years	
	Walls - Masonry	Womens restroom	630	SF	6	10+ years	
	Water Closet	Womens restroom	3	EA	6	6-10 years	



**Category : Exterior Building : Grandstand East** Recommend Location Replacement Item - Type Quantity UOM **Comments** Group Rank Entrance Exterior Doors - Exterior Steel Door ΕA 1 6 10+ years 1 FΑ 6 Exterior Doors - Transom Lite 1 10+ years 1 Exterior Stairs - Steel or Aluminum LF 1 16 6 10+ years Stair Handrail - Steel\_Stair Handrail 1 12 LF 7 10+ years Foundation Foundation - Concrete Entire Building 12.740 LF 7 10+ years Post and beam construction Superstructure - Steel Entire Building 12,700 SF 7 10+ years Grandstand LF Bleacher Seating Entire Building 3.120 6 10+ years Exterior Stairs - Steel or Aluminum Entire Building 36 LF 6 10+ years LF 7 Fencing - Chain Link Entire Building 635 10+ years LF Handrails Entire Building 128 7 10+ years LF Ramp Handrail - Steel\_Ramp Handrail 7 10+ years Entire Building 112 Ramps - Steel or Aluminum Entire Building 56 LF 6 10+ years LF Stair Handrail - Steel Stair Handrail Entire Building 24 7 10+ years Liahtina Exterior Lighting - Lighting 4 ΕA 6 Entire Building 10+ years Exterior Lighting - Wall Mounted Entire Building 2 ΕA 6 10+ years Roof System Coping - Metal Press box 56 LF 6 10+ years Gutter **Downspouts - Exterior Downspouts** Press box 80 LF 6 10+ years Roof - EPDM/ Synthetic Rubber SF Press box 160 6 10+ years Unable to access this roof Roof Structure - Steel / Metal Deck/ SF 7 10+ years Press box 160 Concrete Topping Walls Exterior Walls - Prefabricated Metal Panel SF 7 Press box 348 10+ years Wall Windows Guard - Guards wire guard Entire Building 20 SF 6 10+ years SF 6 40 10+ years Storefront Windows Entire Building SF Windows - Decorative Entire Building 60 7 10+ years **Category : Electrical Building : Grandstand East** Group Item - Type Location Quantity UOM Rank Recommend **Comments** 





Category : Exterior			В	uilding	: Grand	stand West Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance			<b>,</b>				
ппансе	Exterior Doors - Exterior Steel Door	1-Press box	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	1-Press box	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	1-Press box			7	10+ years	
			15	LF			
	Stair Handrail - Steel_Stair Handrail	1-Press box	12		7	10+ years	
	Exterior Doors - Store Front	2-Press box	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	2-Press box	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	2-Press box	16	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	2-Press box	16	LF	7	10+ years	
oundatio	on						
	Foundation - Concrete	Entire Building	19,600	LF	7	10+ years	Post and beam construction
	Superstructure - Steel	Entire Building	19,600	SF	6	1-2 years	Corrosion at support metal plates flooring/ceiling. Peeling paint, rus throughout
randsta							
	Bleacher Seating	Entire Building	6,800	LF	6	10+ years	
	Exterior Stairs - Steel or Aluminum	Entire Building	20	LF	6	10+ years	
	Fencing - Chain Link	Entire Building	776	LF	7	10+ years	
	Handrails	Entire Building	235	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entire Building	128	LF	7	10+ years	
	Ramps - Steel or Aluminum	Entire Building	64	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entire Building	80	LF	7	10+ years	
hting							
	Exterior Lighting - Lighting	Entire Building	16	EA	6	6-10 years	
of Sys	tem						
	Coping - Metal	Press Box	132	LF	6	10+ years	Gutter
	Downspouts - Exterior Downspouts	Press Box	80	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Press Box	650	SF	6	6-10 years	Unable to see this roof, no acces
	Roof Structure - Steel / Metal Deck/	Press Box	650	SF	7	10+ years	
	Concrete Topping					<b>, , , , , , , , , ,</b>	
lls							
	Exterior Walls - Prefabricated Metal Panel Wall	Press box	568	SF	7	10+ years	
ndows							
	Guard - Guards wire guard	Grandstand	168	SF	6	6-10 years	



810 E 103rd STREET, Chicago, IL 60628 **Category : Exterior Building : Grandstand West** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Storefront Windows Press box 252 SF 6 10+ years Windows - Decorative Press box 54 SF 7 10+ years **Category : Electrical Building : Grandstand West** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System ΕA 2 Exit Signs - Multipurpose Room 2nd Floor 4 0-1 year No backup generator or batteries Power Distribution ΕA Lighting and Power Panels - Above 100 A 2nd Floor 1 6 10+ years **Category : Mechanical Building : Grandstand West** Recommend Location UOM Rank Replacement Group Item - Type Quantity Comments Ventilation Exhaust Fans- Indoor - Less than 500 CFM 2nd Floor 3 ΕA 6 6-10 years Category : Room **Building : Grandstand West** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Administrative Suites/Offices AC Unit Press Box 3 ΕA 7 10+ years Ceiling - Plaster/Drywall Press Box 329 SF 7 10+ years Doors - Steel Doors incl hw Press Box ΕA 4 7 10+ years 329 SF Floor - Sport Flooring Press Box 7 10+ years Lighting - Pendent/Surface Press Box 9 ΕA 7 6-10 years SF Walls - Vinyl Coated Gypsum Panel Press Box 864 7 10+ years



Catego	ry : Site	Building : Site							
		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Athletic									
	Frame Press Box	Playing Field	1	EA	6	10+ years			
	Goalpost	Playing Field	2	EA	7	10+ years			
	Lighting	Playing Field	72	EA	6	10+ years	72 lamps on four posts		
	Metal Bleachers	Playing Field	18,750	LF	6	10+ years			
	Scoreboard	Playing Field	2	EA	7	10+ years			
	Surface - Synthetic	Playing Field	72,630	SF	6	6-10 years			
	-								
Civil/Drai									
	Civil/ Drainage - Catch Basin	Entire Site	28	EA	6	10+ years			
	Civil/ Drainage - Site Drain	Entire Site	356	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years			
encina									
	Fencing - Chain Link	Entire Site	1,790	LF	7	10+ years			
	Fencing - Guard Rail	Entire Site	150	LF	6	10+ years			
	Fencing - New Standard Ornamental	Entire Site	748	LF	6	10+ years			
	Fencing - New Standard Ornamental	Entire Site	2	LF	4	1-2 years	Damage to post.		
	Fencing - Old Standard Ornamental	Entire Site	16	LF	4	0-1 year	Broken gate		
Landsca									
anusca	Benches	Entire Site	4	EA	7	10+ years			
	Landscape - Grass	Entire Site	9,084	SF	6	10+ years			
	Landscape - Hardscape- Asphalt	Entire Site	17.288	SF	6				
	Landscape - Hardscape- Asphalt	Entire Site	6.789	SF	5	10+ years	Asphalt walkways- large cracks,		
	Landscape - Hardscape- Asphalt	Entire Site	0,789	ЪГ	5	1-2 years	upheaved and badly damaged		
	Landscape - Hardscape- Asphalt	Entire Site	1,200	SF	4	1-2 years	Damaged areas, alligatored and		
			,			<b>,</b>	missing sections of surface		
	Landscape - Hardscape- Concrete	Entire Site	24,146	SF	6	10+ years	5		
	Landscape - Hardscape- Concrete	Entire Site	145	SF	5	1-2 years	Large crack, continues along		
					-	,	grandstand		
	Lighting - Pole Mounted	Entire Site	36	EA	6	6-10 years	36 lamps on four posts		
	Parkway trees	Entire Site	16	EA	6	10+ years			
Parking I	ot								
	Concrete Curbs	Parking Lot- East	530	LF	6	10+ years			
	Concrete Curbs	Parking Lot- East	30	LF	4	1-2 years	Broken curbs		
	Interior Plantings	Parking Lot- East	500	LF	6	10+ years			
	Lighting - Pole Mounted	Parking Lot- East	16	EA	6	2-5 years			
	Lighting - Pole Mounted	Parking Lot- East	4	EA	6	6-10 years			
	Surface - Asphalt	Parking Lot- East	109,200	SF	6	6-10 years			
	Surface - Asphalt	Parking Lot- East	57,000	SF	4	1-2 years	Large pot holes, large areas of		
	Curraso Asprian		57,000	0	-	1 2 years	Large por noiss, large areas of		



**Building : Site** Category : Site Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments disintegrated or alligatored surfaces SF Surface - Concrete Parking Lot- East 2.500 6 10+ years Concrete Curbs Parking Lot- West 720 LF 6 10+ years 1-2 years Concrete Curbs Parking Lot- West LF 130 4 Broken or missing concrete curbs Lighting - Pole Mounted Parking Lot-West EΑ 6 10+ years 1 SF Surface - Asphalt Parking Lot-West 27,612 6 10+ years This is the west parking lot. Surface - Asphalt Parking Lot- West 200 SF Depressions, large cracks, 4 1-2 years Disintegrating surfaces, alligatored surfaces Sidewalks Sidewalks - Internal Walks Entire Site 360 LF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site SF 6 10+ years 3,064 SF Sidewalks - Perimeter Sidewalks Entire Site 3.000 4 1-2 years Broken, spalled sidewalks Signage Flag Pole - Flag Pole Entire Site ΕA 1 6 6-10 years Entire Site ΕA 7 Monument - Sign 10+ years 1

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



## **Classroom Summary**

					Floor Plan		Glazed	Operable		
				Room	Room	Area	Window	Window	Window	Smart-
	Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board