



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1893	4	47,500
Campus Total			47,500

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	3.2	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3.2	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 1 - North	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 1 - North	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 1 - North	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 1 - North	10	LF	5	10+ years	Minor cracks
	Exterior Doors - Exterior Steel Door	Entrance 2 - East	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 2 - East	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2 - East	47	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 3.1 - South - Boiler room	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 4 - SW	1	EA	6	10+ years	
	Exterior Stairs - Stone	Entrance 4 - SW	3	LF	6	10+ years	
	Entrance Control - Audio and Video	Entrance 5 - West	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 5 - West	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 5 - West	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 5 - West	12	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 5 - West	37	LF	5	2-5 years	Cracked concrete
	Entrance Control - Audio and Video	Entrance 6 - North	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 6 - North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 6 - North	3	LF	5	1-2 years	Cracks in concrete
	Ramp Handrail - Steel_Ramp Handrail	Entrance 6 - North	35	LF	5	10+ years	Concrete is cracked at rail posts
	Ramps - Concrete	Entrance 6 - North	20	LF	5	1-2 years	Cracked concrete at rail posts
	Exterior Doors - Exterior Steel Door	Entrance 7 - Center courtyard	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 3 - SE	1	EA	6	10+ years	
						·	



aicgo	ry : Exterior		В	uilding	: Main			
_				_		Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exterior Stairs - Concrete	Exit 3 - SE	3	LF	5	1-2 years	Cracked concrete	
	Exterior Doors - Exterior Steel Door	Exit 4.1 - SW - 1st floor fire escape	1	EA	6	10+ years		
	Exterior Doors - Transom Lite	Exit 4.1 - SW - 1st floor fire escape	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	Exit 4.2 - 2nd Floor Fire Escape	1	EA	6	10+ years		
	Exterior Doors - Side lite	Exit 4.2 - 2nd Floor Fire Escape	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	Exit 4.2 - 2nd Floor Fire Escape	4	EA	6	10+ years		
	Exterior Stairs - Concrete	Exit 4.2 - 2nd Floor Fire Escape	4	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Exit 4.3 - 3rd Floor Fire Escape	1	EA	6	10+ years		
	Exterior Doors - Side lite	Exit 4.3 - 3rd Floor Fire Escape	2	EA	6	10+ years		
	Exterior Stairs - Concrete	Exit 4.3 - 3rd Floor Fire Escape	4	LF	6	10+ years		
e Esc	ape							
	Fire Escape	South Façade	80	LF	6	10+ years		
undat								
	Foundation - Masonry	Entire Building	600	LF	7	10+ years		
	Foundation - Masonry	Entire Building	20	LF	6	10+ years	Walls need Tuckpointing	
	Superstructure - Heavy Timber	Entire Building	47,400	SF	7	10+ years	. •	
	Superstructure - Heavy Timber	Entire Building	100	SF	5	1-2 years	Engineer is concerned that the reason the tiles pop is in the	
							superstructure	
							superstructure	
hting							superstructure	
hting	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	10+ years	superstructure	
			16		6	10+ years	superstructure	
	stem Access Ladder - Metal	Entire Building Roof 1	16	EA	6	10+ years 2-5 years	superstructure	
	stem						superstructure	
	stem Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	1	EA	5	2-5 years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1 Roof 1	1 65 5	EA LF LF	5 6 5	2-5 years 10+ years 10+ years		
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone	Roof 1 Roof 1 Roof 1	1 65 5 60	EA LF LF	5 6 5	2-5 years 10+ years 10+ years 10+ years		
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta	Roof 1 Roof 1 Roof 1 Roof 1 Roof 1 Roof 1	1 65 5 60 55	EA LF LF LF LF	5 6 5 6 6	2-5 years 10+ years 10+ years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts	Roof 1	1 65 5 60 55 205	EA LF LF LF LF LF	5 6 5 6 6 5	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years		
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height	Roof 1	1 65 5 60 55 205 120	EA LF LF LF LF LF	5 6 5 6 5 6	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height	Roof 1	1 65 5 60 55 205 120 2	EA LF LF LF LF LF LF	5 6 5 6 5 6 5	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen	Roof 1	1 65 5 60 55 205 120 2 4,920	EA LF LF LF LF LF SF	5 6 5 6 5 6 5	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen Roof Structure - Heavy Timber	Roof 1	1 65 5 60 55 205 120 2 4,920 4,920	EA LF LF LF LF LF SF SF	5 6 5 6 5 6 5 6 7	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen Roof Structure - Heavy Timber Access Ladder - Metal	Roof 1	1 65 5 60 55 205 120 2 4,920 4,920	EA LF LF LF LF LF SF SF EA	5 6 5 6 6 5 6 7 5	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years	Open joints at brick chimney	
ghting.	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen Roof Structure - Heavy Timber Access Ladder - Metal Coping - Metal	Roof 1 Roof 2 Roof 2	1 65 5 60 55 205 120 2 4,920 4,920 1 160	EA LF LF LF LF SF SF EA LF	5 6 5 6 6 5 6 7 5 6	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen Roof Structure - Heavy Timber Access Ladder - Metal Coping - Metal Downspouts - Interior Downspouts	Roof 1 Roof 2 Roof 2 Roof 2	1 65 5 60 55 205 120 2 4,920 4,920 1 160 60	EA LF LF LF LF SF EA LF LF	5 6 5 6 6 5 6 7 5 6 6	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years	Open joints at brick chimney	
	Access Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner Coping - Stone Coping - Terra Cotta Downspouts - Exterior Downspouts Parapet - 16" - 30" Height Parapet - 16" - 30" Height Roof - Modified Bitumen Roof Structure - Heavy Timber Access Ladder - Metal Coping - Metal	Roof 1 Roof 2 Roof 2	1 65 5 60 55 205 120 2 4,920 4,920 1 160	EA LF LF LF LF SF SF EA LF	5 6 5 6 6 5 6 7 5 6	2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	Open joints at brick chimney	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof 2	2,810	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 2	2,810	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EA	4	1-2 years	Attic opening is too small for a person to move comfortably up or down the
							ladder
	Access Ladder - Metal	Roof 3	1	EA	4	1-2 years	There is not enough room in the attic opening to get through the ladder safely
	Coping - Metal	Roof 3	160	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 3	80	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	80	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	3,096	SF	6	10+ years	
	Roof Hatch - Metal	Roof 3	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 3	3,096	SF	7	10+ years	
	Coping - Terra Cotta	Roof 4	195	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	35	LF	5	6-10 years	Leaking gutters
	Parapet - 16" - 30" Height	Roof 4	60	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	135	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	1,908	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 4	300	SF	4	1-2 years	Several all patches are coming apart at the seams
	Roof Structure - Heavy Timber	Roof 4	2,208	SF	7	10+ years	at the coame
	Coping - Terra Cotta	Roof 5	75	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 5	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5	75	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	750	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 5	750	SF	7	10+ years	
NA7 II							
_Walls	Cheek-Wall - Concrete	Entire Building	34	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	11	SF	5	1-2 years	Cracked and broken cheek wall at door 2
	Cornice - Cast Stone	Entire Building	120	LF	6	10+ years	300
	Cornice - Cast Stone	Entire Building	3	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	14,400	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	300	SF	4	10+ years	Open joints and cracks in the bricks
	Exterior Walls - Concrete Block	Entire Building	100	SF	6	10+ years	. ,
	Exterior Walls - Stone-Cast	Entire Building	1,275	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	50	SF	5	10+ years	Deteriorated mortar, open joints
	Exterior Walls - Stone-Cut	Entire Building	1,610	SF	5	10+ years	,
_Windows	S						
	Guard - Guards wire guard	Entire Building	930	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Brick	Entire Building	378	LF	6	10+ years	
	Lintels - Brick	Entire Building	12	LF	4	1-2 years	Failing brick lentils at several doors
	Lintels - Steel	Entire Building	65	LF	6	10+ years	
	Lintels - Stone	Entire Building	300	LF	6	10+ years	
	Windows - Decorative	Entire Building	40	SF	6	10+ years	
	Windows - Louver	Entire Building	42	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	210	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,030	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	4	0-1 year	No backup generator
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	4	0-1 year	No backup generator
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	4	0-1 year	Quantity change per current observation No backup Generator
	Exit Signs - Corridors and Stairs	Entire Building	22	EΑ	6	6-10 years	, , , , , , , , , , , , , , , , , , ,
	Exit Signs - Lunchroom	Entire Building	5	EΑ	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	3	EA	5	6-10 years	Lit is poor
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,414	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,660	SF	6	6-10 years	Located in basement Per current observation
	Security System - CCTV	Entire Building	47,500	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	47,500	SF	6	6-10 years	New item added per current
	Cooding Cyclem Initiation Detection	Enail Dalianing	11,000	O.	Ū	o ro youro	observation
Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	47,500	SF	6	6-10 years	
Power D	istribution						
I OMEI D	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years 10+ years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	•	3			•	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	3	EA EA	6 4	10+ years 2-5 years	Quantity change per current
	5 - 15 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	································	· ·	<u> </u>	•	7 7 0 0.0	yg- po. ou



Category	y : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observation Missing breakers
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp						
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	
Category	y : Fire Protection		В	uilding	: Main		
				_		Recommend	
3 roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alarm	1						
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	9,250	SF	6	10+ years	
	Fire Alarm_System	Entire Building	47,500	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	ĒΑ	6	10+ years	
	The Compositions	g	·		· ·	. o . y ca. c	
Pump Roo	om Assembly						
	Fire Pump - Less than 25hp	Entire Building	1	EA	5	2-5 years	corroded
	Jockey Pump	Entire Building	1	EA	3	0-1 year	Pump Missing and abandoned
Sprinkler S	•						
	Dry Sprinkler System	Entire Building	47,500	SF	6	10+ years	
	Sprinkler Heads	Entire Building	47,500	SF	7	10+ years	
	Sprinkler Piping	Entire Building	47,500	SF	6	10+ years	
Category	y : Mechanical		В	uilding	: Main		
,						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Handlir	ng Systems						
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	6-10 years	Control needs to be adjusted
	Steam Coils - Greater than 35000 cfm					•	•
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Dampers are rusted
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	6	6-10 years	•
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	4	2-5 years	No return ductwork
	and Ducts					·	
	Zone Dampers	Mechanical Room	13	EA	5	6-10 years	Manually open and close Pneumati
							system is not working properly
	Zone Dampers	Mechanical Room	13	EA	4	2-5 years	Manually open and close Pneumat
							system is not working properly
Boiler Syst	stome						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	Kewanee - Need some repair
	Pressure Boiler - 50 - 75 HP	Doller Koolli	ı	EA	J	0-10 years	Newaniee - Need Some repair
	1.1000010 Dollo1 00 10111						



	ry : Mechanical		В	uilding	. wam		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	Corroded and needs to be replaced
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	Base corroded and needs to be replaced
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Boiler Room	1	EA	6	10+ years	
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	6-10 years	
	Steam Traps	Boiler Room	8	EA	3	2-5 years	Majority Traps leaking
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	Mohawk
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	Corroded and needs to be replaced
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	Basin needs to be replace
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	Control needs to be replaced
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Steam Traps	Boiler Room	8	ĒΑ	3	2-5 years	Majority traps leaking
Gas Boo	Gas Booster	Boiler Room	2	EA	6	6-10 years	
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	6	10+ years	Quantity change per current observation
	Wall Heater - Electric	Entire Building	2	EA	6	10+ years	
	Cabinet Heaters - With Steam Coil	Entire Building	3	EA	2	0-1 year	Quantity change per current observation Not working per current observation
	Unit Heater - Electric	Entire Building	3	EA	6	10+ years	Quantity change per current observation
	Unit Heater - Electric	Entire Building	3	EA	6	6-10 years	Location change per current observation
	Unit Heater - Electric	Entire Building	1	EA	2	0-1 year	Move from unit heaters Missing coils and cover
	Unit Heater - Steam	Entire Building	4	EA	2	0-1 year	New item added per current observation
Mechani	cal Plumbing						
	Chilled Water Pump - Less than 10	Mechanical Room	2	EA	5	2-5 years	Base Corroded and needs repair



Catego	ry : Mechanical		В	uilding	: Main		
		1	0	11014	D	Recommend	2
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control	E (Ε.Δ.		0.4	N % 11.1
	Electric Thermostat	Entire Building	4	EA	4	0-1 year	New item added per current observation Served unit heaters
	Pneumatic System	Entire Building	47,500	SF	3	1-2 years	New item added per current observation Air compressor working but pipes leaking
	Thermostats - Pneumatic	Entire Building	32	EA	5	2-5 years	Need to be refurbished
Ventilatio	nn						
<u>v Critiane</u>	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EΑ	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	Installed new in 2021 Per current observation
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room Boiler Room	1 1	EA EA	6 6	6-10 years 6-10 years	
	ZOO GAIIONS						
	200 Gallorio						
Piping							
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	47,500	SF	6	10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building	47,500	SF	6	10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Entire Building Entire Building	47,500 47,500	SF SF	6 6		
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	47,500	SF SF	6	10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building Entire Building	47,500 47,500	SF SF	6 6	10+ years 10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building Entire Building Entire Building Entire Building Entire Building	47,500 47,500 47,500	SF SF SF SF	6 6	10+ years 10+ years 10+ years	
Piping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building Entire Building Entire Building	47,500 47,500 47,500 47,500	SF SF SF	6 6 6	10+ years 10+ years 10+ years 10+ years	



Catego	ry : Plumbing	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Vent Piping	Entire Building	47,500	SF	6	10+ years	
Pumps							
·	Pumps - Domestic Booster Pump-Simplex	1st Floor	1	EA	6	6-10 years	Not booster pump - per current observation It's Irrigation pump system and corroded

Category: Room **Building: Main**

iicgo	ry . Room			unung	· Walli	D	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices	Location	Quantity	COM	Italik	Replacement	Comments
ımınısı		100	4	ΓΛ	7	0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Deneirod
	AC Unit	102	1	EA SF	7	6-10 years	Repaired
	Ceiling - Plaster/Drywall	102	420		6	10+ years	
	Doors - Wood Doors inclu hw	102	1	EA	6	10+ years	
	Floor - Tile	102	420	SF	6	10+ years	5
	Lighting - Pendent/Surface	102	6	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	102	1,100	SF	6	10+ years	
	AC Unit	L: Basement Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Basement Office	190	SF	7	10+ years	
	Doors - Wood Doors inclu hw	L: Basement Office	1	EA	7	10+ years	
	Floor - Tile	L: Basement Office	190	SF	7	10+ years	
	Lighting - Pendent/Surface	L: Basement Office	2	EA	5	1-2 years	Exposed wire
	Walls - Masonry	L: Basement Office	270	SF	7	10+ years	
	Walls - Plaster/Drywall	L: Basement Office	270	SF	7	10+ years	
	AC Unit	L: Main Office 1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	L: Main Office 1st Floor	560	SF	6	10+ years	
	Doors - Transom Window	L: Main Office 1st Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	L: Main Office 1st Floor	1	EA	6	10+ years	
	Floor - Tile	L: Main Office 1st Floor	560	SF	6	10+ years	
	Lighting - Pendent/Surface	L: Main Office 1st Floor	8	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	L: Main Office 1st Floor	1,340	SF	6	10+ years	
	AC Unit	L: Principal's Office in Main 1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Principal's Office in Main 1st Floor	190	SF	6	10+ years	
	Doors - Wood Doors inclu hw	L: Principal's Office in Main 1st Floor	1	EA	6	10+ years	
	Floor - Tile	L: Principal's Office in Main 1st Floor	190	SF	6	10+ years	
	Lighting - Pendent/Surface	L. Principal's Office in Main 1st Floor	3	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	L: Principal's Office in Main 1st Floor	695	SF	6	10+ years	•
	Ceiling - Plaster/Drywall	Teacher's Lounge 2nd Floor	250	SF	6	10+ years	
	Doors - Transom Window	Teacher's Lounge 2nd Floor	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge 2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	Teacher's Lounge 2nd Floor	250	SF	6	10+ years	
	Lighting - Pendent/Surface	Teacher's Lounge 2nd Floor	4	EA	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	Teacher's Lounge 2nd Floor	910	SF	6	10+ years	ODSGI VALIONS

Campus Name: Drummond Page : 8 of 23 Assessment Date: 01/31/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Slnk	Teacher's Lounge 2nd Floor	1	EΑ	7	10+ years	
<u>Gymnas</u>	ia						
•	Ceiling - Splined	L: 3rd Floor	2,440	SF	6	10+ years	
	Ceiling - Splined	L: 3rd Floor	24	SF	5	1-2 years	Missing ceiling tile
	Doors - Wood Doors inclu hw	L: 3rd Floor	4	ĒΑ	7	10+ years	3 - 3 3
	Floor - Wood	L: 3rd Floor	2,464	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	L: 3rd Floor	, 1	EA	6	1-2 years	Light not functioning
	Sodium					,	3
	Lighting - Metal Halide/Sodium Vapor	L: 3rd Floor	8	EA	6	10+ years	Updated to match current
	9 - 9					, , , , , ,	observations
	Scoreboards	L: 3rd Floor	1	EA	7	10+ years	
	Sound System	L: 3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	L: 3rd Floor	40	SF	6	10+ years	
	Walls - Plaster/Drywall	L: 3rd Floor	4,025	SF	6	10+ years	
	Walls - Plaster/Drywall	L: 3rd Floor	30	SF	5	1-2 years	Damaged
	•					,	ŭ
unch &	Multipurpose Room						
	AC Unit	L: 1st Floor Lunchroom/Kitchen	2	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	L: 1st Floor Lunchroom/Kitchen	995	SF	6	10+ years	
	Floor - Tile	L: 1st Floor Lunchroom/Kitchen	995	SF	6	10+ years	
	Floor - Tile	L: 1st Floor Lunchroom/Kitchen	12	SF	4	0-1 year	
	Lighting - Pendent/Surface	L: 1st Floor Lunchroom/Kitchen	21	ĒΑ	7	6-10 years	Repaired
	Serving Line	L: 1st Floor Lunchroom/Kitchen	15	LF	6	10+ years	- F
	Storage/ Closet	L: 1st Floor Lunchroom/Kitchen	90	SF	7	10+ years	
	Walls - Plaster/Drywall	L: 1st Floor Lunchroom/Kitchen	1,595	SF	6	10+ years	
	AC Unit	L: Basement	1	ĒΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Basement	995	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	L: Basement	995	SF	7	10+ years	
	Lighting - Pendent/Surface	L: Basement	14	EA	7	6-10 years	Repaired
	Serving Line	L: Basement	8	LF	7	10+ years	
	Storage/ Closet	L: Basement	195	SF	7	10+ years	
	Walls - Plaster/Drywall	L: Basement	990	SF	7	10+ years	
	Ceiling - Plaster/Drywall	L: Basement	945	SF	7	10+ years	
	Doors - Wood Doors inclu hw	L: Basement	1	EA	5	1-2 years	Missing door knob
	Floor - Concrete Epoxy/ Painted	L: Basement	945	SF	7	10+ years	3
	Lighting - Pendent/Surface	L: Basement	14	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	L: Basement	1,045	SF	7	10+ years	- 1
			.,5 10	٠.	•	,	
IDF_ID	F						
_	Finishes	203 Library	170	SF	7	10+ years	
	Other Cooling Unit	203 Library	1	EA	7	6-10 years	
	-	-				-	



Catego	ry : Room		В	uilding	: Main		-5 W Contains Office 1, Officego, in 60022
2 2 2 3 0				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms		•			•	
	Storage Room	005 Book Storage	515	SF	7	10+ years	
	Janitor's Closet	1st Floor	15	SF	7	10+ years	
	Janitor's Closet	2nd Floor	20	SF	7	10+ years	
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	450	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	70	SF	5	10+ years	
	Storage Room	Basement	70	SF	7	10+ years	
	Storage Room	Basement	70	SF	5	10+ years	
	Storage Room	Basement	1,290	SF	5	10+ years	
	Janitor's Closet	Basement	50	SF	5	10+ years	
	Storage Room	Basement	70	SF	5	10+ years	
	Storage Room	Basement	70	SF	5	10+ years	
	Boiler Room	Boiler Room	960	SF	5	10+ years	
	Coal Room	Boiler Room	300	SF	5	10+ years	
	Mechanical/ Service Rooms	Engine Rm	300	SF	7	10+ years	Duplicate
	Mechanical/ Service Rooms	Hot Deck	550	SF	7	10+ years	-1
						,	
Restroor	n						
	Accessories	007	72	SF	7	6-10 years	
	Ceiling - Lay-in	007	6	SF	7	6-10 years	Repaired
	Ceiling - Lay-in	007	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	007	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	007	72	SF	6	10+ years	
	Floor Drain	007	1	EA	7	10+ years	
	Lavatory	007	1	EA	7	10+ years	
	Lighting - Lay-in	007	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	007	260	SF	6	10+ years	
	Water Closet	007	1	EA	6	10+ years	
	Accessories	100	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	100	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	100	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	100	72	SF	6	10+ years	
	Floor Drain	100	1	EA	7	10+ years	
	Lavatory	100	1	EA	6	10+ years	
	Lighting - Pendent/Surface	100	1	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	100	345	SF	6	10+ years	
	Water Closet	100	1	EA	6	10+ years	
	Accessories	104	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	104	40	SF	6	10+ years	
	Lavatory	104	1	EA	6	10+ years	
	Lighting - Pendent/Surface	104	1	EA	6	6-10 years	
	-					-	



Catego	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	104	135	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	104	135	SF	6	10+ years		
	Water Closet	104	1	EA	6	10+ years		
	Accessories	2nd Floor	60	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	60	SF	6	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	60	SF	6	10+ years		
	Lavatory	2nd Floor	1	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Flickering	
	Partitions	2nd Floor	2	EA	7	10+ years	3	
	Walls - Plaster/Drywall	2nd Floor	107	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	107	SF	6	10+ years		
	Water Closet	2nd Floor	2	ĒA	6	10+ years		
	Accessories	2nd Floor	60	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	60	SF	6	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	60	SF	6	10+ years		
	Lavatory	2nd Floor	1	EΑ	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Flickering	
	Partitions	2nd Floor	2	EΑ	7	10+ years	- nonconing	
	Walls - Plaster/Drywall	2nd Floor	107	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	107	SF	6	10+ years		
	Water Closet	2nd Floor	2	EA	6	10+ years		
	Accessories	L: 1st Floor Staff Unisex	55	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	L: 1st Floor Staff Unisex	55	SF	6	10+ years		
	Doors - Wood Doors inclu hw	L: 1st Floor Staff Unisex	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	L: 1st Floor Staff Unisex	55	SF	6	10+ years		
	Lavatory	L: 1st Floor Staff Unisex	1	EA	6	10+ years		
	Lighting - Pendent/Surface	L: 1st Floor Staff Unisex	1	EA	7	6-10 years	Repaired	
	Walls - Plaster/Drywall	L: 1st Floor Staff Unisex	150	SF	6	10+ years	Nopuliou	
	Walls - Structural Glazed Tile	L: 1st Floor Staff Unisex	220	SF	6	10+ years		
	Water Closet	L: 1st Floor Staff Unisex	1	EA	6	10+ years		
	Accessories	L: 1st Floor Staff Unisex Inside	70	SF	7	6-10 years		
	Accessories	Lunchroom	70	Oi	,	0-10 years		
	Ceiling - Plaster/Drywall	L: 1st Floor Staff Unisex Inside	70	SF	6	10+ years		
	Celling - Flaster/Drywall	Lunchroom	70	OI.	U	10+ years		
	Doors - Wood Doors inclu hw	L: 1st Floor Staff Unisex Inside	1	EA	6	10 Lyonre		
	Doors - Wood Doors Inclu IIW		'	EA	O	10+ years		
	Floor - Tile Ceramic/ Porcelain	Lunchroom L: 1st Floor Staff Unisex Inside	70	SF	6	10 L VOOTO		
	FIOOI - THE CETAITHE POTCEIAIN	L: 1st Floor Stair Unisex Inside Lunchroom	70	SF	O	10+ years		
	Layotany		4	Ε^	6	6 10 4000		
	Lavatory	L: 1st Floor Staff Unisex Inside	1	EA	6	6-10 years		
	Lighting Dandont/Curface	Lunchroom	4	ГΛ	_	1.0 voors	Lompionus	
	Lighting - Pendent/Surface	L: 1st Floor Staff Unisex Inside	1	EA	5	1-2 years	Lamp cover	
		Lunchroom						



Catego	ategory : Room		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	L: 1st Floor Staff Unisex Inside	1	EA	7	10+ years	
	0. 1 1 0	Lunchroom			•	4.0	
	Student Lockers - One Tier	L: 1st Floor Staff Unisex Inside Lunchroom	4	EA	6	10+ years	
	Walls - Plaster/Drywall	L: 1st Floor Staff Unisex Inside Lunchroom	337	SF	6	10+ years	
	Water Closet	L: 1st Floor Staff Unisex Inside	1	EA	6	10+ years	
	Water Closet	Lunchroom	1		b	10+ years	
	Accessories	L: 2nd Floor Staff Unisex	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	L: 2nd Floor Staff Unisex	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	L: 2nd Floor Staff Unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	L: 2nd Floor Staff Unisex	40	SF	6	10+ years	
	Lavatory	L: 2nd Floor Staff Unisex	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	L: 2nd Floor Staff Unisex	1	EA	6	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	L: 2nd Floor Staff Unisex	135	SF	6	10+ years	ODSEI VALIONS
			135	SF		•	
	Walls - Tile Ceramic/ Porcelain	L: 2nd Floor Staff Unisex			6	10+ years	
	Water Closet	L: 2nd Floor Staff Unisex	1	EA	6	10+ years	
	Accessories	L: Basement Boys	595	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Basement Boys	595	SF	7	10+ years	
	Doors - Hardware	L: Basement Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	L: Basement Boys	595	SF	7	10+ years	
	Floor Drain	L: Basement Boys	3	EA	7	10+ years	
	Lavatory	L: Basement Boys	4	EA	7	10+ years	
	Lighting - Pendent/Surface	L: Basement Boys	8	EA	7	6-10 years	Repaired
	Partitions	L: Basement Boys	6	EA	7	10+ years	•
	Urinals	L: Basement Boys	12	EA	7	10+ years	
	Walls - Plaster/Drywall	L: Basement Boys	370	SF	7	10+ years	
	Walls - Structural Glazed Tile	L: Basement Boys	1,180	SF	7	10+ years	
	Water Closet	L: Basement Boys	6	EA	7	10+ years	
	Accessories	L: Basement Family Restroom	115	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Basement Family Restroom	115	SF	7	10+ years	
	Doors - Wood Doors inclu hw	L: Basement Family Restroom	113	EA	7	•	
				SF		10+ years	
	Floor - Concrete Epoxy/ Painted	L: Basement Family Restroom	115		7	10+ years	
	Floor Drain	L: Basement Family Restroom	1	EA	7	10+ years	
	Lavatory	L: Basement Family Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	L: Basement Family Restroom	2	EA	6	2-5 years	
	Partitions	L: Basement Family Restroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	L: Basement Family Restroom	430	SF	7	10+ years	
	Water Closet	L: Basement Family Restroom	2	EA	7	10+ years	
	Accessories	L: Basement Girls	595	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	L: Basement Girls	595	SF	7	10+ years	
	Doors - Hardware	L: Basement Girls	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	L: Basement Girls	595	SF	7	10+ years	



Categor	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	L: Basement Girls	3	EΑ	7	10+ years	
	Lavatory	L: Basement Girls	5	EΑ	7	10+ years	
	Lighting - Pendent/Surface	L: Basement Girls	8	EA	7	6-10 years	Repaired
	Partitions	L: Basement Girls	14	EΑ	7	10+ years	
	Walls - Plaster/Drywall	L: Basement Girls	370	SF	7	10+ years	
	Walls - Structural Glazed Tile	L: Basement Girls	1,180	SF	7	10+ years	
	Water Closet	L: Basement Girls	14	EA	7	10+ years	
	Accessories	Teacher's Lounge 2nd Floor	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Teacher's Lounge 2nd Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge 2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Teacher's Lounge 2nd Floor	40	SF	6	10+ years	
	Lavatory	Teacher's Lounge 2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Teacher's Lounge 2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Partitions	Teacher's Lounge 2nd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Teacher's Lounge 2nd Floor	135	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Teacher's Lounge 2nd Floor	135	SF	6	10+ years	
	Water Closet	Teacher's Lounge 2nd Floor	2	EΑ	6	10+ years	
		. cacher o _can.go _nacc.	_	_, ,	•	,	
Categor	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #001 (Art Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	975	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	975	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	21	EA	7	6-10 years	Repaired
	Walls - Plaster/Drywall	Basement	1,005	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #007 (Pre School)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	945	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Storage/ Closet	Basement	70	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,811	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	30	SF	7	10+ years	
	Trans Tradion Dry Wall	Bassmont	30	51	,	ioi youis	
Classroo	m #100 (Pre School)						



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	Repaired
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	965	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	965	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	Repaired
	Storage/ Closet	1st Floor	195	SF	7	10+ years	•
	Walls - Plaster/Drywall	1st Floor	2,036	SF	6	10+ years	
_Classroo	om #101 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	Repaired
	Casework	1st Floor	5	LF	6	10+ years	I- 2011 2 22
	Ceiling - Plaster/Drywall	1st Floor	945	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	945	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Repaired
	Storage/ Closet		195	SF	7	•	Repaired
	Walls - Plaster/Drywall	1st Floor 1st Floor		SF SF		10+ years	
		1st Floor	2,191 50	SF SF	6	10+ years	ana aka d
	Walls - Plaster/Drywall Work Sink	1st Floor	1	EA	5 7	1-2 years 10+ years	cracked
Classro	om #103 (Pre School)						
Classiuc	,	4 at Elaan	4	ГΛ	7	0.40	Demoised
	AC Units	1st Floor	1	EA LF	7	6-10 years	Repaired
	Casework	1st Floor	2		6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	700	SF	6	10+ years	
	Chalk Board	1st Floor	23	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	700	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	Repaired
	Storage/ Closet	1st Floor	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,030	SF	6	10+ years	
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	Repaired
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	945	SF	6	10+ years	
	Doors - Transom Window	1st Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	901	SF	6	10+ years	
	Floor - Tile	1st Floor	901	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile	1st Floor	44	SF	4	0-1 year	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,241	SF	6	10+ years	
	Work Sink	1st Floor	, 1	ĒΑ	7	10+ years	
N	WA 07 (Dr. O. b 1)						
Jassroc	om #107 (Pre School)	4 . =				2.42	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	945	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	945	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Repaired
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,841	SF	6	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	920	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	939	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	6	10+ years	Updated to match current
	Floor - Tile	211d F1001	0	SF	O	10+ years	observations
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,811	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	4	0-1 year	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	945	SF	6	10+ years 10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6		
	Doors - Transom Window Doors - Wood Doors inclu hw				-	10+ years	
		2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	945	SF	6	10+ years	Chinned tiles
	Floor - Tile	2nd Floor	3	SF	5	1-2 years	Chipped tiles
	Lighting - Pendent/Surface	2nd Floor	13	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	10+ years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,841	SF	6	10+ years	
assroo	m #203 (Library)						
	AC Units	2nd Floor	1	EΑ	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Carpet	2nd Floor	1,120	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	4	1-2 years	
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,570	SF	6	10+ years	
assroo	m #204 (Kindergarten)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	945	SF	6	10+ years	
	Chalk Board	2nd Floor	20	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	945	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	Updated to match current status
	Marker Board	2nd Floor	12	LF	6	6-10 years	- p
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,526	SF	6	10+ years	
assroo	m #205 (Computer Lab)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	640	SF	6	10+ years	
	Floor - Tile	2nd Floor	20	SF	5	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	ODSGIVATIONS
	Walls - Plaster/Drywall	2nd Floor	330	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
assroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	



Catego	Category : Classroom		В	uilding	: Main		voortiand officer, officago, ie ooozz
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	945	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	920	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	5	1-2 years	Chipped/cracked
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	Updated to match current
	Marker Board	2nd Floor	10	LF	7	6-10 years	observations
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,841	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	945	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	945	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	14	EA	6	•	Updated to match current
	Lighting - Ferideni/Surface		14		b	10+ years	observations
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,841	SF	6	10+ years	
Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	945	SF	6	10+ years	
	Chalk Board	3rd Floor	16	ĹF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	945	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	Updated to match current
						·	observations
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,841	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	945	SF	6	10+ years	
	,					,	



Catego	ry : Classroom		В	uilding	: Main		45 W Cortiana STREET, Chicago, iL 60622
	,,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	965	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	Updated to match current
	gg	0.0.1.00.	•		· ·	.o. you.o	observations
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,811	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years	
	walle Flactor/Brywall	0.4 1.66.	20	0.	ŭ	io. you.o	
Classroo	om #303 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	10+ years	Updated to match current
	0 0					,	observations
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	1-2 years	Light not functioning
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	0
	Walls - Plaster/Drywall	3rd Floor	1,642	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Baseboard loose
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Cracking
Classics	om #305 (Computer Lab)						
Classio	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	10+ years	Updated to match current
	Lighting - Fendent/Sunace	314 F1001	12	EA	b	10+ years	observations
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,612	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
Classro	om #306 (Regular Classroom)						
CIASSIU	AC Units	3rd Floor	1	EA	7	6.10 1/2072	
	AC UTIIIS	SIU FIOOF	1	EA	/	6-10 years	



atego	ry : Classroom		Building : Main				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	945	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	965	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	Updated to match current observations
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,841	SF	7	10+ years	
lassroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	945	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	945	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	Updated to match current observations
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,841	SF	7	10+ years	Updated to match current observations

Category : Interior **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,092	SF	6	10+ years	
	Doors - Transom Window	1st Floor	256	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,092	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	Updated to match current
							observations
	Walls - Plaster/Drywall	1st Floor	2,296	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,092	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	Updated to match current
							observations
	Walls - Plaster/Drywall	2nd Floor	2,296	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	294	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	294	SF	7	10+ years	
						*	

Campus Name: Drummond Page : 19 of 23 Assessment Date: 01/31/2022



Category : Interior		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	3rd Floor	4	EΑ	4	1-2 years	Light not functioning
	Walls - Plaster/Drywall	3rd Floor	1,022	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Cracking
	Ceiling - Plaster/Drywall	Basement	1,134	SF	7	10+ years	G
	Doors - Wood Doors include hw	Basement	9	EA	7	10+ years	
	Drinking Fountains - Double Fountain	Basement	4	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	1,134	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	26	EA	7	6-10 years	Repaired
	Stairs - Concrete Stairs	Basement	2	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,730	SF	7	10+ years	
Safety							
•	Camera Viewing Station	1st Floor	2	EA	7	10+ years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	5	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	East	312	SF	6	10+ years	
	Floor - Asphalt	East	208	SF	6	10+ years	
	Floor - Tile	East	104	SF	6	10+ years	
	Handrails	East	184	LF	7	10+ years	
	Lighting - Pendent/Surface	East	6	EA	6	10+ years	Updated to match current observations
	Stairs - Asphalt	East	90	LF	6	10+ years	
	Walls - Plaster/Drywall	East	3,584	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	312	SF	6	10+ years	
	Floor - Asphalt	West	208	SF	6	10+ years	
	Floor - Tile	West	104	SF	6	10+ years	
	Handrails	West	184	LF	7	10+ years	
	Lighting - Pendent/Surface	West	6	EA	7	10+ years	Updated to match current observations
	Stairs - Rubber	West	90	LF	6	10+ years	
	Walls - Plaster/Drywall	West	3,584	SF	6	10+ years	
Vertical C	Conveyance						
	Wheelchair Lift - Chair Lift		1	EA	7	10+ years	





Category: Site **Building: Site**

Catego	ory : Site		В	: Site			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	ainage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
	3					,	
Fencina							
· choing	Fencing - Chain Link	Entire Site	110	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	678	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	5	10+ years	Misaligned gate
	1 Chang Trew Standard Chrismental	Little Oile	J		J	101 years	iviisaligrica gate
Landsca	ape						
	Benches	Entire Site	2	EA	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	1,100	SF	7	10+ years	New concrete
	Landscape - Hardscape- Pavers	Entire Site	900	SF	6	10+ years	
	Parkway trees	Entire Site	1	EA	7	10+ years	New tree planted
	Parkway trees	Entire Site	12	EΑ	6	10+ years	•
	Planting Beds/ Area	Entire Site	1,880	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	4,064	SF	7	10+ years	New asphalt
	Play Area - Poured Rubber Surface	Entire Site	2,000	SF	7	10+ years	Basketball
	Play Area - Poured Rubber Surface	Entire Site	4,000	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	5,000	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
Parking	Lot						
T driving	Concrete Curbs	S Parking Lot	310	LF	6	10+ years	
	Lighting - Pole Mounted	S Parking Lot	4	EA	6	10+ years	These are not located in the parking
	Lighting 1 did Medited	o r anang zot	•	_, 、	Ū	io. youro	lot but on the other side of the fence
	Surface - Asphalt	S Parking Lot	4,520	SF	6	10+ years	
	Trash Compactor	S Parking Lot	1,020	EA	6	10+ years	
	Trash Enclosure - Chain Links	S Parking Lot	690	SF	6	10+ years	
	Tradit Ethologara Chain Elinio	or arking Lot	000	O.	J	To Tyouro	
Playgro	und						
	Equipment - School Age 5-12	East	1	EA	7	10+ years	
	Surface - Poured Surface	East	4,000	SF	7	10+ years	Area remesured
	Equipment - Swingset	NE Playground	1	EΑ	7	10+ years	
	Surface - Poured Surface	NE Playground	1,600	SF	7	10+ years	
Sidewal	ke						
Ciucwai	Sidewalks - Internal Walks	Entire Site	415	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10,890	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	300	SF	5	6-10 years	
	C.GOWAING TOTITION ORGANIA	Little Oile	300	51	J	o to yours	



Category : Site		Building : Site						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
_Signage								
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EΑ	6	10+ years		
	Flag Pole - Flag Pole	Entire Site	1	EA	7	6-10 years		
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years		

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Drummond Page: 22 of 23 Assessment Date: 01/31/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

,			Doom	Floor Plan	A ***	Glazed Window	Operable Window	Window	Smort
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Area	Area	Window Stop	Smart- Board
Building : Main		110111001		(51)	7 33 0 03		2134		
Art Room	Art Room	Basement	001	001	975	60	30	N	N
Computer Lab	Regular Classroom	3rd Floor	305	305	730	140	60	N	N
Computer Lab	Special Program	2nd Floor	205	205	680	105	30	N	N
Kindergarten	Kindergarten	1st Floor	104	104	945	165	75	N	N
Kindergarten	Kindergarten	2nd Floor	204	204	945	165	75	N	N
Library	Regular Classroom	2nd Floor	203	203	1,120	165	75	N	Y
Office	Regular Classroom	3rd Floor	303	303	730	140	60	N	N
Pre School	Regular Classroom	1st Floor	100	100	945	165	75	N	N
Pre School	Regular Classroom	1st Floor	101	101	945	165	75	N	N
Pre School	Regular Classroom	1st Floor	103	103	700	105	45	N	N
Pre School	Regular Classroom	1st Floor	107	107	945	165	60	N	N
Pre School	Regular Classroom	Basement	007	006	945	65	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	945	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	945	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	945	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	945	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	945	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	945	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	945	113	52	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	945	165	75	N	N