

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1971	2	23,372
Linked Addition	2015	2	10,666
Campus Total			34,038

Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance	· · · · · · · · · · · · · · · · · · ·		quantity		110.1111		
	Entrance Control - Audio and Video	1	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	1	2	EA	6	10+ years	
	Exterior Doors - Side lite	1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1	16	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1	36	LF	6	10+ years	
	Ramps - Concrete	1	18	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	1	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	
	Exterior Doors - Side lite	2	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	2	EA	6	10+ years	
	Exterior Doors - Side lite	6	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	
	Exterior Stairs - Concrete	6	10	LF	4	0-1 year	Landing has cracking.
Foundat	ion						
	Foundation - Concrete	Entire Building	491	LF	7	10+ years	
	Foundation - Concrete	Entire Building	2	LF	5	0-1 year	Cracked concrete
	Superstructure - Concrete	Entire Building	12,400	SF	7	10+ years	
Lighting							





atego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
of Sys	stem						
	Access Ladder - Metal	D	1	EA	5	2-5 years	
	Coping - Metal	D	123	LF	6	10+ years	
	Downspouts - Interior Downspouts	D	52	LF	6	10+ years	
	Roof - Modified Bitumen	D	1,800	SF	7	10+ years	
	Roof Structure - Concrete	D	1,800	SF	7	10+ years	
	Access Ladder - Metal	Ē	1	ĒΑ	7	10+ years	
	Coping - Metal	Ē	87	LF	6	10+ years	
	Downspouts - Interior Downspouts	Ē	42	LF	6	10+ years	
	Roof - Modified Bitumen	Ē	1,600	SF	6	10+ years	
	Roof Structure - Concrete	Ē	1,600	SF	7	10+ years	
	Coping - Metal	F	346	LF	6	•	
		F	104	LF	6	10+ years	
	Downspouts - Interior Downspouts	r F		SF		10+ years	
	Roof - Metal	F F	8		6	10+ years	
	Roof - Metal	!	61	SF	6	10+ years	0
	Roof - Modified Bitumen	F	8,931	SF	4	0-1 year	Open seams, ponding.
	Roof Structure - Concrete	F	9,000	SF	7	10+ years	
-11-							
alls	Futurian Walla - Danasat Danas I Wall	Fating Desilations	0.007	0.5	7	40	
	Exterior Walls - Precast Panel Wall	Entire Building	2,687	SF SF	7	10+ years	Deterioreta discolant et comercia
	Exterior Walls - Precast Panel Wall	Entire Building	400	21	5	0-1 year	Deteriorated sealant at concrete
	Estariar Walls - Drafabricated Matal Danal	Cotine Divildina	7.507	C.E.	_	C 40	panels. Leaks to interior
	Exterior Walls - Prefabricated Metal Panel	Entire Building	7,567	SF	5	6-10 years	Peeling paint
	Wall						
indows	3						
	Curtain wall - Louver	Entire Building	504	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	2,257	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
-	Exit Signs - Corridors and Stairs	Entire Building	6	EA	4	0-1 year	Lettering cracking and older.
	Exit Signs - Multipurpose Room	Entire Building	2	EA	4	0-1 year	Lettering cracking and older.
	Security System - CCTV	Entire Building	23,372	SF	7	6-10 years	Installed new in 2020. Exterior on
	Security System - Intrusion Detection	Entire Building	23,372	SF	5	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	10	EA	6	6-10 years	
	Stairs	9	10		•	5 .5 youro	
	Emergency Battery Packs - Multipurpose	Entire Building	4	EA	7	6-10 years	
	G = 1, ,	· · · · · · · · · · · · · · · · · · ·	•		•	J -	





Catego	ry : Electrical		В	uilding	: Main		0045 S UTION AVENUE, Chicago, IL 00020
Culogo			_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	3,306	SF	6	10+ years	
	Stairs				_		
	Emergency A/C Power - Lunchrooms	Entire Building	4,828	SF	6	10+ years	
	Automatic Transfer Switch	Entire Building	1	EA	4	1-2 years	Noisy and older.
Main Se	rvice						
IVIAIII SE	Main Electrical Service - 2001 to 3000 A	Electrical Closet-1st Floor	1	EA	4	1-2 years	Older and not reliable.
	120/208/3PH	Electrical Closet-1st Floor	ı	LA	4	1-2 years	Older and not reliable.
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	Building has ATS.
	emergency power		•	_, 、	Ü	o lo youlo	Danaing has 717 C.
	PA System	Entire Building	23,372	SF	6	6-10 years	Connected to Addition.
	,	S .	,			,	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	New item added per current
							observation Fuse panel
	Lighting and Power Panels - 100 A	Entire Building	9	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	
	amp	Entire Duilding	0	Ε.	7	10	
	Main Distribution Panels - Less than 400	Entire Building	2	EA	7	10+ years	
	amp						
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Serves main building and addition.
	Fire Alarm Strobe Lights	Entire Building	23,372	SF	6	10+ years	-
	Fire Alarm_System	Entire Building	23,372	SF	6	10+ years	
_			_				
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	•	Location	Quantity	UOIVI	Kalik	Replacement	Comments
_Air Cond		Doof		Г^		6.10	Company confetence and bitches and the
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	Serves cafeteria and kitchen, split system, evaporators above ceiling.
	than 5 tons						system, evaporators above ceiling.
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Electrical Room	2	EA	5	6-10 years	Not accessible per building enginee
			_	** *	-	,	Mounted above ceiling,
							kitchen/cafeteria area. In plenum
							space Control needs adjustment.
							-

Campus Name: Dunne Page : 3 of 22 Assessment Date: 05/09/2022



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Split system HVAC.
Heating	Devices						
Ticamig	Wall Heater - Electric	Entire Building	2	EA	7	10+ years	New item added per current observation Installed new in offices
	Wall Heater - Electric	Entire Building	4	EA	7	10+ years	observation installed new in onless
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	Minor repair needed
	PTAC - Electric Heating and Self Contained	Entire Building	4	EΑ	6	10+ years	New item added per current
	Cooling	Linus Building	·	271	Ü	To Tyourd	observation Main office, teachers lounge, principal, and counselor office. Thermostat built in.
Tempera	ature Control						
	Electric Controls	1st Floor	2,500	SF	5	6-10 years	With integral temperature control. Control needs adjustment.
	Electric Thermostat	1st Floor	3	EA	5	6-10 years	Minor repair. Serves split system HVAC, kitchen and cafeteria, and MDF room.
Unit Ven							
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	20	EA	5	6-10 years	Entire building, with integral temperature control.
Ventilation	an .						
verman	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Electric Heater - Less than 20 KW	Kitchen Office- 1st Floor	1	EA	6	6-10 years	Serves kitchen in main building only.
Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	23,372	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	23,372	SF	6	10+ years	
	. 5	ū	,			•	

Campus Name: Dunne Page : 4 of 22 Assessment Date: 05/09/2022





ALL A	3CHOOIS					1	0845 S Union AVENUE, Chicago, IL 606
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	23,372	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	23,372	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	23,372	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	23,372	SF	6	10+ years	
	Sanitary Piping	Entire Building	23,372	SF	6	10+ years	
	Storm Piping	Entire Building	23,372	SF	6	10+ years	
	Vent Piping	Entire Building	23,372	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Main		
<u> </u>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	108 Teachers Lounge	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108 Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	108 Teachers Lounge	102	SF	6	10+ years	
	Lighting - Lay-in	108 Teachers Lounge	1	EA	6	6-10 years	
	Power Distribution	108 Teachers Lounge	1	FΑ	7	10+ vears	

Group	iteiii - i ype	Location	Quantity	OCIVI	ivaiin	Replacement	Comments
Adminis	rative Suites/Offices						
	Ceiling - Lay-in	108 Teachers Lounge	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108 Teachers Lounge	1	EΑ	7	10+ years	
	Floor - Tile	108 Teachers Lounge	102	SF	6	10+ years	
	Lighting - Lay-in	108 Teachers Lounge	1	EA	6	6-10 years	
	Power Distribution	108 Teachers Lounge	1	EΑ	7	10+ years	
	Walls - Metal Panel	108 Teachers Lounge	369	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor Counselors Office	445	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Counselors Office	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Counselors Office	445	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor Counselors Office	6	EΑ	6	6-10 years	
	Power Distribution	2nd Floor Counselors Office	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Counselors Office	810	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal's Office	118	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal's Office	8	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	EΑ	7	10+ years	· ·
	Floor - Tile	Assistant Principal's Office	126	SF	6	10+ years	
	Lighting - Lay-in	Assistant Principal's Office	2	EΑ	6	6-10 years	
	Power Distribution	Assistant Principal's Office	4	EΑ	6	10+ years	
	Walls - Metal Panel	Assistant Principal's Office	414	SF	6	10+ years	
	Ceiling - Lay-in	Intervention Office	126	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Intervention Office	1	EΑ	7	10+ years	
	Floor - Tile	Intervention Office	126	SF	7	10+ years	
	Lighting - Lay-in	Intervention Office	1	EΑ	7	10+ years	
	Walls - Metal Panel	Intervention Office	414	SF	7	10+ years	
	Ceiling - Lay-in	Lunchroom Manager Office	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom Manager Office	1	EΑ	7	10+ years	
	Floor - Tile	Lunchroom Manager Office	83	SF	6	10+ years	
	Lighting - Pendent/Surface		1	EA	7	6-10 years	
		Lunchroom Manager Office	1		_	,	





Catego	ry : Room		В	uilding	: Main		<u> </u>
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Lunchroom Manager Office	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Lunchroom Manager Office	397	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	234	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	4	EA	7	10+ years	
	Floor - Tile	Main Office	234	SF	6	10+ years	
	Lighting - Lay-in	Main Office	3	EA	6	6-10 years	
	Power Distribution	Main Office	6	EA	6	10+ years	
	Storage/ Closet	Main Office	86	SF	7	10+ years	
	Walls - Metal Panel	Main Office	576	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Office	109	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	7	10+ years	
	Floor - Tile	Principal's Office	109	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office	2	ĒΑ	6	6-10 years	
	Power Distribution	Principal's Office	10	EΑ	7	10+ years	
	Storage/ Closet	Principal's Office	25	SF	7	10+ years	
	Walls - Metal Panel	Principal's Office	378	SF	6	10+ years	
	Wallo Wotal Fallor	Timoparo Cinico	070	O.	J	101 youro	
Kitchen							
	Ceiling - Lay-in	1st Floor	317	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	-
	Floor - Tile Quarry	1st Floor	325	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	4	EA	6	6-10 years	
	Serving Line	1st Floor	10	LF	7	10+ years	
	Walls - Metal Panel	1st Floor	693	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,464	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	56	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	Trator damago.
	Floor - Tile	1st Floor	1,520	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	6	6-10 years	
	Serving Line	1st Floor	12	LF	7	10+ years	
	Storage/ Closet	1st Floor	88	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	2,184	SF	6	10+ years	
	Walls - Metal Fallel	IST FIOOI	2,104	SF	O	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	Room 202	1	EA	6	10+ years	
	Finishes	Room 202	61	SF	7	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Flr Janitor Closet	30	SF	7	10+ years	
	Janitor's Closet	2nd Flr Janitor Closet	28	SF	7	10+ years	
	Same of Ologot	Zita i ii daintoi diddet	20	Oi.	,	ioi youis	







atego	ry : Room		В	uilding	: Main				
						Recommend			
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Mechanical/ Service Rooms	Electrical Room 110	132	SF	5	10+ years	Damaged ceiling tile.		
stroor									
	Accessories	1st Floor Unisex A	27	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor Unisex A	27	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Unisex A	1	EΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex A	27	SF	6	10+ years			
	Lavatory	1st Floor Unisex A	1	EA	6	10+ years			
	Lighting - Lay-in	1st Floor Unisex A	1	EA	6	6-10 years			
	Walls - Metal Panel	1st Floor Unisex A	135	SF	6	10+ years			
	Water Closet	1st Floor Unisex A	1	EA	6	10+ years			
	Accessories	1st Floor Unisex B	27	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor Unisex B	27	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Unisex B	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex B	27	SF	6	10+ years			
	Lavatory	1st Floor Unisex B	1	EA	6	10+ years			
	Lighting - Lay-in	1st Floor Unisex B	1	EA	6	6-10 years			
	Walls - Metal Panel	1st Floor Unisex B	135	SF	6	10+ years			
	Water Closet	1st Floor Unisex B	1	ĒΑ	6	10+ years			
	Accessories	1st Flr Boys Toilet	222	SF	7	6-10 years			
	Ceiling - Lay-in	1st Flr Boys Toilet	222	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Fir Boys Toilet	222	SF	6	10+ years			
	Floor Drain	1st Fir Boys Toilet	1	EA	7	10+ years			
	Lavatory	1st Flr Boys Toilet	2	EA	6	10+ years			
	Lighting - Lay-in	1st Flr Boys Toilet	3	EA	6	6-10 years			
	Partitions	1st Flr Boys Toilet	1	EA	7	10+ years			
	Urinals	1st Fir Boys Toilet	6	EA	6				
				SF	-	10+ years			
	Walls - Metal Panel	1st Fir Boys Toilet	558		6	10+ years			
	Water Closet	1st Flr Boys Toilet	1	EA	6	10+ years			
	Accessories	1st Flr Girls Toilet	214	SF	7	6-10 years			
	Ceiling - Lay-in	1st Flr Girls Toilet	214	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Flr Girls Toilet	214	SF	6	10+ years			
	Floor Drain	1st Flr Girls Toilet	1	EA	7	10+ years			
	Lavatory	1st Flr Girls Toilet	2	EA	7	10+ years			
	Lighting - Lay-in	1st Flr Girls Toilet	2	EA	6	6-10 years			
	Partitions	1st Flr Girls Toilet	6	EA	7	10+ years			
	Walls - Metal Panel	1st Flr Girls Toilet	537	SF	6	10+ years			
	Water Closet	1st Flr Girls Toilet	6	EA	7	10+ years			
	Accessories	2nd Floor	36	SF	7	6-10 years			
	Accessories	2nd Floor	2	SF	4	0-1 year	Vent fan very loud		
	Ceiling - Lay-in	2nd Floor	38	SF	6	10+ years	ŕ		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	38	SF	6	10+ years			
	Lavatory	2nd Floor	1	EΑ	6	10+ years			

Campus Name: Dunne Page : 7 of 22 Assessment Date: 05/09/2022





Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Metal Panel	2nd Floor	225	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	10+ years	
	Accessories	2nd Flr Boys Toilet	218	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Flr Boys Toilet	218	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Flr Boys Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr Boys Toilet	218	SF	6	10+ years	
	Floor Drain	2nd Flr Boys Toilet	1	EA	7	10+ years	
	Lavatory	2nd Flr Boys Toilet	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Flr Boys Toilet	3	EA	6	6-10 years	
	Partitions	2nd Flr Boys Toilet	1	EA	7	10+ years	
	Urinals	2nd Flr Boys Toilet	6	EA	6	10+ years	
	Walls - Metal Panel	2nd Flr Boys Toilet	635	SF	6	10+ years	
	Walls - Metal Panel	2nd Flr Boys Toilet	4	SF	5	0-1 year	Dented, holes from previous attachments.
	Water Closet	2nd Flr Boys Toilet	1	EA	6	10+ years	attacimiento.
	Accessories	2nd Fir Girls Toilet	239	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Flr Girls Toilet	239	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Flr Girls Toilet	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr Girls Toilet	239	SF	6	10+ years	
	Floor Drain	2nd Flr Girls Toilet	1	EΑ	7	10+ years	
	Lavatory	2nd FIr Girls Toilet	2	EΑ	6	10+ years	
	Lighting - Lay-in	2nd Flr Girls Toilet	3	EΑ	6	6-10 years	
	Partitions	2nd Flr Girls Toilet	6	EA	7	10+ years	
	Walls - Metal Panel	2nd Flr Girls Toilet	720	SF	6	10+ years	
	Water Closet	2nd Flr Girls Toilet	6	ĒΑ	6	10+ years	
Catego	ry : Classroom		В	uilding	: Main		

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #101 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	53	SF	4	0-1 year	Missing/water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
_Classro	om #102 (Kindergarten)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	735	SF	6	10+ years	

Campus Name: Dunne Page: 8 of 22 Assessment Date: 05/09/2022







Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	18	SF	4	0-1 year	Missing/water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroo	m #103 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	727	SF	6	10+ years	
		1st Floor					\\/_t===================================
	Ceiling - Lay-in		26	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroc	m #105 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	737	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Water damage.
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor		EA	_	-	
			10		6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroc	m #107 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	737	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	3	0-1 year	Ceiling continuously leak when it rains. Damaged tile.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	ramo. Damagoa mo.
	Floor - Tile	1st Floor	753	SF	6	10+ years	
				_			
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroo	m #110 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	713	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	40	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	ŭ







Category : Classroom			В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroc	om #112 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	23	SF	7	10+ years	Repaired.
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
laceroo	om #114 (Regular Classroom)						
الاستناداد	Casework	1st Floor	8	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	737	SF	6	•	
	Ceiling - Lay-in Ceiling - Lay-in	1st Floor	16	SF		10+ years	Water damage.
					4	0-1 year	water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	753	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	911	SF	6	10+ years	
Classroc	om #200 (Computer Lab)						
	Casework	2nd Floor	62	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,141	SF	6	10+ years	
	Doors - Store Front	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	1,141	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	Updated to match current
	Walls - Metal Panel	2nd Floor	1,070	SF	6	10+ years	observations
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	753	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	753	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor 2nd Floor	909	SF	6		
	vvalio - ivietai Faitei	ZIIU FI00I	909	SF	O	10+ years	

Campus Name: Dunne Page : 10 of 22 Assessment Date: 05/09/2022





	vrv i Classroom			uilding	. Main		0645 5 Official Avenue, Chicago, IL C		
Catego	Category : Classroom			ullaing	: wam	Recommend	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
O. Gup	Walls - Plaster/Drywall	2nd Floor	2	SF	6	6-10 years	Paint damage		
	Work Sink	2nd Floor	1	EA	7	10+ years	Updated quantity		
Classra	om #202 (Regular Classroom)								
Classio		Ond Floor	9	LF		10			
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	8 726	SF	6	10+ years			
					6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	726	SF	5	2-5 years	Edges curling in a few places.		
	Lighting - Lay-in	2nd Floor	9	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years	D : ():		
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years	Paint chipped.		
Classro	om #203 (Computer Lab)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	753	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	753	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years			
Classroo	om #205 (Regular Classroom)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	753	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	753	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	,			
	Walls - Metal Panel	2nd Floor	911	SF	6	6-10 years			
	vvalis - ivietai Fallei	2110 F1001	911	SF	b	10+ years			
Classro	om #206 (Computer Lab)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	753	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	753	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years			
	Marker Board	2nd Floor	32	LF	7	6-10 years			
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years			
Classroo	om #207 (Regular Classroom)								
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	748	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors Gloci Doors mornw	2110 1 1001		L/\	J	101 yours			





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	748	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years	
lassroo	om #208 (Regular Classroom)						
1000101	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	737	SF	6	10+ years	
						•	Matar dama a
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	753	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	753	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile						
		2nd Floor	753	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	911	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
_		To a decide to	0			Recommend	•
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor	Ceiling - Lay-in	1st Floor Entry Corridor	260	SF	6	10 L VOORO	
			200			10+ years	
		1st Floor Entry Corridor	7	EA	6	10+ years	
	Doors - Steel Doors incl hw				_	4.0	
	Floor - Tile/Sheet	1st Floor Entry Corridor	260	SF	7	10+ years	
	Floor - Tile/Sheet Lighting - Lay-in	1st Floor Entry Corridor 1st Floor Entry Corridor	260 2	SF EA	6	10+ years 6-10 years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor	260 2 558	SF EA SF	6 6		
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in	1st Floor Entry Corridor 1st Floor Entry Corridor	260 2	SF EA SF SF	6	6-10 years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor	260 2 558	SF EA SF	6 6	6-10 years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor	260 2 558 1,185	SF EA SF SF	6 6 6	6-10 years 10+ years 10+ years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor 1st Floor Main Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3	SF EA SF SF EA	6 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor 1st Floor Main Corridor 1st Floor Main Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3 1,185	SF EA SF EA EA SF	6 6 6 7 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3 1,185	SF EA SF EA EA SF EA	6 6 6 7 7 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3 1,185 10 2,223	SF EA SF EA SF EA SF	6 6 6 7 7 6	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3 1,185 10 2,223 216	SF SF SF EA SF EA SF SF	6 6 6 7 7 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor 1st Linked corridor	260 2 558 1,185 2 3 1,185 10 2,223 216 4	SF SF SF EA SF EA SF SF EA	6 6 6 7 7 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
	Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Metal Panel Ceiling - Lay-in	1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Entry Corridor 1st Floor Main Corridor	260 2 558 1,185 2 3 1,185 10 2,223 216	SF SF SF EA SF EA SF SF	6 6 6 7 7 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	

Campus Name: Dunne Page : 12 of 22 Assessment Date: 05/09/2022





Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Plaster/Drywall	1st Linked corridor	560	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Entry Corridor	78	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor Entry Corridor	78	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Entry Corridor	1	EA	6	6-10 years	
	Walls - Metal Panel	2nd Floor Entry Corridor	279	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor Link Corridor	216	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor Link Corridor	2	EA	7	10+ years	Updated quantity
	Floor - Tile/Sheet	2nd Floor Link Corridor	216	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Link Corridor	3	EA	7	10+ years	Updated quantity
	Walls - Plaster/Drywall	2nd Floor Link Corridor	560	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Main Corridor	1,163	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor Main Corridor	3	EA	7	10+ years	Updated quantity
	Floor - Tile/Sheet	2nd Floor Main Corridor	1,153	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Main Corridor	10	SF	4	0-1 year	Separating.
	Lighting - Lay-in	2nd Floor Main Corridor	10	EA	6	10+ years	
	Walls - Metal Panel	2nd Floor Main Corridor	2,135	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	4	0-1 year	Viewing station does not work.
	Security Cameras	1st Floor	3	EA	7	6-10 years	No interior cameras, exterior only.
Stairs							
Stalls	Ceiling - Lay-in	Main Entry Stairway	155	SF	7	10+ years	
	Floor - Concrete	Main Entry Stairway	153	SF	7	10+ years	
	Handrails	Main Entry Stairway	30	LF	7	10+ years	
	Lighting - Lay-in	Main Entry Stairway	1	EA	7	6-10 years	
	Stairs - Concrete	Main Entry Stairway	98	LF	7	10+ years	
	Walls - Metal Panel	Main Entry Stairway	513	SF	7	10+ years	
	Ceiling - Lay-in	Rear Stairway	155	SF	7	10+ years	
	Floor - Concrete	Rear Stairway	153	SF	7	10+ years	
	Handrails	Rear Stairway	30	LF	7	10+ years	
	Lighting - Lay-in	Rear Stairway	1	EA	7	6-10 years	
	Stairs - Concrete	Rear Stairway	98	LF	7	10+ years	
	Walls - Metal Panel	Rear Stairway	513	SF	7	10+ years	
			3.5		-	,	

Campus Name: Dunne Page : 13 of 22 Assessment Date: 05/09/2022



Category : Exterior Building : Linked Addition

alegory . Exterior					Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Location	Quantity	OOM	Italik	Replacement	Comments
ntrance						
Entrance Control - Audio and Vide		1	EA	7	10+ years	
Exterior Doors - Exterior FRP Doo		2	EA	7	10+ years	
Exterior Doors - Transom Lite	3	2	EA	7	10+ years	
Power Door Operator and Controls		1	EA	7	10+ years	
Exterior Doors - Exterior FRP Doo		2	EA	7	10+ years	
Exterior Doors - Transom Lite	4	2	EA	7	10+ years	
Exterior Doors - Exterior FRP Doo		2	EA	7	10+ years	
Exterior Doors - Transom Lite	5	2	EA	7	10+ years	
Exterior Doors - Exterior Steel Doo		1	EA	7	10+ years	
Exterior Doors - Exterior Steel Doo		1	EA	7	10+ years	
Exterior Stairs - Steel or Aluminum	8- Roof C	3	LF	7	10+ years	
oundation						
Foundation - Concrete	Entire Building	1,756	LF	7	10+ years	_
Superstructure - Slab on Grade	Entire Building	10,500	SF	7	10+ years	
Capation Class of Stade	5	.5,500	٠.	,	youro	
ighting Exterior Lighting - Wall Mounted	Entire Building	17	EA	7	10+ years	
Exterior Lighting - Wall Mounted	Entire Building	17	EA	,	10+ years	
oof System						
Coping - Metal	Α	545	LF	6	10+ years	
Downspouts - Interior Downspout		150	LF	6	10+ years	
Parapet - 16" - 30" Height	Α	545	LF	7	10+ years	
Roof - Modified Bitumen	Α	5,400	SF	7	10+ years	
Roof Structure - Steel / Metal Dec	k/ A	5,400	SF	7	10+ years	
Concrete Topping		,			•	
Coping - Metal	В	220	LF	7	10+ years	
Downspouts - Interior Downspout		100	LF	6	10+ years	
Parapet - 16" - 30" Height	В	220	LF	7	10+ years	
Roof - Modified Bitumen	В	4,493	SF	5	0-1 year	Vegetation growth.
Roof Structure - Steel / Metal Dec		4,493	SF	7	10+ years	- <u>G</u> G
Concrete Topping	- -	., .00		•	,	
Coping - Metal	С	50	LF	6	10+ years	
Downspouts - Interior Downspout		12	LF	6	10+ years	
Parapet - 16" - 30" Height	C C	50	LF	7	10+ years	
Roof - Modified Bitumen	Č	572	SF	6	10+ years	
Roof Structure - Steel / Metal Dec		572	SF	7	10+ years	
Concrete Topping		012	O.	•	ioi youio	
/alla						
Valls Priok	Entire Building	0 000	QE.	7	10 L VOORS	
Exterior Walls - Brick	Entire Building	8,809	SF	7	10+ years	

Campus Name: Dunne Page : 14 of 22 Assessment Date: 05/09/2022





Catego	ry : Exterior		Building : Linked Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Vindows								
	Lintels - Steel	Entire Building	103	LF	6	10+ years		
	Windows - Decorative	Entire Building	492	SF	7	10+ years		
Catego	ry : Electrical		В	uildina	: Linked	l Addition		
						Recommend		
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
mergen	cy System							
	Exit Signs - Corridors and Stairs	1st Floor	5	EA	6	6-10 years	Bulb needs to be replaced.	
	Exit Signs - Gym	1st Floor	2	EA	6	6-10 years	Bulb needs to be replaced.	
	Security System - CCTV	Entire Building	10,666	SF	7	6-10 years		
	Security System - Intrusion Detection	Entire Building	10,666	SF	7	6-10 years		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	ĒΑ	6	6-10 years		
	Emergency Battery Packs - Gym	Entire Building	4	EA	6	6-10 years	Quantity change per current observation	
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,888	SF	7	10+ years	New item added per current observation	
Main Ser	vice							
VIGITI COL	PA System	1st Floor	10,666	SF	6	6-10 years		
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years		
Power Di	stribution							
	Lighting and Power Panels - 100 A	1st Floor	1	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	1st Floor	3	EA	7	10+ years		
	Main Distribution Panels - Less than 400 amp	1st Floor	1	EA	7	10+ years		
Catego	ry : Fire Protection		В	uilding	: Linked	I Addition		
						Recommend		
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ire Aları	m							
	Fire Alarm Strobe Lights	Entire Building	10,666	SF	7	10+ years		
	Fire Alarm_System	Entire Building	10,666	SF	6	10+ years		
	Fire Pump Controller	Entire Building	1	EA	6	10+ years		
Pumn Ro	oom Assembly							
	Fire Pump - Less than 25hp	1st Floor	1	EA	7	10+ years		







Catego	ry : Fire Protection	Building : Linked Addition					
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sprinklor	System						
эршке	Sprinkler Heads	Entire Building	10,666	SF	7	10+ years	
	Sprinkler Piping	Entire Building	10,666	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	10,666	SF	7	10+ years	
Catama		o _aag			-	•	
Catego	ry : Mechanical		В	ullaing	: Linked	d Addition Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems		•			•	
	Fan Power Box - Fan Power Box with Electric Coil	1st Floor	3	EA	6	10+ years	New item added per current observation. Serves Addition rooms
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	6	10+ years	RTU-2 Serves gym.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons	Roof	1	EA	6	10+ years	RTU-1, Serves 2 classrooms.
Heating I	Devices						
Journa 1	Cabinet Heaters - With Electric Coil	1st Floor	3	EA	6	10+ years	Quantity change per current observation. Ceiling mounted.
	Unit Heater - Electric	Entire Building	4	EA	7	10+ years	Quantity change per current observation
Tempera	ature Control						
•	Electric Controls	Entire Building	10,666	SF	6	10+ years	
	Electric Thermostat	Entire Building	3	EA	7	10+ years	New item added per current observation Served VAV boxes
	Electric Thermostat	Entire Building	3	EA	6	10+ years	Serves single zone HVAC units, electric cabinet unit heater.
√entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Main Roof	2	EA	6	10+ years	Serves elevator mechanical room.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Main Roof	2	EA	6	10+ years	New item added per current observation Serves gym.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Main Roof	3	EA	6	6-10 years	Quantity change per current observation
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Main Roof	1	EA	6	6-10 years	Quantity change per current observation
	Roof Mounted Duct Work	Main Roof	20	LF	6	10+ years	

Campus Name: Dunne Page : 16 of 22 Assessment Date: 05/09/2022



Catego	ry : Plumbing		В	uilding	: Linked	d Addition	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wat	er						
	Electric Heater - 20 - 50 KW	Mechanical Room	2	EA	6	6-10 years	Serve addition and main building.
iping							
	Domestic Piping-Hot Water Return Lines	1st Floor	10,666	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	1st Floor	10,666	SF	7	10+ years	New item added per current observation
	Domestic Piping-Hot Water from Risers to Fixtures	1st Floor	10,666	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	1st Floor	10,666	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	1st Floor	10,666	SF	7	10+ years	
	Sanitary Piping	1st Floor	10,666	SF	7	10+ years	
	Storm Piping	1st Floor	10,666	SF	7	10+ years	
	Vent Piping	1st Floor	10,666	SF	7	10+ years	
umps							
•	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	7	10+ years	Serves addition and main building
	Pumps - Sump-Simplex	Mechanical Room	1	EA	7	10+ years	In the elevator pit Not accessible
atego	ry : Room		В	uilding	: Linked	d Addition	
						Recommend	
	Hom Type	Location	Quantity	HOM	Donk	Donloomont	Campuanta

						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	158 Gym Office	107	SF	7	10+ years	
	Doors - Wood Doors inclu hw	158 Gym Office	1	EΑ	7	10+ years	
	Floor - Tile	158 Gym Office	107	SF	7	10+ years	
	Lighting - Lay-in	158 Gym Office	2	EΑ	7	6-10 years	
	Power Distribution	158 Gym Office	4	EΑ	7	10+ years	
	Walls - Concrete Block	158 Gym Office	400	SF	7	10+ years	
ymnas	ia						
•	Bleacher Seating	155 Gym	50	EA	7	10+ years	
	Ceiling - Exposed	155 Gym	3,204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	155 Gym	4	EA	7	10+ years	
	Floor - Wood	155 Gym	3,204	SF	7	10+ years	
	Lighting - Pendent/Surface	155 Gym	40	EA	7	6-10 years	
	Scoreboards	155 Gym	1	EA	7	10+ years	
	Sound System	155 Gym	1	EA	7	10+ years	
	Walls - Concrete Block	155 Gym	4,250	SF	7	10+ years	
	vvalis - Concrete Block	155 Gym	4,250	SF	/	10+ years	



Catego	ry : Room		В	uilding	: Linked	d Addition	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechan	ical/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	201	SF	7	10+ years	157 Water Pump Room
	Mechanical/ Service Rooms	1st Floor	48	SF	7	10+ years	152 Elevator Room
	Mechanical/ Service Rooms	1st Floor	265	SF	7	10+ years	153 Electrical
	Storage Room	1st Floor	281	SF	7	10+ years	156 Gym Storage
	Storage Room	1st Floor	265	SF	5	10+ years	160 OFFICE STORAGE, Hole in wall
	Storage Room	2nd Floor	506	SF	7	10+ years	252 Storage
5 .							
Restroo							
	Accessories	154 UNISEX	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	154 UNISEX	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	154 UNISEX	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	154 UNISEX	90	SF	7	10+ years	
	Floor Drain	154 UNISEX	1	EA	7	10+ years	
	Hand Dryer	154 UNISEX	1	EA	7	10+ years	
	Lavatory	154 UNISEX	1	EA	7	10+ years	
	Lighting - Lay-in	154 UNISEX	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	154 UNISEX	400	SF	7	10+ years	
	Water Closet	154 UNISEX	1	EA	7	10+ years	
Catego	ry : Classroom		В	uildina	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #104 (Music Room)						
	Ceiling - Lay-in	1st Floor	1,033	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	1,033	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,370	SF	7	10+ years	Being converted to a music room,
	Traile Tracter/21/Julian		1,010	•	•	.o. you.o	acoustic paneling to be installed
							pictured in middle of room per
							engineer comment
01	//400 /O : Ol						
Classro	om #106 (Science Classroom)	4 . 🗔					
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	995	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	995	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EΑ	7	6-10 years	
	Marker Board	1st Floor	1	LF	7	10+ years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,700	SF	7	10+ years	

Campus Name: Dunne Page : 18 of 22 Assessment Date: 05/09/2022





Category: Classroom **Building: Linked Addition** Recommend

Item - Type Location Quantity UOM Rank Replacement Comments

Group 10+ years Updated quantity Work Sink 1st Floor 2 EΑ

Category : Interior Building · Linked Addition

Catego	ry : Interior	Building : Linked Addition						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	150 Vestibule	203	SF	7	10+ years		
	Doors - Steel Doors incl hw	150 Vestibule	4	EΑ	7	10+ years		
	Floor - Epoxy/ Painted	150 Vestibule	203	SF	7	10+ years		
	Lighting - Lay-in	150 Vestibule	2	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	150 Vestibule	120	SF	7	10+ years		
	Ceiling - Plaster/Drywall	163 Vestibule	123	SF	7	10+ years		
	Ceiling - Plaster/Drywall	163 Vestibule	3	SF	5	0-1 year	Water damage	
	Doors - Store Front	163 Vestibule	4	EA	7	10+ years	_	
	Floor - Epoxy/ Painted	163 Vestibule	126	SF	7	10+ years		
	Lighting - Lay-in	163 Vestibule	1	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	163 Vestibule	280	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,320	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	Water damage	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years	•	
	Floor - Tile/Sheet	1st Floor	1,344	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	266	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,749	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1	SF	5	0-1 year	Dent in plaster, finish damaged.	
	Ceiling - Lay-in	250 vestibule	198	SF	7	10+ years		
	Doors - Steel Doors incl hw	250 vestibule	2	EA	7	10+ years		
	Floor - Tile/Sheet	250 vestibule	198	SF	7	10+ years		
	Lighting - Lay-in	250 vestibule	2	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	250 vestibule	1,400	SF	7	10+ years		
	Ceiling - Lay-in	251 Elevator Lobby	198	SF	7	10+ years		
	Doors - Wood Doors include hw	251 Elevator Lobby	2	EA	6	10+ years		
	Floor - Tile/Sheet	251 Elevator Lobby	198	SF	7	10+ years		
	Lighting - Lay-in	251 Elevator Lobby	1	EA	7	6-10 years		
	Walls - Concrete Block	251 Elevator Lobby	100	SF	7	10+ years		
	Walls - Plaster/Drywall	251 Elevator Lobby	200	SF	7	10+ years		
Safety								
Dalety	Security Cameras	1st Floor	3	EA	7	6-10 years		
	5555 , 546.46		· ·	_, ,	•	3 . 0 , 0		
Vertical 0	Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years		

Page: 19 of 22 Campus Name: Dunne Assessment Date: 05/09/2022



Category : Site Building : Site

Jalegui	ategory : Site		В				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Synthetic	Entire Site	11,380	SF	6	10+ years	
	Sundos Symmons	Zimio dita	11,000	O.	Ü	101 youro	
ivil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	6	10+ years	
encing	Fencing - Chain Link	Entire Site	1,082	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	1,002	LF	4	0-1 year	Damaged post, fence not aligned
	1 choing - Chain Link	Littile Oile	'	LI	7	0-1 year	gates not latching. Damaged gate
	Fencing - Chain Link	Entire Site	30	LF	4	0-1 year	Missing posts, bent top rail.
	Fencing - New Standard Ornamental	Entire Site	230	LF	7	10+ years	
	Tonoing Trow Standard Smallionia	Litting Oild	200		•	.o. you.o	
andscap							
	Benches	Entire Site	10	EA	5	6-10 years	
	Landscape - Grass	Entire Site	15,525	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	3,100	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	2,689	SF	6	10+ years	
	Parkway trees	Entire Site	16	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	1,030	SF	5	10+ years	
	Planting Beds/ Area	Entire Site	300	SF	4	0-1 year	Destroyed.
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
arking L	ot						
anning i	Surface - Asphalt	North	2,430	SF	7	10+ years	New, repaired
	Surface - Asphalt	North	7,131	SF	6	6-10 years	
	Surface - Concrete	North	2,100	SF	7	10+ years	New
	Surface - Concrete	North	462	SF	7	10+ years	11011
	Trash Enclosure - Chain Links	North	520	SF	7	10+ years	
	Trash Enclosure - Chain Links	North	160	SF	4	0-1 year	Broken hinges at gates.
	Vehicular Screening	North	24	LF	6	10+ years	Broken minges at gates.
	vornoular corooning	Horar	21	_,	Ü	101 youro	
aygrou							
	Equipment - School Age 5-12	North	1	EΑ	7	10+ years	
	Surface - Poured Surface	North	3,360	SF	7	10+ years	
idewalk	s						
	Sidewalks - Internal Walks	Entire Site	196	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	10	LF	4	0-1 year	Landing has settled cracking the

Campus Name: Dunne Page : 20 of 22 Assessment Date: 05/09/2022



Category : Site			В	uilding			
					_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	13,351	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	5,117	SF	4	0-1 year	Cracked, disintegrated, missing, upheaved sidewalks.
Signage	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
		Entire Site	1	EA	7	,	
	Marquee - Free Standing Back Lighted		ı		1	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Dunne Page: 21 of 22 Assessment Date: 05/09/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					\-\-				
Computer Lab	Library	2nd Floor	200	NA	1,141	168	17	N	Υ
Computer Lab	Regular Classroom	2nd Floor	203	NA	753	88	9	N	Υ
Computer Lab	Regular Classroom	2nd Floor	206	NA	753	88	9	N	N
Kindergarten	Computer Lab	1st Floor	102	109	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	101	112	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	103	114	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	105	116	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	107	118	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	110	113	753	84	88	N	N
Regular Classroom	Regular Classroom	1st Floor	112	115	753	88	9	N	N
Regular Classroom	Regular Classroom	1st Floor	114	117	753	88	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	NA	753	96	10	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	NA	726	88	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	NA	753	88	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	NA	748	88	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	NA	753	88	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	NA	753	84	9	N	N
Building : Linked Addition									
Music Room	Regular Classroom	1st Floor	104	159	1,033	90	27	N	N
Science Classroom	Science Classroom	1st Floor	106	161	995	90	27	N	N