

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1963 | 3 | 69,287 |
| Campus Total | | | 69,287 |

| Catego | Category : Exterior | | | | : Main | | |
|----------|--------------------------------------|---------------|----------|-----|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | 3 | | | | | | |
| | Entrance Control - Audio and Video | #1 N | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #1 N | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #1 N | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #1 N | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #10 N | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #10 N | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #11 Courtyard | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | #11 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #11 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #11 Courtyard | 3 | LF | 6 | 10+ years | |
| | Exterior Doors - Side lite | #12 Courtayrd | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | #12 Courtayrd | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #12 Courtayrd | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #13 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | #13 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #13 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #14 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | #14 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #14 Courtyard | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #2 W | 2 | EA | 5 | 0-1 year | Rusting. |
| | Exterior Doors - Exterior Steel Door | #3 W | 1 | EA | 5 | 0-1 year | Rusting. |
| | Exterior Doors - Exterior Steel Door | #4 W | 1 | EA | 5 | 0-1 year | Rusting. |
| | Exterior Doors - Exterior FRP Door | #5 W | 2 | EA | 6 | 10+ years | - |
| | Exterior Doors - Transom Lite | #5 W | 1 | EA | 6 | 10+ years | |



| Cotogo | | | | uilding | Main | | 3615 W 16th STREET, Chicago, IL 60623 |
|----------|---|-----------------|---------------|---------|--------|--------------------------|---------------------------------------|
| Catego | ry : Exterior | | В | uilding | : wain | Decemmend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Group | Entrance Control - Audio and Video | #6 S | Quantity 1 | EA | 6 | 10+ years | Comments |
| | Exterior Doors - Exterior FRP Door | #6 S | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #6 S | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #6.5 Exit S | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #7 S | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #7 S | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #8 Exit E | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #8 Exit E | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #8 Exit E | 6 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #9 N | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #9 N | 2 | EA | 6 | 10+ years | |
| | | | E. | L/\ | 0 | lot youro | |
| Foundat | | | | | | | |
| | Foundation - Concrete | Entire Building | 890 | LF | 7 | 10+ years | |
| | Superstructure - Concrete | Entire Building | 69,287 | SF | 7 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 12 | EA | 6 | 10+ years | |
| Roof Sys | stem | | | | | | |
| | Access Ladder - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | Main Roof | 650 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Main Roof | 120 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Main Roof | 650 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | Main Roof | 12,782 | SF | 4 | 0-1 year | Bubbling, missing ballast/exposed ta |
| | | |) - | | | , | in spots. |
| | Roof - Asphalt Gravel Ballast | Main Roof | 4,262 | SF | 4 | 0-1 year | Ponding: Dip in structure or low |
| | | | | | | | amount of ballast. Bubbling, missing |
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | ballast in spots. |
| | Roof Structure - Concrete | Main Roof | 17,044 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Middle Roof | 1 | EA | 7 | 10+ years | |
| | Access Ladder - Metal | Middle Roof | 1 | EA | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Middle Roof | 25 | LF | 6 | 10+ years | |
| | Liner | | 25 | L1 | 0 | ior years | |
| | Chimney - Metal Flue | Middle Roof | 12 | LF | 6 | 10+ years | |
| | Coping - Metal | Middle Roof | 446 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Middle Roof | 180 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Middle Roof | 446 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | Middle Roof | 10.878 | SF | 5 | 2-5 years | |
| | Roof Hatch - Metal | Middle Roof | 10,070 | EA | 7 | 10+ years | |
| | Roof Structure - Concrete | Middle Roof | 10,878 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | | 10,878 | EA | 7 | | |
| | AULESS LAUUEI - IVIELAI | NW High Roof | 1 | EA | 1 | 10+ years | |



Category : Exterior Building : Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Coping - Metal NW High Roof 332 LF 6 10+ vears NW High Roof LF 6 Downspouts - Interior Downspouts 60 10+ years Parapet - Parapet < 16" Height NW High Roof 332 LF 6 10+ years Roof - Asphalt Gravel Ballast NW High Roof SF 5 6.893 2-5 years SF 7 Roof Structure - Concrete NW High Roof 6.893 10+ years Walls Exterior Walls - Brick Entire Building 18,360 SF 6 10+ years SF Exterior Walls - Prefabricated Metal Panel Entire Building 1.050 6 10+ years Wall Exterior Walls - Stone-Cut SF Entire Building 600 6 10+ years Windows Curtain wall - Glazed Double Pane Entire Building 6.515 SF 5 0-1 vear Air/weather penetration SF Curtain wall - Insulated Panel Entire Building 8,500 4 0-1 year Rust/corrosion - Air/weather Penetration SF Curtain wall - Louver Entire Building 160 6 10+ years Curtain wall - Windows SF 6 10+ years Entire Building 2.400 SF Guard - Guards perforated Entire Building 6 10+ years 1,950 Lintels - Steel Entire Building 66 LF 7 10+ years SF Skylite - Glass Double-Pane Entire Building 625 4 0-1 year Broken/hole. Category : Electrical Building : Main Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Emergency System Exit Signs - Corridors and Stairs Entire Building 27 EΑ 6 6-10 years Exit Signs - Lunchroom Entire Building 3 ΕA 6 6-10 years Exit Signs - Multipurpose Room 5 ΕA 6 6-10 years Entire Building Security System - CCTV SF 6 6-10 years Entire Building 69,287 Security System - Intrusion Detection Entire Building SF 6 6-10 years 69.287 Emergency Battery Packs - Corridors and Entire Building 70 FΑ 6 6-10 vears Functional Stairs Emergency Battery Packs - Lunchrooms Entire Building 9 EΑ 6 6-10 years AC generator not required AC generator not required **Emergency Battery Packs - Multipurpose** Entire Building 11 ΕA 6 6-10 years Room **Emergency Battery Packs - Students Toilets** Entire Building 4 EΑ 6 6-10 years AC generator not required Emergency A/C Power - Corridors and 15,920 SF Entire Building 6 10+ years Stairs Emergency A/C Power - Lunchrooms Entire Building 2.350 SF 6 10+ vears SF Emergency A/C Power - Multipurpose Entire Building 4.885 6 10+ years Room Emergency A/C Power - Students Toilets Entire Building 1,605 SF 6 10+ years



| | | | _ | | | | 3615 W 16th STREET, Chicago, IL 600 |
|-----------|--|-----------------|----------|---------|--------|--------------------------|-------------------------------------|
| Catego | ry : Electrical | | В | uilding | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | | | | | | | |
| /lain Se | | | | | | | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 10+ years | Serves main building |
| | Main Electrical Service - 2000 A 277/480/3PH | Electrical Room | 1 | EA | 6 | 10+ years | Serves main building |
| | PA System | Entire Building | 69,287 | SF | 6 | 6-10 years | |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | Serviced and cleaned |
| | Lighting and Power Panels - Above 100 A | Entire Building | 16 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | 0-1 year | Frequently trips |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 4 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | • | 4 | EA | 7 | | |
| | • | Entire Building | | | | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 4 | EA | 7 | 10+ years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | |
| Catego | ry : Fire Protection | | В | uilding | : Main | | |
| Crown | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Group | | Location | Quantity | | Rallk | Replacement | Comments |
| Fire Alar | | | 4 | Ξ. | 0 | 0.40 | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm Strobe Lights | Entire Building | 69,287 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 69,287 | SF | 6 | 6-10 years | |
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| • | | Location | Quantity | | Nain | Replacement | Comments |
| Air Cond | 5 | Fating Duilding | 4 | Γ. | | 10 | |
| | Chemical Pot Feeder | Entire Building | 1 | EA | 6 | 10+ years | |
| | Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons | Entire Building | 1 | EA | 6 | 10+ years | |
| | Glycol Feed | Entire Building | 1 | EA | 6 | 10+ years | |
| | Pipes - Chilled Water Pipe- Steel | Entire Building | 100 | LF | 6 | 10+ years | |
| | Pipes - Dual Temperature Pipe- Steel | Entire Building | 1,200 | LF | 6 | 10+ years | |
| | Pressure Fill System | Entire Building | 1,200 | EA | 6 | 10+ years | |
| Air Hand | lling Systems | | | | | | |
| | Air Handling Unit- Package Single Zone- | Mechanical Room | 1 | EA | 5 | 6-10 years | AHU 1, serves the cafeteria, and |
| | All Handling Onit- I ackage Oligie Zoile- | | I | | 5 | U- TO years | |
| | | | | | | | |



| | | | | | | | 3615 W 16th STREET, Chicago, IL 60623 |
|-----------|--|-----------------|----------|---------|--------|-------------|---|
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Indoor- Dual Temperature Coils - 6000- | | | | | | kitchen. Ceiling mounted. |
| | 10000 cfm | | | | | | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Air Handling Unit- Package Single Zone- | Mechanical Room | 1 | EA | 6 | 6-10 years | AHU 2 serves gym and hallways |
| | Indoor- Dual Temperature Coils - 6000- | | | | | | |
| | 10000 cfm | | | | | | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Air Handling Unit- Package Single Zone- | Mechanical Room | 1 | EA | 6 | 6-10 years | AHU 3, serves corridors and closets |
| | Indoor- Dual Temperature Coils - 6000- | | | | | | |
| | 10000 cfm | Machanical Deem | 4 | | 6 | 6 10 10000 | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| Boiler Sv | vstems | | | | | | |
| | Boiler Auxiliary- Condensing Hot Water - | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | 1001 - 2000 HP | | | | | - | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Condensing- Hot Water Boiler - 1001 - 2000 | Boiler Room | 2 | EA | 6 | 6-10 years | Serves main building |
| | MBH | | | | | | |
| | Glycol Feed System | Boiler Room | 1 | EA | 5 | 6-10 years | Manually fed |
| | Water Fill System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| Heating | Devices | | | | | | |
| 0 | Unit Heater - Hot Water | Boiler Room | 1 | EA | 5 | 6-10 years | With damaged thermostat |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 14 | EA | 6 | 6-10 years | C C |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 8 | EA | 6 | 10+ years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 1 | EA | 5 | 0-1 year | Functional, portion of cover missing. |
| | Fin Tube - Hot Water | Entire Building | 111 | LF | 6 | 10+ years | |
| | Fin Tube - Hot Water | Entire Building | 5 | LF | 5 | 1-2 years | Cover missing. |
| | PTAC - Hot Water Heating and Self | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Contained Cooling | | | | | | |
| Mechani | cal Plumbing | | | | | | |
| | Dual Temperature Pump - 10 - 20 HP | Boiler Room | 2 | EA | 6 | 6-10 years | Floor mounted |
| | Hot Water Pump - Less than 10 | Boiler Room | 3 | EA | 6 | 6-10 years | Serve air handlers, ceiling mounted |
| | Hydronic Supply and Return - Steel | Boiler Room | 300 | LF | 6 | 10+ years | , 3 |
| | | | | | | | |
| Tempera | ature Control | | | | | 0.40 | |
| | DDC System | Entire Building | 69,287 | SF | 6 | 6-10 years | Serves main building. Software upgraded in 2016 |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 6-10 years | In MDF room |
| | Electric Thermostat | Entire Building | 1 | EA | 4 | 0-1 year | Serves unit heater in boiler room, |
| | | | 1 | LA | 4 | u-i yeai | damaged, still functional. |
| | Thermostats - DDC | Entire Building | 40 | EA | 6 | 6-10 years | Serve 40 univents |
| | | | 10 | | ÷ | , | |



| | schools | | | | | | 3615 W 16th STREET, Chicago, IL 606 |
|-----------|--|-----------------|----------|---------|--------|-------------|--------------------------------------|
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| | | | • | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Jnit Ven | tilation | | | | | | |
| | Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 35 | EA | 6 | 6-10 years | DDC controlled |
| | Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 5 | EA | 5 | 6-10 years | Need occasional repair |
| entilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 5 | 6-10 years | In MDF room, previously not assessed |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - Greater than 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 20 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Roof Mounted Duct Work | Entire Building | 15 | LF | 6 | 10+ years | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 10+ years | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 10+ years | |
| atego | ry : Plumbing | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ot Wate | Electric Heater - 20 - 50 KW | 1st Floor | 1 | EA | 5 | 6-10 years | Serves dishwasher, booster heate |
| | | | | | Ū | | previously not assessed. |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 2 | EA | 5 | 6-10 years | 2011 installation |
| iping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 69,287 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 69,287 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 69,287 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 69,287 | SF | 6 | 10+ years | 1963 installation |
| | | | | | | | |



Building : Main Category : Plumbing Recommend UOM Location Group Item - Type Quantity Rank **Replacement** Comments Domestic Piping-Hot/Cold Water Supply Entire Building 10+ years 69,287 SF 6 (from Risers to Fixtures) Sanitary Piping Entire Building 69,287 SF 6 10+ years Storm Piping Entire Building 69,287 SF 6 10+ years Vent Piping SF 6 Entire Building 69,287 10+ years Pumps Pumps - Domestic Booster Pump-Duplex Mechanical Room, Elevator pit 6-10 years ΕA 5 1 Pumps - Sump-Simplex Mechanical Room, Elevator pit ΕA 6 6-10 years Under elevator 1

Building : Main

Category : Room

| Caleyo | | | Building . Main | | | | | | | | |
|---------|-----------------------------|----------------------------------|-----------------|-----|------|-------------|---------------|--|--|--|--|
| | | | | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | | |
| Adminis | rative Suites/Offices | | | | | | | | | | |
| | Ceiling - Plaster/Drywall | Engineers Office | 130 | SF | 7 | 10+ years | | | | | |
| | Doors - Wood Doors inclu hw | Engineers Office | 1 | EA | 7 | 10+ years | | | | | |
| | Floor - Concrete | Engineers Office | 130 | SF | 7 | 10+ years | | | | | |
| | Lighting - Pendent/Surface | Engineers Office | 3 | EA | 7 | 10+ years | | | | | |
| | Power Distribution | Engineers Office | 4 | EA | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | Engineers Office | 420 | SF | 7 | 10+ years | | | | | |
| | Ceiling - Lay-in | Gym Office | 90 | SF | 7 | 6-10 years | | | | | |
| | Doors - Wood Doors inclu hw | Gym Office | 1 | EA | 7 | 10+ years | | | | | |
| | Floor - Tile | Gym Office | 90 | SF | 6 | 6-10 years | | | | | |
| | Lighting - Lay-in | Gym Office | 2 | EA | 7 | 6-10 years | | | | | |
| | Power Distribution | Gym Office | 4 | EA | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | Gym Office | 280 | SF | 7 | 10+ years | | | | | |
| | Ceiling - Plaster/Drywall | Kitchen Office | 50 | SF | 7 | 10+ years | | | | | |
| | Doors - Wood Doors inclu hw | Kitchen Office | 1 | EA | 7 | 10+ years | | | | | |
| | Floor - Tile | Kitchen Office | 35 | SF | 7 | 10+ years | | | | | |
| | Floor - Tile | Kitchen Office | 15 | SF | 4 | 0-1 year | Missing tiles | | | | |
| | Lighting - Pendent/Surface | Kitchen Office | 1 | EA | 7 | 10+ years | | | | | |
| | Power Distribution | Kitchen Office | 2 | EA | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | Kitchen Office | 300 | SF | 7 | 10+ years | | | | | |
| | Ceiling - Lay-in | Main Office - Conference Room | 360 | SF | 7 | 10+ years | | | | | |
| | Doors - Wood Doors inclu hw | Main Office - Conference Room | 2 | EA | 7 | 10+ years | | | | | |
| | Floor - Carpet | Main Office - Conference Room | 360 | SF | 7 | 6-10 years | | | | | |
| | Lighting - Lay-in | Main Office - Conference Room | 6 | EA | 7 | 10+ years | | | | | |
| | Power Distribution | Main Office - Conference Room | 10 | EA | 7 | 10+ years | | | | | |
| | Storage/ Closet | Main Office - Conference Room | 18 | SF | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | Main Office - Conference Room | 780 | SF | 7 | 10+ years | | | | | |
| | Ceiling - Lay-in | Main Office - Principal's Office | 170 | SF | 7 | 10+ years | | | | | |
| | Doors - Wood Doors inclu hw | Main Office - Principal's Office | 1 | EA | 7 | 10+ years | | | | | |
| | Floor - Carpet | Main Office - Principal's Office | 170 | SF | 7 | 6-10 years | | | | | |
| | Lighting - Lay-in | Main Office - Principal's Office | 3 | EA | 7 | 10+ years | | | | | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Main Office - Principal's Office Power Distribution 6 ΕA 10+ vears 7 Main Office - Principal's Office 520 SF 7 Walls - Concrete Block 10+ years Ceiling - Lay-in Main Office 127 570 SF 7 10+ years Doors - Side-lite Main Office 127 SF 7 50 10+ years Doors - Store Front Main Office 127 1 EΑ 7 10+ years SF 7 Doors - Transom Window Main Office 127 30 10+ years Floor - Carpet Main Office 127 92 SF 7 6-10 years SF Floor - Tile Main Office 127 472 7 10+ years Floor - Tile Main Office 127 6 SF 4 0-1 year Missing tiles Lighting - Lay-in Main Office 127 11 FΑ 7 10+ vears Lighting - Pendent/Surface Main Office 127 2 ΕA 7 10+ vears Power Distribution Main Office 127 10 EΑ 7 10+ years Storage/ Closet Main Office 127 6 SF 7 10+ years SF 7 Walls - Concrete Block Main Office 127 1,180 10+ years Ceiling - Lav-in Room 134 SF 7 320 10+ years Doors - Wood Doors inclu hw Room 134 FΑ 7 1 10+ years Floor - Tile 320 SF Room 134 7 10+ years Lighting - Lay-in Room 134 5 EΑ 7 10+ years Power Distribution Room 134 10 EΑ 7 10+ vears Walls - Concrete Block Room 134 700 SF 7 10+ years Work SInk Room 134 ΕA 7 10+ years 1 Workroom in lunchroom SF 7 Ceiling - Lay-in 120 6-10 years Doors - Side-lite SF 7 Workroom in lunchroom 21 10+ years Doors - Wood Doors inclu hw Workroom in lunchroom FΑ 6 6-10 years Damaged door knob. 1 Floor - Tile 120 SF 7 10+ years Workroom in lunchroom Lighting - Lav-in Workroom in lunchroom 2 ΕA 7 6-10 vears Power Distribution Workroom in lunchroom 4 ΕA 7 10+ years Walls - Concrete Block 280 SF 7 Workroom in lunchroom 10+ years Work SInk Workroom in lunchroom 1 ΕA 7 10+ years Gvmnasia Ceiling - Exposed 1st Floor SF 7 3.735 10+ vears Ceiling - Plaster/Drywall SF 1st Floor 1,150 7 10+ years Doors - Steel Doors incl hw 1st Floor 6 ΕA 7 10+ years Floor - Wood 1st Floor SF 7 10+ years 4,885 7 Lighting - Metal Halide/Sodium Vapor 1st Floor 14 EΑ 10+ years Lighting - Metal Halide/Sodium Vapor 1st Floor 6 FΑ 5 0-1 year Lights out over stage Scoreboards FΑ 7 10+ years 1st Floor 1 SF Stage 1st Floor 300 7 10+ vears Stage Curtain EΑ 7 10+ years 1st Floor 12 ΕA 7 Stage Lift 1st Floor 1 10+ years Stage Lighting System 1st Floor 1 ΕA 7 10+ years Stage-Stairs - Wood 1st Floor 9 LF 7 10+ years Storage/ Closet SF 1st Floor 214 5 10+ years Floor tiles broken/missing.



| Catego | ory : Room | | Building : Main | | | | | |
|----------------|----------------------------------|----------------------------------|-----------------|-----|--------|------------------------|-----------------------------------|--|
| | | | | J | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Walls - Concrete Block | 1st Floor | 7,800 | SF | 7 | 10+ years | | |
| | | | , | | | , | | |
| Kitchen | | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 760 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 40 | SF | 5 | 0-1 year | Water damage. | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | ĒA | 7 | 10+ years | i alor damager | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 790 | SF | 7 | 10+ years | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 10 | SF | 4 | 0-1 year | Missing tiles | |
| | Lighting - Pendent/Surface | 1st Floor | 13 | EA | 7 | 10+ years | wissing ties | |
| | Serving Line | 1st Floor | 20 | LF | 7 | 10+ years | | |
| | Storage/ Closet | 1st Floor | 89 | SF | 7 | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | | SF | 7 | | | |
| | Wais - The Ceramic/ Porcelain | | 1,200 | Эг | / | 10+ years | | |
| unch & | Multipurpose Room | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,318 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 1st Floor | 32 | SF | 4 | 0-1 year | Water damage and missing tiles | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | 5 5 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | ĒA | 7 | 10+ years | | |
| | Floor - Tile | 1st Floor | 2,350 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 26 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 2,650 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 1st Floor - Teacher's Dining 121 | 676 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 1st Floor - Teacher's Dining 121 | 24 | SF | 4 | 0-1 year | Water damage | |
| | Doors - Wood Doors inclu hw | 1st Floor - Teacher's Dining 121 | 2 | EA | 7 | 10+ years | Water damage | |
| | Floor - Tile | 1st Floor - Teacher's Dining 121 | 700 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor - Teacher's Dining 121 | 8 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor - Teacher's Dining 121 | 1,376 | SF | 7 | 10+ years | | |
| | | 5 | , | - | | - , | | |
| <u>/IDF_ID</u> | F Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Finishes | 2nd Floor | 188 | SF | 5 | 10+ years | | |
| | Other Cooling Unit | 2nd Floor | 100 | EA | 5 7 | 6-10 years | Ductless split system. | |
| | Window AC Unit | | 1 | EA | 7 | • | Ductiess spiit system. | |
| | | 2nd Floor | I | EA | / | 6-10 years | | |
| /lechani | ical/ Service Rooms | | | | | | | |
| | Boiler Room | 1st Floor | 2,500 | SF | 7 | 10+ years | | |
| | Janitor's Closet | 1st Floor | 138 | SF | 5 | 10+ years | Floor tile missing and damage nea | |
| | Mechanical/ Service Rooms | 1st Floor | 164 | SF | 7 | 10+ years | fin tube. | |
| | Mechanical/ Service Rooms | 1st Floor | 180 | SF | 7 | 10+ years | | |
| | Storage Room | 1st Floor | 250 | SF | 7 | 10+ years 10+ years | | |
| | | 1st Floor | 120 | SF | 7 | - | | |
| | Storage Room | | 120 | эг | 1 | 10+ years | | |
| | | | | | | | | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Storage Room 1st Floor 115 SF 10+ vears 7 Janitor's Closet 2nd Floor SF 7 150 10+ years Mechanical/ Service Rooms 2nd Floor 50 SF 7 10+ years SF 7 Storage Room 2nd Floor 308 10+ years SF 5 Janitor's Closet 3rd Floor 138 10+ years Damage to wall. SF 7 Storage Room 3rd Floor 36 10+ years Storage Room 3rd Floor 422 SF 7 10+ years SF Storage Room 3rd Floor 189 5 10+ years Floor worn. Restroom 1st Floor - Boys 235 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall 1st Floor - Boys 235 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor - Boys ΕA 7 1 10+ vears SF Floor - Tile Ceramic/ Porcelain 1st Floor - Boys 235 7 10+ years ΕA 7 Floor Drain 1st Floor - Bovs 10+ vears 1 Hand Dryer 1st Floor - Boys 2 FΑ 7 6-10 years 3 Lavatory 1st Floor - Boys FΑ 7 10+ years Lighting - Pendent/Surface 5 1st Floor - Boys EΑ 7 10+ years 2 7 Partitions 1st Floor - Boys EΑ 10+ years 1st Floor - Boys 5 ΕA 7 Urinals 10+ years SF Walls - Tile Ceramic/ Porcelain 1st Floor - Bovs 600 7 10+ years Water Closet 1st Floor - Bovs 2 EΑ 7 10+ vears SF Accessories 1st Floor - Girls 240 7 6-10 years Ceiling - Plaster/Drvwall 1st Floor - Girls SF 7 240 10+ vears Doors - Wood Doors inclu hw 1st Floor - Girls 1 EA 7 10+ years Floor - Terrazzo 15 SF 7 1st Floor - Girls 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st Floor - Girls 225 10+ years Floor Drain ΕA 7 1st Floor - Girls 1 10+ years Hand Dryer 2 FΑ 7 1st Floor - Girls 6-10 years Lavatory 1st Floor - Girls 3 EΑ 7 10+ years Lighting - Pendent/Surface 1st Floor - Girls 5 EΑ 7 10+ years 5 Partitions 1st Floor - Girls ΕA 7 10+ vears Walls - Concrete Block 1st Floor - Girls 10 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 1st Floor - Girls 586 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 1st Floor - Girls SF 5 0-1 year 4 Broken tiles 7 Water Closet 1st Floor - Girls 5 ΕA 10+ years SF 7 Accessories 1st Floor - Men North 123 90 6-10 years Ceiling - Plaster/Drywall 90 SF 7 1st Floor - Men North 123 10+ years Doors - Wood Doors inclu hw 1st Floor - Men North 123 1 EΑ 7 10+ vears Floor - Tile Ceramic/ Porcelain 90 SF 7 10+ years 1st Floor - Men North 123 Floor Drain ΕA 7 1st Floor - Men North 123 1 10+ years Hand Dryer 1st Floor - Men North 123 1 ΕA 7 6-10 years 1st Floor - Men North 123 2 ΕA 7 10+ years Lavatory Lighting - Pendent/Surface 1st Floor - Men North 123 3 EΑ 7 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Partitions 1st Floor - Men North 123 FΑ 10+ vears 7 1 ΕA 7 Urinals 1st Floor - Men North 123 1 10+ years Walls - Tile Ceramic/ Porcelain 1st Floor - Men North 123 180 SF 7 10+ years Water Closet ΕA 7 1st Floor - Men North 123 1 10+ years SF 7 Accessories 1st Floor - Women North 124 90 6-10 years SF 7 Ceiling - Plaster/Drywall 1st Floor - Women North 124 90 10+ years Doors - Wood Doors inclu hw 1st Floor - Women North 124 ΕA 7 1 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor - Women North 124 90 7 10+ years Floor Drain 1st Floor - Women North 124 1 ΕA 7 10+ years Hand Dryer 1st Floor - Women North 124 FΑ 7 6-10 years 1 Rank changed to match current observation Lavatory 1st Floor - Women North 124 2 ΕA 7 10+ years Lighting - Pendent/Surface 1st Floor - Women North 124 3 ΕA 7 10+ years 2 7 Partitions 1st Floor - Women North 124 EA 10+ years Walls - Tile Ceramic/ Porcelain SF 7 1st Floor - Women North 124 180 10+ years Water Closet FΑ 7 1st Floor - Women North 124 2 10+ years SF 7 Accessories 2nd Floor - Bovs 235 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor - Boys 211 7 10+ years SF Ceiling - Plaster/Drvwall 2nd Floor - Bovs 24 6 10+ vears Doors - Wood Doors inclu hw 2nd Floor - Boys 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor - Boys 235 SF 7 10+ years 7 Floor Drain 2nd Floor - Boys 1 EΑ 10+ years 2 ΕA 7 Hand Drver 2nd Floor - Boys 6-10 years Lavatory 2nd Floor - Boys 3 FΑ 7 10+ years Lighting - Pendent/Surface 4 FΑ 7 2nd Floor - Boys 10+ years 2 Partitions 2nd Floor - Bovs FΑ 7 10+ vears Urinals 2nd Floor - Boys 5 EΑ 7 10+ years Walls - Tile Ceramic/ Porcelain 2nd Floor - Boys 600 SF 7 10+ years ΕA Water Closet 2nd Floor - Boys 2 7 10+ years Accessories 2nd Floor - Girls 330 SF 7 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor - Girls 330 7 10+ vears Doors - Wood Doors inclu hw 2nd Floor - Girls EΑ 7 10+ vears 1 SF 7 Floor - Terrazzo 2nd Floor - Girls 20 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor - Girls SF 7 10+ years 310 Floor Drain 7 2nd Floor - Girls 1 EΑ 10+ years ΕA 7 Hand Dryer 2nd Floor - Girls 2 6-10 years 2nd Floor - Girls Lavatory 3 EΑ 7 10+ years Lighting - Pendent/Surface 6 2nd Floor - Girls EA 7 10+ years Partitions 2nd Floor - Girls 5 EΑ 7 10+ years 25 SF Walls - Concrete Block 2nd Floor - Girls 7 10+ vears SF Walls - Tile Ceramic/ Porcelain 2nd Floor - Girls 730 7 10+ years FΑ 7 Water Closet 2nd Floor - Girls 5 10+ vears Accessories 2nd Floor - Men 209A 94 SF 7 6-10 years SF Ceiling - Lay-in 2nd Floor - Men 209A 26 7 10+ years



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|--|--|----------|----------|--------|------------------------|-----------------------------------|
| | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 2nd Floor - Men 209A | 38 | SF | 4 | 0-1 year | Water damage and hole in ceiling. |
| | Ceiling - Plaster/Drywall | 2nd Floor - Men 209A | 30 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Men 209A | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor - Men 209A | 64 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor - Men 209A | 30 | SF | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor - Men 209A | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor - Men 209A | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor - Men 209A | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor - Men 209A | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor - Men 209A | 297 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor - Men 209A | 111 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor - Men 209A | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor - Unisex 224A | 108 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor - Unisex 224A | 108 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Unisex 224A | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor - Unisex 224A | 57 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor - Unisex 224A | 51 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor - Unisex 224A | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor - Unisex 224A | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor - Unisex 224A | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor - Unisex 224A | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor - Unisex 224A | 325 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor - Unisex 224A | 95 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor - Unisex 224A 2nd Floor - Unisex 224A | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor - Boys | 235 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - Boys | 235 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor - Boys | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor - Boys | 235 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - Boys | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor - Boys | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor - Boys | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor - Boys | 4 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor - Boys | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor - Boys | 5 | EA | 7 | | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor - Boys | 600 | SF | 7 | 10+ years 10+ years | |
| | Walls - The Ceramic/ Forcelain Water Closet | 3rd Floor - Boys | 2 | EA | 7 | - | |
| | Accessories | 3rd Floor - Girls | 330 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - Girls | 330 | SF | | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor - Girls | 330 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor - Girls | 20 | SF | 7 7 | 10+ years | |
| | | | | | | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor - Girls | 310 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - Girls | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor - Girls | 2 | EA EA | 7 7 | 6-10 years | |
| | Lavatory | 3rd Floor - Girls | 3 | EA | 1 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|---------------------------|----------|---------|--------|-------------|--|
| J | , | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Lighting - Pendent/Surface | 3rd Floor - Girls | 5 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor - Girls | 1 | EA | 5 | 0-1 year | Does not work. |
| | Partitions | 3rd Floor - Girls | 5 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor - Girls | 25 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor - Girls | 730 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - Girls | 5 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor - Men 309A | 64 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor - Men 309A | 34 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - Men 309A | 30 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor - Men 309A | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor - Men 309A | 34 | SF | 4 | 0-1 year | Worn, chipping, and separating throughout. |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor - Men 309A | 30 | SF | 7 | 10+ years | |
| | Lavatory | 3rd Floor - Men 309A | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor - Men 309A | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor - Men 309A | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor - Men 309A | 297 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor - Men 309A | 111 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - Men 309A | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor - Women 324A | 108 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor - Women 324A | 108 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor - Women 324A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor - Women 324A | 57 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor - Women 324A | 51 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - Women 324A | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor - Women 324A | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor - Women 324A | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor - Women 324A | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor - Women 324A | 325 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd Floor - Women 324A | 95 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - Women 324A | 1 | EA | 7 | 10+ years | |
| | Accessories | Between rooms 106 and 110 | 90 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Between rooms 106 and 110 | 90 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Between rooms 106 and 110 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Between rooms 106 and 110 | 90 | SF | 7 | 10+ years | |
| | Floor Drain | Between rooms 106 and 110 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Between rooms 106 and 110 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Between rooms 106 and 110 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Between rooms 106 and 110 | 1 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Between rooms 106 and 110 | 300 | SF | 7 | 10+ years | |
| | Water Closet | Between rooms 106 and 110 | 1 | EA | 7 | 10+ years | |
| | Accessories | Boiler Room | 135 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Boiler Room | 135 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Boiler Room | 2 | EA | 7 | 10+ years | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile Boiler Room 100 SF 10+ vears 6 Floor - Tile Ceramic/ Porcelain SF 7 **Boiler Room** 35 10+ years Boiler Room 1 FΑ 7 10+ years Lavatorv Lighting - Pendent/Surface 3 7 Boiler Room EΑ 10+ years Showers Boiler Room 1 EΑ 7 10+ years 7 Student Lockers - One Tier Boiler Room 10 EΑ 10+ years Walls - Concrete Block **Boiler Room** SF 7 1,040 10+ years SF Walls - Tile Ceramic/ Porcelain **Boiler Room** 120 7 10+ years Water Closet **Boiler Room** 1 ΕA 7 10+ years SF Accessories Classroom 101 36 7 6-10 years Ceiling - Plaster/Drvwall SF Classroom 101 36 7 10+ vears Doors - Wood Doors inclu hw Classroom 101 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain Classroom 101 36 SF 7 6-10 years 7 Floor Drain Classroom 101 1 EA 10+ years 7 Lavatory Classroom 101 1 ΕA 10+ years Lighting - Pendent/Surface Classroom 101 1 FΑ 7 6-10 years Walls - Tile Ceramic/ Porcelain SF Classroom 101 170 7 10+ vears Water Closet Classroom 101 1 ΕA 7 10+ years SF Accessories Classroom 103 36 7 6-10 vears SF Ceiling - Plaster/Drywall Classroom 103 36 6 10+ years Doors - Wood Doors inclu hw Classroom 103 1 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 Classroom 103 36 6-10 years 7 Floor Drain Classroom 103 1 EA 10+ years Lavatory Classroom 103 1 FΑ 6 10+ years Lighting - Pendent/Surface Classroom 103 FΑ 7 1 6-10 years Walls - Tile Ceramic/ Porcelain Classroom 103 170 SF 6 10+ vears Water Closet Classroom 103 EA 6 10+ years 1 In main office A Principal office 64 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall SF In main office A Principal office 64 6 10+ years Doors - Wood Doors inclu hw In main office A Principal office 1 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain In main office A Principal office 64 SF 6 6-10 years Floor Drain In main office A Principal office 1 EΑ 7 10+ vears 7 Hand Dryer In main office A Principal office 1 FΑ 10+ years In main office A Principal office FΑ 6 10+ vears Lavatorv 1 Lighting - Pendent/Surface 6-10 years In main office A Principal office 1 EΑ 7 Lighting - Wall Mounted 2 ΕA 7 In main office A Principal office 6-10 years Walls - Tile Ceramic/ Porcelain SF In main office A Principal office 180 6 10+ years Water Closet In main office A Principal office 1 EA 6 10+ years Accessories Kitchen Office 119C 40 SF 7 6-10 years Kitchen Office 119C SF Ceiling - Plaster/Drvwall 40 7 10+ vears Doors - Wood Doors inclu hw Kitchen Office 119C 1 EΑ 7 10+ years Kitchen Office 119C SF 7 Floor - Tile Ceramic/ Porcelain 40 10+ vears Lavatory Kitchen Office 119C 1 EA 7 10+ years Lighting - Pendent/Surface Kitchen Office 119C 1 EA 7 10+ years



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Walls - Concrete Block Kitchen Office 119C 90 SF 10+ years 7 Walls - Tile Ceramic/ Porcelain Kitchen Office 119C 90 SF 7 10+ years Water Closet Kitchen Office 119C 1 ΕA 7 10+ years Category : Classroom **Building : Main** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Classroom #101 (Pre School) 1st Floor LF Casework 29 6 10+ years Ceiling - Lay-in 1st Floor 1,155 SF 6 10+ years Doors - Side-lite SF 1st Floor 16 7 10+ years Doors - Transom Window 1st Floor 6 SF 7 10+ vears Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ vears Floor - Tile 1st Floor 1.155 SF 7 6-10 vears 7 Lighting - Lay-in 1st Floor 17 FΑ 6-10 years Marker Board 16 LF 6-10 years 1st Floor 6 SF Storage/ Closet 1st Floor 36 7 10+ years Walls - Concrete Block SF 1st Floor 1,160 6 10+ years Work Sink 1st Floor 2 EΑ 7 10+ years Classroom #102 (Office) 1st Floor LF Casework 29 6 10+ years Ceiling - Lay-in 1st Floor 707 SF 6 10+ years Ceiling - Lay-in SF 1st Floor 8 4 0-1 year Water damage tile Doors - Side-lite 1st Floor 16 SF 7 10+ years SF Doors - Transom Window 1st Floor 6 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ vears SF Floor - Tile 1st Floor 715 7 6-10 years FΑ Lighting - Lay-in 1st Floor 7 6-10 years 12 Marker Board 1st Floor 28 1 F 7 6-10 years 775 SF Walls - Concrete Block 1st Floor 7 10+ years Classroom #103 (Pre School) LF Casework 1st Floor 29 6 10+ years SF Ceiling - Lay-in 1st Floor 1.147 7 10+ years Ceiling - Lay-in 1st Floor 8 SF 4 0-1 year Water damage tile Doors - Side-lite SF 1st Floor 16 7 10+ years Doors - Transom Window 1st Floor 6 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ years Floor - Tile 1st Floor 1.155 SF 7 6-10 vears Lighting - Lay-in 1st Floor 17 FΑ 7 6-10 years LF Marker Board 1st Floor 16 7 6-10 years SF Walls - Concrete Block 1st Floor 1,160 7 10+ years



| Catego | ry : Classroom | | В | uilding | : Main | | |
|---------|-----------------------------------|-----------|----------|---------|--------|-------------|-------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| lacaraa | m #104 (Degular Classroom) | | | | | | |
| lassroo | m #104 (Regular Classroom) | | | | 0 | 10 | |
| | Casework | 1st Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 677 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 8 | SF | 4 | 0-1 year | Water damage tile |
| | Ceiling - Plaster/Drywall | 1st Floor | 30 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 28 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 775 | SF | 7 | 10+ years | |
| lassroo | m #105 (Computer Lab) | | | | | | |
| | Casework | 1st Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 715 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 575 | SF | 6 | 10+ years | |
| | | 1st Floor | 200 | SF | | | |
| | Walls - Vinyl Coated Gypsum Panel | | | | 6 | 10+ years | |
| | Wireless System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| lassroo | m #106/108 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 44 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,362 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 8 | SF | 4 | 0-1 year | Damaged tile |
| | Ceiling - Plaster/Drywall | 1st Floor | 60 | SF | 6 | 10+ years | - |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,430 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 24 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 28 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,550 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1,550 | EA | 7 | 10+ years | |
| | | | | | - | , | |
| lassroo | m #107 (Vacant) | | | | | | |
| | Casework | 1st Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 460 | SF | 6 | 10+ years | |



Category : Classroom

| Catego | ory : Classroom | | В | ullaing | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|--------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Ceiling - Lay-in | 1st Floor | 20 | SF | 4 | 0-1 year | Water damage tiles |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | C C |
| | Floor - Tile | 1st Floor | 480 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 240 | SF | 5 | 10+ years | Missing tile |
| | Walls - Concrete Block | 1st Floor | 775 | SF | 7 | 10+ years | |
| Classroo | om #110 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 22 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 840 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 10 | SF | 4 | 0-1 year | Water damage tile |
| | Ceiling - Plaster/Drywall | 1st Floor | 30 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | - | ĒA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 15 | ĒA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 820 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| 0 | | | | | | | |
| Classroo | om #112 (Regular Classroom) | | 24 | | 0 | 10 | |
| | Casework | 1st Floor | 34 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 625 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 90 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | _28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 775 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #114 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 34 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 707 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 8 | SF | 4 | 0-1 year | Water damage tile |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | - |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Elean Tile | det Eleen | 745 | 0 | 7 | 0.10 | |

Building : Main

Floor - Tile

1st Floor

SF

7

715

6-10 years



| Catego | ry : Classroom | | В | | | | |
|----------|-----------------------------|-----------|----------|-----|------|-------------|-------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 775 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #116 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 34 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 707 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 8 | SF | 4 | 0-1 year | Water damage tile |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | C C |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 22 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 775 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| lassroc | m #201 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 33 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 890 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 890 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 930 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #202 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 695 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | |

_Classroom #203 (Regular Classroom)



| Categor | y : Classroom | | B | uilding | • Main | | |
|----------|-----------------------------|-----------|----------|---------|---------|-------------|------------------------|
| | ategory : Classroom | | | ununig | . Walli | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 2nd Floor | 34 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 890 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 890 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 930 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #204 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 707 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 8 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | 0 |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | m #205 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 1 | LF | 6 | 0-1 year | Base end panel missing |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | m #206 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 6 | 10+ years | |
| | | | 715 | SF | 7 | 6-10 years | |
| | Floor - Tile | 2nd Floor | /10 | J J L | | | |



| Catego | ory : Classroom | | B | uilding | • Main | | SOTS W TOUT STREET, Chicago, ie 6062 | | |
|---------|-----------------------------|-----------|----------|---------|-----------|--------------|--------------------------------------|--|--|
| Jaiego | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| o. o ap | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | | | |
| | | | | • | Ū | i e i geolie | | | |
| lassroo | om #207 (Office) | | | | | | | | |
| | Casework | 2nd Floor | 4 | LF | 6 | 0-1 year | Broken backsplash | | |
| | Casework | 2nd Floor | 25 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 715 | SF | 6 | 10+ years | | | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | | | |
| lassro | om #208 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 695 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage | | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | Mater admage | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | | | |
| | | 211011001 | 115 | 01 | 0 | TOF years | | | |
| lassroo | om #210 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 695 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage | | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | | | |
| lassroo | om #212 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | | | |
| | Casework | 2nd Floor | 1 | LF | 6 | 0-1 year | Base end panel missing | | |
| | Ceiling - Lay-in | 2nd Floor | 715 | SF | 6 | 10+ years | | | |
| | | 211011001 | 715 | 0 | 0 | io+ years | | | |



| · · | Schools | | | | | | 3615 W 16th STREET, Chicago, IL 6062 |
|----------|-----------------------------------|-----------|----------|---------|--------|-------------|--------------------------------------|
| Catego | ry : Classroom | | В | uilding | : Main | | |
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | |
| lassroc | om #214 (Computer Lab) | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 695 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | Water damage |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | | 6 | 10+ years | |
| | | 2nd Floor | 775 | SF | 6 | - | |
| | Walls - Concrete Block | | 115 | Эг | 0 | 10+ years | |
| Classroc | om #216 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 695 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage. |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 775 | SF | 6 | 10+ years | |
| lassroc | om #301 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 890 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 0 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 890 | SF | 7 | 6-10 years | |
| | | | | | | | |
| | Lighting - Lay-in Marker Board | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 930 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #302 (Office) Casework 3rd Floor 29 LF 6 10+ years 3rd Floor 715 SF 6 10+ years Ceiling - Lay-in Doors - Side-lite 16 SF 6 10+ years 3rd Floor SF Doors - Transom Window 3rd Floor 6 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 FΑ 6 10+ years SF Floor - Tile 3rd Floor 715 7 6-10 years Lighting - Lay-in 3rd Floor 12 EΑ 7 6-10 years LF Marker Board 3rd Floor 28 6 6-10 years Walls - Concrete Block 775 SF 3rd Floor 6 10+ years Classroom #303 (Art Room) LF Casework 3rd Floor 33 6 10+ vears Ceiling - Lay-in SF 3rd Floor 890 6 10+ years Doors - Side-lite 3rd Floor 16 SF 6 10+ years Doors - Transom Window 3rd Floor 6 SF 6 10+ years Doors - Wood Doors inclu hw ΕA 6 10+ years 3rd Floor 1 SF 7 Floor - Tile 3rd Floor 890 6-10 years Lighting - Lay-in 3rd Floor 12 FΑ 7 6-10 years LF Marker Board 3rd Floor 28 6 6-10 years SF Walls - Concrete Block 3rd Floor 930 6 10+ years Work Sink 3rd Floor 1 EΑ 7 10+ years Classroom #304 (Science) LF Casework 3rd Floor 22 6 10+ years 3rd Floor SF Ceiling - Lay-in 715 6 10+ vears Doors - Side-lite SF 3rd Floor 16 6 10+ years Doors - Transom Window 3rd Floor 6 SF 6 10+ years Doors - Wood Doors inclu hw 6 3rd Floor 1 EΑ 10+ years Floor - Tile SF 7 6-10 years 3rd Floor 715 7 Lighting - Lay-in 3rd Floor 12 EΑ 6-10 years Marker Board 3rd Floor 28 LF 6 6-10 years SF Walls - Concrete Block 3rd Floor 775 6 10+ years Classroom #305 (Faculty Lounge) 3rd Floor LF Casework 29 6 10+ years SF Ceiling - Lay-in 3rd Floor 715 6 10+ years Doors - Side-lite SF 3rd Floor 16 6 10+ years Doors - Transom Window SF 3rd Floor 6 6 10+ vears Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 6 10+ vears Floor - Tile/Sheet 3rd Floor 715 SF 7 6-10 years 7 Lighting - Lay-in 3rd Floor 12 EΑ 6-10 years



| Catego | ory : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------|----------|---------|--------|-------------|----------|
| J | | | | 5 | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | om #306 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | om #307 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | om #308 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| Classroo | om #310 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | | 514 1 1661 | 713 | 01 | ' | 0-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| lassroo | m #312 (Store Room) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| | | 314 1 1001 | 115 | 0 | 0 | TOF years | |
| lassroc | m #314 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| lassroo | m #316 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 29 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 715 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 715 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 775 | SF | 6 | 10+ years | |
| atego | ry : Interior | | В | uilding | : Main | | |
| Ŭ | • | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 8,990 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 10 | EA | 6 | 10+ years | |



| | | | _ | | | | 3615 W 16th STREET, Chicago, IL 60623 |
|--------|--------------------------------------|-----------------|----------|----------|------|-------------|---------------------------------------|
| Catego | ry : Interior | | E | Building | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 1st Floor | 80 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 5 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 8,890 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 100 | SF | 4 | 0-1 year | Cracks in terrazzo |
| | Lighting - Lay-in | 1st Floor | 85 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 5,200 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 7,734 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 2,930 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 10 | SF | 4 | 0-1 year | Broken. |
| | Drinking Fountains - Single Fountain | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 2nd Floor | 2,940 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 36 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 2nd Floor | 182 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 5,860 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 2,930 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 10 | SF | 4 | 0-1 year | Water damage. |
| | Drinking Fountains - Single Fountain | 3rd Floor | 2 | ĒA | 7 | 10+ years | ge |
| | Floor - Terrazzo | 3rd Floor | 2,940 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 19 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 3rd Floor | 182 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 5,860 | SF | 6 | 10+ years | |
| | | | 0,000 | 0. | Ũ | ier yeare | |
| Safety | | | | | | | |
| | Camera Viewing Station | Entire Building | 3 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 7 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 30 | EA | 7 | 6-10 years | |
| | , | | | | | · · · · · | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | North Stair | 210 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | North Stair | 210 | SF | 7 | 10+ years | |
| | Handrails | North Stair | 88 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | North Stair | 4 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | North Stair | 44 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | North Stair | 930 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | North Stair | 930 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | South Stair | 210 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | South Stair | 210 | SF | 7 | 10+ years | |
| | Handrails | South Stair | 88 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | South Stair | 4 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | South Stair | 44 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | South Stair | 930 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | South Stair | 930 | SF | 7 | 10+ years | |
| | | | 380 | 0. | | ior youro | |



Dvorak Technology Academy 3615 W 16th STREET, Chicago, IL 60623

Building : Main Category : Interior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Vertical Conveyance Elevator - Hydraulic Elevator 1st to 3rd floors 1 ΕA 6 10+ years



| Group Item - Type Location Quantity UOM Rank Replacement Comments Civil/Drainage - Catch Basin Civil/Drainage - Site Manhole Entire Site 3 EA 6 10+ years Fencing | Catego | ry : Site | | В | uilding | : Site | Deserves | |
|---|---------------|---------------------------------------|----------------|----------|---------|--------|--------------------------|---|
| Civil Drainage - Catch Basin Entrice Site 3 EA 6 10+ years Fencing Civil Drainage - Site Manhole Entrice Site 166 LF 4 0-1 year Fencing Claurd Rail Entrice Site 166 LF 4 0-1 year Fencing - Cuard Rail Entrice Site 2 LF 6 10+ years Fencing - New Standard Ornamental Entrice Site 24 LF 4 0-1 year Fencing - Wood Fancing w/ Stele Frame Entrice Site 24 LF 4 0-1 year Fencing - Wood Fencing w/ Stele Frame Entrice Site 24 LF 4 0-1 year Benches 12 LF 6 6-10 years Missing, defected, and broken fence slats. Landscape - Grass Entrice Site 9 EA 6 10+ years Landscape - Flandscape - Concrete Entrice Site 175 LF 4 0-1 year Landscape - Hardscape - Concrete Entrice Site 175 EA 6 10+ years Landscape - Hardscape - Concrete Entrice Site 1,375 SF 4 0-1 year Parkway rees Entrice Site 1,375 SF 4 0-1 year Play | Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Civil Drainage - Catch Basin Entrice Site 3 EA 6 10+ years Fencing Civil Drainage - Site Manhole Entrice Site 166 LF 4 0-1 year Fencing Claurd Rail Entrice Site 166 LF 4 0-1 year Fencing - Cuard Rail Entrice Site 2 LF 6 10+ years Fencing - New Standard Ornamental Entrice Site 24 LF 4 0-1 year Fencing - Wood Fancing w/ Stele Frame Entrice Site 24 LF 4 0-1 year Fencing - Wood Fencing w/ Stele Frame Entrice Site 24 LF 4 0-1 year Benches 12 LF 6 6-10 years Missing, defected, and broken fence slats. Landscape - Grass Entrice Site 9 EA 6 10+ years Landscape - Flandscape - Concrete Entrice Site 175 LF 4 0-1 year Landscape - Hardscape - Concrete Entrice Site 175 EA 6 10+ years Landscape - Hardscape - Concrete Entrice Site 1,375 SF 4 0-1 year Parkway rees Entrice Site 1,375 SF 4 0-1 year Play | Civil/Dra | inage | | | | | | |
| Civil/ Drainaĝe - Site Manhole Entire Site 5 EA 6 10+ years Fencing - Fencing - Chain Link Entire Site 166 LF 4 0-1 year Pushed in and bent around green generator. Fencing - Guard Rail Entire Site 128 LF 6 10+ years Pushed in and bent around green generator. Fencing - Guard Rail Entire Site 123 LF 6 10+ years Fencing - Wood Fencing w/ Steel Frame Entire Site 175 LF 6 6-10 years Fencing - Wood Fencing w/ Steel Frame Entire Site 12 LF 4 0-1 year Benches Entire Site 9 EA 6 10+ years Landscape - Flardscape-Asphalt Entire Site 175 LF 9 Landscape - Grass Entire Site 1,750 SF 4 0-1 year Landscape - Hardscape-Asphalt Entire Site 1,750 SF 4 0-1 year Parkway trees Entire Site 1,55 SF 4 0-1 year Play Area - Hardscape-Asphalt Entire Site 1,50 SF 4 0-1 year Surface - Asphalt West Courtyard 1,200 SF 6 < | | | Entire Site | 3 | EA | 6 | 10+ years | |
| Fencing - Chain Link Entire Site 166 LF 4 0-1 year Pusched in and bent around green generator. Fencing - Courd Rail Entire Site 02 LF 6 10+ years generator. Fencing - New Standard Omamental Entire Site 1330 LF 6 10+ years Bent. Fencing - Wood Fencing w/ Steel Frame Entire Site 175 LF 6 0-1 year Missing, defected, and broken fence slats. Landscape Entire Site 9 EA 6 10+ years Missing, defected, and broken fence slats. Landscape - Grass Entire Site 9 EA 6 10+ years Cracking and holes throughout. Landscape - Hardscape - Concrete Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Parkway trees Entire Site 1,375 SF 6 10+ years Cracking and uneven areas. Play Area - Hardscape - Asphalt Entire Site 1,375 SF 6 0-1 year Cracking. Surface - Staphalt Entire Site 1,200 SF 6 6-10 years Damaged/Missi | | | Entire Site | | | | | |
| Fencing - Chain Link Entire Site 166 LF 4 0-1 year Pusched in and bent around green generator. Fencing - Courd Rail Entire Site 02 LF 6 10+ years generator. Fencing - New Standard Omamental Entire Site 1330 LF 6 10+ years Bent. Fencing - Wood Fencing w/ Steel Frame Entire Site 175 LF 6 0-1 year Missing, defected, and broken fence slats. Landscape Entire Site 9 EA 6 10+ years Missing, defected, and broken fence slats. Landscape - Grass Entire Site 9 EA 6 10+ years Cracking and holes throughout. Landscape - Hardscape - Concrete Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Parkway trees Entire Site 1,375 SF 6 10+ years Cracking and uneven areas. Play Area - Hardscape - Asphalt Entire Site 1,375 SF 6 0-1 year Cracking. Surface - Staphalt Entire Site 1,200 SF 6 6-10 years Damaged/Missi | Fencina | | | | | | | |
| Fencing - New Standard Ornamental Fencing - Wood Fencing w/ Steel Frame Fencing - Wood Fencing w/ Steel Frame Entire Site Entire Site Entire Site 1.330 12 LF LF 6 0.1 years 6 Bent. Missing, defected, and broken fence slats. Landscape - - - - - Missing, defected, and broken fence slats. Landscape - - - - - - - Landscape - Hardscape- Asphalt Entire Site 4.00 SF 6 10+ years - Landscape - Hardscape- Concrete Entire Site 1.750 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape- Asphalt Entire Site 1.750 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape- Asphalt Entire Site 1.375 SF 6 10+ years Damaged/Missing Trees Planting Bed/X Area Entire Site 1.375 SF 6 0-1 year Cracking and uneven areas. Surface - Asphalt West Courtyard 1.200 SF 4 0-1 yea | | Fencing - Chain Link | Entire Site | 166 | LF | 4 | 0-1 year | 5 |
| Fencing - New Standard Ornamental Fencing - Wood Fencing with Steel Frame Entire Site 175 LF 4 0-1 year Bent. Landscape 12 LF 4 0-1 year Missing, defected, and broken fence slats. Landscape Benches Entire Site 9 EA 6 10+ years Landscape - Grass Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape - Aghalt Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape - Aghalt Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape - Saphalt Entire Site 1,750 SF 4 0-1 year Cracking and uneven areas. Planting Bed/s Area Entire Site 1,275 SF 6 0-1 year Cracking and uneven areas. Surface - Asphalt Entire Site 12 EA 6 6-10 years Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 4 0-1 year Bending and missing pieces a | | | Entire Site | 92 | | 6 | 10+ years | • |
| Fencing - New Standard Ornamental Fencing - Wood Fencing w/ Steel Frame Entire Site 24 LF 4 0-1 year Bent. Landscape 12 LF 6 6-10 years Missing, defected, and broken fence slats. Landscape Benches Entire Site 9 EA 6 10+ years Missing, defected, and broken fence slats. Landscape -Grass Entire Site 9 EA 6 10+ years Landscape -Grass Entire Site 4,300 SF 4 0-1 year Cracking and holes throughout. Landscape - Hardscape - Asphalt Entire Site 1,750 SF 4 0-1 year Cracking and uneven areas. Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Damaged/Missing Trees Planting Beds/ Area Asphalt Entire Site 2 EA 6 -10 year Cracking and uneven areas. Surface - Concrete Entire Site 2 EA 6 6-10 years Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 4 0-1 year Bendi | | Fencing - New Standard Ornamental | Entire Site | 1,330 | | 6 | 10+ years | |
| Fencing Wood Fencing w/ Steel Frame Entire Site 12 LF 4 0-1 year Missing, defected, and broken fence slats. Landscape Benches Entire Site 9 EA 6 10+ years slats. Landscape - Grass Entire Site 4,300 SF 6 10+ years Cracking and holes throughout. Landscape - Hardscape - Asphalt Entire Site 1,750 SF 4 0-1 year Cracking and uneven areas. Planting Beds/Area Entire Site 1,750 SF 6 0-1 year Cracking and uneven areas. Planting Beds/Area Entire Site 1,375 SF 6 0-1 year Cracking and uneven areas. Planting Beds/Area Entire Site 1,375 SF 6 0-1 year Cracking and uneven areas. Surface - Asphalt Entire Site 1,200 SF 6 6-10 years Cracking and uneven areas. Planting I ot Vest Courtyard 1,200 SF 6 0-1 year Cracking and missing pieces at lowe portion of fencing. Surface - Concrete West Courtyard 1,200 SF 5 | | | Entire Site | 24 | LF | 4 | 0-1 year | Bent. |
| Fencing - Wood Fencing w/ Steel Frame Entire Site 12 LF 4 0-1 year Missing, defected, and broken fence slats. Landscape Benches Entire Site 9 EA 6 10+ years slats. Landscape - Grass Entire Site 4,300 SF 6 10+ years Cracking and holes throughout. Landscape - Hardscape - Asphalt Entire Site 1,770 SF 4 0-1 year Cracking and neven areas. Planting Bed/ Area Entire Site 1,770 SF 4 0-1 year Cracking and uneven areas. Planting Bed/ Area Entire Site 1,375 SF 6 10+ years Cracking and uneven areas. Planting Bed/ Area Entire Site 1,375 SF 6 0-1 year Cracking and uneven areas. Play Area - Hardscape - Asphalt Entire Site 2 EA 6 10+ years Cracking and uneven areas. Surface - Concrete West Courtyard 16,300 SF 4 0-1 year Cracking and missing pieces at lowe portion of fencing. Playground Image: Comparison of thercing Site 1 EA 6 </td <td></td> <td>Fencing - Wood Fencing w/ Steel Frame</td> <td>Entire Site</td> <td>175</td> <td>LF</td> <td>6</td> <td>6-10 years</td> <td></td> | | Fencing - Wood Fencing w/ Steel Frame | Entire Site | 175 | LF | 6 | 6-10 years | |
| Benches Entire Site 9 EA 6 10+ years Landscape - Grass Entire Site 4,300 SF 6 10+ years Landscape - Hardscape - Asphalt Entire Site 1,750 SF 4 0-1 year Landscape - Hardscape - Concrete Entire Site 4,170 SF 4 0-1 year Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Trash Receptacles Entire Site 2 EA 6 -0+ year Parking Lot 2 EA 6 -0+ year Damaged/Missing Trees Play Area - Asphalt West Courtyard 16,300 SF 4 0-1 year Surface - Asphalt West Courtyard 1,200 SF 6 6-10 years Trash Receptacles West Courtyard 1,200 SF 5 0-1 year Equipment - Combo 3-12 Entire Site 1 EA 6 10+ years | | | Entire Site | 12 | LF | 4 | 0-1 year | Missing, defected, and broken fence slats. |
| Landscape - Grass Entire Site 4,300 SF 6 10+ years Cracking and holes throughout. Landscape - Hardscape - Abradst Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Parkway trees Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Planting Beds/Area Entire Site 1,375 SF 6 10+ years Damaged/Missing Trees Play Area - Hardscape - Asphalt Entire Site 1,375 SF 4 0-1 year Cracking and holes throughout. Trash Receptacles Entire Site 1,375 SF 4 0-1 year Cracking. Parking Lot 2 EA 6 6-10 years Cracking and uneven areas. Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Entire Site 1 EA 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site | Landsca | ре | | | | | | |
| Landscape Hardscape Asphalt Entire Site 1,750 SF 4 0-1 year Cracking and holes throughout. Parkway trees Entire Site 15 EA 4 0-1 year Cracking and uneven areas. Planting Beds/ Area Entire Site 15 EA 4 0-1 year Cracking and uneven areas. Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Damaged/Missing Trees Play Area - Hardscape - Asphalt Entire Site 2 EA 6 6-10 years Cracking. | | Benches | Entire Site | 9 | EA | 6 | 10+ years | |
| Landscape - Hardscape - Karking and holes throughout. Landscape - Hardscape - Cracking and holes throughout. Parkway trees Entire Site 15 EA 4 0-1 year Cracking and holes throughout. Planting Beds/ Area Entire Site 15 EA 4 0-1 year Cracking and holes throughout. Play Area Hardscape- Asphalt Entire Site 1,375 SF 6 10+ year Damaged/Missing Trees Play Area - Hardscape- Asphalt Entire Site 2 EA 6 6-10 year Cracking and holes throughout. Trash Receptacles Entire Site 1,375 SF 4 0-1 year Cracking and holes throughout. Play Area - Hardscape- Asphalt Entire Site 2 EA 6 6-10 year Cracking. Trash Receptacles Entire Site 1,200 SF 4 0-1 year Cracking and noises ing pieces at lowe portion of fencing. Surface - Concrete West Courtyard 1,200 SF 5 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Entire Site 1 EA </td <td></td> <td>Landscape - Grass</td> <td>Entire Site</td> <td>4,300</td> <td>SF</td> <td>6</td> <td>10+ years</td> <td></td> | | Landscape - Grass | Entire Site | 4,300 | SF | 6 | 10+ years | |
| Landscape - Hardscape - Concrete Parkway trees Entire Site Entire Site 4,170 SF 4 0-1 year 0-1 year Cracking and uneven areas. Damaged/Missing Trees Planting Beds/ Area Play Area - Hardscape - Asphalt Entire Site 1,375 SF 6 10+ years Damaged/Missing Trees Play Area - Hardscape - Asphalt Entire Site 8,165 SF 4 0-1 year Cracking. Parking Lot 2 EA 6 6-10 years Cracking and uneven areas. Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Cracking and uneven areas. Trash Enclosure - Chain Links West Courtyard 1,200 SF 4 0-1 year Cracking and uneven areas. Playground Image Concrete West Courtyard 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Image Concrete Sidewalks - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. | | | Entire Site | 1,750 | SF | 4 | 0-1 year | Cracking and holes throughout. |
| Parkway trees Entire Site 15 EA 4 0-1 year Damaged/Missing Trees Planting Beds/ Area Entire Site 1,375 SF 6 104 years Cracking. Play Area - Hardscape-Asphalt Entire Site 1,375 SF 6 104 years Cracking. Play Area - Hardscape-Asphalt Entire Site 2 EA 6 6-10 years Cracking. Parking Lot 2 EA 6 6-10 years Cracking and uneven areas. Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. Playground 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Equipment - Combo 3-12 Entire Site 1 EA 6 10+ years Sidewalks Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site <t< td=""><td></td><td></td><td>Entire Site</td><td>4,170</td><td>SF</td><td>4</td><td></td><td></td></t<> | | | Entire Site | 4,170 | SF | 4 | | |
| Planting Beds/ Area Entire Site 1,375 SF 6 10+ years Play Area - Hardscape- Asphalt Entire Site 8,165 SF 4 0-1 year Cracking. Trash Receptacles Entire Site 2 EA 6 6-10 years Cracking and uneven areas. Parking Lot Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. Playground Equipment - Combo 3-12 Entire Site 1 EA 6 10+ years D-1 year Worn around edges and minor holes patched throughout. Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 1 EA 6 10+ years Cracked and uneven. Signage Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | | Parkway trees | Entire Site | 15 | EA | 4 | 0-1 year | Damaged/Missing Trees |
| Play Area - Hardscape - Asphalt Trash Receptacles Entire Site Entire Site Entire Site 8,165 2 SF EA 4 0-1 year 6 Cracking. -Parking Lot Surface - Asphalt Surface - Concrete West Courtyard 16,300 SF 4 0-1 year 6 Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 4 6 6-10 years Trash Enclosure - Chain Links West Courtyard 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. -Playground Equipment - Combo 3-12 Surface - Poured Surface Entire Site 1 EA 6 10+ years 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Perimeter Sidewalks Entire Site 11,120 SF 4 6 10+ years 0-1 year Cracked and uneven. Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | | Planting Beds/ Area | Entire Site | 1,375 | SF | 6 | 10+ years | 0 0 |
| Trash Receptacles Entire Site 2 EA 6 6-10 ýears Parking Lot Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. | | | Entire Site | | | 4 | | Cracking. |
| Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. Playground Image: Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Playground Image: Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Sidewalks Surface - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Cracked and uneven. Signage Signage Signage Signage Signage Signage Signage Signage | | | Entire Site | , | | 6 | | 5 |
| Surface - Asphalt West Courtyard 16,300 SF 4 0-1 year Cracking and uneven areas. Surface - Concrete West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. Playground Image: Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Playground Image: Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Surface - Poured Surface Entire Site 1 EA 6 10+ years Bending and missing pieces at lowe portion of fencing. Sidewalks Surface - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Cracked and uneven. Signage Signage Signage Signage Signage Signage Signage Signage | Parking | Lot | | | | | | |
| Surface - Concrete Trash Enclosure - Chain Links West Courtyard 1,200 SF 6 6-10 years Bending and missing pieces at lowe portion of fencing. Playground 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Equipment - Combo 3-12 Surface - Poured Surface Entire Site 1 EA 6 10+ years patched throughout. Sidewalks Perimeter Sidewalks Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 4 0-1 year Cracked and uneven. Signage Signage Signage Signage Signage Signage Signage Signage Signage | | | West Courtvard | 16.300 | SF | 4 | 0-1 vear | Cracking and uneven areas. |
| Trash Enclosure - Chain Links West Courtyard 1,200 SF 4 0-1 year Bending and missing pieces at lowe portion of fencing. Playground Equipment - Combo 3-12 Entire Site 1 EA 6 10+ years Surface - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Entire Site 11,120 SF 6 10+ years patched throughout. Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years patched and uneven. Signage Signage SF 4 0-1 year Cracked and uneven. | | | | | | | | |
| Equipment - Combo 3-12 Surface - Poured Surface Entire Site 1 EA 6 10+ years Sidewalks Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 4 0-1 year Cracked and uneven. | | | | | | | | Bending and missing pieces at lower portion of fencing. |
| Surface - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | _Playgrou | Ind | | | | | | |
| Surface - Poured Surface Entire Site 2,550 SF 5 0-1 year Worn around edges and minor holes patched throughout. Sidewalks Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | | Equipment - Combo 3-12 | Entire Site | 1 | EA | 6 | 10+ years | |
| Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | | Surface - Poured Surface | Entire Site | 2,550 | SF | 5 | 0-1 year | Worn around edges and minor holes patched throughout. |
| Sidewalks - Perimeter Sidewalks Entire Site 11,120 SF 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. | Sidewall | (5 | | | | | | |
| Sidewalks - Perimeter Sidewalks Entire Site 110 SF 4 0-1 year Cracked and uneven. _Signage | | Sidewalks - Perimeter Sidewalks | Entire Site | 11,120 | SF | 6 | 10+ years | |
| | | | | | | | | Cracked and uneven. |
| | Signage | | | | | | | |
| | _00_ | | North | 1 | EA | 6 | 10+ years | |



Category : Site Building : Site Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Marquee - Free Standing Back lighted w/ North ΕA 6 10+ years 1 LED Monument - Building Mounted Cut Letter North ΕA 6 10+ years 1 Sign

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|-------------------|-------------------|---------------|---------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | intended Usage | Room Eccation | Number | Number | | Αισα | Alea | 0.00 | Doard |
| Art Room | Regular Classroom | 3rd Floor | 303 | 303 | 890 | 160 | 20 | N | N |
| Computer Lab | Regular Classroom | 1st Floor | 105 | 105 | 715 | 160 | 20 | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 214 | 214 | 715 | 156 | 17 | N | N |
| Faculty Lounge | Regular Classroom | 3rd Floor | 305 | 305 | 715 | 160 | 20 | N | N |
| Office | Regular Classroom | 1st Floor | 102 | 102 | 715 | 160 | 20 | N | N |
| Office | Regular Classroom | 2nd Floor | 207 | 207 | 715 | 160 | 20 | N | N |
| Office | Regular Classroom | 3rd Floor | 302 | 302 | 715 | 160 | 20 | N | N |
| Pre School | Kindergarten | 1st Floor | 101 | 101 | 1,155 | 140 | 18 | N | N |
| Pre School | Kindergarten | 1st Floor | 103 | 103 | 1,155 | 140 | 18 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 106/108 | 106/108 | 1,430 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 880 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 114 | 114 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 116 | 116 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 890 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 890 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 890 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 715 | 160 | 20 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | 310 | 715 | 160 | 20 | N | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 314 | 314 | 715 | 160 | 20 | N | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 316 | 316 | 715 | 160 | 20 | N | Ν |
| Science | Regular Classroom | 3rd Floor | 304 | 304 | 715 | 160 | 20 | N | N |
| Store Room | Regular Classroom | 3rd Floor | 312 | 312 | 715 | 160 | 20 | N | N |
| Vacant | Regular Classroom | 1st Floor | 107 | 107 | 480 | 100 | 20 | N | N |