

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1969	2	52,968
Campus Total			52,968

Catego	ry : Exterior	В	uilding	: Main			
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	3						
	Entrance Control - Audio and Video	#1 - main entrance - W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#1 - main entrance - W	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 - main entrance - W	14	LF	4	1-2 years	Cracked concrete and deteriorating Stone
	Exterior Stairs - Stone	#1 - main entrance - W	9	LF	5	2-5 years	Cracked concrete and deteriorating Stone
	Stair Handrail - Steel_Stair Handrail	#1 - main entrance - W	8	LF	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#10 - NW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 - NW	10	LF	5	2-5 years	
	Exterior Stairs - Stone	#10 - NW	10	LF	5	6-10 years	Stone has some spalling
	Stair Handrail - Steel_Stair Handrail	#10 - NW	5	LF	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#2 - SW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 - SW	12	LF	5	6-10 years	
	Exterior Stairs - Stone	#2 - SW	10	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#2 - SW	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3 - SE	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - SE	1	EA	6	6-10 years	
	Ramps - Concrete	#4 - SE	5	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#5- SE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5- SE	12	LF	5	2-5 years	Cracked slab, failures at railing posts
	Exterior Stairs - Stone	#5- SE	10	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#5- SE	10	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	#6 - E	1	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#6 - E	1	EA	7	10+ years	
	Exterior Stairs - Concrete	#6 - E	18	LF	6	6-10 years	No cracks observed
	Exterior Stairs - Stone	#6 - E	3	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - E	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#7 - E	3	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#8 - NE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 - NE	3	LF	6	6-10 years	
	Exterior Stairs - Stone	#8 - NE	3	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#9 NE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9 NE	12	LF	5	1-2 years	Cracks in the concrete
	Exterior Stairs - Stone	#9 NE	9	LF	5	2-5 years	Stone is worn out
	Stair Handrail - Steel Stair Handrail	#9 NE	9 10	LF	5 7	•	
	—					10+ years	Ornamental
	Exterior Doors - Exterior Wood Door	#9.5 - NW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9.5 - NW	3	LF	5	10+ years	
oundati	ion						
	Foundation - Concrete	Entire Building	834	LF	7	10+ years	No exposed foundation
	Superstructure - Concrete	Entire Building	52,968	SF	7	10+ years	
ighting							
-igning	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	6-10 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	5	1-2 years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	5	2-5 years	
Roof Sys	stem						
,	Coping - Metal	Low E roof	15	LF	6	2-5 years	
	Downspouts - Interior Downspouts	Low E roof	12	LF	6	6-10 years	
	Roof - Modified Bitumen	Low E roof	778	SF	5	2-5 years	
	Roof Structure - Concrete	Low E roof	778	SF	7	10+ years	
	Coping - Metal	Low NE roof	6	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Low NE roof	1	LF	7	10+ years	
	Roof - Modified Bitumen	Low NE roof	300	SF	7	6-10 years	
	Roof Structure - Steel / Metal Deck/	Low NE roof	300	SF	7	10+ years	Corrected quantity
	Concrete Topping		000	01	,	for years	
	Coping - Metal	Low NW roof	56	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Low NW roof	12	LF	6	6-10 years	
	Roof - Modified Bitumen	Low NW roof	554	SF	6	6-10 years	
	Roof Structure - Concrete	Low NW roof	554	SF	7	10+ years	
	Chimney - Metal Flue	Low SE roof	20	LF	6	6-10 years	
	Chimney - Metal Flue	Low SE roof	15	LF	6	6-10 years	
	Chimney - Metal Flue	Low SE roof	20	LF	6	6-10 years	
					-		
	Coping - Metal	Low SE roof	56	LF	6	6-10 years	



							9811 S Lowe AVENUE, Chicago, IL 60628
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Low SE roof	520	SF	6	2-5 years	
	Roof Structure - Concrete	Low SE roof	520	SF	7	10+ years	
	Coping - Metal	Low SW roof	12	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Low SW roof	1	LF	6	10+ years	
	Roof - Modified Bitumen	Low SW roof	80	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low SW roof	80	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	5	2-5 years	
	Access Ladder - Metal	Main Roof	1	EA	5	2-5 years	Loose ladder
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	14	LF	6	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	23	LF	6	6-10 years	
	Coping - Metal	Main Roof	1,004	LF	6	2-5 years	
	Downspouts - Interior Downspouts	Main Roof	184	LF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	26,842	SF	4	1-2 years	Large soft spots throughout the roof. Engineer says that they are constantly new leaks springing
	Roof - Modified Bitumen	Main Roof	1,000	SF	2	0-1 year	soft spots with active leaks in the common areas
	Roof Hatch - Metal	Main Roof	2	EA	7	6-10 years	
	Roof Structure - Concrete	Main Roof	27,842	SF	7	6-10 years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	383	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	18,667	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	220	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Brick	Entire Building	200	SF	4	10+ years	Open joints and deteriorated mortar
	Exterior Walls - Precast Panel Wall	Entire Building	108	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	1,098	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	100	SF	5	10+ years	
	3						
	Curtain wall - Louver	Entire Building	108	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,166	SF	6	6-10 years	
	Lintels - Steel	Entire Building	1,242	LF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,590	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Shows sign of deterioration



Catego	ry : Electrical		R	uilding	• Main		9811 S Lowe AVENUE, Chicago, IL 606
Jaicgo				unung	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	5	2-5 years	
	Exit Signs - Gym	Entire Building	6	EA	5	2-5 years	
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	No generator
	Exit Signs - Lunchroom	Entire Building	1	EA	7	10+ years	Installed new in 2021 Per current
	5	5				,	observation
	Exit Signs - Lunchroom	Entire Building	1	EA	5	2-5 years	
	Emergency Battery Packs - Corridors and	Entire Building	22	EA	6	6-10 years	
	Stairs	C					
	Emergency Battery Packs - Gym	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	52,968	SF	7	6-10 years	Installed new in 2021
	Security System - Intrusion Detection	Entire Building	52,968	SF	5	2-5 years	Working but very old and can't be
		-					repaired
/lain Se	rvice						
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power					,	
	PA System	Entire Building	51,517	SF	6	6-10 years	
	Main Electrical Service - 1200 A	Entire Building	[′] 1	EA	4	1-2 years	Shows deteriorated
	120/208/3PH	-					
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	1-2 years	Shows deteriorating
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar		Entire Duilding		۲ ۸	^	0.40	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	51,517	SF	6	10+ years	
	Fire Alarm_System	Entire Building	51,517	SF	6	10+ years	



Building : Main Category : Mechanical Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Air Conditioning Condensing Unit- Roof Mounted - Less 1 ΕA 6 Roof 6-10 years than 5 tons Air Handling Systems Air Handling Unit-Package Single Zone-2nd Floor 1 ΕA 5 2-5 years Control needs to be adjusted Indoor- Hot Water Coils - 4000-8000 cfm Air Intake 2nd Floor 1 EΑ 6 10+ years 6 6-10 years Indoor Return Fans- Centrifugal Squirrel 2nd Floor EΑ 1 Cage - 5000 - 10000 CFM Boiler Systems Boiler Auxiliary- Condensing Hot Water -Boiler Room 1 ΕA 5 6-10 years Boiler is not working per current Less than 500 HP observation and needs to be fixed Flue is leaking Boiler Auxiliary- Condensing Hot Water -Boiler Room ΕA 5 10+ years Fixed per current observation and 1 Less than 500 HP working Chemical Pot Feeder Boiler Room EΑ 6 10+ vears 1 Condensing- Hot Water Boiler - Greater Boiler Room 2 FΑ 6 6-10 years Boiler-2 is not working per current 4000 MBH observation and needs to be fixed Flue is leaking Water Fill System Boiler Room 1 EΑ 6 6-10 years Gas Booster Boiler Room 2 ΕA 6 Gas Booster 6-10 years Heating Devices LF 5 Fin Tube - Hot Water Entire Building 120 6-10 years Cabinet Heaters - With Hot Water Coil Entire Building 12 FΑ 5 6-10 years Corrosion but working Mechanical Plumbing Hydronic Supply and Return - Steel Entire Building 400 LF 6 10+ years Hot Water Pump - 10 - 20 HP Mech. and Boiler Room 2 ΕA 6 10+ years Hot Water Pump - Less than 10 Mech. and Boiler Room ΕA 6 6-10 years 1 Temperature Control DDC System Entire Building 51.517 SF 6 6-10 years Electric Thermostat Entire Building 1 EΑ 7 6-10 years ΕA Thermostats - DDC Entire Building 33 6 6-10 years Unit Ventilation Unit Ventilators- Floor Mounted- Hot Water 39 ΕA 6 Entire Building 6-10 years Quantity change per current



Medgar Evers Elementary School 9811 S Lowe AVENUE, Chicago, IL 60628

Catego	ry : Mechanical		В	uilding	: Main		
j	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Heating Coils Only Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	1	EA	5	2-5 years	observation Valve leaking One unit moved here from original location
Ventilatio	n						
	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof Roof	1 1	EA EA	6 6	10+ years 10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	Per current observation Only 10 exhaust fans are on the roof
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Roof	1	EA	2	0-1 year	No fire suppression per current observation
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	52,968	SF	4	1-2 years	Pipes are Galvanized and leaking
	Domestic Piping-Hot Water Return Risers	Entire Building	52,968	SF	4	1-2 years	Pipes are Galvanized and leaking
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	52,968	SF	4	1-2 years	Pipes are Galvanized and leaking



Category : Plumbing Building : Main Recommend Group Location Replacement Item - Type Quantity UOM Rank Comments Domestic Piping-Hot/Cold Water Supply Pipes are Galvanized and leaking SF Entire Building 52,968 4 1-2 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 52,968 SF 1-2 years Pipes are Galvanized and leaking 4 (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 52,968 SF 4 1-2 years Pipes are Galvanized and leaking (from Risers to Fixtures) Sanitary Piping Entire Building 52,968 SF 6 6-10 years Storm Piping SF Entire Building 52,968 6 6-10 years Vent Piping Entire Building 52,968 SF 6 6-10 years Pumps Pumps - Domestic Booster Pump-Simplex Entire Building 1 ΕA 2 0-1 year Per current observation - not working per building engineer Original and can't fixed

Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	112 Assistant Principles Office	163	SF	6	10+ years	
	Doors - Wood Doors inclu hw	112 Assistant Principles Office	2	EA	6	10+ years	
	Floor - Tile	112 Assistant Principles Office	163	SF	6	10+ years	
	Lighting - Lay-in	112 Assistant Principles Office	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	112 Assistant Principles Office	1	EA	7	6-10 years	
	Power Distribution	112 Assistant Principles Office	6	EA	6	10+ years	
	Storage/ Closet	112 Assistant Principles Office	12	SF	7	10+ years	
	Walls - Concrete Block	112 Assistant Principles Office	842	SF	7	10+ years	
	Work SInk	112 Assistant Principles Office	1	EA	7	10+ years	
	AC Unit	1st - 110 teachers lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st - 110 teachers lounge	8	SF	7	6-10 years	Repaired
	Ceiling - Lay-in	1st - 110 teachers lounge	735	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 110 teachers lounge	1	EA	6	10+ years	
	Floor - Tile	1st - 110 teachers lounge	735	SF	6	10+ years	
	Lighting - Pendent/Surface	1st - 110 teachers lounge	16	EA	7	6-10 years	
	Power Distribution	1st - 110 teachers lounge	6	EA	6	10+ years	
	Walls - Concrete Block	1st - 110 teachers lounge	522	SF	7	10+ years	
	Walls - Metal Panel	1st - 110 teachers lounge	236	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st - 110 teachers lounge	171	SF	7	10+ years	
	AC Unit	1st - Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st - Main Office	451	SF	6	10+ years	
	Doors - Side-lite	1st - Main Office	38	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st - Main Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st - Main Office	1	EA	6	10+ years	
	Floor - Carpet	1st - Main Office	192	SF	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		
	• • • •					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st - Main Office	259	SF	6	10+ years	
	Lighting - Lay-in	1st - Main Office	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Main Office	1	EA	7	6-10 years	
	Power Distribution	1st - Main Office	12	EA	6	10+ years	
	Storage/ Closet	1st - Main Office	61	SF	7	10+ years	
	Walls - Concrete Block	1st - Main Office	936	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st - engineer inside boiler rm	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - engineer inside boiler rm	1	EA	6	10+ years	
	Floor - Tile	1st - engineer inside boiler rm	95	SF	6	10+ years	
	Lighting - Pendent/Surface	1st - engineer inside boiler rm	1	EA	7	6-10 years	
	Power Distribution	1st - engineer inside boiler rm	6	EA	6	10+ years	
	Storage/ Closet	1st - engineer inside boiler rm	12	SF	5	10+ years	
	Walls - Concrete Block	1st - engineer inside boiler rm	355	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st- Kitchen Office	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Kitchen Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Kitchen Office	32	SF	6	10+ years	
	Lighting - Pendent/Surface	1st- Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	1st- Kitchen Office	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- Kitchen Office	187	SF	6	10+ years	
	AC Unit	1st- Rm 125 Gym Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st- Rm 125 Gym Office	216	SF	6	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	1st- Rm 125 Gym Office	1	EA	6	10+ years	
	Floor - Carpet	1st- Rm 125 Gym Office	206	SF	6	6-10 years	-
	Floor - Carpet	1st- Rm 125 Gym Office	10	SF	4	0-1 year	Torn carpet
	Lighting - Lay-in	1st- Rm 125 Gym Office	4	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Rm 125 Gym Office	1	EA	6	6-10 years	
	Power Distribution	1st- Rm 125 Gym Office	8	EA	6	10+ years	
	Storage/ Closet	1st- Rm 125 Gym Office	39	SF	5	10+ years	
	Walls - Concrete Block	1st- Rm 125 Gym Office	489	SF	6	10+ years	
	AC Unit	2nd- Library office 2nd- Library office	1	EA SF	7 6	6-10 years	
	Ceiling - Lay-in Doors - Side-lite	2nd- Library office	143	SF	6 7	10+ years	
	Doors - Steel Doors incl hw	2nd- Library office	16 1	EA	6	10+ years 10+ years	
	Floor - Carpet	2nd- Library office	143	SF	6	,	
			143	EA	6 7	6-10 years	
	Lighting - Lay-in Power Distribution	2nd- Library office 2nd- Library office	4	EA	6	6-10 years 10+ years	
	Walls - Concrete Block	2nd- Library office	210	SF	7	•	
	Walls - Metal Panel	2nd- Library office	210	SF	7	10+ years	
	Work Sink	2nd- Library office	210	EA	7	10+ years 10+ years	
	Ceiling - Lay-in	2nd- Music Office Inside Rm #223	143	SF	6	10+ years	
	Doors - Side-lite	2nd- Music Office Inside Rm #223	143	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd- Music Office Inside Rm #223	10	EA	5	1-2 years	
	Floor - Carpet	2nd- Music Office Inside Rm #223	143	SF	6	6-10 years	
	Lighting - Lay-in	2nd- Music Office Inside Rm #223	2	EA	7	6-10 years	
			2	LA	'	o io years	



					84.1		9811 S Lowe AVENUE, Chicago, IL 60628
Catego	ry : Room		В	uilding	: Main	_	
•			•		- ·	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	2nd- Music Office Inside Rm #223	6	EA	6	10+ years	
	Walls - Concrete Block	2nd- Music Office Inside Rm #223	210	SF	7	10+ years	
	Walls - Metal Panel	2nd- Music Office Inside Rm #223	210	SF	7	10+ years	
	Ceiling - Lay-in	2nd- Teachers Lounge	258	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd- Teachers Lounge	2	EA	6	10+ years	
	Floor - Tile	2nd- Teachers Lounge	256	SF	6	10+ years	
	Floor - Tile	2nd- Teachers Lounge	2	SF	5	1-2 years	Chipped tiles
	Lighting - Lay-in	2nd- Teachers Lounge	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd- Teachers Lounge	4	EA	7	6-10 years	
	Power Distribution	2nd- Teachers Lounge	4	EA	7	10+ years	
	Walls - Concrete Block	2nd- Teachers Lounge	529	SF	7	10+ years	
	AC Unit	Principals Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principals Office	167	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principals Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Principals Office	167	SF	7	10+ years	
	Lighting - Lay-in	Principals Office	5	EA	7	6-10 years	
	Power Distribution	Principals Office	16	EA	6	10+ years	
	Walls - Concrete Block	Principals Office	669	SF	7	10+ years	
_Gymnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	4,315	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile	1st Floor	4,390	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	38	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	9	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	1	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	477	SF	7	10+ years	
	Stage Curtain	1st Floor	4	ĒA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	10	LF	7	10+ years	
	Storage/ Closet	1st Floor	338	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,359	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,359	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	647	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	647	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Serving Line	1st Floor	20	LF	6	10+ years	
	Storage/ Closet	1st Floor	87	SF	5	10+ years	
	Walls - Structural Glazed Tile	1st Floor	867	SF	6	10+ years	
			007	0	0	ior yours	



Medgar Evers Elementary School 9811 S Lowe AVENUE, Chicago, IL 60628

Catego	ry : Room		В	uilding	: Main		
-				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library							
,	AC Unit	2nd- Library	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd- Library	2,118	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd- Library	2	EA	6	10+ years	
	Floor - Carpet	2nd- Library	2,118	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd- Library	26	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd- Library	1	EA	6	6-10 years	
	Storage/ Closet	2nd- Library	149	SF	5	10+ years	
	Walls - Concrete Block	2nd- Library	1,815	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,102	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	2,184	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	36	EA	7	6-10 years	
	Serving Line	1st Floor	6	LF	7	10+ years	
	Storage/ Closet	1st Floor	209	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,649	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	2nd - inside storage room	1	EA	6	10+ years	
	Finishes	2nd - inside storage room	541	SF	7	10+ years	
	Other Cooling Unit	2nd - inside storage room	1	EA	7	6-10 years	Ductless split
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	825	SF	5	10+ years	
	Janitor's Closet	1st Floor	46	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	179	SF	5	10+ years	
	Storage Room	1st Floor	237	SF	5	10+ years	
	Storage Room	1st Floor	58	SF	5	10+ years	
	Vaults	1st Floor	61	SF	5	10+ years	
	Janitor's Closet	2nd Floor	58	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	547	SF	5	10+ years	
	Storage Room	2nd Floor	231	SF	5	10+ years	
	Vaults	2nd Floor	228	SF	5	10+ years	Unable to access, similar to first floor
Restroor	n						
	Accessories	1st - inside 112	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside 112	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 112	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - inside 112	38	SF	6	10+ years	
					-		



Catego	ry : Room		B	uilding	: Main		
Ŭ				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting - Lay-in	1st - inside 112	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st - inside 112	1	EA	7	6-10 years	
	Walls - Concrete Block	1st - inside 112	192	SF	6	10+ years	
	Water Closet	1st - inside 112	1	EA	6	10+ years	
	Accessories	1st - inside Main Office	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside Main Office	43	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - inside Main Office	43	SF	6	10+ years	
	Lavatory	1st - inside Main Office	1	EA	6	10+ years	
	Lighting - Lay-in	1st - inside Main Office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st - inside Main Office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st - inside Main Office	211	SF	7	10+ years	
	Water Closet	1st - inside Main Office	1	EA	6	10+ years	
	Accessories	1st - inside engineer office	39	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside engineer office	39	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside engineer office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - inside engineer office	39	SF	6	10+ years	
	Lavatory	1st - inside engineer office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st - inside engineer office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st - inside engineer office	1	EA	6	6-10 years	
	Walls - Concrete Block	1st - inside engineer office	235	SF	7	10+ years	
	Water Closet	1st - inside engineer office	1	EA	6	10+ years	
	Accessories	1st Floor	294	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	294	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	294	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	5	6-10 years	
	Urinals	1st Floor	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	682	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	6	10+ years	
	Accessories	1st Floor	257	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	257	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	257	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	



Catago	ry : Room		D	uilding	Main		9811 S Lowe AVENUE, Chicago, IL 60628
Calego			D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Partitions	1st Floor	Quantity	EA	5	6-10 years	Repaired
	Partitions	1st Floor	6	EA	5	6-10 years	Repaired
	Walls - Structural Glazed Tile	1st Floor	564	SF	6	10+ years	
	Water Closet	1st Floor	7	EA	6	10+ years	
	Accessories	1st- Inside Rm 104	3	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Rm 104	29	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 104	-0	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Inside Rm 104	29	SF	6	10+ years	
	Lavatory	1st- Inside Rm 104	1	ĒA	6	10+ years	
	Lighting - Pendent/Surface	1st- Inside Rm 104	1	EA	7	10+ years	
	Walls - Concrete Block	1st- Inside Rm 104	188	SF	6	10+ years	
	Water Closet	1st- Inside Rm 104	1	EA	6	10+ years	
	Accessories	1st- Inside Rm 106	5	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Rm 106	29	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 106	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Inside Rm 106	29	SF	6	10+ years	
	Lavatory	1st- Inside Rm 106	1	ĒA	6	10+ years	
	Lighting - Pendent/Surface	1st- Inside Rm 106	1	EA	6	6-10 years	Dim
	Walls - Concrete Block	1st- Inside Rm 106	188	SF	6	10+ years	
	Water Closet	1st- Inside Rm 106	1	ĒA	6	10+ years	
	Accessories	1st- Kitchen Staff Toilet	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Kitchen Staff Toilet	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Kitchen Staff Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Kitchen Staff Toilet	32	SF	6	10+ years	
	Lavatory	1st- Kitchen Staff Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st- Kitchen Staff Toilet	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Kitchen Staff Toilet	1	EA	7	6-10 years	
	Partitions	1st- Kitchen Staff Toilet	1	EA	5	6-10 years	Repaired
	Walls - Structural Glazed Tile	1st- Kitchen Staff Toilet	187	SF	6	10+ years	
	Water Closet	1st- Kitchen Staff Toilet	1	EA	6	10+ years	
	Accessories	1st- Off Multi-Purpose	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Off Multi-Purpose	55	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st- Off Multi-Purpose	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Off Multi-Purpose	55	SF	6	10+ years	
	Floor Drain	1st- Off Multi-Purpose	1	EA	7	10+ years	
	Lavatory	1st- Off Multi-Purpose	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st- Off Multi-Purpose	3	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Off Multi-Purpose	1	EA	7	6-10 years	
	Partitions	1st- Off Multi-Purpose	1	EA	5	6-10 years	
	Showers	1st- Off Multi-Purpose	1	EA	7	10+ years	
	Walls - Concrete Block	1st- Off Multi-Purpose	255	SF	7	10+ years	
	Water Closet	1st- Off Multi-Purpose	1	EA	6	10+ years	
	Accessories	1st- Women's	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Women's	53	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st- Women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- Women's	53	SF	6	10+ years	
	Lavatory	1st- Women's	1	EA	6	10+ years	
	Lighting - Lay-in	1st- Women's	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- Women's	1	EA	7	6-10 years	
	Partitions	1st- Women's	2	EA	5	2-5 years	
	Walls - Concrete Block	1st- Women's	232	SF	6	10+ years	
	Water Closet	1st- Women's	2	EA	6	10+ years	
	Accessories	1st- all gender	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- all gender	49	SF	6	10+ years	
	Doors - Store Front	1st- all gender	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st- all gender	49	SF	6	10+ years	
	Lavatory	1st- all gender	1	EA	6	10+ years	
	Lighting - Lay-in	1st- all gender	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st- all gender	1	EA	7	6-10 years	
	Partitions	1st- all gender	1	EA	5	2-5 years	
	Urinals	1st- all gender	1	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st- all gender	232	SF	6	10+ years	
	Water Closet	1st- all gender	1	EA	6	10+ years	
	Accessories	2nd Floor	257	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	257	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	257	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	7	EA	5	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	564	SF	6	10+ years	
	Water Closet	2nd Floor	7	EA	6	10+ years	
	Accessories	2nd Floor	294	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	294	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	• • • · · ·
	Floor - Tile	2nd Floor	4	SF	5	1-2 years	Missing tiles
	Floor - Tile Ceramic/ Porcelain	2nd Floor	290	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	5	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	5	6-10 years	
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	676	SF	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Structural Glazed Tile SF 2nd Floor 6 5 1-2 years Grout damged Water Closet 2nd Floor 3 ΕA 6 10+ years Accessories 2nd- Unisex 49 SF 7 6-10 years Ceiling - Plaster/Drywall 49 SF 2nd- Unisex 6 10+ years **Doors - Store Front** 2nd- Unisex 1 EΑ 6 10+ years SF Floor - Tile Ceramic/ Porcelain 49 2nd- Unisex 6 10+ years 2nd- Unisex ΕA 6 10+ years Lavatory 1 Lighting - Lay-in 2nd- Unisex 1 ΕA 7 6-10 years Lighting - Wall Mounted 2nd- Unisex 1 ΕA 7 6-10 years Partitions 2nd- Unisex FΑ 5 6-10 years Updated to match current 1 observations Urinals 2nd- Unisex 1 ΕA 6 10+ years Walls - Structural Glazed Tile 2nd- Unisex 232 SF 7 10+ years Water Closet 2nd- Unisex EΑ 6 10+ years 1 SF Accessories 2nd- Women's Inside Teacher's 81 7 6-10 years Lounge 2nd- Women's Inside Teacher's SF Ceiling - Plaster/Drywall 81 6 10+ years Lounae Doors - Wood Doors inclu hw 2nd- Women's Inside Teacher's ΕA 6 1 10+ years Lounge Floor - Tile Ceramic/ Porcelain 2nd- Women's Inside Teacher's 81 SF 6 10+ years Lounge 2nd- Women's Inside Teacher's Lavatory 1 EΑ 6 10+ years Lounae Lighting - Lay-in 2nd- Women's Inside Teacher's ΕA 1 6 6-10 years Dim Lounae 2nd- Women's Inside Teacher's Lighting - Wall Mounted EΑ 7 6-10 years 1 Lounge 2nd- Women's Inside Teacher's Partitions 2 ΕA 7 10+ years Lounge Walls - Concrete Block 2nd- Women's Inside Teacher's SF 292 7 10+ years Lounae 2nd- Women's Inside Teacher's Water Closet 2 FΑ 6 10+ years Lounge

Category : Classroom

Building : Main

			manig			
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #100 (Science Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	75	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	986	SF	7	10+ years	
Ceiling - Lay-in	1st Floor	24	SF	5	1-2 years	Water damage
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	



•							9811 S Lowe AVENUE, Chicago, IL 60628
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,010	SF	7	10+ years	
	Gas Line	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,208	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #104 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,008	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,010	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,272	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	m #106 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,010	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,010	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	ĒA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,272	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #108 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	722	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
			0		•	101 90010	



Catego	ry : Classroom		B	uilding	: Main		
	-			3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
laseroo	m #114 - Work room (Office)						
21233100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	342	SF	6	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	342	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	•	
	Student Lockers - One Tier		2	EA		6-10 years	
		1st Floor		SF	6 7	10+ years	
	Walls - Concrete Block	1st Floor	669	55	/	10+ years	
lassroo	m #116 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	710	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	6	SF	5	2-5 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	5
	Floor - Tile	1st Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	782	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	24	SF	6	10+ years	
laceroo	m #118 (Regular Classroom)						
1455100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	736	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile		-	SF	-	•	
		1st Floor	736		6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	586	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	234	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	m #120 (Regular Classroom)						
lassroc			1	EA	7	6-10 years	
lassroc	AC Units	1st Floor	I				
Classroo		1st Floor 1st Floor	20	LF	6		
Classroc	AC Units					10+ years 10+ years	



XIII I							9811 S Lowe AVENUE, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	741	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	587	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	234	SF	7	10+ years	
Classroo	om #121 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	810	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	810	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	652	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	249	SF	7	10+ years	
						-	
Classroo	om #123 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	670	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	670	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	652	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	249	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	50	EA	6	10+ years	
	Student LUCKEIS - OHE HEI		0	EA	0	io- years	



atego	ry : Classroom		В	uilding	: Main		
-	-			5		Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	6	10+ years	
lassroc	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	6	10+ years	
	Casework	2nd Floor	3	LF	6	1-2 years	Casework finish damaged
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	5
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒA	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	949	SF	6	10+ years	
lassroc	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	731	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	Water damage
	Floor - Tile	2nd Floor	737	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	50	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	811	SF	6	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	24	SF	6	10+ years	
		2110 1 1001	24	0	0	TOF years	
assroo	m #203 (Vacant)			F A			
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	949	SF	7	10+ years	
assroo	m #204 / 206 (Computer Lab)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,448	SF	6	10+ years	



· ·	Schools						9811 S Lowe AVENUE, Chicago, IL 6062
Catego	tegory : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,464	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	12	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,168	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	48	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	715	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Water damage
	Floor - Tile	2nd Floor	731	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board			LF	7	-	
		2nd Floor	36			6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	801	SF SF	7 7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	5F	1	10+ years	
lassroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	737	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	737	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	794	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	7	10+ years	
lassroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	737	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	737	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	36	LF	7	10+ years	
	Mariler Doard	21011001	50	L1	ı	ior years	



Catego	ry : Classroom		В	uilding	: Main		
J				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	802	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	7	10+ years	
	Wallo T lactor, Drywall		21	0.	,	lot youro	
lassroc	m #214 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	733	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	733	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	805	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	19	SF	6	10+ years	
lassroo	m #216 (Regular Classroom)						
7/200100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	716	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	716	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	785	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	SF	7	10+ years	
Classroo	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	739	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	739	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	568	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	238	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
)laseroc	m #220 (Regular Classroom)						
1000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	



XIN S	chools						9811 S Lowe AVENUE, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	622	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	622	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	596	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	238	SF	7	10+ years	
Classroo	m #221 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	69	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,084	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	5
	Floor - Tile	2nd Floor	1,090	SF	6	10+ years	
	Instructional Surface	2nd Floor	4	LF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Sound System	2nd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,200	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	5	10+ years	
lassroo	m #222 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	717	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	717	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	20	EA			
			-	SF	6	10+ years	
	Walls - Concrete Block	2nd Floor	798 24	SF SF	7 7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	24	55	/	10+ years	
atego	ry : Interior		В	uilding	: Main		
Broup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,604	SF	6	10+ years	
			-,				
	Ceiling - Plaster/Drywall	1st Floor	782	SF	6	10+ years	



Building : Main Category : Interior Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Drinking Fountains - Single Fountain 1st Floor 4 ΕA 6-10 vears 7 Floor - Terrazzo 1st Floor 150 SF 7 10+ years Floor - Terrazzo 1st Floor 150 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 390 SF 6 1st Floor 10+ years SF 7 Floor - Tile/Sheet 1st Floor 3,884 10+ years ΕA 7 Lighting - Lay-in 1st Floor 51 6-10 years Lighting - Pendent/Surface 1st Floor ΕA 7 6-10 years 3 Lighting - Wall Mounted 1st Floor 4 ΕA 7 6-10 years Student Lockers - Two Tiers 1st Floor 40 ΕA 6 10+ years SF Walls - Concrete Block 1st Floor 1.797 6 10+ years SF Walls - Structural Glazed Tile 1st Floor 5.625 6 10+ vears Ceiling - Lay-in 2nd Floor 3.442 SF 6 10+ years Ceiling - Lay-in 2nd Floor SF 5 1-2 years 6 Water damage 7 Drinking Fountains - Single Fountain ΕA 2nd Floor 4 10+ years Floor - Terrazzo 240 SF 2nd Floor 6 10+ years Floor - Tile/Sheet SF 7 2nd Floor 3.448 10+ years ΕA 7 Lighting - Lay-in 2nd Floor 64 6-10 years Student Lockers - Two Tiers 2nd Floor 136 EΑ 6 10+ years SF Walls - Concrete Block 2nd Floor 1.656 6 10+ vears SF Walls - Structural Glazed Tile 2nd Floor 4 6 10+ years Grout falling out Walls - Structural Glazed Tile 2nd Floor 3.358 SF 6 10+ years Safetv **Camera Viewing Station** Entire Building 1 ΕA 7 10+ vears Security Cameras Entire Building 8 ΕA 7 6-10 years Stairs North East 206 SF 6 Ceiling - Lay-in 10+ years Floor - Terrazzo North East 77 SF 6 10+ years LF 7 Handrails North East 52 10+ years 3 ΕA 7 Lighting - Lay-in North East 6-10 years LF Stairs - Terrazzo North East 18 6 10+ years Walls - Concrete Block SF 6 North East 488 10+ years Walls - Structural Glazed Tile North East 240 SF 6 10+ years Ceiling - Lay-in North West 206 SF 6 10+ vears Floor - Terrazzo SF North West 77 6 10+ years North West LF 7 Handrails 52 10+ vears Lighting - Lay-in North West 3 FΑ 6 6-10 years Stairs - Terrazzo 18 LF 6 North West 10+ years SF 6 Walls - Concrete Block North West 488 10+ years SF Walls - Structural Glazed Tile North West 240 6 10+ years Ceiling - Lay-in South East 206 SF 6 10+ years SF Floor - Terrazzo South East 77 6 10+ years Handrails South East 52 LF 7 10+ years



Building : Main Category : Interior Recommend UOM Location Group Item - Type Quantity Rank **Replacement** Comments Lighting - Lay-in 6-10 years South East 3 ΕA 7 Stairs - Terrazzo South East 18 LF 6 10+ years SF 10+ years Walls - Concrete Block South East 488 6 Walls - Structural Glazed Tile South East 240 SF 6 10+ years SF South West 206 6 Ceiling - Lay-in 10+ years Floor - Terrazzo South West SF 77 6 10+ years Handrails South West 52 LF 7 10+ years Lighting - Lay-in South West 3 ΕA 7 6-10 years Stairs - Terrazzo South West 18 LF 6 10+ years Walls - Concrete Block South West 488 SF 6 10+ years Walls - Structural Glazed Tile South West SF 10+ years 240 6



Catego	ry : Site	B	uilding	: Site			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	7	10+ years	
Fencing							
	Fencing - Chain Link	East	30	LF	6	10+ years	Not previously assessed
	Fencing - New Standard Ornamental	East	613	LF	6	2-5 years	
andsca							
_unused	Benches	Entire Site	4	EA	7	10+ years	New benches near playground
	Landscape - Grass	Entire Site	8,893	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	1,400	SF	7	10+ years	
	Parkway trees	Entire Site	21	EA	6	6-10 years	
	Planting Beds/ Area	Entire Site	300	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	8,000	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	6,221	SF	5	2-5 years	Cracking, potholes
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	oracking, politoles
			0	L /(Ū	o ro youro	
Parking I							
	Surface - Asphalt	SE site	10,353	SF	4	1-2 years	Alligatored surface throughout, potholes throughout, asphalt is beginning to disintegrate
	Trash Enclosure - Chain Links	SE site	515	SF	6	6-10 years	
Playgrou	nd						
,,,	Equipment - Pre K 3-5	NE site	1	EA	7	10+ years	New
	Equipment - School Age 5-12	NE site	1	EA	7	10+ years	New
	Surface - Poured Surface	NE site	2,219	SF	7	10+ years	New
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	45	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	15	LF	5	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,209	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	175	SF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	196	SF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	4	SF	4	0-1 year	Damaged, cracked
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	



Catego	ry : Site		В	uilding	: Site			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	·		•			•		•	
Computer Lab	Regular Classroom	2nd Floor	204 / 206	204 / 206	1,464	320	160	N	Y
Kindergarten	Regular Classroom	1st Floor	123	123	670	91	35	N	N
Music Room	Art Room	2nd Floor	221	221	1,090	84	28	N	N
Office	Regular Classroom	1st Floor	108	108	716	160	80	N	N
Office	Regular Classroom	2nd Floor	222	222	717	160	80	N	N
Office	Special Education	1st Floor	114 - Work	114	342	52	26	N	N
			room						
Pre School	Kindergarten	1st Floor	104	104	1,010	147	63	N	N
Pre School	Kindergarten	1st Floor	106	106	1,010	147	63	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	716	160	80	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	736	160	80	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	741	160	80	N	N
Regular Classroom	Regular Classroom	1st Floor	121	121	810	105	49	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	735	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	98	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	737	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	731	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	737	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	737	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	716	160	80	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	739	160	80	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	220	220	622	160	80	N	Ν
Science Classroom	Science	1st Floor	100	100	1,010	147	63	N	Ν
Store Room	Regular Classroom	2nd Floor	214	214	733	160	80	N	Y
Vacant	Regular Classroom	2nd Floor	203	203	720	98	42	N	Ν