

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1974	3	42,300
Campus Total			42,300

Category: Exterior **Building: Main** Recommend Replacement Item - Type Location Quantity **UOM** Rank Comments Group Entrance Entrance Control - Audio and Video EΑ 7 1 main 1 6-10 years Exterior Doors - Exterior Wood Door 1 main 3 EΑ 6 6-10 years Exterior Doors - Transom Lite FΑ 6 6-10 years 1 main 1 Exterior Doors - Exterior Wood Door FΑ 6-10 years 2 1 6 Exterior Doors - Exterior Steel Door 3 EΑ 6 6-10 years 1 Exterior Doors - Exterior Wood Door 4 1 EΑ 4 0-1 year Delaminating, warped Exterior Doors - Exterior Steel Door 4.5 - South 2 5 EΑ 2-5 years 2 Exterior Doors - Exterior Steel Door 5 EΑ 6 10+ years Exterior Doors - Transom Lite 5 EΑ 6 10+ years Exterior Doors - Exterior Wood Door 6 south 3 FΑ 6 6-10 years LF 5 Exterior Stairs - Concrete 6 south 10 0-1 vear Large crack Exterior Doors - Exterior Steel Door 7 FΑ 6 10+ years 1 2 Exterior Doors - Side lite 7 FΑ 5 0-1 vear Rusting frames. 5 Exterior Doors - Transom Lite 7 1 FΑ 0-1 year Rusting frames. Exterior Doors - Exterior Steel Door 8 1 EΑ 6 10+ years Exterior Doors - Side lite 8 2 EΑ 5 0-1 year Rusting frames. Exterior Doors - Transom Lite EΑ 5 0-1 year Rusting frames. Exterior Doors - Exterior Steel Door West roof entrance EΑ 5 0-1 year Rusting. Foundation Foundation - Concrete LF **Entire Building** 575 7 10+ years **Entire Building** SF 7 Superstructure - Concrete 575 10+ years



Category : Exterior		В	uilding				
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	2-5 years	
oof Sys	etem						
COI Cy.	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	210	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	30	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	210	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	3,100	SF	4	0-1 year	Bubbling, cracks throughout
	Roof Hatch - Metal	Main Roof	1	EA	5	10+ years	Missing handle
	Roof Structure - Steel / Metal Deck/	Main Roof	3,100	SF	7	10+ years	ga.ia.
	Concrete Topping	Wall Roof	0,100	O.	•	ioi youro	
	Coping - Metal	Main South west	70	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main South west	20	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main South west	70	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Main South west	600	SF	4	0-1 year	Cracks and patches throughout.
	Roof Structure - Concrete	Main South west	600	SF	7	10+ years	eracite and paterios amongrious
	Coping - Metal	Main West	230	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main West	20	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main West	230	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Main West	4,500	SF	4	0-1 year	Cracks and patches throughout.
	Roof Structure - Concrete	Main West	4,500	SF	7	10+ years	orache and pateries uneughout
	Chimney - Metal Flue	North	30	LF	6	10+ years	
	Coping - Metal	North	75	LF	7	10+ years	
	Downspouts - Interior Downspouts	North	20	LF	7	10+ years	
	Parapet - Parapet < 16" Height	North	75	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	North	900	SF	4	0-1 year	Vegetation, cracks, and bubbling
	Roof Structure - Steel / Metal Deck/	North	900	SF	7	10+ years	
	Concrete Topping					, , , , , ,	
alls							
ans	Exterior Walls - Brick	Entire Building	14,718	SF	6	10+ years	
		-				-	
'indows							
	Guard - Guards wire guard	Entire Building	756	SF	6	10+ years	
	Skylite - Lexan	Entire Building	16	SF	5	0-1 year	Leaks
	Windows - Casement Lexan	Entire Building	2,862	SF	4	0-1 year	Leaks, corrosion, cracks.
	Windows - Louver	Entire Building	360	SF	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Main		
		1 and the	0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	0-1 year	Non functional.
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,000	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	4,500	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,000	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	7	6-10 years	
	Security System - CCTV	Entire Building	42,300	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	42,300	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	Old and broken in letters.
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	2	0-1 year	No battery backup
	Exit Signs - Gym	Entire Building	3	EA	7	6-10 years	. 10 Dation, backap
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	
	-	Entire Ballating	· ·	_, .	,	o ro youro	
Main Se	rvice Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	6	6-10 years	
	120/208/3PH Independent Electrical Service for	Electrical Room	1	EA		•	
	emergency power				7	10+ years	
	PA System	Entire Building	42,300	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	4	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	42,300	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	42,300	SF	7	6-10 years	
•	- •	g	•			5 .5 youro	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Itam Tuna	Location	Quantity	HOM	Donk	Recommend	Comments
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•							
•	lling Systems Air Handling Unit- Package Single Zone-	Mechanical Room		EA	6		

Page : 3 of 21




Catego	ry : Mechanical		В	uilding	: Main		0 3 30util Shore DRIVE, Chicago, ic 00048
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Electric Coil - 4000-8000 cfm						
	Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	Serves the lunchroom.
	Indoor- Electric Coil - 4000-8000 cfm	Machaniaal Daam	0	_^	0	40	
	Air Intake	Mechanical Room	2	EA EA	6 5	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained	Roof	I	EA	5	6-10 years	
	Compressor - 11 - 20 tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	6-10 years	
	DX Cooling Only with Self Contained	11001		_/\	Ü	o ro youro	
	Compressor - 5 - 10 tons						
Heating		Fasting Desilyting	40	Ε.Δ.		40	
	Wall Heater - Electric Wall Heater - Electric	Entire Building Entire Building	12 7	EA EA	6 6	10+ years 6-10 years	
	Wall Heater - Electric	Entire Building Entire Building	1	EA	4	•	Old and missing cover
	PTAC - Electric Heating and Self Contained	Main Office	1	EA	6	0-1 year 6-10 years	Old and missing cover.
	Cooling	Mail Office	1	LA	U	0-10 years	
	PTAC - Electric Heating and Self Contained	Main Office	1	EA	6	6-10 years	
	Cooling					5 . 5 , 5 5	
11 4 7	et e						
Unit Ven	Unit Ventilators- Floor Mounted- Electric	Entine Duilding	25	Ε,		4.0.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Come alaceración amb con to ba
	Heating & DX Cooling Coil W/ Self	Entire Building	25	EA	4	1-2 years	Some classrooms appear to be unused and in disarray.
	Contained Compressor						unused and in disarray.
	Contained Compressor						
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	
	CFM	Entire Building	4	ГΛ	6	6.10 , , , , , , , ,	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	5	0-1 year	Damage to top of exhaust fans.
	CFM	Entire Building	2	LA	5	0-1 year	Damage to top of exhaust fails.
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years	
	CFM	Entire Building	2	L/\	O	o to years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6-10 years	
	CFM	9	•	 - ·	•	2 . 2 , 2	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	7	6-10 years	
	500 CFM	ŭ				•	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
	•	<u>-</u>				•	



Catego	ry : Plumbing		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	2	EA	4	0-1 year	Does not work.
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	42,300	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	42,300	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,300	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,300	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,300	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	42,300	SF	7	10+ years	
	Sanitary Piping	Entire Building	42,300	SF	7	10+ years	
	Storm Piping	Entire Building	42,300	SF	7	10+ years	
	Vent Piping	Entire Building	42,300	SF	6	10+ years	
Pumps							
•	Pumps - Sump-Simplex	Entire Building	1	EA	7	10+ years	The pump is the elevator pit.

Category: Room **Building: Main**

	-				D 1	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	102 Executive Director	213	SF	7	10+ years	
	Ceiling - Lay-in	102 Executive Director	32	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	102 Executive Director	1	EA	7	10+ years	
	Floor - Carpet	102 Executive Director	245	SF	6	6-10 years	
	Lighting - Lay-in	102 Executive Director	6	EA	7	6-10 years	
	Power Distribution	102 Executive Director	6	EA	7	10+ years	
	Walls - Concrete Block	102 Executive Director	578	SF	7	10+ years	
	Ceiling - Lay-in	112 Gymnasium Office	208	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	112 Gymnasium Office	2	EA	7	10+ years	
	Floor - Tile	112 Gymnasium Office	208	SF	7	10+ years	
	Lighting - Lay-in	112 Gymnasium Office	2	EA	7	6-10 years	
	Power Distribution	112 Gymnasium Office	6	EA	7	10+ years	
	Storage/ Closet	112 Gymnasium Office	38	SF	5	10+ years	Falling light and ceiling tiles.
	Walls - Concrete Block	112 Gymnasium Office	690	SF	7	10+ years	
	Ceiling - Lay-in	121 Engineer's Office	151	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	121 Engineer's Office	1	EA	7	10+ years	
	Floor - Carpet	121 Engineer's Office	151	SF	4	0-1 year	Torn and stains throughout
	Lighting - Lay-in	121 Engineer's Office	2	EA	7	10+ years	-
	C C ,	Ç				•	





Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution 121 Engineer's Office 4 EΑ 10+ years 7 Storage/ Closet 121 Engineer's Office 25 SF 5 10+ years Walls - Concrete Block 121 Engineer's Office 585 SF 7 10+ years Kitchen Office 133 85 SF 7 Ceiling - Plaster/Drywall 10+ years SF Doors - Side-lite Kitchen Office 133 9 7 10+ years Doors - Wood Doors inclu hw 7 Kitchen Office 133 1 EΑ 10+ years Floor - Tile Kitchen Office 133 85 SF 10+ years 6 Lighting - Pendent/Surface Kitchen Office 133 1 EΑ 7 6-10 years Power Distribution Kitchen Office 133 4 EΑ 7 10+ years SF Storage/ Closet Kitchen Office 133 16 7 10+ years Walls - Concrete Block SF Kitchen Office 133 315 7 10+ years Ceiling - Lav-in Library Conference Room 214 129 SF 6 10+ years Doors - Wood Doors inclu hw Library Conference Room 214 EΑ 6 10+ years 1 Library Conference Room 214 SF 6 Floor - Carpet 129 6-10 years Library Conference Room 214 EΑ 7 6-10 years Lighting - Lay-in 4 Power Distribution Library Conference Room 214 9 FΑ 7 10+ years Library Conference Room 214 SF 7 Walls - Concrete Block 418 10+ years SF Ceiling - Lay-in Main Office 145 587 6 10+ years SF Ceiling - Lav-in Main Office 145 32 4 0-1 vear Water damage Doors - Wood Doors inclu hw 7 Main Office 145 2 EΑ 10+ years Floor - Carpet Main Office 145 571 SF 6 6-10 years Floor - Tile SF 7 10+ years Main Office 145 48 7 Lighting - Lay-in Main Office 145 10 EΑ 6-10 years Power Distribution Main Office 145 12 FΑ 7 10+ years Storage/ Closet Main Office 145 55 SF 7 10+ years 1,156 SF Walls - Concrete Block Main Office 145 7 10+ years SF Ceiling - Lay-in Principal Office 135 165 6 6-10 years Doors - Wood Doors inclu hw Principal Office 135 2 EΑ 7 10+ years Principal Office 135 SF Floor - Carpet 165 7 6-10 years Lighting - Lay-in Principal Office 135 2 EΑ 7 6-10 years Power Distribution Principal Office 135 6 FΑ 7 10+ vears Storage/ Closet Principal Office 135 16 SF 7 10+ years Walls - Concrete Block SF 7 10+ years Principal Office 135 447 Ceiling - Lav-in Teachers Planning Room 309B 386 SF 6 10+ years Teachers Planning Room 309B SF Ceiling - Lay-in 12 4 0-1 year Water damage Doors - Wood Doors inclu hw Teachers Planning Room 309B EΑ 6 10+ years 1 SF Floor - Carpet Teachers Planning Room 309B 398 6 6-10 years Lighting - Lay-in Teachers Planning Room 309B EΑ 7 6-10 years 3 Power Distribution Teachers Planning Room 309B 6 EΑ 7 10+ years Teachers Planning Room 309B SF Storage/ Closet 78 5 10+ years SF Walls - Concrete Block Teachers Planning Room 309B 966 7 10+ years Gvmnasia Ceiling - Lay-in 1st Floor 4,155 SF 6 6-10 years




Catego	ry : Room		В	uilding	: Main		_
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	100	SF	4	0-1 year	Water damage/Broken tiles
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Tile	1st Floor	4,255	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EΑ	7	6-10 years	
	Stage	1st Floor	600	SF	7	10+ years	
	Stage Curtain	1st Floor	3	EΑ	7	6-10 years	
	Stage Lighting System	1st Floor	10	EA	5	6-10 years	Quantity changed to match current observations
	Stage-Stairs - Wood	1st Floor	32	LF	7	10+ years	Quantity changed to match current observations
	Storage/ Closet	1st Floor	267	SF	5	10+ years	obder valience
	Walls - Concrete Block	1st Floor	4,356	SF	7	10+ years	
	valle Controle Block	10111001	1,000	O.	•	101 youro	
Kitchen							
	Ceiling - Plaster/Drywall	Kitchen 134	1,086	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen 134	2	EA	6	10+ years	
	Floor - Tile Quarry	Kitchen 134	1,086	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen 134	12	EA	7	6-10 years	
	Storage/ Closet	Kitchen 134	170	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen 134	1,245	SF	7	10+ years	
Library							
	Casework	Library 216	60	LF	6	10+ years	
	Ceiling - Lay-in	Library 216	1,511	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Library 216	2	ĒΑ	6	10+ years	
	Floor - Carpet	Library 216	1,511	SF	6	6-10 years	
	Lighting - Lay-in	Library 216	18	ĒΑ	6	6-10 years	
	Walls - Concrete Block	Library 216	1,418	SF	7	10+ years	
	Ceiling - Lay-in	Library Audio-Visual Room 213	357	SF	6	6-10 years	This room was not accessible. The room was locked and no key was provided. Components of this room are ranked based on similar rooms.
	Doors - Wood Doors inclu hw	Library Audio-Visual Room 213	1	EA	6	6-10 years	This room was not accessible. The room was locked and no key was provided. Components of this room are ranked based on similar rooms.
	Floor - Carpet	Library Audio-Visual Room 213	357	SF	6	6-10 years	This room was not accessible. The room was locked and no key was provided. Components of this room are ranked based on similar rooms.
	Walls - Concrete Block	Library Audio-Visual Room 213	600	SF	6	10+ years	are ranneu paseu on similar rooms.
	Casework	Library Reading Lab 217	12	LF	6	10+ years 10+ years	
	Casework	Library Neading Lab 217	12	LF	U	10+ years	



Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	Library Reading Lab 217	122	SF	6	10+ years		
	Ceiling - Lay-in	Library Reading Lab 217	18	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	Library Reading Lab 217	1	EA	6	10+ years		
	Floor - Carpet	Library Reading Lab 217	140	SF	6	6-10 years		
	Lighting - Lay-in	Library Reading Lab 217	2	EA	7	6-10 years		
	Walls - Concrete Block	Library Reading Lab 217	380	SF	7	10+ years		
	Ceiling - Lay-in	Library Work Room 212	209	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Library Work Room 212	1	ĒΑ	7	10+ years		
	Floor - Carpet	Library Work Room 212	209	SF	6	6-10 years		
	Lighting - Lay-in	Library Work Room 212	2	EA	7	6-10 years		
	Walls - Concrete Block	Library Work Room 212	229	SF	7	10+ years		
	Walls - Metal Panel	Library Work Room 212	250	SF	6	10+ years		
	valis ivictari arici	Library Work Noom 212	200	O.	O	101 years		
ocker/S	shower Room							
	Accessories	Toilet/Locker Room Kitchen	88	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Toilet/Locker Room Kitchen	88	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Toilet/Locker Room Kitchen	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Toilet/Locker Room Kitchen	38	SF	7	10+ years	Quantity changed to match current	
				-	•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	observations	
	Floor - Tile/Sheet	Toilet/Locker Room Kitchen	50	SF	5	6-10 years		
	Hand Dryer	Toilet/Locker Room Kitchen	1	EA	7	6-10 years		
	Lavatory	Toilet/Locker Room Kitchen	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	Toilet/Locker Room Kitchen	2	EA	7	6-10 years	Quantity changed to match current	
	Lighting - Fendent/Ourlace	Tollet/Locker Room Ritchen	2	LA	,	0-10 years	observations	
	Student Lockers - One Tier	Toilet/Locker Room Kitchen	4	EA	7	10+ years	observations	
	Walls - Concrete Block	Toilet/Locker Room Kitchen	486	SF	7	10+ years		
	Water Closet	Toilet/Locker Room Kitchen	1	EA	7	•		
	water Closet	Tollet/Locker Room Kitchen	I	EA	,	10+ years		
unch &	Multipurpose Room							
	Ceiling - Lay-in	117 Lunchroom	1,934	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	117 Lunchroom	4	EA	7	10+ years		
	Floor - Tile	117 Lunchroom	1,914	SF	6	6-10 years		
	Floor - Tile	117 Lunchroom	20	SF	4	0-1 year	Chipping/cracking	
	Lighting - Lay-in	117 Lunchroom	23	ĒΑ	7	6-10 years	3 17 3 3 3	
	Serving Line	117 Lunchroom	8	LF	7	10+ years		
	Walls - Concrete Block	117 Lunchroom	1,649	SF	7	10+ years		
100honi	cal/ Service Rooms							
nechani	Storage Room Storage Room	118 Store room	210	SF	5	10+ years	Damage to ceiling.	
	Janitor's Closet	1st Floor		SF SF		•	Damage to ceiling.	
		1st Floor 1st Floor	45	SF SF	5	10+ years		
	Mechanical/ Service Rooms		210		7	10+ years		
	Mechanical/ Service Rooms Storage Room	1st Floor 1st Floor	75 612	SF SF	7 7	10+ years 10+ years	Elevator equipment room	
		10t -100r	K17	<-	/	7/11 V/OOrc		



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Vaults	1st Floor	44	SF	7	10+ years	
	Janitor's Closet	2nd Floor	51	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	624	SF	7	10+ years	
	Storage Room	2nd Floor	245	SF	5	10+ years	Water damage to ceiling which caused a hole.
	Janitor's Closet	3rd Floor	51	SF	5	10+ years	Water damage to ceiling tiles/missing.
	Mechanical/ Service Rooms	3rd Floor	1,315	SF	5	10+ years	
	Storage Room	3rd Floor	145	SF	5	10+ years	Water damage to ceiling tiles/missing.
Restrooi	m						
	Accessories	1st floor staff Restroom next to Girls RR	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor staff Restroom next to Girls RR	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor staff Restroom next to Girls RR	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor staff Restroom next to Girls RR	38	SF	7	10+ years	
	Hand Dryer	1st floor staff Restroom next to Girls RR	1	EA	7	6-10 years	
	Lavatory	1st floor staff Restroom next to Girls RR	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st floor staff Restroom next to Girls RR	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor staff Restroom next to Girls RR	225	SF	7	10+ years	
	Water Closet	1st floor staff Restroom next to Girls RR	1	EA	7	10+ years	
	Accessories	Main office	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main office	42	SF	7	10+ years	
	Lavatory	Main office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main office	1	EA	7	6-10 years	
	Walls - Concrete Block	Main office	184	SF	7	10+ years	
	Water Closet	Main office	104	EA	7	10+ years	
	Accessories	Toilet Room (Boys 127)	487	SF	7	6-10 years	
				SF	7		
	Ceiling - Plaster/Drywall	Toilet Room (Boys 127)	487	SF EA		10+ years	
	Doors - Wood Doors inclu hw	Toilet Room (Boys 127)	2		7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet Room (Boys 127)	487	SF	7	10+ years	
	Floor Drain	Toilet Room (Boys 127)	1	EA	7	10+ years	
	Lavatory	Toilet Room (Boys 127)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet Room (Boys 127)	3	EA	6	6-10 years	
	Partitions	Toilet Room (Boys 127)	1	EΑ	7	10+ years	








Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Toilet Room (Boys 127) Urinals 3 EΑ 10+ vears 7 Toilet Room (Boys 127) 572 SF 7 Walls - Concrete Block 10+ years Water Closet Toilet Room (Boys 127) FΑ 7 10+ years 1 Toilet Room (Boys 204) 295 SF 7 Accessories 6-10 years SF Ceiling - Plaster/Drywall Toilet Room (Boys 204) 295 6 10+ years Doors - Wood Doors inclu hw Toilet Room (Boys 204) 2 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Boys 204) 295 SF 6 10+ years Floor Drain Toilet Room (Boys 204) 1 EΑ 7 10+ years Lavatory Toilet Room (Boys 204) 2 EΑ 6 10+ years Lighting - Pendent/Surface Toilet Room (Bovs 204) 3 FΑ 7 6-10 years **Partitions** Toilet Room (Bovs 204) 1 EΑ 7 10+ vears Urinals Toilet Room (Boys 204) 3 EΑ 6 10+ years Walls - Concrete Block Toilet Room (Boys 204) 574 SF 7 10+ years EΑ Water Closet Toilet Room (Boys 204) 1 6 10+ years Toilet Room (Boys 304) SF Accessories 295 4 0-1 year Some items are missing Ceiling - Plaster/Drywall Toilet Room (Boys 304) 295 SF 6 10+ years Needs painting. Doors - Wood Doors inclu hw EΑ Toilet Room (Bovs 304) 1 6 10+ years SF Floor - Tile Ceramic/ Porcelain Toilet Room (Boys 304) 295 6 10+ years Toilet Room (Boys 304) EΑ Floor Drain 7 10+ years 1 Toilet Room (Boys 304) Hand Dryer 2 EΑ 5 0-1 year Needs repair Lavatory Toilet Room (Boys 304) 1 EΑ 4 0-1 year Damaged Lighting - Pendent/Surface Toilet Room (Boys 304) 3 EΑ 4 0-1 year Does not work. 2 Toilet Room (Boys 304) EΑ 5 Partitions 10+ years 3 Urinals Toilet Room (Boys 304) FΑ 6 10+ years Walls - Concrete Block Toilet Room (Boys 304) 574 SF 7 10+ years Water Closet Toilet Room (Bovs 304) 2 EΑ 6 10+ years Toilet Room (Engineers) 25 SF 7 Accessories 6-10 years Ceiling - Plaster/Drywall Toilet Room (Engineers) 25 SF 7 10+ years Doors - Wood Doors inclu hw Toilet Room (Engineers) EΑ 1 7 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Engineers) 25 SF 7 10+ years Toilet Room (Engineers) 1 FΑ 7 10+ vears Lavatory Lighting - Pendent/Surface Toilet Room (Engineers) 1 FΑ 7 6-10 years Quantity changed to match current observations Walls - Concrete Block Toilet Room (Engineers) 180 SF 7 10+ years Water Closet Toilet Room (Engineers) 1 EΑ 7 10+ years Toilet Room (Girls 128) SF 7 6-10 years Accessories 487 SF Ceiling - Plaster/Drywall Toilet Room (Girls 128) 487 7 10+ years Doors - Wood Doors inclu hw EΑ 7 Toilet Room (Girls 128) 2 10+ years SF Floor - Tile Ceramic/ Porcelain Toilet Room (Girls 128) 487 7 10+ years EΑ Floor Drain Toilet Room (Girls 128) 1 7 10+ vears Lavatory Toilet Room (Girls 128) 2 FΑ 6 6-10 years 3 FΑ 7 Lighting - Pendent/Surface Toilet Room (Girls 128) 6-10 years **Partitions** Toilet Room (Girls 128) 4 EΑ 7 10+ years SF Walls - Concrete Block Toilet Room (Girls 128) 572 7 10+ years

Page: 10 of 21







Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Water Closet Toilet Room (Girls 128) 4 EΑ 10+ vears 7 Toilet Room (Girls 205) 293 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall Toilet Room (Girls 205) 293 SF 6 10+ years Doors - Wood Doors inclu hw Toilet Room (Girls 205) 2 EΑ 6 10+ years SF Floor - Tile Ceramic/ Porcelain Toilet Room (Girls 205) 293 6 10+ years Floor Drain EΑ 7 Toilet Room (Girls 205) 1 10+ years Toilet Room (Girls 205) 2 EΑ 10+ years Lavatory 6 Lighting - Pendent/Surface Toilet Room (Girls 205) 3 EΑ 7 6-10 years **Partitions** Toilet Room (Girls 205) 3 EΑ 5 10+ years SF Walls - Concrete Block Toilet Room (Girls 205) 572 7 10+ years Water Closet Toilet Room (Girls 205) 3 EΑ 6 10+ years Accessories Toilet Room (Girls 305 293 SF 4 0-1 year Some items are missing Ceiling - Plaster/Drywall Toilet Room (Girls 305 293 SF 6 10+ years EΑ 6 Doors - Wood Doors inclu hw Toilet Room (Girls 305) 4 10+ years Toilet Room (Girls 305 SF 6 Floor - Tile Ceramic/ Porcelain 293 10+ years Floor Drain FΑ 7 Toilet Room (Girls 305) 1 10+ years Hand Drver Toilet Room (Girls 305 1 FΑ 5 0-1 year Damaged Lavatory Toilet Room (Girls 305 2 EΑ 4 0-1 year Damaged 3 Lighting - Lay-in Toilet Room (Girls 305 EΑ 5 0-1 year Does not work. **Partitions** Toilet Room (Girls 305 4 EΑ 5 10+ years Walls - Concrete Block Toilet Room (Girls 305 572 SF 7 10+ years Toilet Room (Girls 305 Water Closet 4 EΑ 6 10+ years 38 SF 7 Accessories Toilet Room (Principals 136) 6-10 years SF 7 Ceiling - Plaster/Drywall Toilet Room (Principals 136) 38 10+ years Doors - Wood Doors inclu hw Toilet Room (Principals 136) EΑ 7 1 10+ years SF Floor - Tile Ceramic/ Porcelain Toilet Room (Principals 136) 38 7 10+ years Toilet Room (Principals 136) 1 EΑ 7 10+ years Lavatory Lighting - Pendent/Surface Toilet Room (Principals 136) EΑ 7 6-10 years 1 Walls - Concrete Block Toilet Room (Principals 136) SF 225 7 10+ years Water Closet Toilet Room (Principals 136) 1 EΑ 7 10+ years Accessories Toilet Room (Staff 211) 25 SF 7 6-10 years SF Ceiling - Plaster/Drywall Toilet Room (Staff 211) 25 6 10+ years FΑ 7 Doors - Wood Doors inclu hw Toilet Room (Staff 211) 1 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Staff 211) 25 SF 6 10+ years Lavatory Toilet Room (Staff 211) 1 EΑ 6 10+ years Lighting - Lay-in EΑ 5 Toilet Room (Staff 211) 1 6-10 years Walls - Concrete Block SF Toilet Room (Staff 211) 180 7 10+ years Water Closet Toilet Room (Staff 211) EΑ 6 10+ years 1 SF Accessories Toilet Room (Staff 217) 51 7 6-10 years Ceiling - Plaster/Drywall SF Toilet Room (Staff 217) 51 6 10+ vears Doors - Wood Doors inclu hw Toilet Room (Staff 217) 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain SF Toilet Room (Staff 217) 51 6 10+ years Floor Drain Toilet Room (Staff 217) EΑ 7 10+ years 7 Hand Dryer Toilet Room (Staff 217) EΑ 6-10 years





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Toilet Room (Staff 217)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Toilet Room (Staff 217)	1	EA	7	6-10 years	
	Walls - Concrete Block	Toilet Room (Staff 217)	268	SF	7	10+ years	
	Water Closet	Toilet Room (Staff 217)	1	EA	6	10+ years	
	Accessories	Toilet Room (Staff 306)	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room (Staff 306)	51	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room (Staff 306)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet Room (Staff 306)	51	SF	6	10+ years	
	Hand Dryer	Toilet Room (Staff 306)	1	EA	7	6-10 years	
	Lavatory	Toilet Room (Staff 306)	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Toilet Room (Staff 306)	1	EA	7	6-10 years	
	Walls - Concrete Block	Toilet Room (Staff 306)	268	SF	7	10+ years	
	Water Closet	Toilet Room (Staff 306)	1	ĒΑ	6	10+ years	
	Accessories	Toilet Room gym office	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room gym office	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room gym office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet Room gym office	36	SF	7	10+ years	
	Lighting - Pendent/Surface	Toilet Room gym office	1	EA	7	6-10 years	
	Walls - Concrete Block	Toilet Room gym office	252	SF	7	10+ years	
	Water Closet	Toilet Room gym office	1	EA	7	10+ years	
	Accessories	Toilet Room next to 102	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room next to 102	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room next to 102	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet Room next to 102	28	SF	7	10+ years	
	Hand Dryer	Toilet Room next to 102	1	EA	7	6-10 years	
	Lavatory	Toilet Room next to 102	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet Room next to 102	1	EA	7	6-10 years	
	Walls - Concrete Block	Toilet Room next to 102	191	SF	7	6-10 years	
	Water Closet	Toilet Room next to 102	1	EA	7	6-10 years	
	Accessories	Toilet Room next to 102 Toilet Room next to 102	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room next to 102 Toilet Room next to 102	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room next to 102 Toilet Room next to 102	1	EA	7	•	
	Floor - Tile Ceramic/ Porcelain		28	SF	7	10+ years	
	Hand Dryer	Toilet Room next to 102	28 1	SF EA	7	10+ years	
	•	Toilet Room next to 102 Toilet Room next to 102	1	EA EA	7	6-10 years	
	Lavatory Lighting - Pendent/Surface	Toilet Room next to 102 Toilet Room next to 102	1	EA EA	7	10+ years	
	Walls - Concrete Block	Toilet Room next to 102 Toilet Room next to 102	•	SF	7	6-10 years	
			191 1	SF EA	7 7	10+ years	
	Water Closet	Toilet Room next to 102	1	EA	/	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #100 (Art Room)						
	Ceiling - Lay-in	1st Floor	1,250	SF	6	10+ years	

Page : 12 of 21



Catego	ry : Classroom		R	uilding	· Main	700	0.5 South Shore DRIVE, Chicago, it 60649
Outogo	, Classicon			anamg	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	Trate: damage
	Floor - Tile	1st Floor	1,274	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	28	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,166	SF	7	10+ years	
Classroo	om #101 (Computer Lab)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	997	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	400	SF	4	0-1 year	Torn throughout.
	Floor - Tile			SF	7	•	Tom unoughout.
		1st Floor 1st Floor	597	Sr EA	6	10+ years 6-10 years	
	Lighting - Lay-in		14	SF			
	Storage/ Closet	1st Floor	28		5	10+ years	
	Walls - Concrete Block	1st Floor	1,156	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	997	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	18	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	418	SF	4	0-1 year	The carpet is torn and has a lot of stains throughout.
	Floor - Tile	1st Floor	597	SF	6	10+ years	otanio unougnout.
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	28	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,166	SF	7	10+ years	
Classro	om #105 (Covid Care Room)						
(Ceiling - Lay-in	1st Floor	715	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor		SF	6		Changed to match current
	·		685			2-5 years	observations
	Floor - Carpet	1st Floor	30	SF	4	0-1 year	Torn line in the middle of the the floor
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	967	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
					-	,	

Page : 13 of 21



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	685	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Buckled tile
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	691	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	732	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	210	SF	6	10+ years	
Classroc	m #201 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	670	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	36	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Water damage
	Floor - Tile	2nd Floor	706	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	961	SF	7		
	Walls - Concrete Block	2110 F1001	901	SF	,	10+ years	
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	664	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	42	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	_
	Floor - Tile	2nd Floor	706	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	529	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	432	SF	6	10+ years	
Classroc	m #203 (Office)						
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	664	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	water damage
	Floor - Tile	2nd Floor	670	SF	6	10+ years	
		2nd Floor		EA			
	Lighting - Lay-in		10	LF	7	6-10 years	
	Marker Board	2nd Floor	10	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	940	SF	7	10+ years	
Classroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	780	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	

Page : 14 of 21



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	230	SF	7	10+ years	
Classroo	m #205 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	682	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Missing tile
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	gg
	Floor - Carpet	2nd Floor	688	SF	4	0-1 year	Torn/ripped throughout.
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	Tom/npped tillodgilodt.
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	7	10+ years	
	Walls - Goncrete Block Walls - Metal Panel	2nd Floor	230	SF	6	10+ years	
	vvalis - Metal Fallel	211d F1001	230	SF	O	10+ years	
lassroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	679	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	30	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	709	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	10	EΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	709	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	250	SF	6	10+ years	
lassroo	m #208 (Office)						
	Casework	2nd Floor	44	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	764	SF	6	2-5 years	
	Ceiling - Lay-in	2nd Floor	36	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	800	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	968	SF	7	10+ years	
:lassroo	m #300 (Rehabilitation under progress)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	691	SF	6	10+ years	
	Chalk Board		12	SF LF		2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	4		
		3rd Floor		SF	6	10+ years	
	Floor - Carpet	3rd Floor	691	2F	5	6-10 years	

Page : 15 of 21



Catego	Category : Classroom			uilding	: Main	700	, ,			
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor	628	SF	7	10+ years				
	Walls - Concrete Block	3rd Floor	4	SF	5	0-1 year	Cracks			
	Walls - Metal Panel	3rd Floor	320	SF	6	10+ years				
_Classroo	om #301 (Unsafe/Unusable Condition)									
	Ceiling - Lay-in	3rd Floor	649	SF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	18	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	g-			
	Floor - Carpet	3rd Floor	667	SF	4	0-1 year	Stains/water damage throughout			
	Lighting - Lay-in	3rd Floor	8	EA	5	6-10 years	Grame, mare: damage unedgreen			
	Walls - Concrete Block	3rd Floor	745	SF	7	10+ years				
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years				
Classroo	om #302 (Rehabilitation under progress)									
	Casework	3rd Floor	12	LF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	water damage			
	Floor - Carpet	3rd Floor	700	SF	4	0-1 year	Stains/tear/Water damage throughout			
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	Stains/teal/Water damage timoughout			
	Walls - Concrete Block		529	SF	7	10+ years				
	Walls - Metal Panel	3rd Floor 3rd Floor	432	SF	6	10+ years 10+ years				
Classro	om #303 (Rehabilitation under progress)									
Classiu	,	3rd Floor	12	LF	6	10 L VOORO				
	Casework			SF		10+ years				
	Ceiling - Lay-in	3rd Floor	655		6	10+ years	\\/_t			
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage			
	Chalk Board	3rd Floor	28	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years				
	Floor - Carpet	3rd Floor	667	SF	4	0-1 year	Torn and severely damaged throughout.			
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	G			
	Walls - Concrete Block	3rd Floor	725	SF	7	10+ years				
Classroo	om #304 (Rehabilitation under progress)									
	Casework	1st Floor	12	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	691	SF	6	10+ years				
	Chalk Board	1st Floor	16	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Carpet	1st Floor	691	SF	4	0-1 years	Torn and stains throughout.			
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	Tom and otamo unoughout.			
	Walls - Concrete Block	1st Floor	855	SF	7	10+ years				
	Trails Controls Block	1001	333	51	,	ioi youis				

Page : 16 of 21





Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	1st Floor	320	SF	6	10+ years	
	Traile Metal Lane.		323	Ο.		,	
assroo	m #305 (Rehabilitation under progress)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	688	SF	6	6-10 years	
	•				_		
	Lighting - Lay-in	3rd Floor	10	EA SF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	688		7	10+ years	
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years	
Classroo	m #307 (Rehabilitation under progress)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	714	SF	6	10+ years	
	Chalk Board	3rd Floor	12	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	714	SF	6	6-10 years	Stains throughout - need to be
	1 looi Carpot	014 1 1001	,	0.	Ü	o ro youro	cleaned.
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	oleanea.
	Walls - Concrete Block	3rd Floor	751	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7		
	WORK SINK	314 F1001	ı	EA	1	10+ years	
Classroo	m #309 A (Other Instructional Use)						
	Ceiling - Lay-in	3rd Floor	1,265	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	· ·
	Floor - Tile	3rd Floor	1,277	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	85	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	1,402	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years	
	Work Sink				7	,	
	Work Sink	3rd Floor	2	EA	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,125	SF	6	6-10 years	
		4 . = 1		~=			14/ 1 / 1 / 11
	Ceiling - Lay-in	1st Floor	36	SF	4	0-1 year	Water damage/sagging ceiling tile

Page : 17 of 21



Catego	Category : Interior			uilding	: Main		· • • • • • • • • • • • • • • • • • • •		
				-		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	300	SF	7	10+ years	Vestibule		
	Floor - Tile/Sheet	1st Floor	1,861	SF	5	6-10 years			
	Lighting - Lay-in	1st Floor	20	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	3,843	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	1,064	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage		
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	1,070	SF	5	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	6	6-10 years			
	Walls - Concrete Block	2nd Floor	2,055	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	1,380	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Water damage		
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	1,404	SF	5	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years			
	Walls - Concrete Block	3rd Floor	2,850	SF	7	10+ years			
Safety									
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Metal Dedector	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	2	EA	7	6-10 years			
_Stairs									
	Ceiling - Lay-in	Stair #1 South	434	SF	6	10+ years			
	Ceiling - Lay-in	Stair #1 South	6	SF	4	0-1 year	Water damage		
	Floor - Terrazzo	Stair #1 South	432	SF	6	10+ years	Ğ		
	Handrails	Stair #1 South	48	LF	7	10+ years			
	Lighting - Lay-in	Stair #1 South	2	EA	6	6-10 years			
	Stairs - Terrazzo	Stair #1 South	180	LF	6	10+ years			
	Walls - Concrete Block	Stair #1 South	4,320	SF	7	10+ years			
	Ceiling - Lay-in	Stairs #2 North	501	SF	6	10+ years			
	Ceiling - Lay-in	Stairs #2 North	3	SF	4	0-1 year	Water damage.		
	Floor - Terrazzo	Stairs #2 North	504	SF	6	10+ years	•		
	Handrails	Stairs #2 North	48	LF	7	10+ years			
	Lighting - Lay-in	Stairs #2 North	2	EA	7	6-10 years			
	Stairs - Terrazzo	Stairs #2 North	180	LF	6	10+ years			
	Walls - Concrete Block	Stairs #2 North	5,040	SF	7	10+ years			
Vertical (Conveyance								
	Elevator - Hydraulic Elevator	1st to 3rd Floors	1	EA	7	10+ years			



Category : Site Building : Site

Category : Site			Building : Site							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Civil/Drai	nage									
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	7	10+ years				
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	0-1 year	Sinking			
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	10+ years	S			
Fencina										
3	Fencing - Chain Link	Entire Site	1,650	LF	6	6-10 years				
	Fencing - Chain Link	Entire Site	825	LF	4	0-1 year	Holes, loose.			
	Fencing - New Standard Ornamental	Entire Site	350	LF	6	10+ years				
	Fencing - New Standard Ornamental	Entire Site	100	LF	4	0-1 year	Corrosion, bent.			
Landscar	oe .									
·	Landscape - Grass	Entire Site	14,000	SF	7	10+ years				
	Landscape - Hardscape- Concrete	Entire Site	2,200	SF	7	10+ years				
	Parkway trees	Entire Site	9	EA	6	10+ years				
	Trash Receptacles	Entire Site	1	EA	6	10+ years				
Parking I	ot									
	Lighting - Pole Mounted	South	2	EA	6	6-10 years				
	Surface - Asphalt	South	17,400	SF	4	0-1 year	Cracking throughout, areas uneven from cracking.			
	Vehicular Screening	South	320	LF	7	6-10 years	g.			
Playgrou	nd									
	Equipment - School Age 5-12	East	1	EA	6	6-10 years				
	Surface - Square Rubber Mats	East	750	SF	4	0-1 year	Gaps, loose.			
Sidewalk	s									
	Sidewalks - Internal Walks	Entire Site	480	LF	6	10+ years				
	Sidewalks - Perimeter Sidewalks	Entire Site	2,100	SF	7	10+ years				
Signage										
	Flag Pole - Flag Pole	East	1	EA	7	10+ years				
	Marquee - Free Standing Back Lighted	East	1	EA	7	6-10 years				

Page: 19 of 21

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.







Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

Classicolli Sullillary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•						
Art Room	Art Room	1st Floor	100	118	1,274	156	32		Υ
Computer Lab	Kindergarten	1st Floor	101	148	997	120	30		
Computer Lab	Regular Classroom	2nd Floor	201	201	706	104	16		
Covid Care Room	Regular Classroom	1st Floor	105	147	715	104	16		N
Office	Regular Classroom	2nd Floor	203	203	670	104	16		
Office	Regular Classroom	2nd Floor	208	219	800	104	16		
Other Instructional Use	Science Classroom	3rd Floor	309 A	314	1,277	182	32		
Regular Classroom	Kindergarten	1st Floor	103	149	1,015	104	16		Υ
Regular Classroom	Regular Classroom	2nd Floor	200	221	691	104	16		Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	706	104	16		Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	780	126	60		Υ
Regular Classroom	Regular Classroom	2nd Floor	205	220	688	104	16		Υ
Regular Classroom	Special Education	2nd Floor	207	222	709	104	16		Υ
Rehabilitation under progress	Regular Classroom	1st Floor	304	319	691	104	16		
Rehabilitation under progress	Regular Classroom	3rd Floor	300	318	691	104	16		
Rehabilitation under progress	Regular Classroom	3rd Floor	302	302	700	104	16		
Rehabilitation under progress	Regular Classroom	3rd Floor	303	303	667	104	16		
Rehabilitation under progress	Regular Classroom	3rd Floor	305	317	688	104	16		
Rehabilitation under progress	Regular Classroom	3rd Floor	307	316	714	104	16		
Unsafe/Unusable Condition	Regular Classroom	3rd Floor	301	301	667	104	16		