

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Leased-Main	1920	3	79,926
Campus Total			79,926

Catego	ry : Exterior	В	uilding	: Lease	d-Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Main Roof	4	EA	7	6-10 years	
E							
Entrance		4 5 11 67		F A		10	
	Exterior Doors - Exterior Steel Door	1 NW	1	EA	1	10+ years	
	Exterior Doors - Side lite	1 NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	1 NW	1	EA	6	6-10 years	
	Exterior Stairs - Stone	1 NW	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	10 SE	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	10 SE	1	EA	6	6-10 years	
	Exterior Stairs - Stone	10 SE	3	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	11 - North Center Courtyard - Boys	1	EA	4	0-1 year	Warped, water damaged frames
		Bathroom				-	
	Entrance Control - Audio and Video	2 Main N	1	EA	6	10+ years	Camera Not working
	Exterior Doors - Exterior Steel Door	2 Main N	4	EA	6	6-10 years	Ũ
	Exterior Doors - Transom Lite	2 Main N	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	2 Main N	200	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	2 Main N	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	3 N	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	3 N	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	3 N	160	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	3 N	12	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	4 NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	4 NE	1	EA	6	6-10 years	
	Exterior Stairs - Stone	4 NE	5	LF	6	10+ years	
			5	LF	0	ior years	



	6201 S Fairfield AVENUE, Chicago, IL 60629								
Catego	y : Exterior		Building : Leased-Main						
Crown	Hom Tuno	Location	Quantity	UOM	Donk	Recommend	Commente		
Group	Item - Type Exterior Doors - Exterior Steel Door	5 SW	Quantity	EA	Rank 6	Replacement 6-10 years	Comments		
	Exterior Doors - Exterior Steel Door	5 SW	2	EA	6	6-10 years			
	Exterior Stairs - Stone	5 SW	5		6	10+ years			
	Exterior Doors - Exterior Steel Door	6 S	2	EA	6	6-10 years			
	Exterior Doors - Transom Lite	6 S	2	EA	6	6-10 years			
	Exterior Stairs - Stone	6 S	5	LF	6	10+ years			
	Exterior Doors - Exterior Wood Door	7 NW - West Courtyard	2	EA	5	0-1 year	Warped, water damaged frames		
	Exterior Doors - Transom Lite	7 NW - West Courtyard	2	EA	5	0-1 year	Warped, water damaged frames		
	Exterior Stairs - Concrete	7 NW - West Courtyard	6	LF	6	10+ years	Walped, water damaged frames		
	Exterior Doors - Exterior Wood Door	7.1 - Center W - West Courtyard	1	EA	4	0-1 year	Deteriorated door no hardware		
	Exterior Stairs - Concrete	7.1 - Center W - West Courtyard	3	LF	6	-	Detenorated door no hardware		
	Exterior Doors - Exterior Wood Door	8 NE - East courtyard	2	EA	5	10+ years 0-1 year	Warped, water damaged frames		
	Exterior Doors - Transom Lite	8 NE - East courtyard	2	EA	5	0-1 year	Warped, water damaged frames		
	Exterior Stairs - Concrete	8 NE - East courtyard	6		5 6	10+ years	warped, water damaged frames		
	Exterior Doors - Exterior Wood Door	8.1 - Center E - East Courtyard	0	EA	5	2-5 years			
	Exterior Stairs - Concrete	8.1 - Center E - East Courtyard	3	LF	5 6	10+ years			
	Exterior Doors - Exterior Steel Door	8.2 Center - East Courtyard	1	EA	6	6-10 years			
	Exterior Doors - Exterior Wood Door	8.3 - Center S Boiler	1	EA	4	0-1 year	Demagad, some repairs made		
	Entrance Control - Audio	9 SW	1	EA	4 6	6-10 years	Damaged, some repairs made		
	Exterior Doors - Exterior Steel Door	9 SW	1	EA	6	,			
	Exterior Doors - Exterior Steel Door	9 SW	2	EA	6	6-10 years 6-10 years			
	Exterior Doors - Transom Lite	9 SW	2	EA	6				
	Exterior Stairs - Concrete	9 SW	3		6	6-10 years			
	Exterior Stars - Concrete	9 3 10	3	LF	0	10+ years			
Foundati	n								
	Foundation - Concrete	Entire Building	1,344	LF	7	10+ years			
	Superstructure - Concrete	Entire Building	4.000	SF	7	10+ years			
	Superstructure - Heavy Timber	Entire Building	46,316	SF	7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building	29,610	SF	7	10+ years			
		Entro Ballang	20,010	01		lot youro			
Lighting									
0 0	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years			
Roof Sys									
	Access Ladder - Metal	1 - main	1	EA	7	6-10 years	Not an actual access ladder		
	Coping - Clay Tile	1 - main	161	LF	6	10+ years			
	Coping - Terra Cotta	1 - main	302	LF	6	10+ years			
	Downspouts - Exterior Downspouts	1 - main	150	LF	6	6-10 years			
	Parapet - 16" - 30" Height	1 - main	161	LF	6	10+ years			
	Parapet - Parapet > 30"	1 - main	302	LF	6	10+ years			
	Roof - Asphalt Gravel Ballast	1 - main	11,165	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	1 - main	11,165	SF	7	10+ years			
	Coping - Clay Tile	2 - center	38	LF	6	10+ years			



Category : Exterior Building : Leased-Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Coping - Terra Cotta 2 - center 22 LF 10+ vears 6 LF 6 Downspouts - Exterior Downspouts 36 6-10 years 2 - center Parapet - 16" - 30" Height 38 LF 6 10+ years 2 - center Parapet - Parapet > 30" 22 LF 6 2 - center 10+ years SF Roof - Modified Bitumen 2 - center 443 6 6-10 years SF 7 Roof Structure - Steel with Clay Tile Arch 2 - center 443 10+ years Coping - Clay Tile 286 LF 3 - east 6 10+ years LF Coping - Terra Cotta 3 - east 239 6 10+ years **Downspouts - Exterior Downspouts** 3 - east 120 LF 6 6-10 years LF Parapet - 16" - 30" Height 294 6 10+ years 3 - east Parapet - Parapet < 16" Height 110 LF 6 10+ vears 3 - east Parapet - Parapet > 30" 3 - east 121 LF 6 10+ years Roof - Modified Bitumen 9,352 SF 6 6-10 years 3 - east SF 7 Roof Structure - Heavy Timber 3 - east 9,352 10+ years I F Chimney - Brick Chimney- Concrete/ Mortar 75 4 - boiler 6 10+ years Liner LF Coping - Clav Tile 4 - boiler 300 6 10+ vears LF **Downspouts - Exterior Downspouts** 4 - boiler 32 6 6-10 years Parapet - 16" - 30" Height LF 4 - boiler 30 6 10+ vears Parapet - Parapet < 16" Height 4 - boiler 270 LF 6 10+ years Roof - Asphalt Gravel Ballast 4 - boiler 5.110 SF 6 6-10 years Roof - Asphalt Shingle SF 4 - boiler 90 6 6-10 years SF 7 Roof Structure - Heavy Timber 4 - boiler 5,200 10+ years Walls Cheek-Wall - Stone SF 5 Entire Building 80 6-10 years SF Wall at entrance 3 is separating Cheek-Wall - Stone Entire Building 20 4 0-1 year LF 6 Cornice - Masonry Projecting Limestone Entire Building 2.688 10+ years SF Exterior Walls - Brick Entire Building 49.096 6 10+ years SF Exterior Walls - Brick Entire Building 1.030 4 0-1 vear Spalling, cracked masonry Exterior Walls - Stone-Cast Entire Building 556 SF 6 10+ years SF Exterior Walls - Terra Cotta 1.290 6 10+ vears Entire Building Windows Curtain wall - Insulated Panel Entire Building 2.803 SF 6 6-10 vears SF 2.264 6-10 years Guard - Guards wire guard Entire Building 6 LF 6 Lintels - Steel Entire Building 1.262 10+ vears Skylite - Glass Single-Pane Entire Building 179 SF 6 6-10 years SF Skylite - Glass Single-Pane Entire Building 12 4 0-1 year cracked glazing SF Windows - Decorative Entire Building 741 6 6-10 years SF Windows - Sash Aluminum Double-pane Entire Building 5,386 6 6-10 years Windows - Wood- Single-pane Entire Building SF 6 6-10 years 545 SF Windows - Wood- Single-pane Entire Building 689 4 0-1 year Deteriorated, water damaged frames



Catego	ry : Electrical		Building : Leased-Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System							
	Automatic Transfer Switch	Boiler Room	1	EA	6	10+ years		
	Security System - CCTV	Entire Building	79,926	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	79,926	SF	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	2	0-1 year	No battery and no generator backup ! The light sources aren't LED	
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	No battery and no generator backup ! The light sources aren't LED	
	Exit Signs - Multipurpose Room	Entire Building	7	EA	2	0-1 year	No battery and no generator backup ! The light sources aren't LED	
	Emergency A/C Power - Corridors and Stairs	Entire Building	12,000	SF	6	6-10 years	-	
Main Se								
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	10+ years		
	PA System	Entire Building	79,926	SF	6	6-10 years		
	Main Electrical Service - 1600 A 120/240/3PH	Entire Building	1	EA	6	10+ years		
Power D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	The panel has been replaced	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	The panel has been replaced	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	10+ years		
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years		
Catego	ry : Fire Protection		В	uilding	: Lease	d-Main		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar								
	Fire Alarm Panel	Boiler Room	1	EA	6	6-10 years		
	Fire Alarm_System	Boiler Room	79,926	SF	4	1-2 years	Old system, some of the pull levers are not functional. No strobes	
	Fire Pump Controller	Boiler Room	1	EA	5	6-10 years		
Pump Ro	oom Assembly							
	Fire Pump - Less than 25hp	Basement	1	EA	5	6-10 years		
	Jockey Pump	Basement	1	EA	7	6-10 years		



Catego	ry : Fire Protection		В	Building : Leased-Main					
ealege	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		_	anang	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Sprinkler	System					-			
	Dry Sprinkler System	Entire Building	29,610	SF	5	6-10 years			
	Sprinkler Heads	Entire Building	29,610	SF	4	1-2 years	The sprinkler heads are old, beyond		
			,	•.		,	their useful life		
	Sprinkler Piping	Entire Building	29,610	SF	5	10+ years			
Catego	ry : Mechanical		В	uilding	: Lease	d-Main			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Cond									
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	3	EA	6	6-10 years	The A/C units are 8 years old and functional , they serve 2 classrooms on 3rd floor.		
Boiler Sy									
	Piping - Condensate Pipe- Steel	Entire Building	800	LF	6	10+ years			
	Piping - Steam Pipe- Steel	Entire Building	800	LF	6	10+ years			
	Steam Traps	Entire Building	100	EA	5	6-10 years			
	Steam Traps	Entire Building	25	EA	5	6-10 years	No active leaks reported		
Heating I	Devices								
	Radiators - Steam	Entire Building	110	EA	5	6-10 years	Some radiators are new and equipped with valves, however most of them have no temperature adjustment capability		
	Radiators - Steam	Entire Building	15	EA	5	6-10 years	Paint is peeling off		
Tempera	ture Control								
	Electric Thermostat	Entire Building	3	EA	6	10+ years	Serve 3 mini split systems. No AH system.		
Ventilatio		Main Doof		۲۸	6	C 10 ve ere			
	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Main Roof Main Roof	7 3	EA EA	6 6	6-10 years 6-10 years	The units are 2016 installed and they are functional but the power supply is non functional.		
Catego	ry : Plumbing		В	uilding	: Lease	d-Main			
Ū.				J		Recommend			
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years			



Category : Plumbing Building : Leased-Main Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water Storage Tank_Gas - 201 - 500 Boiler Room FΑ 6 6-10 vears 1 Gallons Piping **Domestic Piping-Hot Water Return Lines** Entire Building 79,926 SF 6 10+ years Domestic Piping-Hot Water Return Risers SF Entire Building 79.926 6 10+ vears Domestic Piping-Hot Water from Risers to Entire Building 79.926 SF 6 10+ years Fixtures Domestic Piping-Hot/Cold Water Supply **Entire Building** 79.926 SF 6 10+ years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply SF Entire Building 79.926 6 10+ years (Risers) Domestic Piping-Hot/Cold Water Supply SF Entire Building 79.926 6 10+ years (from Risers to Fixtures) Sanitary Piping SF 79.926 6 Entire Building 10+ vears Storm Piping Entire Building 79.926 SF 6 10+ years SF Vent Piping Entire Building 79.926 6 10+ years Pumps Pumps - Sump-Simplex Boiler Room FΑ 5 6-10 years Under the stairs 1 Pumps - Sump-Simplex Boiler Room 1 FΑ 5 6-10 years **Building : Leased-Main** Category : Room Recommend UOM **Replacement** Comments Group Item - Type Location Quantity Rank Administrative Suites/Offices Ceiling - Plaster/Drywall 101A 327 SF 6 10+ years Doors - Transom Window 101A 45 SF 6 10+ years Doors - Wood Doors inclu hw 6 101A 1 EA 10+ years Floor - Tile 324 SF 6 10+ years 101A Floor - Tile 3 SF 0-1 vear 101A 4 Chipping tiles 7 Lighting - Pendent/Surface 101A 3 FΑ 6-10 years Power Distribution 7 10+ years 101A 4 FΑ SF Walls - Plaster/Drvwall 101A 1.080 6 10+ vears SF Walls - Plaster/Drywall 101A 12 5 0-1 year Large hole in wall, cracked plaster AC Unit 1st floor main offices at NW corner 1 ΕA 7 6-10 years Ceiling - Plaster/Drywall SF 1st floor main offices at NW corner 756 6 10+ years Doors - Transom Window 1st floor main offices at NW corner SF 6 54 10+ years Doors - Wood Doors inclu hw 1st floor main offices at NW corner 2 EΑ 6 10+ years Floor - Wood 1st floor main offices at NW corner 756 SF 7 10+ vears Lighting - Pendent/Surface 1st floor main offices at NW corner 8 FΑ 7 6-10 years Power Distribution 1st floor main offices at NW corner 16 FΑ 7 10+ years Storage/ Closet 1st floor main offices at NW corner 570 SF 7 10+ years



Category : Room **Building : Leased-Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Plaster/Drvwall 1st floor main offices at NW corner 2.296 SF 10+ vears 6 ΕA 7 6-10 vears AC Unit 2nd floor north end room 200 1 Ceiling - Plaster/Drywall 2nd floor north end room 200 383 SF 6 10+ years Doors - Transom Window SF 6 2nd floor north end room 200 9 10+ years Doors - Wood Doors inclu hw 2nd floor north end room 200 1 EA 6 10+ years 383 SF Floor - Wood 2nd floor north end room 200 6 10+ years Lighting - Pendent/Surface 2nd floor north end room 200 ΕA 7 6-10 years 4 6 Power Distribution 2nd floor north end room 200 EΑ 7 10+ years Storage/ Closet 2nd floor north end room 200 48 SF 7 10+ years SF Walls - Plaster/Drywall 2nd floor north end room 200 1.092 6 10+ vears SF Ceiling - Plaster/Drvwall 2nd floor north end room 201 327 6 10+ vears Doors - Transom Window 2nd floor north end room 201 45 SF 6 10+ years Doors - Wood Doors inclu hw ΕA 6 2nd floor north end room 201 1 10+ years SF 6 Floor - Tile 2nd floor north end room 201 327 10+ years Lighting - Pendent/Surface ΕA 7 2nd floor north end room 201 2 6-10 years FΑ 7 Power Distribution 2nd floor north end room 201 4 10+ years SF Walls - Plaster/Drvwall 2nd floor north end room 201 1.082 6 10+ years SF Walls - Plaster/Drywall 2nd floor north end room 201 10 6 10+ years Ceiling - Plaster/Drvwall SF **Basement Engineer's Office** 850 6 10+ vears Ceiling - Plaster/Drywall SF **Basement Engineer's Office** 14 5 0-1 year Water damage. Doors - Wood Doors inclu hw **Basement Engineer's Office** ΕA 6 10+ years 1 Floor - Concrete SF 7 **Basement Engineer's Office** 864 10+ years **Basement Engineer's Office** ΕA 6 Lighting - Pendent/Surface 4 6-10 years Power Distribution **Basement Engineer's Office** 6 FΑ 6 10+ years Walls - Concrete Block **Basement Engineer's Office** SF 6 615 10+ years SF Walls - Plaster/Drvwall **Basement Engineer's Office** 615 6 10+ vears 7 AC Unit Office 301A EA 6-10 years 1 Ceiling - Plaster/Drywall Office 301A 190 SF 6 10+ years Doors - Wood Doors inclu hw 7 Office 301A 1 EΑ 6-10 years Floor - Tile Office 301A 190 SF 7 10+ years Lighting - Pendent/Surface Office 301A 2 FΑ 6 6-10 years Power Distribution Office 301A 4 EΑ 7 10+ vears SF Walls - Plaster/Drywall Office 301A 300 6 10+ years Ceiling - Plaster/Drywall Third floor north end room 301 333 SF 6 10+ years Doors - Transom Window SF Third floor north end room 301 54 6 10+ years Doors - Wood Doors inclu hw ΕA 6 Third floor north end room 301 10+ years 1 SF Floor - Tile Third floor north end room 301 333 6 10+ years Lighting - Pendent/Surface Third floor north end room 301 ΕA 7 6-10 years 2 Third floor north end room 301 Power Distribution 6 EΑ 7 6-10 years SF Walls - Plaster/Drvwall Third floor north end room 301 1.092 6 10+ vears SF Ceiling - Plaster/Drywall custodian break room 160 5 0-1 year Water damage. Doors - Wood Doors inclu hw 2 FΑ 6 10+ vears custodian break room Floor - Concrete custodian break room 160 SF 7 10+ years ΕA Lighting - Pendent/Surface custodian break room 2 6 6-10 years



Building : Leased-Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments custodian break room Storage/ Closet 128 SF 5 10+ years Walls - Plaster/Drvwall 521 SF 6 custodian break room 10+ years Walls - Plaster/Drywall custodian break room 5 SF 4 0-1 year Corner entirely broken Gvmnasia Ceiling - Plaster/Drywall 1st Floor SF 6 6.820 10+ vears Ceiling - Plaster/Drywall 1st Floor 15 SF 5 0-1 year Water damage. Doors - Wood Doors inclu hw 1st Floor 6 EΑ 6 10+ years SF 7 Floor - Wood 1st Floor 6.835 10+ years Updated to match current observations Lighting - Pendent/Surface 18 ΕA 6 6-10 years 1st Floor Sound System 1st Floor 1 EΑ 7 6-10 years 1st Floor SF 10+ years Stage 144 6 Stage Curtain 1st Floor 4 FΑ 7 6-10 years Stage Lighting System ΕA 7 6-10 years 1st Floor 1 Walls - Plaster/Drywall 1st Floor 4.675 SF 6 10+ years Walls - Plaster/Drywall SF 1st Floor 15 5 1-2 years Water damage. Kitchen Ceiling - Plaster/Drywall Basement 1.624 SF 6 10+ years Doors - Wood Doors inclu hw Basement 1 ΕA 6 10+ years SF Floor - Tile Basement 1.618 6 10+ years SF Floor - Tile Basement 6 4 0-1 year Chipped and missing tiles Lighting - Pendent/Surface 20 ΕA 7 6-10 years Basement Serving Line Basement 22 LF 6 10+ years SF Walls - Metal Panel 6 10+ years Basement 1.113 Walls - Plaster/Drywall SF Basement 1.105 6 10+ years SF 5 Walls - Plaster/Drywall 7 0-1 year Baseboards scratched and chipped Basement Lunch & Multipurpose Room Ceiling - Plaster/Drywall Basement SF 6 2.159 10+ years 10+ years Floor - Tile Basement SF 2,157 6 Floor - Tile Basement 2 SF 4 0-1 year Chipped tiles 24 7 Lighting - Pendent/Surface Basement FΑ 6-10 years SF Walls - Plaster/Drywall Basement 1.154 10+ years 6 SF Walls - Plaster/Drywall **Basement** 1.154 6 10+ vears MDF IDF Doors - Steel Doors incl hw Inside 305 1 ΕA 6 10+ years Inside 305 98 SF 7 Finishes 10+ years Other Cooling Unit Inside 305 1 ΕA 7 10+ years Ductless split system. Mechanical/ Service Rooms



Catego	ry : Room		В	uilding	: Lease	d-Main		
-						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Janitor's Closet	1st Floor	25	SF	5	10+ years	Large cracks in door.	
	Janitor's Closet	2nd Floor	25	SF	7	10+ years		
	Janitor's Closet	3rd Floor	25	SF	7	10+ years		
	Boiler Room	Basement	2,314	SF	7	10+ years		
	Coal Room	Basement	403	SF	5	10+ years	5 SF of piece missing from wall.	
	Crawl Space - Unfinished	Basement	1,328	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	1,425	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	687	SF	7	10+ years		
	Storage Room	Basement	1,058	SF	7	10+ years		
	Storage Room	Basement	60	SF	7	10+ years		
	Storage Room	Basement	67	SF	7	10+ years		
Restroor	'n							
	Accessories	.5 Boy's restroom mezzanine	752	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	.5 Boy's restroom mezzanine	752	SF	6	10+ years		
	Floor - Tile	.5 Boy's restroom mezzanine	752	SF	6	10+ years		
	Floor Drain	.5 Boy's restroom mezzanine	1	EA	7	10+ years		
	Lavatory	.5 Boy's restroom mezzanine	5	EA	6	10+ years		
	Lighting - Pendent/Surface	.5 Boy's restroom mezzanine	4	EA	7	6-10 years		
	Partitions	.5 Boy's restroom mezzanine	9	EA	7	10+ years		
	Urinals	.5 Boy's restroom mezzanine	26	EA	6	10+ years		
	Urinals	.5 Boy's restroom mezzanine	4	EA	5	0-1 year	Out of order	
	Walls - Plaster/Drywall	.5 Boy's restroom mezzanine	647	SF	6	10+ years		
	Walls - Plaster/Drywall	.5 Boy's restroom mezzanine	5	SF	5	0-1 year	Crack causing chipping paint	
	Walls - Structural Glazed Tile	.5 Boy's restroom mezzanine	20	SF	6	0-1 year	Holes through tiles	
	Walls - Structural Glazed Tile	.5 Boy's restroom mezzanine	632	SF	6	10+ years		
	Water Closet	.5 Boy's restroom mezzanine	9	EA	6	10+ years		
	Accessories	.5 mezzanine floor girls	834	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	.5 mezzanine floor girls	834	SF	6	10+ years		
	Floor - Tile	.5 mezzanine floor girls	829	SF	6	10+ years		
	Floor - Tile	.5 mezzanine floor girls	5	SF	4	0-1 year	Chipped and cracked tiles	
	Floor Drain	.5 mezzanine floor girls	1	EA	7	10+ years		
	Hand Dryer	.5 mezzanine floor girls	1	EA	7	6-10 years		
	Lavatory	.5 mezzanine floor girls	5	EA	6	10+ years		
	Lighting - Pendent/Surface	.5 mezzanine floor girls	4	EA	7	6-10 years		
	Partitions	.5 mezzanine floor girls	14	EA	7	10+ years		
	Walls - Plaster/Drywall	.5 mezzanine floor girls	680	SF	6	10+ years		
	Walls - Plaster/Drywall	.5 mezzanine floor girls	12	SF	4	0-1 year	Parts of wall falling off and crackir	
	Walls - Structural Glazed Tile	.5 mezzanine floor girls	690	SF	6	10+ years	-	
	Water Closet	.5 mezzanine floor girls	14	EA	6	10+ years		
	Accessories	101A	47	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	101A	47	SF	6	10+ years		
	Doors - Wood Doors inclu hw	101A	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	101A	47	SF	6	10+ years		



Category : Room **Building : Leased-Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lavatorv 101A FΑ 10+ vears 6 1 ΕA 7 6-10 vears Lighting - Pendent/Surface 101A 1 Walls - Plaster/Drywall 101A 155 SF 7 10+ years Updated to match current observations SF Walls - Plaster/Drywall 101A 3 5 0-1 year Cracking. SF Walls - Tile Ceramic/ Porcelain 101A 128 6 10+ years Walls - Tile Ceramic/ Porcelain 101A SF 5 0-1 year 10 Large crack though multiple tiles Water Closet 101A 1 ΕA 6 10+ years Accessories 3rd floor north end 47 SF 7 6-10 years SF Ceiling - Plaster/Drywall 3rd floor north end 47 6 10+ years Doors - Wood Doors inclu hw 3rd floor north end 1 EΑ 6 10+ vears Floor - Tile Ceramic/ Porcelain 3rd floor north end 47 SF 6 10+ years ΕA 6 10+ years Lavatory 3rd floor north end 1 7 Lighting - Pendent/Surface 3rd floor north end 1 EA 6-10 years Partitions 7 3rd floor north end 1 EΑ 10+ years Walls - Plaster/Drywall SF 3rd floor north end 158 6 10+ years Walls - Tile Ceramic/ Porcelain SF 3rd floor north end 138 6 10+ years Water Closet 3rd floor north end 1 EA 6 10+ years SF Accessories 265 7 6-10 years Basement unisex Near door 4 SF Accessories Basement unisex Near door 4 5 5 0-1 year Extremely loud fan. Ceiling - Plaster/Drywall Basement unisex Near door 4 270 SF 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 Basement unisex Near door 4 270 10+ years 6 Lavatorv Basement unisex Near door 4 1 EA 10+ years 2 7 Lighting - Pendent/Surface Basement unisex Near door 4 FΑ 6-10 years Partitions 5 FΑ 7 10+ years Basement unisex Near door 4 7 Urinals Basement unisex Near door 4 EΑ 6 10+ vears SF Walls - Plaster/Drywall Basement unisex Near door 4 347 6 10+ years Updated to match current observations Walls - Structural Glazed Tile SF Basement unisex Near door 4 322 6 10+ years Updated to match current observations SF Walls - Structural Glazed Tile Basement unisex Near door 4 25 4 0-1 vear Large crack, missing tiles Water Closet Basement unisex Near door 4 5 EΑ 7 10+ vears SF 7 Second floor inside 201 47 6-10 years Accessories Ceiling - Plaster/Drywall Second floor inside 201 47 SF 6 10+ years Doors - Wood Doors inclu hw Second floor inside 201 1 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 47 SF 6 Second floor inside 201 10+ years Lavatory Second floor inside 201 1 EΑ 6 10+ years Lighting - Pendent/Surface 7 6-10 years Second floor inside 201 1 EA Walls - Plaster/Drywall Second floor inside 201 158 SF 6 10+ years Walls - Tile Ceramic/ Porcelain SF Second floor inside 201 138 6 10+ vears Water Closet Second floor inside 201 EΑ 6 10+ years 1 Category : Classroom Building : Leased-Main Group Item - Type Location UOM Rank Recommend Quantity Comments

Chicago Public Schools						201 S Fairfield AVENUE, Chicago, IL 60
					Replacement	
lassroom #101 (Regular Classroom)		4		7	0.40	
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current observations
Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
Marker Board	1st Floor	15	LF	7	6-10 years	
Storage/ Closet	1st Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	2,264	SF	6	10+ years	
lassroom #102 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	observations
Marker Board	1st Floor	16	LF	7	6-10 years	
Storage/ Closet	1st Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	2,264	SF	6	10+ years	
lassroom #103 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	14	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	observations
Marker Board	1st Floor	15	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	4	SF	6	0-1 year	Water damage.
Walls - Plaster/Drywall	1st Floor	2,260	SF	6	10+ years	
lassroom #104 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw		16	. .			

Enirfield Elementary Academy





Schools					6	201 S Fairfield AVENUE, Chicago, IL 60
					Replacement	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current observations
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	003017410113
Marker Board	1st Floor	18	LF	7	6-10 years	
Storage/ Closet	1st Floor	-	SF			
		115		7	10+ years	
Walls - Plaster/Drywall	1st Floor	2,257	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	7	SF	5	0-1 year	Water damage.
ssroom #105 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	14	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
					•	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current observations
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
Marker Board	1st Floor	15	LF	7	6-10 years	
Storage/ Closet	1st Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall			SF	6	•	
	1st Floor	2,258			10+ years	
Walls - Plaster/Drywall	1st Floor	6	SF	5	0-1 year	Water damage.
ssroom #106 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
		870	SF	7		Undeted to metable urrent
Floor - Wood	1st Floor		-	-	10+ years	Updated to match current observations
Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
Marker Board	1st Floor	18	LF	7	6-10 years	
Storage/ Closet	1st Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	2,259	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	5	SF	5	0-1 year	Cracking.
sroom #107 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	14				
				6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
Doors - Transom Window	1st Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Wood	1st Floor	870	SF	7	10+ years	Updated to match current observations
Lighting - Pendent/Surface	1st Floor	12	FΔ	7	6-10 years	
Lighting - Pendent/Surface Marker Board	1st Floor 1st Floor	13 15	EA LF	7 7	6-10 years 6-10 years	

				6	201 S Fairfield AVENUE, Chicago, IL
1st Floor	115		7	10+ years	
1st Floor	2,264	SF	6	10+ years	
2nd Floor	1	EA	7	6-10 years	
2nd Floor	6	LF	6	10+ years	
2nd Floor	870	SF	6	10+ years	
2nd Floor	72	SF	6		
2nd Floor	2	EA	6		
2nd Floor	870	SF	6		
2nd Floor					
211411001	2,204	01	0	Tor years	
2nd Floor	1	FA	7	6-10 years	
				•	
			-		
	-				
2nd Floor	1,147	SF	6	10+ years	
2nd Floor	1	EA	7	6-10 years	
2nd Floor	6	LF			
2nd Floor	870	SF		•	
				,	
				•	
		-			
	-			•	Patch and paint in hallway.
	2,204	36	0	TOT years	Fatch and paint in hallway.
			7	6-10 years	
2nd Floor	1	EA		0-10 00010	
	=	EA LF			
2nd Floor	5	LF	6	10+ years	
	=				
	2nd Floor 2nd Floor	1st Floor 2,264 2nd Floor 1 2nd Floor 6 2nd Floor 870 2nd Floor 2 2nd Floor 2 2nd Floor 870 2nd Floor 870 2nd Floor 870 2nd Floor 13 2nd Floor 16 2nd Floor 16 2nd Floor 115 2nd Floor 1 2nd Floor 1 2nd Floor 739 2nd Floor 7 2nd Floor 7 2nd Floor 1 2nd Floor 12 2nd Floor 12 2nd Floor 12 2nd Floor 13 2nd Floor 115 2nd Floor 1 2nd Floor 1 2nd Floor 1 2nd Floor 72 2nd Floor 72 2nd Floor 72 2nd Floor 72	1st Floor 2,264 SF 2nd Floor 1 EA 2nd Floor 6 LF 2nd Floor 870 SF 2nd Floor 72 SF 2nd Floor 2 EA 2nd Floor 2 EA 2nd Floor 13 EA 2nd Floor 13 EA 2nd Floor 13 EA 2nd Floor 15 SF 2nd Floor 115 SF 2nd Floor 5 LF 2nd Floor 5 LF 2nd Floor 739 SF 2nd Floor 72 SF 2nd Floor 2 EA 2nd Floor 12 EA 2nd Floor 12 EA 2nd Floor 13 LF 2nd Floor 14 EA 2nd Floor 12 EA 2nd Floor 15 SF 2nd Floor 14 <td< td=""><td>1st Floor 2,264 SF 6 2nd Floor 1 EA 7 2nd Floor 6 LF 6 2nd Floor 870 SF 6 2nd Floor 72 SF 6 2nd Floor 72 SF 6 2nd Floor 2 EA 6 2nd Floor 13 EA 7 2nd Floor 13 EA 7 2nd Floor 16 LF 7 2nd Floor 1 EA 7 2nd Floor 2 EA 6 2nd Floor 2 EA 6 2nd Floor 12 EA 7 2nd Floor 12 EA 7 2nd Floor 15</td><td>Ist Floor 115 SF 7 10+ years 1st Floor 2,264 SF 6 10+ years 2nd Floor 1 EA 7 6-10 years 2nd Floor 6 LF 6 10+ years 2nd Floor 870 SF 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 13 EA 7 6-10 years 2nd Floor 16 LF 7 6-10 years 2nd Floor 115 SF 7 10+ years 2nd Floor 1 EA 7 6-10 years 2nd Floor 1 EA 7 6-10 years 2nd Floor 2 SF 6 10+ years 2nd Floor 7 SF 6 10+ years 2nd Floor 1</td></td<>	1st Floor 2,264 SF 6 2nd Floor 1 EA 7 2nd Floor 6 LF 6 2nd Floor 870 SF 6 2nd Floor 72 SF 6 2nd Floor 72 SF 6 2nd Floor 2 EA 6 2nd Floor 13 EA 7 2nd Floor 13 EA 7 2nd Floor 16 LF 7 2nd Floor 1 EA 7 2nd Floor 2 EA 6 2nd Floor 2 EA 6 2nd Floor 12 EA 7 2nd Floor 12 EA 7 2nd Floor 15	Ist Floor 115 SF 7 10+ years 1st Floor 2,264 SF 6 10+ years 2nd Floor 1 EA 7 6-10 years 2nd Floor 6 LF 6 10+ years 2nd Floor 870 SF 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 2 EA 6 10+ years 2nd Floor 13 EA 7 6-10 years 2nd Floor 16 LF 7 6-10 years 2nd Floor 115 SF 7 10+ years 2nd Floor 1 EA 7 6-10 years 2nd Floor 1 EA 7 6-10 years 2nd Floor 2 SF 6 10+ years 2nd Floor 7 SF 6 10+ years 2nd Floor 1



					0	201 S Faimeiu AVENUE, Chicago, il 60
					Replacement	
Floor - Wood	2nd Floor	756	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	15	LF	7	6-10 years	
Storage/ Closet	2nd Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,109	SF	6	10+ years	
Walls - Plaster/Drywall	2nd Floor	60	SF	6	10+ years	
assroom #206 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	5	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	•	
Floor - Wood Doors Inclu hw	2nd Floor	2 870	SF	6 6	10+ years	
	2nd Floor 2nd Floor		EA	6 7	10+ years	
Lighting - Pendent/Surface		13			6-10 years	
Marker Board	2nd Floor	16		7	6-10 years	
Storage/ Closet	2nd Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	2,264	SF	6	10+ years	
ssroom #207 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	5	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	756	SF	6	10+ years	
Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
Floor - Wood	2nd Floor	756	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
Marker Board	2nd Floor	19	LF	7	6-10 years	
Storage/ Closet	2nd Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,169	SF	6	10+ years	
assroom #208 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	35	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	870	SF	6	10+ years	
Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
Floor - Wood	2nd Floor	870	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	
					•	
Marker Board	2nd Floor	16		7	6-10 years	
Storage/ Closet	2nd Floor	115	SF	7	10+ years	Doint noor booling also
Walls - Plaster/Drywall	2nd Floor	2,264	SF	6	10+ years	Paint near backpacks.
assroom #209 (Regular Classroom)						

Classroom #209 (Regular Classroom)



	Chools						201 S Fairfield AVENUE, Chicago, IL 6062
						Replacement	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	756	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	756	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7		
						10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,169	SF	6	10+ years	
Classroor	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	21	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	770	SF	6		
					-	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,165	SF	6	10+ years	
Classroo	m #211 (Regular Classroom)						
JIASSI001		On d Els su		F A	7	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	785	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	785	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	101	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	10+ years	
laceroo	m #212 (Library)						
1000	AC Units	2nd Floor	0	۲۸		6 10	
210001001	AL, UNIS		2 1,578	EA	7	6-10 years	
1400100			16/8	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor				<u> </u>	
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Water damage.
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor 2nd Floor	10 21	SF SF	5 6	10+ years	Water damage.
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	2nd Floor	10 21 3	SF SF EA	5	10+ years 10+ years	Water damage.
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor 2nd Floor 2nd Floor 2nd Floor	10 21	SF SF EA SF	5 6	10+ years	Water damage.
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor 2nd Floor 2nd Floor	10 21 3	SF SF EA	5 6 6	10+ years 10+ years	Water damage.
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood	2nd Floor 2nd Floor 2nd Floor 2nd Floor	10 21 3 1,588	SF SF EA SF	5 6 6	10+ years 10+ years 10+ years	Water damage.



301100IS					0	201 S Faimeid AVEINUE, Chicago, IL 60629
					Replacement	
Walls - Plaster/Drywall	2nd Floor	1,940	SF	6	10+ years	
Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Water damage.
, , , , , , , , , , , , , , , , , , ,		-	-	-	-)	
Classroom #213 (Regular Classroom)						
AC Units	2nd Floor	1		7	6 10 years	
		=	EA	7	6-10 years	
Casework	2nd Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	785	SF	6	10+ years	
Chalk Board	2nd Floor	36	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	785	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	6-10 years	
Storage/ Closet	2nd Floor	101	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	10+ years	
		.,	•	U U	let jeale	
Classroom #215 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	6	LF	6	10+ years	
		-				
Ceiling - Plaster/Drywall	2nd Floor	785	SF	6	10+ years	
Chalk Board	2nd Floor	14	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	785	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	6-10 years	
Storage/ Closet	2nd Floor	101	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,195	SF	6	10+ years	
Classroom #216 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	794	SF	6	10+ years	
			SF			
Doors - Transom Window	2nd Floor	18		6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	794	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
Marker Board	2nd Floor	18	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,185	SF	6	10+ years	
Walls - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
Classroom #300 (Office)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	376	SF	6	10+ years	
Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
Doors - Wood Doors inclu hw		9	EA	6		
	3rd Floor	2	EA	O	10+ years	



SCHOOIS					6201	S Fairfield AVENUE, Chicago, IL 606
					Replacement	
Floor - Tile	3rd Floor	376	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
Marker Board	3rd Floor	1	LF	7	6-10 years	
Storage/ Closet	3rd Floor	24	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,038	SF	6	10+ years	
,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,		,			, , , , , , , , , , , , , , , , , , ,	
Classroom #302 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	853	SF	6	10+ years	
Doors - Transom Window	3rd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
Floor - Wood	3rd Floor	853	SF	6	-	
	3rd Floor		EA	7	10+ years	
Lighting - Pendent/Surface		13			6-10 years	
Marker Board	3rd Floor	12	LF	7	6-10 years	
Storage/ Closet	3rd Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,935	SF	6	10+ years	
lassroom #303 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	5	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	853	SF	6	10+ years	
Doors - Transom Window	3rd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
Floor - Wood	3rd Floor	853	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor	13	EA	6	6-10 years	
Marker Board	3rd Floor	13	LA	7	6-10 years	
Storage/ Closet	3rd Floor	115	SF	7		
			SF		10+ years	
Walls - Plaster/Drywall	3rd Floor	1,935	55	6	10+ years	
lassroom #304 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	35	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	853	SF	6	10+ years	
Doors - Transom Window	3rd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
Floor - Wood	3rd Floor	853	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
Marker Board	3rd Floor	12	LF	7	6-10 years	
Storage/ Closet	3rd Floor	115	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,935	SF	6	10+ years	
assroom #305 (Regular Classroom)					-	
Casework	3rd Floor	5	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	853	SF	6	10+ years	
Doors - Transom Window	3rd Floor	72	SF	6	10+ years	
		12	0	0	ior years	



Replacement 3rd Floor Doors - Wood Doors inclu hw 2 ΕA 6 10+ years 3rd Floor 853 SF 6 10+ vears Floor - Wood Lighting - Lay-in 3rd Floor 13 ΕA 7 6-10 years Walls - Plaster/Drywall 1,935 SF 6 10+ years 3rd Floor Classroom #306 (Art Room) AC Units 3rd Floor 1 ΕA 7 6-10 years 35 LF Casework 3rd Floor 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 853 SF 6 10+ years Doors - Transom Window SF 3rd Floor 72 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 ΕA 6 10+ years SF Floor - Wood 3rd Floor 853 6 10+ years Lighting - Pendent/Surface 3rd Floor 13 EΑ 7 6-10 years Marker Board LF 3rd Floor 12 7 6-10 years SF 7 6-10 years Storage/ Closet 3rd Floor 115 Walls - Plaster/Drywall 3rd Floor 1.935 SF 6 10+ years Classroom #307 (Regular Classroom) AC Units 3rd Floor FΑ 7 1 6-10 years Casework 3rd Floor 5 LF 6 10+ years SF Ceiling - Plaster/Drywall 3rd Floor 828 6 10+ years Ceiling - Plaster/Drywall 25 SF 6 3rd Floor 10+ years SF Doors - Transom Window 3rd Floor 72 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 ΕA 6 10+ years Floor - Wood 3rd Floor 853 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 13 EΑ 7 6-10 years Marker Board LF 3rd Floor 12 7 6-10 years SF 7 Storage/ Closet 3rd Floor 115 10+ years Walls - Plaster/Drywall 3rd Floor 1.935 SF 6 10+ years Classroom #308 (Regular Classroom) AC Units 3rd Floor FΑ 7 1 6-10 years Casework 3rd Floor 35 LF 6 10+ years SF Ceiling - Plaster/Drywall 3rd Floor 853 6 10+ years Doors - Transom Window SF 3rd Floor 72 6 10+ vears Doors - Wood Doors inclu hw 3rd Floor 2 EΑ 6 10+ years Floor - Tile 3rd Floor 853 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 13 EΑ 7 6-10 years Marker Board LF 7 3rd Floor 26 6-10 years SF Storage/ Closet 3rd Floor 115 7 10+ years SF Walls - Plaster/Drywall 3rd Floor 1.935 6 10+ years Classroom #309 (Regular Classroom) AC Units 3rd Floor ΕA 7 6-10 years 1 LF 7 Casework 3rd Floor 35 10+ years



					Replacement
Ceiling - Plaster/Drywall	3rd Floor	853	SF	7	10+ years
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years
Floor - Wood	3rd Floor	853	SF	6	10+ years
Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years
Marker Board	3rd Floor	26	LF	7	10+ years
Storage/ Closet	3rd Floor	115	SF	7	10+ years
Walls - Plaster/Drywall	3rd Floor	1,935	SF	6	10+ years

Category : Interior

Building : Leased-Main

	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,593	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	6	10+ years	Updated to match current observations
	Doors - Steel Doors incl hw	1st Floor	2	EA	5	0-1 year	Damaged and paint required
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,626	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	7	SF	4	0-1 year	Missing and cracked tiles
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	10,577	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	8	SF	5	0-1 year	Cracks and chipping paint
	Ceiling - Plaster/Drywall	2nd Floor	4,723	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,723	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	42	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	17,114	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,074	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	3rd Floor	1	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,074	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	42	EA	7	6-10 years	
	Lighting - Wall Mounted	3rd Floor	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,824	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	40	SF	7	10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall	Basement	1,341	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	1	EA	6	10+ years	
	Doors - Wood Doors include hw	Basement	1	EA	5	0-1 year	Crumbling and cracking
	Floor - Concrete Epoxy/ Painted	Basement	1,381	SF	7	10+ years	6 6
	Lighting - Pendent/Surface	Basement	5	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,744	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement	1,704	SF	6	10+ years	



Category : Interior			Building : Leased-Main						
	•		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Safety						•			
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	10	EA	7	6-10 years			
	Security Cameras	1st Floor	10	EA	7	6-10 years			
	Occurry Gameras	13(1100)	17		'	o io years			
Stairs									
SIGIIS	Ceiling - Plaster/Drywall	Center stairs East	143	SF	6	10, 10000			
	Floor - Tile Ceramic/ Porcelain	Center stairs East	54	SF	6	10+ years 10+ years			
	Handrails	Center stairs East	84	LF	5	10+ years			
	Lighting - Wall Mounted	Center stairs East	4	EA	6	6-10 years			
	Stairs - Tile	Center stairs East	75	LF	6	10+ years	Ceramic tile.		
	Walls - Plaster/Drywall	Center stairs East	1,653	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Central Stairs West	143	SF	6	,			
				SF	6	10+ years			
	Floor - Terrazzo Floor - Tile Ceramic/ Porcelain	Central Stairs West Central Stairs West	54 54	SF	6	10+ years			
	Handrails	Central Stairs West	54 84	LF	6 7	10+ years			
			84 4		-	10+ years			
	Lighting - Wall Mounted	Central Stairs West		EA	6	6-10 years			
	Stairs - Terrazzo	Central Stairs West	21	LF	6	10+ years			
	Walls - Plaster/Drywall	Central Stairs West	1,653	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Door 1	148	SF	6	10+ years			
	Floor - Terrazzo	Door 1	202	SF	6	10+ years			
	Handrails	Door 1	129	LF	7	10+ years			
	Lighting - Wall Mounted	Door 1	7	EA	7	6-10 years			
	Stairs - Terrazzo	Door 1	71	LF	6	10+ years			
	Walls - Plaster/Drywall	Door 1	2,733	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Door 12 near 216	153	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Door 12 near 216	131	SF	6	10+ years			
	Handrails	Door 12 near 216	97	LF	7	10+ years			
	Lighting - Wall Mounted	Door 12 near 216	5	EA	6	6-10 years			
	Stairs - Tile	Door 12 near 216	60	LF	6	10+ years	Ceramic tile.		
	Walls - Plaster/Drywall	Door 12 near 216	2,173	SF	5	10+ years			
	Ceiling - Plaster/Drywall	Door 4	153	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Door 4	131	SF	6	10+ years			
	Handrails	Door 4	97	LF	7	10+ years			
	Lighting - Wall Mounted	Door 4	5	EA	6	6-10 years			
	Stairs - Tile	Door 4	60	LF	6	10+ years	Ceramic tile.		
	Walls - Plaster/Drywall	Door 4	2,173	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Door 5	148	SF	6	10+ years			
	Floor - Terrazzo	Door 5	202	SF	6	10+ years			
	Handrails	Door 5	129	LF	7	10+ years			
	Lighting - Wall Mounted	Door 5	7	EA	6	6-10 years			
	Stairs - Terrazzo	Door 5	71	LF	6	10+ years			
	Walls - Plaster/Drywall	Door 5	2,733	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Door 6	148	SF	6	10+ years			



Category : Interior			В						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Terrazzo	Door 6	202	SF	6	10+ years			
	Handrails	Door 6	129	LF	7	10+ years			
	Lighting - Wall Mounted	Door 6	7	EA	7	6-10 years			
	Stairs - Terrazzo	Door 6	71	LF	6	10+ years			
	Walls - Plaster/Drywall	Door 6	2,733	SF	6	10+ years			
	Ceiling - Exposed	Door 6.1 near 215	153	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Door 6.1 near 215	131	SF	6	10+ years			
	Handrails	Door 6.1 near 215	97	LF	7	10+ years			
	Lighting - Wall Mounted	Door 6.1 near 215	5	EA	7	6-10 years			
	Stairs - Tile	Door 6.1 near 215	60	LF	6	10+ years	Ceramic tile.		
	Walls - Plaster/Drywall	Door 6.1 near 215	2,173	SF	6	10+ years			



Category : Site Building : Site Recommend Location Replacement Item - Type Quantity UOM Rank **Comments** Group Civil/Drainage Civil/ Drainage - Catch Basin Entire Site FΑ 6 4 6-10 years ΕA 6 Civil/ Drainage - Site Drain Entire Site 1 6-10 years Civil/ Drainage - Site Manhole Entire Site 4 ΕA 6 6-10 years Fencing Fencing - Guard Rail LF Entire Site 96 6 6-10 years LF Fencing - Old Standard Ornamental Entire Site 269 7 10+ years Landscape Benches Entire Site 4 ΕA 7 10+ years Entire Site SF Landscape - Hardscape- Concrete 177 6 10+ years Play Area - Hardscape- Asphalt Entire Site 1.350 SF 4 0-1 year Large cracking. FΑ Trash Receptacles Entire Site 4 6 10+ years Parking Lot Surface - Asphalt Entire Site 10.000 SF 7 10+ vears Surface - Asphalt SF Entire Site 18.399 4 0-1 year Large cracking and potholes. Playground Equipment - Pre K 3-5 2 ΕA 6 East 10+ years Surface - Poured Surface East 2,300 SF 6 10+ years Sidewalks Sidewalks - Perimeter Sidewalks SF 6 North, East and West 1.746 10+ years Signage FΑ 6 Flag Pole - Building Mounted Flag Pole Entire Site 1 10+ years ΕA Marquee - Free Standing Back Lighted Entire Site 1 6 6-10 years Only one located at building by entrance 1.

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Leased-Main				(/					
Art Room	Regular Classroom	3rd Floor	306	306	853	93	45	N	Y
Library	Art Room	2nd Floor	212	212	1,588	40	30	N	N
Office	Regular Classroom	3rd Floor	300	300	376	47	22	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	870	100	60	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	870	100	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	870	100	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	739	61	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	870	100	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	756	61	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	870	100	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	756	61	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	870	100	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	756	61	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	770	40	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	785	40	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	785	40	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	794	40	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	785	40	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	794	40	30	N	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	853	93	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	853	93	45	N	Y