

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1973	1	19,415
Modular 1 (4-Classroom)	1999	1	3,988
Campus Total			23,403

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Entrance 1 - Northwest	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 1 - Northwest	2	EA	5	1-2 years	Door frames are rusting
	Exterior Doors - Transom Lite	Entrance 1 - Northwest	1	EA	6	6-10 years	
	Power Door Operator and Controls	Entrance 1 - Northwest	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 2 - Northeast	2	EA	5	1-2 years	Door and frame are rusting
	Exterior Doors - Transom Lite	Entrance 2 - Northeast	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	Entrance 2.1 - NE - Outside yard storage	1	EA	4	2-5 years	
	Entrance Control - Audio and Video	Entrance 3 - Southeast	1	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	Entrance 3 - Southeast	2	EA	5	1-2 years	Door and frames are rusting at the base and need attention
	Exterior Doors - Transom Lite	Entrance 3 - Southeast	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 3 - Southeast	8	LF	5	1-2 years	Hairline cracks in concrete
	Exterior Doors - Exterior Steel Door	Entrance 3.1 - East - Outside yard storage	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 4 - Southwest	2	EA	5	1-2 years	Bottom of doors and frames are rusting
	Exterior Doors - Transom Lite	Entrance 4 - Southwest	1	EA	6	6-10 years	3
	Exterior Doors - Exterior Steel Door	Entrance G1 - Greenhouse	1	EA	6	6-10 years	
_Foundati	on						
	Foundation - Concrete	Entire Building	592	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	19,415	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main	_	
	Hama Tama		Owentites		Daula	Recommend	0
Group	Item - Type Topping	Location	Quantity	UOM	Rank	Replacement	Comments
	ropping						
ighting							
- <u>9</u> 9-	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	6-10 years	
Roof Sys	stem						
	Coping - Metal	4-Parking lot	70	LF	6	2-5 years	
	Coping - Metal	4-Parking lot	10	LF	4	0-1 year	Bent, damaged coping
	Downspouts - Exterior Downspouts	4-Parking lot	12	LF	4	0-1 year	Missing downspout
	Roof - Asphalt Gravel Ballast	4-Parking lot	900	SF	6	2-5 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	4-Parking lot	900	SF	7	10+ years	This item was under canopy and walls in the previous assessment
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 1	16	LF	6	6-10 years	
	Coping - Metal	Roof 1	592	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 1	48	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 1	592	LF	6	6-10 years	
	Roof - Modified Bitumen	Roof 1	15,663	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 1	11	ĒA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	15,663	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Metal	Roof 2	250	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	24	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 2	250	LF	6	6-10 years	
	Roof - Modified Bitumen	Roof 2	3,752	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 2	3,752	SF	7	10+ years	
	Concrete Topping		5,752	01	,	TOF years	
Valls							
	Exterior Walls - Brick	Entire Building	5,493	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	120	SF	4	1-2 years	Broken brick near entrances: Crack along control joint, deteriorated mortar
Vindows							
	Lintels - Steel	Entire Building	296	LF	7	10+ years	Priority replacement (a.k.a. RUL) changed to update/correct to match current observations
	Windows - Sash Aluminum	Entire Building	1,200	SF	7	10+ years	Priority replacement (a.k.a. RUL) changed to update/correct to matcl current observations



Catego	ry : Electrical		В	uilding	: Main		47 5 Wabash AVENOE, Chicago, ie 00010
			-			Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System		10.115	05			
	Security System - CCTV	1st Floor	19,415	SF	6	6-10 years	
	Security System - Intrusion Detection	1st Floor	19,415	SF	6	6-10 years	Overstitus above and to sup data (as most to
	Exit Signs - Corridors and Stairs	1st Floor	8	EA	7	6-10 years	Quantity changed to update/correct to match current observations
	Exit Signs - Multipurpose Room	1st Floor	1	EA	6	0-1 year	Sign is not illuminated. Quantity changed to update/correct to match current observations.
	Exit Signs - Multipurpose Room	1st Floor	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st Floor	3,580	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	1st Floor	3,730	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	1st Floor	410	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	5	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	1st Floor	2	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
Main Se	rvice						
	PA System	1st Floor	19,415	SF	6	2-5 years	Also serves Modular; system is operational but very dated.
	Main Electrical Service - 800 A and 120/208/3PH	1st Floor	1	EA	4	2-5 years	Equipment is original to the building. If live-front equipment will be replaced, recommended all original electrical equipment should also be replaced.
	Main Electrical Service- Live Front - 2000 A 120/208/3PH	Electrical Room	1	EA	4	2-5 years	Original to the building, operational but deteriorated. Recommend replacement along with dead front equipment.
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	oquipinoni
Power D	Distribution						
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	6-10 years	Quantity changed to update/correct to match current observations
	Lighting and Power Panels - Above 100 A	1st Floor	7	EA	6	6-10 years	Quantity changed to update/correct to match current observations
	Main Distribution Panels - 400 - 600 amp	1st Floor	2	EA	6	6-10 years	Quantity changed to update/correct to match current observations
	Main Distribution Panels - Greater than 600	1st Floor	2	EA	6	6-10 years	Quantity changed to update/correct to



	SChools					23	47 S Wabash AVENUE, Chicago, IL 60616
Catego	ry : Electrical		В	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	amp						match current observations
Catego	ry : Fire Protection		В	Building	: Main		
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	19,415	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	19,415	SF	6	6-10 years	
Catego	ry : Mechanical		B	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hanc	Iling Systems						
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	7	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	2	EA	7	10+ years	
	Electric and DX Cooling with Self Contained						
	Compressor - 11 - 20 tons	Deef	4		7	10	
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained	Roof	1	EA	1	10+ years	
	Compressor - 21 - 30 tons						
Heating	Devices						
- 0	Wall Heater - Electric	Entire Building	16	EA	6	6-10 years	
Tompor	ature Control						
rempera	Electric Controls	Entire Building	19,415	SF	7	10+ years	Controls are integral to the RTUs
		Entric Duriding	10,410	01	'	Tor years	which were replaced in 2019.
	Electric Thermostat	Entire Building	3	EA	7	10+ years	
	Electric Thermostat	Entire Building	1	EA	6	10+ years	Serves rooftop MAU. Building
		C C				-	Engineer has been at this school for
							five years and has no information or
							the location of this thermostat.
							Unable to find it anywhere in the
							Culinary Room which is served by the MAU.
Ventilatio							
venuiatio	Exhaust Fans- Roof Mounted - 1501 - 8000	1st Floor	5	EA	7	10+ years	Quantity changed to update/correct
	CFM		0	<u> </u>	,	ie. youro	match current observations
	Exhaust Fans- Roof Mounted - 1501 - 8000	1st Floor	1	EA	3	1-2 years	Older unit not able to be repaired;



Catego	ry : Mechanical		В	uilding	: Main		
_			•			Recommend	•
Group	Item - Type CFM	Location	Quantity	UOM	Rank	Replacement	Comments being replaced by a repurposed 15-
	CFM						vear-old unit.
	Exhaust Fans- Roof Mounted - 500 - 1500	1st Floor	6	EA	6	6-10 years	No issue with supplying power to the
	CFM						rooftop exhaust fans. Quantity
							changed to update/correct to match
	Exhaust Fans- Roof Mounted - Less than	1st Floor	1	EA	6	6-10 years	current observations No issue with supplying power to the
	500 CFM			L /(Ū	o royouro	rooftop exhaust fans. Quantity
							changed to update/correct to match
			40		-	40	current observations
	Roof Mounted Duct Work	1st Floor	40	LF	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
•			0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	Gas Heater - 150000 - 300000 BTU/HR	Storage Room	1	EA	6	2-5 years	Apparently installed 2005
				_ / (Ũ	2 0 90010	Apparenti instance 2000
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	19,415	SF	3	2-5 years	Most piping in the building is original
							galvanized material which is corroding and has been pipe-
							clamped. Domestic water piping at
							this school should be upgraded to
	Domestic Piping-Hot Water from Risers to	Entire Building	19,415	SF	3	2-5 years	contemporary materials. Most piping in the building is original
	Fixtures	Entire Building	19,415	35	3	2-5 years	galvanized material which is
							corroding and has been pipe-
							clamped. Domestic water piping at
							this school should be upgraded to contemporary materials.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	19,415	SF	3	2-5 years	Most piping in the building is original
	(Horizontal Lines)	J. J					galvanized material which is
							corroding and has been pipe- clamped. Domestic water piping at
							this school should be upgraded to
							contemporary materials.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	19,415	SF	3	2-5 years	Most piping in the building is original
	(from Risers to Fixtures)						galvanized material which is corroding and has been pipe-
							clamped. Domestic water piping at
							this school should be upgraded to
	Sonitory Dining	Entiro Puilding	10 115	<u>و</u> ر	e	6 10 1000	contemporary materials.
	Sanitary Piping	Entire Building	19,415	SF	6	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		Ť.
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storm Piping	Entire Building	19,415	SF	6	6-10 years	
	Vent Piping	Entire Building	19,415	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		
	·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	100 Main office	900	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100 Main office	1	EA	6	6-10 years	
	Floor - Tile	100 Main office	900	SF	6	6-10 years	
	Lighting - Lay-in	100 Main office	14	EA	7	6-10 years	
	Power Distribution	100 Main office	22	EA	6	6-10 years	
	Storage/ Closet	100 Main office	130	SF	5	6-10 years	
	Walls - Concrete Block	100 Main office	2,310	SF	7	6-10 years	
	Ceiling - Lay-in	100B Assistant principal's office	138	SF	6	6-10 years	
	Doors - Transom Window	100B Assistant principal's office	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100B Assistant principal's office	1	EA	6	6-10 years	
	Floor - Carpet	100B Assistant principal's office	138	SF	6	6-10 years	
	Lighting - Lay-in	100B Assistant principal's office	2	EA	7	6-10 years	
	Power Distribution	100B Assistant principal's office	8	EA	6	6-10 years	
	Walls - Concrete Block	100B Assistant principal's office	320	SF	7	6-10 years	
	Ceiling - Lay-in	100C, Principal's office	192	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100C, Principal's office	1	EA	6	6-10 years	
	Floor - Carpet	100C, Principal's office	192	SF	7	10+ years	
	Lighting - Lay-in	100C, Principal's office	3	EA	7	6-10 years	
	Power Distribution	100C, Principal's office	12	EA	6	6-10 years	
	Walls - Concrete Block	100C, Principal's office	562	SF	7	10+ years	
	Ceiling - Lay-in	100D	78	SF	6	6-10 years	
	Doors - Transom Window	100D	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100D	1	EA	6	6-10 years	
	Floor - Carpet	100D	78	SF	6	6-10 years	
	Lighting - Lay-in	100D	1	EA	7	6-10 years	
	Power Distribution	100D	4	EA	6	6-10 years	
	Walls - Concrete Block	100D	320	SF	7	6-10 years	
	Ceiling - Lay-in	100E	78	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100E	1	EA	6	6-10 years	
	Floor - Carpet	100E	78	SF	6	6-10 years	
	Lighting - Lay-in	100E	1	EA	7	6-10 years	
	Power Distribution	100E	4	EA	6	6-10 years	
	Walls - Concrete Block	100E	320	SF	7	6-10 years	
	Ceiling - Lay-in	100F	162	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100F	1	EA	6	6-10 years	
	Floor - Carpet	100F	162	SF	7	6-10 years	
				EA			



Catego	ry : Room		В	uilding	: Main		Ser S Wabash Avenue, Chicago, ie 00010
U	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	100F	4	EA	6	6-10 years	
	Walls - Concrete Block	100F	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	102B lunch room manager office	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102B lunch room manager office	2	EA	6	6-10 years	
	Floor - Tile	102B lunch room manager office	56	SF	6	6-10 years	
	Lighting - Pendent/Surface	102B lunch room manager office	1	EA	7	6-10 years	
	Power Distribution	102B lunch room manager office	6	EA	6	6-10 years	
	Walls - Concrete Block	102B lunch room manager office	239	SF	7	10+ years	
	Work SInk	102B lunch room manager office	1	EA	7	10+ years	
	Ceiling - Lay-in	105 Building engineer's office	64	SF	6	6-10 years	
	Ceiling - Lay-in	105 Building engineer's office	2	SF	5	1-2 years	
	Doors - Wood Doors inclu hw	105 Building engineer's office	1	EA	6	6-10 years	
	Floor - Carpet	105 Building engineer's office	1	SF	4	6-10 years	
	Lighting - Lay-in	105 Building engineer's office	2	EA	7	6-10 years	
	Power Distribution	105 Building engineer's office	4	EA	6	6-10 years	
	Walls - Concrete Block	105 Building engineer's office	268	SF	7	10+ years	
	Ceiling - Lay-in	109 Teachers lunch room	196	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	109 Teachers lunch room	1	EA	6	6-10 years	
	Floor - Tile	109 Teachers lunch room	196	SF	6	6-10 years	
	Lighting - Lay-in	109 Teachers lunch room	4	EA	7	10+ years	
	Power Distribution	109 Teachers lunch room	8	EA	6	6-10 years	
	Walls - Concrete Block	109 Teachers lunch room	536	SF	7	10+ years	
	Work SInk	109 Teachers lunch room	1	EA	7	10+ years	
	Ceiling - Lay-in	111A Student lounge inside 111	230	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	111A Student lounge inside 111	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	111A Student lounge inside 111	230	SF	7	10+ years	
	Lighting - Lay-in	111A Student lounge inside 111	4	EA	7	6-10 years	
	Walls - Concrete Block	111A Student lounge inside 111	90	SF	6	10+ years	
	Walls - Plaster/Drywall	111A Student lounge inside 111	370	SF	6	10+ years	
	Ceiling - Lay-in	112	143	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	112	1	EA	6	10+ years	
	Floor - Tile	112	143	SF	7	10+ years	
	Lighting - Lay-in	112	2	EA	7	10+ years	
	Power Distribution	112	12	EA	6	6-10 years	
	Walls - Concrete Block	112	436	SF	7	10+ years	
	Ceiling - Lay-in	118. Nurse Office	282	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	118. Nurse Office	1	EA	6	6-10 years	
	Floor - Tile	118. Nurse Office	282	SF	6	6-10 years	
	Lighting - Lay-in	118. Nurse Office	3	EA	7	6-10 years	
	Power Distribution	118. Nurse Office	10	EA	6	6-10 years	
	Walls - Concrete Block	118. Nurse Office	631	SF	7	10+ years	
	Work SInk	118. Nurse Office	1	EA	7	10+ years	
	Ceiling - Lay-in	122	90	SF	6	6-10 years	
	Doors - Transom Window	122	8	SF	6	6-10 years	



	ry : Room		R	uilding	: Main	20	47 S Wabash AVENUE, Chicago, iE 60616
Julogo			5	anang	· man	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	122	1	EA	6	6-10 years	
	Floor - Tile	122	90	SF	6	6-10 years	
	Lighting - Lav-in	122	1	EA	7	6-10 years	
	Power Distribution	122	4	EA	6	6-10 years	
	Storage/ Closet	122	5	SF	7	6-10 years	
	Walls - Concrete Block	122	325	SF	7	6-10 years	
	Ceiling - Lay-in	124	90	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	124	1	EA	6	6-10 years	
	Floor - Tile	124	90	SF	6	6-10 years	
	Lighting - Lay-in	124	1	EA	7	6-10 years	
	Power Distribution	124	4	EA	6	6-10 years	
	Storage/ Closet	124	5	SF	7	6-10 years	
	Walls - Concrete Block	124	325	SF	7	6-10 years	
	Ceiling - Lay-in	126 - Counselor	90	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	126 - Counselor	1	EA	6	6-10 years	
	Floor - Tile	126 - Counselor	90	SF	6	6-10 years	
	Lighting - Lay-in	126 - Counselor	1	EA	7	6-10 years	
	Power Distribution	126 - Counselor	4	EA	6	6-10 years	
	Storage/ Closet	126 - Counselor	5	SF	7	6-10 years	
	Walls - Concrete Block	126 - Counselor	325	SF	7	6-10 years	
Library							
	Casework	111- Industrial Arts	33	LF	6	6-10 years	
	Ceiling - Lay-in	111- Industrial Arts	943	SF	7	6-10 years	
	Doors - Side-lite	111- Industrial Arts	12	SF	6	6-10 years	
	Doors - Transom Window	111- Industrial Arts	3	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	111- Industrial Arts	943	SF	7	10+ years	
	Lighting - Lay-in	111- Industrial Arts	14	EA	7	10+ years	
	Walls - Concrete Block	111- Industrial Arts	566	SF	7	10+ years	
	Walls - Plaster/Drywall	111- Industrial Arts	370	SF	7	10+ years	
Locker/S	hower Room	Charage 440	404			0.40	
	Ceiling - Plaster/Drywall	Storage 110	181	SF	6	6-10 years	
	Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain	Storage 110	1	EA SF	6	6-10 years	
		Storage 110	181	-	6	10+ years	
	Floor Drain	Storage 110	1	EA EA	7	6-10 years	
	Lighting - Pendent/Surface Walls - Concrete Block	Storage 110 Storage 110	3 702	SF	6 7	6-10 years 10+ years	
		Slorage 110	102	36	1	IUT years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	102 Lunch room/107 Gymnasium	5,975	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 Lunch room/107 Gymnasium	12	EA	7	6-10 years	
	Floor - Tile	102 Lunch room/107 Gymnasium	5,975	SF	7	6-10 years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Lay-in 102 Lunch room/107 Gymnasium 4 EΑ 6-10 vears 7 Lighting - Pendent/Surface 102 Lunch room/107 Gymnasium 32 ΕA 7 6-10 years Serving Line 102 Lunch room/107 Gymnasium 18 LF 6 6-10 years Storage/ Closet 56 SF 5 102 Lunch room/107 Gymnasium 6-10 years SF 5 Storage/ Closet 102 Lunch room/107 Gymnasium 56 6-10 years SF Walls - Concrete Block 7 102 Lunch room/107 Gymnasium 7,632 10+ years Walls - Metal Panel 102 Lunch room/107 Gymnasium 1,023 SF 7 10+ years MDF IDF Doors - Wood Doors inclu hw 101 1 EΑ 7 6-10 years 307 SF 5 6-10 years Finishes 101 Stain/missing tile Other Cooling Unit 101 1 EΑ 7 6-10 years Fan Mechanical/ Service Rooms 1st Floor SF Janitor's Closet 29 5 10+ years Mechanical/ Service Rooms 1st Floor 101 SF 7 10+ years SF 7 Storage Room 1st Floor 42 10+ years Storage Room SF 7 1st Floor 141 10+ years SF Vaults 7 1st Floor 101 10+ years Restroom SF 7 Accessories 109 Teachers lunch rm 23 6-10 years Ceiling - Plaster/Drywall 23 SF 10+ years 109 Teachers lunch rm 6 7 Doors - Wood Doors inclu hw 109 Teachers lunch rm 1 ΕA 6-10 years SF Floor - Tile Ceramic/ Porcelain 109 Teachers lunch rm 23 7 10+ vears ΕA 7 10+ years Lavatory 109 Teachers lunch rm 1 Lighting - Pendent/Surface 7 109 Teachers lunch rm 1 EΑ 6-10 vears Walls - Concrete Block 109 Teachers lunch rm 158 SF 7 10+ vears Water Closet 109 Teachers lunch rm ΕA 7 10+ years 1 SF 7 Accessories 118. Nurse office. 60 6-10 years Ceiling - Plaster/Drywall SF 6 118. Nurse office. 60 10+ years Doors - Wood Doors inclu hw 118. Nurse office. 1 EΑ 6 6-10 years Floor - Tile Ceramic/ Porcelain 60 SF 6 118. Nurse office. 10+ years Floor Drain 118. Nurse office. 2 EΑ 7 6-10 years 118. Nurse office. 1 EΑ 7 10+ years Lavatory Lighting - Lay-in 118. Nurse office. 1 EΑ 7 6-10 years Showers 118. Nurse office. 1 EA 7 6-10 years Walls - Concrete Block 118. Nurse office. 171 SF 7 10+ years SF 7 Walls - Tile Ceramic/ Porcelain 118. Nurse office. 74 10+ years Water Closet ΕA 7 118. Nurse office. 1 10+ years SF 7 Accessories Across from 100B 23 6-10 years Ceiling - Plaster/Drywall Across from 100B 23 SF 6 6-10 years Doors - Wood Doors inclu hw Across from 100B 1 FΑ 6 6-10 years



Category : Room		B	uilding	• Main	20	47 5 Wabash AVENOE, Chicago, ie 00010	
Calego	iy. Room		J	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Across from 100B	23	SF	6	6-10 years	
	Lavatory	Across from 100B	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Across from 100B	1	EA	7	6-10 years	
	Walls - Concrete Block	Across from 100B	158	SF	7	6-10 years	
	Water Closet	Across from 100B	1	EA	7	6-10 years	
	Accessories	Adjascent to rm 116 (culinary class room)	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Adjascent to rm 116 (culinary class room)	23	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Adjascent to rm 116 (culinary class room)	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Adjascent to rm 116 (culinary class room)	23	SF	7	10+ years	
	Lavatory	Adjascent to rm 116 (culinary class	1	EA	7	10+ years	
	Lighting - Pendent/Surface	room) Adjascent to rm 116 (culinary class room)	1	EA	7	6-10 years	
	Walls - Concrete Block	Adjascent to rm 116 (culinary class room)	158	SF	7	10+ years	
	Water Closet	Adjascent to rm 116 (culinary class room)	1	EA	7	10+ years	
	Accessories	Boys restroom adjascent to entrance	182	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys restroom adjascent to entrance	182	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys restroom adjascent to entrance	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boys restroom adjascent to entrance	182	SF	7	10+ years	
	Floor Drain	Boys restroom adjascent to entrance	1	EA	7	6-10 years	
	Hand Dryer	Boys restroom adjascent to entrance	1	EA	7	6-10 years	
	Lavatory	Boys restroom adjascent to entrance	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys restroom adjascent to entrance	3	EA	7	6-10 years	
	Partitions	Boys restroom adjascent to entrance	2	EA	7	6-10 years	
	Urinals	Boys restroom adjascent to entrance	2	EA	7	10+ years	
	Walls - Concrete Block	Boys restroom adjascent to entrance	623	SF	7	10+ years	
	Water Closet	Boys restroom adjascent to entrance	2	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-		3					
	Accessories	Girls restroom, adjascent to exit 2	184	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls restroom, adjascent to exit 2	184	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls restroom, adjascent to exit 2	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Girls restroom, adjascent to exit 2	184	SF	6	10+ years	
	Floor Drain	Girls restroom, adjascent to exit 2	1	EA	7	6-10 years	
	Hand Dryer	Girls restroom, adjascent to exit 2	1	EA	7	6-10 years	
	Lavatory	Girls restroom, adjascent to exit 2	2	EA	7	10+ years	
	Lighting - Lay-in	Girls restroom, adjascent to exit 2	3	EA	7	6-10 years	
	Partitions	Girls restroom, adjascent to exit 2	3	EA	7	6-10 years	
	Walls - Concrete Block	Girls restroom, adjascent to exit 2	623	SF	7	10+ years	
	Water Closet	Girls restroom, adjascent to exit 2	3	EA	7	10+ years	
	Accessories	Mens room, across from rm 111	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mens room, across from rm 111	23	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mens room, across from rm 111	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Mens room, across from rm 111	23	SF	7	10+ years	
	Lavatory	Mens room, across from rm 111	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Mens room, across from rm 111	1	EA	7	6-10 years	
	Walls - Concrete Block	Mens room, across from rm 111	158	SF	7	10+ years	
	Water Closet	Mens room, across from rm 111	1	ĒA	7	10+ years	
	Accessories	Outside of rm 109 (teachers lunch	23	SF	7	6-10 years	
		room)			-	j	
	Ceiling - Plaster/Drywall	Outside of rm 109 (teachers lunch	23	SF	6	6-10 years	
		room)		0.	· ·		
	Doors - Wood Doors inclu hw	Outside of rm 109 (teachers lunch	1	EA	7	6-10 years	
		room)		_/ `	-		
	Floor - Tile Ceramic/ Porcelain	Outside of rm 109 (teachers lunch	23	SF	7	10+ years	
		room)	20	0.	•	io: youro	
	Lavatory	Outside of rm 109 (teachers lunch	1	EA	7	10+ years	
	Lavalory	room)	1		'	Tor years	
	Lighting - Pendent/Surface	Outside of rm 109 (teachers lunch	1	EA	7	6-10 years	
		room)		L/\	'	o ro youro	
	Walls - Concrete Block	Outside of rm 109 (teachers lunch	158	SF	7	10+ years	
		room)	150	01	'	TOF years	
	Water Closet	Outside of rm 109 (teachers lunch	1	EA	7	10+ years	
	Water Closet	room)	1	LA	'	TUT years	
	Accessories	Restroom near 100F	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom near 100F	23	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom near 100F	23	EA	6	10+ years	
			23	SF			
	Floor - Tile Ceramic/ Porcelain	Restroom near 100F	23		6	10+ years	
	Lavatory	Restroom near 100F	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom near 100F	1	EA	6	6-10 years	
	Walls - Concrete Block	Restroom near 100F	158	SF	6	10+ years	
	Water Closet	Restroom near 100F	1	EA	6	10+ years	



Building : Main Category : Room Recommend UOM Group Location Item - Type Quantity Rank **Replacement** Comments Womens toilet, across from room SF Accessories 23 7 6-10 years 102 Ceiling - Plaster/Drywall Womens toilet, across from room 23 SF 7 10+ years 102 Womens toilet, across from room Doors - Wood Doors inclu hw 1 ΕA 6 6-10 years 102 Floor - Tile Ceramic/ Porcelain Womens toilet, across from room 23 SF 6-10 years 6 102 Lavatory Womens toilet, across from room 1 ΕA 7 10+ years 102 Lighting - Pendent/Surface Womens toilet, across from room ΕA 7 6-10 years 1 102 Walls - Concrete Block Womens toilet, across from room SF 158 7 10+ years 102 Water Closet Womens toilet, across from room 1 ΕA 7 10+ years 102

Category : Classroom Bu					: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #108 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	436	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	436	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	646	SF	7	10+ years	
Classroo	m #113 (Regular Classroom)						
	Casework	1st Floor	15	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	460	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	460	SF	6	6-10 years	
	Kiln	1st Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	382	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	185	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	198	SF	6	10+ years	
Classroo	m #113 A (Art Room)						
	Casework	1st Floor	18	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	460	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	12	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		R	uilding	• Main	20	347 S Wabash AVENUE, Chicago, IL 60616
Calego			Bunang : Man				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	Commente
	Floor - Tile	1st Floor	460	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	6	EA	7	10+ years	
	Storage/ Closet	1st Floor	253	SF	5	6-10 years	
	Walls - Concrete Block	1st Floor	291	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	185	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	198	SF	7	10+ years	
Classroo	om #116 (Culinary)						
	Ceiling - Lay-in	1st Floor	1,330	SF	6	6-10 years	
	Culinary Exhaust Hood - Type I	1st Floor	1,000	EA	7	10+ years	
	Culinary Exhaust Hood - Type II	1st Floor	1	EA	7	10+ years	
	Culinary Kitchen Equipment	1st Floor	17	EA	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Quarry	1st Floor	1,330	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	748	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	373	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	280	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #117 (Regular Classroom)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	519	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	519	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	517	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	195	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #121 (Other Instructional Use)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	634	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	634	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Storage/ Closet	1st Floor	15	SF	5	6-10 years	
	Walls - Concrete Block	1st Floor	1,002	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	65	SF	6	6-10 years	
	Work Sink	1st Floor	3	EA	7	6-10 years	
		10(1100)	5		'	o io youio	



Category : Classroom Building : Main							
						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #123 (Art Room)						
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	487	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	487	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	858	SF	7	6-10 years	
	Walls - Metal Panel	1st Floor	240	SF	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classroo	m #125 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	487	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	487	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	378	SF	7	6-10 years	
	Walls - Metal Panel	1st Floor	480	SF	7	6-10 years	
Classroo	m #127 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	487	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	487	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	618	SF	7	6-10 years	
	Walls - Metal Panel	1st Floor	240	SF	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Catogo	ry : Interior		D	uilding	· Main		
Jaiego	y . Interior		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	nem - Type		wuantity		Nank	Replacement	Commetit2
Corridor			0.750	05	<u> </u>	0.40	
	Ceiling - Lay-in	1st Floor	3,750	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	6-10 years	
	Drinking Fountains - Double Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,750	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	88	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	102	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	17,125	SF	7	6-10 years	



Catego	ry : Interior		Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Safety							
	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	



Catego	ry : Exterior		В	uilding	: Modul	ar 1 (4-Classro Recommend	om)
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	21	Location	Quantity		Nalik	Replacement	Comments
Entrance		Entrance E. North			0	0.40	
	Exterior Doors - Exterior Steel Door	Entrance 5 - North	1	EA	6	6-10 years	
	Exterior Stairs - Steel or Aluminum	Entrance 5 - North	16	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Entrance 5 - North	21	LF	6	6-10 years	Cleaning
	Exterior Doors - Exterior Steel Door	Entrance 6 - South	1	EA	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 6 - South	70	LF	6	6-10 years	Cleaning
	Ramps - Steel or Aluminum	Entrance 6 - South	36	LF	6	6-10 years	
Foundati	ion						
	Foundation - Concrete	Entire Building	254	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	3,988	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	2-5 years	
Roof Sys	stem						
	Coping - Metal	Roof 3	254	LF	7	6-10 years	
	Downspouts - Exterior Downspouts	Roof 3	144	LF	7	6-10 years	
	Downspouts - Exterior Downspouts	Roof 3	24	LF	5	1-2 years	Pipe Clamp at section of downspour deteriorated mortar at pipe junction
	Roof - Asphalt Shingle	Roof 3	93	SF	7	10+ years	
	Roof - EPDM/ Synthetic Rubber	Roof 3	3,988	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3	3,988	SF	7	6-10 years	
Walls							
<u></u>	Canopy - Metal	Entire Building	100	SF	7	6-10 years	
	Exterior Walls - Vinyl Siding	Entire Building	2,908	SF	7	6-10 years	
	Exterior Walls - Vinyl Siding	Entire Building	12	SF	4	1-2 years	Damaged vinyl siding
Windows	3						
	Guard - Guards perforated	Entire Building	336	SF	6	6-10 years	
	Windows - Louver	Entire Building	4	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	336	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	6	0-1 year	Not working



Catego	ry : Electrical		Building : Modular 1 (4-Classroom)						
Juicgo			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Exit Signs - Corridors and Stairs	1st Floor	1	EA	6	6-10 years	Quantity changed to update/correct to match current observations		
	Emergency Battery Packs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	Quantity changed to update/correct to match current observations		
	Emergency Battery Packs - Students Toilets	1st Floor	1	EA	6	6-10 years	Boys room only. Quantity changed to update/correct to match current observations.		
	Security System - CCTV	Entire Building	3,988	SF	6	6-10 years	Served by Main		
Main Se	rvice								
	PA System	Entire Building	3,988	SF	7	10+ years	Served by Main		
Power D	istribution								
	Lighting and Power Panels - 100 A	1st Floor	3	EA	6	6-10 years			
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	6-10 years			
	Main Distribution Panels - 400 - 600 amp	1st Floor	1	EA	6	6-10 years			
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	om)		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Fire Alar	m								
	Fire Alarm_System	Entire Building	3,988	SF	6	6-10 years	No strobes or pull stations		
Sprinkle									
	Sprinkler Heads	Entire Building	3,988	SF	7	6-10 years			
	Sprinkler Piping	Entire Building	3,988	SF	6	6-10 years			
	Wet Sprinkler System	Entire Building	3,988	SF	6	6-10 years			
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	om)		
-			• • • •			Recommend	•		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Tempera	ature Control								
	Electric Controls	1st Floor	3,988	SF	6	6-10 years	Exterior wall-mounted unit ventilators are equipped with internal controls		
	Electric Thermostat	1st Floor	3	EA	7	6-10 years	• ··· · · · · · · · · · · · · · · · · ·		
	Electric Thermostat	1st Floor	1	EA	6	6-10 years	Quantity changed to update/correct to match current observations		
Unit Ven	tilation								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	4	EA	2	2-5 years	Units were already six years old when the Modular went up. They have been in service for 28 years, can no		



Catego	ry : Mechanical		Building : Modular 1 (4-Classroom)							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
							longer produce both heating and			
							cooling, and replacement parts are no			
							longer available. There is concern			
							that one or more of them will fail in			
							winter and cause water pipes to			
							freeze and burst.			
Ventilatio	n n									
venillalio	Exhaust Fans- Roof Mounted - Less than	Entire Building	6	EA	6	6-10 years	Inside ceiling. Total of six â€" one for			
	500 CFM	Entite Building	0	LA	0	0-10 years	each classroom and one for each			
							restroom. Units fully operational at			
							the time of assessment.			
Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (4-Classro	om)			
•			0			Recommend	0			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Hot Wate										
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	2-5 years				
D										
Piping			0.000	05		0.40				
	Domestic Piping-Hot Water Return Lines	Entire Building	3,988	SF	6	6-10 years				
	Domestic Piping-Hot Water from Risers to	Entire Building	3,988	SF	6	6-10 years				
	Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building	2 000	SF	6	6 10 1000				
	(Horizontal Lines)	Entire Building	3,988	SF	0	6-10 years				
	Domestic Piping-Hot/Cold Water Supply	Entire Building	3,988	SF	6	6-10 years				
	(from Risers to Fixtures)	Entite Building	3,900	36	0	0-10 years				
	Sanitary Piping	Entire Building	3,988	SF	6	6-10 years				
	Storm Piping	Entire Building	3,988	SF	6	6-10 years				
	Vent Piping	Entire Building	3,988	SF	6	6-10 years				
	· •	g	0,000	•	Ū					
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)			
						Recommend				
Group	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroo	m #11 (Regular Classroom)									
	Ceiling - Plaster/Drywall	1st Floor	654	SF	7	6-10 years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years				
	Floor - Tile	1st Floor	654	SF	7	6-10 years				
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years				
	Marker Board	1st Floor	20	LF	7	6-10 years				
	Storage/ Closet Walls - Vinyl Coated Gypsum Panel	1st Floor 1st Floor	65 626	SF SF	5 7	6-10 years 6-10 years				



Catego	ry : Classroom		Building : Modular 1 (4-Classroom)					
_			•			Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #12 (Regular Classroom)							
	Ceiling - Plaster/Drywall	1st Floor	654	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years		
	Floor - Tile	1st Floor	654	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Storage/ Closet	1st Floor	65	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st Floor	626	SF	7	6-10 years		
Classroc	om #13 (Regular Classroom)							
	Ceiling - Plaster/Drywall	1st Floor	654	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile	1st Floor	654	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Storage/ Closet	1st Floor	67	SF	5	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	626	SF	7	6-10 years		
Classroc	om #14 (Computer Lab)							
	Ceiling - Plaster/Drywall	1st Floor	654	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	6-10 years		
	Floor - Tile	1st Floor	654	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	15	ĒA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	626	SF	7	6-10 years		
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	om)	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Green H		Exterior Courtyard	4.40	05	7	10+ years		
						THE VEARS		
	Finishes		140	SF	7			
	Glazing	Exterior Courtyard	140 620	SF	7	10+ years		
Mechani	Glazing cal/ Service Rooms	Exterior Courtyard	620	SF	7			
Mechani	Glazing							
Mechani Restroor	Glazing cal/ Service Rooms Mechanical/ Service Rooms	Exterior Courtyard Room 142A	620 80	SF SF	7	10+ years		
	Glazing cal/ Service Rooms Mechanical/ Service Rooms m Accessories	Exterior Courtyard Room 142A Adjacent 13	620 80 174	SF SF SF	7	10+ years 10+ years 6-10 years		
	Glazing cal/ Service Rooms Mechanical/ Service Rooms m	Exterior Courtyard Room 142A	620 80	SF SF	7 7	10+ years 10+ years		
	Glazing cal/ Service Rooms Mechanical/ Service Rooms m Accessories	Exterior Courtyard Room 142A Adjacent 13	620 80 174	SF SF SF SF EA	7 7 7 7	10+ years 10+ years 6-10 years		
	Glazing <u>cal/ Service Rooms</u> Mechanical/ Service Rooms <u>m</u> Accessories Ceiling - Plaster/Drywall	Exterior Courtyard Room 142A Adjacent 13 Adjacent 13	620 80 174 174	SF SF SF SF	7 7 7 7 7 7 7 7	10+ years 10+ years 6-10 years 6-10 years		



2347 S Wabash AVENUE, Chicago, IL 60616 Building : Modular 1 (4-Classroom) Category : Room Recommend Location Quantity Group Item - Type UOM Rank **Replacement** Comments Lavatory Adjacent 13 2 ΕA 10+ vears 7 Lighting - Pendent/Surface Adjacent 13 3 ΕA 7 6-10 years Partitions Adjacent 13 4 ΕA 7 6-10 years Walls - Vinyl Coated Gypsum Panel Adjacent 13 422 SF 7 6-10 years Water Closet Adjacent 13 4 EΑ 7 10+ years SF 7 Accessories Adjacent 14 139 6-10 years Ceiling - Plaster/Drywall Adjacent 14 139 SF 6-10 years 6 Doors - Wood Doors inclu hw Adjacent 14 1 ΕA 6 6-10 years Floor - Tile Adjacent 14 139 SF 6 6-10 years Floor Drain Adjacent 14 1 ΕA 7 6-10 years Adjacent 14 2 ΕA 7 6-10 vears Lavatorv Lighting - Pendent/Surface Adjacent 14 2 ΕA 7 6-10 years Partitions Adjacent 14 2 ΕA 7 6-10 years 2 ΕA 7 Urinals Adjacent 14 6-10 years Walls - Vinyl Coated Gypsum Panel Adjacent 14 377 SF 7 6-10 years Water Closet 2 FΑ 7 Adjacent 14 6-10 years **Category : Interior** Building : Modular 1 (4-Classroom) Recommend Item - Type Location UOM **Replacement** Comments Group Quantity Rank Corridor 1st Floor 425 SF Ceiling - Plaster/Drywall 6 6-10 vears Drinking Fountains - Single Fountain 1st Floor 1 ΕA 7 6-10 vears Floor - Carpet 425 SF 6-10 years 1st Floor 6 Lighting - Pendent/Surface 1st Floor 5 ΕA 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1,589 SF 7 1st Floor 6-10 years

1st Floor

Security Cameras

Safety

ΕA

1

7

10+ years



Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	6	6-10 years	
	-						
Fencing							
U	Fencing - Chain Link	Entire Site	506	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	20	LF	6	6-10 years	Priority replacement (a.k.a. RUL)
							changed to update/correct to match current observations
	Fencing - New Standard Ornamental	Entire Site	589	LF	6	6-10 years	
Landsca							
	Landscape - Grass	Entire Site	14,425	SF	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	30	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,413	SF	7	6-10 years	
	Parkway trees	Entire Site	10	EA	6	6-10 years	
	Parkway trees	Entire Site	1	EA	6	1-2 years	This is a tree inside the grounds, it is
						-	growing over the roof and needs Pruning
	Planting Beds/ Area	Entire Site	1,606	SF	6	6-10 years	5
	Planting Beds/ Area	Entire Site	2,000	SF	4	1-2 years	Repair or replacement of some boards, rotted.Engineer mentioned that the teacher in charge of this has put out a request to have these replaced
	Retaining Wall - Masonry	Entire Site	400	SF	6	10+ years	Teplaceu
	Retaining Wall - Masonry	Entire Site	400 50	SF	5	1-2 years	Open joints, spoiled concrete coping
	Retaining wai Masoniy	Entire Olice	00	01	0		
Parking I	ot						
5	Surface - Asphalt	North	5,506	SF	6	2-5 years	Rank changed to update/correct to match current observations
	Surface - Asphalt	North	4,506	SF	6	2-5 years	Rank changed to update/correct to match current observations
	Surface - Asphalt	North	1,000	SF	5	0-1 year	Many potholes
	Trash Enclosure - Chain Links	North	385	SF	5	6-10 years	Chain links are generally in good
						,	shape but the gates are off their hinges
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	428	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	90	LF	5	0-1 year	Sidewalk has been upheaved by tree



Category : Site Building : Site Recommend Item - Type Group Location Quantity UOM Rank Replacement Comments Entire Site LF Sidewalks - Internal Walks 90 4 1-2 years Heavily spalled concrete sidewalk at entry number four Sidewalks - Perimeter Sidewalks Entire Site 5,439 SF 6 10+ years Signage Flag Pole - Flag Pole Entire Site 1 FΑ 6 10+ years Marquee - Free Standing Back lighted w/ Entire Site EΑ 6 10+ years 1 LED Monument - Sign Entire Site 1 EΑ 7 6-10 years

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	intellated bodge		Humber	Humber	(01)	Alou	Alou	Otop	Board
Art Room	Regular Classroom	1st Floor	113 A	N/A	460	96	22	N	Y
Art Room	Regular Classroom	1st Floor	123	N/A	487	52	6	N	Y
Computer Lab	Computer Lab	1st Floor	108	N/A	436	65	16	N	Y
Culinary	Culinary	1st Floor	116	N/A	1,330	72	22	N	Y
Other Instructional Use	Other Instructional Use	1st Floor	121	N/A	634	72	22	N	Y
Regular Classroom	Art Room	1st Floor	113	N/A	460	0	0	N	Y
Regular Classroom	Regular Classroom	1st Floor	117	N/A	519	78	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	125	N/A	487	52	6	N	Y
Regular Classroom	Regular Classroom	1st Floor	127	N/A	487	52	6	N	Y
Regular Classicom			121		407	52	0		

Building : Modular 1 (4-Classroom)										
Computer Lab	Regular Classroom	1st Floor	14	С	654	75	30	N	Y	
Regular Classroom	Regular Classroom	1st Floor	11	В	654	75	30	N	Y	
Regular Classroom	Regular Classroom	1st Floor	12	D	654	75	30	N	Y	
Regular Classroom	Regular Classroom	1st Floor	13	А	654	75	30	N	Y	