

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1970	2	29,878
Modular 1 (2-Classroom)	1999	1	1,737
Campus Total			31,615

Catego	Category : Exterior			uilding			
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entranc	9						
	Entrance Control - Audio and Video	#1 - Main - E	1	EA	7	10+ years	
	Exterior Doors - Side lite	#1 - Main - E	2	EA	6	6-10 years	
	Exterior Doors - Store Front	#1 - Main - E	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 - Main - E	3	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - S	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 - S	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 - W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 - NW	1	EA	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#4 - NW	15	LF	6	6-10 years	
	Ramps - Concrete	#4 - NW	15	LF	5	1-2 years	Large cracks in the concrete
	Exterior Doors - Exterior Steel Door	#5 - NW	1	EA	6	6-10 years	C C C C C C C C C C C C C C C C C C C
	Exterior Doors - Exterior Steel Door	#6 - NW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 - NW	3	LF	5	1-2 years	Broken, cracked concrete step
	Exterior Doors - Exterior Steel Door	#7 - NE	1	EA	6	6-10 years	
Foundat	ion						
	Foundation - Concrete	Entire Building	207	LF	7	10+ years	
	Foundation - Concrete	Entire Building	520	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	6	1-2 years	Hairline cracks in the foundation wall.
	Superstructure - Steel	Entire Building	29,878	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		•
J •				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	5	0-1 year	The light fixtures are not attached to the structure. This assessor was able to easily lift the fixtures from the roof
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	4	2-5 years	Old, obsolete fixtures. We are currently using type A bulbs
Roof Sy	stem						
·	Access Ladder - Metal	Center roof	1	EA	5	2-5 years	Old, obsolete ladder. Topp supports are very flimsy, unsecure
	Chimney - Brick Chimney- Stainless Steel Liner	Center roof	37	LF	6	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	Center roof	12	LF	6	10+ years	
	Chimney - Metal Flue	Center roof	49	LF	6	10+ years	
	Chimney - Metal Flue	Center roof	49	LF	6	10+ years	
	Coping - Metal	Center roof	89	LF	6	10+ years	
	Downspouts - Interior Downspouts	Center roof	24	LF	6	10+ years	
	Roof - PVC Membrane	Center roof	2,380	SF	6	6-10 years	
	Roof - PVC Membrane	Center roof	1,000	SF	4	0-1 year	Soft spots, deteriorating repairs, open seams
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Center roof	3,380	SF	7	10+ years	
	Access Ladder - Metal	North roof	1	EA	7	10+ years	Only one ladder here
	Coping - Metal	North roof	299	LF	6	6-10 years	,
	Downspouts - Interior Downspouts	North roof	44	LF	6	10+ years	
	Roof - PVC Membrane	North roof	3,999	SF	6	6-10 years	
	Roof - PVC Membrane	North roof	900	SF	4	0-1 year	Soft spots, deteriorating repairs, open seams
	Roof Hatch - Metal	North roof	1	EA	5	1-2 years	Hatch is damaged and the latch does not work
	Roof Structure - Steel / Metal Deck/ Concrete Topping	North roof	4,899	SF	7	10+ years	
	Access Ladder - Metal	South roof	1	EA	7	10+ years	Only one ladder here
	Coping - Metal	South roof	464	LF	6	10+ years	-
	Downspouts - Interior Downspouts	South roof	75	LF	6	10+ years	
	Roof - PVC Membrane	South roof	9,054	SF	6	6-10 years	
	Roof - PVC Membrane	South roof	2,000	SF	4	0-1 year	Soft spots, deteriorating repairs, open seams
	Roof Hatch - Metal	South roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	South roof	11,054	SF	7	10+ years	

Walls



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Canopy - Concrete/ Stucco	Entire Building	116	SF	6	10+ years	
	Canopy - Metal	Entire Building	50	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	10	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	7,448	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,000	SF	5	10+ years	Deteriorating water
	Exterior Walls - Brick	Entire Building	500	SF	4	1-2 years	Scattered areas of open joints and
			000	01		1 2 youro	craft switch
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	2,383	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	2,303	SF	6	2-5 years	Minor dings
				SF			
	Curtain wall - Insulated Panel	Entire Building	2,541		6	10+ years	
	Curtain wall - Louver	Entire Building	484	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	1,675	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	50	SF	6	10+ years	Any damage was repaired
	Lintels - Steel	Entire Building	21	LF	6	10+ years	
	Windows - Insulated Panel	Entire Building	9	SF	5	1-2 years	Rusted, damaged panel
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Security System - CCTV	Entire Building	29,878	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	29,878	SF	5	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	4,863	SF	6	10+ years	Served from EM panel
	Stairs	5	,			- ,	
	Emergency A/C Power - Lunchrooms	Entire Building	3,024	SF	6	10+ years	Served from EM panel
	Emergency A/C Power - Students Toilets	Entire Building	1,400	SF	6	10+ years	Served from EM panel
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Served from EM panel
	Exit Signs - Multipurpose Room	Entire Building	6	EA	6	6-10 years	Served from EM panel
	Automatic Transfer Switch	Mechanical Room	1	EA	6	10+ years	
			I	LA	0	TOF years	
Main Se							
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Installed in 1970 construction
	PA System	Entire Building	29,878	SF	5	6-10 years	
	Independent Electrical Service for	Entire Building	29,070	EA	5 6	10+ years	
	emergency power		I	EA	0	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and I ower I ariels - Above 100 A		4	LA	'	io+ years	



atego	ory : Electrical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	2	2-5 years	Stage access
tego	ory : Fire Protection		В	uilding	: Main		
		1				Recommend	•
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
e Ala	rm						
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	29,878	SF	6	10+ years	
	Fire Alarm_System	Electrical Room	29,878	SF	6	10+ years	
ntego	ory : Mechanical		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hand	dling Systems						
	Make Up Air Unit- Indoor Mounted- Hot Water Coils - 6000 - 10,000 cfm	Boiler Room	1	EA	6	10+ years	Installed in 1970 construction
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	10+ years	Installed in 1970 construction
	Cage - Less than 5000 CFM			_/ \	Ũ	, e , j eure	
	Air Handling Unit-Package Single Zone-	Mechanical Room and 2nd Floor	1	EA	5	2-5 years	Installed in 1970 construction
	Indoor- Hot Water Coils - 4000-8000 cfm		1	LA	5	Z=0 years	
	Air Intake	Mechanical Room and 2nd Floor	1	EA	6	10+ years	
	Air Intake		I	EA	0	TUT years	
iler S	ystems						
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	5	2-5 years	Installed in 1970 construction
	- 2001 - 3000 MBH						
	Chemical Pot Feeder	Mechanical Room	1	EA	6	10+ years	
	Combustion Dampers	Mechanical Room	1	EA	6	10+ years	
	Non Condensing- Water Tube- Flexible	Mechanical Room	2	EA	5	2-5 years	Installed in 1970 construction
	Tube- Force Draft- Hot Water Boiler - 2001						
	- 3000 MBH						
eating	- 3000 MBH						
eating		Entire Building	18	LF	6	10+ years	Installed in 1970 construction
ating	Devices	Entire Building Entire Building	18 9	LF EA	6 6	10+ years 10+ years	Installed in 1970 construction Installed in 1970 construction
C	Devices Fin Tube - Hot Water		-		-		
C	Devices Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil		-		-		



Catego	ry : Mechanical		B	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ature Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Pneumatic System	Entire Building	29,878	SF	7	10+ years	Per building engineer- system is working Fixed in 2021 summer
	Thermostats - Pneumatic	Entire Building	1	EA	7	10+ years	Per building engineer- system is working Fixed in 2021 summer
	Thermostats - Pneumatic	Entire Building	3	EA	6	6-10 years	3
	Thermostats - Pneumatic	Entire Building	20	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	24	EA	5	6-10 years	Installed in 1970 construction
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	1st floor and Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	2	EA	7	6-10 years	Installed one new in October 2021 Second one is going to installed December 2021 per building engine
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	3	EA	7	6-10 years	Served toilets
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st floor and Roof	1	EA	3	0-1 year	fan needs to be replace-per building served classrooms and corridor
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st floor and Roof	8	EA	6	10+ years	Served classrooms and corridor
Catego	ry : Plumbing		В	uilding	: Main		
Ŭ	· · · ·			Ŭ		Recommend	
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	29,878	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	29,878	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	29,878	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	29,878	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	29,878	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	29,878	SF	6	10+ years	



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sanitary Piping	Entire Building	29,878	SF	6	10+ years	
	Storm Piping	Entire Building	29,878	SF	6	10+ years	
	Vent Piping	Entire Building	29,878	SF	6	10+ years	
Pumps							
	Pumps - Sump-Simplex	Mechanical Room	1	EA	4	1-2 years	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Lay-in	1st floor Main Office	427	SF	7	10+ years	
	Doors - Store Front	1st floor Main Office	1	EA	7	10+ years	
	Floor - Carpet	1st floor Main Office	195	SF	7	6-10 years	
	Floor - Tile	1st floor Main Office	232	SF	6	6-10 years	
	Lighting - Lay-in	1st floor Main Office	7	EA	7	6-10 years	
	Power Distribution	1st floor Main Office	10	EA	7	6-10 years	
	Walls - Concrete Block	1st floor Main Office	674	SF	7	10+ years	
	Ceiling - Lay-in	Counselor office 100A, 1st Floor	227	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor office 100A, 1st Floor	2	EA	6	6-10 years	
	Floor - Tile	Counselor office 100A, 1st Floor	222	SF	6	6-10 years	
	Floor - Tile	Counselor office 100A, 1st Floor	5	SF	4	1-2 years	Missing/broken
	Lighting - Pendent/Surface	Counselor office 100A, 1st Floor	4	EA	7	6-10 years	
	Power Distribution	Counselor office 100A, 1st Floor	2	EA	7	6-10 years	
	Storage/ Closet	Counselor office 100A, 1st Floor	10	SF	7	6-10 years	
	Walls - Concrete Block	Counselor office 100A, 1st Floor	565	SF	7	10+ years	
	Work SInk	Counselor office 100A, 1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	Engineer's Office	179	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's Office	8	SF	5	1-2 years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	6-10 years	
	Floor - Tile	Engineer's Office	187	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office	6	EA	7	6-10 years	
	Storage/ Closet	Engineer's Office	8	SF	7	10+ years	
	Walls - Concrete Block	Engineer's Office	290	SF	6	10+ years	
	Ceiling - Exposed	Gym office inside multi purpose	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	room Gym office inside multi purpose room	1	EA	7	10+ years	
	Floor - Tile/Sheet	Gym office inside multi purpose room	70	SF	5	6-10 years	
	Lighting - Pendent/Surface	Gym office inside multi purpose room	1	EA	6	6-10 years	
	Walls - Concrete Block	Gym office inside multi purpose	320	SF	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments room Kitchen Manager's Office SF Ceiling - Lav-in 294 6 10+ vears Doors - Steel Doors incl hw Kitchen Manager's Office 4 FΑ 6 10+ years Changed to match current observations Floor - Tile Kitchen Manager's Office 294 SF 6 6-10 years Kitchen Manager's Office 7 6-10 years Lighting - Lay-in 4 EΑ **Power Distribution** Kitchen Manager's Office 14 ΕA 7 10+ years Kitchen Manager's Office SF Walls - Concrete Block 456 6 10+ years SF Ceiling - Lay-in Nurse office 100. 1st Floor 375 6 10+ years FΑ Doors - Wood Doors inclu hw Nurse office 100. 1st Floor 6 6-10 years 1 Quantity changed to match current observations Floor - Tile Nurse office 100, 1st Floor 365 SF 6 6-10 years Floor - Tile Nurse office 100, 1st Floor SF 1-2 years 10 4 Missing/broken 7 Lighting - Pendent/Surface Nurse office 100, 1st Floor 10 EΑ 6-10 years Power Distribution Nurse office 100. 1st Floor 6 ΕA 7 6-10 years SF Walls - Concrete Block Nurse office 100, 1st Floor 650 6 10+ years SF Ceiling - Lav-in Principal's Office 151 6 10+ years Doors - Wood Doors inclu hw Principal's Office 1 EΑ 6 6-10 years Principal's Office SF Floor - Carpet 151 6 6-10 vears Lighting - Pendent/Surface Principal's Office 2 EΑ 7 6-10 years Power Distribution Principal's Office 6 ΕA 7 6-10 years Principal's Office Walls - Concrete Block SF 234 6 10+ years SF Teacher's Lounge next to rm. 106 Ceiling - Lav-in 385 6 10+ years Doors - Wood Doors inclu hw Teacher's Lounge next to rm. 106 2 FΑ 6 6-10 years Floor - Tile Teacher's Lounge next to rm. 106 SF 6 6-10 years 385 Lighting - Pendent/Surface Teacher's Lounge next to rm. 106 7 ΕA 7 6-10 vears Teacher's Lounge next to rm. 106 6 **Power Distribution** ΕA 6 6-10 years Walls - Concrete Block Teacher's Lounge next to rm. 106 635 SF 6 10+ years SF Walls - Metal Panel Teacher's Lounge next to rm. 106 6 6 10+ years Work SInk Teacher's Lounge next to rm. 106 1 ΕA 5 6-10 years Lunch & Multipurpose Room Ceiling - Plaster/Drywall 1st Floor 3,024 SF 6 10+ years Changed to match current Doors - Steel Doors incl hw 1st Floor 5 ΕA 6 6-10 years observations Floor - Tile 1st Floor 3.024 SF 6 6-10 years Lighting - Lay-in 1st Floor 20 FΑ 7 6-10 years Serving Line LF 7 6-10 years 1st Floor 12 SF Stage 1st Floor 524 6 6-10 vears SF Storage/ Closet 7 6-10 years 1st Floor 66 Walls - Concrete Block SF 1st Floor 2,056 6 10+ years Walls - Structural Glazed Tile SF 1st Floor 2,056 6 10+ years

MDF IDF



Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	Changed to match current observations	
	Finishes	1st Floor	92	SF	5	6-10 years		
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	CRAC unit	
Mechan	ical/ Service Rooms							
	Boiler Room	1st Floor	927	SF	7	10+ years		
	Janitor's Closet	1st Floor	59	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	134	SF	7	10+ years	Electrical room	
	Storage Room	1st Floor	72	SF	7	10+ years		
	Storage Room	1st Floor	128	SF	7	10+ years	Changed to match current observations	
	Storage Room	1st Floor	35	SF	7	10+ years		
	Storage Room	1st Floor	35	SF	7	10+ years		
	Storage Room	1st Floor	100	SF	5	10+ years		
	Storage Room	1st Floor	100	SF	5	10+ years		
	Vaults	1st Floor	65	SF	7	10+ years		
	Janitor's Closet	2nd Floor	59	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	330	SF	7	10+ years	Fan room accessible from	
			000	01		ior youro	multipurpose room	
Restroo	m							
	Accessories	1st Floor	302	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	302	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	Quantity changed to match current observations	
	Floor - Tile Ceramic/ Porcelain	1st Floor	302	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	3	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years		
	Partitions	1st Floor	7	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	688	SF	7	10+ years		
	Water Closet	1st Floor	7	EA	7	10+ years		
	Accessories	1st Floor	343	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	343	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	Quantity changed to match current	
					-	2	observations	
	Floor - Tile Ceramic/ Porcelain	1st Floor	343	SF	6	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	3	EA	6	6-10 years		
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years		
					_	4.0		
	Lighting - Pendent/Surface	1st Floor	3	EA EA	7 5	10+ years		



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Urinals 1st Floor 6 ΕA 6-10 years 7 1st Floor 725 SF Walls - Structural Glazed Tile 6 10+ vears Water Closet 1st Floor 2 FΑ 7 6-10 years 53 SF 7 Accessories 2nd Floor 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor 53 6 10+ years Doors - Wood Doors inclu hw ΕA 2nd Floor 1 6 6-10 years Floor - Tile Ceramic/ Porcelain 2nd Floor 53 SF 6 6-10 years Lavatorv 2nd Floor 1 ΕA 6 6-10 years Lighting - Lay-in 2nd Floor 1 ΕA 7 6-10 years Lighting - Wall Mounted 2nd Floor FΑ 7 10+ vears 1 Partitions 2nd Floor 1 ΕA 7 6-10 years Urinals 2nd Floor 1 EΑ 6 6-10 years Walls - Structural Glazed Tile 2nd Floor 82 SF 6 10+ years 6 Water Closet 2nd Floor 1 EA 10+ years SF 7 Accessories 2nd Floor 302 6-10 years Ceiling - Plaster/Drywall 302 SF 2nd Floor 6 10+ years Doors - Wood Doors inclu hw ΕA 2nd Floor 4 6 10+ years Changed due to site observations Floor - Tile Ceramic/ Porcelain 2nd Floor 302 SF 6 10+ years Floor Drain 2nd Floor ΕA 7 10+ vears 1 Lavatory 2nd Floor 3 EΑ 6 10+ years Lighting - Lay-in 2nd Floor 1 ΕA 7 6-10 years Lighting - Pendent/Surface 3 7 2nd Floor EΑ 6-10 years 7 ΕA 7 Partitions 2nd Floor 10+ years 688 SF 7 Walls - Structural Glazed Tile 2nd Floor 10+ years Water Closet ΕA 7 2nd Floor 7 10+ years SF Accessories 2nd Floor 343 7 6-10 years Ceiling - Plaster/Drywall SF 2nd Floor 343 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 3 ΕA 6 10+ years Changed due to site observations Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 4 1-2 years Floor - Tile Ceramic/ Porcelain 2nd Floor 343 SF 6 10+ years Floor Drain 2nd Floor FΑ 7 10+ vears 1 Lavatorv 2nd Floor 3 EΑ 6 10+ vears 7 Lighting - Lay-in 2nd Floor 1 FΑ 6-10 years Lighting - Pendent/Surface 2nd Floor 3 FΑ 7 6-10 years Partitions 2 7 2nd Floor EΑ 10+ years 6 ΕA Urinals 2nd Floor 6 10+ years Walls - Structural Glazed Tile SF 2nd Floor 725 6 10+ years Water Closet ΕA 2nd Floor 2 6 10+ years SF Accessories In Engineer's Office 34 7 6-10 years SF Ceiling - Plaster/Drvwall In Engineer's Office 34 6 10+ vears Doors - Wood Doors inclu hw In Engineer's Office 1 ΕA 6 10+ years In Engineer's Office SF 6 Floor - Tile Ceramic/ Porcelain 34 10+ vears Lavatory In Engineer's Office 1 EA 6 10+ years In Engineer's Office 7 Lighting - Lay-in 1 EA 6-10 years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Concrete Block In Engineer's Office 54 SF 6 10+ vears Water Closet In Engineer's Office ΕA 6 1 10+ vears Accessories In Main Office 55 SF 7 6-10 years Ceiling - Plaster/Drywall In Main Office 55 SF 6 10+ years Doors - Wood Doors inclu hw In Main Office 1 EA 6 6-10 years 55 SF Floor - Tile Ceramic/ Porcelain In Main Office 6 6-10 years In Main Office ΕA 6 6-10 years Lavatory 1 Lighting - Lay-in In Main Office 1 ΕA 7 10+ years Lighting - Wall Mounted In Main Office 1 ΕA 7 10+ years Partitions In Main Office 1 FΑ 7 10+ vears Walls - Concrete Block In Main Office 85 SF 6 10+ vears Water Closet In Main Office 1 ΕA 6 6-10 years 30 SF 7 6-10 years Accessories In Room 108 SF Ceiling - Plaster/Drywall In Room 108 30 6 10+ years Doors - Wood Doors inclu hw ΕA In Room 108 1 6 10+ years Floor - Tile Ceramic/ Porcelain 30 SF 6 In Room 108 10+ years ΕA Lavatorv In Room 108 1 6 10+ years Lighting - Lay-in In Room 108 1 EΑ 7 6-10 years Walls - Concrete Block SF In Room 108 142 6 10+ vears Water Closet In Room 108 1 EA 6 10+ years Accessories In classroom 106 30 SF 7 6-10 years Ceiling - Plaster/Drywall SF In classroom 106 30 6 10+ years Doors - Wood Doors inclu hw In classroom 106 6 1 EA 10+ years SF Floor - Tile Ceramic/ Porcelain In classroom 106 30 6 10+ years FΑ 6 Lavatorv In classroom 106 1 10+ years Lighting - Pendent/Surface In classroom 106 1 ΕA 7 6-10 years Walls - Concrete Block SF In classroom 106 142 7 10+ years Water Closet ΕA 7 In classroom 106 1 10+ years SF Accessories Men's Room near the Main Entry 95 7 6-10 years Ceiling - Plaster/Drywall Men's Room near the Main Entry 95 SF 6 10+ years Doors - Wood Doors inclu hw 1 FΑ 6 10+ vears Men's Room near the Main Entry Floor - Tile Ceramic/ Porcelain Men's Room near the Main Entry 95 SF 6 10+ vears FΑ 1 6 6-10 years Lavatory Men's Room near the Main Entry Lighting - Lay-in Men's Room near the Main Entry 2 FΑ 7 6-10 vears Lighting - Wall Mounted 7 Men's Room near the Main Entry 1 EΑ 6-10 years ΕA 7 Partitions Men's Room near the Main Entry 1 10+ years 2 Urinals Men's Room near the Main Entry EΑ 6 10+ years Walls - Structural Glazed Tile SF Men's Room near the Main Entry 204 6 10+ years Water Closet Men's Room near the Main Entry 1 ΕA 6 10+ years SF Accessories Staff on 1st floor inside counselors 55 7 6-10 years office SF Ceiling - Plaster/Drywall Staff on 1st floor inside counselors 55 6 10+ years office Doors - Wood Doors inclu hw Staff on 1st floor inside counselors 1 EA 6 10+ years



Catego	ry : Room	bom Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		office						
	Floor - Tile Ceramic/ Porcelain	Staff on 1st floor inside counselors office	55	SF	6	10+ years		
	Lavatory	Staff on 1st floor inside counselors office	1	EA	6	10+ years		
	Lighting - Lay-in	Staff on 1st floor inside counselors office	1	EA	7	6-10 years		
	Lighting - Wall Mounted	Staff on 1st floor inside counselors office	1	EA	7	6-10 years		
	Walls - Structural Glazed Tile	Staff on 1st floor inside counselors office	85	SF	6	10+ years		
	Water Closet	Staff on 1st floor inside counselors office	1	EA	6	10+ years		
	Accessories	Women's Room Near Main Office	101	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Women's Room Near Main Office	101	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Women's Room Near Main Office	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Women's Room Near Main Office	101	SF	6	6-10 years		
	Lavatory	Women's Room Near Main Office	1	EA	6	6-10 years		
	Lighting - Lay-in	Women's Room Near Main Office	2	EA	7	6-10 years		
	Lighting - Wall Mounted	Women's Room Near Main Office	1	EA	6	6-10 years		
	Partitions	Women's Room Near Main Office	2	EA	7	6-10 years		
	Walls - Structural Glazed Tile	Women's Room Near Main Office	164	SF	6	10+ years		
	Water Closet	Women's Room Near Main Office	2	EA	6	10+ years		

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	om #102 (Regular Classroom)						
	Casework	1st Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	770	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	770	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	800	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	50	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	17	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	770	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	770	SF	7	10+ years	



Catego	ategory : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	800	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	50	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
lassroc	om #104 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	770	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	770	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor		EA	7	•	
	Marker Board		20	LF	6	10+ years	
		1st Floor	15			6-10 years	
	Walls - Concrete Block	1st Floor	800	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	50	SF	6	10+ years	
lassroc	om #106 (Regular Classroom)						
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	955	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	6-10 years	
	Floor - Tile	1st Floor	955	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	27	ĒA	7	10+ years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	49	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1.040	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	36	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	om #108 (Kindergarten)						
	Casework	1st Floor	30	LF	6	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	955	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	955	EA	6 6	6-10 years	
				SF		•	
	Floor - Tile	1st Floor	955		6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	10+ years	
	Marker Board	1st Floor	6	LF	6	6-10 years	O III II
	Storage/ Closet	1st Floor	49	SF	5	10+ years	Some ceiling tiles are damaged
	Walls - Concrete Block	1st Floor	1,040	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	36	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	17	LF	6	6-10 years	



Building : Main Category : Classroom Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Ceiling - Lay-in 2nd Floor 770 SF 6-10 vears 6 Chalk Board 2nd Floor LF 2-5 vears 20 4 Doors - Wood Doors inclu hw 2nd Floor ΕA 6 6-10 years 1 SF 6 Floor - Tile 2nd Floor 770 6-10 years 7 Lighting - Pendent/Surface 2nd Floor 20 EΑ 6-10 years LF Marker Board 2nd Floor 15 6 6-10 years Walls - Concrete Block 2nd Floor 800 SF 6 10+ years SF Walls - Metal Panel 2nd Floor 50 6 10+ years Classroom #202 (Regular Classroom) 2nd Floor 17 LF 6 6-10 years Casework Ceiling - Lay-in 2nd Floor 732 SF 6 6-10 years SF Ceiling - Lay-in 2nd Floor 48 5 2-5 years LF Chalk Board 2nd Floor 20 4 2-5 years Doors - Wood Doors inclu hw 2nd Floor ΕA 6 6-10 vears 1 Floor - Tile 2nd Floor 770 SF 6 6-10 years 7 Lighting - Pendent/Surface 2nd Floor 20 FΑ 6-10 years Marker Board 2nd Floor 15 LF 6 6-10 years SF Walls - Concrete Block 2nd Floor 800 6 10+ years Walls - Metal Panel 2nd Floor SF 50 6 10+ years Classroom #203 (Special Education) 2nd Floor LF Casework 17 6 6-10 years Ceiling - Lay-in 2nd Floor 770 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 6 10+ years 2nd Floor 770 SF 6 Floor - Tile 10+ vears Lighting - Pendent/Surface 2nd Floor 20 EΑ 7 6-10 years Marker Board 2nd Floor LF 6 30 6-10 years Walls - Concrete Block 2nd Floor 800 SF 6 10+ years SF Walls - Metal Panel 2nd Floor 50 6 10+ years 7 Work Sink 2nd Floor 1 EΑ 10+ years Classroom #204 (Regular Classroom) LF Casework 2nd Floor 17 6 6-10 years SF Ceiling - Lay-in 2nd Floor 746 6 10+ years SF Ceiling - Lav-in 2nd Floor 24 5 2-5 vears Chalk Board LF 2nd Floor 20 4 2-5 years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 6 6-10 years SF 6 6-10 years Floor - Tile 2nd Floor 770 Lighting - Pendent/Surface 2nd Floor 20 ΕA 6 6-10 years Marker Board 2nd Floor LF 6 15 6-10 years Walls - Concrete Block 2nd Floor 770 SF 6 10+ years SF Walls - Metal Panel 2nd Floor 50 6 10+ years



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	17	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	770	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	50	SF	6	10+ years	
lassroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	17	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	770	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	770	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	50	SF	6	10+ years	
	om #207 (Library)						
1022100	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	696	SF	6	6-10 years	
				SF			
	Ceiling - Lay-in	2nd Floor	24 10	LF	5	2-5 years	
	Chalk Board	2nd Floor			4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	690	SF	7	10+ years	Upgraded because damaged carpo was separated into own item line
	Floor - Carpet	2nd Floor	30	SF	5	1-2 years	
	Lighting - Pendent/Surface	2nd Floor	20	ĒA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,152	SF	6	10+ years	
lassroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	17	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	770	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	770	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	



Category : Classroom		В	uilding	: Main		C Estanda WENCE, Childge, iE Cooo	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	2nd Floor	50	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
Galogo				anang	· mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,204	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,204	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	32	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	26	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	77	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	2,483	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,483	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,625	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	64	SF	5	2-5 years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	1,659	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	32	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor	26	LF	6	10+ years	
	Student Lockers - One Tier	2nd Floor	165	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,286	SF	6		
	Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor	1,286	SF	6	10+ years	
	Wails - Structural Glazed The	2110 F1001	1,200	Эг	0	10+ years	
Safety							
	Camera Viewing Station	N/A	6	EA	7	10+ years	
	Security Cameras	N/A	2	EA	7	10+ years	Exterior
	Security Cameras	N/A	4	EA	7	10+ years	Interior
Stairs							
	Ceiling - Lay-in	Multi purpose room	114	SF	7	10+ years	
	Ceiling - Lay-in	Multi purpose room	36	SF	5	1-2 years	
	Floor - Concrete	Multi purpose room	150	SF	7	10+ years	
	Handrails	Multi purpose room	28	LF	5	2-5 years	
	Lighting - Lay-in	Multi purpose room	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Multi purpose room	1	EA	7	10+ years	
	Stairs - Concrete	Multi purpose room	64	LF	7	10+ years	
	Walls - Concrete Block	Multi purpose room	1,010	SF	7	10+ years	
	Walls - Concrete Block	Multi purpose room	40	SF	6	1-2 years	
	Ceiling - Lay-in	North	72	SF	6	10+ years	
	Ceiling - Lay-in	North	36	SF	5	1-2 years	
	Floor - Terrazzo	North	108	SF	6	10+ years	
	Handrails	North	93	LF	7	10+ years	
						,	



Catego	Category : Interior				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Handrails	North	4	LF	5	1-2 years	
	Lighting - Lay-in	North	4	EA	7	10+ years	
	Stairs - Terrazzo	North	108	LF	6	10+ years	Changed due to site observations
	Walls - Concrete Block	North	175	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	175	SF	6	10+ years	
	Ceiling - Lay-in	South	72	SF	6	10+ years	
	Ceiling - Lay-in	South	36	SF	5	1-2 years	
	Floor - Terrazzo	South	108	SF	6	6-10 years	
	Handrails	South	92	LF	7	6-10 years	
	Lighting - Lay-in	South	4	EA	7	6-10 years	
	Stairs - Terrazzo	South	108	LF	6	6-10 years	
	Walls - Concrete Block	South	156	SF	6	10+ years	
	Walls - Structural Glazed Tile	South	156	SF	6	10+ years	



Category : Exterior Building : Modular 1 (2-Classroom) Recommend Location **Replacement** Comments Item - Type Quantity UOM Group Rank Entrance #10 - NE ΕA Exterior Doors - Exterior Steel Door 6 10+ years 1 5 LF 6 #10 - NE 10+ years Exterior Stairs - Concrete LF **Exterior Stairs - Wood** #10 - NE 20 6 10+ years Stair Handrail - Wood Stair Handrail #10 - NE 25 LF 6 10+ years Exterior Doors - Exterior Steel Door #8 - S 1 EA 6 6-10 years Ramp Handrail - Wood Ramp Handrail 90 LF #8 - S 6 10+ years LF Ramp Handrail - Wood_Ramp Handrail #8 - S 5 6 10+ years Ramps - Wood Ramp #8 - S 45 LF 6 10+ vears Exterior Doors - Exterior Steel Door #9 - NW 1 EΑ 6 10+ years LF Exterior Stairs - Concrete #9 - NW 5 6 10+ vears LF **Exterior Stairs - Wood** #9 - NW 20 6 10+ years 25 LF Stair Handrail - Wood Stair Handrail 6 10+ years #9 - NW Foundation SF 7 Superstructure - Steel Entire Building 1.737 10+ years Lighting ΕA Exterior Lighting - Wall Mounted Entire Building 5 6 10+ years Roof System **Downspouts - Exterior Downspouts** Main Roof 20 LF 6 10+ years Roof - Metal Main Roof SF 2,084 6 10+ years Roof Structure - Steel / Metal Deck/ 2,084 SF 7 Main Roof 10+ years Concrete Topping Walls Exterior Walls - Wood Siding Entire Building 2,276 SF 6 10+ years SF Exterior Walls - Wood Siding Entire Building 4 3 1-2 years Hole in the wall, damaged siding and substrate Windows Guard - Guards perforated Entire Building SF 6 16 2-5 years Windows - Casement Aluminum SF 6 2-5 years Entire Building 16 Windows are in working order **Category : Electrical** Building : Modular 1 (2-Classroom) Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Emergency System **Emergency Battery Packs - Corridors and** 1st Floor 3 EΑ 6 6-10 years Stairs



12810 S Escanaba AVENUE, Chicago, IL 60633 Building : Modular 1 (2-Classroom) **Category : Electrical** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Exit Signs - Corridors and Stairs 1st Floor 5 FΑ 5 6-10 years Main Service PA System Electrical Room SF 5 1.737 6-10 years Power Distribution Lighting and Power Panels - 100 A 1st Floor 2 ΕA 6 10+ years **Category : Fire Protection** Building : Modular 1 (2-Classroom) Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Fire Alarm Fire Alarm System Entire Building 1,737 SF 5 6-10 years Sprinkler System Sprinkler Heads Entire Building 1,737 SF 7 10+ years Sprinkler Piping SF Entire Building 1,737 6 10+ years Wet Sprinkler System Entire Building 1,737 SF 6 10+ years Building : Modular 1 (2-Classroom) **Category : Mechanical** Recommend **Replacement** Comments Item - Type Location UOM Rank Group Quantity Temperature Control Electric Thermostat 2 ΕA 1st Floor 5 6-10 years Unit Ventilation Unit Ventilators - Vertical Package Electric Exterior wall mounted 2 ΕA 6 Installed in 1990 construction 2-5 years Heat & Self Contained Cooling Ventilation Exhaust Fans- Roof Mounted - Less than 2 FΑ Roof 5 2-5 years 500 CFM Building : Modular 1 (2-Classroom) **Category : Plumbing** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water Electric Heater - Less than 20 KW 1st Floor ΕA 5 2-5 years 1 Piping **Domestic Piping-Hot Water Return Lines** 1st Floor 1.737 SF 6 10+ years



12810 S Escanaba AVENUE, Chicago, IL 60633 Building : Modular 1 (2-Classroom) **Category : Plumbing** Recommend Group Item - Type **Replacement** Comments Location Quantity UOM Rank Domestic Piping-Hot/Cold Water Supply 10+ years 1st Floor SF 1,737 6 (Horizontal Lines) Sanitary Piping 1st Floor 1,737 SF 6 10+ years Storm Piping 1,737 SF 1st Floor 6 10+ years Vent Piping SF 1st Floor 1,737 6 10+ years Category · Classroom Building : Modular 1 (2-Classroom)

Catego	ry : Classroom		Building : Modular 1 (2-Classroom)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #M301 (Pre School)								
	Ceiling - Plaster/Drywall	1st Floor	4	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	696	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	680	SF	6	6-10 years			
	Floor - Tile	1st Floor	20	SF	4	2-5 years			
	Instructional Surface	1st Floor	12	LF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	6	LF	6	6-10 years			
	Storage/ Closet	1st Floor	12	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	875	SF	6	10+ years			
Classroo	om #M302 (Pre School)								
	Ceiling - Plaster/Drywall	1st Floor	700	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	675	SF	6	10+ years			
	Floor - Tile	1st Floor	15	SF	4	2-5 years			
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	6	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	875	SF	6	10+ years			
Catego	ry : Room		Building : Modular 1 (2-Classroom)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Mechan	cal/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	25	SF	5	2-5 years			
Restroo	n								
	Accessories	1st Floor, #1	44	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor, #1	44	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor, #1	1	EA	6	6-10 years			
	Floor - Tile	1st Floor, #1	44	SF	6	6-10 years			
	Floor Drain	1st Floor, #1	1	EA	7	6-10 years			



Catego	Category : Room				Building : Modular 1 (2-Classroom)					
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lavatory	1st Floor, #1	1	EA	6	6-10 years				
	Lighting - Metal Halide/Sodium Vapor	1st Floor, #1	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor, #1	154	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor, #1	9	SF	5	2-5 years				
	Water Closet	1st Floor, #1	1	EA	6	10+ years				
	Accessories	1st Floor, #2	44	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor, #2	32	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor, #2	12	SF	5	1-2 years				
	Doors - Wood Doors inclu hw	1st Floor, #2	1	EA	6	10+ years				
	Floor - Tile	1st Floor, #2	38	SF	6	10+ years				
	Floor - Tile	1st Floor, #2	6	SF	4	2-5 years				
	Floor Drain	1st Floor, #2	1	EA	7	10+ years				
	Lavatory	1st Floor, #2	1	EA	6	10+ years				
	Lighting - Metal Halide/Sodium Vapor	1st Floor, #2	1	EA	7	6-10 years				
	Walls - Vinyl Coated Gypsum Panel	1st Floor, #2	165	SF	6	10+ years				
	Water Closet	1st Floor, #2	1	EA	6	10+ years				

Category : Interior

Building : Modular 1 (2-Classroom)

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	120	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	112	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	8	SF	4	1-2 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	186	SF	7	10+ years	



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Athletic SF 7 Surface - Asphalt South 8.770 10+ years New basketball courts South 33.000 SF Surface - Asphalt 6 10+ years SF Surface - Asphalt South 10.000 4 1-2 years Entire running track is in bad shape. Many cracks, worn surfaces Civil/Drainage Civil/ Drainage - Catch Basin S & NW site 5 ΕA 6 10+ years Civil/ Drainage - Site Manhole S & NW site 3 ΕA 6 10+ years Fencina Fencing - Chain Link LF Entire Site 26 6 10+ years Fencing - Chain Link Entire Site 1.292 LF 6 10+ years LF Fencing - Chain Link Entire Site 56 4 2-5 years Worn out bent or missing components of chain-link fence Fencing - New Standard Ornamental Entire Site LF 6 565 10+ years Fencing - New Standard Ornamental Entire Site 10 LF 5 1-2 years Missing gates Landscape Benches Entire Site 3 ΕA 6 10+ years Entire Site SF 6 10+ years Landscape - Grass 7,538 Landscape - Hardscape- Pavers Entire Site 8,000 SF 7 10+ years New pavers Entire Site Parkway trees 47 EΑ 6 10+ years Planting Beds/ Area Entire Site 8,000 SF 7 10+ years New planting/drainage areas SF Planting Beds/ Area Entire Site 800 10+ years 6 Play Area - Hardscape- Asphalt Entire Site 14.642 SF 6 10+ years Play Area - Synthetic Turf SF Entire Site 3.000 7 10+ years New turf area near playgrounds SF Retaining Wall - Concrete Entire Site 200 7 10+ years New retaining walls in new developments Walking Path - Crushed Stone Entire Site 500 SF 7 New walking paths 10+ years Parking Lot Surface - Asphalt Parking Lot- East 10.060 SF 6 10+ years Verified dimension SF Surface - Asphalt Parking Lot- East 3.000 1-2 years Verified Dimension, Potholes, 4 alligatoredsurface, large cracks Lighting - Pole Mounted Old, broken, obsolete light fixtures Parking Lot-West 5 EΑ 4 0-1 year Surface - Asphalt Parking Lot- West SF 6 6-10 years 17,000 SF Surface - Asphalt Parking Lot- West 5.000 4 1-2 years Alligatored surface, large cracks, Potholes

Playground



Category : Site			B	uilding	: Site				
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Equipment - Combo 3-12	Southeast	3	EA	7	10+ years	New playground and surface		
	Equipment - Swingset	Southeast	1	EA	7	10+ years	New playground and surface		
	Surface - Poured Surface	Southeast	8,850	SF	7	10+ years	New playground and surface		
	Equipment - Pre K 3-5	Southwest	1	EA	7	10+ years	New playground and surface		
	Equipment - Swingset	Southwest	1	EA	7	10+ years	New playground and surface		
	Surface - Poured Surface	Southwest	4,000	SF	7	10+ years	New playground and surface		
Sidewalk	S								
	Sidewalks - Internal Walks	Entire Site	500	LF	7	10+ years	New internal walks		
	Sidewalks - Internal Walks	Entire Site	124	LF	6	10+ years			
	Sidewalks - Internal Walks	Entire Site	25	LF	4	0-1 year	Sidewalk in front of entrance one.		
							Badly broken pavement, upheaved		
							pavement More than 2 1/2 inches		
	Sidewalks - Perimeter Sidewalks	Entire Site	13,475	SF	6	10+ years			
Signage									
	Flag Pole - Flag Pole	Site East and North East	1	EA	6	10+ years			
	Monument - Building Mounted Cut Letter	Site East and North East	1	EA	6	10+ years			
	Sign					-			

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated ٠
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like ٠ chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Kindergarten	Kindergarten	1st Floor	108	108	955	216	60	N	N
Library	Regular Classroom	2nd Floor	207	207	720	128	48	N	N
Regular Classroom	Kindergarten	1st Floor	106	106	955	216	60	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	770	144	40	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	770	144	40	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	770	144	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	770	144	40	N	N
Special Education	Regular Classroom	2nd Floor	203	203	770	144	40	N	N
· · ·		·						•	
Building : Modular 1 (2-Classr	oom)								
Pre School	Pre School	1st Floor	M301	0	700	16	8	N	N
Pre School	Pre School	1st Floor	M302	0	700	16	8	N	Ν