

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1953	3	63,323
Addition	2013	3	35,910
Campus Total			99,233

Category : Exterior Building : Main

aicgo	y . Exterior		Bulluling : Main					
		La cardina	0		D	Recommend	•	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Entrance Control - Audio and Video	1	1	EA	6	10+ years		
	Exterior Doors - Store Front	1	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	1	1	EA	6	10+ years		
	Exterior Stairs - Concrete	1	96	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	1	30	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	10	1	EA	6	10+ years		
	Exterior Stairs - Concrete	10	45	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	10	20	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	11	1	EA	6	10+ years		
	Exterior Stairs - Concrete	11	15	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	11	20	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	12	1	EA	6	10+ years		
	Exterior Stairs - Steel or Aluminum	12	20	LF	5	2-5 years	Rust	
	Stair Handrail - Steel_Stair Handrail	12	10	LF	5	10+ years	Rust	
	Exterior Doors - Exterior Steel Door	13	1	EA	6	10+ years		
	Exterior Stairs - Steel or Aluminum	13	20	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	13	10	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	14	1	EA	6	10+ years		
	Exterior Stairs - Concrete	14	45	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	14	20	LF	6	10+ years		
	Entrance Control - Audio and Video	15	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	15	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	15	1	EA	6	10+ years		





Catego	Category : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	15	72	LF	6	10+ years	
	Power Door Operator and Controls	15	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	15	42	LF	6	10+ years	
	Ramps - Concrete	15	66	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	15	30	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	16	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	16	2	EA	6	10+ years	
	Exterior Stairs - Concrete	16	160	LF	6	10+ years	
	Exterior Stairs - Concrete	16	20	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	1	EA	6	10+ years	
	Exterior Stairs - Stone	2	23	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	2	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2.5	1	EA	6	10+ years	
	Exterior Stairs - Concrete	2.5	83	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	2.5	24	LF	6	10+ years	
	Exterior Doors - Store Front	3	2	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	3	1	ΕA	6	10+ years	
	Exterior Stairs - Concrete	3	65	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	3	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	9	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	9	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	9	65	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	9	24	LF	6	10+ years	
Foundati	ion						
Oundat	Foundation - Concrete	Entire Building	1,058	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	63,323	SF	7	10+ years	
	Superstructure Steel with Stay The Arch	Entire Ballating	00,020	O.	,	101 years	
Lighting	Fotosian Linksian - Danmart Danf Marrat	Entire Deliblica	40	Ε.Δ		40	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	16	EΑ	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	
Roof Sys							
	Access Ladder - Metal	Α	2	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	A	35	LF	5	2-5 years	Failing/Damaged Brick Work - Joint
	Liner						Failure
	Chimney - Brick Chimney- Stainless Steel Liner	Α	5	LF	4	1-2 years	Deteriorated Mortar Joints - Cracking Mortar at Joints
	Coping - Clay Tile	Α	60	LF	6	10+ years	
	Coping - Stone	A	998	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	320	LF	6	10+ years	
	Parapet - 16" - 30" Height	Ä	673	LF	6	10+ years	
	rarapor to oo rieigiir	, ,	0/3	L I	J	TOT years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Α	15	LF	4	1-2 years	Deteriorated Mortar Joints - Cracking Mortar at Joints
	Parapet - Parapet > 30"	Α	331	LF	6	10+ years	
	Parapet - Parapet > 30"	Α	40	LF	4	1-2 years	Deteriorated Mortar Joints - Cracking Mortar at Joints
	Roof - Modified Bitumen	Α	24,041	SF	4	2-5 years	Loose from Substrate - Air Bubbles Loose
	Roof Hatch - Metal	Α	2	EA	5	6-10 years	Hatch is obsolete - Subpar
	Roof Structure - Steel with Clay Tile Arch	Α	24,041	SF	7	10+ years	•
	Coping - Stone	В	64	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	32	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	64	LF	6	10+ years	
	Roof - Modified Bitumen	В	440	SF	5	6-10 years	Cracking/Bubbling
	Roof Structure - Steel with Clay Tile Arch	В	440	SF	7	10+ years	
	Access Ladder - Metal	C	1	EA	7	10+ years	
	Coping - Stone	C	180	LF	6	10+ years	
	Downspouts - Interior Downspouts	C	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	C	180	LF	6	10+ years	
	Roof - Modified Bitumen	C	3,850	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	C	3,850	SF	7	10+ years	
			-,			, , , , ,	
Walls							
	Cheek-Wall - Stone	Entire Building	376	SF	6	2-5 years	Cracked/Broken/Damaged
	Exterior Walls - Brick	Entire Building	18,562	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	213	SF	4	1-2 years	Shifting Brick/Cracks in Brick - Deteriorated Mortar Joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	285	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	174	SF	6	10+ years	
	Lintels - Steel	Entire Building	969	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	96	SF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	6,195	SF	6	10+ years	
	pane	5 24.14.119	3,100	٥.	Ū	10. 300.0	
	Windows - Decorative	Entire Building	204	SF	6	10+ years	
	Windows - Louver	Entire Building	15	SF	6	10+ years	Door 2.5
		g				.o. yea.e	200. 2.0
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System		•				
_	Emergency A/C Power - Auditoium and	Entire Building	3,959	SF	6	6-10 years	





Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Aisle Lighting				_		
	Emergency A/C Power - Corridors and	Entire Building	8,742	SF	6	6-10 years	
	Stairs				_		
	Emergency A/C Power - Students Toilets	Entire Building	1,497	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	4	EA	6	6-10 years	
	Aisle Lighting	E (00	_^	•	0.40	
	Emergency Battery Packs - Corridors and	Entire Building	20	EA	6	6-10 years	
	Stairs	Entire Duilding	2	Γ.	^	C 40	
	Emergency Battery Packs - Gym	Entire Building	3	EΑ	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EΑ	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	4	EΑ	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	63,323	SF	5	6-10 years	
Main Ser	vice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years	Serves main building only
	277/480/3PH					•	3 ,
	PA System	Entire Building	63,323	SF	6	6-10 years	Connects to addition
Dower Di	istribution						
Power D	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10 L Voors	
	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building		EA		10+ years	
	Main Distribution Panels - Greater than 600		13	EA	7 7	10+ years	
		Entire Building	1	EA	1	10+ years	
	amp Transformers - 277/480 - 120/208	Entire Building	2	EA	6	10 L VOORO	
	Transformers - 277/400 - 120/200	Entire Building	2	LA	O	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları		Fating Duilding	4			40	One control and addition building
	Fire Alarm Panel	Entire Building	1	EA SF	6	10+ years	Serves main and addition buildings
	Fire Alarm Strobe Lights	Entire Building	63,323	SF SF	6	10+ years	
	Fire Alarm_System	Entire Building	63,323	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Chemical Pot Feeder	Entire Building	1	EA	5	6-10 years	
	Glycol Feed	Entire Building	1	EA	5	6-10 years	
	Condensing Unit- Roof Mounted - 5-10	Roof	1	EΑ	5	6-10 years	Serves auditorium



atego	ry : Mechanical		В	uilding	: Main	_		
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	tons Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves MDF room, previously not assessed	
ir Hand	Iling Systems							
	Fan Coil Unit- Celing Mounted - Steam	1st Floor	2	EA	6	6-10 years	In gym, 2 found	
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Attic	2	EA	5	6-10 years		
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Attic	1	EA	5	6-10 years	In second floor mechanical room, previously not assessed	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves tunnel	
	Air Intake	Mechanical Room	1	EA	5	6-10 years		
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	6-10 years		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	50	LF	6	6-10 years		
	Zone Dampers	Mechanical Room	12	EA	5	6-10 years		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves tunnel	
	Air Intake	Mechanical Room	1	EA	5	6-10 years		
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	6-10 years		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	50	LF	6	6-10 years		
	Zone Dampers	Mechanical Room	22	EA	5	6-10 years		
	Air Handling Unit- Built Up- Single Zone- Steam Coils and Chilled Water Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves auditorium	
	Air Intake	Mechanical Room	1	EA	6	6-10 years		
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	_	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons	Roof	1	EA	6	6-10 years	Serves computer room	
iler Sy	ystems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Entire Building	2	EA	6	6-10 years		



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Chemical Feeder	Entire Building	2	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	6	10+ years	
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	2	EA	6	6-10 years	Serves main and addition building.
	Steam- Low Pressure Boiler - 151 - 200 HP						Serves 2 heat exchangers
	Piping - Condensate Pipe- Steel	Entire Building	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	400	LF	6	6-10 years	Minor leaks occasionally repaired
	Steam Traps	Entire Building	30	EA	5	6-10 years	
	Vacuum Pump	Entire Building	1	EA	5	6-10 years	
Heat Exc	changers						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	2	EA	6	10+ years	Serves addition. No HW boiler in
	Туре						addition
Heating	Devices						
	Radiators - Steam	Entire Building	14	EA	4	2-5 years	Deteriorated, difficult to control
			_		_		temperature
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	13	EA	6	10+ years	Cover is removed
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Basement	2	EA	6	10+ years	Serve heat exchanger, previously not assessed
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years	Chilled and hot water pipes
	Chilled Water Pump - Less than 10	Mechanical Room	3	EA	6	6-10 years	Serve main and addition buildings
Tempera	ture Control						
•	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve 2 ceiling mounted fan coil units, previously not assessed
	Hybrid Pneumatic/DDC System	Entire Building	63,323	SF	5	6-10 years	Pneumatic actuators, digital controls
	Thermostats - Pneumatic	Entire Building	2	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	38	EΑ	6	6-10 years	
		9				, ,	
Unit Ven							
	Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils	Entire Building	29	EA	5	6-10 years	
	Unit Ventilators- Ceiling Mounted- Hot Water & Chilled Water Coils	Library	2	EA	6	6-10 years	In library
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	4	EA	5	6-10 years	In attic

Campus Name: Hale Page : 6 of 46 Assessment Date: 12/08/2021



Catego	ry : Mechanical		В	uilding	: Main	<u>_</u>	140 S Melvina AVENUE, Chicago, IL 60638
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Plumbing		R	uilding	· Main		
Calcgo	ry . r rambing			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat						•	
	Gas Heater - 300001 - 600000 BTU/HR	Entire Building	1	EA	6	6-10 years	Tankless
	Hot Water Storage Tank_Gas - 201 - 500	Entire Building	1	EA	6	6-10 years	Recently installed
	Gallons						
Piping							
трид	Domestic Piping-Hot Water Return Lines	Entire Building	63,323	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot Water Return Risers	Entire Building	63,323	SF	6	6-10 years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water from Risers to	Entire Building	63,323	SF	6	6-10 years	There are a few pipe clamps
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	63,323	SF	6	6-10 years	Minor leaks occasionally repaired
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building	62 222	SF	6	6 10 years	There are a few pine clamps
	(Risers)	Entire Building	63,323	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot/Cold Water Supply	Entire Building	63,323	SF	6	6-10 years	There are a few pipe clamps
	(from Risers to Fixtures)	9	55,525			5 · 5 / 5 · · · ·	The state of the s
	Sanitary Piping	Entire Building	63,323	SF	6	6-10 years	
	Storm Piping	Entire Building	63,323	SF	6	6-10 years	
	Vent Piping	Entire Building	63,323	SF	6	6-10 years	
Pumps							
	Pumps - Ejector-Duplex	Entire Building	1	EA	5	6-10 years	
	Pumps - Sump-Duplex	Entire Building	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	5	6-10 years	In crawlspace
Catego	ry : Room		R	uilding	· Main		
Galogo			_	anding	· mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	016 East- School Psychologist Office	109	SF	6	10+ years	
	Doors - Wood Doors inclu hw	016 East- School Psychologist Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	016 East- School Psychologist Office	109	SF	5	10+ years	
	Lighting - Pendent/Surface	016 East- School Psychologist Office	2	EA	6	6-10 years	
	Power Distribution	016 East- School Psychologist Office	6	EA	6	6-10 years	
	Name: Hala	Dogo : 7					Accomment Date: 12/09/202



Category : Room			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	016 East- School Psychologist	380	SF	6	10+ years	
		Office					
	Ceiling - Plaster/Drywall	114 Office	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	114 Office	3	EA	6	10+ years	
	Floor - Tile	114 Office	220	SF	6	10+ years	
	Lighting - Pendent/Surface	114 Office	4	EA	6	6-10 years	
	Power Distribution	114 Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	114 Office	449	SF	6	10+ years	
	Work SInk	114 Office	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	116 West- Office	104	SF	6	10+ years	
	Ceiling - Plaster/Drywall	116 West- Office	5	SF	5	0-1 year	Damaged
	Doors - Wood Doors inclu hw	116 West- Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	116 West- Office	109	SF	5	10+ years	
	Lighting - Pendent/Surface	116 West- Office	2	EA	6	6-10 years	
	Power Distribution	116 West- Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	116 West- Office	324	SF	6	10+ years	
	Ceiling - Exposed	Engineer's Office	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Engineer's Office	220	SF	5	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	3	EA	6	6-10 years	1 fixture needs to be relamped
	Lighting - Pendent/Surface	Engineer's Office	1	EA	5	0-1 year	·
	Power Distribution	Engineer's Office	4	EA	6	6-10 years	
	Walls - Concrete Block	Engineer's Office	568	SF	6	10+ years	
	Ceiling - Exposed	Gymnasium Office	109	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gymnasium Office	1	EA	6	10+ years	Door finish damaged, cracks
	Floor - Concrete	Gymnasium Office	109	SF	5	10+ years	-
	Lighting - Pendent/Surface	Gymnasium Office	1	EA	6	6-10 years	
	Power Distribution	Gymnasium Office	2	EA	6	6-10 years	
	Walls - Concrete Block	Gymnasium Office	501	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Office	490	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Tile	Main Office	490	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office	8	EA	6	6-10 years	
	Power Distribution	Main Office	14	EA	6	6-10 years	
	Storage/ Closet	Main Office	56	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	816	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Principal's Office	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Principal's Office	160	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office	4	EA	6	6-10 years	
	Power Distribution	Principal's Office	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	435	SF	6	10+ years	
Auditoriu	um & Theater	·				•	

Auditorium & Theater





ategory : Room	В	uilding	: Main		
		_		Recommend	
oup Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Ceiling - Plaster/Drywall 1st Floor	4,154	SF	6	10+ years	
Doors - Steel Doors incl hw 1st Floor	4	EA	6	10+ years	
Doors - Wood Doors inclu hw 1st Floor	8	EA	6	10+ years	
Floor - Concrete 1st Floor	1,980	SF	5	10+ years	
Floor - Tile Ceramic/ Porcelain 1st Floor	194	SF	6	10+ years	
Floor - Tile/Sheet 1st Floor	1,980	SF	5	10+ years	
Lighting - Pendent/Surface 1st Floor	84	ĒΑ	6	6-10 years	
Main Floor Seating 1st Floor	419	ĒΑ	5	10+ years	
Stage 1st Floor	467	SF	6	10+ years	
Stage Curtain 1st Floor	5	EA	7	10+ years	
Stage Lighting System 1st Floor	1	EA	5	6-10 years	
Stage-Stairs - Wood 1st Floor	25	LF	6	10+ years	
Walls - Plaster/Drywall 1st Floor	2,465	SF	6	10+ years	
Walls - Tile 1st Floor	2,465	SF	6	-	
vvalis - Tile TSt Floor	2,405	SF	b	10+ years	
/mnasia					
Ceiling - Exposed Gymnasium	3,505	SF	6	10+ years	
Doors - Steel Doors incl hw Gymnasium	2	EA	6	10+ years	
Doors - Wood Doors inclu hw Gymnasium	2	EA	6	10+ years	
Floor - Wood Gymnasium	3,505	SF	6	10+ years	
Lighting - Pendent/Surface Gymnasium	18	EA	6	6-10 years	
Scoreboards Gymnasium	1	EA	5	6-10 years	
Storage/ Closet Gymnasium	139	SF	5	10+ years	
Walls - Concrete Block Gymnasium	2,416	SF	6	10+ years	
Walls - Structural Glazed Tile Gymnasium	1,894	SF	6	10+ years	
orary					
Casework Library used as Classroom 200B	75	LF	6	6-10 years	
Ceiling - Plaster/Drywall Library used as Classroom 200B	1,387	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
Doors - Wood Doors inclu hw Library used as Classroom 200B	3	EA	6	10+ years	
Floor - Tile Library used as Classroom 200B	1,387	SF	6	10+ years	
Lighting - Pendent/Surface Library used as Classroom 200B	33	EA	6	10+ years	
Storage/ Closet Library used as Classroom 200B	66	SF	7	6-10 years	
Walls - Plaster/Drywall Library used as Classroom 200B	2,150	SF	7	10+ years	Observed painted walls. Rank
VValis - Flaster/Drywaii Library used as Classicotti 2005	2,130	Si.	,	10+ years	changed to update current observation.
nch & Multipurpose Room					
Ceiling - Lay-in 016 Basement Teachers Lounge	1,807	SF	6	6-10 years	
Ceiling - Lay-in 016 Basement Teachers Lounge	120	SF	4	2-5 years	
Doors - Steel Doors incl hw 016 Basement Teachers Lounge	1	EA	6	10+ years	
	•		-	· ,	



Catego	ry : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Doors - Wood Doors inclu hw	016 Basement Teachers Lounge	3	EA	6	10+ years		
	Floor - Tile/Sheet	016 Basement Teachers Lounge	1,927	SF	5	10+ years		
	Lighting - Lay-in	016 Basement Teachers Lounge	20	ĒΑ	6	6-10 years		
	Lighting - Lay-in	016 Basement Teachers Lounge	9	EΑ	5	1-2 years	Damaged enclosures	
	Walls - Concrete Block	016 Basement Teachers Lounge	1,138	SF	6	10+ years	Damagea energeares	
	Walle Collecte Block	o to Basemont Touchors Loungs	1,100	O.	O	101 youro		
MDF_ID	F							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Finishes	2nd Floor	143	SF	7	6-10 years		
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split system	
viechani	cal/ Service Rooms	4-4-51		05		40		
	Janitor's Closet	1st Floor	28	SF	5	10+ years		
	Janitor's Closet	1st Floor	32	SF	5	10+ years		
	Mechanical/ Service Rooms	1st Floor	66	SF	5	10+ years		
	Air Tunnel	Basement	1,643	SF	5	10+ years		
	Air Tunnel	Basement	1,643	SF	5	10+ years		
	Boiler Room	Basement	2,043	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	761	SF	5	10+ years		
	Storage Room	Basement	1,858	SF	5	10+ years		
	Storage Room	Basement	133	SF	5	10+ years		
	Storage Room	Basement	133	SF	5	10+ years		
	Storage Room	Basement	156	SF	5	10+ years		
	Storage Room	Basement	340	SF	5	10+ years		
	Storage Room	Basement	203	SF	5	10+ years		
5 1	_							
Restroor	Accessories	014 Basement Mens	108	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	014 Basement Mens	108	SF	6	10+ years		
	Doors - Wood Doors inclu hw	014 Basement Mens	100	EA	6	10+ years		
		014 Basement Mens	' - '	SF	6	•		
	Floor - Tile Ceramic/ Porcelain		108		-	10+ years		
	Lavatory	014 Basement Mens	1	EΑ	6	6-10 years		
	Lighting - Pendent/Surface	014 Basement Mens	1	EΑ	6	6-10 years		
	Partitions	014 Basement Mens	1	EA	5	6-10 years		
	Urinals	014 Basement Mens	2	EA	6	6-10 years		
	Walls - Plaster/Drywall	014 Basement Mens	311	SF	6	10+ years		
	Water Closet	014 Basement Mens	1	EA	6	6-10 years		
	Accessories	107A	20	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	107A	20	SF	6	10+ years		
	Doors - Wood Doors inclu hw	107A	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	107A	20	SF	6	10+ years		
	Lighting - Pendent/Surface	107A	1	EA	6	6-10 years		
	Lighting - Lendent/Odnace	10171	•	SF	•	o io youio		

Campus Name: Hale Page : 10 of 46 Assessment Date: 12/08/2021



	Category : Room			Building : Main						
Water Closet										
Accessories	Group							Comments		
Ceiling - Plaster/Dywall 109A										
Doors - Wood Doors inclu hw 109A							•			
Floor - Tile Ceramic Porcelain 109A										
Lighting - Pendent/Surface 109A 139 SF 6 10+ years										
Walls - Plaster/Drywall 109A 139 SF 6 10+ years Walter Closet 109A 1 EA 6 6-10 years Accessories 111A 47 SF 7 6-10 years Ceiling - Plaster/Drywall 111A 47 SF 6 10+ years Doors - Wood Doors inclu hw 111A 47 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 111A 47 SF 6 10+ years Layatory 111A 1 EA 6 6-10 years Lighting - Pendent/Surface 111A 1 EA 6 6-10 years Lighting - Wall Mounted 111A 1 EA 6 10+ years Lighting - Wall Mounted 111A 1 EA 6 10+ years Walls - Plaster/Drywall 111A 1 EA 6 10+ years Walts - Plaster/Drywall 111A 2 21 SF 6 10+ years Celling -							10+ years			
Water Closest 109A							10+ years			
Accessories				139		-				
Ceiling - Plaster/Drywall										
Doors - Wood Doors inclu hw							6-10 years			
Floor - Tile Ceramic/ Porcelain		Ceiling - Plaster/Drywall	111A	47	SF	6	10+ years			
Lavatory			111A				10+ years			
Lighting - Pendent/Surface 111A 1 EA 6 10 - Years Lighting - Wall Mounted 111A 1 EA 6 10 - Years Partitions 111A 1 EA 6 6-10 years Partitions 111A 1 EA 6 10 - Years Partitions 111A 1 EA 7 10 - Years Partitions 111A 1 EA 6 10 years Partitions 111A 1 EA 7 10 years Partitions 111A 1 EA 1		Floor - Tile Ceramic/ Porcelain	111A	47	SF					
Lighting - Wall Mounted			111A	1	EA		6-10 years			
Partitions 111A 1 EA 7 6-10 years Walls - Plaster/Drywall 111A 221 SF 6 10+ years Water Closet 111A 1 EA 6 6-10 years Accessories 1st Floor 290 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 290 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 290 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 290 SF 6 10+ years Floor Drain 1st Floor 2 EA 6 10+ years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Lay-in 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 319 SF 6 10+ years Walls - Plaster/Drywa		Lighting - Pendent/Surface	111A	1	EA	6	10+ years			
Walls - Plaster/Drywall 111A 221 SF 6 10+ years Water Closet 111A 1 EA 6 6-10 years Accessories 1st Floor 290 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 290 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 290 SF 6 10+ years Floor Drain 1st Floor 290 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 10+ years Lavatory 1st Floor 1 EA 6 6-10 years Lighting - Lay-in 1st Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Walter Closet 1st Floor 319 SF 6 10+ years Accessories<		Lighting - Wall Mounted	111A	1	EA	6	10+ years			
Water Closet 111A 1 EA 6 6-10 years Accessories 1st Floor 290 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 290 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 290 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 290 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 10+ years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Lay-in 1st Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 31 SF 6 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 282 SF 5 6-10 years		Partitions	111A	1		7	6-10 years			
Accessories		Walls - Plaster/Drywall	111A	221	SF	6	10+ years			
Ceiling - Plaster/Drywall 1st Floor 290 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 3 EA 6 10+ years Floor - Tille Ceramic/ Porcelain 1st Floor 290 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 10+ years Layatory 1st Floor 2 EA 6 6-10 years Lighting - Lay-in 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 319 SF 6 10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10 years Waller - Structural Glazed Tile 1st Floor 9 EA 6 10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years <td></td> <td>Water Closet</td> <td>111A</td> <td>1</td> <td>EA</td> <td>6</td> <td>6-10 years</td> <td></td>		Water Closet	111A	1	EA	6	6-10 years			
Doors - Wood Doors inclu hw		Accessories	1st Floor	290		5	6-10 years			
Doors - Wood Doors inclu hw		Ceiling - Plaster/Drywall	1st Floor	290	SF	6	10+ years			
Floor Drain		Doors - Wood Doors inclu hw	1st Floor	3	EA	6				
Lavatory		Floor - Tile Ceramic/ Porcelain	1st Floor		SF		•			
Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Lay-in 1st Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 9 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 282 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 282 SF 6 10+ years Layatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years <td></td> <td>Floor Drain</td> <td>1st Floor</td> <td>1</td> <td>EA</td> <td>7</td> <td>10+ years</td> <td></td>		Floor Drain	1st Floor	1	EA	7	10+ years			
Lighting - Lay-in 1st Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partitions 1st Floor 9 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 282 SF 6 10+ years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Urinals 1st Floor 2 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years		Lavatory	1st Floor	2	EA	6				
Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Partititions 1st Floor 9 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Layatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years <td></td> <td></td> <td>1st Floor</td> <td></td> <td>EA</td> <td></td> <td></td> <td></td>			1st Floor		EA					
Partitions 1st Floor 9 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 282 SF 6 10+ years Layatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Urinals 1st Floor 325 SF 6 10+ years			1st Floor	2	EA		-			
Walls - Plaster/Drywall 1st Floor 319 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 2 EA 6 10+ years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ year			1st Floor		EA					
Walls - Structural Glazed Tile 1st Floor 319 SF 6 10+ years Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 2 EA 6 10+ years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10				319						
Water Closet 1st Floor 9 EA 6 6-10 years Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 325 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 2 EA 6 6-10 years										
Accessories 1st Floor 282 SF 5 6-10 years Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 2 EA 6 6-10 years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years										
Ceiling - Plaster/Drywall 1st Floor 282 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years							,			
Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor 2st SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 5 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet Accessories 2 EA 6 6-10 years 325 SF 6 10+ years 325 SF 6 10+ years 325 SF 6 10+ years							•			
Floor - Tile Ceramic/ Porcelain 1st Floor 282 SF 6 10+ years Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years										
Floor Drain 1st Floor 1 EA 7 6-10 years Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years							•			
Lavatory 1st Floor 2 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years										
Lighting - Pendent/Surface 1st Floor 4 EA 6 6-10 years Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years										
Partitions 1st Floor 2 EA 5 6-10 years Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years							•			
Urinals 1st Floor 4 EA 6 6-10 years Walls - Plaster/Drywall 1st Floor 325 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor 325 SF 6 10+ years Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years		• •					•			
Walls - Plaster/Drywall1st Floor325SF610+ yearsWalls - Structural Glazed Tile1st Floor325SF610+ yearsWater Closet1st Floor2EA66-10 yearsAccessories2nd Floor307SF76-10 years							•			
Walls - Structural Glazed Tile1st Floor325SF610+ yearsWater Closet1st Floor2EA66-10 yearsAccessories2nd Floor307SF76-10 years							•			
Water Closet 1st Floor 2 EA 6 6-10 years Accessories 2nd Floor 307 SF 7 6-10 years							•			
Accessories 2nd Floor 307 SF 7 6-10 years						_				
Soling - Laster/Drywaii Zhu Fiool Sur Se i 10+ years Observed painted ceiling. Rank							-	Observed painted sailing Pank		
		Cenning - Flaster/Drywall	ZHU FIUUI	307	SF	1	TOT years	Observed pairtied ceiling. Rank		

Campus Name: Hale Page : 11 of 46 Assessment Date: 12/08/2021



Catego	Category: Room		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	307	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	Observed clean lavatories. Rank changed to update current observation.
	Lighting - Lay-in	2nd Floor	1	EA	7	10+ years	Observed fixture working properly. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	10+ years	
	Partitions	2nd Floor	9	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	353	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Walls - Structural Glazed Tile	2nd Floor	353	SF	7	10+ years	No visible cracks observed. Rank changed to update current observation.
	Water Closet	2nd Floor	9	EA	7	6-10 years	Observed flush valves functioning and properly working. Rank changed to update current observation.
	Accessories	2nd Floor	283	SF	7	6-10 years	,
	Ceiling - Plaster/Drywall	2nd Floor	283	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	283	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Floor Drain	2nd Floor	1	EA	7	6-10 years	•
	Lavatory	2nd Floor	2	EA	7	6-10 years	Observed clean lavatories. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	10+ years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	$\overline{4}$	EA	7	6-10 years	Observed flush valves functioning and properly working. Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	332	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Walls - Structural Glazed Tile	2nd Floor	332	SF	7	10+ years	No cracks observed. Rank changed to update current observation.

Campus Name: Hale Page : 12 of 46 Assessment Date: 12/08/2021





Catego	ry : Room		В	uilding	: Main		, ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd Floor	2	EA	7	6-10 years	Observed flush valves functioning
							and properly working. Rank changed to update current observation.
	Accessories	2nd Floor	59	SF	7	6-10 years	•
	Ceiling - Plaster/Drywall	2nd Floor	59	SF	7	10+ years	Observed painted ceiling. Rank
	Ç ,					•	changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	59	SF	6	10+ years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	6	10+ years	
	Partitions	2nd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	232	SF	7	10+ years	Rank changed to update current
	•		_		-	•	observation.
	Walls - Plaster/Drywall	2nd Floor	8	SF	6	2-5 years	Observed peeling paint.
	Water Closet	2nd Floor	1	EA	6	6-10 years	
	Accessories	Basement South Unisex	33	SF	5	6-10 years	Bathroom portion has been demolished
	Ceiling - Exposed	Basement South Unisex	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement South Unisex	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement South Unisex	33	SF	5	10+ years	
	Lavatory	Basement South Unisex	1	ĒΑ	6	6-10 years	Bathroom converted into an office
	Lighting - Pendent/Surface	Basement South Unisex	1	EA	6	6-10 years	
	Walls - Concrete Block	Basement South Unisex	224	SF	6	10+ years	
	Water Closet	Basement South Unisex	1	ĒΑ	6	6-10 years	
	Accessories	Engineer's Toilet	33	SF	5	6-10 years	
	Ceiling - Exposed	Engineer's Toilet	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Toilet	1	EA	6	10+ years	
	Floor - Carpet	Engineer's Toilet	33	SF	6	10+ years	
	Lavatory	Engineer's Toilet Engineer's Toilet	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Toilet Engineer's Toilet	1	EA	6		
	Walls - Concrete Block		231	SF		6-10 years	
		Engineer's Toilet			6	10+ years	
	Water Closet	Engineer's Toilet	1	EA	6	6-10 years	
	Accessories	Main Office Toilet	36	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Toilet	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office Toilet	36	SF	6	10+ years	
	Lavatory	Main Office Toilet	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Main Office Toilet	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Main Office Toilet	183	SF	6	10+ years	
	Water Closet	Main Office Toilet	1	EA	6	6-10 years	
	Accessories	Mens at Gymnasium	117	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Mens at Gymnasium	117	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Mens at Gymnasium	1	EA	6	10+ years	

Campus Name: Hale Page : 13 of 46 Assessment Date: 12/08/2021





Category			Building : Main							
				_		Recommend				
Group It	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
F	Floor - Tile Ceramic/ Porcelain	Mens at Gymnasium	116	SF	6	10+ years				
F	Floor - Tile Ceramic/ Porcelain	Mens at Gymnasium	1	SF	5	0-1 year				
L	avatory	Mens at Gymnasium	1	EA	6	6-10 years				
L	ighting - Pendent/Surface	Mens at Gymnasium	1	EA	6	6-10 years				
Р	Partitions	Mens at Gymnasium	1	EA	5	6-10 years				
U	Jrinals	Mens at Gymnasium	2	EA	6	6-10 years				
٧	Valls - Plaster/Drywall	Mens at Gymnasium	238	SF	6	10+ years				
V	Valls - Structural Glazed Tile	Mens at Gymnasium	238	SF	6	10+ years				
٧	Vater Closet	Mens at Gymnasium	1	EA	6	6-10 years				
Α	Accessories	Womens at Gymnasium	131	SF	5	6-10 years				
C	Ceiling - Plaster/Drywall	Womens at Gymnasium	50	SF	6	0-1 year	Damaged			
	Ceiling - Plaster/Drywall	Womens at Gymnasium	81	SF	5	10+ years				
D	Doors - Wood Doors inclu hw	Womens at Gymnasium	1	EA	6	10+ years				
F	Floor - Tile Ceramic/ Porcelain	Womens at Gymnasium	131	SF	6	10+ years				
L	_avatory	Womens at Gymnasium	2	EA	6	6-10 years				
L	ighting - Pendent/Surface	Womens at Gymnasium	1	EA	6	6-10 years				
Р	Partitions	Womens at Gymnasium	2	EA	5	6-10 years				
٧	Valls - Plaster/Drywall	Womens at Gymnasium	237	SF	6	0-1 year	Damaged			
٧	Valls - Structural Glazed Tile	Womens at Gymnasium	237	SF	6	10+ years	-			
٧	Vater Closet	Womens at Gymnasium	2	EA	6	6-10 years				

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #020 (Store Room)						
	Ceiling - Exposed	Basement	1,405	SF	6	10+ years	
	Chalk Board	Basement	42	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	3	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,405	SF	7	10+ years	
	Lighting - Lay-in	Basement	18	EA	6	6-10 years	
	Marker Board	Basement	12	LF	6	6-10 years	
	Storage/ Closet	Basement	179	SF	5	10+ years	
	Walls - Concrete Block	Basement	995	SF	6	10+ years	
Classro	om #100 (Health)						
	Ceiling - Plaster/Drywall	1st Floor	408	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	408	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	820	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	

Campus Name: Hale Page : 14 of 46 Assessment Date: 12/08/2021





Catego	ry : Classroom	_	В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #102 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	701	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	701	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,012	SF	6	10+ years	
			-,			, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	701	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	701	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,010	SF	6	10+ years	
	•		·			•	
Classroo	om #104 (Regular Classroom)						
	Casework	1st Floor	27	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	710	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	6	10+ years	
Classroo	om #105 (Kindergarten)	4 . 🗖				0.10	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	793	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	793	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	32	LF	6	6-10 years	
	Storage/ Closet	1st Floor	82	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,021	SF	6	10+ years	
Classroo	om #106 (Regular Classroom)						
CIGOSI OU	Casework	1st Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor	708	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	





Catego	ry : Classroom		D	uildina	· Main	0	140 S Melvina AVENUE, Chicago, IL 60638		
Catego	ry : Classroom		В	Building : Main Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments		
Group	Doors - Wood Doors inclu hw	1st Floor	Quantity 1	EA	6	6-10 years	Comments		
	Floor - Tile	1st Floor	708	SF	6	•			
						10+ years			
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years			
	Marker Board	1st Floor	21	LF	6	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,018	SF	6	10+ years			
Classroo	om #107 (Kindergarten)								
	Casework	1st Floor	23	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	950	SF	6	10+ years			
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years			
	Floor - Tile	1st Floor	950	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years			
	Marker Board	1st Floor	24	LF	6				
	Storage/ Closet	1st Floor	64	SF		6-10 years			
				SF SF	5 6	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,053	SF	О	10+ years			
Classroo	om #108 (Regular Classroom)								
	Casework	1st Floor	22	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	711	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	1st Floor	711	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	10+ years			
	Marker Board	1st Floor	21	LF	6	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,021	SF	6	10+ years			
Classros	om #109 (Kindergarten)								
Classiuc	Casework	1st Floor	33	LF	-	6.10 years			
		1st Floor	33 1,049	SF	6	6-10 years			
	Ceiling - Plaster/Drywall		· · · · · · · · · · · · · · · · · · ·		6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	1,049	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	26	EA	7	10+ years			
	Marker Board	1st Floor	18	LF	6	6-10 years			
	Storage/ Closet	1st Floor	15	SF	7	10+ years			
	Storage/ Closet	1st Floor	41	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,121	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
Classroo	om #110 (Regular Classroom)								
<u></u>	Casework	1st Floor	9	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	701	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
		.5551	•		Ü	.o. youro			

Campus Name: Hale Page : 16 of 46 Assessment Date: 12/08/2021



Catego	ory : Classroom		В	uilding	: Main		140 S MEMILIA AVENUE, CHICAGO, IL 60636
J				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	701	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,002	SF	6	10+ years	
Classroo	om #111 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	292	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	292	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	ĒΑ	6	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	673	SF	6	10+ years	
_Classroo	om #112 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	732	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,039	SF	6	10+ years	
Classroo	om #113 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	751	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	751	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	10+ years	
	Marker Board	1st Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,147	SF	6	10+ years	
Classro	om #200 (Computer Lab)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	761	SF	7	10+ years	Observed painted ceiling. Rank
	Celling - Flaster/Drywaii	211d F1001	761	SF	,	10+ years	changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	00001744011.
	Floor - Tile	2nd Floor	761	SF	7	10+ years	Observed clean floor. Rank changed
						-	to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	Observed fixtures working/ functioning properly. Rank changed

Campus Name: Hale Page : 17 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	24	LF	0	0.40	to update current observation.
			21		6	6-10 years	Observed rejected wells Deals
	Walls - Plaster/Drywall	2nd Floor	1,109	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	m #201 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	6	2-5 years	Observed peeling paint
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	754	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	Observed clean marke board. Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	1,058	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	486	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	486	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	10+ years	·
	Marker Board	2nd Floor	8	LF	7	6-10 years	Observed clean marker board. Rank changed to update current observation.
	Storage/ Closet	2nd Floor	51	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.



Catego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Casework	2nd Floor	9	LF	6	6-10 years	Comments
	Ceiling - Plaster/Drywall	2nd Floor	702	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	702	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	27	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	565	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	565	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	Quantity changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	2-5 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
_Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	704	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	704	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	21	LF	7	6-10 years	Observed marker board in good condition. Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	7	10+ years	Observed painted walls. Rank changed to update current

Campus Name: Hale Page : 19 of 46 Assessment Date: 12/08/2021



Categor	y : Classroom		В	uilding	: Main		
_	B		0			Recommend	2
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments observation.
Classroo	m #206 (Regular Classroom)						
Classiool	Casework	2nd Floor	9	LF	6	6.10 vooro	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	710	SF	6 7	6-10 years 10+ years	Observed painted ceiling. Rank
	Celling - Plaster/Drywali	2114 F1001	710	SF	1	10+ years	changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	699	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	699	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	Observed fixtures working/functioning properly. Rank changed to update current observation.
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classrooi	m #208 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	703	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	703	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	31	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	7	10+ years	Observed painted walls. Rank

Campus Name: Hale Page : 20 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments changed to update current observation.
Classroo	m #209 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	704	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Observed door in good condition and properly working. Rank changed to update current observation.
	Floor - Tile	2nd Floor	704	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	·
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	962	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	m #210 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	706	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Observed door & hardware in good condition. Rank changed to update current observation.
	Floor - Tile	2nd Floor	706	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	Observed clean marker board. Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	1,006	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	m #211 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	698	SF	7	10+ years	Rank changed to update current observation.
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	6	2-5 years	Observed peeling paint.
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	701	SF	7	10+ years	Observed clean floor. Rank changed

Campus Name: Hale Page : 21 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Main	_	
0	Hama Tuma	Lagation	O	ПОМ	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	to apaate current observation.
	Marker Board	2nd Floor	21	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	959	SF	7	10+ years	Observed painted walls. Rank
	wallo Tiladol/Biywall	2110 1 1001	300	O.	•	To Tyouro	changed to update current observation.
Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	Observed painted walls. Rank
	,					•	changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	10+ years	Observed clean floor. Rank change to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	Observed clean marker board. Ran changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	983	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	754	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	754	SF	7	10+ years	Observed clean floor. Rank change to update current observation.
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	10+ years	•
	Marker Board	2nd Floor	22	LF	7	6-10 years	Observed clean marker board. Ran changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	1,047	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments





Catego	ry : Interior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	4,103	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	4	EA	5	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	71	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	4,103	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Student Lockers - One Tier	1st Floor	186	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,870	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,870	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,141	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Drinking Fountains - Double Fountain	2nd Floor	4	EΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,141	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EΑ	7	10+ years	
	Student Lockers - One Tier	2nd Floor	202	EA	7	6-10 years	Observed painted lockers. Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	2,335	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Walls - Structural Glazed Tile	2nd Floor	2,335	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	693	SF	6	10+ years	
	Floor - Terrazzo	North	426	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	72	SF	6	10+ years	
	Floor - Tile/Sheet	North	105	SF	5	10+ years	
	Handrails	North	54	LF	5	10+ years	
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years	
	Lighting - Wall Mounted	North	1	EA	6	6-10 years	
	Stairs - Terrazzo	North	127	LF	6	10+ years	
	Walls - Plaster/Drywall	North	966	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	966	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	692	SF	6	10+ years	
	Floor - Terrazzo	South	426	SF	6	10+ years	

Campus Name: Hale Page : 23 of 46 Assessment Date: 12/08/2021



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	South	71	SF	6	10+ years	
	Floor - Tile/Sheet	South	105	SF	5	10+ years	
	Handrails	South	54	LF	5	10+ years	
	Lighting - Pendent/Surface	South	4	EA	6	6-10 years	
	Lighting - Wall Mounted	South	2	EA	6	6-10 years	
	Stairs - Terrazzo	South	127	LF	6	10+ years	
	Walls - Plaster/Drywall	South	943	SF	6	10+ years	
	Walls - Structural Glazed Tile	South	943	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	305	SF	6	10+ years	
	Floor - Terrazzo	West	134	SF	6	10+ years	
	Floor - Tile/Sheet	West	88	SF	5	10+ years	
	Handrails	West	54	LF	5	10+ years	
	Lighting - Pendent/Surface	West	4	EΑ	6	6-10 years	
	Lighting - Wall Mounted	West	2	EA	6	6-10 years	
	Stairs - Terrazzo	West	104	LF	6	10+ years	
	Walls - Plaster/Drywall	West	522	SF	6	10+ years	
	Walls - Structural Glazed Tile	West	522	SF	6	10+ years	



Category : Exterior Building : Addition

atego	ry : Exterior		В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Store Front	4	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	4	2	EA	7	10+ years	
	Entrance Control - Audio and Video	5	1	ĒΑ	7	10+ years	
	Exterior Doors - Store Front	5	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	5	1	EA	7	10+ years	
	Power Door Operator and Controls	5	1	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	6	1	EA	7	10+ years	
	Exterior Doors - Store Front	7	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	7	1	EA	7	10+ years	
	Exterior Doors - Store Front	8	2	EA	7	10+ years	
	Exterior Doors - Store Front Exterior Doors - Transom Lite	8	1	EA	7		
	Exterior Doors - Transom Lite	0	1	EA	,	10+ years	
ındati							
	Foundation - Concrete	Entire Building	427	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	35,910	SF	7	10+ years	
	Topping						
nting							
-	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
	3g	· · · - · · · · · · · · · · · · · · · ·	· ·		-	,	
of Sys	tem						
-	Access Ladder - Metal	D	1	EA	7	10+ years	
	Coping - Metal	D	500	LF	7	10+ years	
	Downspouts - Interior Downspouts	D	144	LF	6	10+ years	
	Parapet - 16" - 30" Height	D	30	LF	7	10+ years	
	Parapet - Parapet > 30"	D	460	LF	7	6-10 years	
	Roof - Modified Bitumen	D	11,970	SF	6	10+ years	
	Roof Hatch - Metal	D	11,570	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	D	11,970	SF	7	10+ years	
	Concrete Topping	D	11,970	SI⁻	,	TOT years	
	Concrete Toppling						
lls							
	Exterior Walls - Brick	Entire Building	15,720	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	2,256	SF	7	10+ years	
	Wall	Little building	2,230	JI	,	TOT years	
	vvali						
ndows							
	Curtain wall - Glazed Double Pane	Entire Building	246	SF	7	10+ years	
	Lintels - Steel	Entire Building	524	LF	7	10+ years	
	Storefront Windows	Entire Building	4,912	SF	7	10+ years	
	Otoronont vvindows	Entire ballaring	4,312	JI	,	TOT years	

Campus Name: Hale Page : 25 of 46 Assessment Date: 12/08/2021



Catego	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storefront Windows	Entire Building	48	SF	7	10+ years	
	Windows - Decorative	Entire Building	68	SF	7	10+ years	
	Windows - Louver	Entire Building	160	SF	7	10+ years	
atego	ry : Electrical		В	uilding	: Additio	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	cy System						
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,845	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	5,067	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,068	SF	6	10+ years	
/lain Sei	vice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves addition
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	1 found, previously not assessed
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	Found 2
Catego	ry : Fire Protection		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	35,910	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp	Pump Room G06	1	EA	6	10+ years	2013 installation, serves addition
	Jockey Pump	Pump Room G06	1	EA	6	10+ years	

Campus Name: Hale Page : 26 of 46 Assessment Date: 12/08/2021



Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Sprinkler							
	Sprinkler Heads	Entire Building	35,910	SF	7	10+ years	
	Sprinkler Piping	Entire Building	35,910	SF	7	10+ years	0 189
	Wet Sprinkler System	Entire Building	35,910	SF	6	10+ years	Serves addition
Catego	ry : Mechanical		В	uilding	: Additi		
0	Ham Tuna	Logotion	O	HOM	Donk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	<u> </u>	Doof	2			10	Faund 2
	Chemical Pot Feeder Chiller Air Casled Sarall Type Reaf Mounted	Roof Roof	2	EA EA	6 6	10+ years	Found 2
	Chiller-Air Cooled-Scroll Type-Roof Mounted - Greater than 200 tons	ROOI	Į	EA	О	10+ years	Serves both buildings
	Glycol Feed	Roof	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	2	EA	6	6-10 years	Serves elevator room and MDF room
	than 5 tons		_	_, .		0 10 your	
_Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	6	10+ years	Evaporator, 1 in elevator mechanical
	·	· ·				•	room, other in MDF room (not
							assessed). See interior assessment
							of MDF room.
	VAV Box	Entire Building	29	EA	6	10+ years	Located above ceilings, served by 2
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	AHUs AHU 1, serves first floor
	Indoor- Hot Water and Chilled Water Coils -	Wechanical Room	'	LA	O	10+ years	Alto 1, serves mist moor
	8001-12000 cfm						
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	AHU 2, serves second and third floor
	Indoor- Hot Water and Chilled Water Coils -		·	`	· ·	. o · you.o	7 11 10 =, 001 100 0000114 4114 11114 111001
	20001-30000 cfm						
	Air Intake	Mechanical Room	1	EA	6	10+ years	
l la ation a	Davisas.						
Heating	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	
	Unit Heater - Electric	Entire Building	1	EA	6	10+ years 10+ years	
	Unit Heater - Hot Water	Entire Building	6	EA	6	10+ years	
	Radiator Panels - Electric	Entire Building	4	EA	6	10+ years	In restrooms
	radiator ranels Electric	Little Building	7		O	TOT years	iii iosiiooiiis
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	700	LF	6	10+ years	Connected to main building
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	10+ years	Connected to heat exchanger in main
	Chilled Water Pump - Less than 10	Machanical Poom	4	⊏∧	6	10 Lycara	building Serve both buildings
	Crimed water Pump - Less than 10	Mechanical Room	4	EA	6	10+ years	Serve both buildings

Campus Name: Hale Page : 27 of 46 Assessment Date: 12/08/2021



Nathan Hale Elementary School 6140 S Melvina AVENUE, Chicago, IL 60638

outego	ry : Mechanical		В	uilding	: Additi		
			a	11614	ъ.	Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
empera	ture Control						
	DDC System	Entire Building	35,910	SF	6	6-10 years	Serves addition
	Electric Controls	Entire Building	3,510	SF	6	10+ years	Electric thermostats serve unit heaters, mini split system
	Thermostats - DDC	Entire Building	30	EA	6	10+ years	nodioro, mini opini oyotom
entilatio	on.						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	3	EA	6	10+ years	RF1, RF2
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	•
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	Serves dishwasher
atego	ry : Plumbing		В	uilding	: Additi	on	
roun	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
roup		Location	Quantity	UOIVI	Kalik	Replacement	Comments
10+ ///0+4							
lot Wate	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years	
Hot Wate		Mechanical Room Mechanical Room	1 2	EA EA	5 6	6-10 years 6-10 years	Serves dishwasher, previously no assessed 2013 installation, serves addition
	Electric Heater - Less than 20 KW					-	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines	Mechanical Room Entire Building	35,910	EA SF	6	6-10 years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Mechanical Room Entire Building Entire Building	35,910 35,910	EA SF SF	6 6 6	6-10 years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to	Mechanical Room Entire Building	35,910	EA SF	6	6-10 years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Mechanical Room Entire Building Entire Building	35,910 35,910	EA SF SF	6 6 6	6-10 years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Mechanical Room Entire Building Entire Building Entire Building	35,910 35,910 35,910	SF SF SF	6 6 6 6	6-10 years 10+ years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Mechanical Room Entire Building Entire Building Entire Building Entire Building	35,910 35,910 35,910 35,970	SF SF SF SF	6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Mechanical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	35,910 35,910 35,910 35,970 35,910	SF SF SF SF SF	6 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Mechanical Room Entire Building	35,910 35,910 35,910 35,970 35,910 35,910	SF SF SF SF SF	6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	assessed
	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Mechanical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	35,910 35,910 35,910 35,970 35,910	SF SF SF SF SF	6 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	assessed
Piping	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Mechanical Room Entire Building	35,910 35,910 35,910 35,970 35,910 35,910 35,910 35,910	SF SF SF SF SF SF	6 6 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	assessed
Piping	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Mechanical Room Entire Building	35,910 35,910 35,910 35,970 35,910 35,910 35,910 35,910	SF SF SF SF SF SF	6 6 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	assessed

Campus Name: Hale Page : 28 of 46 Assessment Date: 12/08/2021





Category : Plumbing Building : Addition

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

assessed

Category : Room Building : Addition

Calego	ry . Room			unanig	. Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	trative Suites/Offices						
	Ceiling - Lay-in	214 Office	328	SF	7	10+ years	
	Doors - Side-lite	214 Office	45	SF	7	10+ years	
	Doors - Steel Doors incl hw	214 Office	1	EA	7	10+ years	
	Doors - Transom Window	214 Office	9	SF	7	10+ years	
	Floor - Tile	214 Office	328	SF	7	10+ years	
	Lighting - Pendent/Surface	214 Office	4	EA	7	10+ years	
	Power Distribution	214 Office	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	214 Office	631	SF	7	10+ years	
	Ceiling - Lay-in	314 Office	328	SF	7	6-10 years	Observed clean ceiling. Rank
							changed to update current
							observation.
	Doors - Side-lite	314 Office	45	SF	7	10+ years	Observed side light in good condition.
							Rank changed to update current
							observation.
	Doors - Steel Doors incl hw	314 Office	1	EA	7	10+ years	Observed door in good condition.
							Rank changed to update current
							observation.
	Doors - Transom Window	314 Office	9	SF	7	10+ years	Observed transom window in good
							condition. Rank changed to update
							current observation.
	Floor - Tile	314 Office	328	SF	7	10+ years	Observed clean floor. Rank changed
							to update current observation.
	Lighting - Pendent/Surface	314 Office	4	EA	7	6-10 years	Observed fixtures functioning and
							properly working. Rank changed to
							update current observation.
	Power Distribution	314 Office	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	314 Office	631	SF	7	10+ years	Observed painted walls. Rank
							changed to update current
							observation.
	Ceiling - Lay-in	Office 336 New Asset	204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office 336 New Asset	1	EA	7	10+ years	
	Floor - Tile	Office 336 New Asset	204	SF	7	10+ years	
	Lighting - Lay-in	Office 336 New Asset	2	EA	7	10+ years	
	Power Distribution	Office 336 New Asset	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Office 336 New Asset	580	SF	7	10+ years	
	Ceiling - Lay-in	Office G15 Kitchen	161	SF	6	6-10 years	
	Doors - Side-lite	Office G15 Kitchen	42	SF	6	10+ years	
	Doors - Steel Doors incl hw	Office G15 Kitchen	1	EA	6	10+ years	

Campus Name: Hale Page: 29 of 46 Assessment Date: 12/08/2021



tem - Type Floor - Tile Quarry Lighting - Pendent/Surface	Location Office G15 Kitchen	Quantity	UOM		Recommend	
Floor - Tile Quarry Lighting - Pendent/Surface		Quantity	LION			
ighting - Pendent/Surface	Office G15 Kitchen			Rank	Replacement	Comments
	Office O 13 Mitchell	161	SF	6	10+ years	
	Office G15 Kitchen	3	EA	6	6-10 years	
Power Distribution	Office G15 Kitchen	8	EA	6	6-10 years	
Valls - Concrete Block	Office G15 Kitchen	363	SF	6	10+ years	
Walls - Plaster/Drywall	Office G15 Kitchen	121	SF	6	10+ years	
Sattle and Landin	4-4-51	4.000	0.5		0.40	
				-		
				-		
	1st Floor	15	EA	6		
	1st Floor	2	EA	6	6-10 years	
Storage/ Closet	1st Floor	159	SF	5	10+ years	
Walls - Concrete Block	1st Floor	1,286	SF	6	10+ years	
ultipurpose Room						
	G19	4 875	SF	6	6-10 years	
Dears Stool Doors incl by						
					•	
		=				
					•	
		, -				
		10	EA	6		
ighting - Lay-in	G19	2	EA	6	6-10 years	
ighting - Pendent/Surface	G19	54	EA	6	6-10 years	
Walls - Concrete Block	G19	2,095	SF	6	10+ years	
Doors - Steel Doors incl hw	2nd Floor	1	FΑ	7	10+ vears	
					-	Ductless split system
· ·	2.13 / 100	·		·	5 .5 you.5	2 doneso cp.m cyclem
Janitor's Closet	1st Floor	57	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	2,866	SF	7	10+ years	
Mechanical/ Service Rooms	1st Floor	228	SF			
Mechanical/ Service Rooms						
					•	
					•	
Storage Room	2nd Floor	123	SF	7	10+ years	
	Valls - Concrete Block Ultipurpose Room Ceiling - Lay-in Ceiling - Plaster/Drywall Coors - Steel Doors incl hw Coors - Store Front Cloor - Concrete Cloor - Tile/Sheet ighting - Lay-in ighting - Lay-in ighting - Pendent/Surface Valls - Concrete Block Coors - Steel Doors incl hw Cinishes Cother Cooling Unit / Service Rooms anitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms	Noors - Steel Doors incl hw loor - Tile Quarry last Floor lighting - Lay-in last Floor lighting - Pendent/Surface last Floor lighting - Pendent/Surface last Floor la	Steel Doors incl hw	Doors	1st Floor 2	1st Floor 1st Floor 2

Campus Name: Hale Page : 30 of 46 Assessment Date: 12/08/2021



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	3rd Floor	78	SF	7	10+ years	Observed painted Room in good condition. Rank changed to update current observation.
	Storage Room	3rd Floor	128	SF	7	10+ years	Storage Room 324 Observed painted room in good condition. Rank changed to update current observation.
	Storage Room	3rd Floor	208	SF	7	10+ years	Observed painted room in good condition. Rank changed to update current observation.
Restroor	n						
	Accessories	220 Womens	77	SF	7	6-10 years	
	Ceiling - Lay-in	220 Womens	77	SF	7	10+ years	
	Doors - Steel Doors incl hw	220 Womens	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	220 Womens	77	SF	7	10+ years	
	Floor Drain	220 Womens	1	EA	7	6-10 years	
	Lavatory	220 Womens	1	EA	7	6-10 years	
	Lighting - Lay-in	220 Womens	1	EA	7	10+ years	
	Showers	220 Womens	1	EA	7	6-10 years	
	Walls - Concrete Block	220 Womens	200	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	220 Womens	59	SF	7	10+ years	
	Water Closet	220 Womens	1	EA	7	6-10 years	Observed flush valve functioning and
	Water closes	220 Womone	·	271	,	o ro youro	properly working. Rank changed to update current observation.
	Accessories	236 Girls	270	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	236 Girls	270	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	236 Girls	270	SF	7	10+ years	
	Floor Drain	236 Girls	1	EA	7	6-10 years	
	Hand Dryer	236 Girls	2	EA	7	6-10 years	
	Lavatory	236 Girls	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	236 Girls	3	EA	7	10+ years	
	Partitions	236 Girls	6	ΕA	7	6-10 years	
	Walls - Concrete Block	236 Girls	492	SF	7	10+ years	
	Walls - Structural Glazed Tile	236 Girls	57	SF	7	10+ years	
	Water Closet	236 Girls	6	EA	7	6-10 years	
	Accessories	238 Boys	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	238 Boys	298	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	238 Boys	298	SF	7	10+ years	
	Floor Drain	238 Boys	1	EA	7	6-10 years	
	Hand Dryer	238 Boys	2	EA	7	6-10 years	
	Lavatory	238 Boys	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	238 Boys	3	EA	7	10+ years	
	Partitions	236 Boys	3	EA	7	6-10 years	
	FAUUIOUS	ZOO DUVS		ĽA	/	o- io veais	

Campus Name: Hale Page : 31 of 46 Assessment Date: 12/08/2021



Category : Room			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Urinals	238 Boys	3	EA	7	6-10 years			
	Walls - Concrete Block	238 Boys	526	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.		
	Walls - Structural Glazed Tile	238 Boys	53	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.		
	Water Closet	238 Boys	3	EA	7	6-10 years			
	Accessories	322 Mens	76	SF	7	6-10 years	Observed accessories in good condition. Rank changed to update current observation.		
	Ceiling - Lay-in	322 Mens	76	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.		
	Doors - Steel Doors incl hw	322 Mens	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	322 Mens	76	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.		
	Floor Drain	322 Mens	1	EA	7	6-10 years	·		
	Lavatory	322 Mens	1	EA	6	6-10 years			
	Lighting - Lay-in	322 Mens	1	EA	6	6-10 years			
	Showers	322 Mens	1	EA	5	6-10 years			
	Walls - Concrete Block	322 Mens	203	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.		
	Walls - Tile Ceramic/ Porcelain	322 Mens	54	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.		
	Water Closet	322 Mens	1	EA	6	6-10 years			
	Accessories	332 Girls	250	SF	7	6-10 years	Observed accessories in good condition. Rank changed to update current observation.		
	Ceiling - Plaster/Drywall	332 Girls	250	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.		
	Floor - Tile Ceramic/ Porcelain	332 Girls	250	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.		
	Floor Drain	332 Girls	1	EA	7	10+ years			
	Hand Dryer	332 Girls	2	EA	7	6-10 years			
	Lavatory	332 Girls	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	332 Girls	2	EA	7	10+ years	Quantity and Rank changed to update current observation.		
	Lighting - Pendent/Surface	332 Girls	1	EA	6	2-5 years	•		
	Partitions	332 Girls	6	ĒA	7	6-10 years	Observed painted partitions. Rank changed to update current		

Campus Name: Hale Page : 32 of 46 Assessment Date: 12/08/2021



Catego	ategory : Room Building : Addition						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	332 Girls	474	SF	7	10+ years	observation. No visible mortar cracks observed. Rank changed to update current observation.
	Walls - Structural Glazed Tile	332 Girls	53	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.
	Water Closet	332 Girls	6	EA	7	6-10 years	Observed flush valves functioning and properly working. Rank changed to update current observation.
	Accessories	334 Boys	250	SF	7	6-10 years	Observed accessories in good condition. Rank changed to update current observation.
	Ceiling - Plaster/Drywall	334 Boys	250	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Floor - Tile Ceramic/ Porcelain	334 Boys	250	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Floor Drain	334 Boys	1	EA	7	6-10 years	
	Hand Dryer	334 Boys	2	EA	7	6-10 years	Observed hand dryers working/ functional. Rank changed to update current observation.
	Lavatory	334 Boys	3	EA	7	6-10 years	Quantity changed to update current observation. 1 lavatory in the ADA stall. Rank changed to update current observation.
	Lighting - Pendent/Surface	334 Boys	3	EA	7	6-10 years	Observed relamped fixtures to be working/ functional. Rank changed to update current observation.
	Partitions	334 Boys	3	EA	7	6-10 years	
	Urinals	334 Boys	3	EA	6	6-10 years	
	Walls - Concrete Block	334 Boys	474	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.
	Walls - Structural Glazed Tile	334 Boys	53	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.
	Water Closet	334 Boys	3	EA	7	6-10 years	Observed Sloan flush valves functioning and properly working. Rank changed to update current observation.
	Accessories	G03 Mens	62	SF	7	6-10 years	
	Ceiling - Lay-in	G03 Mens	62	SF	7	10+ years	
	Doors - Steel Doors incl hw	G03 Mens	1	EA	7	10+ years	

Campus Name: Hale Page : 33 of 46 Assessment Date: 12/08/2021



Nathan Hale Elementary School

Catego	ory : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Ceramic/ Porcelain	G03 Mens	62	SF	7	10+ years			
	Floor Drain	G03 Mens	1	EA	7	6-10 years			
	Hand Dryer	G03 Mens	1	EA	7	6-10 years			
	Lavatory	G03 Mens	1	EA	7	6-10 years			
	Lighting - Lay-in	G03 Mens	1	EA	7	10+ years			
	Walls - Concrete Block	G03 Mens	262	SF	7	10+ years			
	Water Closet	G03 Mens	1	EA	7	6-10 years			
	Accessories	G04 Womens	65	SF	7	6-10 years			
	Ceiling - Lay-in	G04 Womens	65	SF	7	10+ years			
	Doors - Steel Doors incl hw	G04 Womens	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	G04 Womens	65	SF	7	10+ years			
	Floor Drain	G04 Womens	1	EA	7	6-10 years			
	Hand Dryer	G04 Womens	1	EA	7	6-10 years			
	Lavatory	G04 Womens	1	EA	7	6-10 years			
	Lighting - Lay-in	G04 Womens	1	EA	7	10+ years			
	Walls - Concrete Block	G04 Womens	253	SF	7	10+ years			
	Water Closet	G04 Womens	1	EA	7	6-10 years			
Catego	ory : Classroom		В	uilding	: Additi	on			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classro	om #215 (Regular Classroom)								
	Casework	2nd Floor	30	LF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	953	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	953	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.		

Classroom #216 (Regular Classroom)

, ,					
Casework	2nd Floor	30	LF	7	6-10 years
Ceiling - Lay-in	2nd Floor	927	SF	7	10+ years
Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years
Floor - Tile	2nd Floor	927	SF	7	10+ years
Lighting - Lay-in	2nd Floor	5	EΑ	7	10+ years
Lighting - Lay-in	2nd Floor	3	EA	7	10+ years
Lighting - Pendent/Surface	2nd Floor	8	EΑ	7	10+ years
Marker Board	2nd Floor	24	LF	7	6-10 years

Observed clean marker board. Rank changed to update current



Categor	y : Classroom		В	Building : Addition				
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	M II DI (/D II	0 15	4 000	05	-	40	observation.	
	Walls - Plaster/Drywall	2nd Floor	1,092	SF	7	10+ years	Observed painted walls. Rank	
							changed to update current	
							observation.	
Classroo	m #217 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	868	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile			SF	7			
		2nd Floor	868	_		10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,065	SF	7	10+ years	Observed painted walls. Rank	
							changed to update current	
							observation.	
Classroo	m #219 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	863	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	863	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	5	EΑ	7	10+ years		
		2nd Floor	8	EA	7	-		
	Lighting - Pendent/Surface					10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,074	SF	7	10+ years		
Classroo	m #221 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	866	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	2nd Floor	866	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years		
	Lighting Dandont/Confess					•		
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,076	SF	7	10+ years		
<u>Classro</u> o	m #223 (Regular Classroom)							
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	878	SF	7	10+ years		
			510	Ŭ.	•	, , , , , ,		

Campus Name: Hale Page : 35 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	878	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	Observed clean marker board, Rank
						,	changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years	Observed painted painted walls. Rank changed to update current observation.
_Classroo	om #240 (Regular Classroom)						
	Casework	2nd Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	830	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board		24	LF	-	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1.049	SF	6 7	10+ years	Observed painted walls. Rank
	walls - Flaster/Drywall	2110 1 1001	1,049	Si.	,	TOT years	changed to update current observation.
Classroo	om #242 (Regular Classroom)						
	Casework	2nd Floor	30	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	902	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	902	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	5	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,102	SF	7	10+ years	Observed painted walls. Rank
	walls - Flastel/Diywall	ZIIU FIOOI	1,102	Sir	,	TOT years	changed to update current observation.
_Classroo	om #315 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	922	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	

Campus Name: Hale Page : 36 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Additi	on	
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	3rd Floor	922	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Marker Board	3rd Floor	22	LF	6	6-10 years	•
	Walls - Plaster/Drywall	3rd Floor	1,088	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
_Classroo	om #316 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	6-10 years	Observed casework in good condition. Rank changed to update
							current observation.
	Ceiling - Lay-in	3rd Floor	900	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	update current observation. Observed fixtures functioning and properly working. Rank changed to update current observation.
	Marker Board	3rd Floor	32	LF	6	6-10 years	apadio odironi obodivation.
	Walls - Plaster/Drywall	3rd Floor	1,073	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	om #317 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	865	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.

Campus Name: Hale Page : 37 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Additi	on	
			•			Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	5	EΑ	7	6-10 years	Quantity and Rank changed to update current observation. Fixtures are functioning and properly working.
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,075	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	om #319 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	6-10 years	Observed casework in good condition. Rank changed to update current observation.
	Ceiling - Lay-in	3rd Floor	655	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Floor - Tile	3rd Floor	655	SF	7	10+ years	Observed clean floor. Rank changed to update current observation
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Marker Board	3rd Floor	24	LF	7	6-10 years	Observed clean marker board. Rank changed to update current observation.
	Walls - Plaster/Drywall	3rd Floor	939	SF	7	6-10 years	Observed painted walls. Rank changed to update current observation.
Classroo	om #321 (Regular Classroom)						
	Casework	3rd Floor	26	LF	7	6-10 years	Observed casework in good condition. Rank changed to update

Campus Name: Hale Page : 38 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Additi	on	
			.			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	750	SF	7	6-10 years	current observation. Observed ceiling in good condition. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation. Engineer ordered a new light switch.
	Walls - Plaster/Drywall	3rd Floor	1,006	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroo	om #323 (Computer Lab)						
	Casework	3rd Floor	3	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,123	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,123	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	Quantity and Rank changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed to update current observation.
	Marker Board	3rd Floor	24	LF	7	6-10 years	Observed marker board in good condition. Rank changed to update current observation.
	Walls - Plaster/Drywall	3rd Floor	1,194	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Wireless System	3rd Floor	1	EA	5	6-10 years	observation.

Campus Name: Hale Page : 39 of 46 Assessment Date: 12/08/2021



Catego	ry : Classroom		В	uilding	: Addition	on	
~	Itam Tuna	Location	Ougatitu	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Classroo	m #330 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	374	SF	7	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	374	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	707	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	206	SF	7	10+ years	
Classroo	m #338 (Art Room)						
	Casework	3rd Floor	33	LF	6	6-10 years	
	Ceiling - Exposed	3rd Floor	1,612	SF	7	10+ years	Observed painted ceiling. Rank
	Zaming Expected	574 1 1551	1,612	O.	•	ro. youro	changed to update current observation.
	Ceiling - Exposed	3rd Floor	3	SF	5	1-2 years	Damaged plaster
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	Observed doors functioning and
						, , , , , ,	properly working. Rank changed to update current observation.
	Floor - Tile	3rd Floor	1,615	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Kiln	3rd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	302	SF	7	10+ years	Observed painted room. Rank changed to update current observation.
	Walls - Concrete Block	3rd Floor	480	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.
	Walls - Plaster/Drywall	3rd Floor	1,209	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Work Sink	3rd Floor	1	EA	5	6-10 years	observation.
Catego	ry : Interior		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Ceiling - Lay-in	1st Floor	222	SF	6	6-10 years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	1st Floor	95	SF	6	10+ years	
	James I lactor, Dry Wall	1001 1001	33	٥.	9	. o . youro	



Catego	ry : Interior		В	uilding	: Addition	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	317	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Stairs - Concrete Stairs	1st Floor	42	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,592	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	8	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,592	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	41	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	12	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	100	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	513	SF	7	10+ years	No visible mortar cracks observed.
							Rank changed to update current observation.
	Walls - Plaster/Drywall	2nd Floor	2,259	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
	Ceiling - Lay-in	3rd Floor	2,382	SF	7	6-10 years	Observed clean ceiling. Rank changed to update current
	Ceiling - Plaster/Drywall	3rd Floor	146	SF	7	10+ years	observation. Observed painted ceiling. Rank changed to update current observation.
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	10+ years	observation.
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years 10+ years	Observed fountains working properly
	Dilliking Fountains - Single Fountain	314 F1001	2	EA	7	10+ years	Rank changed to update current observation.
	Drinking Fountains - Single Fountain	3rd Floor	1	EΑ	5	1-2 years	Observed fountain not working
	Floor - Tile/Sheet	3rd Floor	2,528	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	3rd Floor	19	EA	7	6-10 years	Observed relamped fixtures. Rank
			-			,	changed to update current observation.
	Lighting - Pendent/Surface	3rd Floor	38	EA	7	6-10 years	Observed working fixtures. Rank changed to update current observation.
	Student Lockers - One Tier	3rd Floor	11	EA	7	6-10 years	Observed clean and painted lockers. Rank changed to update current observation.
	Student Lockers - Two Tiers	3rd Floor	80	EA	7	6-10 years	Observed clean and painted lockers. Rank changed to update current observation.

Campus Name: Hale Page : 41 of 46 Assessment Date: 12/08/2021



Category : Interior Building : Addition								
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	3rd Floor	513	SF	7	6-10 years	No visible mortar cracks observed.	
							Rank changed to update current	
	Walls - Plaster/Drywall	3rd Floor	2,259	SF	7	6-10 years	observation. Observed painted walls. Rank	
	Walls - Flastel/Drywall	31d F1001	2,239	SF	,	0-10 years	changed to update current	
							observation.	
	Ceiling - Lay-in	Ground Level	595	SF	6	6-10 years		
	Ceiling - Plaster/Drywall	Ground Level	279	SF	6	10+ years		
	Doors - Steel Doors incl hw	Ground Level	2	EA	6	10+ years		
	Doors - Store Front	Ground Level	4	EA	6	10+ years		
	Floor - Tile/Sheet	Ground Level	874	SF	5	10+ years		
	Lighting - Lay-in	Ground Level	8	EA	6	6-10 years		
	Student Lockers - One Tier	Ground Level	5	EA	6	6-10 years		
	Walls - Concrete Block	Ground Level	1,500	SF	6	10+ years		
_Stairs								
	Ceiling - Exposed	East	376	SF	7	10+ years		
	Ceiling - Lay-in	East	363	SF	7	10+ years		
	Floor - Tile/Sheet	East	774	SF	7	10+ years		
	Handrails	East	126	LF	7	10+ years		
	Lighting - Lay-in	East	6	EA	7	10+ years		
	Lighting - Wall Mounted	East	3	EA	7	10+ years		
	Stairs - Concrete	East	289	LF	7	10+ years		
	Walls - Concrete Block	East	3,849	SF	7	10+ years		
	Ceiling - Exposed	West	376	SF	7	10+ years		
	Ceiling - Lay-in	West	363	SF	7	10+ years		
	Floor - Tile/Sheet	West	774	SF	7	10+ years		
	Handrails	West	126	LF	7	10+ years		
	Lighting - Lay-in	West	6	EA	7	10+ years		
	Lighting - Wall Mounted	West	3	EA	7	10+ years		
	Stairs - Concrete	West	289	LF	7	10+ years		
	Walls - Concrete Block	West	3,432	SF	7	10+ years		
Vertical	Conveyance							
	Elevator - Hydraulic Elevator	Ground Floor to Third Floor	1	EA	7	10+ years		



Category : Site Building : Site

Jategoi	ry : Site		В	ullaing	: Site		
		I a setta a	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	•						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	19	EA	6	10+ years	
encing							
ŭ	Fencing - Chain Link	Entire Site	44	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,286	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	5	1-2 years	Bent - Damaged
andscar	oe .						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	45,419	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	11,852	SF	6	10+ years	
	Parkway trees	Entire Site	['] 15	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,950	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	1,320	SF	6	10+ years	
arking L	_ot						
9	Concrete Curbs	Entire Site	1,012	LF	7	10+ years	
	Interior Plantings	Entire Site	19	LF	6	10+ years	
	Pavers	Entire Site	17,050	SF	6	10+ years	
	Surface - Asphalt	Entire Site	49,739	SF	6	10+ years	
	Trash Compactor	Entire Site	1	ĒΑ	7	10+ years	
	Trash Enclosure - Masonry	Entire Site	960	SF	7	10+ years	
idewalk	s						
	Sidewalks - Perimeter Sidewalks	Entire Site	9,738	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,050	SF	5	2-5 years	
ignage							
	Flag Pole - Flag Pole	Southeast	1	EA	7	10+ years	
				EA			

Campus Name: Hale Page : 43 of 46 Assessment Date: 12/08/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hale Page: 44 of 46 Assessment Date: 12/08/2021





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	2nd Floor	200	202	761	138	18	N	N
Health	Regular Classroom	1st Floor	100	NA	408	184	96		
Kindergarten	Kindergarten	1st Floor	105	105	793	184	24	N	Υ
Kindergarten	Kindergarten	1st Floor	107	107	950	253	33	N	Υ
Kindergarten	Kindergarten	1st Floor	109	109	1,049	276	36	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	701	184	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	701	184	24	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	710	184	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	708	184	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	711	184	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	701	184	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	111	111	292	92	12	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	732	184	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	751	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	754	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	486	138	18	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	702	188	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	565	92	12	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	704	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	710	147	41	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	699	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	703	147	41	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	704	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	706	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	701	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	730	184	24	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	754	184	24	N	Υ
Store Room	Regular Classroom	Basement	020	Class Room	1,405	132	21	N	N
Building : Addition									
Art Room	Art Room	3rd Floor	338	307	1,615	830	0	N	Υ
Computer Lab	Computer Lab	3rd Floor	323	310	1,123	232	21	N	N
Regular Classroom	Office	3rd Floor	330	330	374	72	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	214	953	202	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	216	927	202	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	213	868	174	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	219	212	863	174	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	221	211	866	174	14	N	Υ





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	223	210	878	174	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	240	206	830	174	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	242	207	902	174	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	315	314	922	202	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	316	316	900	202	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	317	313	865	174	14	N	Y
Regular Classroom	Regular Classroom	3rd Floor	319	312	655	145	7	N	N
Regular Classroom	Regular Classroom	3rd Floor	321	311	750	145	14	N	N