

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1903	3	74,643
Campus Total			74,643

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 Main S	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1 Main S	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	1 Main S	2	EA	7	10+ years	
	Exterior Doors - Exterior Wood Door	2 W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 W	2	EA	7	10+ years	
	Exterior Stairs - Concrete	2 W	12	LF	5	6-10 years	
	Exterior Doors - Exterior Wood Door	3 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3 W	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	4 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	4 N	1	EA	6	10+ years	
	Exterior Stairs - Stone	4 N	0	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4.5 N	2	EA	4	2-5 years	Corroded doors
	Exterior Doors - Exterior Wood Door	5 E	2	EA	6	10+ years	
	Exterior Stairs - Stone	5 E	4	LF	5	10+ years	
	Entrance Control - Audio	6 E	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	6 E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	6 E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	6 E	16	LF	5	1-2 years	Concrete has been repaired, but it continues to deteriorate
	Exterior Doors - Exterior Steel Door	7-Light courts	1	EA	6	10+ years	
	Exterior Stairs - Concrete	7-Light courts	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	8 - Light court	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	8 - Light court	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Northeast Fire Escape	3	EA	6	10+ years	



Group Item - Type Location Quantity UOM Recommend Recommend Exterior Stairs - Concrete Northeast Fire Escape 15 LF 7 10 + years Cracked concrete Exterior Doors - Exterior Steil Doors Northwest Fire Escape 1 EA 4 0.1 years Cracked concrete Exterior Stairs - Concrete Northwest Fire Escape 15 LF 5 1.2 years Fire Escape Entire Building 107 L 6 10+ years Fire Escape Entire Building 117 L F 6 10+ years Fire Escape Entire Building 15 LF 6 10+ years Several Surface rods at stair treads an rom ong goad Fire Escape Entire Building 71 LF 7 10+ years Several Surface rods at stair treads an rom ong goad Foundation Masony Entire Building 71,844 SF 7 10+ years Superstructure - Heavy Timber Entire Building 71,844 SF 7 10+ years	Catego	Category : Exterior		В	uilding	: Main		Ţ	
Exterior Stairs - Concrete Northeast Fire Escape 15 LF 7 10+ years Cracked concrete Exterior Doors - Exterior Steel Doors - Transom Lite Northwast Fire Escape 1 EA 4 0-1 years Linet at transoms is corroded and deflected with bick above detaching from the fa&gade Exterior Stairs - Concrete Northwast Fire Escape 15 LF 5 1-2 years Fire Escape Entre Building 117 LF 6 10+ years Fire Escape Fire Escape Entre Building 117 LF 6 10+ years and landings are bent and and create an uneven ground Fire Escape Entre Building 5 LF 4 0-1 year Fire Escape is not properly anchored to masony Foundation Mesonry Entre Building 71.144 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entre Building 2.79 SF 7 10+ years Lighting Chime y - Brick Chimney- Stainless Steel Low 20 LF 6 10+ years Chime y - Brick Chimney - Stainless Steel Low 20 LF 6 10+ years	J	•			Ŭ		Recommend		
Exterior Doors - Exterior Stell Door Northwest Fire Escape 3 EA 6 10-1 year Exterior Doors - Transom Lite Northwest Fire Escape 1 EA 4 0-1 year Exterior Doors - Transom Lite Northwest Fire Escape 15 LF 5 1-2 years Fire Escape Entire Building 117 LF 6 10-1 year Several Surface rods at stair transds and landings are bent and create an unerong mound Fire Escape Entire Building 15 LF 5 0-1 year Several Surface rods at stair transds and landings are bent and create an unerong mound Fire Escape Entire Building 7 LF 4 0-1 year Several Surface rods at stair transds and landings are bent and create an unerong mound Foundation Fire Escape Entire Building 78.24 SF 7 10+ years Superstructure - Heavy Timber Entire Building 71.844 SF 7 10+ years Superstructure - Heavy Timber Entire Building 71.844 SF 7 10+ years Cold System Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10	Group		Location	Quantity	UOM	Rank	Replacement	Comments	
Exterior Doors - Transom Lite Northwest Fire Escape 1 EA 4 0-1 year Lintle at transoms is corroded and deficience with brick above detaching from the faŧade Exterior Stairs - Concrete Northwest Fire Escape 15 LF 5 1-2 years Fire Escape Entire Building 117 LF 6 10+ years and landings are bear and create an uneven ground Fire Escape Entire Building 15 LF 5 0-1 year Several Surface rods at stair treads and landings are bear and create an uneven ground Fire Escape Entire Building 5 LF 4 0-1 year Fire escape in the faŧade Foundation Entire Building 5 LF 7 10+ years Several Surface rods at stair treads an uneven ground Foundation Entire Building 71844 SF 7 10+ years Superstructure - Neavy Timber Entire Building 14 EA 6 6-10 years Lighting Chirney - Brick Chimney-Stainless Steel Low 2799 SF 7 10+ years Chirney - Meigh Flue Low 20 LF 6 10+ years Th	-	Exterior Stairs - Concrete	Northeast Fire Escape	15	LF	7	10+ years	Cracked concrete	
Exterior Doors - Transom Lite Northwest Fire Escape 1 EA 4 0-1 year Lintle at transoms is corroded and deficience with brick above detaching from the faŧade Exterior Stairs - Concrete Northwest Fire Escape 15 LF 5 1-2 years Fire Escape Entire Building 117 LF 6 10+ years and landings are bear and create an uneven ground Fire Escape Entire Building 15 LF 5 0-1 year Several Surface rods at stair treads and landings are bear and create an uneven ground Fire Escape Entire Building 5 LF 4 0-1 year Fire escape in the faŧade Foundation Entire Building 5 LF 7 10+ years Several Surface rods at stair treads an uneven ground Foundation Entire Building 71844 SF 7 10+ years Superstructure - Neavy Timber Entire Building 14 EA 6 6-10 years Lighting Chirney - Brick Chimney-Stainless Steel Low 2799 SF 7 10+ years Chirney - Meigh Flue Low 20 LF 6 10+ years Th		Exterior Doors - Exterior Steel Door		3	EA	6			
Exterior Stairs - Concrete Northwest Fire Escape 15 LF 5 1-2 years Fire Escape Entire Building 117 LF 6 10+ years Fire Escape Entire Building 90 LF 6 10+ years Fire Escape Entire Building 90 LF 5 0-1 year Fire Escape Entire Building 15 LF 4 0-1 year Fire Escape Entire Building 5 LF 7 10+ years Foundation - Masonry Entire Building 71.844 SF 7 10+ years Superstructure - Heavy Timber Entire Building 71.844 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 71.844 SF 7 10+ years Lighting Chimney - Brick Chimney- Stainless Steel Low 55 LF 6 10+ years Chimney - Brick Chimney- Stainless Steel Low 219 LF 6 10+ years Chimney - Motal Flue Low 219 LF 6 10+ years Chimney - Motal Flue Low 219 LF 6 10+ years Parapet - 16'-30' Height Low 219 LF		Exterior Doors - Transom Lite			EA	4		deflected with brick above detaching	
Fire Escape Fire Escape Fire EscapeEntire Building117 Entire BuildingLF610+ years 6Several Surface rods at stair treads and landings are bent and create an uneven groundFire EscapeEntire Building15LF50-1 yearSeveral Surface rods at stair treads and landings are bent and create an uneven groundFoundationEntire Building5LF40-1 yearSeveral Surface rods at stair treads and landings are bent and create an uneven groundFoundationMasonry Superstructure - Heavy Timber Superstructure - Steel with Clay Tile ArchEntire Building71,844SF710+ yearsEterior LightingWall MountedEntire Building14EA66-10 yearsLightingEntire Building14EA66-10 yearsChimney - Brick Chimney- Stainless Steel LightLow20LF610+ yearsChimney - Brick Chimney- Stainless Steel LowLow20LF610+ yearsParapet - 16* - 30' Height Access Ladder - MetalLow2,799SF710+ yearsRoof - Modified BitumenLow2,799SF710+ yearsRoof - Modified BitumenLow2,799SF710+ yearsRoof - Modified BitumenLow2,799SF710+ yearsRoof - Modified BitumenLow2,799SF710+ yearsAccess Ladder - MetalMain1EA40-1 yearsAcces		Exterior Stairs - Concrete	Northwest Fire Escape	15	LF	5	1-2 years		
Fire EscapeEntire Building90LF610+ years several Surface rods at stair treads and landings are bent and orcate an unewon ground Fire EscapeFire EscapeEntire Building5LF40-1 yearSeveral Surface rods at stair treads and landings are bent and orcate an unewon ground Fire escape is not properly anchored to masonryFoundationEntire Building629LF710+ yearsFoundation - MasonryEntire Building71.844SF710+ yearsSuperstructure - Heavy TimberEntire Building71.844SF710+ yearsSuperstructure - Steel with Clay Tile ArchEntire Building14EA66-10 yearsLiphtingChimney - Brick Chimney- Stainless SteelLow20LF610+ yearsChimney - Metal FlueLow20LF610+ yearsChimney - Metal FlueLow21LF610+ yearsDownspouts - Exterior DownspoutsLow219LF610+ yearsParapet - 16" - 30" HeightLow2.799SF710+ yearsRoof Structure - Steel with Clay Tile ArchLow2.799SF710+ yearsAccess Ladder - MetalMain1EA40-1 yearMain1EA40-1 yearThe ladder its made of small rod members and small bars. It does not have sufficient support, and bounces have sufficient support, and bounces have sufficient support, and bounces	Fire Esc	ape							
Fire EscapeEntire Building90LF610+ years several Surface rods at stair treads and landings are bent and orcate an uneven ground Fire EscapeFire EscapeEntire Building5LF40-1 yearSeveral Surface rods at stair treads and landings are bent and orcate an uneven ground Fire escape is not properly anchored to masonryFoundationEntire Building629LF710+ yearsFoundation - MasonryEntire Building71,844SF710+ yearsSuperstructure - Heavy TimberEntire Building71,844SF710+ yearsSuperstructure - Steel with Clay Tile ArchEntire Building14EA66-10 yearsLightingChimney - Brick Chimney- Stainless SteelLow20LF610+ yearsChimney - Metal FlueLow20LF610+ yearsChimney - Metal FlueLow219LF610+ yearsDownspouts - Exterior DownspoutsLow219LF610+ yearsParapet - 16", -30" HeightLow2,799SF710+ yearsRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA40-1 yearThere were no reports of leakage at this not.1EA40-1 yearThere were no ach side, 1 is a 25SF710+ yearsChimney - Steel with Clay Tile ArchLow2,799SF7<			Entire Building	117	LF	6	10+ vears		
Fire EscapeEntire Building15LF50-1 yearSeveral Surface rods at stair treads an uneven ground reate an uneven ground Fire escape is not properly anchored to maxonryFoundation5LF40-1 yearSeveral Surface rods at stair treads an uneven ground Fire escape is not properly anchored to maxonryFoundationEntire Building5LF40-1 yearSeveral Surface rods at stair treads an uneven ground Fire escape is not properly anchored to maxonryFoundationEntire Building5LF710-1 yearsFoundationEntire Building71.84SF710-1 yearsLightingEntire Building71.84SF710-1 yearsLightingEntire Building14EA66-10 yearsLightingEntire Building14EA610-1 yearsRoof SystemLow20LF610+ yearsChimney - Metal FlueLow21LF610+ yearsDownspouts - Exterior DownspoutsLow219LF610+ yearsParapet - 16* - 30* HeightLow27.99SF710- yearsRoof - Modified BitumenLow27.99SF710- yearsAccess Ladder - MetalMain1EA40-1 yearAccess Ladder - WetalMain1EA40-1 yearAccess Ladder - WoodMain1EA40-1 year		•							
Fire Escape Entire Building 5 LF 4 0-1 year and landings are bent and create an uneven ground. Foundation Fo		1						Several Surface rods at stair treads	
Foundation Foundation - Masonry Entire Building 629 LF 7 10+ years Superstructure - Heavy Timber Entire Building 71,844 SF 7 10+ years Superstructure - Steel with Clay Tile Arch Entire Building 71,844 SF 7 10+ years Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney-Stainless Steel Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Downspouts - Exterior Downspouts Low 219 LF 6 10+ years Parapet - 16* - 30' Height Low 2,799 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The la			-	-		-		and landings are bent and create an uneven ground Fire escape is not properly anchored	
Superstructure - Heavy Timber Superstructure - Steel with Clay Tile Arch Entire Building 71,844 2,799 SF 7 10+ years Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney- Stainless Steel Liner Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Coping - Clay Tile Low 20 LF 6 10+ years Downspouts - Exterior Downspouts Parapet - 16' - 30' Height Low 219 LF 6 10+ years Roof Structure - Steel with Clay Tile Arch Low 219 LF 6 10+ years Roof - Modified Bitumen Low 2,799 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient suport, and bounces	Foundat	ion						to masonry	
Superstructure - Heavy Timber Superstructure - Steel with Clay Tile Arch Entire Building 71,844 2,799 SF 7 10+ years Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney- Stainless Steel Liner Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Coping - Clay Tile Low 20 LF 6 10+ years Downspouts - Exterior Downspouts Parapet - 16' - 30' Height Low 219 LF 6 10+ years Roof Structure - Steel with Clay Tile Arch Low 219 LF 6 10+ years Roof - Modified Bitumen Low 2,799 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient suport, and bounces		Foundation - Masonry	Entire Building	629	LF	7	10+ years		
Superstructure - Steel with Clay Tile Arch Entire Building 2,799 SF 7 10+ years Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney- Stainless Steel Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Coping - Clay Tile Low 219 LF 6 10+ years Downspouts - Exterior Downspouts Low 219 LF 6 10+ years Roof - Modified Bitumen Low 2,799 SF 7 10+ years Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 5 2-5 years - Access Ladder - Wood Main 1 EA 4 0-1 year - - Access Ladder - Wood Main 1 EA 4 0-1 year - - -				71.844			•		
Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney - Stainless Steel Liner Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Coping - Clay Tile Low 219 LF 6 10+ years Downspouts - Exterior Downspouts Low 219 LF 6 10+ years Parapet - 16" - 30" Height Low 2,799 SF 6 6-10 years Roof Structure - Steel with Clay Tile Arch Access Ladder - Metal Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 5 2-5 years The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year Old handmade ladder									
Exterior Lighting - Wall Mounted Entire Building 14 EA 6 6-10 years Roof System Chimney - Brick Chimney - Stainless Steel Liner Low 55 LF 6 10+ years Chimney - Metal Flue Low 20 LF 6 10+ years Coping - Clay Tile Low 219 LF 6 10+ years Downspouts - Exterior Downspouts Low 219 LF 6 10+ years Parapet - 16" - 30" Height Low 2,799 SF 6 6-10 years Roof Structure - Steel with Clay Tile Arch Access Ladder - Metal Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 5 2-5 years The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year Old handmade ladder	Liahtina								
Chimney - Brick Chimney- Stainless SteelLow55LF610+ yearsLinerChimney - Metal FlueLow20LF610+ yearsCoping - Clay TileLow219LF610+ yearsDownspouts - Exterior DownspoutsLow219LF610+ yearsParapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder	5 5	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	6-10 years		
Chimney - Brick Chimney- Stainless SteelLow55LF610+ yearsLinerChimney - Metal FlueLow20LF610+ yearsCoping - Clay TileLow219LF610+ yearsDownspouts - Exterior DownspoutsLow219LF610+ yearsParapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder	Roof Sy	stem							
Chimney - Metal FlueLow20LF610+ yearsCoping - Clay TileLow219LF610+ yearsDownspouts - Exterior DownspoutsLow100LF610+ yearsParapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsAccess Ladder - MetalMain1EA40-1 yearThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder		Chimney - Brick Chimney- Stainless Steel	Low	55	LF	6	10+ years		
Coping - Clay TileLow219LF610+ yearsDownspouts - Exterior DownspoutsLow100LF610+ yearsParapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsThere were no reports of leakage at this roof. See engineer reportRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsAccess Ladder - MetalMain1EA40-1 yearThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearAccess Ladder - WoodMain1EA40-1 year			Low	20	LF	6	10+ vears		
DownspoutsExterior DownspoutsLow100LF610+ yearsParapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsThere were no reports of leakage at this roof. See engineer reportRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsAccess Ladder - MetalMain1EA40-1 yearThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder				-					
Parapet - 16" - 30" HeightLow219LF610+ yearsRoof - Modified BitumenLow2,799SF66-10 yearsThere were no reports of leakage at this roof. See engineer reportRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsAccess Ladder - MetalMain1EA40-1 yearThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder									
Roof - Modified BitumenLow2,799SF66-10 yearsThere were no reports of leakage at this roof. See engineer reportRoof Structure - Steel with Clay Tile ArchLow2,799SF710+ yearsAccess Ladder - MetalMain1EA52-5 yearsAccess Ladder - MetalMain1EA40-1 yearThe ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small bars. It does not have sufficient support, and bouncesAccess Ladder - WoodMain1EA40-1 yearOld handmade ladder									
Roof Structure - Steel with Clay Tile Arch Low 2,799 SF 7 10+ years Access Ladder - Metal Main 1 EA 5 2-5 years Access Ladder - Metal Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year Old handmade ladder				_				There were no reports of lookens of	
Access Ladder - Metal Main 1 EA 5 2-5 years Access Ladder - Metal Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder it's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year Old handmade ladder					-	-			
Access Ladder - Metal Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year The ladder is attached only with one small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bounces		Roof Structure - Steel with Clay Tile Arch		2,799					
small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not have sufficient support, and bounces Access Ladder - Wood Main 1 EA 4 0-1 year Old handmade ladder		Access Ladder - Metal	Main	1		5	2-5 years		
		Access Ladder - Metal	Main	1	EA	4	0-1 year	small screw on each side. It is a 25 foot long ladder at an angle. The ladder It's made of small rod members and small bars. It does not	
		Access Ladder - Wood	Main	1	EA	4	0-1 year		
		Coping - Stone	Main	140		7	10+ years		



Catego	ry : Exterior		В	uilding	: Main	1050 W Comelia AVENCE, Chicago, 12 00057		
ealege			_	anang		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Downspouts - Exterior Downspouts	Main	1,225	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main	10	LF	4	0-1 year	Gutter flashing has been covered wit Roof cement for repairs . Roof still leaks. There is a bucket in the interio that has to be emptied during the rair	
	Parapet - 16" - 30" Height	Main	140	LF	7	10+ years		
	Roof - Asphalt Shingle	Main	10,606	SF	6	6-10 years		
	Roof - Modified Bitumen	Main	7,370	SF	5	2-5 years	Many patches, with roof cement cracking	
	Roof Hatch - Metal	Main	2	EA	3	1-2 years	Old, clumsy, heavy, roof hatches	
	Roof Structure - Heavy Timber	Main	17,387	SF	7	10+ years		
Walls								
	Cornice - Masonry Projecting Limestone	Entire Building	78	LF	6	10+ years		
	Exterior Walls - Brick	Entire Building	24,342	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	1,500	SF	4	1-2 years	Open joints and deteriorated mortar, spalled brick	
	Exterior Walls - Brick	Entire Building	100	SF	3	0-1 year	Open joints, deflected lintel above fir escape door, cracks in the brick	
	Exterior Walls - Stone-Cut	Entire Building	7,109	SF	6	10+ years		
	Exterior Walls - Stone-Cut	Entire Building	200	SF	5	10+ years		
Windows	3							
	Guard - Guards perforated	Entire Building	2,021	SF	6	10+ years		
	Lintels - Brick	Entire Building	11	LF	7	10+ years		
	Lintels - Steel	Entire Building	571	LF	7	10+ years		
	Lintels - Steel	Entire Building	5	LF	4	0-1 year	Bowed, deflected lintel. Cracked single pane glass transom	
	Lintels - Stone	Entire Building	343	LF	6	10+ years		
	Windows - Decorative	Entire Building	80	SF	6	6-10 years		
	Windows - Sash Aluminum Double-pane	Entire Building	7,816	SF	6	10+ years		
Catego	ry : Electrical		В	uilding	: Main	Desember		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Emerger	ncy System							
C	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years		
	Security System - Intrusion Detection	Entire Building	71,844	SF	6	6-10 years		
	, , ,	Entire Building	5	ĒA	7	6-10 years	Replace new in 2020	
	Exit Signs - Corridors and Stairs							
	Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs							
	Exit Signs - Corridors and Stairs	Entire Building	26 7	EA	6	6-10 years		
			26				East lunch room	



	ry : Electrical		D	uilding	·Main		50 W Cornelia AVENUE, Chicago, IL 60657
Calego	y. Electrical		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Exit Signs - Lunchroom	Entire Building	Quantity 1	EA	6	6-10 years	South lunch room
	Emergency Battery Packs - Corridors and	Entire Building	35	EA	7	10+ years	South lanch room Served from EM panel
	Stairs	C				5	
	Emergency Battery Packs - Gym	Entire Building	6	EA	7	10+ years	Served from EM panel
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	7	10+ years	West lunch room From EM panel
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	7	10+ years	Served from EM panel South lunch room
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	7	10+ years	East lunch room From EM panel
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	Served from EM panel
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,710	SF	6	6-10 years	From EM panel
	Emergency A/C Power - Gym	Entire Building	5,771	SF	6	6-10 years	Served from EM panel
	Emergency A/C Power - Lunchrooms	Entire Building	1,934	SF	7	10+ years	West lunch room (boys play room) From EM panel
	Emergency A/C Power - Lunchrooms	Entire Building	1,934	SF	7	10+ years	East lunch room (girls play room) From EM panel
	Emergency A/C Power - Lunchrooms	Entire Building	1,110	SF	7	6-10 years	South lunch room Per building engineer- all working right now and don't need to replace From EM pane
	Emergency A/C Power - Students Toilets	Entire Building	1,255	SF	6	6-10 years	From EM panel
Main Sei	vice						
	Main Electrical Service - 1200 A 120/240/3PH	Basement	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	71,844	SF	4	0-1 year	System is original - only works in the corridor per building engineer
Power D							
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	MDF room 208 closet - new installed in 2018
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	1-2 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	2-5 years	Fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	1-2 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	2-5 years	
Catego	y : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar						-	



Catego	ry : Fire Protection		В	uilding	: Main		
Ŭ				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Basement	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Basement	74,643	SF	6	6-10 years	
	Fire Alarm_System	Basement	74,643	SF	6	6-10 years	
			1 1	EA	4		Still working par building anging
	Fire Pump Controller	Basement	I	EA	4	1-2 years	Still working - per building enginee
ump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Basement	1	EA	4	2-5 years	
Sprinkler	System						
-	Dry Sprinkler System	Entire Building	74,643	SF	5	6-10 years	
	Sprinkler Heads	Entire Building	74,643	SF	3	0-1 year	
	Sprinkler Piping	Entire Building	74,643	SF	4	0-1 year	
		Entite Building	74,043	36	4	0-1 year	
atego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Basement	1	EA	5	6-10 years	
	Air Intake	Basement	2	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Basement	1	EA	5	2-5 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	6	6-10 years	
	Zone Dampers	Basement	38	EA	6	6-10 years	Room 106 actuator has been disconnected Room 206 actuator connect with 106 and control both rooms
Boiler Sy		_					
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Basement	2	EA	5	6-10 years	1974
	Chemical Feed System	Basement	1	EA	6	6-10 years	
	Combustion Dampers	Basement	2	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	3	0-1 year	Duplex- vacuum and condensate pump all in one Tank is rusted and leaks
	Feed Water Pumps and Tank	Basement	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Basement	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Basement	200	LF	5	6-10 years	
					5		
	Piping - Steam Pipe- Steel	Basement	200	LF	5	6-10 years	
	Steam Traps	Basement	12	EA	5	6-10 years	



Alexander Hamilton Elementary School 1650 W Cornelia AVENUE, Chicago, IL 60657

Jatego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	Devices	Loodion	Quantity	00111	i taint	Replacement	ooninonto
leaning	Wall Heater - Electric	Basement	3	EA	5	6-10 years	Per building engineer- 3 unit heaters
	Fin Tube - Steam	Basement	100	LF	6	6-10 years	
	Unit Heater - Gas	Boiler Room	2	EA	5	2-5 years	
					-	,	
Tempera	ature Control						
	Pneumatic System	Entire Building	74,643	SF	7	6-10 years	Per building engineer- working right now with no issues
	Thermostats - Pneumatic	Entire Building	37	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	1	EA	5	0-1 year	Room 106 thermostat not working - line needs to be fixed 206 thermosta also control 106 room
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
_				_			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Hot Wat		Location	Quantity		Rank		
-		Location Basement	Quantity 1	UOM EA	Rank 7		Comments No more leaks- per building engineer and it's fixed Cap the connection and reconnect from top with copper pipes
-	er Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA		Replacement 6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
Hot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines	Basement Entire Building	74,643	EA	7	6-10 years 6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
Hot Wat	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Basement Entire Building Entire Building	1 74,643 74,643	EA SF SF	7 6 6	6-10 years 6-10 years 6-10 years 6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
lot Wat	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Basement Entire Building	74,643	EA SF SF SF	7	6-10 years 6-10 years	No more leaks- per building enginee and it's fixed Cap the connection and
Hot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Basement Entire Building Entire Building Entire Building Entire Building	1 74,643 74,643	EA SF SF SF SF	7 6 6	Replacement6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
Hot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Basement Entire Building Entire Building Entire Building Entire Building Entire Building	1 74,643 74,643 74,643 74,643 74,643	EA SF SF SF SF SF	7 6 6 6	Replacement6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
Hot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Basement Entire Building Entire Building Entire Building Entire Building	1 74,643 74,643 74,643 74,643 74,643	EA SF SF SF SF SF SF	7 6 6 6 6	Replacement6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
lot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Basement Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 74,643 74,643 74,643 74,643 74,643 74,643 74,643 74,643	EA SF SF SF SF SF SF SF	7 6 6 6 6 6	Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and
Hot Wat	er Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Basement Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 74,643 74,643 74,643 74,643 74,643 74,643	EA SF SF SF SF SF SF	7 6 6 6 6 6 6	Replacement6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years	No more leaks- per building engineer and it's fixed Cap the connection and



atego	ry : Room		В	uilding	: Main		50 W Cornelia AVENUE, Chicago, IL 606
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices					-	
	AC Unit	105 - 1st flr. principal	1	EA	5	6-10 years	
	Ceiling - Exposed	105 - 1st flr. principal	614	SF	6	10+ years	Changed to match current
		· · · · · · · · · · · · · · · · · · ·		•.	-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	observations
	Doors - Transom Window	105 - 1st flr. principal	8	SF	6	6-10 years	Quantity changed to match curren observations
	Doors - Wood Doors inclu hw	105 - 1st flr. principal	2	EA	6	6-10 years	
	Floor - Wood	105 - 1st flr. principal	614	SF	6	10+ years	
	Lighting - Pendent/Surface	105 - 1st flr. principal	3	EA	6	6-10 years	
	Power Distribution	105 - 1st flr. principal	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	105 - 1st flr. principal	1,178	SF	6	10+ years	
	AC Unit	105 Main office	1	EA	7	6-10 years	
	Ceiling - Lay-in	105 Main office	510	SF	7	10+ years	
	Doors - Transom Window	105 Main office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Main office	1	ĒA	6	10+ years	
	Floor - Wood	105 Main office	510	SF	6	10+ years	
	Lighting - Pendent/Surface	105 Main office	6	ĒA	7	6-10 years	
	Power Distribution	105 Main office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	105 Main office	950	SF	7	10+ years	
	AC Unit	Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	392	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	392	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	3	EA	6	6-10 years	
	Power Distribution	Engineer's Office	8	EA	6	10+ years	
	Storage/ Closet	Engineer's Office	36	SF	5	10+ years	Quantity changed to match currer
	Walls - Concrete Block	Engineer's Office	224	SF	e	10, 10000	observations
	Walls - Concrete Block Walls - Plaster/Drywall	Engineer's Office Engineer's Office	224	SF	6 6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office		SF	6 6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	60	EA			
	Floor - Tile		1	SF	6 6	10+ years	
	Lighting - Pendent/Surface	Kitchen Office Kitchen Office	60 1	EA	6 6	10+ years 6-10 years	
	Power Distribution	Kitchen Office	2	EA SF	6	6-10 years	
	Walls - Plaster/Drywall	Kitchen Office	260	SF	6	10+ years	
mnasi							
	Ceiling - Plaster/Drywall	3rd Flr. Gym	5,721	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Flr. Gym	50	SF	5	1-2 years	Paint peeling
	Doors - Side-lite	3rd Flr. Gym	50	SF	7	10+ years	
	Doors - Transom Window	3rd Flr. Gym	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Flr. Gym	4	EA	6	10+ years	
	Floor - Sport Flooring	3rd Flr. Gym	5,771	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Flr. Gym	24	EA	7	10+ years	



nts
nts
to match current
ions
not work. Paint cracked and
not work. Paint cracked and
eded
, ded
racked
to motob ourront
to match current
amaged
5



Catego	ry : Room		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Boy's Playroom	1,934	SF	6	10+ years	
	Floor - Epoxy/ Painted	Boy's Playroom	1,934	SF	7	10+ years	
	Lighting - Pendent/Surface	Boy's Playroom	18	EA	6	6-10 years	
	Walls - Masonry	Boy's Playroom	655	SF	6	10+ years	
	Walls - Plaster/Drywall	Boy's Playroom	184	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Boy's Playroom	920	SF	6	10+ years	
	Ceiling - Exposed	Boy's Playroom #2	880	SF	6	10+ years	Changed to match current
	-			•	-	-	observations
	Floor - Epoxy/ Painted	Boy's Playroom #2	880	SF	7	10+ years	
	Lighting - Pendent/Surface	Boy's Playroom #2	18	EA	6	6-10 years	
	Walls - Masonry	Boy's Playroom #2	571	SF	6	10+ years	
	Walls - Plaster/Drywall	Boy's Playroom #2	571	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Girl's Playroom	1,934	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girl's Playroom	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	Girl's Playroom	1,934	SF	7	10+ years	
	Lighting - Pendent/Surface	Girl's Playroom	18	EA	6	6-10 years	
	Walls - Concrete Block	Girl's Playroom	184	SF	6	10+ years	Changed to match current observations
	Walls - Masonry	Girl's Playroom	655	SF	6	10+ years	
	Walls - Masonry	Girl's Playroom	20	SF	6	1-2 years	Masonry is cracked
	Walls - Metal Panel	Girl's Playroom	920	SF	6	10+ years	,
	Ceiling - Plaster/Drywall	Staff lunchroom basement	220	SF	7	10+ years	
	Floor - Tile	Staff lunchroom basement	220	SF	7	10+ years	
	Lighting - Pendent/Surface	Staff lunchroom basement	4	EA	6	10+ years	
	Power Distribution	Staff lunchroom basement	2	EA	7	10+ years	
	Student Lockers - One Tier	Staff lunchroom basement	7	EA	7	6-10 years	Staff lockers
	Walls - Concrete Block	Staff lunchroom basement	440	SF	7	10+ years	
	F						
	Doors - Steel Doors incl hw	2nd Flr. MDF/IDF	1	EA	6	10+ years	
	Finishes	2nd Flr. MDF/IDF	125	SF	5	10+ years	Paint cracked. Broken ceiling tile
	Window AC Unit	2nd Flr. MDF/IDF	1	EA	7	6-10 years	C C
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	16	SF	5	10+ years	
	Janitor's Closet	1st Floor	16	SF	5	10+ years	
	Janitor's Closet	2nd Floor	16	SF	7	10+ years	
	Janitor's Closet	2nd Floor	16	SF	7	10+ years	
	Janitor's Closet	3rd Floor	12	SF	7	10+ years	
	Janitor's Closet	3rd Floor	12	SF	5	10+ years	Paint peeling on walls
	Storage Room	3rd Floor	182	SF	5	1-2 years	
				SF	5		
	Storage Room	3rd Floor	182	55	<u> </u>	1-2 vears	
	Storage Room Air Intake Plenums	3rd Floor Basement	182 250	SF	5 5	1-2 years 10+ years	



Catego	ry : Room		B	uilding	: Main				
	.,					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Boiler Room	Basement	1,440	SF	5	10+ years			
	Coal Room	Basement	840	SF	5	10+ years			
	Janitor's Closet	Basement	198	SF	5	1-2 years	Changed to match current		
							observations. Paint cracked and peeling		
	Mechanical/ Service Rooms	Basement	910	SF	5	1-2 years	peemig		
	Mechanical/ Service Rooms	Basement	80	SF	5	1-2 years	Electrical room. Masonry spalling		
	Storage Room	Basement	189	SF	7	10+ years	Electrical room. Masonry spannig		
	Storage Room	Basement	196	SF	5	1-2 years	Changed to match current		
	Storage Room	Dasement	130	01	5		observations. Paint is cracking and peeling.		
Restroo									
	Accessories	101 Inside	66	SF	7	6-10 years	Newly remodeled		
	Ceiling - Exposed	101 Inside	66	SF	6	10+ years	Changed to match current observations		
	Doors - Wood Doors inclu hw	101 Inside	1	EA	7	10+ years	Newly remodeled		
	Floor - Tile Ceramic/ Porcelain	101 Inside	66	SF	7	10+ years	Newly remodeled		
	Floor Drain	101 Inside	1	EA	7	10+ years			
	Lavatory	101 Inside	1	EA	7	10+ years	Newly remodeled		
	Lighting - Pendent/Surface	101 Inside	1	EA	7	10+ years	Newly replaced		
	Walls - Plaster/Drywall	101 Inside	200	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	101 Inside	220	SF	7	10+ years			
	Water Closet	101 Inside	1	EA	6	10+ years			
	Accessories	105 Toilet	76	SF	7	6-10 years	Quantity changed to match current observations		
	Ceiling - Plaster/Drywall	105 Toilet	76	SF	6	10+ years	Quantity changed to match current observations		
	Doors - Wood Doors inclu hw	105 Toilet	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	105 Toilet	76	SF	6	10+ years			
	Lavatory	105 Toilet	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	105 Toilet	1	EA	7	6-10 years	Exposed wall switch wiring		
	Walls - Plaster/Drywall	105 Toilet	450	SF	6	10+ years	Quantity changed to match current observations		
	Water Closet	105 Toilet	1	EA	6	10+ years			
	Accessories	1st flr. unisex	38	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	1st flr. unisex	38	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st flr. unisex	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st flr. unisex	38	SF	6	10+ years			
	Lavatory	1st flr. unisex	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	1st flr. unisex	1	EA	6	6-10 years			
	Partitions	1st flr. unisex	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st flr. unisex	220	SF	6	10+ years			
	Water Closet	1st flr. unisex	220	EA	6				
	Waler Ciusel	ISUM. UMSEX	1	EA	0	10+ years			



Category : Room **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Accessories 2nd Floor Staff 28 SF 6-10 vears 7 Ceiling - Plaster/Drywall 28 SF 2nd Floor Staff 6 10+ vears Doors - Wood Doors inclu hw 2nd Floor Staff 1 FΑ 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 2nd Floor Staff 28 10+ years 7 Floor Drain 2nd Floor Staff 1 EΑ 6-10 years Hand Dryer 7 2nd Floor Staff 1 EΑ 6-10 years 2nd Floor Staff ΕA 6-10 years Lavatory 1 6 Lighting - Pendent/Surface 2nd Floor Staff 1 ΕA 7 6-10 years Walls - Plaster/Drywall 2nd Floor Staff 230 SF 6 10+ years Water Closet 2nd Floor Staff EΑ 6 6-10 years 1 Accessories 2nd Flr. Girls 251 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Flr. Girls 251 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Flr. Girls 251 SF 6 10+ years 7 ΕA Floor Drain 2nd Flr. Girls 1 10+ years Hand Dryer 2 ΕA 7 2nd Flr. Girls 6-10 years FΑ Lavatory 2nd Flr. Girls 1 6 6-10 years Lighting - Pendent/Surface 6 2nd Flr. Girls ΕA 6 6-10 years Partitions 2nd Flr. Girls 5 ΕA 7 6-10 years Walls - Plaster/Drvwall SF 2nd Flr. Girls 730 6 10+ vears Water Closet 2nd Flr. Girls 5 EΑ 6 6-10 years Accessories 2nd flr. Boys 251 SF 7 6-10 years Ceiling - Plaster/Drywall SF 2nd flr. Boys 251 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd flr. Boys SF 6 251 10+ years 7 Floor Drain 2nd flr. Boys FΑ 10+ years 1 Hand Dryer 2 ΕA 7 6-10 years 2nd flr. Boys Lavatorv 2nd flr. Bovs 1 FΑ 6 6-10 years Lighting - Pendent/Surface 6 7 2nd flr. Boys ΕA 6-10 years Partitions 2nd flr. Boys 2 ΕA 7 6-10 years 5 Urinals 2nd flr. Boys ΕA 6 6-10 years Walls - Plaster/Drywall 2nd flr. Boys 522 SF 6 10+ years SF Walls - Vinyl Coated Gypsum Panel 2nd flr. Boys 208 6 10+ vears Water Closet 2nd flr. Bovs 2 ΕA 6 6-10 vears SF Accessories Basement By engineer's office 76 7 Changed to match current 6-10 years observations Ceiling - Plaster/Drywall Basement By engineer's office 76 SF 7 10+ years Changed to match current observations Doors - Wood Doors inclu hw Basement By engineer's office 1 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain Basement By engineer's office SF 76 7 10+ years Changed to match current observations 2 ΕA Basement By engineer's office 6 6-10 vears Lavatorv Lighting - Pendent/Surface Basement By engineer's office 1 ΕA 6 6-10 years Basement By engineer's office FΑ 7 Partitions 1 10+ years Urinals Basement By engineer's office 1 EΑ 6 10+ years Basement By engineer's office SF 7 Walls - Concrete Block 281 10+ years Changed to match current



XII A						168	50 W Cornelia AVENUE, Chicago, IL 60657
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
						-	observations
	Water Closet	Basement By engineer's office	1	EA	6	10+ years	
	Accessories	Basement Toilet inside staff	76	SF	7	6-10 years	
		lunchroom		•		- · · · · · · · ·	
	Ceiling - Plaster/Drywall	Basement Toilet inside staff	76	SF	6	10+ years	
		lunchroom		•	•	, , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	Basement Toilet inside staff	1	EA	6	10+ years	
		lunchroom		_/ \	· ·	,jeure	
	Floor - Tile Ceramic/ Porcelain	Basement Toilet inside staff	75	SF	6	10+ years	
		lunchroom	10	0.	Ũ	io: youro	
	Floor - Tile Ceramic/ Porcelain	Basement Toilet inside staff	1	SF	4	1-2 years	Missing
		lunchroom	·	01	•	1 2 youro	Wieding
	Floor Drain	Basement Toilet inside staff	1	EA	7	10+ years	
		lunchroom	I		'	Tor years	
	Hand Dryer	Basement Toilet inside staff	1	EA	7	6-10 years	
		lunchroom			'	0-10 years	
	Lavatory	Basement Toilet inside staff	2	EA	6	10+ years	
	Lavalory	lunchroom	Z	LA	0	TUT years	
	Lighting Dondont/Surface	Basement Toilet inside staff	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	lunchroom	I	EA	0	6-10 years	
	Partitions	Basement Toilet inside staff	2	EA	7	6-10 years	
	Faninons	lunchroom	Z	EA	1	0-10 years	
	Urinals		1	EA	7	10, 10000	
	Unhais	Basement Toilet inside staff lunchroom	1	EA	7	10+ years	
	Walls - Concrete Block		204	SF	6	10, , , , , , , , , , , , , , , , , , ,	
	Walls - Concrete Block	Basement Toilet inside staff lunchroom	281	SF	6	10+ years	
	Water Closet	Basement Toilet inside staff	2	EA	6	10+ years	
	Water Closet	lunchroom	Z	EA	0	10+ years	
	Accessories	Boiler Room	20	oг	F	6 10 10000	
	Accessories		38	SF SF	5	6-10 years	Changed to match surrout
	Ceiling - Exposed	Boiler Room	60	5F	5	1-2 years	Changed to match current observations. Paint is cracked and
	Deere Weed Deere included	Deiler Deere	4		<u>^</u>	10	peeling
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boiler Room	60	SF	6	10+ years	Changed to match current
	Leveter	Deiles De est	4	Γ.	0	10	observations
	Lavatory	Boiler Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	6-10 years	
	Showers	Boiler Room	1	EA	5	6-10 years	Missing showerhead
	Walls - Masonry	Boiler Room	337	SF	6	0-1 year	Changed to match current
							observations. No mortar cracks, paint
							is cracked and peeling and there is
			. –	6 -	_		no option for that.
	Walls - Masonry	Boiler Room	15	SF	5	1-2 years	Masonry is spalling
	Walls - Plaster/Drywall	Boiler Room	48	SF	4	1-2 years	Paint is peeling. Large holes at base



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Vinyl Coated Gypsum Panel	Boiler Room	96	SF	7	10+ years	
	Water Closet	Boiler Room	1	EA	6	10+ years	
	Accessories	Bsmt. Boys	396	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Boys	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Boys	396	SF	6	10+ years	
	Floor Drain	Bsmt. Boys	2	EA	7	10+ years	
	Hand Dryer	Bsmt. Boys	2	EA	7	6-10 years	
	Lavatory	Bsmt. Boys	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Boys	6	EA	6	6-10 years	
	Partitions	Bsmt. Boys	3	EA	7	6-10 years	
	Urinals	Bsmt. Boys	10	EA	6	6-10 years	
	Walls - Concrete Block	Bsmt. Boys	628	SF	6	10+ years	
	Water Closet	Bsmt. Boys	3	EA	6	10+ years	
	Accessories	Bsmt. Girls	396	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Girls	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Girls	396	SF	6	10+ years	
	Floor Drain	Bsmt. Girls	2	EA	7	10+ years	
	Hand Dryer	Bsmt. Girls	2	EA	5	6-10 years	
	Lavatory	Bsmt. Girls	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Girls	6	EA	6	6-10 years	
	Partitions	Bsmt. Girls	12	EA	7	6-10 years	
	Walls - Concrete Block	Bsmt. Girls	628	SF	6	10+ years	
	Water Closet	Bsmt. Girls	12	EA	6	10+ years	

Category : Classroom

Category : Classroom			В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroc	m #008 (Dance Room)						
	Casework	Basement	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,127	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	1,127	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	35	EA	6	6-10 years	
	Marker Board	Basement	12	LF	6	6-10 years	
	Storage/ Closet	Basement	75	SF	5	10+ years	
	Wall Mirrors	Basement	15	SF	7	10+ years	
	Walls - Masonry	Basement	1,040	SF	6	10+ years	Changed to match current observations
	Weight/ Fitness Room Floor Matting	Basement	900	SF	6	10+ years	
Classroo	m #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	871	SF	6	10+ years	Changed to match current



Catego	ory : Classroom		B	Building : Main			
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•						•	observations
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Storage/ Closet	1st Floor	125	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	õ	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
				SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	01	-	,	
lassroo	Walls - Plaster/Drywall	1st Floor	1,272	01	_		
Classroo		1st Floor	1,272	EA	5		
Classroo	om #104 (Health) AC Units				56	6-10 years 10+ years	
Classroo	om #104 (Health) AC Units Ceiling - Lay-in	1st Floor	1	EA SF		6-10 years 10+ years	
Classroo	om #104 (Health) AC Units Ceiling - Lay-in Doors - Transom Window	1st Floor 1st Floor 1st Floor	1 607 10	EA	6 6	6-10 years 10+ years 10+ years	
Classroo	om #104 (Health) AC Units Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 607 10 2	EA SF SF EA	6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years	
Classroo	om #104 (Health) AC Units Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 607 10 2 607	EA SF SF EA SF	6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years	
Classroo	om #104 (Health) AC Units Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 607 10 2	EA SF SF EA	6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years	



Category : Classroom

Catego	ry : Classroom		В	ullaing	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,149	SF	6	6-10 years	
Classroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	860	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,336	SF	6	10+ years	
. .							
lassroo	m #108 (Regular Classroom)	4 - 4 5			-	0.40	
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	õ	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
	Work Sink	1st Floor	1,272	EA	5	6-10 years	
					-	,	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	10+ years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
			074	05	~	40 ⁻	
	Floor - Wood	1st Floor	871	SF	6	10+ years	

Building : Main



Category : Classroom		В	uilding	: Main			
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
						-	
lassroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
lassroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
	-					,	
lassroo	m #203 (Regular Classroom)					0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	75	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
lassroo	m #204 (Science)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,171	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,171	SF	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	62	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,682	SF	6	10+ years	
Classroo	om #205 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	852	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Missing tile
	Chalk Board	2nd Floor	12	LF	4	2-5 years	5
	Doors - Transom Window	2nd Floor	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	50	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,336	SF	6	10+ years	
	Wallo Plastol, Drywall		1,000	01	0	ior youro	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	607	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	607	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,149	SF	6	10+ years	
Classroo	m #207 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	858	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Qty changed because tiles replaced by 8ft unit. Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	by on ann. Water damage
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Wall paint cracked
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracking in wall

Classroom #208 (Computer Lab)



Catego	Category : Classroom		В	uilding	: Main		
- 30						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	789	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	80	SF	5	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	5
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	1-2 years	Paint cracked
Classroc	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	847	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	12	LF	4	2-5 years	i i i i i i i i i i i i i i i i i i i
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,270	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	6	1-2 years	Paint is peeling
Classroc	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	855	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	i i i i i i i i i i i i i i i i i i i
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Wall paint and ceiling tiles damaged
	Walls - Plaster/Drywall	2nd Floor	15	SF	6	1-2 years	Paint peeled
	Walls - Plaster/Drywall	2nd Floor	1,257	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	775	SF	6	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	Damaged ceiling tiles
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	1,252	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	791	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	80	SF	4	0-1 year	Changed to match current
			00	01		o i you	observations
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	0000114110110
	Doors - Wood Doors inclu hw	3rd Floor	9 1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	58		6		
	Storage/ Closet	3rd Floor	175	SF	5	6-10 years	Wall paint and ceiling tiles damaged
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	1-2 years	waii paint and ceiling tiles damaged
	walls - Plastel/Drywall	310 F1001	1,272	55	0	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	871	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Paint cracked and peeling on walls
	Walls - Plaster/Drywall	3rd Floor	25	SF	6	1-2 years	Paint is peeling
	Walls - Plaster/Drywall	3rd Floor	1,247	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	855	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Lighting - rendent/Sunace	510 1 1001	14	LA	'	0-10 years	



	Schools					165	50 W Cornelia AVENUE, Chicago, IL 60657
Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Wall paint and ceiling tiles damaged
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	847	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Wall paint and ceiling tiles damaged
	Walls - Plaster/Drywall	3rd Floor	15	SF	6	1-2 years	Wall cracked
	Walls - Plaster/Drywall	3rd Floor	1,257	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	863	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Wall paint and ceiling tiles damaged
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Ceiling - Lay-in	1st Floor	2,824	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2,024	EA	7	10+ years	Changed to match current

Lighting - Lay-in Walls - Plaster/Drywall 1st Floor 34 1st Floor 5,744 Ceiling - Lay-in 2nd Floor 2,720 Drinking Fountains - Single Fountain 2nd Floor 2 Floor - Asphalt Floor 2nd Floor 2,720 Lighting - Pendent/Surface 2nd Floor 26

1st Floor

Floor - Asphalt Floor

2,735

SF

ΕA

SF

SF

ΕA

SF

ΕA

6

6

6

6

7

6

6

observations

10+ years

6-10 years

10+ years

10+ years

10+ years

10+ years

6-10 years



Category : Interior			В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Student Lockers - Two Tiers	2nd Floor	19	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,576	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,364	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	36	SF	5	1-2 years	Water damage
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	Qty changed to match current observations
	Floor - Asphalt Floor	3rd Floor	1,400	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	ĒA	6	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	75	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,699	SF	6	10+ years	
	Ceiling - Exposed		2,099	SF	6		Changed to motch ourrent
		Basement			-	10+ years	Changed to match current observations
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	Changed to match current observations
	Doors - Wood Doors include hw	Basement	2	EA	6	10+ years	Qty changed to match current observations
	Drinking Fountains - Single Fountain	Basement	9	EA	7	10+ years	Drinking fountains are in boy's and girls play rooms
	Floor - Concrete Epoxy/ Painted	Basement	890	SF	7	10+ years	Changed to match current observations
	Floor - Concrete Epoxy/ Painted	Basement	10	SF	4	1-2 years	Paint peeling
	Lighting - Pendent/Surface	Basement	8	EA	6	6-10 years	Changed to match current observations
	Stairs - Concrete Stairs	Basement	12	LF	6	10+ years	Changed to match current observations
	Walls - Concrete Block	Basement	240	SF	6	10+ years	Changed to match current observations
	Walls - Masonry	Basement	160	SF	6	10+ years	Changed to match current observations
	Walls - Masonry	Basement	100	SF	5	1-2 years	Changed to match current observations. Masonry cracked an spalling
afety							
	Camera Viewing Station Security Cameras	1st Floor 1st Floor	1	EA EA	7 7	6-10 years 6-10 years	Front door
	Security Cameras		1	EA	1	o-ro years	
tairs							
	Ceiling - Lay-in	East stairs	122	SF	5	0-1 year	Water damage
	Ceiling - Plaster/Drywall	East stairs	328	SF	6	10+ years	Changed to match current observations
	Floor - Asphalt	East stairs	675	SF	6	10+ years	Changed to match current observations
	Handrails	East stairs	270	LF	7	10+ years	Changed to match current



Catego	ry : Interior		P	uilding	· Main	100	50 W Comelia AVENDE, Chicago, IL 60657
Calego	ry . Interior		В	unung	. พลาก	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	item - Type	Location	Qualitity		Nalik	Replacement	observations
	Lighting - Chandelier, Incandescent	East stairs	3	EA	6	6-10 years	observations
	Lighting - Pendent/Surface	East stairs	6	EA	6	6-10 years	Changed to match current
			0	LA	0	0-10 years	observations
	Stairs - Asphalt	East stairs	504	LF	6	10+ years	Changed to match current
					Ũ	lot youro	observations
	Walls - Plaster/Drywall	East stairs	300	SF	6	1-2 years	Paint cracking
	Walls - Plaster/Drywall	East stairs	3,300	SF	6	10+ years	Changed to match current
			-,	•.	Ţ.	, ,	observations
	Ceiling - Lay-in	South	328	SF	6	10+ years	Changed to match current
	5					,	observations
	Ceiling - Lay-in	South	8	SF	5	1-2 years	Water damage
	Floor - Asphalt	South	84	SF	6	10+ years	C C
	Handrails	South	72	LF	7	10+ years	
	Lighting - Wall Mounted	South	2	EA	7	6-10 years	
	Stairs - Asphalt	South	216	LF	6	10+ years	Changed to match current
							observations
	Walls - Plaster/Drywall	South	140	SF	6	10+ years	
	Ceiling - Lay-in	West stairs	414	SF	6	10+ years	Changed to match current
							observations
	Ceiling - Lay-in	West stairs	36	SF	5	1-2 years	Water damage
	Floor - Asphalt	West stairs	675	SF	6	10+ years	Changed to match current
					_		observations
	Handrails	West stairs	270	LF	7	10+ years	Changed to match current
					•	0.40	observations
	Lighting - Chandelier, Incandescent	West stairs	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	West stairs	1	EA	6	0-1 year	Bulb is out
	Lighting - Pendent/Surface	West stairs	5	EA	6	6-10 years	Changed to match current
	Ctaire Aanhalt		504	. –	0	10	observations
	Stairs - Asphalt	West stairs	504	LF	6	10+ years	Changed to match current
	Walls Blactor/Drawall	West stairs	2 400	SF	e	10, vooro	observations
	Walls - Plaster/Drywall	West stairs	3,400	ЗГ	6	10+ years	Changed to match current observations
	Walls - Plaster/Drywall	West stairs	200	SF	6	1-2 years	Paint cracked and peeling
	walls - Flastel/Diywall		200	эг	U	I-Z years	Faint Gracked and peeling



Catego	Category : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	7	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	379	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	667	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	250	LF	6	10+ years	
Landsca	pe						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	12,006	SF	4	1-2 years	
	Landscape - Hardscape- Asphalt	Entire Site	1,337	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,000	SF	6	10+ years	Verifiedquantities
	Landscape - Hardscape- Pavers	Entire Site	578	SF	6	10+ years	
	Parkway trees	Entire Site	1	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	5,127	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	5,122	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	400	SF	5	1-2 years	Large cracks and alligatoredsurface
	Play Area - Synthetic Turf	Entire Site	4,080	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	201	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking	Lot						
Ũ	Surface - Asphalt	North	16,665	SF	6	6-10 years	
	Surface - Asphalt	North	800	SF	5	1-2 years	Potholes, alligatored surface, large cracks
	Surface - Concrete	North	1,500	SF	7	10+ years	
	Trash Enclosure - Chain Links	North	898	SF	7	10+ years	
	Trash Enclosure - Chain Links	North	160	SF	4	1-2 years	Broken gate and post, broken sectior of fence
Playgrou	Ind						
	Equipment - School Age 5-12	NE	1	EA	7	10+ years	
	Surface - Poured Surface	NE	1,188	SF	7	10+ years	
	Surface - Poured Surface	North	1,800	SF	7	10+ years	
	Equipment - Pre K 3-5	South east	, í 1	EA	6	10+ years	
	Surface - Poured Surface	South east	1,800	SF	5	2-5 years	
Sidewall	(S						
	Sidewalks - Perimeter Sidewalks	Entire Site	12,006	SF	7	10+ years	
			,000	2.	•		



Category : Site			E	Building : Site				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Signage								
0 0	Flag Pole - Flag Pole	Site SE	1	EA	6	10+ years		
	Marquee - Free Standing Back Lighted	Site SE	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter	Site SE	1	EA	7	10+ years		
	Sign					-		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-				
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board				
Building : Main													
Art Room	Regular Classroom	2nd Floor	205	205	860	118	64	N	N				
Computer Lab	Regular Classroom	2nd Floor	208	208	871	177	80	N	Y				
Dance Room	Regular Classroom	Basement	008	008	1,127	88	35	N	N				
Health	Regular Classroom	1st Floor	104	104	607	80	40	N	N				
Music Room	Regular Classroom	2nd Floor	207	207	860	118	64	N	Y				
Regular Classroom	Multi Purpose Room	2nd Floor	206	206	607	80	40	N	N				
Regular Classroom	Regular Classroom	1st Floor	101	101	871	189	94	N	N				
Regular Classroom	Regular Classroom	1st Floor	102	102	871	118	80	N	Y				
Regular Classroom	Regular Classroom	1st Floor	103	103	871	177	80	N	N				
Regular Classroom	Regular Classroom	1st Floor	107	107	860	118	64	N	N				
Regular Classroom	Regular Classroom	1st Floor	108	108	871	177	80	N	Y				
Regular Classroom	Regular Classroom	1st Floor	109	109	871	118	80	N	N				
Regular Classroom	Regular Classroom	1st Floor	110	110	871	177	80	N	Y				
Regular Classroom	Regular Classroom	2nd Floor	201	201	871	189	94	N	Y				
Regular Classroom	Regular Classroom	2nd Floor	202	202	871	118	80	N	Y				
Regular Classroom	Regular Classroom	2nd Floor	203	203	871	177	80	N	Y				
Regular Classroom	Regular Classroom	2nd Floor	209	209	871	118	80	N	Y				
Regular Classroom	Regular Classroom	2nd Floor	210	210	871	177	80	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	301	301	871	150	60	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	302	302	871	118	80	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	303	303	871	177	80	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	308	308	871	177	80	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	309	309	871	118	80	N	Y				
Regular Classroom	Regular Classroom	3rd Floor	310	310	871	177	80	N	Y				
Science	Regular Classroom	2nd Floor	204	204	1,171	120	60	Ν	Ν				