

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1912	3	38,104
Addition	1971	1	21,588
Campus Total			59,692

Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance	,,	Location	Quantity	OCIVI	Italik	Replacement	Comments
EIIIIance	Exterior Doors - Exterior Steel Door	Entrance 3 - South - Boiler room	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3 - South - Boiler room Entrance 3, Previously 5 - NE	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 3, Previously 5 - NE	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 3, Previously 5 - NE	14	LF	5	2-5 years	Cracked concrete
	Exterior Doors - Exterior Steel Door	Entrance 4 - SE	6	EA	7	10+ years	Cracked concrete
	Exterior Doors - Transom Lite	Entrance 4 - SE	3	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 4 - SE	10	LF	6	10+ years	
	Ramps - Concrete	Entrance 4 - SE	10	LF	6	10+ years	Hairline cracks in the concrete
	Entrance Control - Audio and Video	Main entrance 1 - North	10	EA	6	10+ years	riannie cracks in the concrete
	Exterior Doors - Exterior FRP Door	Main entrance 1 - North	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main entrance 1 - North	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Main entrance 1 - North	28	LF	5	2-5 years	Cracked concrete
	Exterior Stairs - Concrete	Main entrance 1 - North	20	LI	5	2-5 years	Cracked concrete
Foundati	on						
	Foundation - Masonry	Entire Building	515	LF	7	10+ years	
	Foundation - Masonry	Entire Building	30	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	38,104	SF	7	10+ years	
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	10+ years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building Entire Building	1	EA	6	10+ years	
	Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted	Entire Building Entire Building	11	EA	6	10+ years	
	Exterior Lighting - wall wounted	Little building	11	LA	U	10+ years	



	Schools						2819 W 21st PLACE, Chicago, IL 60623
Catego	ory : Exterior		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	1-2 years	Broken lamp fixture near boiler room number three door
Roof Sy	stem						
	Access Ladder - Metal	Roof 2	1	EA	4	0-1 year	Dangerous transition from the space between the ceiling and the roof to the roof. The ladder does not Reach the roof
	Coping - Metal	Roof 2	55	LF	7	10+ years	
	Coping - Stone	Roof 2	355	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	85	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	200	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	410	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	9,025	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 2	1	ĒΑ	7	10+ years	Repaired
	Roof Structure - Steel / Metal Deck/	Roof 2	9,025	SF	7	10+ years	
	Concrete Topping	11001 2	0,020	٥.	•	io. youro	
	Coping - Stone	Roof 3	195	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	40	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	2	LF	4	0-1 year	Broken, corroded cast-iron pipe with a missing piece
	Parapet - Parapet < 16" Height	Roof 3	205	LF	7	10+ years	a missing piece
	Parapet - Parapet > 30"	Roof 3	70	LF	6	2-5 years	
	Roof - Modified Bitumen	Roof 3	6,590	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 3	6,590	SF	7	10+ years	
	Concrete Topping	. 100. 0	2,223	٠.	•	.o. you.o	
	Coping - Clay Tile	Roof 4	84	LF	6	10+ years	Verified amount of coping
	Coping - Clay Tile	Roof 4	18	LF	4	0-1 year	Open joints and broken tiles
	Downspouts - Exterior Downspouts	Roof 4	30	LF	6	10+ years	open jointe and broken thee
	Parapet - 16" - 30" Height	Roof 4	44	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	20	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 4	26	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4	75	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 4	50	SF	5	1-2 years	This bit of modified bitumen roofing
	Kooi - Modified Bitumen	N001 4	30	SF	3	1-2 years	a patch on top of PVC. It's seams a failing, coming apart
	Roof - PVC Membrane	Roof 4	1,100	SF	6	6-10 years	g,
	Roof - PVC Membrane	Roof 4	100	SF	4	0-1 year	Soft spots, Deteriorated sealant at counter flashing, broken counter flashing
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	1,325	SF	7	10+ years	9
	Coping - Clay Tile	Roof 5	15	LF	6	10+ years	
	Coping - Clay Tile	Roof 5	13	LF	6	2-5 years	
		3 - 3 - 3			-	,•	



Catego	ry : Exterior		В	uilding	: Main		Ţ
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Roof 5	48	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5	8	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 5	20	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 5	920	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 5	920	SF	7	10+ years	
	Concrete Topping					-	
	Chimney - Brick Chimney- Stainless Steel	Roof 6	1	LF	7	10+ years	
	Liner					-	
	Coping - Clay Tile	Roof 6	28	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	50	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 6	13	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 6	15	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 6	1,025	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 6	1,025	SF	7	10+ years	
	Concrete Topping		·			·	
	Coping - Clay Tile	Roof 7	40	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	6	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	26	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 7	40	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 7	465	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 7	465	SF	7	10+ years	
	Concrete Topping					, , , , , ,	
	Coping - Stone	Roof 8	28	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 8	12	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 8	28	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 8	80	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 8	80	SF	7	10+ years	
	Concrete Topping			О.	•	.o. you.o	
	Coping - Stone	Roof 9	45	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 9	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 9	45	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 9	235	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 9	235	SF	7	10+ years	
	Concrete Topping	110010	200	O.	•	ioi youro	
	Concrete Topping						
_Walls							
VVAIIS	Cornice - Cast Stone	Entire Building	45	LF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	13,375	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Open joints, deteriorated mortar
	Exterior Walls - Prefabricated Metal Panel	Entire Building	1,200	SF	7	10+ years	opon jointo, deteriorated mortar
	Wall	· ·	,		,	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,500	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	207	SF	5	10+ years	Open joints and cracks in the Stone
	Exterior Walls - Stucco	Entire Building	1,175	SF	6	10+ years	Dirty



Group

Category : Exterior

Item - Type

Exterior Walls - Stucco

Charles G Hammond Elementary School 2819 W 21st PLACE, Chicago, IL 60623

Comments

Damaged wall

Building : Main

Rank

3

UOM

SF

Quantity

50

Recommend

Replacement

1-2 years

/indows	3						
	Guard - Guards perforated	Entire Building	1,830) SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	560		6	6-10 years	
	Lintels - Brick	Entire Building	1:		6	10+ years	
	Lintels - Steel	Entire Building	599	5 LF	6	10+ years	
	Windows - Louver	Entire Building	18		6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,48	5 SF	6	10+ years	
atego	ry : Electrical			Building	: Main		
Ŭ						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nergen	ncy System						
	Automatic Transfer Switch	Electrical Room			4	2-5 years	Older switch ant not reliable
	Security System - CCTV	Entire Building	38,10		6	6-10 years	AI system
	Security System - Intrusion Detection	Entire Building	38,10		6	6-10 years	
	Exit Signs - Auditoium	Entire Building	;	B EA	6	6-10 years	New item added per current observation
	Exit Signs - Corridors and Stairs	Entire Building	18	B EA	6	6-10 years	With batteries
	Exit Signs - Gym	Entire Building	;	B EA	6	6-10 years	New item added per current observation
	Exit Signs - Multipurpose Room	Entire Building	:	2 EA	6	6-10 years	With batteries
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	5,98		6	10+ years	New item added per current observation
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,643	3 SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	5,98	3 SF	6	10+ years	
	Emergency Battery Packs - Gym	Entire Building		2 EA	6	6-10 years	New item added per current observation
ain Ser	vice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room		I EA	4	2-5 years	Aged and deteriorated
	Independent Electrical Service for emergency power	Electrical Room		I EA	4	2-5 years	Older Switch and not reliable
	PA System	Entire Building	38,10	4 SF	5	6-10 years	Served addition also Both buildin partially working Older system
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	:	2 EA	7	10+ years	New item added per current observation Fuse panel
	Lighting and Power Panels - 100 A	Entire Building		6 EA	7	10+ years	Location change per current

Location

Entire Building



Category : Electrical

Charles G Hammond Elementary School 2819 W 21st PLACE, Chicago, IL 60623

Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
						observation
	Entire Building	3	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Making noise
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	· ·
y : Fire Protection		E	Building	: Main		
			_		Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
n						
		1			·	Partially working per building engineer, older system not reliable No strobe lights
Fire Alarm_System	Mechanical Room	38,104	SF	4	2-5 years	Older system and no strobe lights installed
y : Mechanical		E	Building	: Main		
	Location	Quantity	UOM	Rank	Replacement	Comments
tioning						
Condensing Unit- Roof Mounted - 21-30 tons	Roof	2	EA	7	10+ years	Feeding AHU1
Condensing Unit- Roof Mounted - Less than 5 tons	Wall mounted	2	EA	5	6-10 years	One compressor needs repair
ing Systems						
Air Handling Unit- Built Up- Single Zone- Steam Coils and Chilled Water Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	10+ years	
Air Intake	Mechanical Room	1	EA			
Auxiliarias 15001 25000 ofm				_	10+ years	
	Mechanical Room	1	EA	5	ioi yeais	
Return Duct Work - Masonry and Ducts-	Mechanical Room Mechanical Room	100	LF	5 5	10+ years	
		·			10+ years 10+ years	Manually open and close Control needs to be adjusted
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake	Mechanical Room	100	LF	5	10+ years 10+ years 6-10 years	
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm	Mechanical Room Mechanical Room	100	LF EA	5 5	10+ years 10+ years	needs to be adjusted
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonry and Ducts-	Mechanical Room Mechanical Room Mechanical Room	100 1 1	LF EA EA	5 5 5	10+ years 10+ years 6-10 years	needs to be adjusted
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm	Mechanical Room Mechanical Room Mechanical Room Mechanical Room	100 1 1 1 1	LF EA EA EA	5 5 5 6	10+ years 10+ years 6-10 years 10+ years	needs to be adjusted Manually open and close
)	Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp y: Fire Protection Item - Type The Alarm Panel Fire Alarm Panel Fire Alarm_System y: Mechanical Item - Type John Condensing Unit- Roof Mounted - 21-30 tons Condensing Unit- Roof Mounted - Less than 5 tons Ing Systems Air Handling Unit- Built Up- Single Zone- Steam Coils and Chilled Water Coils - 15001 - 25000 cfm Air Intake	Lighting and Power Panels - Above 100 A Lighting Entire Building Entire Buildi	Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp Entire Building 1 y: Fire Protection E Location Quantity Mechanical Room 1 Fire Alarm Panel Mechanical Room 38,104 y: Mechanical Location Quantity Mechanical E Location Quantity Mechanical E Mechanical Room 38,104 Augustity Mechanical Augustity Mechanical Room 1 Mechanical Room 1 Mechanical Room 1 Mechanical Room 1	Lighting and Power Panels - Above 100 A Lighting Building Lighting and Power Panels - Above 100 A Lighting Building Lighting B	Lighting and Power Panels - Above 100 A Lighting and Power Panels Lighting and Power Panels Lighting and Power Panels Leaf 7 Leaf 7 Leaf 7 Leaf 7 Leaf 7 Leaf 7 Leaf	Lighting and Power Panels - Above 100 A Entire Building 1 EA 7 10+ years Lighting and Power Panels - Above 100 A Entire Building 1 EA 4 2-5 years Recommend Replacement Location Mechanical Room 1 EA 3 0-1 year Recommend Replacement Location Wechanical Room 38,104 SF 4 2-5 years Y: Mechanical Location Quantity UOM Rank Recommend Replacement Location Quantity UOM Rank Recommend Replacement Location Wechanical Room 2 EA 7 10+ years Location Quantity UOM Rank Recommend Replacement Location Wechanical Room 1 EA 5 6-10 years Location Recommend Replacement Location Location Recommend Replacement Location Location Recommend Replacement Location Recommend Replacement Location Location Recommend Replacement Location Recommend Recommend Recommend Replacement Location Recommend Recommend Reco

Building: Main

Recommend



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Air Intake	Mechanical Room	1	EA	5	6-10 years	Manually connected dampers
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	Needs minor repair
	Return Duct Work - Masonry and Ducts-	Mechanical Room	200	LF	5	10+ years	System needs rebalanced
	Missing or Existing Shaft	Woonamour Room	200		·	io. youro	Cyclom noodo robalaneod
	Zone Dampers	Mechanical Room	16	EA	5	6-10 years	Quantity change per current
	Zono Bamporo	Weenamear Neem	10	_, 、	Ü	o ro youro	observation Manually open and clos
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	10+ years	Boiler 2 valve leaking and only one
	Pressure Boiler - 151 - 200 HP						bypass working Served addition 2
	Chemical Feed System	Boiler Room	1	EA	5	10+ years	System needs to be repaired
	Combustion Dampers	Boiler Room	2	EA	5	10+ years	
	Condensate Pump	Boiler Room	4	EA	5	10+ years	Quantity change per current
					•	, , , , , , , , , , , , , , , , , , , ,	observation
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	10+ years	Pumps and control needs to be
	r cod water r dinpo dila raint	Bollot (Coll)	•		O	101 youro	refurbished
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	10+ years	Boiler 2 valve leaking and only one
	Steam- Low Pressure Boiler - 151 - 200 HP	Bollet Rootti	2	LA	J	10+ years	bypass working Served addition to
	Piping - Condensate Pipe- Steel	Boiler Room	250	LF	e	10	bypass working Served addition to
					6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	250	LF	6	10+ years	
	Steam Traps	Boiler Room	35	EA	5	6-10 years	Minor repair needed
Heat Exc	changers						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	5	6-10 years	Pumps need some repair
	Type	Boiler Room	'	L/ \	0	o to years	r amps need some repair
	.,,,,,						
Heating							
	Unit Heater - Electric	Boiler Room	1	EA	2	0-1 year	Not working per current observation
	Unit Heater - Steam	Boiler Room	1	EA	5	6-10 years	Need some repair
	Wall Heater - Electric	Entire Building	4	EA	6	10+ years	Quantity change per current
		G				•	observation
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Move to down Not working per
	114	g	·		_	o . y ca.	current observation Older unit
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	150	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	5	6-10 years	Need some repair
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
Tempera	ature Control						
	Electric Thermostat	Entire Building	9	EA	5	6-10 years	
•	LIEGUIG THEITHUSIAI	Little Bulluling	9				
•		Entiro Building	20 104	QE.	_	6 10 years	Both huilding has Proumatic and
·	Hybrid Pneumatic/DDC System	Entire Building	38,104	SF	5	6-10 years	Both building has Pneumatic and DDC system, can't control actuators



O-to-				• • • • • • • • • • • • • • • • • •	N# - '		2819 W 21st PLACE, Chicago, IL 60623
Catego	y : Mechanical		В	uilding	: Main	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	nem - Type	Location	Quantity	COM	Italik	Replacement	and damper manually open and clos
	Thermostats - DDC	Entire Building	19	EA	6	6-10 years	and damper mandally open and elec
	Thermostats - DDC	Entire Building	2	EA	4	1-2 years	Manually open and close Not repair
	Thermostats - Pneumatic	Entire Building	2	EA	4	1-2 years	Manually open and close
Ventilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	Quantity change per current w
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	6	10+ years	Quantity change per current observation
	Roof Mounted Duct Work	Entire Building	100	LF	6	10+ years	
Catego	y : Plumbing		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		5 " 5					1
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	Installed new in 2021
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	38,104	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	38,104	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	38,104	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	38,104	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	38,104	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	38,104	SF	6	10+ years	
	Sanitary Piping	Entire Building	38,104	SF	6	10+ years	
	Storm Piping	Entire Building	38,104	SF	6	10+ years	
	Vent Piping	Entire Building	38,104	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	6-10 years	
Catego	y : Room		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices		•				



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st fl Copy Room Next to Gym	725	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st fl Copy Room Next to Gym	2	EA	6	10+ years	
	Floor - Tile	1st fl Copy Room Next to Gym	22	SF	4	1-2 years	Cracked floor
	Floor - Tile/Sheet	1st fl Copy Room Next to Gym	703	SF	7	10+ years	
	Lighting - Pendent/Surface	1st fl Copy Room Next to Gym	6	EA	6	10+ years	
	Walls - Plaster/Drywall	1st fl Copy Room Next to Gym	1,148	SF	6	10+ years	
	AC Unit	1st fl Main Office 103	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st fl Main Office 103	560	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st fl Main Office 103	3	EA	6	10+ years	
	Floor - Wood	1st fl Main Office 103	560	SF	6	10+ years	
	Lighting - Pendent/Surface	1st fl Main Office 103	10	EA	7	10+ years	
	Power Distribution	1st fl Main Office 103	20	EA	6	10+ years	
	Storage/ Closet	1st fl Main Office 103	240	SF	5	10+ years	No entry, based on past assessment
	Walls - Plaster/Drywall	1st fl Main Office 103	1,290	SF	6	10+ years	
	AC Unit	Parent/student meeting room next to main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Parent/student meeting room next to main office	302	SF	7	10+ years	
	Doors - Transom Window	Parent/student meeting room next to main office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Parent/student meeting room next to main office	1	EA	6	10+ years	
	Floor - Wood	Parent/student meeting room next to main office	302	SF	7	10+ years	
	Lighting - Pendent/Surface	Parent/student meeting room next to main office	3	EA	7	10+ years	
	Power Distribution	Parent/student meeting room next to main office	10	EA	7	10+ years	
	Storage/ Closet	Parent/student meeting room next to main office	15	SF	7	10+ years	
	Walls - Plaster/Drywall	Parent/student meeting room next to main office	855	SF	7	10+ years	
	AC Unit	Room 200 Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 200 Office	370	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 200 Office	1	ĒΑ	6	10+ years	
	Floor - Tile	Room 200 Office	370	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 200 Office	5	EA	7	10+ years	
	Power Distribution	Room 200 Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 200 Office	920	SF	6	10+ years	
	Work Slnk	Room 200 Office	1	EA	7	10+ years	
_Gymnas	ia						
•	Ceiling - Plaster/Drywall	1st Floor	5,988	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		<u> </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Sport Flooring	1st Floor	5,988	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	10+ years	
	Main Floor Seating	1st Floor	322	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	10+ years	
	Stage	1st Floor	200	SF	7	10+ years	
	Stage Curtain	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	1st Floor	14	LF	7	10+ years	
	Storage/ Closet	1st Floor	145	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,890	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,900	SF	6	10+ years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	40	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	480	SF	5	10+ years	
	Storage Room	1st Floor	430	SF	7	10+ years	
	Mechanical/ Service Rooms	1st fl Engineers office old Girls	240	SF	7	10+ years	
	Mechanical/ Service Rooms	Restroom	240	Si	,	10+ years	
	Janitor's Closet	2nd Floor	35	SF	7	10+ years	Quantity updated
	Janitor's Closet	3rd Floor	32	SF	7	10+ years	Updated quantity
_Restroo	m						
	Accessories	1st Floor Boys	365	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Boys	365	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	365	SF	7	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Lavatory	1st Floor Boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	5	EA	7	10+ years	
	Partitions	1st Floor Boys	3	EA	7	-	
	Urinals	1st Floor Boys	3	EA	7	10+ years	
	Walls - Concrete Block		_	SF	-	10+ years	
		1st Floor Boys	400	SF SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	420	SF SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	120		6	10+ years	
	Water Closet	1st Floor Boys	3	EA	7	10+ years	
	Accessories	1st fl Engineer's Bathroom	50	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st fl Engineer's Bathroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st fl Engineer's Bathroom	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st fl Engineer's Bathroom	50	SF	7	10+ years	
	Lavatory	1st fl Engineer's Bathroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st fl Engineer's Bathroom	1	EA	7	10+ years	
	Walls - Concrete Block	1st fl Engineer's Bathroom	150	SF	6	10+ years	
	Walls - Plaster/Drywall	1st fl Engineer's Bathroom	150	SF	6	10+ years	
	Water Closet	1st fl Engineer's Bathroom	1	EA	6	10+ years	
	Accessories	1st fl In Boiler Room	29	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st fl In Boiler Room	29	SF	6	10+ years	



Category : Room			В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st fl In Boiler Room	1	EA	6	10+ years	
	Floor - Concrete	1st fl In Boiler Room	29	SF	7	10+ years	
	Lavatory	1st fl In Boiler Room	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st fl In Boiler Room	3	EA	7	10+ years	
	Walls - Concrete Block	1st fl In Boiler Room	220	SF	6	10+ years	
	Water Closet	1st fl In Boiler Room	1	EA	6	10+ years	
	Accessories	1st fl Main Office	42	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st fl Main Office	34	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st fl Main Office	8	SF	4	1-2 years	Cracked ceiling
	Doors - Wood Doors inclu hw	1st fl Main Office	1	EA	6	10+ years	•
	Floor - Tile Ceramic/ Porcelain	1st fl Main Office	42	SF	6	10+ years	
	Lavatory	1st fl Main Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st fl Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st fl Main Office	395	SF	6	10+ years	
	Walls - Plaster/Drywall	1st fl Main Office	5	SF	5	1-2 years	Cracked wall
	Water Closet	1st fl Main Office	1	ĒΑ	6	10+ years	
	Accessories	200A Toilet - 200 Office	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	200A Toilet - 200 Office	53	SF	6	10+ years	
	Doors - Wood Doors inclu hw	200A Toilet - 200 Office	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	200A Toilet - 200 Office	24	SF	7	10+ years	
	Floor - Tile	200A Toilet - 200 Office	29	SF	7	10+ years	
	Lighting - Pendent/Surface	200A Toilet - 200 Office	1	EA	7	10+ years	
	Partitions	200A Toilet - 200 Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	200A Toilet - 200 Office	400	SF	6	10+ years	
	Water Closet	200A Toilet - 200 Office	2	EA	4	0-1 year	Out of order
	Accessories	300A Toilet - 300 Office	53	SF	7	6-10 years	Out of order
	Ceiling - Plaster/Drywall	300A Toilet - 300 Office	53	SF	6	10+ years	
	Doors - Wood Doors inclu hw	300A Toilet - 300 Office	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	300A Toilet - 300 Office	24	SF	7	10+ years	
	Floor - Tile	300A Toilet - 300 Office	29	SF	7	10+ years	
	Lighting - Pendent/Surface	300A Toilet - 300 Office	1	EA	7	10+ years	
	Partitions	300A Toilet - 300 Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	300A Toilet - 300 Office	400	SF	6	10+ years	
	Water Closet	300A Toilet - 300 Office	2	EA	6	10+ years	
	Accessories	Bathroom 102A - In room 102	73	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Bathroom 102A - In room 102	73	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Bathroom 102A - In room 102	73	EA	7	10+ years	
	Floor - Tile	Bathroom 102A - In room 102	7	SF	4		Damaged floor
	Floor - Tile/Sheet	Bathroom 102A - In room 102 Bathroom 102A - In room 102	66	SF SF	7	1-2 years 10+ years	Damayeu 11001
	Lavatory	Bathroom 102A - In room 102	1	EA	7	,	
	Lighting - Pendent/Surface		1	EA	6	10+ years	
		Bathroom 102A - In room 102	· · · · · · · · · · · · · · · · · · ·	SF	6	10+ years	
	Walls - Plaster/Drywall	Bathroom 102A - In room 102	460 1	_		10+ years	
	Water Closet	Bathroom 102A - In room 102	342	EA SF	7 7	10+ years	
	Accessories	Boys - Next to Room 303	342	SF	,	6-10 years	



Category : Room Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Boys - Next to Room 303	312	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boys - Next to Room 303	30	SF	5	1-2 years	Water damage, peeling paint
	Doors - Wood Doors inclu hw	Boys - Next to Room 303	2	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys - Next to Room 303	342	SF	7	10+ years	
	Floor Drain	Boys - Next to Room 303	1	EΑ	7	6-10 years	
	Lavatory	Boys - Next to Room 303	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys - Next to Room 303	4	EA	7	10+ years	
	Partitions	Boys - Next to Room 303	4	EA	7	6-10 years	
	Urinals	Boys - Next to Room 303	3	EA	7	10+ years	
	Walls - Masonry	Boys - Next to Room 303	1,708	SF	7	10+ years	
	Walls - Plaster/Drywall	Boys - Next to Room 303	1,700	SF	6	10+ years	
	Walls - Structural Glazed Tile	Boys - Next to Room 303	12	SF	7	10+ years	
	Water Closet	Boys - Next to Room 303	3	EA	7	10+ years	
	Accessories	Girl toilet - next to room 203	350	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girl toilet - next to room 203	350	SF	6	6-10 years	Peeling paint
	Doors - Wood Doors inclu hw	Girl toilet - next to room 203	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girl toilet - next to room 203	350	SF	6	10+ years	
	Floor Drain	Girl toilet - next to room 203	1	EΑ	7	10+ years	
	Lavatory	Girl toilet - next to room 203	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girl toilet - next to room 203	4	EA	7	10+ years	
	Partitions	Girl toilet - next to room 203	6	EA	7	10+ years	
	Walls - Masonry	Girl toilet - next to room 203	525	SF	6	10+ years	
	Walls - Plaster/Drywall	Girl toilet - next to room 203	525	SF	6	10+ years	
	Walls - Structural Glazed Tile	Girl toilet - next to room 203	12	SF	7	10+ years	
	Water Closet	Girl toilet - next to room 203	6	EA	7	10+ years	

Category : Classroom **Building: Main**

	, . c.a.c. c		_	<u>.</u>			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	555	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	4	SF	5	1-2 years	Damaged tile
	Floor - Tile/Sheet	1st Floor	555	SF	7	10+ years	-
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years	
lassroo	m #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	

Campus Name: Hammond Page : 11 of 29 Assessment Date: 04/14/2022



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	1st Floor	910	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Cracked tile
	Floor - Tile/Sheet	1st Floor	890	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,500	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Cracking
Classroo	om #201 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,374	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
_ Oldoor ot	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	6	6-10 years	Peeling paint
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	r eemig paint
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,374	SF	6	10+ years	
Classro	om #203 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	840	SF	6	6-10 years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	Coal Woaling
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	
Classroo	om #204 (Faculty Lounge)						
	` , ,						



Catego	ry : Classroom		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	7	10+ years	
_Classroo	om #205 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	. <u> </u>	EA	6	10+ years	
	Floor - Wood	1st Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,374	SF	6	10+ years	
	, , , , , , , , , , , , , , , , , , ,		.,	-	•	, , , , , , , , , , , , , , , , , , , ,	
_Classroo	om #300 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	370	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	367	SF	7	10+ years	Updated to match current observations
	Floor - Tile	2nd Floor	3	SF	5	1-2 years	Chipping tile
	Lighting - Pendent/Surface	2nd Floor	5	ĒΑ	7	10+ years	- 11 3
	Walls - Plaster/Drywall	2nd Floor	920	SF	6	10+ years	
_Classroo	om #301 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	620	SF	7	10+ years	
	Floor - Wood	2nd Floor	220	SF	6	6-10 years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	Coal Wouling
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	
	·		.,571	٥.	Ŭ	,	
_Classroo	om #302 (Regular Classroom)						

Campus Name: Hammond Page: 13 of 29 Assessment Date: 04/14/2022



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	840	SF	6	6-10 years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	
lassroc	om #303 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	. <u>-</u> 1	EA	5	1-2 years	Split door, loose around fixture
	Floor - Wood	2nd Floor	840	SF	7	10+ years	Opin door, loose around lixture
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	
lassroc	om #304 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	12	EA	7		
	Floor - Wood	2nd Floor	840	SF	7	10+ years	
						10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	
lassroc	om #305 (Regular Classroom)	0-45-				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	6	6-10 years	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,374	SF	6	10+ years	



XXIII.	Schools						2819 W 21st PLACE, Chicago, IL 60623
Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ory : Interior		R	uilding	· Main		
Calego	i y . interior			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	· ·		•			•	
	Ceiling - Plaster/Drywall	1st Floor	3,253	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	ĒΑ	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,233	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Missing/cracked floor
						•	Wissing/Cracked floor
	Lighting - Pendent/Surface	1st Floor	24	EΑ	7	10+ years	
	Student Lockers - One Tier	1st Floor	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	5,306	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,695	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,695	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,436	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,695	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,675	SF	7	•	
			•	SF		10+ years	Cracking
	Floor - Tile/Sheet	3rd Floor	20		5	1-2 years	Cracking
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years	
	Student Lockers - Three Tiers	3rd Floor	6	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	7	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,436	SF	6	10+ years	
Safety							
_oarety	Camera Viewing Station	Entire Building	2	EA	7	2-5 years	Can not view cameras. Viewing
	Cambra viewing Clatteri	Entire Ballating	_		•	2 o youro	station will be updated next month
	Metal Dedector	Entire Building	1	EA	7	6-10 years	station will be updated flext flioriti
		•	3	EA	7		Compress will be undeted next month
	Security Cameras	Entire Building	3	EA	/	2-5 years	Cameras will be updated next month
							Additional cameras scheduled to be
							added.
Stairs							
	Ceiling - Plaster/Drywall	Door 5/ Entrance #3	500	SF	7	10+ years	
	Floor - Asphalt	Door 5/ Entrance #3	500	SF	6	10+ years	
	Handrails	Door 5/ Entrance #3	205	LF	7	10+ years	
	Lighting - Pendent/Surface	Door 5/ Entrance #3	205	EA	7	10+ years	
	Stairs - Asphalt		-	LF	, 6		
	Stalls - Aspitalt	Door 5/ Entrance #3	100	ᄕ	Ö	10+ years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Door 5/ Entrance #3	1,340	SF	7	10+ years	
	Walls - Plaster/Drywall	Door 5/ Entrance #3	40	SF	5	1-2 years	
	Ceiling - Plaster/Drywall	Main stair Center	657	SF	6	10+ years	
	Floor - Asphalt	Main stair Center	627	SF	6	10+ years	
	Floor - Asphalt	Main stair Center	30	SF	5	1-2 years	Cracking
	Handrails	Main stair Center	205	LF	7	10+ years	•
	Lighting - Pendent/Surface	Main stair Center	6	EA	7	10+ years	
	Stairs - Asphalt	Main stair Center	100	LF	6	10+ years	
	Walls - Plaster/Drywall	Main stair Center	2,835	SF	6	10+ years	

Campus Name: Hammond Page : 16 of 29 Assessment Date: 04/14/2022





Category : Exterior **Building: Addition**

	y : Exterior		В				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	Entrance 2 - West	2	EA	6	6-10 years	Doors are beginning to corrode a
						-	bases and frames
	Exterior Doors - Side lite	Entrance 2 - West	1	EA	4	1-2 years	Corroded side light
oundation							
	Foundation - Masonry	Entire Building	242	LF	7	10+ years	
	Superstructure - Steel	Entire Building	21,588	SF	7	10+ years	
مملئمم							
ghting_	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	10+ years	Prepared
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EΑ	6	10+ years	r roparou
	3 3 1	S				,	
oof Sys							
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	40	LF	7	10+ years	
	Liner	Doof 4	_		_	4.0	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	5	LF	5	1-2 years	
	Coping - Stone	Roof 1	385	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	80	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	385	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 1	10,794	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 1	10,794	SF	7	10+ years	
	Concrete Topping	11001 1	10,701	O.	•	Tot youro	
	3						
/alls	E (: W II B: I	F 6 B 7 8	5.075			40	
	Exterior Walls - Brick	Entire Building	5,675	SF	6	10+ years	0
	Exterior Walls - Brick	Entire Building	10	SF	4	1-2 years	Open joints
	Exterior Walls - Stone-Cast	Entire Building	150	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	650	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	50	SF	5	10+ years	
/indows							
	Guard - Guards perforated	Entire Building	1,236	SF	6	10+ years	
	Lintels - Brick	Entire Building	80	LF	6	10+ years	
	Lintels - Steel	Entire Building	195	LF	6	10+ years	



atego	ry : Electrical		В	uilding	: Additio		
						Recommend	_
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,361	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,443	SF	6	10+ years	New item added per current observation
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	21,588	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	21,588	SF	6	6-10 years	
lain Ser	vice						
	PA System	Entire Building	21,588	SF	5	6-10 years	Served from main Partially workin per building engineer
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	New item added per current observation
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	2 2	EA EA	7 7	10+ years 10+ years	Location change per current observation
atego	ry : Fire Protection		В	uilding	: Additio	on	
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm_System	main building	21,588	SF	4	2-5 years	Older system and no strobe lights installed Served from main
atego	ry : Mechanical		В	uilding	Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Cond	itioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	2-5 years	
leating l	Devices						
	Cabinet Heaters - With Hot Water Coil	1st Floor	2	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	20	LF	6	10+ years	
	cal Plumbing						

Campus Name: Hammond Page : 18 of 29 Assessment Date: 04/14/2022



	ry : Mechanical		R	uilding	: Additi	on	2819 W 21St FLACE, Chicago, IL 60625
Calego	ry . Mechanical		D	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о а. р	Hydronic Supply and Return - Steel	1st Floor	200	LF	7	10+ years	Served from main
	, , , , , , , , , , , , , , , , , , , ,					j	
Tempera	ature Control						
•	Electric Thermostat	Entire Building	1	EA	6	10+ years	MDF room Quantity change per current observation
	Pneumatic System	Entire Building	21,588	SF	5	6-10 years	Both building has Pneumatic and DDC system, can't control actuators and damper manually open and close
	Thermostats - Pneumatic	Entire Building	6	EA	5	6-10 years	Manually open and close
	Thermostats - Pneumatic	Entire Building	1	EA	4	0-1 year	New item added per current observation Missing thermostat Room 111
_Ventilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	New item added per current observation Installed in 2020
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	Installed in 2020
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	2-5 years	New item added per current observation Noisy and belts need to be replaced
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	7	10+ years	Installed in 2020
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	5	6-10 years	Motor and belts needs to be replaced
	Roof Mounted Duct Work	Entire Building	50	LF	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additi		
0	N T	Landina	0	LIONA	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Piping	Demonstic Diminus Het Meteu Detuma Linea	Estina Duildin a	04.500	0.5		40	
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building Entire Building	21,588 21,588	SF SF	6 6	10+ years 10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building Entire Building	21,588	SF SF	6	10+ years 10+ years	
	Fixtures	Entire ballaring	21,300	Oi	U	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	21,588	SF	6	10+ years	Served from main building
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	21,588	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	21,588	SF	6	10+ years	
	Sanitary Piping	Entire Building	21,588	SF	6	10+ years	



Catego	ry : Plumbing		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storm Piping	Entire Building	21,588	SF	6	10+ years	
	Vent Piping	Entire Building	21,588	SF	6	10+ years	

Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Administ	rative Suites/Offices								
	Ceiling - Lay-in	1st fl Staff Lunchroom Inside	382	SF	6	10+ years			
		Lunchroom							
	Ceiling - Lay-in	1st fl Staff Lunchroom Inside	8	SF	4	1-2 years	Stain tile		
		Lunchroom			_				
	Doors - Wood Doors inclu hw	1st fl Staff Lunchroom Inside	1	EA	7	10+ years			
		Lunchroom			_				
	Floor - Tile/Sheet	1st fl Staff Lunchroom Inside	390	SF	7	10+ years			
	11.12	Lunchroom	40	_^	-	4.0			
	Lighting - Lay-in	1st fl Staff Lunchroom Inside	12	EA	7	10+ years			
	Dower Distribution	Lunchroom	4	ГΛ	6	10			
	Power Distribution	1st fl Staff Lunchroom Inside Lunchroom	4	EA	6	10+ years			
	Walls - Plaster/Drywall	1st fl Staff Lunchroom Inside	220	SF	6	10+ years			
	Walls - Flastel/Drywall	Lunchroom	220	SI	O	10+ years			
	Ceiling - Plaster/Drywall	Engineer office	240	SF	6	2-5 years			
	Doors - Wood Doors inclu hw	Engineer office	1	EA	6	6-10 years			
	Floor - Tile	Engineer office	240	SF	6	6-10 years			
	Lighting - Lay-in	Engineer office	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	Engineer office	493	SF	6	2-5 years			
	Walls - Plaster/Drywall	Engineer office	15	SF	5	0-1 year	Damaged wall		
	,	3		_	_	, , , , , ,			
Kitchen									
	Ceiling - Plaster/Drywall	1st Floor	1,164	SF	6	10+ years			
	Doors - Hardware	1st Floor	2	EA	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile Quarry	1st Floor	1,164	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	20	EA	7	10+ years			
	Serving Line	1st Floor	22	LF	7	10+ years			
	Walls - Concrete Block	1st Floor	1,274	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	1st Floor	2,443	SF	6	10+ years			
	Doors - Hardware	1st Floor	6	EA	6	10+ years			
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Cracked/damaged tile		
	Floor - Tile/Sheet	1st Floor	2,403	SF	5	10+ years			
	Lighting - Lay-in	1st Floor	59	EA	7	10+ years			

Page : 20 of 29 Campus Name: Hammond Assessment Date: 04/14/2022



Category : Room		В	uilding	: Addition			
	_					Recommend	_
roup	Item - Type	Location	Quantity	UOM	Rank		Comments
	Walls - Plaster/Drywall	1st Floor	1,274	SF	7	10+ years	
OF IDE	=						
<u> </u>	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated quantity
	Finishes	2nd Floor	120	SF	7	10+ years	Updated quantity
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	Split unit
echanio	cal/ Service Rooms						
COHOTIN	Boiler Room	1st fl Pump Room	1,890	SF	7	10+ years	
	Coal Room	1st fl Pump Room	650	SF	7	10+ years	
	Mechanical/ Service Rooms	1st fl Pump Room	1,330	SF	5	10+ years	
	Mechanical/ Service Rooms	1st fl Pump Room	450	SF	5	6-10 years	Fan room 2
	Storage Room	1st fl Pump Room	320	SF	5	10+ years	Inside boiler rm
		1st il Pump Room	200	SF SF		•	
	Storage Room				5	10+ years	Next to fan rm 2
	Storage Room	1st fl Storage next to girls rr	185	SF	7	6-10 years	
	Janitor's Closet	Janitor closet - next to boy restroom 2nd floor	63	SF	7	10+ years	Updated to match current observations
	Storage Room	Storage next to resource rm 107	185	SF	7	6-10 years	
estroon	n						
23110011	Accessories	1st fl Girls Restroom	270	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st fl Girls Restroom	270	SF	7	10+ years	
	Doors - Hardware	1st fl Girls Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st fl Girls Restroom	270	SF	6	10+ years	
	Floor Drain	1st fl Girls Restroom		EA	7		
			1			10+ years	
	Lavatory	1st fl Girls Restroom	3	EΑ	6	10+ years	
	Lighting - Lay-in	1st fl Girls Restroom	4	EA	7	10+ years	
	Partitions	1st fl Girls Restroom	6	EΑ	5	2-5 years	
	Walls - Concrete Block	1st fl Girls Restroom	620	SF	7	10+ years	
	Water Closet	1st fl Girls Restroom	6	EΑ	7	10+ years	
	Accessories	1st fl staff in pump rm/old women's rr	142	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st fl staff in pump rm/old women's	142	SF	6	10+ years	
	Doors - Steel Doors incl hw	rr 1st fl staff in pump rm/old women's	1	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	rr 1st fl staff in pump rm/old women's	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	rr 1st fl staff in pump rm/old women's	142	SF	6	10+ years	
	Lavatory	rr 1st fl staff in pump rm/old women's	1	EA	6	10+ years	
	Lighting - Lay-in	rr 1st fl staff in pump rm/old women's	2	EA	7	10+ years	



Catego	ry : Room		Building : Addition								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
		rr									
	Student Lockers - One Tier	1st fl staff in pump rm/old women's	9	EA	6	10+ years					
		rr			_						
	Walls - Concrete Block	1st fl staff in pump rm/old women's	416	SF	6	10+ years					
	W II O	rr	0.5	0.5	•	4.0					
	Walls - Structural Glazed Tile	1st fl staff in pump rm/old women's	65	SF	6	10+ years					
	Water Closet	rr 1st fl staff in pump rm/old women's	1	EA	6	10 Lyong					
	Water Closet	· · ·	1	EA	6	10+ years					
	Accessories	rr 1st fl Staff Restroom - next to 107	76	SF	7	10+ years					
	Ceiling - Plaster/Drywall	1st fl Staff Restroom - next to 107	76	SF	6	10+ years					
	Doors - Wood Doors inclu hw	1st fl Staff Restroom - next to 107	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	1st fl Staff Restroom - next to 107	76	SF	6	10+ years					
	Lavatory	1st fl Staff Restroom - next to 107	1	EA	5	10+ years					
	Lighting - Lay-in	1st fl Staff Restroom - next to 107	1	EA	7	10+ years					
	Partitions	1st fl Staff Restroom - next to 107	1	EA	7	10+ years					
	Urinals	1st fl Staff Restroom - next to 107	1	EA	6	10+ years					
	Walls - Concrete Block	1st fl Staff Restroom - next to 107	208	SF	6	10+ years					
	Walls - Plaster/Drywall	1st fl Staff Restroom - next to 107	66	SF	6	10+ years					
	Water Closet	1st fl Staff Restroom - next to 107	1	EA	6	10+ years					
	Accessories	1st fl toilet 111A	38	SF	7	10+ years					
	Ceiling - Lay-in	1st fl toilet 111A	38	SF	6	6-10 years					
	Doors - Steel Doors incl hw	1st fl toilet 111A	1	ĒΑ	6	10+ years					
	Floor - Tile/Sheet	1st fl toilet 111A	38	SF	7	10+ years					
	Lavatory	1st fl toilet 111A	1	EA	6	10+ years					
	Lighting - Lay-in	1st fl toilet 111A	1	EA	7	10+ years					
	Walls - Masonry	1st fl toilet 111A	228	SF	6	10+ years					
	Walls - Plaster/Drywall	1st fl toilet 111A	34	SF	6	10+ years					
	Water Closet	1st fl toilet 111A	1	EA	6	10+ years					
	Accessories	Boy restroom - next to room 211	421	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	Boy restroom - next to room 211	421	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Boy restroom - next to room 211	3	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	Boy restroom - next to room 211	421	SF	6	10+ years					
	Floor Drain	Boy restroom - next to room 211	1	EA	7	10+ years					
	Lavatory	Boy restroom - next to room 211	3	EA	7	10+ years					
	Lighting - Lay-in	Boy restroom - next to room 211	5	EA	7	10+ years					
	Partitions	Boy restroom - next to room 211	5	EA	7	10+ years					
	Urinals	Boy restroom - next to room 211	5	EA	7	10+ years					
	Walls - Structural Glazed Tile	Boy restroom - next to room 211	876	SF	7	10+ years					
	Water Closet	Boy restroom - next to room 211	4	EA	7	10+ years					



Category : Classroom			В	on			
Group Item - Type		Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	m #107 (Other Instructional Use)	Location	Quantity	OCIVI	Ivalik	Replacement	Comments
Jassroo	,	4at Flace	400	SF		10	
	Ceiling - Lay-in	1st Floor	460		6	10+ years	\\/
	Ceiling - Lay-in	1st Floor	10	SF	4	1-2 years	Water damage/cracked tile
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	470	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	668	SF	7	10+ years	
`laeeroo	m #111 (Kindergarten)						
21000	Casework	1st Floor	36	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	950	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA		10+ years	
			· · · · · · · · · · · · · · · · · · ·	SF	6		
	Floor - Tile/Sheet	1st Floor	950		7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	36	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,082	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #206 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,190	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Water stains
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	Water stante
	Floor - Tile	2nd Floor	1,190	SF	7	10+ years	
	Floor - Tile	2nd Floor	1,190	SF	5	1-2 years	Broken tiles
	Lighting - Lay-in	2nd Floor	36	EA	7	10+ years	Diokeil tiles
				LF			
	Marker Board	2nd Floor	20		7	6-10 years	
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	Updated quantity
	Walls - Concrete Block	2nd Floor	1,246	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	804	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	5	1-2 years	Water damage, sagging
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	806	SF	7	10+ years	
	Floor - Tile	2nd Floor	2	SF	5	1-2 years	Broken corner on tile
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	DIGNOTI COTTOT OF THE
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	954	SF	7	•	
	vvalis - Culturete Bluck	ZIIU FIOOI	904	SF	,	10+ years	
	m #208 (Regular Classroom)						



Category : Classroom			В	on			
			_			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	800	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	800	SF	7	10+ years	
	Floor - Tile	2nd Floor	3	SF	5	1-2 years	Cracking tiles
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	954	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	m #209 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	800	SF	7		
						10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	954	SF	7	10+ years	
assroc	m #210 (Store Room)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	800	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	784	SF	7	10+ years	
	Floor - Tile	2nd Floor	16	SF	5	1-2 years	Cracking
	Lighting - Lay-in	2nd Floor	18	ĒA	7	10+ years	3
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EΑ	6	10+ years	
	Walls - Concrete Block	2nd Floor	950	SF	7	10+ years	
assroc	m #211 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	785	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	785	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor 2nd Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier		10	EA	7 7		
		2nd Floor				10+ years	
	Walls - Concrete Block	2nd Floor	938	SF	7	10+ years	

Campus Name: Hammond Page : 24 of 29 Assessment Date: 04/14/2022



Category : Classroom			R	uildina	: Additio	2819 W 21st PLACE, Chicago, IL 606	
Catego	Ty . Classicolli		٠	unung	. Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Casework	2nd Floor	22	LF	7	10+ years	Comments
		2nd Floor	808	SF		,	
	Ceiling - Lay-in				7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	7	10+ years	01.1
	Floor - Tile	2nd Floor	1	SF	5	1-2 years	Chipping
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	954	SF	7	10+ years	
Classroo	m #213 (Kindergarten)						
	Casework	2nd Floor	11	LF	7	10+ years	
	Casework	2nd Floor	11	LF	6	6-10 years	Counter Veneer bubbling up
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	2 2 2 3 3 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	796	SF	7	10+ years	
	Floor - Tile	2nd Floor	4	SF	5	1-2 years	Chipping tiles
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	Orlipping tiles
	Marker Board	2nd Floor	20	LF	7	6-10 years	
			10	EA	7	•	
	Student Lockers - One Tier	2nd Floor 2nd Floor	954	SF	7	10+ years	
	Walls - Concrete Block	211a F1001	954	SF	,	10+ years	
Classroo	m #215 (Kindergarten)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	785	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	785	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	938	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Additio	on	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		4 . =:					
	Ceiling - Lay-in	1st Floor	1,775	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Triple Fountain	1st Floor	1	EA	5	10+ years	
	Floor - Tile/Sheet	1st Floor	1,767	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	8	SF	4	1-2 years	Cracked floor
	FIDUI - TIIE/SHEEL	13(1100)	U	EA	7	1-2 years	Cracked 11001



Catego	ry : Interior		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	2,074	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,324	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EΑ	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,324	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	924	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,386	SF	6	10+ years	
	Ceiling - Lay-in	Engineer room corridor	72	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Engineer room corridor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	Engineer room corridor	72	SF	5	2-5 years	
	Lighting - Pendent/Surface	Engineer room corridor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Engineer room corridor	153	SF	6	6-10 years	
	Walls - Plaster/Drywall	Engineer room corridor	10	SF	5	0-1 year	
Safety							
	Security Cameras	1st Floor	2	EA	7	2-5 years	Additional cameras scheduled to be added.
Stairs							
	Ceiling - Lay-in	West Stair	262	SF	7	10+ years	
	Floor - Terrazzo	West Stair	380	SF	7	10+ years	
	Handrails	West Stair	80	LF	7	10+ years	
	Lighting - Lay-in	West Stair	6	EA	7	10+ years	
	Stairs - Terrazzo	West Stair	19	LF	7	10+ years	
	Walls - Structural Glazed Tile	West Stair	1,144	SF	7	10+ years	
						-	



Category : Site **Building: Site**

Catego	iy. Oile			unung	. Oile	Decemmend		
0	Ham Time	Location	Overetite	LIOM	Dank	Recommend	Comments	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Civil/Dra								
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	6	10+ years		
	Civil/ Drainage - Catch Basin	Entire Site	2	EΑ	6	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years		
_Fencing								
Ū	Fencing - Chain Link	Entire Site	200	LF	6	10+ years		
	Fencing - New Standard Ornamental	Entire Site	365	LF	6	6-10 years		
	Fencing - New Standard Ornamental	Entire Site	100	LF	5	1-2 years	Some panels of fencing are corroded,	
					•	,	with no paint left on them	
	Fencing - Old Standard Ornamental	Entire Site	190	LF	6	10+ years		
	Fencing - Old Standard Ornamental	Entire Site	20	LF	5	1-2 years	Broken fences and gates	
	· · · · · · · · · · · · · · · · · · ·				•	,	g	
_Landsca	ine							
	Benches	Entire Site	10	EA	6	6-10 years		
	Landscape - Grass	Entire Site	2,282	SF	6	10+ years		
	Landscape - Hardscape- Concrete	Entire Site	40	SF	7	10+ years	New concrete	
	Landscape - Hardscape - Concrete	Entire Site	3,252	SF	6	10+ years	14CW concrete	
	Landscape - Hardscape- Concrete	Entire Site	500	SF	4	0-1 year	Broken concrete and play area by	
	Landscape - Hardscape- Concrete	Little Site	500	SF	4	0-1 year	door number three	
	Parkway trees	Entire Site	10	EA	6	10+ years	door number timee	
	Parkway trees	Entire Site	4	EA	6	10+ years	One new tree, verified number of	
	1 anway iroos	Entire ofte	7	L/ \	O	101 years	trees on the parkway	
	Parkway trees	Entire Site	1	EA	4	1-2 years	One missing tree	
	Planting Beds/ Area	Entire Site	294	SF	6	10+ years	One missing tree	
	Play Area - Hardscape- Asphalt	Entire Site	4,485	SF	6	10+ years		
	Play Area - Hardscape- Asphalt	Entire Site	20	SF	6	10+ years		
	Retaining Wall - Concrete	Entire Site	290	SF	7	10+ years		
	Retaining Wall - Concrete	Entire Site	40	SF SF	, 5		Several cracks and spalling along the	
	Retaining Wall - Concrete	Entire Site	40	SF	Э	1-2 years		
							entire retaining wall	
Dorking	l ot							
Parking	Concrete Curbs	West	35	LF	6	10+ years		
	Surface - Asphalt	West	35 17,015	SF	7	10+ years 10+ years		
	•			SF SF		•	Laws avails and since of	
	Surface - Asphalt	West	1,000	SF.	6	6-10 years	Large cracks and signs of	
	Surface - Concrete	West	560	SF	7	10+ years	alligatorring	
	Trash Enclosure - Chain Links	West	1,300	SF	7	10+ years		
	Hash Eliciosule - Olidili Elliks	VVGSL	1,300	J.	,	10+ years		
_Playgrou	und							
	Equipment - School Age 5-12	West	1	EA	6	6-10 years		
	Surface - Poured Surface	West	2,250	SF	4	1-2 years	Despite several small and large	
	Tanada Tanada Canada		2,200	٥.	•	jouio	- septio several email and large	



Charles G Hammond Elementary School

2819 W 21st PLACE, Chicago, IL 60623

Catego	Category : Site			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							patches, this playground surface continues to develop new holes, tears and large areas of broken surface
Sidewalk	KS .						
	Sidewalks - Internal Walks	Entire Site	145	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10,635	SF	7	10+ years	
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hammond Page: 28 of 29 Assessment Date: 04/14/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	203	103	840	180	60	N	Υ
Faculty Lounge	Regular Classroom	2nd Floor	204	104	840	180	60		Y
Faculty Lounge	Regular Classroom	2nd Floor	300	Rest Room	370	90	30	N	Y
Kindergarten	Kindergarten	1st Floor	102	Kind.	910	180	60	N	Y
Office	Library	1st Floor	101	Library	555	120	40	N	Y
Regular Classroom	Regular Classroom	1st Floor	201	101	840	180	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	202	102	840	180	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	205	105	840	180	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	301	201	840	180	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	302	202	840	180	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	303	203	840	180	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	304	204	840	180	60	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	305	205	840	180	60	N	Y

Building : Addition									
Computer Lab	Regular Classroom	2nd Floor	206	NA	1,190	171	63	Y	Y
Kindergarten	Other Instructional Use	1st Floor	111	Girls play room	950	96	28	Y	Y
Kindergarten	Regular Classroom	2nd Floor	213	n/a	800	95	35	Υ	Y
Kindergarten	Regular Classroom	2nd Floor	215	n/a	785	114	42	Υ	Υ
Other Instructional Use	Multi Purpose Room	1st Floor	107	Engine Room	470	0	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	n/a	808	114	42	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	208	n/a	800	114	42	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	n/a	800	114	42	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	211	n/a	785	114	42	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	212	n/a	808	114	42	Y	Y
Store Room	Regular Classroom	2nd Floor	210	n/a	800	114	42	Y	Υ