



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	2	12,582
Addition 1	1940	2	15,537
Addition 2	1955	2	6,162
Campus Total			34,281

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	Fire Escape	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Main Entrance #1	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Main Entrance #1	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Main Entrance #1	88	LF	6	10+ years	
	Exterior Stairs - Stone	Main Entrance #1	7	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Main Entrance #1	64	LF	7	10+ years	
Fire Esca	ape						
	Fire Escape	North Façade	28	LF	6	10+ years	
						,	
_Foundati	on						
Cundan	Foundation - Concrete	Entire Building	360	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	12,582	SF	7	10+ years	
	Superstructure Stock with Stay The 7 ton	Entire Dallating	12,002	O.	•	101 youro	
Lighting							
Lighting	Exterior Lighting Derenet or Deef Mounted	Foot Foods	2	EA	6	101 2000	
	Exterior Lighting - Parapet or Roof Mounted	East Façade	2	EA	6	10+ years	
Roof Sys							
	Access Ladder - Metal	A	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	A	42	LF	6	10+ years	
	Liner						

Campus Name: Harte Page : 1 of 29 Assessment Date: 11/22/2021





ALL A							1556 E 56th STREET, Chicago, IL 60637
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Terra Cotta	A	189	LF	7	10+ years	
	Parapet - 16" - 30" Height	A	149	LF	6	10+ years	
	Roof - Modified Bitumen	A	3,865	SF	5	2-5 years	
	Roof Hatch - Metal	A	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Α	3,865	SF	7	10+ years	
	Coping - Terra Cotta	В	44	LF	6	10+ years	
	Parapet - Parapet > 30"	В	44	LF	6	10+ years	
	Roof - Modified Bitumen	В	121	SF	5	2-5 years	No access
	Roof Structure - Steel with Clay Tile Arch	В	121	SF	7	10+ years	
	Coping - Terra Cotta	С	38	LF	6	10+ years	
	Parapet - Parapet > 30"	С	38	LF	6	10+ years	
	Roof - Modified Bitumen	С	88	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	С	88	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	80	SF	7	10+ years	
	Cornice - Terra Cotta	Entire Building	250	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	9,826	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	504	SF	5	6-10 years	
		· ·				•	
Windows	3						
	Guard - Guards perforated	Entire Building	211	SF	6	10+ years	
	Lintels - Steel	Entire Building	19	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	100	LF	7	10+ years	
	Windows - Insulated Panel	Entire Building	131	SF	6	10+ years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	734	SF	6	10+ years	
Catego	ry : Electrical		D	uilding	· Main		
Calego	iy. Liedii Idai		D	unung	. iviaiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System		•				
	Socurity System CCTV	Entiro Building	12 501	SE.	6	6 10 voore	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
Ü	Security System - CCTV	Entire Building	12,581	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	12,581	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,757	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	5	6-10 years	Repaired
Main Se	rvice						
	PA System	Entire Building	34,281	SF	5	6-10 years	A few speakers were replaced, serves all buildings on campus

Campus Name: Harte Page : 2 of 29 Assessment Date: 11/22/2021



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						
<u> TOWELD</u>	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
_			_				
Catego	ry : Fire Protection		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	-	Location	Quantity	COM	raint	Ropidoomont	Commonic
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Recently installed, serves all 3
		3				,	buildings
	Fire Alarm Strobe Lights	Entire Building	12,582	SF	6	10+ years	Recently installed, previously not
	Fire Alarm_System	Entire Building	12,582	SF	7	10+ years	assessed Recently upgraded, connected to
	The Alam_Oystem	Entire Ballating	12,302	Oi	,	10+ years	other buildings
							ű
Catego	ry : Mechanical		В	uilding	: Main		
Croun	Itam Tuna	Lagation	Quantitu	ПОМ	Donk	Recommend	Comments
Group Air Cond	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	3	EA	6	6-10 years	Serve 3 fan coil units in offices
Air Hanc	lling Systems						
All Hand	Air Handling Unit- Built Up- Multi Zone- Hot	Entire Building	1	EA	5	6-10 years	Serves main building and additions,
	Water and Chilled Water Coils - 15001 -	3				, , , , , ,	AHU 1
	25000 cfm						
	Air Intake Return Duct Work - Indoor- Vertical Shaft	Entire Building Entire Building	1 40	EA LF	6 6	10+ years	
	and Ducts	Entire Building	40	LF	6	10+ years	
	Zone Dampers	Entire Building	21	EA	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	3	EA	5	6-10 years	Previously not assessed, in offices
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	6-10 years	RF1
	Type - 10001 - 20000 CFM						
Heating	Devices						
<u></u>	Wall Heater - Electric	Basement	2	EA	6	6-10 years	
						,	
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	6-10 years	Connected to boilers in addition 1
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Ceiling mounted, serves air handler AHU 1
							7410-1

Campus Name: Harte Page : 3 of 29 Assessment Date: 11/22/2021



							1556 E 56th STREET, Chicago, IL 60637
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Tempera	ature Control						
	DDC System Electric Thermostat	Entire Building Entire Building	12,582 3	SF EA	6 5	6-10 years 10+ years	Serves all 3 buildings Serve 3 fan coil units, mini split system, previously not assessed
	Thermostats - DDC	Entire Building	21	EA	6	6-10 years	Serve 21 dampers for AHU 1
Ventilatio	on						
	Roof Mounted Duct Work	Roof	15	LF	5	10+ years	Serves RF 1, previously not assessed
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate		Location	Quantity	OOM	Italik	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	5	6-10 years	Burners cleaned, serves all building on campus, functional
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	12,582	SF	6	6-10 years	There are a few pipe clamps, functional, occasional leaks repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	12,582	SF	6	6-10 years	There are a few pipe clamps, functional
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	12,582	SF	6	6-10 years	There are a few pipe clamps, functional, occasional leaks repaired
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	12,582	SF	6	6-10 years	Minor leaks occasionally repaired, 1930 installation, functional
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	12,582	SF	6	6-10 years	Minor leaks occasionally repaired, functional
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	12,582	SF	6	6-10 years	There are a few pipe clamps, functional, occasional leaks repaired
	Sanitary Piping	Entire Building	12,582	SF	5	6-10 years	•
	Storm Piping	Entire Building	12,582	SF	5	6-10 years	
	Vent Piping	Entire Building	12,582	SF	5	6-10 years	
Catego	ry : Room		В	uilding	: Main		
		Location	Overtite -	LIOM	Donk	Recommend	Comments
Group	Item - Type rative Suites/Offices	Location	Quantity	UOM	Rank	Replacement	Comments
AUIIIIIISI	AC Unit	1st Floor - Main Office	1	EA	4	1-2 years	Only blows air per Engineer. Priority changed to update current observation
	Ceiling - Plaster/Drywall	1st Floor - Main Office	468	SF	7	10+ years	330017411011





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor - Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office	468	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Main Office	12	EA	7	6-10 years	
	Power Distribution	1st Floor - Main Office	8	EA	7	10+ years	
	Storage/ Closet	1st Floor - Main Office	126	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	1,139	SF	7	10+ years	
	Ceiling - Exposed	Basement - Custodial	104	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement - Custodial	1	EA	7	10+ years	
	Floor - Tile	Basement - Custodial	104	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - Custodial	1	EA	7	6-10 years	
	Power Distribution	Basement - Custodial	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Custodial	54	SF	6	10+ years	Wood slat wall
	Walls - Plaster/Drywall	Basement - Custodial	456	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Custodial	10	SF	4	1-2 years	Damaged wood slat walls
	Work SInk	Basement - Custodial	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Basement Engineer's Office	112	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement Engineer's Office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement Engineer's Office	112	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Engineer's Office	2	EA	7	10+ years	
	Power Distribution	Basement Engineer's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Basement Engineer's Office	158	SF	7	10+ years	Not block- concrete walls observed
	Walls - Masonry	Basement Engineer's Office	392	SF	7	10+ years	
	AC Unit	Principals Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals Office	147	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Principals Office	8	SF	6	10+ years	
	Doors - Transom Window	Principals Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principals Office	1	EA	7	10+ years	
	Floor - Tile	Principals Office	155	SF	7	10+ years	
	Lighting - Pendent/Surface	Principals Office	3	EA	7	6-10 years	
	Power Distribution	Principals Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principals Office	578	SF	7	10+ years	
_Lunch &	Multipurpose Room						
	Ceiling - Exposed	Basement	282	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	282	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	5	EA	7	10+ years	
	Walls - Concrete Block	Basement	340	SF	7	10+ years	
	Walls - Masonry	Basement	340	SF	7	10+ years	
	walle Maserily	Basement	0.10	O.	•	101 youro	
_MDF_ID							
	Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
	Finishes	Basement	118	SF	7	10+ years	





Catego	ry : Room		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Window AC Unit	Basement	1	EA	7	6-10 years	
/lechani	cal/ Service Rooms						
	Storage Room	2nd Floor	14	SF	7	10+ years	Space reaccessed as ceiling is apparent and appears to be in goo condition
	Boiler Room	Basement	586	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	130	SF	7	10+ years	
	Storage Room	Basement	759	SF	7	10+ years	
	Storage Room	Basement	294	SF	7	10+ years	
Prep Roo	om						
	Ceiling - Plaster/Drywall	2nd Floor	92	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	6	SF	4	0-1 year	Water damaged, bubbling, peeling
	Doors - Side-lite	2nd Floor	30	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	88	SF	7	6-10 years	
	Floor - Carpet	2nd Floor	10	SF	4	0-1 year	Worn
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
Restroon	n						
	Accessories	103A	17	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103A	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103A	1	EΑ	7	10+ years	
	Floor - Tile	103A	17	SF	7	10+ years	
	Lavatory	103A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	103A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	103A	127	SF	7	10+ years	
	Water Closet	103A	1	EA	7	10+ years	
	Accessories	2nd Floor - Prep Room	18	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Prep Room	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Prep Room	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor - Prep Room	12	SF	6	10+ years	
	Floor - Tile	2nd Floor - Prep Room	6	SF	4	0-1 year	Cracking, worn
	Lighting - Pendent/Surface	2nd Floor - Prep Room	1	ĒΑ	7	6-10 years	<i>5.</i>
	Walls - Plaster/Drywall	2nd Floor - Prep Room	155	SF	6	10+ years	
	Water Closet	2nd Floor - Prep Room	1	EΑ	7	10+ years	
	Accessories	Basement Boys	410	SF	7	6-10 years	
	Ceiling - Lay-in	Basement Boys	366	SF	7	10+ years	
	····································		550	SF	•	,	





Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Basement Boys	36	SF	4	1-2 years	Damaged tiles
	Doors - Wood Doors inclu hw	Basement Boys	1	EA	7	10+ years	
	Floor - Tile/Sheet	Basement Boys	410	SF	7	10+ years	
	Floor Drain	Basement Boys	2	EΑ	7	10+ years	
	Hand Dryer	Basement Boys	2	EA	7	6-10 years	
	Lavatory	Basement Boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys	8	EΑ	7	10+ years	
	Partitions	Basement Boys	4	EA	7	10+ years	
	Urinals	Basement Boys	7	EA	7	10+ years	
	Walls - Concrete Block	Basement Boys	130	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Boys	520	SF	7	10+ years	
	Water Closet	Basement Boys	4	ĒΑ	7	10+ years	
	Accessories	Basement Girls	410	SF	7	6-10 years	
	Ceiling - Lay-in	Basement Girls	410	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Girls	1	EA	7	10+ years	
	Floor - Terrazzo	Basement Girls	410	SF	7	10+ years	
	Floor Drain	Basement Girls	1	EA	7	10+ years	
	Hand Dryer	Basement Girls	2	EA	7	6-10 years	
	Lavatory	Basement Girls	3	EΑ	7	10+ years	
	Lighting - Lay-in	Basement Girls	7	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement Girls	1	EΑ	7	6-10 years	
	Partitions	Basement Girls	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Girls	648	SF	7	10+ years	
	Water Closet	Basement Girls	9	EA	7	10+ years	
	Accessories	Main Office	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	28	SF	7	10+ years	
	Lavatory	Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	7	6-10 years	
	Partitions	Main Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office	169	SF	7	10+ years	
	Water Closet	Main Office	2	EA	7	10+ years	
	Water Closet	Maiir Omoo	_		•	To Tyouro	
Catego	ry : Classroom		В	uilding	: Main		
2				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #003 (Regular Classroom)		•				
	Ceiling - Exposed	Basement	380	SF	7	10+ years	
	Doors - Transom Window	Basement	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	380	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	873	SF	7	10+ years	
	Trans Tidoto/Diywall	Dasomon	073	01	,	TOT years	

Campus Name: Harte Page : 7 of 29 Assessment Date: 11/22/2021





Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #004 (Regular Classroom)						
	Ceiling - Plaster/Drywall	Basement	832	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	832	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EΑ	7	10+ years	
	Walls - Masonry	Basement	1,240	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #103 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	No
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	No
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,321	SF	7	10+ years	
Classroo	om #105 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	801	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	801	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,286	SF	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	803	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	803	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	







Catego	ry : Classroom		В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,321	SF	7	10+ years	
Classroc	m #203 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	806	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	4	0-1 year	Water damage, cracked, peeling
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	813	SF	7	10+ years	
	Floor - Wood	2nd Floor	3	SF	4	0-1 year	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	25	SF	4	0-1 year	Water damage.
	walls - Flastel/Drywall	2110 1 1001	25	31	4	0-1 year	vvater damage.
Classroc	m #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,328	SF	7	10+ years	
Classroo	m #205 (Computer Lab)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	799	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood Boots inclu tiw	2nd Floor	799	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	11	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,165	SF	7	10+ years 10+ years	
				SF EA	7	-	
	Wireless System	2nd Floor	1	ĽΑ	1	10+ years	
Classroc	m #207 (Science Classroom)						
	Casework	2nd Floor	3	LF	7	10+ years	







Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	761	SF	6	10+ years	
	Floor - Wood	2nd Floor	5	SF	4	0-1 year	Damaged, large scratches
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	59	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	5	0-1 year	Holes, damaged
	Work Sink	2nd Floor	1	EA	7	10+ years	-

Building: Main Category: Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor - North	770	SF	7	10+ years	
	Floor - Terrazzo	1st Floor - North	111	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - North	659	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor - North	17	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor - North	30	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor - North	13	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - North	1,947	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - South	328	SF	6	10+ years	
	Doors - Side-lite	1st Floor - South	28	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - South	2	EA	6	10+ years	
	Doors - Transom Window	1st Floor - South	24	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor - South	2	EA	6	10+ years	
	Floor - Terrazzo	1st Floor - South	152	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - South	134	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor - South	4	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor - South	30	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - South	726	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - South	227	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - North	700	SF	6	10+ years	
	Doors - Side-lite	2nd Floor - North	22	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - North	18	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor - North	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor - North	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - North	715	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor - North	5	SF	4	0-1 year	
	Lighting - Pendent/Surface	2nd Floor - North	4	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor - North	5	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor - North	36	LF	7	10+ years	
						=	

Campus Name: Harte Page : 10 of 29 Assessment Date: 11/22/2021





Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Student Lockers - Two Tiers	2nd Floor - North	17	EA	6	10+ years	Previous assessment stated one tier lockers, currently two tier lockers
	Student Lockers - Two Tiers	2nd Floor - North	1	EA	4	0-1 year	Missing door
	Walls - Plaster/Drywall	2nd Floor - North	1,566	SF	6	10+ years	-
	Ceiling - Plaster/Drywall	2nd Floor - South	264	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor - South	259	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor - South	5	SF	4	0-1 year	
	Lighting - Wall Mounted	2nd Floor - South	3	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor - South	34	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - South	600	SF	6	10+ years	
	Ceiling - Exposed	Basement	1,810	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	Basement	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	1,810	SF	7	10+ years	
	Lighting - Wall Mounted	Basement	29	EA	7	6-10 years	
	Walls - Masonry	Basement	1,954	SF	6	10+ years	
Safety							
<u> </u>	Camera Viewing Station	Entire Building	1	EA	7	10+ years	
	Security Cameras	Entire Building	6	EΑ	7	10+ years	
	Security Cameras	Entire Building	10	EA	7	6-10 years	
	•	<u> </u>				,	
Stairs							
	Ceiling - Plaster/Drywall	North	152	SF	6	10+ years	
	Floor - Terrazzo	North	25	SF	6	10+ years	
	Handrails	North	20	LF	5	6-10 years	
	Lighting - Pendent/Surface	North	1	EA	6	10+ years	
	Stairs - Terrazzo	North	104	LF	6	10+ years	
	Walls - Plaster/Drywall	North	303	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	152	SF	6	10+ years	
	Floor - Terrazzo	South	25	SF	6	10+ years	
	Handrails	South	20	LF	5	6-10 years	
	Lighting - Pendent/Surface	South	1	EA	6	6-10 years	
	Stairs - Terrazzo	South	104	LF	6	10+ years	
	Walls - Plaster/Drywall	South	303	SF	6	10+ years	



Category : Exterior			В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance	9								
	Entrance Control - Audio and Video	2	1	EA	7	6-10 years			
	Exterior Doors - Exterior Steel Door	2	2	EA	5	2-5 years			
	Exterior Doors - Transom Lite	2	<u>-</u>	ĒΑ	6	6-10 years			
	Exterior Stairs - Stone	2	7	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	5	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	5	1	EA	5	2-5 years			
	Exterior Stairs - Stone	5	7	LF	5	2-5 years			
									
_Foundat	Foundation - Concrete	Entire Puilding	247	LF	7	10 L VOORS			
		Entire Building	247	SF	7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building		SF SF	7 7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building	15,337	5F	/	10+ years			
_Lighting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years			
Roof Sys	etem								
_rtoor oy.	Coping - Terra Cotta	D	99	LF	6	10+ years			
	Downspouts - Interior Downspouts	D	38	LF	6	10+ years			
	Parapet - 16" - 30" Height	D	99	LF	6	10+ years			
	Roof - Modified Bitumen	D	2,158	SF	5	2-5 years			
	Roof Structure - Steel with Clay Tile Arch	D	2,158	SF	7	10+ years			
	Access Ladder - Metal	Ē	2,130	EA	7	10+ years			
	Chimney - Metal Flue	Ē	45	LF	6	10+ years			
	Coping - Terra Cotta	Ē	81	LF	6	10+ years			
	Downspouts - Interior Downspouts	Ē	28	LF	6	10+ years			
	Parapet - 16" - 30" Height	Ē	37	LF	6	10+ years			
	Parapet - Parapet > 30"	Ē	44	LF	6	10+ years			
	Roof - Modified Bitumen	Ē	2,010	SF	5	2-5 years			
	Roof Hatch - Metal	Ē	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	Ē	2,010	SF	7	10+ years			
	Coping - Terra Cotta	F	14	LF	6	10+ years			
	Parapet - 16" - 30" Height	F	14	LF	6	10+ years			
	Roof - Modified Bitumen	F	49	SF	5	2-5 years			
	Roof Structure - Steel with Clay Tile Arch	F	49	SF	7	10+ years			
	Access Ladder - Metal	G	1	EA	7	10+ years			
	Access Ladder - Wood	Ğ	1	EA	5	2-5 years			
	Coping - Terra Cotta	G	53	LF	6	10+ years			
	Downspouts - Interior Downspouts	Ğ	38	LF	6	10+ years			
	Parapet - 16" - 30" Height	Ğ	53	LF	6	10+ years			
	· 22	-	00		•	,			

Campus Name: Harte Page : 12 of 29 Assessment Date: 11/22/2021







aicge	ory : Exterior		В						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof - Modified Bitumen	G	1,162	SF	5	2-5 years			
	Roof Hatch - Metal	G	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	G	1,162	SF	7	10+ years			
Valls									
Valis	Cornice - Terra Cotta	Entire Building	30	LF	6	10+ years			
	Exterior Walls - Brick	Entire Building	5,292	SF	6	10+ years			
	Exterior Walls - Terra Cotta	Entire Building	232	SF	6	10+ years			
Vindow	s Guard - Guards perforated	Entire Building	261	SF	6	10+ years			
	Lintels - Steel	Entire Building	72	LF	7	10+ years			
	Windows - Insulated Panel	Entire Building	36	SF	7	10+ years			
	Windows - Insulated Faller Windows - Louver	Entire Building	4	SF	7	10+ years			
	Windows - Louvei Windows - Sash Lexan	Entire Building	732	SF	6	10+ years 10+ years			
	Wildows - Gasii Lexaii	Littile building	132	OI.	O	10+ years			
Catego	ry : Electrical		Building : Addition 1						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	ncy System		4007						
_merge	Emergency A/C Power - Gym	1st Floor	2,844	SF	6	10+ years			
	Emergency Battery Packs - Corridors and	Entire Building	18	EA	6	10+ years			
					U	TOT years			
	0 , ,	g	.0			•			
	Stairs	G	_	EA	6	-			
	Stairs Emergency Battery Packs - Gym	Entire Building	2		-	6-10 years			
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms	Entire Building Entire Building	_	EA	6	6-10 years 6-10 years	Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building	2 6 1	EA EA	6 5	6-10 years 6-10 years 6-10 years	Repaired Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building	2 6 1 17	EA EA EA	6 5 5	6-10 years 6-10 years 6-10 years 6-10 years	Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	2 6 1 17 2	EA EA EA	6 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom	Entire Building	2 6 1 17 2 3	EA EA EA EA	6 5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV	Entire Building	2 6 1 17 2 3 15,537	EA EA EA EA SF	6 5 5 5 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection	Entire Building	2 6 1 17 2 3 15,537 15,537	EA EA EA EA SF SF	6555565	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Repaired		
	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV	Entire Building	2 6 1 17 2 3 15,537	EA EA EA EA SF	6 5 5 5 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building	2 6 1 17 2 3 15,537 15,537	EA EA EA EA SF SF	6555565	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Serves all 3 buildings,tested,		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building Mechanical Room	2 6 1 17 2 3 15,537 15,537	EA EA EA EA SF SF EA	65555656	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Repaired Serves all 3 buildings,tested, functional		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building	2 6 1 17 2 3 15,537 15,537	EA EA EA EA SF SF	6555565	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Serves all 3 buildings,tested,		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building Mechanical Room	2 6 1 17 2 3 15,537 15,537	EA EA EA EA SF SF EA	65555656	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Repaired Serves all 3 buildings,tested, functional		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building Mechanical Room	2 6 1 17 2 3 15,537 15,537	EA EA EA SF SF EA	6 5 5 5 5 6 5 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Repaired Serves all 3 buildings,tested, functional Serves all 3 buildings		
Main Se	Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection Automatic Transfer Switch	Entire Building Mechanical Room	2 6 1 17 2 3 15,537 15,537	EA EA EA SF SF EA	6 5 5 5 5 6 5 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Repaired Repaired Repaired Serves all 3 buildings,tested, functional Serves all 3 buildings		

Campus Name: Harte Page: 13 of 29 Assessment Date: 11/22/2021



Category : Electrical

Bret Harte Elementary School 1556 E 56th STREET, Chicago, IL 60637

_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - 100 A	Basement	2	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Basement	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Basement	8	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Basement	1	EΑ	7	10+ years	Functional panels rated 7, 800 A.
	amp						Tested, functional
	Main Distribution Panels - Greater than 600	Basement	2	EA	7	10+ years	1200 A
	amp					•	
	·						
Catego	ry : Fire Protection		В	uilding	: Addition	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	15,537	SF	6	10+ years	Previously not assessed, recently
	i no mann onoso Ligino	Zimio Bananig	10,007	٥.	Ū	ioi youro	installed
	Fire Alarm_System	Entire Building	15,537	SF	6	10+ years	Recently upgraded
	i no mani_oyotom	Entire Ballating	10,007	O.	Ü	101 youro	reconny apgradou
Catego	ry : Mechanical		В	uildina	: Additio	on 1	
Juliogo	i y i moonamour			anding	. / taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	· ·	Location	Quantity	00111	Marin	Ropidoomon	Comments
_Air Hano	ling Systems					0.40	0 188 4 11110
	Air Handling Unit- Built Up- Multi Zone- Hot	Basement	1	EA	6	6-10 years	Serves addition 1, AHU 2
	Water Coils - 15001 - 25000 cfm	_			_		
	Air Intake	Basement	1	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Basement	40	LF	6	6-10 years	
	and Ducts						
	Zone Dampers	Basement	18	EA	6	6-10 years	11 for addition 1, 7 for addition 2
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	10+ years	RF 2
	Type - 10001 - 20000 CFM						
Boiler Sy	rstems						
•	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	10+ years	
	- 2001 - 3000 MBH		_		-	- ,	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Glycol Feed System	Boiler Room	_ 1	EA	5	6-10 years	Manually fed
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	6	10+ years	Serves all 3 buildings on campus,
	Tube- Force Draft- Hot Water Boiler - 2001	= =	_	_, .	J	, . ,	B1, B2
	- 3000 MBH						- · ,
	Water Fill System	Boiler Room	1	EA	6	10+ years	
	Tato. Tim Oyotom	2001 1.00111	'	_, .	Ü	io. jouio	
Heating	Devices						
	Unit Heater - Electric	Boiler Room	1	EA	5	6-10 years	Cleaned, functional
						,	·
Campus	Name: Harte		Page : 14 of 29				Assessment Date: 11/22/2021
Campus I			. ago . 1 1 01 20				7.000001110111 Date. 11/22/2021

Building: Addition 1

Recommend



Catego	ry : Mechanical		В	uilding	: Addition		
		1		11614	ъ.	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
1echan	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	10+ years	Serves air handler AHU 2, ceiling mounted
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	10+ years	Serve boilers
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	Connected to other buildings
empera	ature Control						
•	DDC System	Entire Building	15,537	SF	6	10+ years	Serve all 3 buildings
	Thermostats - DDC	Entire Building	18	EA	6	10+ years	Serve 18 zone dampers at AHU 2
/entilati	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Roof Mounted Duct Work	Entire Building	10	LF	5	10+ years	Serves RF 2
Catego	ory : Plumbing		Building : Addition 1				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	15,537	SF	6	10+ years	Minor leaks occasionally repaired
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,537	SF	6	10+ years	There are a few pipe clamps
	(from Risers to Fixtures)						
	(from Risers to Fixtures) Sanitary Piping	Entire Building	15,537	SF	6	10+ years	
	(from Risers to Fixtures)	Entire Building Entire Building	15,537 15,537	SF SF	6 6	10+ years 10+ years	
	(from Risers to Fixtures) Sanitary Piping						
⊃umps_	(from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building	15,537	SF	6	10+ years	
⊇umps_	(from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building	15,537	SF	6	10+ years	Tested, functional
•	(from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building	15,537 15,537	SF SF EA	6 6	10+ years 10+ years 6-10 years	Tested, functional
Pumps Catego	(from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping Pumps - Sump-Simplex	Entire Building Entire Building	15,537 15,537	SF SF EA	6 6 5	10+ years 10+ years 6-10 years	Tested, functional







	Category : Classroom			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Ceiling - Exposed	Basement	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	730	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	
	Walls - Masonry	Basement	1,068	SF	7	10+ years	
Classro	om #002 (Counseling Room)						
Classice	` ,	Dagament	275	SF	7	10	
	Ceiling - Exposed	Basement	375		7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	375	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	9	EA	7	6-10 years	
	Walls - Masonry	Basement	580	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	193	SF	7	10+ years	
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	784	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	784	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,312	SF	7	10+ years	
Classro	om #102 (Regular Classroom)						
Classice	AC Units	1st Floor	2	EA	7	6-10 years	
		1st Floor	4	LF	7		
	Casework					10+ years	
	Ceiling - Plaster/Drywall	1st Floor	784	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Wood	1st Floor	784	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,269	SF	7	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	

Campus Name: Harte Page : 16 of 29 Assessment Date: 11/22/2021





Catego	ry : Classroom		В	uilding	: Addition	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	801	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	801	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,193	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	773	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	cracked, peeling
	Chalk Board	2nd Floor	20	LF	4	2-5 years	cracked, peeling
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
			1	EA	7	•	
	Doors - Wood Doors inclu hw	2nd Floor	•	SF		10+ years	
	Floor - Wood	2nd Floor	773		7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	cracked, peeling
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	793	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	793	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	801	SF	7	10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor	9	SF	7		
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	7	10+ years	
						10+ years	
	Floor - Wood	2nd Floor	798	SF	6	10+ years	Damarad
	Floor - Wood	2nd Floor	3	SF	4	0-1 year	Damaged

Campus Name: Harte Page : 17 of 29 Assessment Date: 11/22/2021







Category : Classroom					Building : Addition 1				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	9	SF	5	2-5 years			
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	10+ years			
Categor	ry : Room		В	uilding	: Additi	on 1			
			0	11014	.	Recommend	•		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Gymnasia									
	Ceiling - Plaster/Drywall	1st Floor	1,880	SF	7	10+ years			
	Doors - Transom Window	1st Floor	36	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years			
	Floor - Wood	1st Floor	1,880	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years			
	Sound System	1st Floor	1	EA	7	10+ years			
	Stage	1st Floor	232	SF	7	10+ years			
	Stage Curtain	1st Floor	10	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	10+ years			
	Stage-Stairs - Asphalt	1st Floor	34	LF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	730	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	3,121	SF	7	10+ years			
Kitchen									
	Ceiling - Plaster/Drywall	Basement	578	SF	7	10+ years			
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years			
	Floor - Tile	Basement	578	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	5	EA	7	6-10 years			
	Serving Line	Basement	12	LF	7	10+ years			
	Walls - Concrete Block	Basement	484	SF	7	10+ years			
	Walls - Masonry	Basement	484	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement	120	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement	48	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Exposed	Basement	1,056	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years			
	Floor - Tile	Basement	1,056	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	12	EA	7	10+ years			
	Walls - Masonry	Basement	682	SF	7	10+ years			
Mechanic	cal/ Service Rooms								
	Janitor's Closet	2nd Floor	61	SF	7	10+ years	Second floor		
	Boiler Room	Basement	800	SF	7	10+ years	Boiler Room		
	DOILET LYOUTH	Dascilicili	800	S⊢	,	TOT years	Polici I/Oom		

Campus Name: Harte Page : 18 of 29 Assessment Date: 11/22/2021





Category : Room			В	Building : Addition 1				
			•			Recommend	•	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Mechanical/ Service Rooms	Basement	700	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	200	SF	7	10+ years		
	Storage Room	Basement	418	SF	7	10+ years	In Main Building, not Addition	

Category: Interior Building: Addition 1

						Recommend	
р	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
or							
	Ceiling - Plaster/Drywall	1st Floor South	681	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor South	2	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor South	2	EA	6	10+ years	
	Floor - Terrazzo	1st Floor South	182	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor South	499	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor South	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor South	1,841	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor South	270	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor West	700	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor West	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor West	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor West	700	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor West	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor West	1,771	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor South	661	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor South	4	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor South	661	SF	7	10+ years	
	Lighting - Wall Mounted	2nd Floor South	9	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor South	17	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor South	1,470	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor West	705	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor West	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor West	705	SF	4	0-1 year	Cracking
	Lighting - Wall Mounted	2nd Floor West	16	ĒΑ	7	6-10 years	3
	Student Lockers - Two Tiers	2nd Floor West	48	EA	6	10+ years	
	Student Lockers - Two Tiers	2nd Floor West	3	EA	5	0-1 year	
	Walls - Plaster/Drywall	2nd Floor West	1,151	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South Stairs Corridor	178	SF	7	10+ years	
	Doors - Steel Doors incl hw	South Stairs Corridor	2	EΑ	7	10+ years	
	Floor - Terrazzo	South Stairs Corridor	178	SF	7	10+ years	
	Lighting - Wall Mounted	South Stairs Corridor	3	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	South Stairs Corridor	26	LF	7	10+ years	
	Walls - Plaster/Drywall	South Stairs Corridor	435	SF	7	10+ years	
	Walls - Structural Glazed Tile	South Stairs Corridor	135	SF	7	10+ years	

Stairs



Catego	Category : Interior			Building : Addition 1					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	North	177	SF	7	10+ years			
	Floor - Epoxy/ Painted	North	67	SF	7	10+ years			
	Floor - Terrazzo	North	188	SF	7	10+ years			
	Floor - Tile/Sheet	North	144	SF	7	10+ years			
	Handrails	North	123	LF	7	10+ years			
	Lighting - Pendent/Surface	North	2	EA	7	6-10 years			
	Lighting - Wall Mounted	North	6	EA	7	6-10 years			
	Stairs - Terrazzo	North	223	LF	7	10+ years			
	Walls - Plaster/Drywall	North	2,008	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South	223	SF	7	10+ years			
	Floor - Epoxy/ Painted	South	77	SF	7	10+ years			
	Floor - Terrazzo	South	117	SF	7	10+ years			
	Floor - Tile/Sheet	South	65	SF	7	10+ years			
	Handrails	South	127	LF	7	10+ years			
	Lighting - Pendent/Surface	South	2	EA	7	6-10 years			
	Lighting - Wall Mounted	South	5	EA	7	6-10 years			
	Stairs - Terrazzo	South	221	LF	7	10+ years			
	Walls - Plaster/Drywall	South	1,881	SF	6	10+ years			



Category: Exterior **Building: Addition 2** Recommend Location Replacement Item - Type Quantity **UOM** Comments Group Rank Entrance 3 FΑ Exterior Doors - Exterior Wood Door 1 4 0-1 year Severe pealing throughout 3 3 LF 7 Exterior Stairs - Stone 10+ years Entrance Control - Audio and Video 4 1 EΑ 6 6-10 years Missed in prior assessment Exterior Doors - Exterior Steel Door 4 2 EΑ 6 10+ years Foundation LF 7 Foundation - Concrete Entire Building 243 10+ years Superstructure - Concrete **Entire Building** 6.162 SF 7 10+ years _Liahtina Exterior Lighting - Parapet or Roof Mounted 3 EΑ 7 **Entire Building** 10+ years Roof System Access Ladder - Metal Н 2 EΑ 7 10+ years LF Coping - Stone Η 198 6 10+ years **Downspouts - Exterior Downspouts** Н 30 LF 6 10+ years Parapet - 16" - 30" Height LF Н 198 6 10+ years Roof - Modified Bitumen Н SF 5 2-5 years 3.081 7 Roof Hatch - Metal Н EΑ 10+ years Roof Structure - Steel with Clay Tile Arch Н SF 3.081 10+ years Walls Exterior Walls - Brick **Entire Building** 5.073 SF 6 10+ years Windows Lintels - Steel **Entire Building** 129 LF 7 10+ years SF Windows - Insulated Panel **Entire Building** 324 6 10+ years SF Windows - Sash Lexan/ Glass Double-pane **Entire Building** 642 10+ years Category: Electrical **Building: Addition 2** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Emergency System Exit Signs - Corridors and Stairs **Entire Building** 2 EΑ 5 6-10 years Repaired Emergency Battery Packs - Corridors and EΑ **Entire Building** 1 6 6-10 years Stairs Emergency Battery Packs - Students Toilets **Entire Building** EΑ 6 6-10 years Emergency A/C Power - Corridors and SF **Entire Building** 980 6 10+ years Stairs Security System - CCTV **Entire Building** 6,162 SF 6 6-10 years

Campus Name: Harte Page : 21 of 29 Assessment Date: 11/22/2021



							1556 E 56th STREET, Chicago, IL 60
Catego	ry : Electrical	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	6,162	SF	6	6-10 years	
Main Ser	vice						
	PA System	Entire Building	6,162	SF	5	6-10 years	Connected to 2 other buildings,
	·	· ·				·	previously not assessed
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Previously not assessed
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Previously not assessed
		· ·				•	•
Catego	ry : Fire Protection		В	uilding	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	6,162	SF	6	10+ years	Recently installed
	Fire Alarm_System	Entire Building	6,162	SF	7	10+ years	Recently upgraded
Catego	ry : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	Connect to boiler in addition 1,
	,,	<u> </u>				•	previously not assessed
Tempera	ture Control						
·	DDC System	Entire Building	6,162	SF	6	10+ years	Served from main building
	Thermostats - DDC	Entire Building	7	EA	6	10+ years	Air handler in addition 1. See
							dampers in building 1
Ventilatio	on						
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	
	500 CFM						
Catego	ry : Plumbing		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	6,162	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	6,162	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	6,162	SF	6	10+ years	

Campus Name: Harte Page : 22 of 29 Assessment Date: 11/22/2021



Category : Plumbing

Bret Harte Elementary School 1556 E 56th STREET, Chicago, IL 60637

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,162	SF	6	10+ years	Minor leaks occasionally repaired
	(Horizontal Lines)				_		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	6,162	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,162	SF	6	10+ years	There are a few pipe clamps
	(from Risers to Fixtures)	Fination Dividalina	0.400	C.E.	•	40	
	Sanitary Piping	Entire Building	6,162	SF	6	10+ years	
	Storm Piping	Entire Building	6,162	SF	6	10+ years	
	Vent Piping	Entire Building	6,162	SF	6	10+ years	
atego	ry : Room		В	uilding	: Additio		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	7.	Location	Quantity	OCIVI	Naiik	Replacement	Comments
Janninisti	rative Suites/Offices	4 of Floor Adirectors at Decom			7	0.40	
	AC Unit	1st Floor - Adjustment Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Adjustment Room	268	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Adjustment Room	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Adjustment Room	268	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Adjustment Room	6	EA	7	6-10 years	
	Power Distribution	1st Floor - Adjustment Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Adjustment Room	633	SF	7	10+ years	
	AC Unit	2nd Floor - Teachers Lounge	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Lounge	245	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - Teachers Lounge	243	SF	6	10+ years	
	Floor - Tile	2nd Floor - Teachers Lounge	2	SF	4	0-1 year	Cracked, chipped
	Lighting - Pendent/Surface	2nd Floor - Teachers Lounge	3	EΑ	7	6-10 years	, 11
	Power Distribution	2nd Floor - Teachers Lounge	4	ΕA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teachers Lounge	845	SF	7	10+ years	
ibrary							
Didiy	AC Unit	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	120	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	910	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Carpet	2nd Floor	835	SF	7	6-10 years	
	Floor - Tile	2nd Floor	75	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	25	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	954	SF	7	10+ years	
1echani	cal/ Service Rooms						
Condition	Janitor's Closet	1st Floor	12	SF	5	6-10 years	
	Janitor's Closet	Janitor's closet	12	SF	7	10+ years	Second floor

Building: Addition 2

Campus Name: Harte Page : 23 of 29 Assessment Date: 11/22/2021





atego	ry : Room		В	uilding	: Additi	on 2	
					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
estroor	n						
	Accessories	109A	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109A	19	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A	1	EA	7	10+ years	
	Floor - Tile	109A	19	SF	7	10+ years	
	Lighting - Pendent/Surface	109A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	109A	160	SF	7	10+ years	
	Water Closet	109A	1	EA	7	10+ years	
	Accessories	1st Floor - Next to 108	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Next to 108	42	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Next to 108	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Next to 108	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Next to 108	50	SF	7	10+ years	
	Lavatory	1st Floor - Next to 108	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Next to 108	1	EA	7	6-10 years	
	Partitions	1st Floor - Next to 108	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Next to 108	219	SF	7	10+ years	
	Water Closet	1st Floor - Next to 108	1	EA	7	10+ years	
		1st Floor - Next to 109	35	SF	7	,	
	Accessories Ceiling - Plaster/Drywall	1st Floor - Next to 109	35	SF	7	6-10 years	
	Doors - Wood Doors inclu hw		35	EA	7	10+ years	
		1st Floor - Next to 109	-		-	10+ years	
	Floor - Tile	1st Floor - Next to 109	35	SF	7	10+ years	
	Lavatory	1st Floor - Next to 109	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Next to 109	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Next to 109	168	SF	7	10+ years	
	Water Closet	1st Floor - Next to 109	1	EA	7	10+ years	
	Accessories	2nd Floor	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	32	SF	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	171	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor - Teachers Lounge	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Lounge	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - Teachers Lounge	28	SF	4	1-2 years	damaged, worn tile throughout
	Lavatory	2nd Floor - Teachers Lounge	1	ĒΑ	7	10+ years	<i>y</i> ,
	Lighting - Pendent/Surface	2nd Floor - Teachers Lounge	1	EA	7	6-10 years	
	Partitions	2nd Floor - Teachers Lounge	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teachers Lounge	148	SF	7	10+ years	





XXX S	CITOOIS						1556 E 56th STREET, Chicago, IL 60637
Categor	ry : Room		В	uilding	: Addition	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Water Closet	2nd Floor - Teachers Lounge	1	EA	7	10+ years	
0-1	Ola sama and		_		A .1.1'4'	0	
Categor	ry : Classroom		В	uilding	: Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OOW	Italik	Replacement	Comments
Classroo	m #108 (Regular Classroom)						
	AC Units	1st Floor		EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	848	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	963	SF	7	10+ years	
Classroo	m #109 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	848	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,151	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Clasaras	m #200 (Bagular Classroom)						
Classioo	m #208 (Regular Classroom)	0-15	4	Ε,	7	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	848	SF	7	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,143	SF	7	10+ years	
Categoi	ry : Interior		В	uildina	: Additio	on 2	
Julogoi	,			anamg	. , taditi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	350	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	

Campus Name: Harte Page : 25 of 29 Assessment Date: 11/22/2021



Catego	ry : Interior	·	В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	1st Floor	345	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	5	SF	4	0-1 year	Damaged flooring
	Lighting - Wall Mounted	1st Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	879	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	364	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	364	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	20	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	620	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	East	226	SF	6	10+ years	
	Floor - Terrazzo	East	202	SF	6	10+ years	
	Handrails	East	51	LF	7	10+ years	
	Lighting - Pendent/Surface	East	2	EA	6	6-10 years	
	Stairs - Terrazzo	East	85	LF	6	10+ years	
	Walls - Plaster/Drywall	East	1,075	SF	6	10+ years	
	Walls - Structural Glazed Tile	East	147	SF	6	10+ years	

Campus Name: Harte Page : 26 of 29 Assessment Date: 11/22/2021



Category : Site Building : Site

Catego	ry : Site		Building : Site							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Civil/Dra										
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years				
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years				
Fencina										
ŭ	Fencing - Chain Link	Entire Site	105	LF	6	6-10 years				
	Fencing - New Standard Ornamental	Entire Site	110	LF	7	10+ years				
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	70	LF	7	10+ years				
Landsca	pe									
	Landscape - Hardscape- Concrete	East	755	SF	7	10+ years				
	Parkway trees	East	1	EA	7	10+ years				
	Planting Beds/ Area	East	125	SF	6	10+ years				
	Play Area - Hardscape- Asphalt	East	4,564	SF	7	10+ years				
	Trash Receptacles	East	3	EA	7	10+ years				
Parking	Lot									
· ·	Concrete Curbs	Parking Lot- North	200	LF	7	10+ years				
	Pavers	Parking Lot- North	380	SF	7	10+ years				
	Trash Enclosure - Chain Links	Parking Lot- North	78	SF	6	6-10 years				
Playgrou	und									
, ,	Equipment - Combo 3-12	North	1	EA	7	10+ years				
	Surface - Poured Surface	North	2,423	SF	6	2-5 years				
	Surface - Poured Surface	North	10	SF	4	0-1 year	Holes			
	Equipment - Combo 3-12	South	1	EA	7	10+ years				
	Surface - Poured Surface	South	2,457	SF	7	10+ years				
Sidewall	ks									
	Sidewalks - Internal Walks	South	250	LF	7	10+ years				
	Sidewalks - Perimeter Sidewalks	South	3,078	SF	7	10+ years	sidewalks repaired			
Signage										
<u> </u>	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years				
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years				

Campus Name: Harte Page: 27 of 29 Assessment Date: 11/22/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.







Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Harte Page: 28 of 29 Assessment Date: 11/22/2021





Classroom Summary

Classroom Summary									
			_	Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					+				
Computer Lab	Regular Classroom	2nd Floor	205	203	810	150	75	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	105	103	810	150	75	Υ	Υ
Pre School	Pre School	1st Floor	103	101	825	150	75	Υ	Υ
Regular Classroom	Faculty Lounge	Basement	003	003	380	24	24	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	104	825	150	75	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	201	816	150	75	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	202	810	150	75	Y	Υ
Regular Classroom	Regular Classroom	Basement	004	004	832	36	36		
Science Classroom	Regular Classroom	2nd Floor	207	204	766	120	60	Υ	Υ
Building : Addition 1									
Art Room	Library	Basement	001	Bsmt.	730	18	18	N	N
				Library					
Counseling Room	Library	Basement	002	N/A	375	12	12	N	N
Regular Classroom	Regular Classroom	1st Floor	101	115	793	150	75	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	102	114	793	150	75	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	106	110	810	150	75	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	208	802	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	208	802	150	75	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	204	810	150	75	N	Υ
			•	•	•	•		•	
Building : Addition 2									
Kindergarten	Kindergarten	1st Floor	109	111	848	180	90	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	108	110	848	180	90	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	212	848	180	90	Υ	Υ