

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1902	3	62,100
Addition-Gymnasium/auditorium	1913	2	7,750
Campus Total			69,850

Category : Exterior Building : Main

atego	I Y . Exterior		unung				
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
trance	• •	Location	Quantity	OCIVI	Italik	Replacement	Comments
шансе	Entrance Control - Audio and Video	1 - E	1	EA	5	2-5 years	Outdated
	Exterior Doors - Exterior Steel Door	1 - E	3	EΑ	6	10+ years	Culturiou
	Exterior Doors - Side lite	1 - E	6	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	1 - E	3	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - E	30	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	10 - E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2 - SE	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	2 - SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	2 - SE	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3 - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 - NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	3 - NE	6	LF	6	10+ years	
	Exterior Doors - Store Front	5 - S	4	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 - SW	2	EA	5	0-1 year	Rusted around edges and graffit
	Exterior Stairs - Concrete	6 - SW	5	LF	7	10+ years	0 0
	Exterior Doors - Exterior Steel Door	7 W - Boiler Rm	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	7 W - Boiler Rm	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	8 - NW	1	EA	6	10+ years	
	Exterior Doors - Side lite	8 - NW	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	8 - NW	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	A2/A3 - Fire Escape Doors	2	EA	6	6-10 years	Doors Marked A2 and A3 on Site
	Exterior Doors - Side lite	A2/A3 - Fire Escape Doors	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	A2/A3 - Fire Escape Doors	2	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	A2/A3 - Fire Escape Doors	10	LF	6	6-10 years	
re Esc	ape						
	Fire Escape	West Façade	80	LF	5	6-10 years	
oundati	on						
	Foundation - Concrete	Entire Building	948	LF	6	10+ years	
	Superstructure - Heavy Timber	Entire Building	62,100	SF	7	10+ years	
ghting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years	
oof Sys	stem						
,	Access Ladder - Metal	A	2	EA	7	10+ years	
	Coping - Clay Tile	A	207	LF	6	10+ years	
	Coping - Terra Cotta	A	382	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	60	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	180	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	489	LF	6	10+ years	
	Parapet - Parapet > 30"	A	100	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	A	14,033	SF	4	0-1 year	Per site engineer leaks in various spots. Missing gravel in spots.
	Roof Hatch - Metal	Α	1	EA	4	1-2 years	Hatch is aged/misaligned/bent. Sits on opening acting as a cover as opposed to being an actual roof ha
	Roof Structure - Heavy Timber	A	14,033	SF	7	10+ years	
	Access Ladder - Metal	В	2	ĒΑ	7	10+ years	
	Coping - Stone	В	56	LF	6	10+ years	
	Downspouts - Exterior Downspouts	В	8	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	56	LF	6	10+ years	
	Roof - Modified Bitumen	В	368	SF	5	10+ years	
	Roof Structure - Steel / Metal Deck/	В	368	SF	7	10+ years	
	Concrete Topping Chimney - Brick Chimney- Concrete/ Mortar Liner	С	70	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	С	5	LF	5	2-5 years	
	Liner	0	000		0	40	
	Coping - Clay Tile	C	386	LF	6	10+ years	
	Downspouts - Exterior Downspouts	С	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	С	386	LF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	С	4,688	SF	4	0-1 year	Leaks, bubbling, blistering, vegetat growth.



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Concrete	С	4,688	SF	7	10+ years	
\A/-II-							
Walls	Cornice - Metal Projecting	Entire Building	373	LF	5	2-5 years	Rust/Corrosion
	Exterior Walls - Brick	Entire Building	19,543	SF	6	10+ years	Rusi/Corrosion
	Exterior Walls - Brick	Entire Building	2,025	SF	4	0-1 year	Open joints and deteriorated mortar.
	EXTERIOR WAIIS - DRICK	Entire building	2,023	SF	4	0-1 year	Stepped Cracking in brick/mortar. Shifting/Displaced brick wall. Graffiti.
	Exterior Walls - Stone-Cast	Entire Building	1,520	SF	5	10+ years	G
	Exterior Walls - Stone-Cut	Entire Building	400	SF	5	10+ years	
		· ·				•	
Window							
	Guard - Guards perforated	Entire Building	1,553	SF	6	6-10 years	
	Lintels - Steel	Entire Building	284	LF	6	10+ years	Quantity Adjusted
	Lintels - Steel	Entire Building	6	LF	4	0-1 year	Rust/Corrosion w/major deflection.
	Lintels - Stone	Entire Building	325	LF	6	10+ years	
	Windows - Decorative	Entire Building	72	SF	6	6-10 years	
	Windows - Louver	Entire Building	24	SF	6	6-10 years	Rust/Bent vanes
	Windows - Sash Aluminum Double-pane	Entire Building	5,315	SF	5	6-10 years	
Catama	w Fleetwicel		В	: a : a	. Main		
Catego	ry : Electrical		В	uilding	: wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System		•			•	
- 5	UPS - Less than 30 KW	Electrical Room	1	EA	4	1-2 years	Batteries are more than 5 years Old. UPS To be removed in 2022.
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Serves UPS, UPS batteries not charged.
	Automatic Transfer Switch	Electrical Room	1	EΑ	6	6-10 years	Serves UPS, UPS batteries not
			· ·		Ü	o .o you.o	charged.
	Automatic Transfer Switch	Electrical Room	1	EA	4	1-2 years	charged.
	Automatic Transfer Switch Security System - Intrusion Detection	Electrical Room Entire Building	·		-	-	charged. Deteriorated, serves second feed, not
	Security System - Intrusion Detection		1	EA	4	1-2 years 6-10 years	charged. Deteriorated, serves second feed, not
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs	Entire Building Entire Building	62,100 16	EA SF EA	4 6 6	1-2 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom	Entire Building Entire Building Entire Building	1 62,100	EA SF EA EA	4 6 6 6	1-2 years 6-10 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not reliable.
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Emergency A/C Power - Auditoium and	Entire Building Entire Building	62,100 16 3	EA SF EA	4 6 6	1-2 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and	Entire Building Entire Building Entire Building Entire Building	62,100 16 3	EA SF EA EA EA	4 6 6 6 6	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not reliable. Bulb replaced
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 62,100 16 3 1 3,000	SF EA EA SF SF	4 6 6 6 6 6	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not reliable. Bulb replaced Previously not assessed
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 62,100 16 3 1 3,000 10,766 2,200	EA SF EA EA SF SF	4 6 6 6 6 6	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not reliable. Bulb replaced
	Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 62,100 16 3 1 3,000	SF EA EA SF SF	4 6 6 6 6 6	1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	charged. Deteriorated, serves second feed, not reliable. Bulb replaced Previously not assessed

Campus Name: Jungman Page : 3 of 29 Assessment Date: 04/21/2022



Catego	ry : Electrical		В	uilding	: Main		
calogo			_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. ор	Emergency Battery Packs - Corridors and	Entire Building	3	EA	6	6-10 years	Mounted at the back of exit signs,
	Stairs	g	_			- · · · · · · · · · · · · · · · · · · ·	add on,recently installed.
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	,,,,
	g,,	9	_			,	
Main Se	rvice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years	Serves main and addition buildings
	120/208/3PH		·		· ·	,	correct mann and dadmen bananige
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	Second feed, ATS and second meter
	emergency power		·			- · · · · · · · · · · · · · · · · · · ·	, , , , , , , , , , , , , , , , , , , ,
	PA System	Entire Building	62,100	SF	6	6-10 years	Connected to addition
	,	3	,			,	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	EM panel
	Lighting and Power Panels - 100 A	Entire Building	7	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	8	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Serviced and repaired.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EΑ	7	10+ years	
	1.5.1.0.0.1.1.0.0	g	·	_, .	-	.o. you.o	
Catego	ry : Fire Protection		В	uilding	: Main		
_			0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar		Fating Desilations		Ε.Δ		40	One control and addition building
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves main and addition building.
	Fire Alarm Strobe Lights	Entire Building	62,100	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	62,100	SF	6	6-10 years	Connected to addition building
	Fire Pump Controller	Entire Building	1	EA	4	1-2 years	More than 40 years old, not reliable
Dumn D	oom Assembly						
_unp N	Fire Pump - 25-50 hp	Pump Room	1	EA	4	1-2 years	Deteriorated, not reliable
	File Fullip - 25-50 lip	Fullip Room	ı	EA	4	1-2 years	Deteriorated, not reliable
Sprinklei	System						
	Dry Sprinkler System	Entire Building	62,100	SF	5	2-5 years	
	Sprinkler Heads	Entire Building	62,100	SF	2	1-2 years	Older than 50 years old.
	Sprinkler Piping	Entire Building	62,100	SF	6	6-10 years	
3 - 4 :	ma Marahanian	-	_		B	•	
	ry : Mechanical	Lasation		uilding		Danam	Commonto
Jroup	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



						1740 0 Miller OTTLET, Officago, in 0000
					Replacement	
Nir Conditioning Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	10+ years	Serves STEM lab fan coil unit
ir Handling Customs						
sir Handling Systems Fan Coil Unit- Celing Mounted - Electric	3rd floor STEM video lab	1	EA	6	10+ years	Serves STEM lab on third floor
Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves STEIN IAD OIT HING 11001
Air Intake	Mechanical Room	2	EA	5	6-10 years	Dampers cleaned and lubricated, functional. Intake on roof not painte
Auxiliaries - 15000 - 30000 cfm	Mechanical Room	1	EA	5	6-10 years	
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	6-10 years	Common return, functional
Zone Dampers	Mechanical Room	6	EA	5	6-10 years	Functional
Zone Dampers	Mechanical Room	23	EA	5	6-10 years	Manually operated, functional. BAS control issue
Boiler Systems						
Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	4	1-2 years	Old, deteriorated, scheduled for replacement.
Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
Combustion Dampers	Boiler Room	2	EA	6	6-10 years	Two dampers serve two boilers.
Condensate Pump	Boiler Room	1	EA	5	6-10 years	
Condensate Pump	Boiler Room	1	EA	5	6-10 years	
Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	4	1-2 years	Requires frequent repair, deteriorated, serves main and addition building, scheduled for replacement.
Piping - Condensate Pipe- Steel	Boiler Room	150	LF	5	6-10 years	
Piping - Steam Pipe- Steel	Boiler Room	150	LF	5	6-10 years	
Steam Traps	Boiler Room	18	EA	5	6-10 years	
leating Devices						
Cabinet Heaters - With Electric Coil	Basement	1	EA	6	6-10 years	Ceiling mounted
Unit Heater - Steam	Basement restroom	1	EA	5	2-5 years	
Unit Heater - Steam	Boiler Room	1	EA	5	2-5 years	Functional
Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	
Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Thermostat replaced
emperature Control						
Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves STEM lab fan coil unit
Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serves unit heater, and exhaust far



					Danlasamant	1740 & Willief & TREET, Grillouge, ie 0000
					Replacement	
Pneumatic System	Entire Building	62,100	SF	4	1-2 years	previously not assessed. Leaks, mostly manually controlled dampers.
Thermostats - Pneumatic	Entire Building	10	EA	4	1-2 years	Deteriorated, not calibrated, some leak.
Thermostats - Pneumatic	Entire Building	20	EA	4	1-2 years	Leak, temperatures are manually controlled at dampers.
Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	Ceiling mounted
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Ceiling mounted
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	0-1 year	Repaired, but still noisy, not balanced.
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	4	0-1 year	Noisy, not ballanced
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	3	0-1 year	No cover. Scheduled to be replaced
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	7	EA	5	6-10 years	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	4	0-1 year	Noisy, not balanced.
Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression
Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	Above recently removed dishwashe in kitchen area, functional.
Category : Plumbing		Rı	uildina :	· Main		

Category : Plumbing

Building : Main

Group Hot Wat	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_HOL WAI	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Deteriorated, old, still functional, not reliable, serves main building only. No plumbing in gym/auditorium building.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	62,100	SF	6	2-5 years	There are a few pipe clamps
	Domestic Piping-Hot Water Return Risers	Entire Building	62,100	SF	6	2-5 years	Minor leaks occasionally repaired
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	62,100	SF	6	2-5 years	Functional



Catego	ry : Plumbing		В	uilding	_		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	62,100	SF	6	2-5 years	More than 100 years old
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	62,100	SF	6	2-5 years	Minor leaks occasionally repaired
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	62,100	SF	6	2-5 years	Minor leaks are occasionally repaired
	Sanitary Piping	Entire Building	62,100	SF	5	2-5 years	Minor leaks occasionally repaired
	Storm Piping	Entire Building	62,100	SF	5	2-5 years	Functional, occasionally repaired
	Vent Piping	Entire Building	62,100	SF	5	2-5 years	Vent pipes, no leaks, minor corrosion.
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Tank Room	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Tank Room	1	EA	6	6-10 years	Under elevator

Category: Room **Building: Main**

Craun	Hom Tune	Lagation	Quantitu	ПОМ	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Exposed	003	520	SF	6	10+ years	
	Doors - Wood Doors inclu hw	003	5	EA	7	10+ years	
	Floor - Wood	003	520	SF	6	10+ years	
	Lighting - Pendent/Surface	003	10	EA	7	6-10 years	
	Power Distribution	003	10	EA	7	10+ years	
	Storage/ Closet	003	12	SF	7	10+ years	
	Walls - Plaster/Drywall	003	920	SF	6	10+ years	
	Ceiling - Exposed	006	242	SF	6	10+ years	
	Doors - Wood Doors inclu hw	006	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	006	242	SF	7	10+ years	
	Lighting - Pendent/Surface	006	3	EA	7	10+ years	
	Power Distribution	006	2	EA	7	10+ years	
	Walls - Masonry	006	320	SF	7	10+ years	
	Walls - Plaster/Drywall	006	320	SF	6	10+ years	
	Ceiling - Lay-in	202	468	SF	7	10+ years	
	Doors - Steel Doors incl hw	202	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	202	2	EA	7	10+ years	
	Floor - Tile	202	468	SF	7	6-10 years	
	Lighting - Lay-in	202	6	EA	7	6-10 years	
	Power Distribution	202	2	EA	7	10+ years	
	Walls - Plaster/Drywall	202	1,100	SF	7	10+ years	
	Ceiling - Lay-in	Basement - 009	280	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - 009	1	EA	7	10+ years	
	Floor - Tile	Basement - 009	270	SF	7	6-10 years	
	Floor - Tile	Basement - 009	10	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	Basement - 009	5	EA	7	10+ years	

Campus Name: Jungman Page : 7 of 29 Assessment Date: 04/21/2022



Category : Room		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Basement - 009	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - 009	608	SF	7	10+ years	
	Ceiling - Exposed	Basement - Engineer	143	SF	6	10+ years	
	Doors - Transom Window	Basement - Engineer	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer	1	EΑ	7	10+ years	
	Floor - Concrete	Basement - Engineer	143	SF	5	0-1 year	Visible cracks
	Lighting - Pendent/Surface	Basement - Engineer	2	EA	7	10+ years	
	Power Distribution	Basement - Engineer	2	EA	7	10+ years	
	Walls - Masonry	Basement - Engineer	320	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym	301	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym	5	SF	5	0-1 year	Damaged gypsum ceiling
	Doors - Side-lite	Gym	64	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym	1	EA	7	10+ years	
	Floor - Wood	Gym	306	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym	5	EA	7	10+ years	
	Power Distribution	Gym	2	EΑ	7	10+ years	
	Walls - Masonry	Gym	180	SF	7	10+ years	
	Walls - Plaster/Drywall	Gym	180	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years	
	Floor - Tile	Kitchen	70	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen	1	EA	7	10+ years	
	Power Distribution	Kitchen	2	EA	7	10+ years	
	Walls - Concrete Block	Kitchen	240	SF	6	10+ years	
	Walls - Plaster/Drywall	Kitchen	100	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Principal office	272	SF	7	10+ years	
	Doors - Side-lite	Principal office	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal office	2	EA	7	10+ years	
	Floor - Carpet	Principal office	272	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal office	8	EA	7	6-10 years	
	Power Distribution	Principal office	13	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal office	594	SF	7	10+ years	
	AC Unit	main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	main office	303	SF	7	10+ years	
	Ceiling - Plaster/Drywall	main office	20	SF	5	0-1 year	Water damage.
	Doors - Side-lite	main office	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	main office	2	EA	7	10+ years	
	Floor - Tile	main office	313	SF	7	6-10 years	
	Floor - Tile	main office	10	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	main office	8	EA	6	6-10 years	
	Power Distribution	main office	18	EA	7	10+ years	
	Walls - Plaster/Drywall	main office	648	SF	7	10+ years	
	Ceiling - Plaster/Drywall	work room -main office	96	SF	7	10+ years	
	Floor - Tile	work room -main office	96	SF	7	6-10 years	
						- -	



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	work room -main office	2	EA	7	6-10 years	
	Power Distribution	work room -main office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	work room -main office	360	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	872	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	3	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	862	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	10	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	Basement	19	ĒΑ	7	10+ years	g
	Storage/ Closet	Basement	72	SF	7	10+ years	
	Walls - Concrete Block	Basement	1,030	SF	7	10+ years	
	Walls - Masonry	Basement	320	SF	6	10+ years	
unch &	Multipurpose Room						
	Ceiling - Exposed	Basement	1,250	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,250	SF	5	10+ years	
	Lighting - Lay-in	Basement	30	EA	7	10+ years	
	Walls - Metal Panel	Basement	800	SF	7	10+ years	
	Ceiling - Lay-in	Basement - Faculty Break Room	927	SF	7	10+ years	
	Coming Lay in	004	027	O.	•	To Tyouro	
	Chalk Board	Basement - Faculty Break Room	8	LF	4	2-5 years	
	onam zoara	004	· ·		•	_ 0 ,000	
	Doors - Wood Doors inclu hw	Basement - Faculty Break Room	1	EA	7	10+ years	
	Boole Wood Boole Mold III	004	•	_, `	•	ioi youro	
	Floor - Wood	Basement - Faculty Break Room	927	SF	6	10+ years	
	11001 11004	004	021	0.	Ü	To Tyouro	
	Lighting - Pendent/Surface	Basement - Faculty Break Room	11	EA	7	10+ years	
	giig . ondonyodiidoo	004		_, .	•	io. youro	
	Storage/ Closet	Basement - Faculty Break Room	114	SF	7	10+ years	
	5.5.4go/ 5.555t	004		٥.	•	. o . youro	
	Walls - Masonry	Basement - Faculty Break Room	1,308	SF	7	10+ years	
	Trans Masonly	004	1,000	51	,	ioi youis	
	Walls - Plaster/Drywall	Basement - Faculty Break Room	253	SF	7	10+ years	
	Traile Tidetel/DryWall	004	200	Oi.	,	ioi youis	
	Ceiling - Lay-in	Basement - Serving	555	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Serving	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - Serving	555	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Serving	16	EA	7	10+ years	
	Serving Line	Basement - Serving Basement - Serving	20	LF	7	10+ years	
	Walls - Metal Panel	Basement - Serving	558	SF	7	•	
	vvalis - IVIELAI FAITEI	Dasement - Serving	558	SF	′	10+ years	



Calego	Category : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
MDF_ID							
	Doors - Wood Doors inclu hw	201A	1	EA	7	10+ years	
	Finishes	201A	216	SF	5	10+ years	Water damage ceiling tiles.
	Window AC Unit	201A	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Air Intake Plenums	Basement, 1st, 2nd, and 3rd Floor	1,684	SF	7	10+ years	
	Boiler Room	Basement, 1st, 2nd, and 3rd Floor	1,140	SF	5	10+ years	
	Boiler Room	Basement, 1st, 2nd, and 3rd Floor	75	SF	5	10+ years	
	Coal Room	Basement, 1st, 2nd, and 3rd Floor	540	SF	7	10+ years	
	Janitor's Closet	Basement, 1st, 2nd, and 3rd Floor	40	SF	7	10+ years	
	Janitor's Closet	Basement, 1st, 2nd, and 3rd Floor	25	SF	7	10+ years	
	Janitor's Closet	Basement, 1st, 2nd, and 3rd Floor	60	SF	7	10+ years	
	Janitor's Closet	Basement, 1st, 2nd, and 3rd Floor	15	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement, 1st, 2nd, and 3rd Floor	437	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement, 1st, 2nd, and 3rd Floor	25	SF	5	10+ years	
	Storage Room	Basement, 1st, 2nd, and 3rd Floor	1,015	SF	7	10+ years	
Restroor	n						
	Accessories	009A	30	SF	7	6-10 years	
	Ceiling - Lay-in	009A	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	009A	1	ĒΑ	6	10+ years	
	Floor - Tile	009A	30	SF	7	10+ years	
	Lavatory	009A	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	009A	1	ΕA	7	10+ years	
	Lighting - Wall Mounted	009A	3	EA	7	10+ years	
	Walls - Plaster/Drywall	009A	88	SF	7	10+ years	
	Water Closet	009A	1	EA	7	10+ years	
	Accessories	100A	56	SF	7	6-10 years	
	Ceiling - Lay-in	100A	51	SF	6	10+ years	
	Ceiling - Lay-in	100A	5	SF	5	0-1 year	Water damaged tile
	Doors - Wood Doors inclu hw	100A	1	EA	7	10+ years	Traio: daagod inc
	Floor - Tile	100A	56	SF	6	6-10 years	
	Lavatory	100A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	100A	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	100A	390	SF	6	10+ years	
	Water Closet	100A	1	EA	7	10+ years	
	Accessories	102A	30	SF	7	6-10 years	
	Ceiling - Lay-in	102A	18	SF	6	10+ years	
	Ceiling - Lay-in	102A	12	SF	4	0-1 year	Water damaged and missing tile
	Doors - Wood Doors inclu hw	102A	1	EA	7	10+ years	Tracor damaged and missing the
	Floor - Tile	102A	26	SF	7	6-10 years	
	Floor - Tile	102A	4	SF	4	0-10 years	Damaged tiles

Campus Name: Jungman Page : 10 of 29 Assessment Date: 04/21/2022



Catego	ategory : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	102A	1	EA	6	10+ years	
	Lighting - Wall Mounted	102A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	102A	264	SF	7	10+ years	
	Water Closet	102A	1	EA	7	10+ years	
	Accessories	2nd Floor	208	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	208	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	208	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	6	EA	7	10+ years	
	Walls - Metal Panel	2nd Floor	414	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	150	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	256	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	312	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	312	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	312	SF	7	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EΑ	7	6-10 years	
	Partitions	2nd Floor	7	ĒΑ	7	10+ years	
	Walls - Metal Panel	2nd Floor	626	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	114	SF	7	10+ years	
	Water Closet	2nd Floor	7	ĒΑ	7	10+ years	
	Accessories	2nd Floor - Men	208	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Men	208	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Men	2	EA	7	10+ years	
	Floor - Tile	2nd Floor - Men	199	SF	7	6-10 years	
	Floor - Tile	2nd Floor - Men	9	SF	4	0-1 year	Missing.
	Lavatory	2nd Floor - Men	1	EA	7	10+ years	wiconig.
	Lighting - Lay-in	2nd Floor - Men	2	EA	7	6-10 years	
	Lighting - Lay-in Lighting - Pendent/Surface	2nd Floor - Men	1	EA	7	6-10 years	
	Partitions	2nd Floor - Men	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Men	840	SF	7	10+ years	
	Water Closet	2nd Floor - Men	2	EA	7	10+ years	
	Accessories	2nd Floor - Wen 2nd Floor - Women	208	SF	7	6-10 years	
	Benches	2nd Floor - Women 2nd Floor - Women	208	SF LF	7	<u>-</u>	
	DEHOUS	ZIIU FIOOI - WOITIEII	О	ᄕ	1	10+ years	

Campus Name: Jungman Page : 11 of 29 Assessment Date: 04/21/2022



Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	2nd Floor - Women	205	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor - Women	3	SF	4	0-1 year	Missing.			
	Doors - Wood Doors inclu hw	2nd Floor - Women	1	EA	7	10+ years				
	Floor - Terrazzo	2nd Floor - Women	208	SF	6	10+ years				
	Lavatory	2nd Floor - Women	1	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor - Women	6	EΑ	7	6-10 years				
	Partitions	2nd Floor - Women	2	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor - Women	826	SF	6	10+ years				
	Water Closet	2nd Floor - Women	2	EA	7	10+ years				
	Accessories	Basement	292	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Basement	292	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years				
	Floor - Tile Quarry	Basement	292	SF	7	10+ years				
	Floor Drain	Basement	1	EA	7	10+ years				
	Hand Dryer	Basement	1	EΑ	5	0-1 year	Not working			
	Lavatory	Basement	2	EA	7	10+ years				
	Lighting - Pendent/Surface	Basement	9	EA	6	10+ years				
	Partitions	Basement	8	EA	7	10+ years				
	Walls - Concrete Block	Basement	320	SF	7	10+ years				
	Walls - Plaster/Drywall	Basement	350	SF	7	10+ years				
	Water Closet	Basement	8	EA	7	10+ years				
	Accessories	Basement	292	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Basement	292	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Basement	292	SF	6	10+ years				
	Floor Drain	Basement	3	EA	7	10+ years				
	Hand Dryer	Basement	1	EA	5	0-1 year	Does not turn on.			
	Lavatory	Basement	2	EA	7	10+ years				
	Lighting - Pendent/Surface	Basement	5	EΑ	7	10+ years				
	Partitions	Basement	3	EA	7	10+ years				
	Urinals	Basement	6	EA	7	10+ years				
	Walls - Concrete Block	Basement	1,132	SF	7	10+ years				
	Water Closet	Basement	3	EA	7	10+ years				
	Accessories	Boiler Room	32	SF	7	6-10 years				
	Ceiling - Exposed	Boiler Room	32	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	7	10+ years				
	Floor - Tile	Boiler Room	27	SF	6	6-10 years				
	Floor - Tile	Boiler Room	5	SF	4	0-1 year	Damaged tiles			
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	10+ years				
	Walls - Concrete Block	Boiler Room	240	SF	7	10+ years				
	Water Closet	Boiler Room	1	EA	7	10+ years				
	Accessories	Engineer	40	SF	7	6-10 years				
	Ceiling - Exposed	Engineer	40	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Engineer	1	EA	7	10+ years				

Campus Name: Jungman Page : 12 of 29 Assessment Date: 04/21/2022



Ceiling - Lay-in

Joseph Jungman Elementary School 1746 S Miller STREET, Chicago, IL 60608

Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Engineer	40	SF	6	6-10 years	
	Lavatory	Engineer	1	EΑ	6	10+ years	
	Lighting - Chandelier, Incandescent	Engineer	1	EA	7	10+ years	
	Walls - Masonry	Engineer	275	SF	7	10+ years	
	Walls - Masonry	Engineer	5	SF	5	0-1 year	Cracking
	Water Closet	Engineer	1	EA	7	10+ years	-
	Accessories	Kitchen	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	2	EA	7	10+ years	
	Floor - Concrete	Kitchen	70	SF	7	10+ years	
	Lavatory	Kitchen	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	Kitchen	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	Kitchen	1	EA	5	0-1 year	Broken diffuser
	Student Lockers - One Tier	Kitchen	2	EA	7	10+ years	
	Walls - Concrete Block	Kitchen	192	SF	6	10+ years	
	Walls - Plaster/Drywall	Kitchen	56	SF	6	10+ years	
	Water Closet	Kitchen	1	EA	7	10+ years	
	Accessories	main office 1st floor	98	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	main office 1st floor	98	SF	6	10+ years	
	Doors - Wood Doors inclu hw	main office 1st floor	1	EA	7	•	
	Floor - Terrazzo	main office 1st floor	98	SF	4	10+ years	Cardboard on floor and separating.
		main office 1st floor	1	EA	7	0-1 year	Caruboard on floor and Separating.
	Lavatory			EA	7	10+ years	
	Lighting - Pendent/Surface Partitions	main office 1st floor main office 1st floor	2	EA	7	6-10 years	
			=			10+ years	
	Walls - Plaster/Drywall	main office 1st floor	420	SF	7	10+ years	
	Water Closet	main office 1st floor	1	EA SF	7	10+ years	
	Accessories	unisex across form 105	182		7	6-10 years	
	Ceiling - Lay-in	unisex across form 105	182	SF	6	10+ years	
	Doors - Wood Doors inclu hw	unisex across form 105	2	EA	7	10+ years	
	Floor - Tile	unisex across form 105	182	SF	6	6-10 years	
	Lavatory	unisex across form 105	1	EA	7	10+ years	
	Lighting - Pendent/Surface	unisex across form 105	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	unisex across form 105	294	SF	6	10+ years	
	Walls - Plaster/Drywall	unisex across form 105	70	SF	5	0-1 year	Damaged wall
	Water Closet	unisex across form 105	1	EA	7	10+ years	
atego	ry : Classroom		В	uilding	: Main		
	,					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #100 (Pre School)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	12	LF	7	10+ years	
	Ceiling - Lay-in	Basement	867	SF	7	10+ years	
	Coiling - Lay-in	Racement	20	SE.	1	0-1 year	Water damaged tiles

Campus Name: Jungman Page: 13 of 29 Assessment Date: 04/21/2022

20

SF

0-1 year

Water damaged tiles

Basement



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	Basement	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	882	SF	7	6-10 years	
	Floor - Tile	Basement	5	SF	4	0-1 year	Chipped.
	Lighting - Pendent/Surface	Basement	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,560	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #101 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,030	SF	7	10+ years	
	Doors - Transom Window	1st Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,020	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	Damagea tiles
	Marker Board	1st Floor	26	LF	7	6-10 years	
	Storage/ Closet	1st Floor	172	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	7	•	
			1,534		7	10+ years	
	Work Sink	1st Floor	1	EA	,	10+ years	
Classroo	nm #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	33	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	928	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	4	0-1 year	Water damage
	Doors - Transom Window	1st Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	938	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Broken tiles
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	90	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,416	SF	7	10+ years	
Classroo	m #104 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	25	EA	7	10+ years	
	Floor - Wood Doors inclu riw	1st Floor	950	SF	7		
	Lighting - Pendent/Surface			SF EA	7	10+ years 6-10 years	
	Liantina - Pengent/Surface	1st Floor	16	ĽΑ	1	p-10 years	



Categoi	ry : Classroom		В	uilding	: Main		
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,612	SF	7	10+ years	
	•		·			•	
Classroo	m #105 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,107	SF	7	10+ years	
	Doors - Transom Window	1st Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,087	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Damaged tiles
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	· ·
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,140	SF	7	10+ years	
	walle Flactor Drywall	1001	2,110	O.	,	101 youro	
lassroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,014	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	16	SF	4	0-1 year	Missing.
	Chalk Board	1st Floor	24	LF	4	2-5 years	•
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	1,030	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	172	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	7	10+ years	
	walls - Flaster/Drywall	13111001	1,004	Oi.	,	10+ years	
lassroo	m #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,025	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	28	LF	4	2-5 years	3
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	1,045	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	167	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	7	10+ years	
	walls - 1 laster/Drywall	13(1100)	1,334	OI.	,	10+ years	
lassroo	m #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	AC UIIIS	2110 1 1001	· · · · · · · · · · · · · · · · · · ·	LF		0-10 years	



Catego	ry : Classroom		В	uilding	: Main		· • • • •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	887	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	887	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,560	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	858	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	858	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,529	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Wall cracking
01	(1000 (Danislan Olasanaan)						
Classio	om #203 (Regular Classroom)	0 15				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	945	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	945	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,612	SF	7	10+ years	
Classroo	om #204 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,107	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,107	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,200	SF	7	10+ years	
	Work Sink	2nd Floor	_,1	ĒΑ	7	10+ years	
						,	



Category : Classroom			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_							
lassroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,107	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,740	SF	7	10+ years	
l							
assroo	m #206 (Regular Classroom)	2nd Floor				0.40	
	AC Units		1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,071	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	36	SF	4	0-1 year	Water damage.
	Doors - Transom Window	2nd Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	1,107	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,740	SF	7	10+ years	
assroo	m #208 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,000	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	995	SF	6	6-10 years	
	Floor - Tile			SF	-		Missing
		2nd Floor	5		4	0-1 year	Missing.
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	107	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,480	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
assroo	m #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,100	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	7	SF	4	0-1 year	Water damage.
		0.0	•	LF	•	2-5 years	



Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,740	SF	6	10+ years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,087	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage.
	Chalk Board	3rd Floor	24	LF	4	2-5 years	water damage.
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Bools Incid IIW	3rd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1,107	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor		SF			
	Walls - Plaster/Drywall		216	SF SF	7 7	10+ years	
	walls - Flastel/Drywall	3rd Floor	2,740	SF	,	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,107	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,740	SF	7	10+ years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,452	SF	7	6-10 years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	1,452	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,223	SF	7	10+ years	
		0.01.1001	2,220	٥.	•	.o. youro	
Classroo	m #304 (Regular Classroom)						

Campus Name: Jungman Page : 18 of 29 Assessment Date: 04/21/2022



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,740	SF	7	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,740	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,097	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage.
	Chalk Board	3rd Floor	24	LF	4	2-5 years	vvator damago.
	Doors - Transom Window	3rd Floor	414	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,107	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	216	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,720	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	0-1 year	Water damage.
Classroo	om #308 (Regular Classroom)						
2,000,00	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	7	10+ years	
	Chalk Board	3rd Floor	1,107	LF		2-5 years	
	Doors - Transom Window		9	SF	4 7	-	
		3rd Floor	9	SF EA		10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	⊏A	7	10+ years	

Campus Name: Jungman Page: 19 of 29 Assessment Date: 04/21/2022



Catego	ry : Classroom	Category : Classroom			Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
	Floor - Wood	3rd Floor	1,107	SF	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years				
	Marker Board	3rd Floor	24	LF	7	6-10 years				
	Storage/ Closet	3rd Floor	216	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	2,740	SF	7	10+ years				

Building: Main Category : Interior

Juit ge.	y . mitorioi			unung			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	item - Type	Location	Quantity	UOIVI	Naiik	Replacement	Comments
rridor	0 "	=	2.225			40	
	Ceiling - Plaster/Drywall	1st Floor	2,625	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EΑ	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	/	10+ years	
	Floor - Asphalt Floor	1st Floor	2,625	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	30	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,126	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,615	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracking.
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,385	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	240	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	94	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,150	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Cracking.
	Ceiling - Lay-in	3rd Floor	2,345	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	40	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	3rd Floor	240	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,385	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	240	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	34	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,170	SF	6	10+ years	
	Ceiling - Exposed	Basement	1,544	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	498	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	3	ĒΑ	7	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	2,042	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	30	ĒΑ	7	10+ years	
	Walls - Masonry	Basement	1,880	SF	6	10+ years	Paint chipping and cracking.

Campus Name: Jungman Page : 20 of 29 Assessment Date: 04/21/2022



Catego	ory : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement	1,720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Vestibules	666	SF	6	10+ years	
	Doors - Side-lite	Vestibules	128	SF	7	10+ years	
	Doors - Store Front	Vestibules	2	EΑ	7	10+ years	
	Doors - Transom Window	Vestibules	178	SF	7	10+ years	
	Doors - Wood Doors include hw	Vestibules	14	EA	7	10+ years	
	Floor - Asphalt Floor	Vestibules	180	SF	6	10+ years	
	Floor - Terrazzo	Vestibules	162	SF	6	10+ years	
	Floor - Tile/Sheet	Vestibules	324	SF		10+ years	
	Lighting - Pendent/Surface	Vestibules	13	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Vestibules	1	EA	6	2-5 years	
	Walls - Masonry	Vestibules	642	SF	7	10+ years	
	Walls - Plaster/Drywall	Vestibules	628	SF	6	10+ years	
	· · · · · · · · · · · · · · · · · · ·				-	, , , , , , , , , , , , , , , , , , , ,	
Stairs							
	Ceiling - Plaster/Drywall	Basement	270	SF	7	10+ years	
	Floor - Asphalt	Basement	180	SF	6	10+ years	
	Handrails	Basement	30	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement	3	EΑ	7	10+ years	
	Stairs - Asphalt	Basement	42	LF	7	10+ years	
	Walls - Concrete Block	Basement	108	SF	7	10+ years	
	Walls - Masonry	Basement	336	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - at Boy's Restroom	200	SF	6	10+ years	
	Floor - Asphalt	Basement - at Boy's Restroom	200	SF	6	10+ years	
	Handrails	Basement - at Boy's Restroom	12	ĹF	7	10+ years	
	Lighting - Pendent/Surface	Basement - at Boy's Restroom	2	EA	7	10+ years	
	Stairs - Asphalt	Basement - at Boy's Restroom	60	LF	7	10+ years	
	Walls - Masonry	Basement - at Boy's Restroom	600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - at Girl's Restroom	200	SF	7	10+ years	
	Floor - Asphalt	Basement - at Girl's Restroom	200	SF	7	10+ years	
	Handrails	Basement - at Girl's Restroom	12	LF	7	10+ years	
	Lighting - Pendent/Surface	Basement - at Girl's Restroom	2	EA	7	10+ years	
	Stairs - Asphalt	Basement - at Girl's Restroom	60	LF	7	10+ years	
	Walls - Masonry	Basement - at Girl's Restroom	575	SF	6	10+ years	
	Walls - Masonry	Basement - at Girl's Restroom	25	SF	5	0-1 year	Spalling masonry and peeling paint.
	Ceiling - Exposed	North	448	SF	7	10+ years	opaning masonly and pecing paint.
	Ceiling - Laposed Ceiling - Lay-in	North	420	SF	7	10+ years	
	Ceiling - Lay-in	North	30	SF	4	0-1 year	Water damage.
	Ceiling - Lay-in Ceiling - Plaster/Drywall	North	325	SF	7	10+ years	Tratol dalliago.
	Floor - Asphalt	North	375	SF	6	10+ years	
	Handrails	North	154	LF	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	10+ years	
	Stairs - Asphalt	North	490	LF	7	10+ years 10+ years	
	Walls - Plaster/Drywall		4,250	SF	7	,	
	vvalis - Mastel/Drywall	North	4,230	SF	,	10+ years	

Campus Name: Jungman Page : 21 of 29 Assessment Date: 04/21/2022



Catego	Category : Interior			uilding	Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	South	2,575	SF	6	10+ years	
	Ceiling - Lay-in	South	50	SF	4	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	South	240	SF	6	10+ years	
	Floor - Asphalt	South	375	SF	6	6-10 years	
	Handrails	South	142	LF	7	10+ years	
	Lighting - Pendent/Surface	South	7	EA	7	6-10 years	
	Stairs - Asphalt	South	448	LF	7	10+ years	
	Walls - Plaster/Drywall	South	4,250	SF	6	10+ years	
	Ceiling - Plaster/Drywall	middle	648	SF	7	10+ years	
	Floor - Asphalt	middle	341	SF	7	10+ years	
	Handrails	middle	138	LF	7	10+ years	
	Lighting - Pendent/Surface	middle	5	EA	7	6-10 years	
	Stairs - Asphalt	middle	394	LF	7	10+ years	
	Walls - Plaster/Drywall	middle	1,440	SF	7	10+ years	
_Vertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	10+ years	



Catego	Category : Exterior			Building : Addition-Gymnasium/auditorium Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance									
	Exterior Doors - Exterior Steel Door	4	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	4	3	EA	6	10+ years			
	Exterior Stairs - Concrete	4	32	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	9	2	EA	6	10+ years			
	Exterior Stairs - Concrete	9	6	LF	6	2-5 years			
Foundati	on								
	Foundation - Concrete	Entire Building	396	LF	7	10+ years			
	Superstructure - Steel with Clay Tile Arch	Entire Building	7,750	SF	7	10+ years			
Liabtina									
Lighting	Exterior Lighting - Parapet or Roof Mounted	Main Roof	5	EA	6	10+ years			
Roof Sys	tom								
TXOOL Oys	Coping - Clay Tile	D	65	LF	6	10+ years			
	Coping - Clay file Coping - Stone	D	210	LF	6	10+ years			
	Downspouts - Exterior Downspouts	D	16	LF	6	10+ years			
	Downspouts - Interior Downspouts	D	140	LF	6	10+ years			
	Parapet - 16" - 30" Height	D	275	LF	6	10+ years			
	Roof - Asphalt Gravel Ballast	D	7,540	SF	5	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	D	7,540	SF	7	10+ years			
	Coping - Clay Tile	Ē	31	LF	6	10+ years			
	Downspouts - Exterior Downspouts	Ē	12	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Ē	31	LF	6	10+ years			
	Roof - Modified Bitumen	Ē	210	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	Ē	210	SF	7	10+ years			
Walls									
	Cheek-Wall - Stone	Entire Building	12	SF	5	6-10 years			
	Cornice - Metal Projecting	Entire Building	140	LF	5	6-10 years			
	Exterior Walls - Brick	Entire Building	5,852	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	1,250	SF	4	0-1 year	Open joints/cracked masonry/deteriorating joints.		
	Exterior Walls - Brick	Entire Building	20	SF	4	0-1 year	Open joints/stepped cracked masonry and mortar/shifting and displaced brick.		
	Exterior Walls - Stone-Cut	Entire Building	233	SF	6	10+ years			
	Exterior Walls - Stone-Cut	Entire Building	75	SF	4	0-1 year	Open joints, cracked, and chipping.		
Windows									

Campus Name: Jungman Page : 23 of 29 Assessment Date: 04/21/2022



Catego	ry : Exterior		В	uildina	: Addition	on-Gymnasiun	n/auditorium
Jaiogo	y i =xiono:		_	uug	. , (Recommend	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Guard - Guards perforated	Entire Building	200	SF	6	10+ years	
	Lintels - Steel	Entire Building	35	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	200	SF	5	10+ years	
	Trinadina Casii / Ilaiiiii Zaazia paila	g		О.	Ū	.o. you.o	
Catego	ry : Electrical		В	uilding	: Additi	on-Gymnasiun	n/auditorium
	•			J		Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	cy System						
	Emergency A/C Power - Auditoium and	1st Floor	2,500	SF	6	6-10 years	
	Aisle Lighting					•	
	Emergency A/C Power - Corridors and	1st Floor	2,000	SF	6	6-10 years	
	Stairs					•	
	Emergency A/C Power - Gym	1st Floor	2,200	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and	1st Floor	2	EA	6	6-10 years	
	Stairs					-	
	Exit Signs - Auditoium	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	Hard to read.
	Exit Signs - Gym	Entire Building	2	EA	4	0-1 year	Hard to read.
	Security System - Intrusion Detection	Entire Building	7,750	SF	6	6-10 years	
Main Ser							
	PA System	1st Floor	7,750	SF	5	6-10 years	Connected to main building,
							previously not assessed.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Serviced, not live, serves addition,
		C				•	located in air handler room. Expose
							bus bar taped with duct tape.
Cata	n Fire Brotestian		В	م ما المالي	. A al al ! 4 !	C	./
Jatego	ry : Fire Protection		В	ullaing	. Additi	on-Gymnasiun Recommend	i/auditorium
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		2004	quantity	CO	rtariit	rtopiacomont	Commonte
no man	Fire Alarm Strobe Lights	Entire Building	7,750	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	7,750	SF	6	6-10 years	Connected to main building
	The Alami_System	Entire Ballating	7,700	O.	Ū	o io youio	Commoded to main banding
Catego	ry : Mechanical		В	uilding	: Additi	on-Gymnasiun	n/auditorium
						Recommend	
Froup		Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone-	Mechanical Room	1	EA	5	6-10 years	Serves gym.

Assessment Date: 04/21/2022 Page : 24 of 29 Campus Name: Jungman



Catego	ry : Mechanical		В	Building : Addition-Gymnasium/auditorium						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Steam Coils - 15001 - 25000 cfm									
	Air Intake	Mechanical Room	1	EA	5	6-10 years				
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years				
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	5	6-10 years				
	Missing or Existing Shaft									
/lechani	ical Plumbing									
VICOLIGIII	Condensate-Steel or Galvanized	Entire Building	100	LF	5	6-10 years	Condensate and steam, connected			
	Condensate-Steel of Galvanized	Entire building	100	LI	3	0-10 years	boiler in main building, serves air handler in addition.			
<u>Tempera</u>	ature Control									
	Pneumatic System	Entire Building	7,750	SF	4	1-2 years	Served from main building. Leaks, not reliable.			
	Thermostats - Pneumatic	Entire Building	2	EA	4	1-2 years	Not calibrated, serves gym and auditorium			
Catego	ry : Plumbing		Building : Addition-Gymnasium/auditorium							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Piping										
, 5	Storm Piping	Entire Building	7,750	SF	5	2-5 years				
Pumps										
•	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years	Crawlspace, difficult to access			
Catego	ry : Room		В	uilding	: Additio	on-Gymnasiun	n/auditorium			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Gymnas	ia									
•	Bleacher Seating	1st Floor	572	EA	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor	7,488	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	9	ĒΑ	6	10+ years				
		1st Floor	3,776	SF	7	6-10 years				
	FIGOR - LIIE/Sheet	1001		SF	4	0-1 year	Damaged tile.			
	Floor - Tile/Sheet	1st Floor	201			o-i yeai	Damagea lile.			
	Floor - Tile/Sheet	1st Floor	20 3 602			10± vears				
	Floor - Tile/Sheet Floor - Wood	1st Floor	3,692	SF	7	10+ years				
	Floor - Tile/Sheet Floor - Wood Lighting - Pendent/Surface	1st Floor 1st Floor	3,692 50	SF EA	7 7	6-10 years				
	Floor - Tile/Sheet Floor - Wood Lighting - Pendent/Surface Sound System	1st Floor 1st Floor 1st Floor	3,692 50 1	SF EA EA	7 7 7	6-10 years 10+ years				
	Floor - Tile/Sheet Floor - Wood Lighting - Pendent/Surface Sound System Stage	1st Floor 1st Floor 1st Floor 1st Floor	3,692 50 1 1,280	SF EA EA SF	7 7 7 7	6-10 years 10+ years 10+ years				
	Floor - Tile/Sheet Floor - Wood Lighting - Pendent/Surface Sound System Stage Stage Curtain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,692 50 1 1,280 2	SF EA EA SF EA	7 7 7 7 7	6-10 years 10+ years 10+ years 10+ years				
	Floor - Tile/Sheet Floor - Wood Lighting - Pendent/Surface Sound System Stage	1st Floor 1st Floor 1st Floor 1st Floor	3,692 50 1 1,280	SF EA EA SF	7 7 7 7	6-10 years 10+ years 10+ years				



Catego	ory : Room		Building : Addition-Gymnasium/auditorium						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stage-Stairs - Wood	1st Floor	30	LF	7	10+ years			
	Storage/ Closet	1st Floor	30	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	7,085	SF	7	10+ years			
_Mechan	ical/ Service Rooms								
	Storage Room	109 Book Storage	650	SF	5	10+ years	Water damage ceiling.		

Category : Interior Building · Addition-Gymnasium/auditorium

y . IIILEITOI	Building : Addition-Gymnasium/auditorium						
					Recommend		
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Ceiling - Plaster/Drywall	auditorium vestibule	84	SF	7	10+ years		
Floor - Concrete	auditorium vestibule	84	SF	7			
Lighting - Pendent/Surface	auditorium vestibule	2	EΑ	7	6-10 years		
Walls - Concrete Block	auditorium vestibule	378	SF	7	10+ years		
Walls - Plaster/Drywall	auditorium vestibule	162	SF	7	10+ years		
Ceiling - Plaster/Drywall	gym vestibule	160	SF	7	10+ years		
Doors - Wood Doors include hw	gym vestibule	4	EA	6	10+ years		
Floor - Concrete	gym vestibule	160	SF	7	10+ years		
Lighting - Pendent/Surface	gym vestibule	2	EA	6	10+ years		
Walls - Plaster/Drywall	gym vestibule	520	SF	6	10+ years		
Ceiling - Plaster/Drywall	at gym balcony	104	SF	6	10+ years		
Floor - Asphalt	at gym balcony	16	SF	7	10+ years		
Handrails	at gym balcony	61	LF	7	10+ years		
Stairs - Asphalt	at gym balcony	88	LF	7			
Walls - Plaster/Drywall	at gym balcony	338	SF	7	10+ years		
	Ceiling - Plaster/Drywall Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Wood Doors include hw Floor - Concrete Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Asphalt Handrails Stairs - Asphalt	Location Ceiling - Plaster/Drywall auditorium vestibule Floor - Concrete auditorium vestibule Lighting - Pendent/Surface auditorium vestibule auditorium vestibule Walls - Concrete Block auditorium vestibule Walls - Plaster/Drywall auditorium vestibule Ceiling - Plaster/Drywall gym vestibule Doors - Wood Doors include hw gym vestibule Floor - Concrete gym vestibule Lighting - Pendent/Surface gym vestibule gym vestibule Geiling - Plaster/Drywall gym vestibule gym vestibule gym vestibule gym vestibule Geiling - Plaster/Drywall gym vestibule Geiling - Plaster/Drywall gym balcony at gym balcony at gym balcony Stairs - Asphalt at gym balcony at gym balcony stairs - Asphalt at gym balcony at gym balcony stairs - Asphalt at gym balcony at gym balcony stairs - Asphalt stairs - Asp	Item - TypeLocationQuantityCeiling - Plaster/Drywallauditorium vestibule84Floor - Concreteauditorium vestibule84Lighting - Pendent/Surfaceauditorium vestibule2Walls - Concrete Blockauditorium vestibule378Walls - Plaster/Drywallauditorium vestibule162Ceiling - Plaster/Drywallgym vestibule160Doors - Wood Doors include hwgym vestibule4Floor - Concretegym vestibule160Lighting - Pendent/Surfacegym vestibule2Walls - Plaster/Drywallgym vestibule520Ceiling - Plaster/Drywallat gym balcony104Floor - Asphaltat gym balcony16Handrailsat gym balcony61Stairs - Asphaltat gym balcony88	Item - TypeLocationQuantityUOMCeiling - Plaster/Drywallauditorium vestibule84SFFloor - Concreteauditorium vestibule84SFLighting - Pendent/Surfaceauditorium vestibule2EAWalls - Concrete Blockauditorium vestibule378SFWalls - Plaster/Drywallauditorium vestibule162SFCeiling - Plaster/Drywallgym vestibule160SFDoors - Wood Doors include hwgym vestibule4EAFloor - Concretegym vestibule160SFLighting - Pendent/Surfacegym vestibule2EAWalls - Plaster/Drywallgym vestibule520SFCeiling - Plaster/Drywallat gym balcony104SFFloor - Asphaltat gym balcony16SFHandrailsat gym balcony61LFStairs - Asphaltat gym balcony88LF	Item - TypeLocationQuantityUOMRankCeiling - Plaster/Drywallauditorium vestibule84SF7Floor - Concreteauditorium vestibule84SF7Lighting - Pendent/Surfaceauditorium vestibule2EA7Walls - Concrete Blockauditorium vestibule378SF7Walls - Plaster/Drywallauditorium vestibule162SF7Ceiling - Plaster/Drywallgym vestibule160SF7Doors - Wood Doors include hwgym vestibule4EA6Floor - Concretegym vestibule160SF7Lighting - Pendent/Surfacegym vestibule2EA6Walls - Plaster/Drywallgym vestibule520SF6Ceiling - Plaster/Drywallat gym balcony16SF7Handrailsat gym balcony16SF7Stairs - Asphaltat gym balcony88LF7	Item - TypeLocationQuantityUOMRankRecommendCeiling - Plaster/Drywallauditorium vestibule84SF710+ yearsFloor - Concreteauditorium vestibule84SF710+ yearsLighting - Pendent/Surfaceauditorium vestibule2EA76-10 yearsWalls - Concrete Blockauditorium vestibule378SF710+ yearsWalls - Plaster/Drywallauditorium vestibule162SF710+ yearsCeiling - Plaster/Drywallgym vestibule160SF710+ yearsDoors - Wood Doors include hwgym vestibule4EA610+ yearsFloor - Concretegym vestibule160SF710+ yearsLighting - Pendent/Surfacegym vestibule2EA610+ yearsWalls - Plaster/Drywallgym vestibule520SF610+ yearsCeiling - Plaster/Drywallat gym balcony16SF710+ yearsFloor - Asphaltat gym balcony16SF710+ yearsHandrailsat gym balcony61LF710+ yearsStairs - Asphaltat gym balcony88LF710+ years	

Campus Name: Jungman Page : 26 of 29 Assessment Date: 04/21/2022



Catego	Category : Site		В	uilding	: Site		
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	0-1 year	Sinking - breaking concrete.
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	0-1 year	Collapsing.
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	0-1 year	Breaking concrete.
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	0-1 year	Sinking - breaking concrete.
Fencina							
	Fencing - Chain Link	Entire Site	20	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	279	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,002	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	55	LF	4	0-1 year	Bent/broken.
	Fencing - New Standard Ornamental	Entire Site	55 55	LF	4	0-1 year	Bent.
	rending - New Standard Offiamental	Littile Site	55	LI	4	0-1 year	bent.
Landsca	pe						
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	11,640	SF	6	10+ years	
	Parkway trees	Entire Site	25	EA	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	10,704	SF	4	0-1 year	Cracking and uneven surfaces.
	Trash Receptacles	Entire Site	2	EA	6	6-10 years	
Parking	Lot						
9	Surface - Asphalt	North	16,110	SF	4	0-1 year	Cracking and standing water
							throughout.
Playgrou	ind						
, ,	Equipment - School Age 5-12	South	1	EA	5	2-5 years	
	Surface - Square Rubber Mats	South	2,244	SF	4	0-1 year	Gaps, loose, vegetation growth.
	Equipment - Swingset	South	1	EA	4	0-1 year	Missing swings.
	Surface - Square Rubber Mats	South	1,330	SF	4	0-1 year	Gaps, loose, and vegetation growth.
	Equipment - School Age 5-12	South	1	EA	6	6-10 years	
	Surface - Square Rubber Mats	South	496	SF	4	0-1 year	Gaps, loose, vegetation growth.
Sidewalk	rs.						
	Sidewalks - Perimeter Sidewalks	Entire Site	125	SF	7	10+ years	Repaired.
	Sidewalks - Perimeter Sidewalks	Entire Site	10,842	SF	6	10+ years	• ** ***
Signage							
uguaye	Flag Pole - Building Mounted Flag Pole	East	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	East	1	EA	4	0-1 year	Per site engineer sign does not work
		 -	·	<i></i> ,	•	- , ,	



Category : Site

Joseph Jungman Elementary School

1746 S Miller STREET, Chicago, IL 60608

Cate	Dailegory . One						
Grou	p Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marquee - Building Mounted Back Lighted w/ LED	East	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	East	2	EA	6	10+ years	Dirty/Clean

Building . Site

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Jungman Page: 28 of 29 Assessment Date: 04/21/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main							1	1	
Faculty Lounge	Regular Classroom	1st Floor	101	101	1,030	123	70	N	Υ
Kindergarten	Pre School	1st Floor	102	102	948	1,460	16	N	Υ
Office	Regular Classroom	1st Floor	105	105	1,107	123	51	N	Υ
Office	Regular Classroom	2nd Floor	208	208	1,000	190	84	N	Υ
Pre School	Pre School	Basement	100	100	887	160	16	N	N
Regular Classroom	Library	3rd Floor	302	302	1,107	105	9	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	1,030	123	51	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	1,045	140	12	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	887	160	16	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	858	85	34	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	945	140	67	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,107	147	67	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,107	123	51	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	300	300	1,107	142	68	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	1,107	123	51	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	1,452	172	85	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,107	142	68	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	1,107	142	68	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	1,107	142	68	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	1,107	190	84	N	N
Science Classroom	Regular Classroom	2nd Floor	204	204	1,107	123	12	N	N
Store Room	Regular Classroom	1st Floor	104	104	950	123	12	N	Υ
Building : Addition-Gymna				Ţ		,	1		
Dogular Classroom	Dogular Classroom	1ot Eleor	100	100	1 000	102	01	NI NI	V

Building : Addition-Gymnasium/auditorium									
Regular Classroom	Regular Classroom	1st Floor	109	109	1,008	193	81	N	Υ