



#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1881	3	58,108
Campus Total			58,108

atego	ry : Exterior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Lower Roofs	3	EA	7	10+ years	
	Cell Equipment - Cabinets	Lower Roofs	2	EA	7	10+ years	
	Cell Equipment - Antenna	Main Roof	6	EA	7	10+ years	
Entrance	2						
	Entrance Control - Audio and Video	Door 1 - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 1 - West	2	EA	5	0-1 year	Rusting around edges.
	Exterior Doors - Transom Lite	Door 1 - West	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - West	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 2 - North	2	EA	5	0-1 year	Rusting.
	Exterior Doors - Transom Lite	Door 2 - North	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 2 - North	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3 - West center	1	EA	5	0-1 year	Rusting.
	Exterior Doors - Exterior Steel Door	Door 4 - Southwest	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - Southwest	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4 - Southwest	9	LF	6	10+ years	
	Entrance Control - Audio and Video	Door 5 - south	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 5 - south	4	EA	7	10+ years	
	Power Door Operator and Controls	Door 5 - south	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6 - East	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - South West	1	EA	5	0-1 year	Rust/Corrosion - Deteriorating Frames
	Exterior Doors - Exterior Steel Door	Door 8 - Fire escape	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 8 - Fire escape	4	EA	6	6-10 years	Needs to be repainted.

Campus Name: Mcclellan Page : 1 of 26 Assessment Date: 12/16/2021



Catego	ry : Exterior		В	uilding	: Main		
_	<del></del>		0	11014	D	Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	Door 8 - Fire escape	3	EA	6	6-10 years	
re Esc	ane						
IC LSO	Fire Escape	NW Site	135	LF	6	6-10 years	
	1 110 200apo	THE GIRE	100		Ü	o ro youro	
oundati	ion						
	Foundation - Masonry	Entire Building	534	LF	7	10+ years	
	Foundation - Masonry	Entire Building	50	LF	4	0-1 year	Weathered/Aged/Deterioration -
							Water Penetration with Mold and
							organic vegetation growth present
	Superstructure - Concrete	Entire Building	58,108	SF	7	10+ years	
ghting							
giiiiig	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	Quantity Adjusted
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	4	0-1 year	Quantity Adjusted- Broken
		Ç				Ţ	Fixtures/Missing Fixture
oof Svs	stom						
JUL Gys	Access Ladder - Wood	Roof 1 south	2	EA	7	6-10 years	
	Coping - Metal	Roof 1 south	23	LF	5	6-10 years	
	Coping - Stone	Roof 1 south	298	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1 south	189	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 1 south	275	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1 south	46	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 1 south	7,980	SF	5	0-1 year	Vegetation growth.
	Roof - Metal	Roof 1 south	20	SF	5	0-1 year	Rusting.
	Roof - Modified Bitumen	Roof 1 south	250	SF	6	10+ years	Elevator roof.
	Roof Hatch - Metal	Roof 1 south	1	EA	5	1-2 years	Out of Date/Bent/Misaligned - Rus
	Roof Structure - Heavy Timber	Roof 1 south	8,250	SF	7	10+ years	Out of Date/Dent/Misaligned - Nus
	Access Ladder - Wood	Roof 2 upper west	0,230	EA	4	1-2 years	Wooded -
	Access Ladder - Wood	11001 2 upper west		LA		1-2 years	Worned/Deteriorating/Loose,
							unattached at top/bottom
	Coping - Clay Tile	Roof 2 upper west	258	LF	6	10+ years	·
	Downspouts - Exterior Downspouts	Roof 2 upper west	134	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 2 upper west	68	LF	5	10+ years	
	Parapet - Parapet > 30"	Roof 2 upper west	190	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 2 upper west	3,962	SF	5	0-1 year	Per building engineer there is a lot patching located at this roof.
	Roof Hatch - Metal	Roof 2 upper west	1	EA	5	2-5 years	Misaligned/Bent - latch ineffective
	Roof Structure - Heavy Timber	Roof 2 upper west	3,962	SF	7	10+ years	9
	Access Ladder - Metal	Roof 3	1	EΑ	7	10+ years	
	Access Ladder - Wood	Roof 3	1	EA	4	0-1 year	Deteriorating/Not securely attache top/Aged

Campus Name: Mcclellan Page : 2 of 26 Assessment Date: 12/16/2021



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Clay Tile	Roof 3	155	LF	6	2-5 years	
	Downspouts - Exterior Downspouts	Roof 3	63	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Roof 3	155	LF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof 3	2,023	SF	5	0-1 year	Vegetation growth.
	Roof - Modified Bitumen	Roof 3	162	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 3	1	EΑ	7	10+ years	Upgraded/improved
	Roof Structure - Heavy Timber	Roof 3	2,185	SF	7	10+ years	13
	Access Ladder - Metal	Roof 4 - lower east	_,	ĒΑ	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4 - lower east	65	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4 - lower east	80	LF	5	2-5 years	
	Coping - Clay Tile	Roof 4 - lower east	176	LF	6	10+ years	Quantity Adjusted to match observations.
	Coping - Stone	Roof 4 - lower east	16	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4 - lower east	40	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Roof 4 - lower east	192	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 4 - lower east	2,522	SF	4	0-1 year	Leaks/Cracks/missing gravel - organic/vegetative growth
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4 - lower east	2,522	SF	7	10+ years	organia, regolanie gronni
	Coping - Stone	Roof 5 - lower west roofs	25	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 5 - lower west roofs	32	LF	5	2-5 years	
	Parapet - Parapet < 16" Height	Roof 5 - lower west roofs	25	LF	5	10+ years	
	Roof - EPDM/ Synthetic Rubber	Roof 5 - lower west roofs	31	SF	4	0-1 year	Ponding
	Roof - Modified Bitumen	Roof 5 - lower west roofs	100	SF	6	6-10 years	Quantity Adjusted
	Roof Structure - Heavy Timber	Roof 5 - lower west roofs	131	SF	7	10+ years	Quantity Adjusted
	Coping - Stone	Roof 6	34	LF	7	10+ years	Quantity Adjusted
	Downspouts - Exterior Downspouts	Roof 6	15	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 6	34	LF	7	10+ years	
				SF	7		
	Roof - Modified Bitumen	Roof 6	240			10+ years	
	Roof Structure - Heavy Timber	Roof 6	240	SF	7	10+ years	
	Coping - Stone	Roof 7 - Southwest Entrance	34	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 7 - Southwest Entrance	15	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 7 - Southwest Entrance	34	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 7 - Southwest Entrance	250	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 7 - Southwest Entrance	250	SF	7	10+ years	
s							
	Canopy - Metal	Entire Building	84	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,168	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	403	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	20	LF	4	0-1 vear	Open Joints/Missing

Campus Name: Mcclellan Page : 3 of 26 Assessment Date: 12/16/2021



Catego	ry : Exterior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							Components/Rust/Corrosion
	Exterior Walls - Brick	Entire Building	505	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	4,200	SF	7	10+ years	Elevator Addition
	Exterior Walls - Brick	Entire Building	34,740	SF	6	10+ years	Quantity Adjusted
	Exterior Walls - Brick	Entire Building	720	SF	4	0-1 year	Significant Damage- Missing
							Mortar/Cracks/Holes, Peeling Paint
							and shifting brick
	Exterior Walls - Prefabricated Metal Panel	Entire Building	90	SF	6	6-10 years	
	Wall						
	Exterior Walls - Stone-Cast	Entire Building	580	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	30	SF	4	0-1 year	Cracks/Missing Mortar
_Windows	e						
vviiidow.	Curtain wall - Glazed Double Pane	Entire Building	200	SF	7	10+ years	"Storefront"
	Guard - Guards perforated	Entire Building	2,968	SF	6	6-10 years	
	Lintels - Brick	Entire Building	15	ĹF	6	10+ years	
	Lintels - Stone	Entire Building	479	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	72	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	24	SF	4	0-1 year	Cracked and rusted.
	Windows - Sash Aluminum Double-pane	Entire Building	4,999	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	2	SF	5	0-1 year	Changed quantity to 2 SF. Bullet hole at one (1 x 2) pane only. Per Site Engineer others fixed.

Category : Electrical **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	cy System						
· ·	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves AC generator
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,146	SF	6	6-10 years	,
	Emergency A/C Power - Multipurpose Room	Entire Building	4,503	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	2,747	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	7	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	7	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	Previously not assessed
	Security System - CCTV	Entire Building	58,108	SF	6	6-10 years	-
	Security System - Intrusion Detection	Entire Building	58,108	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	4	0-1 year	Old, worn lettering.

Campus Name: Mcclellan Page : 4 of 26 Assessment Date: 12/16/2021



Categoi	ry : Electrical		B	uilding	: Main		
						Recommend	
<b>3roup</b>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - 60	Site - East	1	EA	4	2-5 years	Requires frequent repairs
	- 100 KW						
ain Ser	vice						
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH					•	
	PA System	Entire Building	58,108	SF	6	6-10 years	
ower Di	istribution						
OWEI D	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A  Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A  Lighting and Power Panels - Above 100 A		3	EA	7		
		Entire Building				10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	7	10+ years	<b>5</b> 10
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Found 2
Catego	ry : Fire Protection		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Aları			•			•	
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	58,108	SF	6	10+ years	
	Fire Alarm_System	Entire Building	58,108	SF	6	10+ years	Upgraded in 2015
	Fire Pump Controller	Entire Building	30,100	EA	5	6-10 years	Older
	The Fullip Controller	Littile building	ı	LA	3	0-10 years	Oldel
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Boiler Room	1	EA	5	6-10 years	
Sprinkler	System						
	Dry Sprinkler System	Boiler Room	58,108	SF	6	10+ years	
	Sprinkler Heads	Boiler Room	58,108	SF	7	10+ years	
	Sprinkler Piping	Boiler Room	58,108	SF	6	10+ years	
Categoi	ry : Mechanical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	itioning						
ur Cona	Condensing Unit- Ground Mounted - Less	Site - East	3	EA	5	6-10 years	Found 3, serve fan coil units, CU 1,

Campus Name: Mcclellan Page : 5 of 26 Assessment Date: 12/16/2021



Catego	ry : Mechanical		В	uilding	: Main		
0	Hama Tama	Laadlan	0	11014	D	Recommend	0
Group	Item - Type than 5 tons	Location	Quantity	UOM	Rank	Replacement	Comments CU 2, CU 3
	than 5 tons						CU 2, CU 3
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Basement	2	EA	5	6-10 years	Previously not assessed, third unit is
	Tan con onit- cening Mounted - Liectric	basement	2	LA	3	0-10 years	in MDF room (see interior room for third ductless).
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves classrooms and offices, AHU 1
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	5	6-10 years	Painted
	Missing or Existing Shaft	Woonamour Room	100		Ū	o ro youro	- annoa
	Zone Dampers	Mechanical Room	15	EA	5	6-10 years	North side, adjusted quantity
	Zone Dampers	Mechanical Room	20	EA	5	6-10 years	South side
	Make Up Air Unit-Ground Mounted- Gas Heating - 6000 - 10,000 cfm	Site South	1	EA	6	10+ years	MAU 1, serves kitchen
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	2	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Boiler Room	2	EA 	5	6-10 years	Serves main building, recently retubed
	Piping - Condensate Pipe- Steel	Boiler Room	350	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	350	LF	5	6-10 years	There are a few pipe clamps
	Steam Traps	Boiler Room	35	EA	5	6-10 years	
Heating	Devices						
J	Radiators - Steam	2nd Floor	2	EA	6	10+ years	
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Older
_Tempera	ature Control						
	DDC System	Entire Building	58,108	SF	5	6-10 years	Software not upgraded
	Electric Thermostat	Entire Building	5	ĒA	5	6-10 years	Serves gas unit heater. Previously not assessed. Serves exhaust fan. Remote control thermostats serve 3 evaporator fan coil units.

Campus Name: Mcclellan Page : 6 of 26 Assessment Date: 12/16/2021



Catego	ry : Mechanical		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Thermostats - DDC	Entire Building	32	EA	6	6-10 years	Adjusted quantity per zone and damper count
	Thermostats - DDC	Entire Building	3	EA	4	0-1 year	A few thermostats do not send signal to actuators, not calibrated.
Ventilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	Serves electrical room, 2 found, thru wall
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	25	LF	6	6-10 years	Serves kitchen, previously not assessed
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	assesseu
Catego	ry : Plumbing		В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - 150000 - 300000 BTU/HR	Boiler Room Boiler Room	1 1	EA EA	6 6	6-10 years 6-10 years	2019 installation
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	58,108	SF	4	2-5 years	Water pressure to top floor is minima
	Domestic Piping-Hot Water Return Risers	Entire Building	58,108	SF	4	2-5 years	Occasional leak repaired
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,108	SF	4	2-5 years	There are pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,108	SF	4	2-5 years	There are pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,108	SF	4	2-5 years	Leaks occasionally repaired, internally partially calcified
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,108	SF	4	2-5 years	Pipes are extensively calcifies
	Sanitary Piping	Entire Building	58,108	SF	6	6-10 years	
	Storm Piping	Entire Building	58,108	SF	6	6-10 years	
			· · · · · · · · · · · · · · · · · · ·			6-10 years	
	Vent Piping	Entire Building	58,108	SF	6	0-10 years	
Pumps	Vent Piping	Entire Building	58,108	SF	ь	0-10 years	

Campus Name: Mcclellan Page: 7 of 26 Assessment Date: 12/16/2021



#### **George B McClellan Elementary School**

3527 S Wallace STREET, Chicago, IL 60609

						0.	DET O Wallace OTTLET, Officago, in 00003
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pumps - Sump-Simplex	Basement	1	EA	7	10+ years	Under recently constructed elevator addition, previously not assessed
	Pumps - Sump-Simplex	Basement	2	EA	4	0-1 year	Rusted, deteriorated
Catego	ry : Room	Building : Main					
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Plaster/Drywall	1.5 Floor - 109 Teachers Lounge	260	SF	7	10+ years	
	Doors - Side-lite	1.5 Floor - 109 Teachers Lounge	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - 109 Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	1.5 Floor - 109 Teachers Lounge	260	SF	6	6-10 years	
	Lighting - Pendent/Surface	1.5 Floor - 109 Teachers Lounge	4	EA	7	10+ years	
	Power Distribution	1.5 Floor - 109 Teachers Lounge	4	EA	7	10+ years	
	Storage/ Closet	1.5 Floor - 109 Teachers Lounge	120	SF	5	2-5 years	

2-5 years Storage/ Closet 1.5 Floor - 109 Teachers Lounge SF 7 Walls - Plaster/Drywall 1.5 Floor - 109 Teachers Lounge 700 10+ years AC Unit 1st Floor - 107 Main Office 1 EΑ 6-10 years Ceiling - Plaster/Drywall SF 7 1st Floor - 107 Main Office 525 10+ years SF Doors - Transom Window 1st Floor - 107 Main Office 40 7 10+ years Doors - Wood Doors inclu hw 1st Floor - 107 Main Office EΑ 6 10+ years 1 Floor - Tile 1st Floor - 107 Main Office 525 SF 6 6-10 years EΑ Lighting - Pendent/Surface 1st Floor - 107 Main Office 10 7 10+ years Power Distribution 1st Floor - 107 Main Office 6 EΑ 7 10+ years Walls - Plaster/Drywall SF 7 1st Floor - 107 Main Office 324 10+ years Walls - Plaster/Drywall 1st Floor - 107 Main Office SF 7 760 10+ years Ceiling - Plaster/Drywall SF 1st Floor - 107A Office inside main 195 6 10+ years office, conference room Doors - Transom Window 1st Floor - 107A Office inside main 35 SF 7 10+ years office, conference room Doors - Wood Doors inclu hw 1st Floor - 107A Office inside main 2 EΑ 7 10+ years office, conference room Floor - Carpet 1st Floor - 107A Office inside main 195 SF 6 6-10 years Flooring needs to be cleaned around office, conference room sink. Lighting - Pendent/Surface 1st Floor - 107A Office inside main 7 EΑ 7 10+ years office, conference room Power Distribution 1st Floor - 107A Office inside main 2 FΑ 7 10+ years office, conference room Walls - Plaster/Drywall 1st Floor - 107A Office inside main 300 SF 7 10+ years office, conference room Walls - Plaster/Drywall 1st Floor - 107A Office inside main 300 SF 6 10+ years office, conference room AC Unit 1st Floor - 107B Principal office 1 EΑ 7 6-10 years inside main office Ceiling - Plaster/Drywall 1st Floor - 107B Principal office 160 SF 7 10+ years

Campus Name: Mcclellan Page : 8 of 26 Assessment Date: 12/16/2021



atego	ry : Room		В	uilding	: Main			
			0 111		<b>.</b>	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Dagra Cida lita	inside main office	4.0	SF	7	40		
	Doors - Side-lite	1st Floor - 107B Principal office inside main office	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - 107B Principal office	1	EA	7	10+ years		
	Doors - Wood Doors Inclu IIW	inside main office	'	LA	,	10+ years		
	Floor - Wood	1st Floor - 107B Principal office	160	SF	6	10+ years		
	11001 11004	inside main office	100	O.	Ü	ioi youlo		
	Lighting - Pendent/Surface	1st Floor - 107B Principal office	3	EA	7	10+ years		
	3 3	inside main office				,		
	Power Distribution	1st Floor - 107B Principal office	4	EA	7	10+ years		
		inside main office				•		
	Storage/ Closet	1st Floor - 107B Principal office	5	SF	7	10+ years		
		inside main office						
	Walls - Plaster/Drywall	1st Floor - 107B Principal office	312	SF	7	10+ years		
		inside main office						
	Walls - Plaster/Drywall	1st Floor - 107B Principal office	312	SF	6	10+ years		
	- · · · · · · · · · · · · · · · · · · ·	inside main office			_			
	Ceiling - Plaster/Drywall	2nd Floor Teacher's Lounge	139	SF	7	10+ years		
	Doors - Side-lite	2nd Floor Teacher's Lounge	70	SF	7	10+ years		
	Doors - Transom Window	2nd Floor Teacher's Lounge	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Teacher's Lounge	1	EA	7	10+ years		
	Floor - Tile	2nd Floor Teacher's Lounge	139	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor Teacher's Lounge	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor Teacher's Lounge	670	SF	6	10+ years		
	Ceiling - Exposed	Basement Engineer's Office at Middle West	150	SF	4	0-1 year	Cracking.	
	Doors - Wood Doors inclu hw	Basement Engineer's Office at Middle West	1	EA	6	6-10 years		
	Floor - Tile	Basement Engineer's Office at	150	SF	7	10+ years		
	11001 - 1116	Middle West	150	OI.	,	10+ years		
	Lighting - Pendent/Surface	Basement Engineer's Office at	2	EA	7	10+ years		
	gg : 0acg aacc	Middle West	_		•	.o. you.o		
	Power Distribution	Basement Engineer's Office at	10	EA	7	10+ years		
		Middle West				,		
	Walls - Plaster/Drywall	Basement Engineer's Office at	484	SF	6	10+ years		
	·	Middle West				•		
	Ceiling - Exposed	Counselors Room A Basement	506	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Counselors Room A Basement	1	EA	7	10+ years		
	Floor - Tile	Counselors Room A Basement	506	SF	6	6-10 years		
	Lighting - Pendent/Surface	Counselors Room A Basement	6	ĒΑ	7	10+ years		
	Power Distribution	Counselors Room A Basement	12	EA	7	10+ years		
	Storage/ Closet	Counselors Room A Basement	30	SF	7	10+ years		
	Walls - Masonry	Counselors Room A Basement	800	SF	6	10+ years		
	Ceiling - Exposed	Counselors Room B Basement	170	SF	7	10+ years		
	Genning - Exposed	Counseiors Room o basement	170	3F	1	10+ years		



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Counselors Room B Basement	1	EA	7	10+ years	
	Floor - Tile	Counselors Room B Basement	170	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselors Room B Basement	4	EA	7	10+ years	
	Power Distribution	Counselors Room B Basement	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselors Room B Basement	630	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Manager	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Manager	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen Manager	35	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager	1	EA	7	10+ years	
	Power Distribution	Kitchen Manager	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Manager	243	SF	7	10+ years	
Gvmnas	ia						
	Ceiling - Plaster/Drywall	3rd Floor	3,465	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	100	SF	5	0-1 year	Water damage.
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	ŭ
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Floor - Wood	3rd Floor	3,565	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	3rd Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Sound System	3rd Floor	1	EΑ	7	6-10 years	
	Stage	3rd Floor	365	SF	6	10+ years	
	Stage Curtain	3rd Floor	2	EA	7	6-10 years	
	Stage-Stairs - Wood	3rd Floor	12	LF	7	10+ years	
	Storage/ Closet	3rd Floor	7	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,360	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	960	SF	6	10+ years	
	Walls - Flastel/Drywall	314 F1001	900	SI	Ü	10+ years	
Kitchen	Ceiling - Lay-in	Basement	500	SF	7	10+ years	
	Doors - Wood Doors inclu hw			EA	7		
		Basement	3	SF		10+ years	
	Floor - Tile Quarry	Basement	500		7	10+ years	
	Lighting - Lay-in	Basement	7	EA	7	10+ years	
	Storage/ Closet	Basement	100	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement	900	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	Lunchroom A	1,435	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom A	3	EA	7	10+ years	
	Floor - Tile	Lunchroom A	1,185	SF	7	10+ years	
	Floor - Tile Quarry			SF			



catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Lunchroom A	15	EA	7	10+ years	
	Serving Line	Lunchroom A	20	LF	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom A	850	SF	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom A	500	SF	7	10+ years	
	Ceiling - Exposed	Lunchroom B	750	SF	7	10+ years	
	Doors - Steel Doors incl hw	Lunchroom B	2	EA	7	10+ years	
	Floor - Tile	Lunchroom B	750	SF	7	10+ years	
	Lighting - Pendent/Surface	Lunchroom B	8	EA	7	10+ years	
	Storage/ Closet	Lunchroom B	75	SF	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom B	500	SF	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom B	500	SF	7	10+ years	
MDF_ID	F						
_	Doors - Steel Doors incl hw	Basement - Inside Counselor B	1	EA	6	10+ years	
	Finishes	Basement - Inside Counselor B	117	SF	7	10+ years	
	Other Cooling Unit	Basement - Inside Counselor B	1	EA	7	6-10 years	Ductless split system.
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	6	SF	5	6-10 years	Water damage throughout walls.
	Janitor's Closet	2nd Floor	60	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	191	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	25	SF	5	0-1 year	Door damaged, no doorknob. Wat damaged wall and ceiling.
	Air Intake Plenums	Basement	250	SF	7	10+ years	damaged wan and cening.
	Boiler Room	Basement	900	SF	5	10+ years	Paint chipping and peeling
	Coal Room	Basement	400	SF	5	10+ years	throughout. Paint chipping and peeling throughout.
	Janitor's Closet	Basement	50	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	72	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	300	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	330	SF	5	10+ years	Paint chipping and peeling throughout.
	Storage Room	Basement	100	SF	7	10+ years	anoughout.
	Storage Room	Basement	100	SF	7	10+ years	
	Storage Room	Basement	125	SF	7	10+ years	
	Storage Room	Basement	125	SF	7	10+ years	
	Storage Room	Basement	500	SF	7	10+ years	
	Storage Room	Basement	25	SF	7	10+ years	
	Storage Room	Basement	125	SF	7	10+ years	
	Storage Room	Basement	150	SF	7	10+ years	



Catego	tegory : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	<ol> <li>1.5 floor inside teachers Lounge, Women's</li> </ol>	30	SF	7	10+ years	
	Ceiling - Plaster/Drywall	<ol> <li>1.5 floor inside teachers Lounge, Women's</li> </ol>	30	SF	5	0-1 year	Minor water damage.
	Doors - Wood Doors inclu hw	<ol> <li>1.5 floor inside teachers Lounge, Women's</li> </ol>	1	EA	6	10+ years	
	Floor - Tile	1.5 floor inside teachers Lounge, Women's	25	SF	6	10+ years	
	Floor - Tile	1.5 floor inside teachers Lounge, Women's	5	SF	5	0-1 year	Cracking.
	Lavatory	1.5 floor inside teachers Lounge, Women's	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1.5 floor inside teachers Lounge, Women's	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 floor inside teachers Lounge, Women's	150	SF	7	10+ years	
	Water Closet	1.5 floor inside teachers Lounge, Women's	1	EA	7	10+ years	
	Accessories	1st Floor inside Classroom #104	46	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor inside Classroom #104	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor inside Classroom #104	1	EA	6	10+ years	
	Floor - Tile	1st Floor inside Classroom #104	46	SF	6	6-10 years	
	Lavatory	1st Floor inside Classroom #104	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor inside Classroom #104	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor inside Classroom #104	260	SF	6	10+ years	
	Water Closet	1st Floor inside Classroom #104	1	EA	6	10+ years	
	Accessories	1st Floor inside Classroom #108	30	SF	7	10+ years	
		1st Floor inside Classroom #108	30	SF	7		
	Ceiling - Plaster/Drywall		30	SF EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor inside Classroom #108	=	SF	7	10+ years	
	Floor - Tile	1st Floor inside Classroom #108 1st Floor inside Classroom #108	30	SF EA	6	6-10 years	
	Lavatory		1		7 7	10+ years	
	Lighting - Pendent/Surface	1st Floor inside Classroom #108	1	EA		10+ years	
	Walls - Plaster/Drywall	1st Floor inside Classroom #108	80	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor inside Classroom #108	80	SF	6	10+ years	
	Water Closet	1st Floor inside Classroom #108	1	EA	6	10+ years	
	Accessories	2nd Floor - Boys Toilet	460	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boys Toilet	460	SF	6	10+ years	Observed peeling paint throughout
	Doors - Transom Window	2nd Floor - Boys Toilet	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Boys Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	460	SF	6	10+ years	
	Floor Drain	2nd Floor - Boys Toilet	1	EA	7	10+ years	
	Lavatory	2nd Floor - Boys Toilet	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Boys Toilet	12	EA	7	6-10 years	
	Partitions	2nd Floor - Boys Toilet	3	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	2nd Floor - Boys Toilet	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Boys Toilet	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Boys Toilet	185	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	490	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	10	SF	4	0-1 year	Missing.
	Water Closet	2nd Floor - Boys Toilet	3	ĒΑ	6	10+ years	3
	Accessories	2nd Floor Girls Toilet across from Library 205	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls Toilet across from Library 205	317	SF	6	10+ years	Observed peeling paint throughout.
	Doors - Wood Doors inclu hw	2nd Floor Girls Toilet across from Library 205	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Toilet across from Library 205	317	SF	6	10+ years	
	Floor Drain	2nd Floor Girls Toilet across from Library 205	1	EA	7	10+ years	
	Lavatory	2nd Floor Girls Toilet across from Library 205	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls Toilet across from Library 205	4	EA	5	0-1 year	Covers missing.
	Partitions	2nd Floor Girls Toilet across from Library 205	8	EA	7	6-10 years	Observed 8 partitions
	Walls - Plaster/Drywall	2nd Floor Girls Toilet across from Library 205	515	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls Toilet across from Library 205	515	SF	7	10+ years	
	Water Closet	2nd Floor Girls Toilet across from Library 205	8	EA	7	6-10 years	
	Accessories	2nd Floor Mens at SE corner	66	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Mens at SE corner	66	SF	7	10+ years	
	Doors - Transom Window	2nd Floor Mens at SE corner	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Mens at SE corner	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Mens at SE corner	66	SF	7	10+ years	
	Lavatory	2nd Floor Mens at SE corner	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Mens at SE corner	2	EA	7	6-10 years	
	Partitions	2nd Floor Mens at SE corner	1	EA	7	6-10 years	
	Urinals	2nd Floor Mens at SE corner	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Mens at SE corner	240	SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain	2nd Floor Mens at SE corner 2nd Floor Mens at SE corner	240	SF SF	7	10+ years 10+ years	
	Water Closet	2nd Floor Mens at SE corner	2 <del>4</del> 0	EA	7	6-10 years	
	Accessories	2nd Floor Mens at SE corner 2nd Floor inside Teacher's Lounge	86	SF	7	6-10 years	
				SF SF			
	Ceiling - Plaster/Drywall	2nd Floor inside Teacher's Lounge	86		7	10+ years	
		and Floor inside Teacherle Leave		_ ^	7	10	
	Doors - Wood Doors inclu hw Floor - Tile	2nd Floor inside Teacher's Lounge 2nd Floor inside Teacher's Lounge	1 86	EA SF	7 6	10+ years 6-10 years	

Campus Name: Mcclellan Page : 13 of 26 Assessment Date: 12/16/2021



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor inside Teacher's Lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor inside Teacher's Lounge	1	EA	7	6-10 years	
	Partitions	2nd Floor inside Teacher's Lounge	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor inside Teacher's Lounge	504	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor inside Teacher's Lounge	10	SF	5	0-1 year	Water damage.
	Water Closet	2nd Floor inside Teacher's Lounge	2	EA	7	6-10 years	
	Accessories	Basement - Unisex	135	SF	7	10+ years	
	Ceiling - Exposed	Basement - Unisex	65	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Unisex	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Unisex	135	SF	7	10+ years	
	Floor Drain	Basement - Unisex	1	EA	7	10+ years	
	Hand Dryer	Basement - Unisex	1	EA	7	6-10 years	
	Lavatory	Basement - Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - Unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Unisex	50	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - Unisex	144	SF	7	10+ years	
	Water Closet	Basement - Unisex	1	EA	7	10+ years	
	Accessories	Basement Boys Toilet	200	SF	7	10+ years	
	Ceiling - Exposed	Basement Boys Toilet	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Boys Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Boys Toilet	200	SF	7	10+ years	
	Floor Drain	Basement Boys Toilet	1	ĒΑ	7	10+ years	
	Hand Dryer	Basement Boys Toilet	1	ĒΑ	7	6-10 years	
	Lavatory	Basement Boys Toilet	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys Toilet	5	EA	7	10+ years	
	Partitions	Basement Boys Toilet	2	ĒΑ	7	10+ years	
	Urinals	Basement Boys Toilet	3	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Basement Boys Toilet	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Boys Toilet	600	SF	7	10+ years	
	Water Closet	Basement Boys Toilet	2	EA	7	10+ years	
	Accessories	Basement Girls Toilet	200	SF	7	10+ years	
	Ceiling - Exposed	Basement Girls Toilet	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Girls Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Girls Toilet	200	SF	7	10+ years	
	Floor Drain	Basement Girls Toilet	1	EA	7	10+ years	
	Hand Dryer	Basement Girls Toilet	1	EA	7	6-10 years	
	Lavatory	Basement Girls Toilet	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Girls Toilet	5	EA	7	10+ years	
	Partitions	Basement Girls Toilet Basement Girls Toilet	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Girls Toilet Basement Girls Toilet	120	SF	7	10+ years	
	Walls - Plaster/Drywaii Walls - Tile Ceramic/ Porcelain	Basement Girls Toilet Basement Girls Toilet	600	SF SF	7	-	
			5	SF EA	7	10+ years	
	Water Closet	Basement Girls Toilet	5	ĽΑ	1	10+ years	

Campus Name: Mcclellan Page : 14 of 26 Assessment Date: 12/16/2021



Catego	ry : Classroom		В	uilding			
_						Recommend	
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #008 (Play Room)						
	Ceiling - Exposed	Basement	778	SF	6	10+ years	Paint is chipping and peeling pretty badly throughout.
	Ceiling - Exposed	Basement	50	SF	4	0-1 year	Water damage and hole.
	Floor - Concrete Epoxy/ Painted	Basement	828	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	11	EΑ	7	10+ years	
	Walls - Masonry	Basement	1,220	SF	7	10+ years	
	Work Sink	Basement	3	EA	7	10+ years	
lassroc	om #101 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	820	SF	7	10+ years	
	Chalk Board	1st Floor	70	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,493	SF	6	10+ years	
lassroc	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	950	SF	6	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	33	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,487	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	25	SF	5	0-1 year	Cracking.
lassroc	om #103 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	942	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	942	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,544	SF	6	10+ years	
Classroo	m #104 (Kindergarten)						
Oldboroc	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	,	
	Floor - Tile	1st Floor	870	SF	6	10+ years	
						10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,512	SF	6	10+ years	
Classroc	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	790	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Cracking.
	Chalk Board	1st Floor	40	LF	4	2-5 years	3
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	10+ years	
	Marker Board	1st Floor	26	LF	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,377	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	15	SF	5	0-1 year	Cracking.
Classros	m #106 (Regular Classroom)						
Classiuc	,	1st Floor	A	Г^	7	6.10	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF CF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	20	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,413	SF	7	10+ years	



Category : Classroom		В	uilding				
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Cracks in plaster.
Classroc	om #108 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	946	SF	6	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Floor - Tile	1st Floor	46	SF	4	0-1 year	Cracking/chipped.
	Lighting - Pendent/Surface	1st Floor	15	ĒA	6	10+ years	3. 11.
	Storage/ Closet	1st Floor	27	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,479	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	Rank changed to update current
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	observation.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Books inclu fiw	2nd Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	133	SF	7	10+ years	Classroom Storage Room
	Walls - Plaster/Drywall	2nd Floor	1,512	SF	6	10+ years	Needs painting above door.
Classros	om #203 (Regular Classroom)						
Classiuc	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	942	SF	7	10+ years 10+ years	Observed painted ceiling. Rank
	Cening - Flaster/Drywall	ZIIU FIOOI	942	SF	1	iu+ years	changed to update current observation.
	Chalk Board	2nd Floor	15	LF	4	2-5 years	observation.
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	942	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	Classroom Storage Closet
	Walls - Plaster/Drywall	2nd Floor	1,544	SF	7	10+ years	Ciassiculii Siciage Ciosel
0.1	·		,-			,	
Classroc	om #204 (Regular Classroom)	01.51-			-	0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	5	2-5 years	Water damage to ceiling.
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	7	10+ years	
lassroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	809	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	809	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	ĒΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	180	SF	7	10+ years	Classroom Storage Closet
	Walls - Plaster/Drywall	2nd Floor	1,397	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	0-1 year	Cracking.
lassroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	851	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	851	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,436	SF	6	10+ years	
lassroo	om #207 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	926	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	2nd Floor	926	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	14	LF	7 7		
		2nd Floor 2nd Floor	150	SF		6-10 years	Classroom Storage Classt
	Storage/ Closet				7	10+ years	Classroom Storage Closet
	Walls - Plaster/Drywall	2nd Floor	1,589	SF	6	10+ years	

Campus Name: Mcclellan Page : 18 of 26 Assessment Date: 12/16/2021



Catego	ry : Classroom		В	uilding	: Main	_	
C#01:	Itam Tuna	l costic-	O. and to	LICA	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	785	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	785	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	159	SF	7	10+ years	Classroom Storage Closet
	Walls - Plaster/Drywall	2nd Floor	1,145	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	m #301 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	829	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	25	SF	5	0-1 year	Water damage.
	Chalk Board	3rd Floor	40	LF	4	2-5 years	rraior damage.
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	854	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	2	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,425	SF	6	10+ years	
laceron	m #302 (Regular Classroom)						
<i>JI</i> 233100	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor		SF	6	•	
	Chalk Board	3rd Floor	950 28	LF	4	10+ years 2-5 years	
	Doors - Transom Window	3rd Floor	6	SF	7		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
			· · · · · · · · · · · · · · · · · · ·	SF	6	10+ years	
	Floor - Wood	3rd Floor	950			10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	2	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,512	SF	6	10+ years	
Classroc	m #303 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	917	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	25	SF	5	0-1 year	Water damage/patched.
	Chalk Board	3rd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	



Doors - Wood Doors inclu hw   3rd Floor   1   EA   7   10+ years   Floor - Wood   3rd Floor   942   SF   6   10+ years   10+
Floor - Wood
Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         8         LF         7         6-10 years           Storage/ Closet         3rd Floor         13         SF         7         10+ years           Walls - Plaster/Drywall         3rd Floor         2         EA         7         6-10 years           Casework         3rd Floor         2         EA         7         10+ years           Cailing - Plaster/Drywall         3rd Floor         6         LF         7         10+ years           Ceiling - Plaster/Drywall         3rd Floor         1,181         SF         6         10+ years           Chalk Board         3rd Floor         44         LF         4         2-5 years           Doors - Transom Window         3rd Floor         8         SF         7         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         7         10+ years           Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         22         SF         7         10+ years
Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         8         LF         7         6-10 years           Storage/ Closet         3rd Floor         13         SF         7         10+ years           Walls - Plaster/Drywall         3rd Floor         2         EA         7         6-10 years           Casework         3rd Floor         2         EA         7         10+ years           Cailing - Plaster/Drywall         3rd Floor         6         LF         7         10+ years           Ceiling - Plaster/Drywall         3rd Floor         1,181         SF         6         10+ years           Chalk Board         3rd Floor         44         LF         4         2-5 years           Doors - Transom Window         3rd Floor         8         SF         7         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         7         10+ years           Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         22         SF         7         10+ years
Marker Board         3rd Floor         8         LF         7         6-10 years           Storage/ Closet         3rd Floor         13         SF         7         10+ years           Walls - Plaster/Drywall         3rd Floor         1,544         SF         6         10+ years           Classroom #304 (Regular Classroom)         AC Units         3rd Floor         2         EA         7         6-10 years           Casework         3rd Floor         6         LF         7         10+ years           Ceiling - Plaster/Drywall         3rd Floor         1,181         SF         6         10+ years           Chalk Board         3rd Floor         44         LF         4         2-5 years           Doors - Transom Window         3rd Floor         8         SF         7         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         7         10+ years           Floor - Wood         3rd Floor         1,181         SF         6         10+ years           Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         12         LF         7         6-10 year
Storage/ Closet Walls - Plaster/Drywall         3rd Floor         13         SF         7         10+ years           Classroom #304 (Regular Classroom)           AC Units         3rd Floor         2         EA         7         6-10 years           Casework         3rd Floor         6         LF         7         10+ years           Ceiling - Plaster/Drywall         3rd Floor         1,181         SF         6         10+ years           Chalk Board         3rd Floor         44         LF         4         2-5 years           Doors - Transom Window         3rd Floor         8         SF         7         10+ years           Doors - Wood Doors inclu hw         3rd Floor         1         EA         7         10+ years           Floor - Wood         3rd Floor         1,181         SF         6         10+ years           Lighting - Pendent/Surface         3rd Floor         21         EA         7         6-10 years           Marker Board         3rd Floor         12         LF         7         6-10 years           Storage/ Closet         3rd Floor         2         SF         7         10+ years
Walls - Plaster/Drywall       3rd Floor       1,544       SF       6       10+ years         Classroom #304 (Regular Classroom)         AC Units       3rd Floor       2       EA       7       6-10 years         Casework       3rd Floor       6       LF       7       10+ years         Ceiling - Plaster/Drywall       3rd Floor       1,181       SF       6       10+ years         Chalk Board       3rd Floor       44       LF       4       2-5 years         Doors - Transom Window       3rd Floor       8       SF       7       10+ years         Doors - Wood Doors inclu hw       3rd Floor       1       EA       7       10+ years         Floor - Wood       3rd Floor       1,181       SF       6       10+ years         Lighting - Pendent/Surface       3rd Floor       21       EA       7       6-10 years         Marker Board       3rd Floor       12       LF       7       6-10 years         Storage/ Closet       3rd Floor       2       SF       7       10+ years
AC Units 3rd Floor 2 EA 7 6-10 years Casework 3rd Floor 6 LF 7 10+ years Ceiling - Plaster/Drywall 3rd Floor 1,181 SF 6 10+ years Chalk Board 3rd Floor 44 LF 4 2-5 years Doors - Transom Window 3rd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Wood 3rd Floor 1,181 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
AC Units 3rd Floor 2 EA 7 6-10 years Casework 3rd Floor 6 LF 7 10+ years Ceiling - Plaster/Drywall 3rd Floor 1,181 SF 6 10+ years Chalk Board 3rd Floor 44 LF 4 2-5 years Doors - Transom Window 3rd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Wood 3rd Floor 1,181 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
Casework 3rd Floor 6 LF 7 10+ years Ceiling - Plaster/Drywall 3rd Floor 1,181 SF 6 10+ years Chalk Board 3rd Floor 44 LF 4 2-5 years Doors - Transom Window 3rd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Wood 3rd Floor 1,181 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
Ceiling - Plaster/Drywall  Sr
Chalk Board 3rd Floor 44 LF 4 2-5 years Doors - Transom Window 3rd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Wood 3rd Floor 1,181 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
Doors - Transom Window3rd Floor8SF710+ yearsDoors - Wood Doors inclu hw3rd Floor1EA710+ yearsFloor - Wood3rd Floor1,181SF610+ yearsLighting - Pendent/Surface3rd Floor21EA76-10 yearsMarker Board3rd Floor12LF76-10 yearsStorage/ Closet3rd Floor2SF710+ years
Doors - Wood Doors inclu hw3rd Floor1EA710+ yearsFloor - Wood3rd Floor1,181SF610+ yearsLighting - Pendent/Surface3rd Floor21EA76-10 yearsMarker Board3rd Floor12LF76-10 yearsStorage/ Closet3rd Floor2SF710+ years
Floor - Wood 3rd Floor 1,181 SF 6 10+ years Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
Lighting - Pendent/Surface3rd Floor21EA76-10 yearsMarker Board3rd Floor12LF76-10 yearsStorage/ Closet3rd Floor2SF710+ years
Marker Board 3rd Floor 12 LF 7 6-10 years Storage/ Closet 3rd Floor 2 SF 7 10+ years
Storage/ Closet 3rd Floor 2 SF 7 10+ years
M II DI ( /D II ) 0   EI
Walls - Plaster/Drywall 3rd Floor 1,512 SF 6 10+ years
Classroom #306 (Regular Classroom)
AC Units 3rd Floor 1 EA 7 6-10 years
Casework 3rd Floor 4 LF 7 10+ years
Ceiling - Plaster/Drywall 3rd Floor 416 SF 7 10+ years
Doors - Transom Window 3rd Floor 6 SF 7 10+ years
Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years
Floor - Wood Sold Hold HW Sid Floor 416 SF 6 10+ years
Lighting - Pendent/Surface 3rd Floor 3 EA 7 6-10 years
Marker Board 3rd Floor 6 LF 7 6-10 years
Walls - Plaster/Drywall 3rd Floor 1,236 SF 6 10+ years
Classroom #307 (Regular Classroom)
AC Units 3rd Floor 1 EA 7 6-10 years
Casework 3rd Floor 18 LF 7 10+ years
Ceiling - Plaster/Drywall 3rd Floor 925 SF 6 10+ years
Chalk Board 3rd Floor 25 LF 4 2-5 years
Doors - Transom Window 3rd Floor 6 SF 7 10+ years
Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years
Floor - Wood 3rd Floor 925 SF 6 10+ years
Lighting - Pendent/Surface 3rd Floor 21 EA 7 6-10 years
Marker Board 3rd Floor 16 LF 7 6-10 years
Storage/ Closet 3rd Floor 6 SF 7 10+ years
2.2.2.2.2.

Campus Name: Mcclellan Page : 20 of 26 Assessment Date: 12/16/2021



Catego	ory : Classroom		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,572	SF	6	10+ years	
Classro	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	895	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EΑ	7	6-10 years	
	Marker Board	3rd Floor	4	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	87	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	
Catego	ory : Interior		В	uilding	: Main		
						Recommend	

<b>Group</b> Corridor	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
COITIGOL	Ceiling - Exposed	1st Floor	85	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,998	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	5	0-1 year	Cracking.
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	213	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,880	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	10+ years	
	Stairs - Concrete Stairs	1st Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,416	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	0-1 year	Cracking.
	Ceiling - Lay-in	2nd Floor	85	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,665	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	150	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	213	SF	7	10+ years	
	Floor - Wood	2nd Floor	2,452	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	·
	Walls - Plaster/Drywall	2nd Floor	4,948	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	15	SF	5	0-1 year	Water damage.
	Ceiling - Plaster/Drywall	3rd Floor	1,127	SF	6	10+ years	-
	Ceiling - Plaster/Drywall	3rd Floor	25	SF	5	0-1 year	Water damage.
	Doors - Transom Window	3rd Floor	75	SF	7	10+ years	-
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	

Campus Name: Mcclellan Page : 21 of 26 Assessment Date: 12/16/2021



				uilding	· iviaiii					
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Asphalt Floor	3rd Floor	429	SF	7	10+ years				
	Floor - Wood	3rd Floor	723	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years				
	Walls - Plaster/Drywall	3rd Floor	3,241	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	0-1 year	Water damage.			
	Ceiling - Exposed	Basement Corridor North	1,500	SF	6	10+ years				
	Doors - Steel Doors incl hw	Basement Corridor North	1	EA	7	10+ years				
	Floor - Concrete	Basement Corridor North	1,050	SF	7	10+ years				
	Floor - Tile/Sheet	Basement Corridor North	450	SF	7	10+ years				
	Lighting - Pendent/Surface	Basement Corridor North	21	EA	7	10+ years				
	Stairs - Concrete Stairs	Basement Corridor North	25	LF	7	10+ years				
	Student Lockers - One Tier	Basement Corridor North	6	EA	7	10+ years				
	Walls - Masonry	Basement Corridor North	2,170	SF	7	10+ years				
	Walls - Plaster/Drywall	Basement Corridor North	500	SF	7	10+ years				
	Ceiling - Exposed	Basement South	340	SF	7	10+ years				
	Doors - Wood Doors include hw	Basement South	2	EA	7	10+ years				
	Drinking Fountains - Single Fountain	Basement South	3	EA	7	10+ years				
	Floor - Tile/Sheet	Basement South	340	SF	7	10+ years				
	Lighting - Pendent/Surface	Basement South	4	EA	7	10+ years				
	Walls - Plaster/Drywall	Basement South	750	SF	7	10+ years				
	Ceiling - Lay-in	Elevator Lobby South Ground Floor	120	SF	7	10+ years				
	3	Entrance				,				
	Doors - Store Front	Elevator Lobby South Ground Floor	8	EA	7	10+ years				
		Entrance	_			, , , , , , , , , , , , , , , , , , , ,				
	Floor - Concrete	Elevator Lobby South Ground Floor	120	SF	7	10+ years				
		Entrance				, , , , , , , , , , , , , , , , , , , ,				
	Lighting - Pendent/Surface	Elevator Lobby South Ground Floor	4	EA	7	10+ years				
	-ig.i.i.ig	Entrance	·		-	. o . y ca. c				
	Walls - Plaster/Drywall	Elevator Lobby South Ground Floor	416	SF	7	10+ years				
	Traile Tractoristy trail	Entrance	110	O.	•	ioi youro				
	Ceiling - Lay-in	South Elevator Lobby 1st Floor	320	SF	7	10+ years				
	Floor - Tile/Sheet	South Elevator Lobby 1st Floor	320	SF	7	10+ years				
	Lighting - Lay-in	South Elevator Lobby 1st Floor	4	EA	7	10+ years				
	Walls - Plaster/Drywall	South Elevator Lobby 1st Floor	410	SF	7	10+ years				
	vvalio i lastei/Drywali	Could Elevated Lebby 13t 1 loof	410	O.	,	101 years				
Safetv										
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years				
	Security Cameras	Entire Building	1	EA	7	6-10 years	No indoor cameras			
	•	Ŭ				<b>,</b>				
Stairs										
	Ceiling - Plaster/Drywall	North	420	SF	6	10+ years				
	Floor - Asphalt	North	225	SF	6	10+ years				
	Handrails	North	156	LF	7	10+ years				
		North	2	EA	7	6-10 years				

Campus Name: Mcclellan Page : 22 of 26 Assessment Date: 12/16/2021



Category : Interior			Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	North	1	EA	6	6-10 years			
	Stairs - Asphalt	North	75	LF	6	10+ years			
	Walls - Plaster/Drywall	North	2,033	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South	345	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South	5	SF	5	0-1 year	Water damage.		
	Floor - Asphalt	South	350	SF	7	10+ years			
	Handrails	South	158	LF	7	10+ years			
	Lighting - Lay-in	South	2	EA	7	6-10 years			
	Lighting - Pendent/Surface	South	1	EΑ	7	6-10 years			
	Stairs - Asphalt	South	75	LF	7	10+ years			
	Walls - Plaster/Drywall	South	1,880	SF	7	10+ years			
Vertical	Conveyance								
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years			





Category : Site **Building: Site** 

Category . Site		ь	unanig				
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Synthetic	South	5,980	SF	7	6-10 years	
	Lighting	South	4	EA	7	10+ years	
	Surface - Synthetic	South	1,795	SF	7	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	Sinking.
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	<b>o</b>
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	7	10+ years	
encina							
	Fencing - Chain Link	Entire Site	482	LF	7	10+ years	Quantity Adjusted
	Fencing - Chain Link	Entire Site	32	LF	4	0-1 year	Bent/curling.
	Fencing - Iron and Concrete Post	Entire Site	60	LF	6	6-10 years	· ·
	Fencing - New Standard Ornamental	Entire Site	431	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	0-1 year	Falling over.
andscar	oe						
	Benches	Entire Site	6	EA	7	10+ years	
	Benches	Entire Site	5	EA	4	0-1 year	Aged/Deteriorated/broken - visible ro
	Landscape - Grass	Entire Site	1,554	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	581	SF	7	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	743	SF	4	0-1 year	Broken/cracked.
	Parkway trees	Entire Site	15	ĒA	7	10+ years	
	Planting Beds/ Area	Entire Site	108	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	11,706	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	4,993	SF	6	6-10 years	
	Trash Receptacles	Entire Site	2	EΑ	7	6-10 years	
arking L	ot						
<u></u>	Concrete Curbs	NE Parking Lot	163	LF	6	10+ years	
	Concrete Curbs	NE Parking Lot	15	LF	4	0-1 year	Broken - Significant damage
	Interior Plantings	NE Parking Lot	50	LF	5	2-5 years	Clean/Weed/Seed
	Surface - Asphalt	NE Parking Lot	11,128	SF	4	0-1 year	Cracking and holes.
	Trash Enclosure - Chain Links	NE Parking Lot	48	SF	6	10+ years	Cracking and notes.
	Vehicular Screening	NE Parking Lot	60	LF	6	10+ years	
laygrou	ad						
iayyiuu	Equipment - Pre K 3-5	Entire Site	1	EA	7	10+ years	
	Equipment - School Age 5-12	Entire Site	1	EA	7	10+ years	
	Equipment - School Age 3-12	LIMITE ONE	1	LA	,	TOT years	



Category : Site			В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	Entire Site	1,500	SF	6	10+ years	
	Surface - Poured Surface	Entire Site	1,625	SF	6	10+ years	
_Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	51	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	106	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,250	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	7	SF	4	0-1 year	Uneven.
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	5	2-5 years	Base cracked.
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	5	0-1 year	Broken Stone letter "E"
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	5	6-10 years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Mcclellan Page: 25 of 26 Assessment Date: 12/16/2021

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

,			Doom	Floor Plan Room	Aroo	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Room Number	Number	Area (SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	3rd Floor	301	301	854	140	80	N	N
Kindergarten	Regular Classroom	1st Floor	103	103	942	100	48	N	N
Kindergarten	Regular Classroom	1st Floor	104	104	870	175	100	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	946	175	100	N	N
Play Room	Play Room	Basement	800	800	828	60	30	N	N
Regular Classroom	Office	3rd Floor	306	306	416	35	20	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	820	175	100	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	950	175	100	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	800	140	80	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	830	140	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	950	175	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	942	100	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	950	175	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	809	75	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	851	140	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	926	75	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	785	75	36		
Regular Classroom	Regular Classroom	3rd Floor	302	302	950	175	100	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	942	100	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,181	175	100	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	925	75	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	895	180	96	N	N