

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1962	2	43,300
Campus Total			43,300

Catego	Category : Exterior				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	Entrance 2 - NW	4	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 2 - NW	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 2 - NW	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 2 - NW	46	LF	5	1-2 years	Cracked Concrete
	Exterior Doors - Exterior FRP Door	Entrance 3 - NE	4	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 3 - NE	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 3 - NE	4	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 3A - East	4	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 3B - East	2	EA	6	6-10 years	
	Entrance Control - Audio and Video	Entrance 4 - East	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 4 - East	2	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 4A - SE	1	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 4A - SE	2	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 5 - SE	2	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 5 - SE	2	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 6 - SW	2	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 6 - SW	2	EA	6	6-10 years	
	Exterior Doors - Store Front	Entrance 7 - Courtyard	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Main Entrance 1 - West	1	EA	6	6-10 years	
	Exterior Doors - Side lite	Main Entrance 1 - West	2	EA	6	6-10 years	
	Exterior Doors - Store Front	Main Entrance 1 - West	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Main Entrance 1 - West	2	EA	6	6-10 years	
	Power Door Operator and Controls	Main Entrance 1 - West	1	EA	4	0-1 year	Disrepair



Category	/:Exterior		B	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
oundatio	n					-		
	Foundation - Concrete	Entire Building	1,280	LF	7	10+ years		
	Foundation - Concrete	Entire Building	, 10	LF	6	10+ years		
	Superstructure - Steel	Entire Building	43,300	SF	7	10+ years		
		Linito Dullaling	10,000	0.	•	lot youro		
ghting								
	Exterior Lighting - Wall Mounted	Entire Building	31	EA	6	6-10 years		
oof Syste	em							
,	Access Ladder - Metal	Roof 1 - main north	1	EA	7	6-10 years		
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1 - main north	23	LF	6	10+ years		
	Liner					5		
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1 - main north	5	LF	5	2-5 years	Deteriorating Mortar Joints	
	Liner		(=0	. –				
	Coping - Metal	Roof 1 - main north	476	LF	6	2-5 years		
	Downspouts - Interior Downspouts	Roof 1 - main north	96	LF	5	2-5 years		
	Roof - Asphalt Gravel Ballast	Roof 1 - main north	13,210	SF	5	2-5 years		
	Roof - Asphalt Gravel Ballast	Roof 1 - main north	500	SF	4	0-1 year	Missing Ballast - Bubbling of Roo	
	Roof Hatch - Metal	Roof 1 - main north	1	EA	5	6-10 years	No operational latch - Hinges or r aligned/damaged	
	Roof Structure - Steel / Metal Deck/	Roof 1 - main north	13,710	SF	7	10+ years		
	Concrete Topping							
	Coping - Metal	Roof 2 - elev	38	LF	6	6-10 years		
	Downspouts - Exterior Downspouts	Roof 2 - elev	15	LF	6	6-10 years		
	Parapet - Parapet < 16" Height	Roof 2 - elev	28	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 2 - elev	90	SF	6	6-10 years		
	Roof Structure - Concrete				7			
		Roof 2 - elev	90	SF	-	10+ years		
	Chimney - Metal Flue	Roof 3 South	26	LF	6	6-10 years		
	Coping - Metal	Roof 3 South	550	LF	6	6-10 years		
	Downspouts - Interior Downspouts	Roof 3 South	65	LF	6	6-10 years		
	Downspouts - Interior Downspouts	Roof 3 South	26	LF	5	2-5 years		
	Roof - Asphalt Gravel Ballast	Roof 3 South	11,645	SF	5	2-5 years	Leaks Reported where Roof mee	
						-	wall north at courtyard/Trees drip overhang and on roof	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3 South	11,645	SF	7	10+ years		
	Access Ladder - Metal	Roof 4 - Gym	2	EA	7	6-10 years		
	Coping - Metal	Roof 4 - Gym	260	LF	6	6-10 years		
	Downspouts - Interior Downspouts	Roof 4 - Gym	48	LF	6	6-10 years		
	Roof - Asphalt Gravel Ballast	Roof 4 - Gym		SF	6			
			3,800		-	6-10 years	Polloot missing is as at	
	Roof - Asphalt Gravel Ballast	Roof 4 - Gym	200	SF	5	2-5 years	Ballast missing in spots - Roofing Exposed/Blistering	
	Roof Hatch - Metal	Roof 4 - Gym	1	EA	5	2-5 years	No operational latch	



Catego	ry : Exterior		B	uilding	• Main		4413 3 King DKIVE, Chicago, ie 00030
Calego	ry. Exterior		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ereup	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4 - Gym	4,000	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	8,008	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	528	SF	5	6-10 years	Spot tuck pointing needed -
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,284	SF	5	2-5 years	Cracking/Deteriorating Mortar Joints. Rust/Corrosion present
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	6,710	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	795	SF	6	6-10 years	
	Lintels - Steel	Entire Building	62	LF	6	10+ years	
	Windows - Insulated Panel	Entire Building	692	SF	5	2-5 years	Rust/Deteriorating Hardware
	Windows - Louver	Entire Building	117	SF	5	2-5 years	Rust/Corrosion - worned
Catego	ry : Electrical		В	uilding	: Main		
				Ţ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	9	EA	6	6-10 years	Recently serviced
	Emergency Battery Packs - Corridors and Stairs	Entire Building	23	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	43,300	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	43,300	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,682	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,300	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,152	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,250	SF	6	10+ years	
_Main Se	rvice						
	Main Electrical Service - 1000 A	Electrical Room	1	EA	4	2-5 years	Old, not reliable, functional,
	120/208/3PH			<u> </u>		20 90010	replacement parts not available
	PA System	Entire Building	43,300	SF	5	6-10 years	
		-					



	Schools						4415 S King DRIVE, Chicago, IL 60653
Catego	ry : Electrical		В	uilding	: Main		
Group	ltem - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	nem - Type	Location	Quantity	001	INAIIK	Replacement	Comments
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	1-2 years	Missing circuit breakers, live
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Recently serviced, 2 found
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	-
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	

Category : Fire Protection

amp

Category : Fire Protection	В	uilding				
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building	1 43,300	EA SF	6 6	6-10 years 10+ years	
Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	43,300	SF	6	10+ years	

Category · Mechanical

Catego	Category : Mechanical			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Air Hand	ling Systems						
	Make Up Air Unit- Indoor Mounted- Gas Heating Coils - Less than 6000 cfm	1st Floor	1	EA	5	6-10 years	Ceiling mounted in kitchen, recently serviced
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Attic	1	EA	5	6-10 years	Serves multipurpose room, recently serviced
	Air Intake	Attic	1	EA	6	6-10 years	
	Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - Greater than 30,000 cfm	Roof	1	EA	6	6-10 years	Serves north side of building
Boiler S	vstems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	



Calego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
leating	Devices					0.40	
	Wall Heater - Electric	1st Floor	2	EA	5	6-10 years	
	Unit Heater - Hot Water	Boiler Room	1	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	190	LF	6	10+ years	Recently serviced
	Fin Tube - Hot Water	Entire Building	60	LF	5	6-10 years	Recently serviced
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	12	EA	5	6-10 years	Recently serviced
Mechani	cal Plumbing						
	Hydronic Supply and Return - Galvanized	Entire Building	700	LF	6	10+ years	Insulated
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Serves air handler
	Hot Water Pump - Less than 10	Entire Building	2	EA	5	6-10 years	
-							
empera	ture Control	Entire Duilding	42.200	0	<u>^</u>	10	Cotture a strugger de d
	DDC System	Entire Building	43,300	SF	6	10+ years	Software not upgraded
	Electric Thermostat	Entire Building	7	EA	6	6-10 years	Serves unit heater, single zone iten
	Thermostats - DDC	Entire Building	29	EA	6	10+ years	
	Thermostats - DDC	Entire Building	1	EA	4	1-2 years	Does not work, temperature manua controlled
Jnit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	22	EA	6	10+ years	
	Heating Coils Only	C C				-	
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	8	EA	5	6-10 years	
	Heating Coils Only	0					
/entilatio							
undation	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	In kitchen
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Behind grill, above ceiling mounted
		Entito Dananig		273	Ũ	e le jeure	serviced, motor replaced, not
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entiro Building	6	EA	6	6 10 years	accessible
	CFM	Entire Building	0	EA	U	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	14	EA	6	6-10 years	
	CFM						
	Roof Mounted Duct Work	Entire Building	95	LF	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



	Schools						4415 S King DRIVE, Chicago, IL 6
						Replacement	
ot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
bing							
2119	Domestic Piping-Hot Water Return Lines	Entire Building	43,300	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	43,300	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	43,300	SF	6	10+ years	
	Fixtures	Ū.				-	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	43,300	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	43,300	SF	6	10+ years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	43,300	SF	6	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	43,300	SF	5	6-10 years	
	Storm Piping	Entire Building	43,300	SF	6	10+ years	
	Vent Piping	Entire Building	43,300	SF	6	10+ years	
umps							
umpa	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	2	0-1 year	Does not work, not needed,
		3				,	abandoned
	Pumps - Ejector-Duplex	Entire Building	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Under elevator
atego	ry : Room		В	uilding	: Main		
alogo				anang	· mann	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Iminist	trative Suites/Offices						
	AC Unit	Assistant Principal's Office	1	EA	7	6-10 years	
	Ceiling - Splined	Assistant Principal's Office	135	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Assistant Principal's Office	135	SF	7	10+ years	
	Lighting - Pendent/Surface	Assistant Principal's Office	2	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office	8	EA	6	10+ years	
	Storage/ Closet	Assistant Principal's Office	16	SF	7	10+ years	
	Walls - Concrete Block	Assistant Principal's Office	316	SF	6	10+ years	
	Ceiling - Splined	Counselor's Office	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Counselor's Office	90	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselor's Office	4	EA	7	6-10 years	
	Power Distribution	Counselor's Office	8	EA	6	10+ years	
	Storage/ Closet	Counselor's Office	56	SF	7	10+ years	
	Walls - Concrete Block	Counselor's Office	300	SF	6	10+ years	
	Work Sink	Counselor's Office	1	FΔ	7	10+ years	

Work SInk

1

ΕA

7

10+ years

Counselor's Office



4415 S I	King DRIVE	Chicago,	IL 60653

<u> </u>	Category : Room Building : Main							
Calego			D	unung	. Walli	Decommond		
Crown	Hom Tuno	Location	Quantity	UOM	Donk	Recommend Replacement	Commente	
Group	Item - Type			SF	Rank		Comments	
	Ceiling - Splined	Diverse Learning Team Room Used as Engineer's Office	260		6	10+ years		
	Doors - Wood Doors inclu hw	Diverse Learning Team Room Used as Engineer's Office	1	EA	6	10+ years		
	Floor - Tile/Sheet	Diverse Learning Team Room Used as Engineer's Office	260	SF	7	10+ years		
	Lighting - Pendent/Surface	Diverse Learning Team Room Used as Engineer's Office	8	EA	7	6-10 years		
	Power Distribution	Diverse Learning Team Room Used as Engineer's Office	8	EA	6	10+ years		
	Storage/ Closet	Diverse Learning Team Room Used as Engineer's Office	65	SF	7	10+ years		
	Walls - Concrete Block	Diverse Learning Team Room Used as Engineer's Office	512	SF	6	10+ years		
	Work Sink	Diverse Learning Team Room Used as Engineer's Office	1	EA	7	10+ years		
	AC Unit	Engineer's Office in Boiler Room	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Engineer's Office in Boiler Room	102	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Engineer's Office in Boiler Room	102	EA	6	10+ years		
	Floor - Tile/Sheet	Engineer's Office in Boiler Room	102	SF	7	10+ years		
	Lighting - Pendent/Surface	Engineer's Office in Boiler Room	102	EA	7	6-10 years		
	Power Distribution	Engineer's Office in Boiler Room	12	EA	6	6-10 years		
	Storage/ Closet	Engineer's Office in Boiler Room	50	SF				
	Walls - Concrete Block		320	SF	7 6	10+ years		
		Engineer's Office in Boiler Room				10+ years		
	Ceiling - Plaster/Drywall	Gym Office	80	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years		
	Floor - Tile	Gym Office	80	SF	6	10+ years		
	Lighting - Pendent/Surface	Gym Office	2	EA	7	6-10 years		
	Power Distribution	Gym Office	4	EA	6	6-10 years		
	Walls - Concrete Block	Gym Office	160	SF	6	10+ years		
	Ceiling - Splined	Lunch Office	90	SF	6	10+ years		
	Doors - Side-lite	Lunch Office	63	SF	6	10+ years		
	Doors - Transom Window	Lunch Office	3	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Lunch Office	1	EA	6	10+ years		
	Floor - Tile/Sheet	Lunch Office	90	SF	7	10+ years		
	Lighting - Pendent/Surface	Lunch Office	2	EA	7	6-10 years		
	Power Distribution	Lunch Office	4	EA	6	10+ years		
	Walls - Concrete Block	Lunch Office	285	SF	6	10+ years		
	Work SInk	Lunch Office	2	EA	7	10+ years		
	AC Unit	Principal's Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Principal's Office	456	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years		
	Floor - Tile/Sheet	Principal's Office	456	SF	7	10+ years		
	Lighting - Pendent/Surface	Principal's Office	9	EA	7	6-10 years		
			Ũ		•	2.0,00.0		



4415 S King DRIVE, Chicago, IL 60653 Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution Principal's Office 12 ΕA 6 10+ vears Principal's Office 760 SF 6 Walls - Concrete Block 10+ years Work SInk Principal's Office EΑ 7 10+ years 1 Ceiling - Splined Teacher's lounge 676 SF 6 10+ years Doors - Wood Doors inclu hw Teacher's lounge EΑ 6 10+ years 1 SF Floor - Tile/Sheet 676 7 Teacher's lounge 10+ years Lighting - Pendent/Surface Teacher's lounge ΕA 7 6-10 years 12 Power Distribution Teacher's lounge 6 EΑ 6 10+ years Walls - Concrete Block Teacher's lounge 850 SF 6 10+ years SF Ceiling - Plaster/Drywall Waiting/Main Office 130 6 Quantity changed to update current 10+ years observation Ceiling - Splined Waiting/Main Office 130 SF 6 10+ years Quantity changed to update current observation Doors - Wood Doors inclu hw Waiting/Main Office 1 EΑ 6 10+ years Floor - Tile/Sheet Waiting/Main Office SF 7 6-10 years 260 Waiting/Main Office EΑ 7 Lighting - Lay-in 2 6-10 years Lighting - Pendent/Surface Waiting/Main Office 2 7 ΕA 6-10 years Power Distribution Waiting/Main Office 12 ΕA 6 10+ years Storage/ Closet Waiting/Main Office SF 122 7 10+ vears Walls - Concrete Block Waiting/Main Office SF 415 6 10+ years Walls - Masonry Waiting/Main Office 112 SF 6 10+ years Gvmnasia Ceiling - Lay-in 1st Floor 3.300 SF 6 10+ vears Doors - Wood Doors inclu hw 1st Floor 8 EΑ 6 10+ years Floor - Sport Flooring 3,300 SF 7 10+ years 1st Floor ΕA 7 Lighting - Chandelier, Incandescent 1st Floor 1 6-10 years Scoreboards 7 6-10 years 1st Floor 1 ΕA Sound System EΑ 7 1st Floor 1 6-10 years 364 SF Stage 1st Floor 6 10+ years Stage Curtain 1st Floor 6 EΑ 7 10+ years Stage Lift 1st Floor 1 ΕA 7 6-10 years Stage Lighting System 1st Floor 1 EΑ 7 6-10 years Stage-Stairs - Tile 1st Floor 12 LF 6 10+ years Storage/ Closet 1st Floor 110 SF 7 10+ years Walls - Masonry SF 1st Floor 3,720 6 10+ years Kitchen Ceiling - Plaster/Drywall 1st Floor 500 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EΑ 6 10+ years Floor - Tile Quarry SF 1st Floor 500 6 10+ years Lighting - Pendent/Surface 1st Floor ΕA 7 6-10 years 16 LF Serving Line 1st Floor 17 6 10+ years Storage/ Closet 1st Floor 60 SF 7 10+ years



Catego	ategory : Room		В	uilding	4415 S King DRIVE, Chicago, IE 600		
outogo				Recomm			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor	900	SF	6	10+ years	
unch &	Multipurpose Room						
	AC Unit	1st Floor	2	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	1,152	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	1,152	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
MDF_ID	F						
_	Doors - Wood Doors inclu hw	107	1	EA	7	10+ years	
	Finishes	107	91	SF	7	6-10 years	Quantity and Rank changed to update current observation
	Finishes	107	16	SF	5	1-2 years	Damaged tiles
	Other Cooling Unit	107	10	EA	7	10+ years	AC unit above ceiling
		107		L/(,	Tor years	
/lechan	ical/ Service Rooms						
	Boiler Room	1st Floor	680	SF	7	10+ years	
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	65	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	7	10+ years	
	Vaults	1st Floor	65	SF	7	10+ years	
	Janitor's Closet	2nd Floor	72	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	72	SF	7	10+ years	
	Storage Room	2nd Floor	432	SF	7	10+ years	
Prep Ro	om						
•	Casework	210	14	LF	6	10+ years	
	Ceiling - Splined	210	260	SF	6	10+ years	
	Doors - Wood Doors inclu hw	210	2	EA	6	10+ years	
	Floor - Tile/Sheet	210	260	SF	7	10+ years	
	Lighting - Pendent/Surface	210	6	EA	6	6-10 years	
	Walls - Concrete Block	210	105	SF	6	10+ years	
	Walls - Plaster/Drywall	210	665	SF	6	10+ years	
	Walls - Structural Glazed Tile	210	30	SF	6	10+ years	
	Work Sink	210	1	EA	7	10+ years	
Restroo	m						
000000	Accessories	142	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	142	25	SF	6	10+ years	
	Doors - Hardware	142		EA	6	10+ years	
					-	,	



	4415 S King DRIVE, Chicago, IL 60653									
Catego	ry : Room		В	uilding	: Main					
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile	142	25	SF	6	10+ years				
	Lavatory	142	1	EA	6	10+ years				
	Lighting - Pendent/Surface	142	1	EA	6	6-10 years				
	Walls - Concrete Block	142	120	SF	6	10+ years				
	Water Closet	142	1	EA	6	10+ years				
	Accessories	143	25	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	143	25	SF	6	10+ years				
	Doors - Hardware	143	1	EA	6	10+ years				
	Floor - Tile	143	25	SF	6	10+ years				
	Lavatory	143	1	EA	6	10+ years				
	Lighting - Pendent/Surface	143	1	EA	6	6-10 years				
	Walls - Structural Glazed Tile	143	160	SF	6	10+ years				
	Water Closet	143	1	EA	6	10+ years				
	Accessories	1st FI Unisex Staff Restroom	20	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st FI Unisex Staff Restroom	20	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st FI Unisex Staff Restroom	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st FI Unisex Staff Restroom	20	SF	6	10+ years				
	Lavatory	1st FI Unisex Staff Restroom	1	EA	6	10+ years				
	Lighting - Pendent/Surface	1st FI Unisex Staff Restroom	1	EA	7	6-10 years				
	Walls - Structural Glazed Tile	1st FI Unisex Staff Restroom	144	SF	6	10+ years				
	Water Closet	1st FI Unisex Staff Restroom	1	EA	6	10+ years				
	Accessories	1st Floor Boys North	230	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor Boys North	230	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor Boys North	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys North	230	SF	6	10+ years				
	Floor Drain	1st Floor Boys North	1	EA	7	10+ years				
	Hand Dryer	1st Floor Boys North	1	EA	7	6-10 years				
	Lavatory	1st Floor Boys North	3	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor Boys North	4	EA	6	6-10 years				
	Partitions	1st Floor Boys North	1	EA	7	10+ years				
	Urinals	1st Floor Boys North	4	EA	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor Boys North	540	SF	6	10+ years				
	Water Closet	1st Floor Boys North	1	EA	6	10+ years				
	Accessories	1st Floor Boys South	170	SF	7	6-10 years	Quantity changed to update current			
	Ceiling - Plaster/Drywall	1st Floor Boys South	170	SF	6	10+ years	observation			
	Doors - Wood Doors inclu hw	1st Floor Boys South	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys South	170	SF	6	10+ years				
	Floor Drain	1st Floor Boys South	1	EA	7	10+ years				
	Hand Dryer	1st Floor Boys South	1	EA	7	6-10 years				
	Lavatory	1st Floor Boys South	2	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor Boys South	2	EA	7	6-10 years				
	Partitions	1st Floor Boys South	1	EA	7	10+ years				
	Urinals	1st Floor Boys South	2	EA	6	10+ years				



	bry : Room		B	uilding	· Main		4415 S King DRIVE, Chicago, IL 60653
Calego	iy. Room		D	unung	. พลาก	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Walls - Structural Glazed Tile	1st Floor Boys South	425	SF	6	10+ years	Comments
	Water Closet	1st Floor Boys South	1	EA	6	10+ years	
	Accessories	1st Floor Girls South	170	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls South	170	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls South	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls South	170	SF	6	10+ years	
	Floor Drain	1st Floor Girls South	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls South	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls South	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls South	2	EA	7	6-10 years	
	Partitions	1st Floor Girls South	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls South	425	SF	6	10+ years	
	Water Closet	1st Floor Girls South	2	EA	6	10+ years	
	Accessories	1st floor Girls North 117	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor Girls North 117	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor Girls North 117	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor Girls North 117	230	SF	6	10+ years	
	Floor Drain	1st floor Girls North 117	1	EA	7	10+ years	
	Hand Dryer	1st floor Girls North 117	1	EA	7	6-10 years	
	Lavatory	1st floor Girls North 117	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st floor Girls North 117	4	EA	7	6-10 years	
	Partitions	1st floor Girls North 117	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st floor Girls North 117	540	SF	6	10+ years	
	Water Closet	1st floor Girls North 117	5	EA	6	10+ years	
	Accessories	2nd Floor Boys Northeast	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys Northeast	230	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Northeast	230	SF	6	10+ years	
	Floor Drain	2nd Floor Boys Northeast	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Boys Northeast	1	EA	7	6-10 years	
	Lavatory	2nd Floor Boys Northeast	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys Northeast	5	EA	7	6-10 years	
	Partitions	2nd Floor Boys Northeast	1	EA	7	10+ years	
	Urinals	2nd Floor Boys Northeast	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Boys Northeast	540	SF	6	10+ years	
	Water Closet	2nd Floor Boys Northeast	1	EA	6	10+ years	
	Accessories	2nd Floor Girls North	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls North	230	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls North	230	SF	6	10+ years	
	Floor Drain	2nd Floor Girls North	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girls North	1	EA	7	6-10 years	
	Lavatory	2nd Floor Girls North	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls North	4	EA	7	6-10 years	
	Partitions	2nd Floor Girls North	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girls North	540	SF	6	10+ years	
			0+0	0	0	ior yours	



Catego	ry : Room		В	uilding	: Main		
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd Floor Girls North	6	EA	6	10+ years	
	Accessories	Assist Principal Toilet	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Assist Principal Toilet	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Assist Principal Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Assist Principal Toilet	25	SF	6	10+ years	
	Lavatory	Assist Principal Toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Assist Principal Toilet	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Assist Principal Toilet	160	SF	6	10+ years	
	Water Closet	Assist Principal Toilet	1	EA	6	10+ years	
	Accessories	Men's 2nd Floor northwest	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's 2nd Floor northwest	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's 2nd Floor northwest	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's 2nd Floor northwest	25	SF	6	10+ years	
	Floor Drain	Men's 2nd Floor northwest	1	EA	7	10+ years	
	Lavatory	Men's 2nd Floor northwest	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Men's 2nd Floor northwest	1	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Men's 2nd Floor northwest	160	SF	6	10+ years	
	Water Closet	Men's 2nd Floor northwest	1	EA	6	10+ years	
	Accessories	Mens First Floor Northwest	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mens First Floor Northwest	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Mens First Floor Northwest	1	EA	6	10+ years	
	Floor - Tile	Mens First Floor Northwest	30	SF	7	10+ years	
	Floor Drain	Mens First Floor Northwest	1	EA	7	10+ years	
	Lavatory	Mens First Floor Northwest	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Mens First Floor Northwest	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Mens First Floor Northwest	175	SF	6	10+ years	
	Water Closet	Mens First Floor Northwest	1	EA	6	10+ years	
	Accessories	Restroom in 102	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 102	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 102	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	Restroom in 102	60	SF	7	10+ years	
	Floor Drain	Restroom in 102	1	EA	7	10+ years	
	Lavatory	Restroom in 102	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom in 102	1	EA	7	6-10 years	
	Partitions	Restroom in 102	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in 102	310	SF	6	10+ years	
	Water Closet	Restroom in 102	1	EA	6	10+ years	
	Accessories	Restroom in Counselor's Office	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in Counselor's Office	288	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in Counselor's Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in Counselor's Office	288	SF	6	10+ years	
	Floor Drain	Restroom in Counselor's Office	1	EA	7	10+ years	
	Lavatory	Restroom in Counselor's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom in Counselor's Office	1	EA	7	6-10 years	
	Lighting I chucht/oundoe		I	LA	'	o io years	



Category : Room			В	uilding	: Main		
Ū				-		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	Restroom in Counselor's Office	512	SF	6	10+ years	
	Water Closet	Restroom in Counselor's Office	1	EA	6	10+ years	
	Accessories	Staff Restroom/Lunch 156	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Restroom/Lunch 156	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff Restroom/Lunch 156	1	EA	6	10+ years	
	Floor - Tile Quarry	Staff Restroom/Lunch 156	30	SF	7	10+ years	
	Floor Drain	Staff Restroom/Lunch 156	1	EA	7	10+ years	
	Hand Dryer	Staff Restroom/Lunch 156	1	EA	7	6-10 years	
	Lavatory	Staff Restroom/Lunch 156	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Staff Restroom/Lunch 156	1	EA	7	6-10 years	
	Student Lockers - One Tier	Staff Restroom/Lunch 156	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	Staff Restroom/Lunch 156	175	SF	6	10+ years	
	Water Closet	Staff Restroom/Lunch 156	1	EA	6	10+ years	
	Accessories	Women's 2nd Floor northwest	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's 2nd Floor northwest	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's 2nd Floor northwest	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's 2nd Floor northwest	25	SF	6	10+ years	
	Floor Drain	Women's 2nd Floor northwest	1	EA	7	10+ years	
	Lavatory	Women's 2nd Floor northwest	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's 2nd Floor northwest	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Women's 2nd Floor northwest	160	SF	6	10+ years	
	Water Closet	Women's 2nd Floor northwest	1	EA	6	10+ years	
	Accessories	Women's First Floor Northwest by Classroom 103	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's First Floor Northwest by Classroom 103	26	SF	6	10+ years	Quantity changed to update curre observation
	Ceiling - Plaster/Drywall	Women's First Floor Northwest by Classroom 103	4	SF	5	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Women's First Floor Northwest by Classroom 103	1	EA	6	10+ years	
	Floor - Tile	Women's First Floor Northwest by Classroom 103	30	SF	6	10+ years	
	Floor Drain	Women's First Floor Northwest by Classroom 103	1	EA	7	10+ years	
	Lavatory	Women's First Floor Northwest by Classroom 103	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's First Floor Northwest by Classroom 103	1	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Women's First Floor Northwest by Classroom 103	175	SF	6	10+ years	
	Water Closet	Women's First Floor Northwest by Classroom 103	1	EA	6	10+ years	



Irvin C Mollison Elementary School 4415 S King DRIVE, Chicago, IL 60653

Catego	ry : Classroom		B	uilding	• Main		4415 5 King DRIVE, Chicago, IE 00055
Galego				unung	· mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #101 (Regular Classroom)	2004.000	Quantity			Replacement	
_0/255100	AC Units	1st Floor	1	EA	7	6 10 years	
	Casework	1st Floor		LF	7	6-10 years 10+ years	
	Casework Ceiling - Splined	1st Floor	16 792	SF	6		
	•	1st Floor	36	SF	7	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor	30 1	EA	6 6	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years 6-10 years	
		1st Floor	24	EA	6	,	
	Lighting - Pendent/Surface	1st Floor	12			6-10 years	
	Marker Board			LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	904	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	6-10 years	
	Doors - Side-lite	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	904	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #103 (Regular Classroom)						
Classion	AC Units	1st Floor	1		7	0.40	
			1	EA LF	7	6-10 years	
	Casework	1st Floor	16		6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	904	SF	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
		13(1100)	12	LI	'	o io years	



Catego	ry : Classroom		R	uilding	: Main		
Jaicgo	ry . 01033100111			unung	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Walls - Concrete Block	1st Floor	904	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
			•	273		To t youro	
lassroo	om #105 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	47	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	1,816	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	38	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,500	SF	6	10+ years	
lassroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	904	SF	7	10+ years	
lassro	om #107 (Special Education)						
71000100	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	588	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
						•	
	Doors - Wood Doors inclu hw	1st Floor	-	EA SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	588		7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	930	SF	6	10+ years	
lassroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
			1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor					
	Doors - Wood Doors inclu hw Floor - Tile/Sheet	1st Floor 1st Floor	792	SF	7	10+ years	
			-			10+ years 6-10 years	Quantity changed to update currer observation



Category : Classroom

oalogo	ry : Classroom		D	ullaing	. Wall		
C	Hom Tune	Location	Quantity		Donk	Recommend	Commente
Group	Item - Type Walls - Concrete Block	1st Floor	Quantity 904	UOM SF	Rank 7	Replacement	Comments
	Walls - Concrete Block	IST FIOOI	904	35	/	10+ years	
lassroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	904	SF	6	10+ years	
			001	0.	Ũ	io youro	
assroc	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	792	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	792	SF	7	10+ years	Quantity changed to update cur observation
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	Observation
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	904	SF	7	10+ years	
assro	om #142 (Kindergarten)						
000100	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	296	SF	6	10+ years	
	Ceiling - Splined	1st Floor	778	SF	6	10+ years	
	Doors - Side-lite	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,074	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	96	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	973	SF	7	10+ years	
	Work Sink	1st Floor	973 1	EA	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	WOR SINK	151 F1001	1	EA	1	iu+ years	
assroc	om #143 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	

Building : Main



0					Mair		4415 S King DRIVE, Chicago, IL 6065
Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	296	SF	6	10+ years	
	Ceiling - Splined	1st Floor	778	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,074	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	973	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
	om #202 (Regular Classroom)						
Jassio	AC Units	2nd Floor	1		7	0.40	
		2nd Floor	1	EA LF	7	6-10 years	
	Casework		16		6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
Classroo	om #203 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
		2nd Floor	792	SF	7	10+ years	
	Floor - Tile/Sheet	2110 1 1001	102				
	Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor	24	ĒA	6	6-10 years	
					6 6		



Category : Classroom			В	uilding	: Main		4415 C King DKIVE, Onicago, iE 00000
U	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	2nd Floor	2	EA	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
Classroo	om #205 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	790	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	2	SF	4	0-1 year	Missing
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Side-lite	2nd Floor	36	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	26	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classro	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	ĒA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
				υ.	Ŭ		



Catego	ry : Classroom		В	uilding	: Main		
Ţ	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
lassroc	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF			
					6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	
lassroc	m #210 (Science Classroom)					0.40	
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	65	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,340	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,340	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	612	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
lassroc	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	792	SF	7	10+ years	



Catego	Category : Classroom			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Side-lite	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	792	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	904	SF	7	10+ years	


Category : Interior			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	6,486	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	720	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	6,486	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	74	EA	7	6-10 years	
	Walls - Masonry	1st Floor	660	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	560	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,010	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,200	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,200	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	1,472	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	84	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	2	EA	7	10+ years	
	Security Cameras	1st Floor	6	EA	7	6-10 years	
	Security Cameras	1st Floor	8	EA	7	6-10 years	
Stairs							
2.001.0	Ceiling - Plaster/Drywall	East stair 1	154	SF	6	10+ years	
	Floor - Terrazzo	East stair 1	64	SF	6	10+ years	
	Handrails	East stair 1	96	LF	7	10+ years	
	Lighting - Pendent/Surface	East stair 1	1	EA	7	6-10 years	
	Stairs - Terrazzo	East stair 1	28	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	West stair 2	154	SF	6	6-10 years	
	Floor - Terrazzo	West stair 2	64	SF	6	10+ years	
	Handrails	West stair 2	96	LF	7	10+ years	
	Lighting - Pendent/Surface	West stair 2	1	EA	7	6-10 years	
	0 0						



							THE OTHING DIVINE, OFFICAGO, IE 00000
Catego	Category : Interior			Building			
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Terrazzo	West stair 2	24	LF	6	10+ years	
Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless	1st Floor	1	EA	7	10+ years	
	Hydraulic					2	



	ry : Site	В	uilding				
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	6-10 years	
encing							
-	Fencing - Chain Link	Entire Site	718	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	100	LF	4	0-1 year	Disrepair/Significant damage
	Fencing - New Standard Ornamental	Entire Site	440	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	80	LF	6	6-10 years	
andsca	pe						
	Benches	Entire Site	5	EA	6	6-10 years	
	Landscape - Grass	Entire Site	5,507	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,150	SF	6	10+ years	
	Parkway trees	Entire Site	7	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	2,520	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	27,613	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	250	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	ĒA	6	6-10 years	
	Walking Path - Crushed Stone	Entire Site	20	SF	5	2-5 years	Concrete Pavers/Setting disrepai unaligned/uneven, cracked/broken/missing.
Parking							
	Surface - Asphalt	East	8,095	SF	6	6-10 years	
	Trash Enclosure - Chain Links	East	640	SF	6	6-10 years	
Playgrou							
Playgrou	Equipment - Combo 3-12	East	1	EA	6	6-10 years	
Playgrou		East East	1 2,300	SF	6 6	6-10 years 6-10 years	
Playgrou	Equipment - Combo 3-12						Damaged, with failing patch work
	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface	East East	2,300	SF	6	6-10 years	Damaged, with failing patch work
	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface	East East Entire Site	2,300	SF SF LF	6	6-10 years 0-1 year 10+ years	
	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface	East East	2,300 200 230 20	SF SF LF LF	6 4	6-10 years 0-1 year 10+ years 1-2 years	Damaged, with failing patch work
	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface	East East Entire Site	2,300 200 230	SF SF LF	6 4 6	6-10 years 0-1 year 10+ years	
Sidewall	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface Sidewalks - Internal Walks Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	East East Entire Site Entire Site	2,300 200 230 20	SF SF LF LF	6 4 6 4	6-10 years 0-1 year 10+ years 1-2 years	
Sidewall	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface Sidewalks - Internal Walks Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	East East Entire Site Entire Site Entire Site West	2,300 200 230 20	SF SF LF LF SF EA	6 4 6 4	6-10 years 0-1 year 10+ years 1-2 years	
Playgrou Sidewall Signage	Equipment - Combo 3-12 Surface - Poured Surface Surface - Poured Surface Sidewalks - Internal Walks Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	East East Entire Site Entire Site Entire Site	2,300 200 230 20 6,350	SF SF LF LF SF	6 4 6 4 6	6-10 years 0-1 year 10+ years 1-2 years 10+ years	



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	203	203	792	140	24	N	N
Computer Lab	Regular Classroom	2nd Floor	205	205	792	140	24	N	N
Kindergarten	Kindergarten	1st Floor	142	Room 142	1,074	233	80	N	N
Kindergarten	Kindergarten	1st Floor	143	Room 143	1,074	280	30	N	Y
Library	Library	1st Floor	105	105	1,816	210	24	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	792	168	18	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	792	168	12	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	792	140	24	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	792	168	18	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	792	168	18	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	108	792	168	18	Ν	N
Regular Classroom	Regular Classroom	1st Floor	110	110	792	168	12	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	792	168	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	792	168	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	792	168	18	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	792	168	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	792	168	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	792	140	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	792	168	18	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	792	168	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	792	168	18	N	N
Science Classroom	Regular Classroom	2nd Floor	210	210	1,340	336	36	N	N
Special Education	Special Education	1st Floor	107	107	588	70	8	Ν	Ν