#### 6011 S Rockwell STREET, Chicago, IL 60629

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1926	3	77,600
Addition	1995	2	19,700
Field House	1924	1	1,900
Campus Total			99,200

Category : Exterior Building : Main

	Ty : Exterior		Danaing . main					
	_					Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ell Equ	ipment							
	Cell Equipment - Antenna	North Courtyard	1	EA	7	10+ years		
	Cell Equipment - Cabinets	North Courtyard	1	EA	7	10+ years		
ntrance	9							
	Entrance Control - Audio and Video	#1 W	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#1 W	2	EA	5	6-10 years		
	Exterior Doors - Transom Lite	#1 W	1	EΑ	6	6-10 years		
	Exterior Stairs - Concrete	#1 W	84	LF	6	6-10 years		
	Power Door Operator and Controls	#1 W	1	EA	7	10+ years		
	Stair Handrail - Steel_Stair Handrail	#1 W	60	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#12 S	2	EΑ	5	2-5 years	Rust and paint	
	Exterior Doors - Transom Lite	#12 S	2	EΑ	5	6-10 years		
	Exterior Stairs - Concrete	#12 S	72	LF	6	6-10 years		
	Stair Handrail - Steel_Stair Handrail	#12 S	30	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#13 S	2	EA	5	10+ years	Rust and paint	
	Exterior Doors - Transom Lite	#13 S	2	EΑ	5	2-5 years		
	Exterior Stairs - Concrete	#13 S	90	LF	6	6-10 years		
	Stair Handrail - Steel_Stair Handrail	#13 S	36	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	#14 W	2	EΑ	6	6-10 years		
	Exterior Doors - Transom Lite	#14 W	1	EA	7	10+ years		
	Exterior Stairs - Concrete	#14 W	84	LF	6	6-10 years		
	Stair Handrail - Steel_Stair Handrail	#14 W	60	LF	7	10+ years		

Campus Name: Morrill Page : 1 of 43 Assessment Date: 02/14/2022



	Catego	ategory : Exterior		В	Building : Main					
Exterior Doors - Exterior Steel Door	_						Recommend			
Exterior Doors - Transom Lite	Group		Location	Quantity	UOM	Rank		Comments		
Exterior Stairs - Concrete		Exterior Doors - Exterior Steel Door	#15 Exit W	1	EA	6				
Exterior Doors - Exterior Stell Door		Exterior Doors - Transom Lite	#15 Exit W	1	EΑ	6	6-10 years			
Exterior Doors - Transom Lile		Exterior Stairs - Concrete	#15 Exit W	6	LF	6	6-10 years			
Exterior Stairs - Concrete		Exterior Doors - Exterior Steel Door	#2 N	2	EA	6	6-10 years			
Stair Handrail - Steel Stair Handrail #2 N		Exterior Doors - Transom Lite	#2 N	2	EA	6	6-10 years			
Exterior Doors - Exterior Steel Door		Exterior Stairs - Concrete	#2 N	90	LF	6	6-10 years			
Exterior Doors - Exterior Steel Door		Stair Handrail - Steel_Stair Handrail	#2 N	30	LF	6				
Exterior Doors - Transom Lite		Exterior Doors - Exterior Steel Door	#3 N	2	EA	6	•			
Stair Handrail - Steel Stair Handrail		Exterior Doors - Transom Lite	#3 N	1	EA		6-10 years			
Stair Handrail - Steel, Stair Handrail		Exterior Stairs - Concrete	#3 N	72	LF		•			
Exterior Doors - Exterior Steel Door		Stair Handrail - Steel Stair Handrail	#3 N	30	LF	6	•			
Exterior Doors - Side lite		Exterior Doors - Exterior Steel Door	#4 E		EA					
Exterior Doors - Transom Lite						-				
Exterior Stairs - Concrete										
Stair Handrail - Steel Stair Handrail							•			
Exterior Doors - Exterior Steel Door										
Exterior Doors - Side lite							<u>-</u>			
Exterior Doors - Transom Lite							•			
Exterior Stairs - Stone #5 Exit E 3 LF 7 10+ years Exterior Doors - Exterior Steel Door #5.5 E 2 EA 6 10+ years Exterior Doors - Exterior Steel Door #6 E 1 EA 6 6-10 years Exterior Doors - Exterior Steel Door #6 E 2 EA 5 2-5 years Exterior Stairs - Concrete #6 E 2 EA 5 2-5 years Exterior Stairs - Concrete #6 E 2 EA 5 2-5 years Exterior Stairs - Concrete #6 E 2 EA 5 2-5 years Exterior Stairs - Concrete #6 E 2 EA 7 10+ years Exterior Doors - Exterior Steel Door #6.1 Boiler Room 1 EA 6 6-10 years Exterior Doors - Exterior Stairs - Concrete #6.1 Boiler Room 1 EA 6 6-10 years Exterior Stairs - Concrete #6.1 Boiler Room 3 LF 6 10+ years Exterior Doors - Exterior Steel Door #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Exterior Stairs - Concrete #7 Exit E 2 EA 5 2-5 years Broken Glass Exterior Stairs - Concrete #7 Exit E 2 EA 5 2-5 years Exterior Stairs - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 915 LF 6 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years							•			
Exterior Doors - Exterior Steel Door							•			
Entrance Control - Audio and Video			-			=				
Exterior Doors - Exterior Steel Door						-				
Exterior Stairs - Concrete										
Power Door Operator and Controls #6 E 1 EA 7 10+ years Exterior Doors - Exterior Doors - Exterior Doors - Exterior Steel Door #6.1 Boiler Room 1 EA 6 6-10 years Exterior Stairs - Concrete #6.1 Boiler Room 3 LF 6 10+ years Exterior Doors - Exterior Steel Door #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Exterior Steel Door #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 year Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 year Broken Glass Exterior Doors - Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stairs - Stone #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years Rusted  Fire Escape  Fire Escape  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years										
Exterior Doors - Exterior Steel Door										
Exterior Doors - Transom Lite			_	· ·						
Exterior Stairs - Concrete #6.1 Boiler Room 3 LF 6 10+ years Exterior Doors - Exterior Steel Door #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 years Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stainless Steel #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years Rusted  Fire Escape  Fire Escape  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years										
Exterior Doors - Exterior Steel Door #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 year Broken Glass Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stairless Steel #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years Rusted  Fire Escape  Foundation  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years										
Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 6 6-10 years Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 year Broken Glass Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stainless Steel #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape  Fire Escape  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years							•			
Exterior Doors - Transom Lite #6.2 Boiler Room 1 EA 4 0-1 year Broken Glass  Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years  Exterior Doors - Exterior Stainless Steel #7 Exit E 2 EA 5 2-5 years  Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape  Fire Escape Façade- NE 66 LF 5 6-10 years Rusted  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years  Foundation - Concrete Entire Building 100 LF 6 10+ years				· ·			•			
Exterior Stairs - Stone #6.2 Boiler Room 3 LF 7 10+ years Exterior Doors - Exterior Stainless Steel #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape  Fire Escape Façade- NE 66 LF 5 6-10 years Rusted  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years				•		-		Broken Glass		
Exterior Doors - Exterior Stainless Steel #7 Exit E 2 EA 5 2-5 years Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape Fire Escape Façade- NE 66 LF 5 6-10 years Rusted  Foundation Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years								Dionon Olass		
Door Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape Fire Escape Façade- NE 66 LF 5 6-10 years Rusted  Foundation Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years							•			
Exterior Stairs - Concrete #7 Exit E 8 LF 6 6-10 years  Fire Escape Fire Escape Façade- NE 66 LF 5 6-10 years Rusted  Foundation  Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years			TI LAIL L	2	LA	3	2-0 years			
Fire Escape Fire Escape Foundation Foundation - Concrete			#7 Fyit F	ρ	ΙF	6	6-10 years			
Fire Escape Façade- NE  66 LF 5 6-10 years Rusted  Foundation  Foundation - Concrete		Extendi diana donolete	"I LAIL L	0	LI	J	o To years			
Fire Escape Façade- NE  66 LF 5 6-10 years Rusted  Foundation  Foundation - Concrete	_Fire Esc	ape								
Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years			Façade- NE	66	LF	5	6-10 years	Rusted		
Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete Entire Building 100 LF 6 10+ years	Fa									
Foundation - Concrete Entire Building 100 LF 6 10+ years	roundat		Entire Building	015	IF	7	10± vears			
Superstructure - Confere Entire Building 11,000 SF 1 10+ years							•			
		Superstructure - Contrete	Little building	11,000	SF.	,	10+ years			

Campus Name: Morrill Page : 2 of 43 Assessment Date: 02/14/2022



Categoi	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	6	6-10 years	
Roof Sys							
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler House Roof	65	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler House Roof	10	LF	5	6-10 years	
	Coping - Terra Cotta	Boiler House Roof	206	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler House Roof	32	LF	6	6-10 years	
	Parapet - Parapet > 30"	Boiler House Roof	206	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Boiler House Roof	2,630	SF	4	0-1 year	Per engineer, Leaks reported
	Roof Structure - Concrete	Boiler House Roof	2,630	SF	7	10+ years	-
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Coping - Terra Cotta	Main Roof	509	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	120	LF	6	6-10 years	
	Parapet - Parapet > 30"	Main Roof	509	LF	6	10+ years	
	Roof - PVC Membrane	Main Roof	13,319	SF	5	2-5 years	
	Roof Hatch - Metal	Main Roof	2	ĒΑ	7	10+ years	
	Roof Structure - Concrete	Main Roof	13,319	SF	7	10+ years	
	Coping - Terra Cotta	North Roof	353	LF	6	10+ years	
	Downspouts - Interior Downspouts	North Roof	120	LF	6	10+ years	
	Parapet - Parapet > 30"	North Roof	353	LF	6	10+ years	
	Roof - PVC Membrane	North Roof	7,354	SF	6	2-5 years	
	Roof Structure - Concrete	North Roof	7,354	SF	7	10+ years	
	Access Ladder - Metal	South Roof	1	ĒΑ	7	10+ years	
	Coping - Terra Cotta	South Roof	349	LF	6	10+ years	
	Downspouts - Interior Downspouts	South Roof	105	LF	6	6-10 years	
	Parapet - Parapet > 30"	South Roof	349	LF	6	10+ years	
	Roof - PVC Membrane	South Roof	7,026	SF	5	2-5 years	
	Roof Structure - Concrete	South Roof	7,026	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	170	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	565	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	28,800	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	3,200	SF	6	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	2,264	SF	6	6-10 years	
	Lintels - Steel	Entire Building	848	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	4	LF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,784	SF	6	6-10 years	

Campus Name: Morrill Page : 3 of 43 Assessment Date: 02/14/2022



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Emergency Battery Packs - Auditoium and Aisle Lighting	1st Floor	3	EA	4	2-5 years	Functional equipment with outdated technology and scarcity of replacement parts.
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	Serves Main and Addition
	Exit Signs - Auditoium	Entire Building	6	EA	4	2-5 years	Vintage equipment that remains
							operational as intended in service.
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	4	2-5 years	Vintage equipment that remains operational as intended in service.
	Exit Signs - Gym	Entire Building	4	EA	4	2-5 years	Quantity changed to match current observations. Vintage equipment that remains operational as intended in service.
	Security System - CCTV	Entire Building	77,600	SF	6	6-10 years	33.1.33.
	Security System - Intrusion Detection	Entire Building	77,600	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,450	SF	6	6-10 years	
_Main Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves Main and Addition
	PA System	Entire Building	77,600	SF	6	6-10 years	Serves the entire school
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	10+ years	Serves Main and Addition
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Quantity changed as total has been divided/aggregated and based on current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	



Catego	Category : Fire Protection				: Main		
Croun	Hom Time	Laggian	Quantity	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Serves Main and Addition. Panel is functional and passes inspection but is approaching the end of its service life.
	Fire Alarm Strobe Lights	Entire Building	52,870	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	77,600	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	7	10+ years	
Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	Boiler Room	1	EA	5	6-10 years	
	Jockey Pump	Boiler Room	1	EA	6	6-10 years	
Sprinkle	r System						
	Wet Sprinkler System	Entire Building	19,700	SF	6	6-10 years	Wet Sprinkler System serves Addition only, but is located in Main.

Category : Mechanical **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Air Cond	<b>7</b> 1	2004.10.1	quantity	00	rtariit	Ropidoomont	
7 111 22 21 2	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment.
_Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	AHU-3 serves north part of Main
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	6	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	150	LF	7	10+ years	
	Zone Dampers	Basement	18	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	AHU-2, serves south part of Main
	Air Intake	Basement	1	EA	7	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	7	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	7	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	400	LF	6	6-10 years	
	Zone Dampers	Basement	20	EA	7	10+ years	

Campus Name: Morrill Page : 5 of 43 Assessment Date: 02/14/2022



Catego	ry : Mechanical		В	uilding	: Main				
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-4 serves gym		
	Air Intake	Mechanical Room	1	EA	7	10+ years			
	Auxiliaries - 4000 - 8000 cfm	Mechanical Room	1	EΑ	5	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	7	10+ years			
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-1 serves auditorium		
	Air Intake	Mechanical Room	1	EA	7	10+ years			
	Auxiliaries - 4000 - 8000 cfm	Mechanical Room	1	EA	6	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	7	10+ years			
Boiler Sy	ystems								
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Auxiliaries for Boiler B-2 are not directly affected by the boiler tube replacement that is needed.		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years			
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.		
	Combustion Dampers	Boiler Room	1	EA	4	1-2 years	Combustion damper actuator for Boiler B-2 in the process of being replaced at the time of assessment.		
	Condensate Pump	Boiler Room	1	EA	6	6-10 years			
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	4	0-1 year	Boiler B-2 of service at the time of assessment. Needs 12 boiler tubes replaced. Rank, Reason and Priorit Rep adjusted based on current observations and per Building Engineer.		
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	5	2-5 years	5		
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years			
	Steam Traps	Boiler Room	46	ĒA	6	6-10 years	Upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.		

Campus Name: Morrill Page : 6 of 43 Assessment Date: 02/14/2022



Hot Water Pump - Less than 10  Boiler Room  1 EA 5 6-10 years Hydronic loop Pump is leakin Priority Rep accurrent observed.  Temperature Control  Pneumatic System  Entire Building  77,600 SF 4 0-1 year Also serves A broken down a spaces of the controlled by to the controlled by to the controlled by to the controlled by the controlled	pumps for Addition. pumps for Addition. g. Rank, Reason and
Heat Exchanger - Steam to Hot Water Shell Boiler Room 1 EA 6 6-10 years Hydronic loop Type  Heating Devices  Unit Heater - Gas Boiler Room 1 EA 6 6-10 years  Mechanical Plumbing Hydronic Supply and Return - Steel Basement 400 LF 6 6-10 years Hydronic loop Hour Boiler Room 1 EA 5 6-10 years Hydronic loop Hydro	pumps for Addition. pumps for Addition. g. Rank, Reason and
Type  Heating Devices  Unit Heater - Gas  Boiler Room  1 EA 6 6-10 years  Mechanical Plumbing  Hydronic Supply and Return - Steel Basement Hot Water Pump - Less than 10 Boiler Room 1 EA 6 6-10 years Hydronic loop Hot Water Pump - Less than 10 Boiler Room 1 EA 5 6-10 years Hydronic loop Pump is leakin Priority Rep a current obsen  Temperature Control  Pneumatic System Entire Building T7,600 SF 4 0-1 year Also serves A broken down a spaces of the controlled by t Controlled by t Controlled System Thermostats - Pneumatic Entire Building 40 EA 4 0-1 year Quantity chan divided/aggree not operations Contaminated pneumatic system Exhaust Fans- Roof Mounted - 500 - 1500 Roof 4 EA 6 6-10 years	pumps for Addition. pumps for Addition. g. Rank, Reason and
Unit Heater - Gas  Boiler Room  1 EA 6 6-10 years  Alechanical Plumbing  Hydronic Supply and Return - Steel Basement Hot Water Pump - Less than 10 Boiler Room 1 EA 6 6-10 years Hydronic loop Hot Water Pump - Less than 10 Boiler Room 1 EA 5 6-10 years Hydronic loop Pump is leaking Pump is leaking Pump is leaking Pump is leaking Priority Rep are current observ  Temperature Control  Pneumatic System Entire Building 77,600 SF 4 0-1 year Also serves A broken down as spaces of the controlled by Controlled by Thermostats - Pneumatic Entire Building 40 EA 4 0-1 year Quantity chan divided/aggree not operations contaminated pneumatic system  Exhaust Fans- Roof Mounted - 500 - 1500 Roof 4 EA 6 6-10 years	pumps for Addition. g. Rank, Reason and
Unit Heater - Gas  Boiler Room  1 EA 6 6-10 years  Mechanical Plumbing  Hydronic Supply and Return - Steel Basement 400 LF 6 6-10 years Hydronic loop Hot Water Pump - Less than 10 Boiler Room  Hot Water Pump - Less than 10 Boiler Room  1 EA 5 6-10 years Hydronic loop Pump is leaking Pu	pumps for Addition. g. Rank, Reason and
Hydronic Supply and Return - Steel Basement 400 LF 6 6-10 years Hot Water Pump - Less than 10 Boiler Room 1 EA 5 6-10 years Hydronic loop Hot Water Pump - Less than 10 Boiler Room 1 EA 5 6-10 years Hydronic loop Pump is leaking Priority Rep are current observed.  Temperature Control  Pneumatic System Entire Building 77,600 SF 4 0-1 year Also serves A broken down a spaces of the controlled by the controlle	pumps for Addition. g. Rank, Reason and
Hydronic Supply and Return - Steel Basement 400 LF 6 6-10 years Hot Water Pump - Less than 10 Boiler Room 1 EA 6 6-10 years Hydronic loop Hot Water Pump - Less than 10 Boiler Room 1 EA 5 6-10 years Hydronic loop Pump is leaking Priority Rep are current observing.  Temperature Control  Pneumatic System Entire Building 77,600 SF 4 0-1 year Also serves A broken down a spaces of the controlled by the controll	pumps for Addition. g. Rank, Reason and
Hot Water Pump - Less than 10 Hot Water Pump - Less than 10 Hot Water Pump - Less than 10 Boiler Room	pumps for Addition. g. Rank, Reason and
Hot Water Pump - Less than 10  Boiler Room  1 EA 5 6-10 years Hydronic loop Pump is leaking Priority Rep as current observed to the control Server Also serves A broken down a spaces of the controlled by the con	pumps for Addition. g. Rank, Reason and
Pump is leaking Priority Replan current observed and spaces of the control spaces of the controlled by	g. Rank, Reason and
Pneumatic System  Entire Building  77,600 SF 4 0-1 year Also serves A broken down a spaces of the controlled by t Controlled b	
broken down a spaces of the controlled by the co	
Thermostats - Pneumatic Entire Building 40 EA 4 0-1 year Quantity chan divided/aggree not operations contaminated pneumatic systems.  Ventilation  Exhaust Fans- Roof Mounted - 500 - 1500 Roof 4 EA 6 6-10 years	Idition. System has and temperatures in al school are manually the Building Engineer.
Exhaust Fans- Roof Mounted - 500 - 1500 Roof 4 EA 6 6-10 years	ged as total has been lated. Thermostats ar I and have been with oil from the
Exhaust Fans- Roof Mounted - 500 - 1500 Roof 2 EA 6 6-10 years CFM	
Category : Plumbing Building : Main	
Recommend	
Group Item - Type Location Quantity UOM Rank Replacement Comments	
Hot Water	
no current act unit with signs	
Piping	Fully operational with ve leaks leaks but old of deterioration and ee end of its service lif
Domestic Piping-Hot Water Return Lines Entire Building 77,600 SF 6 6-10 years Domestic plun	ve leaks leaks but old of deterioration and le end of its service lif
Campus Name: Morrill Page : 7 of 43 As	ve leaks leaks but old of deterioration and

Campus Name: Morrill Page : 7 of 43 Assessment Date: 02/14/2022



Catego	ategory : Plumbing		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Risers	Entire Building	77,600	SF	6	6-10 years	since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer. Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,600	SF	6	6-10 years	Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	77,600	SF	6	6-10 years	Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	77,600	SF	6	6-10 years	Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	77,600	SF	6	6-10 years	Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Sanitary Piping	Entire Building	77,600	SF	6	2-5 years	Domestic plumbing system upgraded since last assessment. Rank, Reason and Priority Rep adjusted based on current observations and per Building Engineer.
	Storm Piping Vent Piping	Entire Building Entire Building	77,600 77,600	SF SF	6 6	6-10 years 6-10 years	po. Danding Engineer.
Pumps							
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	
	Pumps - Sump-Simplex	Basement	2	EA	6	10+ years	

Campus Name: Morrill Page : 8 of 43 Assessment Date: 02/14/2022



atogo,	ategory : Room			uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices					-	
	AC Unit	105 Main Office Suite	1	EA	7	6-10 years	
	Ceiling - Lay-in	105 Main Office Suite	538	SF	7	10+ years	
	Ceiling - Plaster/Drywall	105 Main Office Suite	122	SF	7	10+ years	
	Doors - Transom Window	105 Main Office Suite	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105 Main Office Suite	1	EA	7	10+ years	
	Floor - Carpet	105 Main Office Suite	660	SF	6	6-10 years	
	Lighting - Lay-in	105 Main Office Suite	8	EA	7	10+ years	
	Lighting - Pendent/Surface	105 Main Office Suite	1	EA	7	10+ years	
	Power Distribution	105 Main Office Suite	10	EA	7	10+ years	
	Storage/ Closet	105 Main Office Suite	70	SF	7	10+ years	
	Walls - Plaster/Drywall	105 Main Office Suite	1,889	SF	6	10+ years	
	AC Unit	111 School Counselor Room	1,009	EA	7	6-10 years	
	Ceiling - Lay-in	111 School Counselor Room	573	SF	6	10+ years	
	Doors - Transom Window	111 School Counselor Room	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111 School Counselor Room	10	EA	7	•	
		111 School Counselor Room	573	SF	7	10+ years	
	Floor - Tile	111 School Counselor Room		SF EA	7	10+ years	
	Lighting - Lay-in Power Distribution	111 School Counselor Room	8 10	EA EA		10+ years	
					7	10+ years	
	Walls - Plaster/Drywall	111 School Counselor Room	1,650	SF	7	10+ years	
	Ceiling - Lay-in	214C Peace Room	234	SF	6	10+ years	NA
	Ceiling - Lay-in	214C Peace Room	16	SF	4	1-2 years	Water damage stain
	Doors - Wood Doors inclu hw	214C Peace Room	1	EA	7	10+ years	
	Floor - Terrazzo	214C Peace Room	250	SF	7	10+ years	
	Lighting - Lay-in	214C Peace Room	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	214C Peace Room	520	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Auditorium Sound Room used as Storage	75	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium Sound Room used as Storage	1	EA	6	10+ years	
	Floor - Carpet	Auditorium Sound Room used as Storage	75	SF	6	6-10 years	
	Lighting - Pendent/Surface	Auditorium Sound Room used as Storage	1	EA	7	10+ years	
	Power Distribution	Auditorium Sound Room used as Storage	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Auditorium Sound Room used as Storage	277	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's Office in Basement	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office in Basement	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office in Basement	75	SF	6	10+ years	
	Lighting - Lay-in	Engineer's Office in Basement	1	EA	4	1-2 years	Fixture not functional
	Power Distribution	Engineer's Office in Basement	4	EA	7	10+ years	i Ataro not fanotional
	Walls - Plaster/Drywall	Engineer's Office in Basement	297	SF	6	10+ years	

Campus Name: Morrill Page : 9 of 43 Assessment Date: 02/14/2022



Catego	ry : Room		В	uilding	: Main		TTO ROCKWEII OTREET, Officago, 12 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	Engineer's Office in Basement	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Office in Gym	348	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office in Gym	1	EA	6	10+ years	
	Floor - Tile	Gym Office in Gym	348	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office in Gym	3	EA	7	6-10 years	divided by rank
	Lighting - Pendent/Surface	Gym Office in Gym	1	EA	4	0-1 year	Missing cover
	Power Distribution	Gym Office in Gym	4	EA	7	10+ years	· ·
	Storage/ Closet	Gym Office in Gym	70	SF	7	10+ years	
	Walls - Concrete Block	Gym Office in Gym	160	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym Office in Gym	206	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym Office in Gym	2	SF	5	10+ years	Peeling paint
	Walls - Structural Glazed Tile	Gym Office in Gym	445	SF	6	10+ years	01
	Work Slnk	Gym Office in Gym	1	EA	7	10+ years	
Auditoriu	ım & Theater						
Auditoni	Balcony Seating	1st Floor	83	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,800	SF	7 7		
	Doors - Transom Window			SF SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor 1st Floor	30 6	EA	_	10+ years	
				SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted Lighting - Chandelier, Incandescent	1st Floor	2,800	SF EA	7	10+ years	
		1st Floor	7		6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Lighting - Wall Mounted	1st Floor	14	EΑ	7	10+ years	
	Main Floor Seating	1st Floor	288	EΑ	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	498	SF	7	10+ years	
	Stage Curtain	1st Floor	7	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	10	LF · –	7	10+ years	
	Stairs - Terrazzo	1st Floor	10	LF	6	10+ years	
	Storage/ Closet	1st Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,000	SF	7	10+ years	
_Gymnas	ia						
-	Ceiling - Plaster/Drywall	1st Floor	2,760	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	2,760	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	10+ years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Walls - Masonry	1st Floor	1,996	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,510	SF	7	10+ years	
	-					•	

Campus Name: Morrill Page : 10 of 43 Assessment Date: 02/14/2022



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
MDF_ID							
	Doors - Transom Window	Room 204	10	SF	5	10+ years	
	Doors - Wood Doors inclu hw	Room 204	1	EA	7	10+ years	
	Finishes	Room 204	225	SF	5	10+ years	water damage in ceiling and pealing paint in walls
	Other Cooling Unit	Room 204	1	EA	7	10+ years	Ductless split
	Window AC Unit	Room 204	2	EA	7	6-10 years	·
Mechani	cal/ Service Rooms						
100110111	Storage Room	1.5 above gym office	470	SF	7	10+ years	
	Janitor's Closet	1st Floor	21	SF	5	2-5 years	
	Mechanical/ Service Rooms	1st Floor	125	SF	7	10+ years	
	Storage Room	1st Floor	135	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	
	Air Tunnel	Basement	4,083	SF	7	10+ years	
	Auditorium Plenums	Basement	198	SF	7	10+ years	
	Boiler Room	Basement	2,619	SF	7	10+ years	
	Coal Room	Basement	988	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	9,939	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	332	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	160	SF	5	10+ years	
	Storage Room	Basement	435	SF	5	6-10 years	
	Vaults	Basement	100	SF	7	10+ years	
Restroor	n						
	Accessories	Boys 2nd floor SE next to 213	388	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 2nd floor SE next to 213	388	SF	7	10+ years	
	Doors - Transom Window	Boys 2nd floor SE next to 213	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys 2nd floor SE next to 213	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 2nd floor SE next to 213	388	SF	7	10+ years	
	Floor Drain	Boys 2nd floor SE next to 213	1	ĒΑ	7	10+ years	
	Hand Dryer	Boys 2nd floor SE next to 213	1	EA	4	0-1 year	Non functioning
	Lavatory	Boys 2nd floor SE next to 213	2	ΕA	7	10+ years	· · · · · · · · · · · · · · · · · · ·
	Lighting - Pendent/Surface	Boys 2nd floor SE next to 213	5	EA	7	6-10 years	
	Partitions	Boys 2nd floor SE next to 213	2	EA	7	6-10 years	
	Urinals	Boys 2nd floor SE next to 213	7	EA	7	10+ years	
	Walls - Plaster/Drywall	Boys 2nd floor SE next to 213	990	SF	7	10+ years	
	Water Closet	Boys 2nd floor SE next to 213	2	ĒΑ	7	10+ years	
	Accessories	Boys North 3rd floor next to 306	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys North 3rd floor next to 306	380	SF	7	10+ years	
	Doors - Transom Window	Boys North 3rd floor next to 306	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys North 3rd floor next to 306	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys North 3rd floor next to 306	380	SF	7	10+ years	

Page: 11 of 43 Campus Name: Morrill Assessment Date: 02/14/2022



Catego	Category : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Boys North 3rd floor next to 306	1	EA	7	10+ years	
	Lavatory	Boys North 3rd floor next to 306	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys North 3rd floor next to 306	5	EA	7	6-10 years	
	Partitions	Boys North 3rd floor next to 306	2	EA	7	6-10 years	
	Urinals	Boys North 3rd floor next to 306	4	EA	7	10+ years	Renovated, new quantity
	Walls - Plaster/Drywall	Boys North 3rd floor next to 306	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	Boys North 3rd floor next to 306	398	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys North 3rd floor next to 306	50	SF	7	10+ years	
	Water Closet	Boys North 3rd floor next to 306	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Boys SE next to Addition entry 1st floor	382	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys SE next to Addition entry 1st floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys SE next to Addition entry 1st floor	380	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boys SE next to Addition entry 1st floor	2	SF	5	1-2 years	Cracked tiles
	Floor Drain	Boys SE next to Addition entry 1st floor	1	EA	7	10+ years	
	Hand Dryer	Boys SE next to Addition entry 1st floor	1	EA	7	6-10 years	
	Lavatory	Boys SE next to Addition entry 1st floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys SE next to Addition entry 1st floor	5	EA	7	10+ years	
	Partitions	Boys SE next to Addition entry 1st floor	3	EA	7	10+ years	
	Urinals	Boys SE next to Addition entry 1st floor	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Boys SE next to Addition entry 1st floor	398	SF	6	10+ years	
	Walls - Plaster/Drywall	Boys SE next to Addition entry 1st floor	50	SF	5	6-10 years	
	Walls - Structural Glazed Tile	Boys SE next to Addition entry 1st floor	398	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys SE next to Addition entry 1st floor	50	SF	6	10+ years	
	Water Closet	Boys SE next to Addition entry 1st floor	3	EA	6	10+ years	
	Accessories	Gilrs South 3rd floor next to 314	380	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Gilrs South 3rd floor next to 314	380	SF	7	10+ years	
	Doors - Transom Window	Gilrs South 3rd floor next to 314	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gilrs South 3rd floor next to 314	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gilrs South 3rd floor next to 314	380	SF	6	10+ years	

Campus Name: Morrill Page : 12 of 43 Assessment Date: 02/14/2022



Catego	ategory : Room		В	uilding	: Main		. 5 :
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Gilrs South 3rd floor next to 314	1	EA	7	10+ years	
	Hand Dryer	Gilrs South 3rd floor next to 314	1	EA	5	2-5 years	
	Lavatory	Gilrs South 3rd floor next to 314	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Gilrs South 3rd floor next to 314	5	EA	7	6-10 years	
	Partitions	Gilrs South 3rd floor next to 314	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Gilrs South 3rd floor next to 314	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	Gilrs South 3rd floor next to 314	398	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Gilrs South 3rd floor next to 314	50	SF	7	10+ years	
	Water Closet	Gilrs South 3rd floor next to 314	6	EA	7	10+ years	
	Accessories	Girls NE 2nd floor next to 203	382	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls NE 2nd floor next to 203	382	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls NE 2nd floor next to 203	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls NE 2nd floor next to 203	382	SF	7	10+ years	
	Floor Drain	Girls NE 2nd floor next to 203	1	EA	7	10+ years	
	Hand Dryer	Girls NE 2nd floor next to 203	1	EΑ	7	6-10 years	
	Lavatory	Girls NE 2nd floor next to 203	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Girls NE 2nd floor next to 203	5	EΑ	7	6-10 years	
	Partitions	Girls NE 2nd floor next to 203	5	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Girls NE 2nd floor next to 203	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	Girls NE 2nd floor next to 203	398	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls NE 2nd floor next to 203	50	SF	7	10+ years	
	Water Closet	Girls NE 2nd floor next to 203	5	EA	7	10+ years	
	Accessories	Girls SE 2nd floor next to Addition	382	SF	7	6-10 years	
	Accessories	entry	302	Si	,	0-10 years	
	Ceiling - Plaster/Drywall	Girls SE 2nd floor next to Addition	382	SF	7	10+ years	
	Coming Tractor/21/Wan	entry	552	O.	•	ioi youlo	
	Doors - Wood Doors inclu hw	Girls SE 2nd floor next to Addition	1	EA	7	10+ years	
		entry			•	, , , , , , , , , , , , , , , , , , , ,	
	Floor - Tile Ceramic/ Porcelain	Girls SE 2nd floor next to Addition	330	SF	7	10+ years	
	. i.e i.e. ceraiiie, i ereelaii	entry		٠.	•	. o . y cano	
	Floor - Tile Ceramic/ Porcelain	Girls SE 2nd floor next to Addition	50	SF	5	1-2 years	Chipped
		entry		-	-	,	
	Floor Drain	Girls SE 2nd floor next to Addition	1	EA	7	10+ years	
		entry	•		•	. o . y ca. c	
	Hand Dryer	Girls SE 2nd floor next to Addition	1	EA	7	6-10 years	
		entry				- · · · · · · · · · · · · · · · · · · ·	
	Lavatory	Girls SE 2nd floor next to Addition	2	EA	7	10+ years	
	Lavatory	entry	_	_, 、	•	ioi youlo	
	Lighting - Pendent/Surface	Girls SE 2nd floor next to Addition	5	EA	6	6-10 years	
	Lighting Tondon's Canado	entry	ŭ	_, `	·	o io jouio	
	Partitions	Girls SE 2nd floor next to Addition	9	EA	7	6-10 years	
	- Gradono	entry	3	_/ \	,	o to yours	
	Walls - Plaster/Drywall	Girls SE 2nd floor next to Addition	398	SF	7	10+ years	
	vvalio i lastoi/Diywali	entry	330	Ji	'	TOT years	
		ond y					



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	Girls SE 2nd floor next to Addition	398	SF	7	10+ years	
		entry					
	Walls - Tile Ceramic/ Porcelain	Girls SE 2nd floor next to Addition	50	SF	7	10+ years	
		entry				-	
	Water Closet	Girls SE 2nd floor next to Addition	9	EΑ	7	10+ years	
		entry					
	Accessories	Girls SE next to 113 1st floor	388	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Girls SE next to 113 1st floor	388	SF	7	10+ years	
	Doors - Transom Window	Girls SE next to 113 1st floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls SE next to 113 1st floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls SE next to 113 1st floor	387	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls SE next to 113 1st floor	10	SF	5	1-2 years	Cracked tiles
	Floor Drain	Girls SE next to 113 1st floor	1	EA	7	10+ years	
	Hand Dryer	Girls SE next to 113 1st floor	1	EA	7	6-10 years	
	Lavatory	Girls SE next to 113 1st floor	2	ΕA	7	10+ years	
	Lighting - Pendent/Surface	Girls SE next to 113 1st floor	5	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Girls SE next to 113 1st floor	1	EΑ	5	1-2 years	Issuing cover
	Partitions	Girls SE next to 113 1st floor	8	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Girls SE next to 113 1st floor	530	SF	7	10+ years	
	Walls - Structural Glazed Tile	Girls SE next to 113 1st floor	530	SF	7	10+ years	
	Walls - Structural Glazed Tile	Girls SE next to 113 1st floor	2	SF	6	6-10 years	
	Water Closet	Girls SE next to 113 1st floor	8	EA	7	10+ years	
	Accessories	Toilet in Main Office Suite	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet in Main Office Suite	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in Main Office Suite	26	SF	7	10+ years	
	Lavatory	Toilet in Main Office Suite	1	EA	7	10+ years	
	Lighting - Lay-in	Toilet in Main Office Suite	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in Main Office Suite	202	SF	7	10+ years	
	Water Closet	Toilet in Main Office Suite	1	EA	7	10+ years	
	Accessories	Toilet in engineer office	25	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in engineer office	20	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Toilet in engineer office	5	SF	4	1-2 years	Water damage, blistering paint and
	Coming Tractor/Dry Wan	Tollot in originoor office	J	O.	•	1 2 youro	plaster
	Doors - Wood Doors inclu hw	Toilet in engineer office	1	EA	6	6-10 years	pidotoi
	Floor - Concrete	Toilet in engineer office	25	SF	5	6-10 years	
	Lighting - Pendent/Surface	Toilet in engineer office	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Toilet in engineer office	124	SF	6	10+ years	
	Walls - Plaster/Drywall	Toilet in engineer office	15	SF	5	1-2 years	Water damage, blistering paint and
	·	<u>-</u>				-	plaster, spalling
	Water Closet	Toilet in engineer office	1	EA	6	10+ years	
	Accessories	Toilet in room 108	70	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Toilet in room 108	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet in room 108	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in room 108	60	SF	7	10+ years	

Campus Name: Morrill Page : 14 of 43 Assessment Date: 02/14/2022



Catego	ry : Room		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Toilet in room 108	1	EA	7	10+ years	
	Hand Dryer	Toilet in room 108	1	EA	7	6-10 years	
	Lavatory	Toilet in room 108	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet in room 108	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in room 108	180	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Toilet in room 108	180	SF	7	10+ years	
	Water Closet	Toilet in room 108	1	EΑ	7	10+ years	
	Accessories	Toilet in room 113	53	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Toilet in room 113	53	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet in room 113	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in room 113	52	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet in room 113	1	SF	5	1-2 years	Cracked tiles
	Floor Drain	Toilet in room 113	1	EA	7	•	Cracked tiles
						10+ years	
	Lavatory	Toilet in room 113	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Toilet in room 113	1	EA	7	10+ years	
	Partitions	Toilet in room 113	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Toilet in room 113	198	SF	7	10+ years	
	Water Closet	Toilet in room 113	2	EA	7	10+ years	
	Accessories	Women Staff SE 2nd floor next to addition entry	96	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women Staff SE 2nd floor next to addition entry	96	SF	7	10+ years	Corrected quantity
	Doors - Transom Window	Women Staff SE 2nd floor next to addition entry	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women Staff SE 2nd floor next to addition entry	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women Staff SE 2nd floor next to	96	SF	7	10+ years	
	Lavatory	addition entry Women Staff SE 2nd floor next to	1	EA	7	10+ years	
	Lighting - Pendent/Surface	addition entry Women Staff SE 2nd floor next to	2	EA	6	6-10 years	
	Partitions	addition entry Women Staff SE 2nd floor next to	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	addition entry Women Staff SE 2nd floor next to	398	SF	7	10+ years	
	Walls - Structural Glazed Tile	addition entry Women Staff SE 2nd floor next to	297	SF	7	10+ years	
	Water Closet	addition entry Women Staff SE 2nd floor next to addition entry	2	EA	7	10+ years	
	Accessories	Women Teacher Toilet SE across from Gym	96	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Women Teacher Toilet SE across from Gym	94	SF	6	10+ years	

Campus Name: Morrill Page : 15 of 43 Assessment Date: 02/14/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Women Teacher Toilet SE across	2	SF	5	10+ years	Rating based on current observations
		from Gym					
	Doors - Transom Window	Women Teacher Toilet SE across	10	SF	7	10+ years	
		from Gym					
	Doors - Wood Doors inclu hw	Women Teacher Toilet SE across	1	EA	7	10+ years	
		from Gym		~-	_		
	Floor - Tile Ceramic/ Porcelain	Women Teacher Toilet SE across	92	SF	5	6-10 years	
	Floor Tile Commist Donastain	from Gym	4	0.5	4	4.0	NAI
	Floor - Tile Ceramic/ Porcelain	Women Teacher Toilet SE across	4	SF	4	1-2 years	Missing
	Loyotony	from Gym Women Teacher Toilet SE across	1	EA	7	10	
	Lavatory	from Gym	ı	EA	,	10+ years	
	Lighting - Pendent/Surface	Women Teacher Toilet SE across	2	EA	6	10+ years	
	Lighting Tendent/Ounded	from Gym	_	L/\	O	101 years	
	Partitions	Women Teacher Toilet SE across	2	EA	7	10+ years	
	- articorio	from Gym	_	_, \	•	ioi youlo	
	Walls - Plaster/Drywall	Women Teacher Toilet SE across	398	SF	7	10+ years	
	, .	from Gym				,	
	Walls - Structural Glazed Tile	Women Teacher Toilet SE across	297	SF	7	10+ years	
		from Gym				•	
	Water Closet	Women Teacher Toilet SE across	2	EA	7	10+ years	
		from Gym					

Category : Classroom **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	7	10+ years	

Campus Name: Morrill Page : 16 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	6	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	680	SF	6	6-10 years	
	Floor - Tile	1st Floor	50	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	1st Floor	12	ĒΑ	6	10+ years	zamagea nee.
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
Classroo	om #107 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	750	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	750	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #108 (Kindergarten)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,146	SF	7	10+ years	
	Doors - Transom Window	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	1,146	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	6	10+ years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	232	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,650	SF	7	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Cacononi	1001	r	_1	J	io. yours	

Page : 17 of 43 Campus Name: Morrill Assessment Date: 02/14/2022



Catego	ategory : Classroom			uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years			
	Chalk Board	1st Floor	30	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	730	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years			
	Marker Board	1st Floor	21	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years			
Classroo	om #112 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years			
	Doors - Transom Window	1st Floor	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	730	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years			
	Marker Board	1st Floor	40	LF	7	6-10 years			
	Storage/ Closet	1st Floor	18	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years			
Classroo	om #113 (Kindergarten)								
0.000.00	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	40	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	967	SF	7	10+ years			
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	1st Floor	41	SF	7	10+ years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	20	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	20	EA	6	10+ years			
	Floor - Carpet	1st Floor	41	SF	7	,			
	Floor - Wood	1st Floor	967	SF	7	6-10 years			
		1st Floor	15	EA	7	10+ years			
	Lighting - Lay-in					10+ years			
	Marker Board	1st Floor	5	LF	7	6-10 years			
	Storage/ Closet	1st Floor	18	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,105	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #114 (Kindergarten)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years			
	Doors - Transom Window	1st Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			

Campus Name: Morrill Page: 18 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	730	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	39	LF	7	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
assroo	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	760	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
	Floor - Wood	1st Floor	760	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	39	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	6	•	
	walls - Plaster/Drywall	ISI FIOOI	900	SF	б	10+ years	
assroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
assroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	706	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	22	LF	4	2-5 years	a.c. damago
	Doors - Transom Window	2nd Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	20	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	,	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	968	SF	7	6-10 years	
	vvalis - Flastel/DLYWall	ZIIU FIOOI	908	SF	1	10+ years	

Campus Name: Morrill Page: 19 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom	В	uilding	: Main			
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	714	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Missing tile / water damage
	Chalk Board	2nd Floor	33	LF	4	2-5 years	3
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	-	
						6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
lassroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Wood Books including	2nd Floor	730	SF	6	10+ years	
		2nd Floor	12	EA	7		
	Lighting - Lay-in					6-10 years	
	Marker Board	2nd Floor	31	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
Classroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	2nd Floor 2nd Floor	730	SF	6		
						10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
lassroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	13	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
					7 7	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	1	10+ years	

Page : 20 of 43 Campus Name: Morrill Assessment Date: 02/14/2022



Calego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	33	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
Classroc	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	13	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	13	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	13	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	6	10+ years	
Classroc	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	

Campus Name: Morrill Page : 21 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	6	10+ years	
Classroc	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor 2nd Floor	730 27	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7		
						10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	19	LF	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	968	SF	7	10+ years	
Classroc	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
_Classroc	om #214B (Office)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	340	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	25	SF	4	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	Trator damago
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	365	SF	6	10+ years	
		2nd Floor 2nd Floor		SF EA	7		
	Lighting - Lay-in		6	LF		6-10 years	
	Marker Board	2nd Floor 2nd Floor	4 484	SF	7 7	6-10 years 10+ years	
	Walls - Plaster/Drywall						

Campus Name: Morrill Page : 22 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Nooroo	m #245 (Dagular Classroom)						
Jassroo	m #215 (Regular Classroom)	Ond Floor	4	ΓΛ	7	0.40	
	AC Units	2nd Floor	1	EA LF	7	6-10 years	
	Casework	2nd Floor	7		6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
Classroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	1-2 years	Water damage
	Chalk Board	3rd Floor	21	LF	4	2-5 years	Water damage
	Doors - Transom Window	3rd Floor	10	SF	7		
					7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA SF	=	10+ years	
	Floor - Wood	3rd Floor	730		6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
lassroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Chalk Board	3rd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	6	10+ years	
	Work Sink	3rd Floor	2	EA	4	1-2 years	Appears out of servive
	WOLK SILIK	SIU FIOOI	2	EA	4	1-2 years	Appears out of servive
lassroo	m #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
		0 1 5	7	LF	c		
	Casework	3rd Floor	7	ᄕ	6	10+ years	

Campus Name: Morrill Page : 23 of 43 Assessment Date: 02/14/2022



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	27	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	715	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
Classroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Chalk Board	3rd Floor	730	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	-	
			· · · · · · · · · · · · · · · · · · ·			10+ years	
	Floor - Wood	3rd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	6	10+ years	
Classroc	om #309 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	35	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
Classroc	om #310 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6		
		3rd Floor	12	EA	7	10+ years	
	Lighting - Lay-in			LF		6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	12 968	SF	7 6	6-10 years 10+ years	
				<b>&gt;</b> -	h		

Campus Name: Morrill Page : 24 of 43 Assessment Date: 02/14/2022



	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	718	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	1-2 years	Stained
	Chalk Board	3rd Floor	33	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	15	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
	valio i lactor/Drywan	014 1 1001	000	O1	,	101 youro	
lassroo	m #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	9	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
	vvalio i laster/Brywan	314 1 1001	300	Oi.	,	101 years	
Classroo	m #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	7	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
	walls - Flastel/Drywall	314 [100]	900	SI	,	10+ years	
lassroo	m #314 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	<u> </u>			LF	4	2-5 years	



## Donald Morrill Math & Science Elementary School 6011 S Rockwell STREET, Chicago, IL 60629

Categor	y : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	965	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
ategor	y : Interior		В	uilding	: Main		
	Itam Tuna	Location	Ouantitu	HOM	Donk	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	5,400	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	10	EA	6	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,200	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	64	EA	6	10+ years	
	Lighting - Wall Mounted	1st Floor	6	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	233	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,300	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	5,380	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	5	1-2 years	Cracked tile/ water damage
	Drinking Fountains - Double Water Cooler	2nd Floor	2	EA	7	10+ years	ű
	Floor - Terrazzo	2nd Floor	1,200	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,200	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	64	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	315	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,300	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,700	SF	7	10+ years	
	Drinking Fountains - Double Water Cooler	3rd Floor	2,700	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	600	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,090	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,090	SF	5	•	Missing
			31			1-2 years	Missing
	Lighting - Lay-in	3rd Floor		EΑ	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	164	EA SF	7 7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,155	<b>5</b> F	/	10+ years	
afety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	9	EA	7	6-10 years	
	Security Cameras	Entire Building	2	EA	7	6-10 years	
tairs							

Campus Name: Morrill Page : 26 of 43 Assessment Date: 02/14/2022



Category : Interior			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	North	360	SF	7	10+ years	
	Floor - Terrazzo	North	360	SF	7	10+ years	
	Handrails	North	55	LF	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	6-10 years	
	Stairs - Terrazzo	North	120	LF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North	1,058	SF	7	10+ years	
	Ceiling - Lay-in	North East	370	SF	7	10+ years	
	Floor - Terrazzo	North East	370	SF	7	10+ years	
	Handrails	North East	110	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	4	EA	7	6-10 years	
	Stairs - Terrazzo	North East	240	LF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North East	2,116	SF	7	10+ years	. ,
	Ceiling - Lay-in	South	360	SF	7	10+ years	
	Floor - Terrazzo	South	360	SF	7	10+ years	
	Handrails	South	55	LF	7	10+ years	
	Lighting - Pendent/Surface	South	2	EA	7	6-10 years	
	Stairs - Terrazzo	South	120	LF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	South	1,058	SF	7	10+ years	. ,
	Ceiling - Lay-in	South East	370	SF	7	10+ years	
	Floor - Terrazzo	South East	370	SF	7	10+ years	
	Handrails	South East	40	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	4	EA	7	6-10 years	
	Stairs - Terrazzo	South East	240	LF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	South East	2,116	SF	7	10+ years	

Campus Name: Morrill Page : 27 of 43 Assessment Date: 02/14/2022





Category : Exterior **Building: Addition** 

	y . Exterior		_	anan g	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Donk	Replacement	Comments
Group		Location	Quantity	UOIVI	Rank	Replacement	Comments
_Entrance		_					
	Exterior Doors - Exterior Steel Door	#10 S	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 S	20	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#10 S	16	LF	7	10+ years	
	Exterior Doors - Side lite	#11 SW	4	EA	6	6-10 years	
	Exterior Doors - Store Front	#11 SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#11 SW	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#11 SW	48	LF	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#11 SW	60	LF	7	10+ years	
	Ramps - Concrete	#11 SW	30	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#11 SW	36	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#8 W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 W	36	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8 W	20	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 N	1	ĒΑ	6	10+ years	
	Exterior Stairs - Concrete	#9 N	16	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 N	8	LF	6	6-10 years	
	otan Hanaran otooi_otan Hanaran	<i>"</i> 011	9		·	o ro youro	
Foundati	on						
_i oundan	Foundation - Concrete	Entire Building	500	LF	7	10	
	Superstructure - Steel	Entire Building Entire Building	19,700	SF	7 7	10+ years 10+ years	
	Superstructure - Steel	Entire Building	19,700	SF	′	10+ years	
1 . 1							
_Lighting_		E // B // P				0.40	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	6-10 years	
Doof Cur	to an						
Roof Sys		M : D (					
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	532	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	130	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Main Roof	8,527	SF	4	0-1 year	Cracking and soft spots throughout
	Roof Structure - Steel / Metal Deck/	Main Roof	8,527	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	North Low Roof	122	LF	6	6-10 years	
	Downspouts - Interior Downspouts	North Low Roof	34	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	North Low Roof	1,963	SF	4	0-1 year	Soft spots and cracking throughout
	Roof Structure - Steel / Metal Deck/	North Low Roof	1,963	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	68	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,155	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,845	SF	6	10+ years	

Campus Name: Morrill Page : 28 of 43 Assessment Date: 02/14/2022



Category : Exterior

## Donald Morrill Math & Science Elementary School 6011 S Rockwell STREET, Chicago, IL 60629

**Building: Addition** 

Calego	ory : Exterior			sunanig	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Terra Cotta	Entire Building	5	SF	4	0-1 year	Cracking
_Window	e						
_vvii iuow	Guard - Guards perforated	Entire Building	1,680	SF	6	6-10 years	
	Lintels - Steel	Entire Building	420	LF	7	10+ years	
	Windows - Louver	Entire Building	70	SF	6	6-10 years	
	Windows - Louvei Windows - Sash Aluminum	Entire Building	2,784	SF	6	6-10 years	
		Entire Building	2,764 576		6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire building	576	SF	O	6-10 years	
Catego	ry : Electrical		E	Building	: Additi		
			<b>a</b>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System						
	Emergency Battery Packs - Corridors and Stairs	1st Floor	9	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	10	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	1st Floor	2	EA	6	6-10 years	Quantity changed to match current observations.
	Security System - CCTV	Entire Building	19,700	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	19,700	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	10+ years	Quantity changed to match current observations
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	4	0-1 year	Sign faces have faded lettering which negatively affects legibility.
	Exit Signs - Lunchroom	Entire Building	1	EA	5	0-1 year	Lunchroom has a means of egress that is missing an exit sign.
	Exit Signs - Lunchroom	Entire Building	2	EA	4	0-1 year	Quantity changed to match current observations. Sign faces have faded lettering which negatively affects legibility.
Main Se	ervice						
	PA System	Entire Building	19,700	SF	6	6-10 years	Served by Main
_Power F	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	EM fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	Panel LL1 is a companion panel to LR1 but was locked with no available key at the time of assessment.
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	Quantity changed to match current observations
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
0	Nome: Morrill		Daga : 20 of 42				Accessment Date: 02/44/2022

Campus Name: Morrill Page : 29 of 43 Assessment Date: 02/14/2022



valego	ry : Electrical		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type  Main Distribution Danala   Leas then 400	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	Item Type changed to match curren observations.
Catego	ry : Fire Protection		В	uilding	: Additi	on	
	<del></del>	L d	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	m Fire Alarm Strobe Lights	Entire Building	10.700	SF		6.10 2000	
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	19,700 19,700	SF SF	6 6	6-10 years 6-10 years	FACP is in Main
	The Alami_System	Little Building	13,700	Oi	U	0-10 years	1 AOI 13 III Walli
Sprinkler	System						
	Sprinkler Heads	Entire Building	19,700	SF	7	10+ years	
	Sprinkler Piping	Entire Building	19,700	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	· Additi	on	
<b>G</b> alogo.	y i moonamou			anamg	. / taarir	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	5						
	Condensing Unit- Roof Mounted - Less than 5 tons	2nd Floor	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone- Outdoor Roof Mounted- Hot Water Coils - 12001-20000 cfm	Lower Roof	1	EA	5	6-10 years	Not directly accessible in a safe manner at the time of assessment due to snow/ice conditions.
	Air Handling Unit-Package Single Zone- Outdoor Roof Mounted- Hot Water Coils - 4000-8000 cfm	Lower Roof	1	EA	5	6-10 years	Not directly accessible in a safe manner at the time of assessment due to snow/ice conditions.
	Air Handling Unit-Package Single Zone- Outdoor Roof Mounted- Hot Water Coils - 4000-8000 cfm	Lower Roof	1	EA	5	6-10 years	Not directly accessible in a safe manner at the time of assessment due to snow/ice conditions.
Heating [	Devices						
3-	Cabinet Heaters - With Hot Water Coil	1st Floor	2	EA	6	6-10 years	Located in the lobby area of the building.
	Fin Tube - Hot Water	Entire Building	145	LF	5	6-10 years	Quantity changed as total has been divided/aggregated.
	cal Plumbing			LF			
Mechanio	Hydronic Supply and Return - Galvanized		150		6	6-10 years	Supplied from Main boiler room

Campus Name: Morrill Page : 30 of 43 Assessment Date: 02/14/2022



Catego	ry : Mechanical		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Electric Thermostat Pneumatic System	Entire Building Entire Building	1 19,700	EA SF	6 4	6-10 years 0-1 year	For the lobby area of the Addition. Located in Main. System has broken down and temperatures in all spaces of the school are manually controlled by the Building Engineer except for the lobby area and the rooms with unit ventilators.
	Thermostats - Pneumatic	Entire Building	4	EA	6	6-10 years	Four zones. Thermostats are not operational and have been contaminated with oil from the pneumatic system.
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	4	EA	5	6-10 years	Room 216 (2), 217, and 220. All are operational with one unit completing maintenance at the time of assessment.
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	3	EA	5	6-10 years	Room 116, 117 and 119. Quantity changed to match current observations.
_Ventilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment due to snow/ice conditions.

**Category: Plumbing Building: Addition** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	1st Floor	1	EA	5	6-10 years	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	1st Floor	1	EA	6	10+ years	
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	19,700	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	19,700	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	19,700	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	19,700	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	19,700	SF	6	6-10 years	

Campus Name: Morrill Page : 31 of 43 Assessment Date: 02/14/2022



Category : Plumbing			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	19,700	SF	6	6-10 years	
	Sanitary Piping	Entire Building	19,700	SF	6	6-10 years	
	Storm Piping	Entire Building	19,700	SF	6	6-10 years	
	Vent Piping	Entire Building	19,700	SF	6	6-10 years	
Pumps							
	Pumps - Sump-Simplex	Other	1	EA	6	10+ years	Located at the bottom of the elevator pit. Inaccessible at the time of assessment. Pump operates as intended in service per Building Engineer.

Category: Room **Building: Addition** 

Juicge	ny i itooiii		Dullaring : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dminis	trative Suites/Offices									
	Ceiling - Lay-in	116 Teacher's Lounge	523	SF	7	10+ years				
	Doors - Wood Doors inclu hw	116 Teacher's Lounge	1	ĒΑ	7	10+ years				
	Floor - Tile	116 Teacher's Lounge	523	SF	7	10+ years				
	Lighting - Lay-in	116 Teacher's Lounge	9	ĒΑ	7	10+ years				
	Power Distribution	116 Teacher's Lounge	10	EA	7	10+ years				
	Walls - Concrete Block	116 Teacher's Lounge	749	SF	7	10+ years				
	Walls - Plaster/Drywall	116 Teacher's Lounge	300	SF	7	10+ years				
	Ceiling - Lay-in	Kitchen Office/Storage	220	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Kitchen Office/Storage	1	EA	7	10+ years				
	Floor - Tile	Kitchen Office/Storage	220	SF	7	10+ years				
	Lighting - Lay-in	Kitchen Office/Storage	4	EΑ	7	10+ years				
	Power Distribution	Kitchen Office/Storage	4	EA	7	10+ years				
	Walls - Concrete Block	Kitchen Office/Storage	601	SF	7	10+ years				
	Ceiling - Lay-in	Office 217	560	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office 217	1	EA	6	10+ years				
	Floor - Carpet	Office 217	560	SF	6	2-5 years				
	Lighting - Lay-in	Office 217	6	EA	7	6-10 years				
	Walls - Plaster/Drywall	Office 217	864	SF	7	10+ years				
	Ceiling - Lay-in	Office in Library 219	436	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Office in Library 219	1	EA	7	10+ years				
	Floor - Carpet	Office in Library 219	436	SF	7	6-10 years				
	Lighting - Lay-in	Office in Library 219	2	EA	7	6-10 years				
	Walls - Plaster/Drywall	Office in Library 219	600	SF	7	10+ years				
	Work SInk	Office in Library 219	1	EA	7	10+ years				
	Ceiling - Lay-in	Teacher's Work Room 218	560	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Teacher's Work Room 218	1	EA	7	10+ years				

Campus Name: Morrill Page : 32 of 43 Assessment Date: 02/14/2022



Catego	Category : Room		В	uilding	: Additi		
_						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	Teacher's Work Room 218	560	SF	6	2-5 years	
	Lighting - Lay-in	Teacher's Work Room 218	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Teacher's Work Room 218	864	SF	7	10+ years	
itchen							
	Ceiling - Lay-in	1st Floor	1,535	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,535	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	10+ years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,300	SF	7	10+ years	
ibrary							
	Ceiling - Lay-in	Room 219 2nd floor	2,345	SF	6	10+ years	Moisture stain around air diffusers
	Ceiling - Lay-in	Room 219 2nd floor	25	SF	4	1-2 years	throughout Water damage
	Doors - Wood Doors inclu hw			Sr EA			water damage
		Room 219 2nd floor	2		7	10+ years	
	Floor - Tile	Room 219 2nd floor	2,370	SF	7	10+ years	
	Lighting - Lay-in	Room 219 2nd floor	29	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 219 2nd floor	4,960	SF	7	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	118 Lunchroom 1st floor	3,029	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118 Lunchroom 1st floor	3	EA	7	10+ years	
	Floor - Tile	118 Lunchroom 1st floor	3,029	SF	7	10+ years	
	Lighting - Lay-in	118 Lunchroom 1st floor	36	EA	7	10+ years	
	Storage/ Closet	118 Lunchroom 1st floor	281	SF	7	10+ years	
	Walls - Concrete Block	118 Lunchroom 1st floor	5,398	SF	7	10+ years	
	Walls - Plaster/Drywall	118 Lunchroom 1st floor	350	SF	7	10+ years	
MDF ID	E						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	150	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EΑ	7	10+ years	Ductless split
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Loading Docks	1st Floor	180	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	65	SF	7	10+ years	
	Janitor's Closet	2nd Floor	50	SF SF	7	10+ years 10+ years	
	James 3 Gloset	2110 1 1001	30	OI.	,	10+ years	
estroor	n						

Page : 33 of 43 Campus Name: Morrill Assessment Date: 02/14/2022



Catego	Category : Room			Building : Addition					
			_			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_	Accessories	1st Floor	62	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	62	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	62	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	124	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	102	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	1st Floor	62	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	62	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	62	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	124	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	102	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	Toilet in 119	40	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Toilet in 119	40	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Toilet in 119	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Toilet in 119	40	SF	7	10+ years			
	Floor Drain	Toilet in 119	1	EA	7	10+ years			
	Lavatory	Toilet in 119	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Toilet in 119	1	EA	7	10+ years			
	Walls - Concrete Block	Toilet in 119	100	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Toilet in 119	100	SF	7	10+ years			
	Water Closet	Toilet in 119	1	EA	7	10+ years			
	Accessories	Toilet in Kitchen	40	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Toilet in Kitchen	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Toilet in Kitchen	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Toilet in Kitchen	40	SF	7	10+ years			
	Floor Drain	Toilet in Kitchen	1	ĒΑ	7	10+ years			
	Lavatory	Toilet in Kitchen	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Toilet in Kitchen	1	EA	7	10+ years			
	Walls - Concrete Block	Toilet in Kitchen	130	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Toilet in Kitchen	100	SF	7	10+ years			
	Water Closet	Toilet in Kitchen	1	EA	7	10+ years			



Catego	ry : Classroom		В	uilding	: Additio	on	•
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #117 (Office)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	523	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	523	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	ĒΑ	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	746	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years	
	·					•	
Classroo	m #119 (Pre School)						
	Ceiling - Lay-in	1st Floor	1,005	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	-
	Floor - Tile	1st Floor	1,029	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,046	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	279	SF	7	10+ years	
Classroo	m #216 (Art Room)						
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,069	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,069	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	1,280	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
01	#000 (O: D						
Classroo	m #220 (Store Room)	01 51				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	726	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF SF	7 7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,200	5F	1	10+ years	
Catego	ry : Interior		R	uildina	: Additio	on	
Jacogo	y :			anding	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	<b>,</b>					•	



Catego	ry : Interior	Building : Addition					
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	844	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,810	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,654	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	4	EA	6	10+ years	
	Student Lockers - Two Tiers	1st Floor	9	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,708	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	770	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,158	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,158	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	2,500	SF	7	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	12	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
Stairs							
Otans	Ceiling - Plaster/Drywall	Center stairs	180	SF	7	10+ years	
	Floor - Tile	Center stairs	180	SF	7	10+ years	
	Handrails	Center stairs	58	LF	7	10+ years	
	Lighting - Pendent/Surface	Center stairs	2	EA	6	6-10 years	
	Stairs - Concrete	Center stairs	120	LF	7	10+ years	Corrected quantity
	Ceiling - Lay-in	North	180	SF	7	10+ years	
	Floor - Tile	North	180	SF	7	10+ years	
	Handrails	North	58	LF	7	10+ years	
	Lighting - Lay-in	North	2	EA	7	6-10 years	
	Stairs - Tile	North	120	LF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North	1,160	SF	7	10+ years	,
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	6-10 years	

Campus Name: Morrill Page : 36 of 43 Assessment Date: 02/14/2022



Category : Exterior			В	uilding	: Field H		
0	Ham Time	Location	Ouantitus	UOM	Dank	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance		_					
	Exterior Doors - Exterior Steel Door	#16 S	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#16 S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#17 S	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#17 S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#18 N	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#18 N	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#19 N	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#19 N	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#20 N	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#20 N	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#21 S	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#21 S	3	LF	6	10+ years	
			_			, , , , , , , , , , , , , , , , , , ,	
_Foundat	ion Foundation - Concrete	Fatire Duilding	227	LF	7	10	
		Entire Building	237	SF	7 7	10+ years	
	Superstructure - Heavy Timber	Entire Building	1,900	SF	,	10+ years	
Roof Sy							
	Downspouts - Exterior Downspouts	Main Roof	60	LF	6	6-10 years	
	Roof - Metal	Main Roof	2,383	SF	5	2-5 years	Rusted
	Roof Structure - Heavy Timber	Main Roof	1,906	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	2,114	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10	SF	4	0-1 year	Missing brick
	Exterior Walls Brick	Little Building	10	O.	-	o i yeai	Wildering Briok
Window							
	Guard - Guards wire guard	Entire Building	360	SF	5	2-5 years	
	Lintels - Steel	Entire Building	90	LF	7	10+ years	
	Windows - Wood- Single-pane	Entire Building	360	SF	4	0-1 year	Rotten, deteriorating
Catego	ry : Electrical		В	uilding	: Field H	łouse	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_	· ·	Location	Qualitity	UUIVI	Naiik	Replacement	Comments
_ <u></u> Emerge	ncy System						
	Security System - Intrusion Detection	Entire Building	1,900	SF	6	6-10 years	
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	6-10 years	



Catego	ry : Mechanical		Building : Field House						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Heating	Devices								
	Gas/ Natural Draft Furnace - Less than 100 MBH	1st Floor	1	EA	5	6-10 years			
Tempera	ature Control								
	Electric Thermostat	Entire Building	1	EA	6	6-10 years			
Ventilation	on								
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Restroom exhaust fan in the attic space, not safely accessible at the time of assessment.		

Category : Plumbing **Building: Field House** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
_Piping_							
. •	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	1,900	SF	3	0-1 year	Building is not in use and water service has been disconnected.
	Sanitary Piping	Entire Building	1,900	SF	6	6-10 years	
	Storm Piping	Entire Building	1,900	SF	4	1-2 years	Deteriorated and damaged with missing sections.
	Vent Piping	Entire Building	1,900	SF	6	6-10 years	Inside the walls and inaccessible at the time of assessment.

Category: Room **Building: Field House** 

	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lunch &	Multipurpose Room						
	Ceiling - Splined	Room 1	270	SF	6	10+ years	Wood ceiling
	Doors - Wood Doors inclu hw	Room 1	1	EA	6	10+ years	•
	Floor - Concrete	Room 1	270	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 1	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 1	648	SF	7	10+ years	
	Ceiling - Splined	Room 1E	460	SF	6	10+ years	Wood ceiling
	Doors - Wood Doors inclu hw	Room 1E	1	EA	6	10+ years	-
	Floor - Concrete	Room 1E	460	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 1E	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	Room 1E	960	SF	6	10+ years	
	Ceiling - Splined	Room 1W	460	SF	6	10+ years	Wood ceiling

Campus Name: Morrill Page : 38 of 43 Assessment Date: 02/14/2022



atego	ry : Room		В	Building : Field House					
_				_		Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Room 1W	1	EA	6	10+ years			
	Floor - Concrete	Room 1W	460	SF	7	10+ years			
	Lighting - Pendent/Surface	Room 1W	6	EA	7	10+ years			
	Walls - Structural Glazed Tile	Room 1W	960	SF	6	10+ years			
echani	cal/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	100	SF	7	10+ years			
	Storage Room	1st Floor	50	SF	7	10+ years			
estroor	n								
	Accessories	1st floor Men's	50	SF	5	2-5 years			
	Ceiling - Plaster/Drywall	1st floor Men's	50	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st floor Men's	1	EA	6	10+ years			
	Floor - Epoxy/ Painted	1st floor Men's	50	SF	5	2-5 years	Worn and cracked paint		
	Floor Drain	1st floor Men's	1	EA	7	10+ years			
	Lavatory	1st floor Men's	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st floor Men's	1	EA	7	10+ years			
	Partitions	1st floor Men's	1	EA	5	6-10 years			
	Urinals	1st floor Men's	2	EA	6	10+ years			
	Walls - Structural Glazed Tile	1st floor Men's	260	SF	6	10+ years			
	Water Closet	1st floor Men's	1	EA	6	10+ years			
	Accessories	1st floor Women's	50	SF	5	2-5 years			
	Ceiling - Plaster/Drywall	1st floor Women's	50	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st floor Women's	1	EA	6	10+ years			
	Floor - Epoxy/ Painted	1st floor Women's	50	SF	5	2-5 years			
	Floor Drain	1st floor Women's	1	EA	7	10+ years			
	Lavatory	1st floor Women's	2	EA	6	10+ years			
	Partitions	1st floor Women's	1	EA	5	2-5 years	Rusted and torn		
	Walls - Structural Glazed Tile	1st floor Women's	260	SF	6	10+ years			
	Water Closet	1st floor Women's	1	EA	4	0-1 year	Broken		
Category : Interior		В	uilding	: Field I	louse				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
afety	Sagurity Compress	Entire Duilding	4	ΓΛ	7	10 L VOORS			
	Security Cameras	Entire Building	4	EA	7	10+ years			



Category : Site **Building: Site** 

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	South	5,798	SF	6	6-10 years	
	Lighting	South	4	EA	6	6-10 years	
	Surface - Synthetic	South	9,734	SF	6	6-10 years	
	Lighting	South	4	EΑ	6	6-10 years	
	Surface - Asphalt	South	3,662	SF	7	10+ years	
	Canado /tophak	Coun	0,002	O.	•	To Tyouro	
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	6	10+ years	
encina							
	Fencing - Chain Link	Entire Site	320	LF	4	0-1 year	Leaning and Bent throughout
	Fencing - New Standard Ornamental	Entire Site	540	LF	6	10+ years	9
andsca	na						
<u>.anusca</u>	Benches	Entire Site	4	EA	7	10+ years	
	Landscape - Grass	Entire Site	17,940	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	4,765	SF	6	6-10 years	
	Lighting - Pole Mounted	Entire Site	6	EA	6	6-10 years	
	Parkway trees	Entire Site	56	EA	6	6-10 years	
	Planting Beds/ Area	Entire Site	5,114	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	3,662	SF	7	10+ years	
				SF			
	Play Area - Hardscape- Asphalt	Entire Site	9,016		7	10+ years	
	Play Area - Synthetic Turf	Entire Site	2,072	SF	6	6-10 years	
	Trash Receptacles	Entire Site	4	EA	7	10+ years	
Parking I	Lot						
	Surface - Asphalt	Northeast Courtyard	20,000	SF	6	6-10 years	
	Surface - Asphalt	Northeast Courtyard	6,902	SF	4	0-1 year	Severe alligator cracking and hole
	Surface - Concrete	Northeast Courtyard	8,308	SF	5	6-10 years	
	Trash Compactor	Northeast Courtyard	1	EΑ	6	6-10 years	
	Trash Enclosure - Chain Links	Northeast Courtyard	1,600	SF	7	10+ years	
Playgrou	und						
	Surface - Poured Surface	South Courtyard	931	SF	7	10+ years	
	Equipment - School Age 5-12	Southeast courtyard	1	EΑ	7	10+ years	
	Surface - Poured Surface	Southeast courtyard	2,678	SF	7	10+ years	
Sidewalk							
bidewalk		Entire Cite	040	1.5		6.10	
	Sidewalks - Internal Walks	Entire Site	640	LF	6	6-10 years	

Campus Name: Morrill Page: 40 of 43 Assessment Date: 02/14/2022



#### **Donald Morrill Math & Science Elementary School**

6011 S Rockwell STREET, Chicago, IL 60629

Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	10,576	SF	6	6-10 years	Uneven at front of building
Signage							
	Flag Pole - Flag Pole	East	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	East	1	EA	6	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Morrill Page : 41 of 43 Assessment Date: 02/14/2022

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				EL BI					
			D	Floor Plan	A	Glazed	Operable	\A(!	0
0	lest a un de el Ula a una	Daniel andian	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		0.15	0.10	040	700	70			
Computer Lab	Regular Classroom	3rd Floor	310	310	730	70	6	N	N
Kindergarten	Art Room	1st Floor	113	113	967	130	12	Y	N
Kindergarten	Kindergarten	1st Floor	108	108	1,146	130	14	Y	Y
Kindergarten	Regular Classroom	1st Floor	114	114	730	100	12	Υ	Υ
Office	Regular Classroom	1st Floor	107	107	750	80	6	Υ	Y
Office	Regular Classroom	2nd Floor	214B	214B	365	100	9	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	730	100	9	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	730	100	9	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	730	100	9	Υ	N
Regular Classroom	Regular Classroom	1st Floor	109	109	730	100	6	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	730	100	9	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	760	100	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	730	90	7	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	730	100	9	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	730	90	7	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	730	100	9	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	730	90	7	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214A	730	100	9	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	730	100	9	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	730	80	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	730	80	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	715	80	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	730	80	6		
Regular Classroom	Regular Classroom	3rd Floor	311	311	730	80	6	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	730	80	6	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	730	80	6	N	N
Science Classroom	Regular Classroom	3rd Floor	309	309	730	80	6	N	N
Science Classroom	Regular Classroom	3rd Floor	314	314	730	80	6	N	Y
		•	•	,	ı			•	<u> </u>
Building : Addition									
Art Room	Science	2nd Floor	216	205	1,069	156	156		
Office	Regular Classroom	1st Floor	117	107	523	52	49	Υ	



**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Pre School	Pre School	1st Floor	119	119	1,029	157	75		Υ
Store Room	Multi Purpose Room	2nd Floor	220	222	726	156	156	N	N