Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Leased-Main | 1926 | 3 | 42,197 |
| Campus Total | | | 42,197 |

Category : Exterior Building : Leased-Main

| | | | | | | Recommend | |
|----------|---------------------------------------|-----------------|----------|-----|------|-------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | | | | | | | |
| | Entrance Control - Audio | #1 - Main - E | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | #1 - Main - E | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | #1 - Main - E | 1 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Stone | #1 - Main - E | 32 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #2 - SE | 2 | EA | 5 | 0-1 year | Corroding door and frame |
| | Exterior Doors - Transom Lite | #2 - SE | 1 | EA | 5 | 0-1 year | Corroding frame |
| | Exterior Stairs - Stone | #2 - SE | 24 | LF | 5 | 6-10 years | Minor cracking. |
| | Exterior Doors - Exterior Steel Door | #2.5 - SW | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #2.5 - SW | 12 | LF | 6 | 2-5 years | |
| | Exterior Stairs - Concrete | #2.5 - SW | 16 | LF | 4 | 0-1 year | Cracked, broken steps |
| | Stair Handrail - Steel_Stair Handrail | #2.5 - SW | 25 | LF | 6 | 10+ years | |
| | Entrance Control - Audio | #3 - NW | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #3 - NW | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #3 - NW | 1 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Stone | #3 - NW | 8 | LF | 5 | 0-1 year | Cracked stone |
| Foundati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 333 | LF | 7 | 10+ years | |
| | Foundation - Concrete | Entire Building | 20 | LF | 6 | 0-1 year | Settlement of slab, sunken area, underneath stairs at door number three and two. |
| | Foundation - Concrete | Entire Building | 10 | LF | 5 | 0-1 year | Seepage through cracks in the concrete foundation. |
| | Foundation - Concrete | Entire Building | 10 | LF | 4 | 0-1 year | Lightwell wells are badly damaged |



| Catego | egory : Exterior | | | uilding | : Lease | d-Main | | |
|-----------|---|-----------------|----------|---------|---------|-------------|---|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Superstructure - Concrete | Entire Building | 29,960 | SF | 7 | 10+ years | and missing Sections of concrete. | |
| | Superstructure - Concrete | Entire building | 29,900 | SF | , | 10+ years | | |
| Lighting | | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 3 | EA | 6 | 6-10 years | | |
| Roof Sys | etem | | | | | | | |
| rtoor cys | Access Ladder - Wood | Main Roof | 1 | EA | 4 | 0-1 year | There is no ladder to get to the space | |
| | 7,00000 200007 | Main 1700. | · | 273 | · | o i you. | between the roof and ceiling. The ladder to go up to the roof is handmade and nailed together. | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Main Roof | 49 | LF | 7 | 10+ years | nandmade and nalied together. | |
| | Coping - Stone | Main Roof | 373 | LF | 7 | 10+ years | Sealant is in very good shape | |
| | Downspouts - Exterior Downspouts | Main Roof | 201 | LF | 4 | 0-1 year | Engineer says that the clean outs are open because the drains do not work very well. Every downspout on the roof there are several patches. The gutter is 3 x 4" which is smaller than 6 inch diameter of the downspout. Water freezes at the gutters on the | |
| | | | | | | | roof, Water backs up and freezes. When it thaws it creates leaks on the interior coming through the tops of the windows. There is a collapsed sewer/stack line with 12 toilets that cont work. Engineer suspects that the downspouts may tie to this collapsed sewer. | |
| | Parapet - 16" - 30" Height | Main Roof | 365 | LF | 7 | 10+ years | Repaired | |
| | Parapet - Parapet > 30" | Main Roof | 8 | LF | 7 | 10+ years | Repaired | |
| | Roof - Modified Bitumen | Main Roof | 7,490 | SF | 6 | 10+ years | | |
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | | |
| | Roof Structure - Steel with Clay Tile Arch | Main Roof | 7,490 | SF | 7 | 10+ years | | |
| Walls | | | | | | | | |
| | Cheek-Wall - Stone | Entire Building | 4 | SF | 6 | 10+ years | | |
| | Cornice - Cast Stone | Entire Building | 462 | LF | 6 | 10+ years | | |
| | Cornice - Cast Stone | Entire Building | 20 | LF | 5 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 16,497 | SF | 6 | 10+ years | | |
| | | | 00 | CE | 4 | 0 1 1/00" | Crooked manager and ininte at do | |
| | Exterior Walls - Brick | Entire Building | 20 | SF | 4 | 0-1 year | Cracked masonry, open joints at do three | |



| Category : Exterior Building : Leased-Main | | | | | | | |
|--|--|-----------------|---------------------------------------|---------|---------|-------------|--|
| | _ | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exterior Walls - Stone-Cast | Entire Building | 50 | SF | 5 | 10+ years | |
| Window | e | | | | | | |
| VVIIIGOV | Curtain wall - Insulated Panel | Entire Building | 1,274 | SF | 6 | 10+ years | |
| | Guard - Guards wire guard | Entire Building | 300 | SF | 6 | 10+ years | |
| | Guard - Guards wire guard | Entire Building | 184 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 441 | LF | 6 | 6-10 years | |
| | Windows - Decorative | Entire Building | 240 | SF | 7 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 2,141 | SF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | | · · · · · · · · · · · · · · · · · · · | SF | 5 | | |
| | windows - Sash Aluminum Double-pane | Entire Building | 113 | SF | Э | 10+ years | |
| Catego | ry : Electrical | | В | uilding | : Lease | d-Main | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerge | ncy System | | - | | | 0.10 | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 16 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 15 | EA | 2 | 0-1 year | No AC power or EM generator or battery backup |
| | Exit Signs - Multipurpose Room | Entire Building | 4 | EA | 2 | 0-1 year | No AC power or EM generator or battery backup. |
| | Security System - CCTV | Entire Building | 42,197 | SF | 6 | 6-10 years | battory backup. |
| | Security System - Intrusion Detection | Entire Building | 42,197 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and | Entire Building | 6,262 | SF | 6 | 10+ years | |
| | Stairs | Zimo Dananig | 0,202 | ٥. | Ü | io. you.o | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,999 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Multipurpose | Entire Building | 10,238 | SF | 6 | 10+ years | |
| | Room | Zimo Dananig | 10,200 | ٥. | Ü | io. you.o | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,051 | SF | 6 | 10+ years | |
| Main Se | rvice | | | | | | |
| | Independent Electrical Service for | Basement | 1 | EA | 6 | 10+ years | |
| | emergency power | | | | | , | |
| | Main Electrical Service - 800 A and | Electrical Room | 1 | EA | 6 | 10+ years | |
| | 120/240/3PH | | | | - | , | |
| | PA System | Entire Building | 42,197 | SF | 6 | 6-10 years | |
| | 7 | | , | | - | , | |
| Power D | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 6 | EA | 6 | 10+ years | Quantity change per current observation |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EA | 6 | 10+ years | |
| | Transformers - 120/240 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | |
| | | S | | | | , | |



| Catego | ry : Electrical | | В | uilding | : Lease | | |
|-----------|--|-----------------|------------|---------|---------|-------------|--|
| C=== | Itana Tima | Laatian | Overetites | LIOM | Dank | Recommend | C |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Catego | ry : Fire Protection | | В | uilding | : Lease | d-Main | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 42,197 | SF | 4 | 0-1 year | Old system |
| Catego | ry : Mechanical | | В | uildina | : Lease | d-Main | |
| Jaiogo | . y r moonamou. | | _ | u | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Conc | litioning | | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Entire Building | 2 | EA | 6 | 6-10 years | New item added per current observation. Exterior wall by music |
| | Condensing Unit- Roof Mounted - Less | Entire Building | 1 | EA | 6 | 6-10 years | room. Belongs to church, maintained by |
| | than 5 tons | Entire building | • | LA | O | 0-10 years | church. |
| Boiler Sy | | | | | | | |
| | Boiler Auxiliary- Steam Boiler - Less than 50 HP | Entire Building | 3 | EA | 5 | 6-10 years | Valve leaking |
| | Chemical Feed System | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Chemical Feeder | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Entire Building | 3 | EA | 6 | 10+ years | |
| | Condensate Pump | Entire Building | 4 | EA | 6 | 10+ years | Quantity change per current observation |
| | Feed Water Pumps and Tank | Entire Building | 1 | EA | 6 | 10+ years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - Less than 50 HP | Entire Building | 3 | EA | 5 | 6-10 years | Valve leaking |
| | Piping - Condensate Pipe- Steel | Entire Building | 120 | LF | 5 | 6-10 years | Clamp installed |
| | Piping - Steam Pipe- Steel | Entire Building | 120 | LF | 5 | 6-10 years | Clamp installed |
| | Steam Traps | Entire Building | 12 | EA | 5 | 6-10 years | Corroded |
| Heating | Devices | | | | | | |
| | Unit Heater - Electric | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Radiators - Steam | Entire Building | 85 | EA | 6 | 6-10 years | |
| Tempera | ature Control | | | | | | |
| • | DDC System | Entire Building | 42,197 | SF | 5 | 1-2 years | Older system. |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 10+ years | New item added per current observation |



North River Elementary School

| ALL A | Schools | | | | | 3 | 729 W Leland AVENUE, Chicago, IL 6062 |
|------------|--|---|----------|----------|---------|------------------------|--|
| Catego | ry : Mechanical | | В | | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Thermostats - DDC | Entire Building | 1 | EA | 6 | 6-10 years | |
| /entilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | In food prep, 1 in church multipurpose and roof and entire building | 1 | EA | 6 | 10+ years | New item added per current observation Kitchen |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | In food prep, 1 in church multipurpose and roof and entire building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | In food prep, 1 in church multipurpose and roof and entire building | 4 | EA | 6 | 10+ years | Toilet |
| | Exhaust Fans- Indoor - Less than 500 CFM | In food prep, 1 in church multipurpose and roof and entire building | 3 | EA | 6 | 6-10 years | |
| atego | ry : Plumbing | | В | uilding | : Lease | d-Main | |
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | er | | | | | | |
| | Gas Heater - Less than 150000 BTU/HR Electric Heater - Less than 20 KW | Boiler Room Entire Building | 1 1 | EA EA | 6 7 | 2-5 years 10+ years | Serves only kitchen |
| Piping | | | | | | | |
| . 5 | Domestic Piping-Hot Water Return Lines | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Sanitary Piping | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 42,197 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 42,197 | SF | 6 | 10+ years | |
| umps | | | | | | | |
| • | Pumps - Ejector-Simplex | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | | | | | | | |
| Catego | ry : Room | | В | uilding | : Lease | d-Main | |





| | | | | | Replacement | |
|-----------------------------|--|-----|----------|--------|-------------|-----------------|
| ve Suites/Offices | | | | | | |
| AC Unit | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 162 | SF | 6 | 10+ years | |
| Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| Floor - Carpet | 2nd Floor | 134 | SF | 6 | 6-10 years | Stained. |
| Floor - Tile | 2nd Floor | 28 | SF | 6 | 2-5 years | |
| ighting - Pendent/Surface | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Power Distribution | 2nd Floor | 6 | EA | 6 | 10+ years | |
| Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 2nd Floor | 362 | SF | 6 | 10+ years | |
| Ceiling - Plaster/Drywall | 2nd Floor Conference Room | 145 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 2nd Floor Conference Room | 1 | ĒΑ | 6 | 10+ years | |
| Floor - Wood | 2nd Floor Conference Room | 145 | SF | 6 | 6-10 years | |
| ighting - Lay-in | 2nd Floor Conference Room | 2 | EA | 7 | 10+ years | |
| Power Distribution | 2nd Floor Conference Room | 10 | EΑ | 6 | 10+ years | |
| Walls - Plaster/Drywall | 2nd Floor Conference Room | 314 | SF | 6 | 10+ years | |
| Work Sink | 2nd Floor Conference Room | 1 | EA | 7 | 10+ years | |
| AC Unit | Admin Ofc in Main Office #2 1st floor | 1 | EA | 7 | 6-10 years | |
| Ceiling - Splined | Admin Ofc in Main Office #2 1st floor | 89 | SF | 7 | 10+ years | |
| Floor - Terrazzo | Admin Ofc in Main Office #2 1st floor | 89 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | | 09 | EA | | | |
| | Admin Ofc in Main Office #2 1st floor | 4 | | 7 6 | 10+ years | |
| Power Distribution | Admin Ofc in Main Office #2 1st floor | - | EA | | 10+ years | |
| Walls - Concrete Block | Admin Ofc in Main Office #2 1st floor | 58 | SF SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | Admin Ofc in Main Office #2 1st floor | 173 | | 7 | 10+ years | |
| Ceiling - Splined | Admin Ofc in Main Office 1st floor | 89 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Admin Ofc in Main Office 1st floor | 1 | EA | 7 | 10+ years | |
| Floor - Terrazzo | Admin Ofc in Main Office 1st floor | 89 | SF | 6 | 10+ years | |
| ighting - Pendent/Surface | Admin Ofc in Main Office 1st floor | 1 | EA | 7 | 10+ years | |
| Power Distribution | Admin Ofc in Main Office 1st floor | 4 | EA | 7 | 10+ years | |
| Walls - Concrete Block | Admin Ofc in Main Office 1st floor | .58 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | Admin Ofc in Main Office 1st floor | 173 | SF | 7 | 10+ years | |
| AC Unit | Assistant Principal's Office 1st floor | 1 | EA | 4 | 0-1 year | Out of service. |
| Ceiling - Splined | Assistant Principal's Office 1st floor | 125 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | Assistant Principal's Office 1st floor | 1 | EA | 6 | 10+ years | |
| Floor - Terrazzo | Assistant Principal's Office 1st floor | 125 | SF | 7 | 10+ years | |
| ighting - Pendent/Surface | Assistant Principal's Office 1st floor | 1 | EA | 7 | 10+ years | |
| Power Distribution | Assistant Principal's Office 1st floor | 6 | EA | 6 | 10+ years | |
| Nalls - Plaster/Drywall | Assistant Principal's Office 1st floor | 258 | SF | 6 | 10+ years | |
| Ceiling - Lay-in | Counselor's Office - 3rd floor | 163 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | Counselor's Office - 3rd floor | 1 | EA | 6 | 10+ years | |
| Floor - Wood | Counselor's Office - 3rd floor | 163 | SF | 6 | 10+ years | |
| _ighting - Lay-in | Counselor's Office - 3rd floor | 1 | EA | 7 | 6-10 years | |
| Power Distribution | Counselor's Office - 3rd floor | 4 | EA | 6 | 10+ years | |
| Storage/ Closet | Counselor's Office - 3rd floor | 20 | SF | 7 | 10+ years | |
| Nalls - Plaster/Drywall | Counselor's Office - 3rd floor | 278 | SF | 6 | 10+ years | |
| Ceiling - Plaster/Drywall | Engineer's Office | 135 | SF | 7 | 10+ years | |



| | | | | | | Replacement | |
|----------|--------------------------------------|------------------------------|-------|----|---|-------------|---------------|
| | Floor - Concrete | Engineer's Office | 135 | SF | 7 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | Engineer's Office | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Engineer's Office | 6 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Engineer's Office | 520 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Kitchen Manager's Office | 75 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Kitchen Manager's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Kitchen Manager's Office | 75 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen Manager's Office | 1 | EA | 7 | 10+ years | |
| | Power Distribution | Kitchen Manager's Office | 4 | EΑ | 6 | 10+ years | |
| | Walls - Metal Panel | Kitchen Manager's Office | 198 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Main Office on 1st Floor | 350 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Main Office on 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | Main Office on 1st Floor | 350 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Main Office on 1st Floor | 3 | EA | 7 | 10+ years | |
| | Power Distribution | Main Office on 1st Floor | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Main Office on 1st Floor | 100 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Main Office on 1st Floor | 22 | SF | 5 | 0-1 year | Cracked brick |
| | Walls - Plaster/Drywall | Main Office on 1st Floor | 365 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Principal's Office 2nd floor | 101 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Principal's Office 2nd floor | 24 | SF | 4 | 0-1 year | Water damage. |
| | Doors - Wood Doors inclu hw | Principal's Office 2nd floor | 1 | EA | 6 | 10+ years | · · |
| | Floor - Wood | Principal's Office 2nd floor | 125 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Principal's Office 2nd floor | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Principal's Office 2nd floor | 6 | EA | 6 | 10+ years | |
| | Storage/ Closet | Principal's Office 2nd floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Office 2nd floor | 258 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Teacher's Room -3rd floor | 162 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Teacher's Room -3rd floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | Teacher's Room -3rd floor | 162 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Teacher's Room -3rd floor | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Teacher's Room -3rd floor | 6 | EA | 7 | 10+ years | |
| | Storage/ Closet | Teacher's Room -3rd floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Teacher's Room -3rd floor | 362 | SF | 6 | 10+ years | |
| _Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 277 | SF | 6 | 6-10 years | |
| | Doors - Transom Window | Basement | 3 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 277 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 4 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | Basement | 545 | SF | 7 | 10+ years | |
| | | | - ·- | | | , | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,235 | SF | 7 | 10+ years | 0 1: |
| | Ceiling - Plaster/Drywall | 1st Floor | 30 | SF | 5 | 0-1 year | Cracking. |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |



| | | | | | | 3729 W Leiand AVENUE, Chicago, iL 60 |
|--|------------------------|-------|----|--------|---|--------------------------------------|
| | | | | | Replacement | |
| Floor - Terrazzo | 1st Floor | 1,265 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 6 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 1st Floor | 1,904 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | Basement | 1,499 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Basement | 2 | EΑ | 6 | 10+ years | |
| Floor - Tile | Basement | 1,499 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | Basement | 18 | EA | 7 | 10+ years | |
| Serving Line | Basement | 14 | LF | 6 | 6-10 years | |
| Walls - Plaster/Drywall | Basement | 1,549 | SF | 7 | 10+ years | |
| Walls - Structural Glazed Tile | Basement | 1,549 | SF | 7 | 10+ years | |
| | | ., | - | - | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| F_IDF | | | | | 40 | _ |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| Finishes | 3rd Floor | 196 | SF | 7 | 10+ years | |
| Window AC Unit | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| chanical/ Service Rooms | | | | | | |
| Mechanical/ Service Rooms | 1st Floor | 176 | SF | 7 | 10+ years | |
| Storage Room | 1st Floor | 53 | SF | 7 | 10+ years | |
| Janitor's Closet | 2nd Floor | 32 | SF | 5 | 10+ years | Ceiling paint chipping and peelin |
| Janitor's Closet | 3rd Floor | 32 | SF | 5 | 10+ years | Needs paint throughout. |
| Boiler Room | Basement | 679 | SF | 5 | 10+ years | Needs paint throughout. |
| Mechanical/ Service Rooms | Basement | 90 | SF | 5 | 10+ years | |
| | | | SF | | , | |
| Storage Room | Basement | 340 | SF | 5 | 10+ years | |
| stroom | | | | | | |
| Accessories | 1st Floor | 126 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 126 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| Floor - Tile Ceramic/ Porcelain | 1st Floor | 100 | SF | 6 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | 1st Floor | 26 | SF | 4 | 0-1 year | Cracked floor. |
| Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | Gradica noor. |
| Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Lavatory | 1st Floor | 2 | EA | 6 | 10+ years | |
| | | 1 | EA | 7 | • | |
| Lighting - Pendent/Surface | 1st Floor | | | | 10+ years | |
| Partitions | 1st Floor | 2 | EΑ | 7 | 10+ years | |
| Urinals | 1st Floor | 3 | EA | 6 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 141 | SF | 7 | 10+ years | |
| Walls - Structural Glazed Tile | 1st Floor | 141 | SF | 7 | 10+ years | |
| Water Closet | 1st Floor | 2 | EA | 6 | 6-10 years | |
| Accessories | 1st Floor | 159 | SF | 7 | 6-10 years | |
| | 4 of Elean | 159 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | 1st Floor | 100 | | | | |
| | 1st Floor 1st Floor | 139 | ĒΑ | 6 | 10+ years | |
| Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 6 | • | |
| Ceiling - Plaster/Drywall | | | | | 10+ years 10+ years 6-10 years | |



| | | | | | Replacement | |
|---------------------------------|-----------|-----|----|---|------------------------|---------------|
| Lighting - Pendent/Surface | 1st Floor | 1 | EΑ | 7 | 10+ years | |
| Partitions | 1st Floor | 4 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 152 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | 1st Floor | 152 | SF | 7 | 10+ years | |
| Water Closet | 1st Floor | 4 | EA | 7 | 10+ years | |
| Accessories | 2nd Floor | 67 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 67 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | 2nd Floor | 67 | SF | 6 | 10+ years | |
| Lavatory | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Partitions | 2nd Floor | 1 | EΑ | 7 | 10+ years | |
| Walls - Plaster/Drywall | 2nd Floor | 101 | SF | 6 | 10+ years | |
| Walls - Structural Glazed Tile | 2nd Floor | 101 | SF | 6 | 10+ years | |
| Water Closet | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| Accessories | 3rd Floor | 67 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor | 67 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | 3rd Floor | 67 | SF | 6 | 10+ years | |
| Lavatory | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| Partitions | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | 3rd Floor | 101 | SF | 6 | 10+ years | |
| Walls - Structural Glazed Tile | 3rd Floor | 101 | SF | 6 | 10+ years | |
| Water Closet | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Accessories | Basement | 331 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | Basement | 331 | SF | 7 | 10+ years | |
| Doors - Transom Window | Basement | 3 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | Basement | 331 | SF | 6 | 10+ years | |
| Hand Dryer | Basement | 1 | EA | 7 | 6-10 years | |
| Lavatory | Basement | 1 | EA | 6 | 10+ years | |
| Lighting - Pendent/Surface | Basement | 2 | EA | 7 | 10+ years | |
| Partitions | Basement | 6 | EA | 7 | | |
| Urinals | Basement | 12 | EA | 6 | 10+ years 10+ years | |
| | | 172 | SF | 7 | - | |
| Walls - Plaster/Drywall | Basement | | SF | | 10+ years | Water damage |
| Walls - Plaster/Drywall | Basement | 40 | SF | 4 | 0-1 year | Water damage. |
| Walls - Structural Glazed Tile | Basement | 212 | | 7 | 10+ years | |
| Water Closet | Basement | 6 | EA | 6 | 10+ years | |
| Accessories | Basement | 387 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | Basement | 387 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | Basement | 387 | SF | 6 | 10+ years | |
| Floor Drain | Basement | 1 | EA | 7 | 10+ years | |
| Hand Dryer | Basement | 1 | EΑ | 7 | 6-10 years | |
| Lavatory | Basement | 1 | EΑ | 6 | 10+ years | |
| Lighting - Pendent/Surface | Basement | 2 | EA | 7 | 10+ years | |



| | | | | | Replacement | |
|---------------------------------|-------------------------------|-----|----|---|-------------|-----------------------|
| Partitions | Basement | 13 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | Basement | 265 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | Basement | 250 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | Basement | 15 | SF | 5 | 0-1 year | Cracking around sink. |
| Water Closet | Basement | 13 | EΑ | 7 | 10+ years | |
| Accessories | In the Multipurpose Room | 28 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | In the Multipurpose Room | 28 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | In the Multipurpose Room | 1 | EΑ | 7 | 10+ years | |
| Floor - Concrete Epoxy/ Painted | In the Multipurpose Room | 28 | SF | 5 | 10+ years | Paint peeling off. |
| Floor Drain | In the Multipurpose Room | 1 | EΑ | 7 | 10+ years | |
| Lavatory | In the Multipurpose Room | 1 | EA | 7 | 10+ years | |
| Lighting - Pendent/Surface | In the Multipurpose Room | 1 | EA | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | In the Multipurpose Room | 102 | SF | 7 | 10+ years | |
| Water Closet | In the Multipurpose Room | 1 | EΑ | 7 | 10+ years | |
| Accessories | Pre-K Shared by Rooms 103/105 | 48 | SF | 7 | 6-10 years | |
| Ceiling - Lay-in | Pre-K Shared by Rooms 103/105 | 48 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Pre-K Shared by Rooms 103/105 | 1 | EA | 7 | 10+ years | |
| Floor - Concrete Epoxy/ Painted | Pre-K Shared by Rooms 103/105 | 48 | SF | 7 | 10+ years | |
| Floor Drain | Pre-K Shared by Rooms 103/105 | 1 | EA | 7 | 10+ years | |
| Lavatory | Pre-K Shared by Rooms 103/105 | 1 | EA | 6 | 10+ years | |
| Lighting - Lay-in | Pre-K Shared by Rooms 103/105 | 1 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | Pre-K Shared by Rooms 103/105 | 55 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | Pre-K Shared by Rooms 103/105 | 55 | SF | 7 | 10+ years | |
| Water Closet | Pre-K Shared by Rooms 103/105 | 1 | EA | 7 | 10+ years | |

Building: Leased-Main Category : Classroom

| | | | | | | Recommend | |
|---------|-----------------------------|-----------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classro | om #101 (Office) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 840 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EΑ | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EΑ | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,111 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 649 | SF | 7 | 10+ years | |
| Classro | om #103 (Special Education) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 620 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 620 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | | | | | | | |



| Category : Classroom | |
|--|--|
| Marker Board 1st Floor 9 LF 7 6-10 years Walls - Concrete Block 1st Floor 800 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 368 SF 7 10+ years Quantity changed Classroom #104 (Regular Classroom) AC Units 1st Floor 1 EA 7 6-10 years Ceiling - Splined 1st Floor 700 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years | |
| Walls - Concrete Block Walls - Plaster/Drywall 1st Floor 800 SF 7 10+ years 368 SF 7 10+ years 7 10+ years Quantity changed Classroom #104 (Regular Classroom) AC Units 1st Floor 1 EA 7 6-10 years Ceiling - Splined 1st Floor 700 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years | |
| Walls - Plaster/Drywall 1st Floor 368 SF 7 10+ years Quantity changed Classroom #104 (Regular Classroom) AC Units 1st Floor 1 EA 7 6-10 years Ceiling - Splined 1st Floor 700 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years | |
| Classroom #104 (Regular Classroom) | |
| AC Units | |
| AC Units | |
| Ceiling - Splined 1st Floor 700 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years | |
| Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years Classroom #105 (Special Education) | |
| Floor - Terrazzo 1st Floor 700 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years | |
| Lighting - Pendent/Surface 1st Floor 10 EA 7 10+ years Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years Classroom #105 (Special Education) | |
| Marker Board 1st Floor 16 LF 7 6-10 years Walls - Concrete Block 1st Floor 943 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years Classroom #105 (Special Education) | |
| Walls - Concrete Block Walls - Plaster/Drywall 1st Floor 943 SF 7 10+ years 474 SF 7 10+ years 1st Floor Classroom #105 (Special Education) | |
| Walls - Plaster/Drywall 1st Floor 474 SF 7 10+ years Classroom #105 (Special Education) | |
| | |
| | |
| | |
| Ceiling - Splined 1st Floor 620 SF 7 10+ years | |
| Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years | |
| Floor - Terrazzo 1st Floor 620 SF 7 10+ years | |
| Lighting - Pendent/Surface 1st Floor 12 EA 7 10+ years | |
| Walls - Concrete Block 1st Floor 848 SF 7 10+ years Quantity changed | |
| Walls - Plaster/Drywall 1st Floor 320 SF 7 10+ years | |
| _Classroom #106 (Regular Classroom) | |
| AC Units 1st Floor 1 EA 7 6-10 years | |
| Casework 1st Floor 10 LF 7 10+ years | |
| Ceiling - Splined 1st Floor 620 SF 7 10+ years | |
| Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years | |
| Floor - Terrazzo 1st Floor 620 SF 7 10+ years | |
| Lighting - Pendent/Surface 1st Floor 12 EA 7 10+ years | |
| Marker Board 1st Floor 16 LF 7 6-10 years | |
| Walls - Concrete Block 1st Floor 595 SF 7 10+ years | |
| Walls - Plaster/Drywall 1st Floor 435 SF 7 10+ years | |
| _Classroom #201 (Regular Classroom) | |
| AC Units 2nd Floor 1 EA 7 6-10 years | |
| Ceiling - Lay-in 2nd Floor 670 SF 6 10+ years | |
| Ceiling - Plaster/Drywall 2nd Floor 30 SF 6 10+ years | |
| Doors - Transom Window 2nd Floor 48 SF 7 10+ years | |
| Doors - Wood Doors inclu hw 2nd Floor 2 EA 6 10+ years | |
| Floor - Wood Boots inclum W 2nd Floor 2 EA 6 104 years | |
| Floor - Wood 2nd Floor 8 SF 4 0-1 year Boards separating | |
| Lighting - Lay-in 2nd Floor 8 EA 7 10+ years | |
| Lighting - Lay-in 2nd ribbi 0 LA 7 10+ years | |



| Category : Classroom | | | В | uilding | : Lease | | |
|----------------------|------------------------------|------------------------|----------|----------|---------|-------------|----------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 909 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 20 | SF | 5 | 0-1 year | Water damage |
| Classroo | m #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 670 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 48 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 690 | SF | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 10 | SF | 4 | 0-1 year | Finish worn |
| | Lighting - Lay-in | 2nd Floor | 8 | EA | 7 | 10+ years | i illion wom |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 881 | SF | 6 | - | |
| | walls - Plastel/Drywall | 2110 F1001 | 001 | SF | b | 10+ years | |
| lassroo | m #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 670 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 36 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 700 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 929 | SF | 6 | 10+ years | |
| lassroo | m #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 670 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 48 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood Boots including | 2nd Floor 2nd Floor | 685 | SF | 6 | 10+ years | |
| | Floor - Wood | | 15 | SF SF | 4 | | Finish wearing |
| | | 2nd Floor | | | | 0-1 year | Finish wearing |
| | Lighting - Lay-in | 2nd Floor | 8 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 871 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 10 | SF | 5 | 0-1 year | Cracking and dented. |
| lassroo | m #205 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 590 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 6 | • | |





| Category : Classroom | | | В | Building : Leased-Main | | | | | | |
|----------------------|---|------------------------|-----------|------------------------|--------|-------------|------------------------|--|--|--|
| | | | Recommend | | | | | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| - | Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Wood | 2nd Floor | 620 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 10 | ĒΑ | 6 | 10+ years | Extremely loud buzzing | | | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | 3 | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 852 | SF | 6 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 10 | SF | 5 | 0-1 year | Cracking. | | | |
| assroc | om #206 (Regular Classroom) | | | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 586 | SF | 6 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 4 | SF | 4 | 0-1 year | Water damage | | | |
| | Ceiling - Lay-in Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 6 | 10+ years | water damage | | | |
| | Doors - Transom Window | | 18 | SF | _ | | | | | |
| | Doors - Transom Window Doors - Wood Doors inclu hw | 2nd Floor 2nd Floor | 18 | SF EA | 7 6 | 10+ years | | | | |
| | | | | | - | 10+ years | | | | |
| | Floor - Wood | 2nd Floor | 620 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 9 | EΑ | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 5 | 0-1 year | Cover damaged | | | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 879 | SF | 6 | 10+ years | | | | |
| assroc | om #301 (Regular Classroom) | | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Lay-in | 3rd Floor | 670 | SF | 6 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 30 | SF | 6 | 10+ years | | | | |
| | Doors - Transom Window | 3rd Floor | 48 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | | | |
| | Floor - Wood | 3rd Floor | 660 | SF | 6 | 10+ years | | | | |
| | Floor - Wood | 3rd Floor | 40 | SF | 4 | 0-1 year | Finish worn out | | | |
| | Lighting - Lay-in | 3rd Floor | 8 | EA | 7 | 10+ years | | | | |
| | Marker Board | 3rd Floor | 40 | LF | 7 | 6-10 years | | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 860 | SF | 6 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 21 | SF | 5 | 0-1 year | Water damage | | | |
| assroc | om #302 (Regular Classroom) | | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Lay-in | 3rd Floor | 700 | SF | 6 | 10+ years | | | | |
| | Doors - Transom Window | 3rd Floor | 48 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | | | |
| | Floor - Wood Books including | 3rd Floor | 700 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 3rd Floor | 8 | EA | 7 | 10+ years | | | | |
| | Marker Board | 3rd Floor | 40 | LF | 7 | 6-10 years | | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 876 | SF | 6 | <u>-</u> | | | | |
| | vvalis - Flastei/Di yWall | 31U F1001 | 8/6 | SF | О | 10+ years | | | | |





| Category : Classroom | | | Building : Leased-Main | | | | | | |
|----------------------|---|-----------|------------------------|-----|------|-------------|------------------|--|--|
| | _ | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Walls - Plaster/Drywall | 3rd Floor | 5 | SF | 5 | 0-1 year | Cracking. | | |
| Classroo | m #303 (Regular Classroom) | | | | | | | | |
| Classico | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 670 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-III Ceiling - Plaster/Drywall | 3rd Floor | 30 | SF | 6 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 20 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 48 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 700 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 8 | EA | 7 | 10+ years | | | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 873 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 8 | SF | 5 | 0-1 year | Bent metal panel | | |
| | walle Flactor, 21, wall | 0.0 1.00. | · · | O. | Ü | o i youi | Dem metal paner | | |
| Classroo | m #304 (Regular Classroom) | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 670 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 30 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 48 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 700 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 8 | EA | 7 | 10+ years | | | |
| | Marker Board | 3rd Floor | 40 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 881 | SF | 6 | 10+ years | | | |
| Classroo | m #305 (Regular Classroom) | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 620 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EΑ | 6 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 620 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 8 | EA | 7 | 10+ years | | | |
| | Marker Board | 3rd Floor | 30 | LF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 3rd Floor | 24 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 797 | SF | 6 | 10+ years | | | |
| Classroo | m #306 (Regular Classroom) | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 620 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 620 | SF | 6 | 10+ years | | | |





| Catego | ry : Classroom | | Bı | Building : Leased-Main | | | | | | |
|----------|-----------------------------|-----------|----------|------------------------|------|-------------|----------|--|--|--|
| | | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Lighting - Lay-in | 3rd Floor | 4 | EΑ | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 3rd Floor | 24 | SF | 6 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 797 | SF | 6 | 10+ years | | | | |
| Classroc | om #Music Room (Music Room) | | | | | | | | | |
| | AC Units | Basement | 2 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Plaster/Drywall | Basement | 740 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | Basement | 40 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EΑ | 6 | 10+ years | | | | |
| | Floor - Tile | Basement | 740 | SF | 6 | 10+ years | | | | |
| | Lighting - Pendent/Surface | Basement | 6 | EΑ | 7 | 10+ years | | | | |
| | Walls - Metal Panel | Basement | 495 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | Basement | 495 | SF | 7 | 10+ years | | | | |

Category: Interior **Building: Leased-Main**

| 0 | Mana Tana | Lasatian | 0 | шом | DI- | Recommend | 0 |
|-----------|--------------------------------------|-----------|----------|-----|------|-------------|----------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Corridor | | | | | | | |
| | Ceiling - Splined | 1st Floor | 1,203 | | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 1,203 | | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 8 | | 7 | 10+ years | |
| | Stairs - Concrete Stairs | 1st Floor | 20 | | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,000 | SF | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 18 | _ | 5 | 0-1 year | Cracking blocks |
| | Walls - Plaster/Drywall | 1st Floor | 526 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 8 | SF | 5 | 0-1 year | Cracking. |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 50 | | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 12 | SF | 4 | 0-1 year | Missing tiles |
| | Ceiling - Lay-in | 2nd Floor | 200 | | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,003 | SF | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 2nd Floor | 1,203 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,593 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 21 | SF | 5 | 0-1 year | Cracking |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,188 | SF | 6 | 10+ years | • |
| | Ceiling - Plaster/Drywall | 3rd Floor | 15 | | 5 | 0-1 year | Water damage |
| | Drinking Fountains - Single Fountain | 3rd Floor | 1 | EA | 7 | 10+ years | Ç |
| | Floor - Concrete Epoxy/ Painted | 3rd Floor | 1,203 | | 7 | 10+ years | Quantity changed |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | | 7 | 10+ years | , |
| | Walls - Plaster/Drywall | 3rd Floor | 1,590 | | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 24 | | 4 | 0-1 year | Hole in wall and cracking. |
| | Ceiling - Plaster/Drywall | Basement | 1,169 | | 6 | 10+ years | 3 |
| | • | Basement | 2 | | 7 | | |
| | Drinking Fountains - Single Fountain | Basement | 2 | EA | 7 | 10+ years | |

Campus Name: North River Page : 15 of 19 Assessment Date: 02/28/2022



| Category : Interior | | | Building : Leased-Main | | | | | | |
|---------------------|---------------------------------|-----------------|------------------------|-----|------|-------------|-----------|--|--|
| _ | Recomm | | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| _ | Floor - Concrete Epoxy/ Painted | Basement | 1,169 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Basement | 8 | EΑ | 7 | 10+ years | | | |
| | Walls - Metal Panel | Basement | 830 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Basement | 820 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Basement | 10 | SF | 6 | 6-10 years | | | |
| Safety | | | | | | | | | |
| | Camera Viewing Station | Entire Building | 1 | EA | 7 | 6-10 years | | | |
| | Security Cameras | Entire Building | 3 | EA | 7 | 6-10 years | | | |
| Stairs | | | | | | | | | |
| | Ceiling - Plaster/Drywall | North | 210 | SF | 6 | 10+ years | | | |
| | Floor - Concrete Epoxy/ Painted | North | 210 | SF | 7 | 10+ years | | | |
| | Handrails | North | 48 | LF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | North | 2 | EΑ | 7 | 10+ years | | | |
| | Stairs - Terrazzo | North | 30 | LF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | North | 300 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | North | 26 | SF | 5 | 0-1 year | Cracking. | | |
| | Ceiling - Plaster/Drywall | South | 210 | SF | 6 | 10+ years | | | |
| | Floor - Concrete Epoxy/ Painted | South | 210 | SF | 5 | 10+ years | | | |
| | Handrails | South | 48 | LF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | South | 2 | EΑ | 6 | 10+ years | | | |
| | Stairs - Terrazzo | South | 30 | LF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | South | 326 | SF | 6 | 10+ years | | | |



| Category : Site | | | | | | | |
|-----------------|---|-------------------|----------|-----|------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Civil/Dra | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 2 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Drain | Entire Site | 1 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 1 | EA | 6 | 10+ years | |
| _Fencing | | | | | | | |
| | Fencing - Guard Rail | Entire Site | 62 | LF | 7 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 88 | LF | 6 | 10+ years | |
| Landsca | ne | | | | | | |
| Landood | Landscape - Hardscape- Concrete | East | 200 | SF | 4 | 0-1 year | Cracked and sunken concrete at |
| | · | | | | | · | entrance number two and entrance |
| | Parkway trees | East | 3 | EA | 6 | 10+ years | number three. |
| | Trash Receptacles | East | 3 | EA | 6 | 10+ years | |
| | Trasii Neceptacies | Last | 3 | LA | O | 10+ years | |
| _Parking_ | | | | | | | |
| | Pavers | Parking Lot- West | 4,048 | SF | 6 | 6-10 years | |
| | Pavers | Parking Lot- West | 3 | SF | 4 | 0-1 year | Missing pavers |
| | Surface - Asphalt | Parking Lot- West | 6,000 | SF | 6 | 10+ years | This area was not previously included in the assessment, but it is part of the parking lot. |
| | Surface - Asphalt | Parking Lot- West | 1,200 | SF | 4 | 0-1 year | This is part of the alley. This alley is badly damaged with extensive areas of potholes cracked and disintegrating asphalt. There is evidence of leaks to the basement from the holes in this alley asphalt. |
| | Surface - Asphalt | Parking Lot- West | 789 | SF | 4 | 0-1 year | Large cracks and potholes throughout. |
| _Sidewall | | | | | | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 1,583 | SF | 6 | 10+ years | |
| Signage | | | | | | | |
| -0-9 | Monument - Building Mounted Cut Letter Sign | East Facade | 1 | EA | 6 | 10+ years | |

Campus Name: North River Page: 17 of 19 Assessment Date: 02/28/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be







ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: North River Page: 18 of 19 Assessment Date: 02/28/2022





Classroom Summary

| - | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|------------------------|-------------------|---------------|--------|--------------------|------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Leased-Main | | | • | | | | | | |
| Music Room | Art Room | Basement | Music | 001 | 740 | 51 | 24 | N | N |
| | | | Room | | | | | | |
| Office | Music Room | 1st Floor | 101 | 101 | 840 | 96 | 48 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 700 | 72 | 40 | N | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 620 | 72 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 700 | 72 | 40 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 700 | 72 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 700 | 72 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 700 | 72 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 620 | 72 | 40 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 620 | 72 | 40 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 700 | 72 | 40 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 700 | 72 | 40 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 700 | 72 | 40 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 700 | 72 | 40 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 620 | 72 | 40 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 620 | 72 | 40 | N | N |
| Special Education | Regular Classroom | 1st Floor | 103 | 103 | 620 | 72 | 40 | N | Υ |
| Special Education | Regular Classroom | 1st Floor | 105 | 105 | 620 | 72 | 40 | N | N |