

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1907	3	77,140
Campus Total			77,140

Category : Exterior Building : Main

	TY LEXIONE			anamg		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	}					·	
	Exterior Doors - Exterior Steel Door	Entrance 1-North	2	EA	5	0-1 year	Corroded frames, door was repaired but corrosion persists.
	Exterior Doors - Transom Lite	Entrance 1-North	1	EΑ	6	10+ years	•
	Exterior Stairs - Concrete	Entrance 1-North	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 1A-North / Boiler Room	1	EΑ	5	0-1 year	Corroding door and frame
	Exterior Doors - Transom Lite	Entrance 1A-North / Boiler Room	1	EΑ	6	6-10 years	-
	Exterior Doors - Overhead Rolling/ Garage	Entrance 1B-North / Outside Yard	1	EA	4	0-1 year	Corroded door
	Door	Storage					
	Exterior Doors - Exterior Steel Door	Entrance 2-West	2	EA	5	0-1 year	Corroding doors and frames
	Exterior Stairs - Concrete	Entrance 2-West	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3-SW	2	EA	5	0-1 year	Corroded doors and frames
	Exterior Doors - Side lite	Entrance 3-SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 3-SW	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 3-SW	15	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 5-SE	2	EA	5	0-1 year	Corroded doors and frames
	Exterior Doors - Side lite	Entrance 5-SE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 5-SE	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 5-SE	15	LF	5	0-1 year	Cracking.
	Exterior Doors - Exterior Steel Door	Entrance 6-NE	2	EA	6	6-10 years	Door bottom was repaired
	Exterior Stairs - Concrete	Entrance 6-NE	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 7-Auditorium - E. Fire Escape	2	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	Exit 7-Auditorium - E. Fire Escape	6	LF	5	0-1 year	Large cracks in stone.
	Exterior Doors - Exterior Steel Door	Exit 8-Auditorium - W. Fire Escape	2	EA	6	6-10 years	-
	Exterior Stairs - Concrete	Exit 8-Auditorium - W. Fire Escape	6	LF	6	6-10 years	



Category : Exterior			В	uilding	: Main			
_				_		Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Entrance Control - Audio and Video	Main Entrance 4-S	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	Main Entrance 4-S	3	EΑ	4	0-1 year	Corroded doors and frames	
	Exterior Doors - Transom Lite	Main Entrance 4-S	3	EA	6	6-10 years		
ire Esc	ape							
	Fire Escape	Auditorium - E, W	26	LF	5	10+ years		
	Fire Escape	Auditorium - E, W	10	LF	4	0-1 year	Broken Stringer, corroded anchor	
	ta							
oundat		Fatina Dadidia a	000			40		
	Foundation - Masonry	Entire Building	820	LF	7	10+ years		
	Superstructure - Steel with Clay Tile Arch	Entire Building	77,140	SF	7	10+ years		
ghting								
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years		
oof Sys	stem							
,	Access Ladder - Metal	Roof 1	1	EA	7	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	70	LF	6	10+ years		
	Liner					•		
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	10	LF	5	10+ years		
	Liner							
	Coping - Clay Tile	Roof 1	242	LF	6	10+ years		
	Coping - Clay Tile	Roof 1	16	LF	5	10+ years		
	Coping - Terra Cotta	Roof 1	390	LF	6	10+ years		
	Coping - Terra Cotta	Roof 1	20	LF	4	0-1 year	Loose coping section, open joints	
	Downspouts - Exterior Downspouts	Roof 1	170	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Roof 1	5	LF	4	0-1 year	Bent, broken downspouts	
	Downspouts - Interior Downspouts	Roof 1	266	LF	6	10+ years	. ,	
	Parapet - 16" - 30" Height	Roof 1	595	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Roof 1	175	LF	6	10+ years		
	Parapet - Parapet > 30"	Roof 1	50	LF	5	10+ years		
	Roof - Asphalt Gravel Ballast	Roof 1	12,475	SF	7	6-10 years		
	Roof - Asphalt Gravel Ballast	Roof 1	335	SF	4	0-1 year	Soft spots	
	Roof - Modified Bitumen	Roof 1	100	SF	6	6-10 years	Out spots	
	Roof Hatch - Metal	Roof 1	100	EA	7	10+ years		
	Roof Structure - Steel with Clay Tile Arch	Roof 1	12,910	SF	7	10+ years		
	Coping - Clay Tile	Roof 2	12,910	LF	6	10+ years		
	Coping - Clay Tile Coping - Clay Tile	Roof 2	40	LF	5	10+ years 10+ years		
	Coping - Clay File Coping - Metal			LF	5 7	-		
		Roof 2	100	SF	7	10+ years		
	Roof - Asphalt Gravel Ballast	Roof 2	6,145			6-10 years	Domago to country fleshing	
	Roof - Asphalt Gravel Ballast	Roof 2	165	SF	5	0-1 year	Damage to counter flashing.	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	6,310	SF	7	10+ years		
	Coping - Clay Tile	Roof 3 - N. Lower Roof	88	LF	6	10+ years		



Catego	ry : Exterior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Roof 3 - N. Lower Roof	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3 - N. Lower Roof	6	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3 - N. Lower Roof	88	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 3 - N. Lower Roof	1,783	SF	5	0-1 year	Vegetation growth.
	Roof Structure - Steel with Clay Tile Arch	Roof 3 - N. Lower Roof	1,783	SF	7	10+ years	
	Coping - Clay Tile	Roof 4 - N. Lower Roofs	88	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4 - N. Lower Roofs	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4 - N. Lower Roofs	6	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4 - N. Lower Roofs	88	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 4 - N. Lower Roofs	1,783	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4 - N. Lower Roofs	1,783	SF	7	10+ years	
Walls							
	Cornice - Terra Cotta	Entire Building	735	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	28,650	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	4	0-1 year	Open Joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	945	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	200	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	400	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,320	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	100	SF	5	10+ years	
Windows	3						
	Clerestory - Glass Single-Pane	Entire Building	945	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,177	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	570	SF	6	6-10 years	
	Lintels - Brick	Entire Building	300	LF	6	10+ years	
	Lintels - Brick	Entire Building	20	LF	5	0-1 year	Corroded, displacing brick and terracotta above large window unit.
	Lintels - Steel	Entire Building	610	LF	6	10+ years	•
	Lintels - Stone	Entire Building	165	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	12	LF	4	0-1 year	Corroded, displacing brick and terracotta above large window unit.
	Windows - Louver	Entire Building	10	SF	6	10+ years	tens abore large window drint.
	Windows - Sash Aluminum Double-pane	Entire Building	8,475	SF	6	10+ years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	158	SF	6	6-10 years	
	Windows - Wood- Single-pane	Entire Building	54	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						



Catego	ry : Electrical		В	uilding	: Main		_
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Automatic Transfer Switch	Electrical Room	1	EA	4	1-2 years	Noisy and not reliable
	Security System - CCTV	Entire Building	77,140	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	77,140	SF	5	2-5 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,714	SF	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,049	SF	6	2-5 years	
	Emergency A/C Power - Gym	Entire Building	3,879	SF	6	2-5 years	New item added per current observation
	Emergency A/C Power - Lunchrooms	Entire Building	1,105	SF	6	2-5 years	
	Exit Signs - Auditoium	Entire Building	7	EA	2	0-1 year	Quantity change per current observation No EM generator or battery backup power
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No EM generator or battery backup power
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	No EM generator or battery backup power
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	No EM generator or battery backup power
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	7	10+ years	New item added per observation Installed in 2021
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	1	EA	4	1-2 years	Older fixture. New item added per current observation.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	4	1-2 years	Older fixtures
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	7	10+ years	Replace new in 2021.
_Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	Corroded.
	PA System	Entire Building	77,140	SF	6	6-10 years	Installed new system in 2021
_Power_D	vistribution						
	Lighting and Power Panels - 100 A	Electrical Room	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Electrical Room	2	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	6-10 years	New item added per current observation Fuse panel
	Lighting and Power Panels - Above 100 A	Electrical Room	10	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Electrical Room	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Electrical Room	5	EA	6	6-10 years	

Campus Name: Oglesby Page : 4 of 26 Assessment Date: 05/10/2022



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
			0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları							
	Fire Alarm Panel	1st Floor	1	EA	3	0-1 year	Not reliable and older. Need upgrade.
	Fire Alarm Strobe Lights	1st Floor	77,140	SF	3	0-1 year	No strobe lights
	Fire Alarm_System	1st Floor	77,140	SF	4	0-1 year	Not reliable and older.
Catego	ry : Mechanical		В	uilding	· Main		
Juli go.	y i moonamoa			anamg		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ling Systems						
All Hand	Air Handling Unit- Package Multi Zone-	Mechanical Room	1	EA	5	6-10 years	Serves Main AHU-1. Coils leaking.
	Indoor- Steam Coils - 20001-30000 cfm					•	· ·
	Air Intake	Mechanical Room	1	EA	7	10+ years	Installed new in 2021
	Zone Dampers	Mechanical Room	28	EA	7	10+ years	All new actuators and pneumatic system installed in 2021
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-2 Serves Auditorium. Coils leak.
	Air Intake	Mechanical Room	1	EA	7	6-10 years	Replace new in 2021
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	10+ years	New item added per current
	,		•		Ū	.o. you.o	observation Leaking coils.
	Zone Dampers	Mechanical Room	10	EA	7	10+ years	All new actuators and pneumatic system installed in 2021.
Boiler Sy	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EΑ	4	1-2 years	Manually fed.
	Combustion Dampers	Boiler Room	2	EA	4	1-2 years	Blades corroded and older.
	Condensate Pump	Boiler Room	2	EA	6	2-5 years	Diagos contodos ana cidor.
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	1-2 years	Older tank and pumps.
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	Control needs replacement
	Steam- Low Pressure Boiler - 101 - 150 HP		'			•	·
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	Control needs replacement

Campus Name: Oglesby Page : 5 of 26 Assessment Date: 05/10/2022



Catego	ry : Mechanical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	4	1-2 years	Older pipes
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	4	1-2 years	Older pipes
	Steam Traps	Boiler Room	18	EA	6	6-10 years	
_Heating	Devices						
J	Wall Heater - Electric	Entire Building	2	EA	7	10+ years	Quantity change per current observation New installed in 2021
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Not working - storage in basement Per building engineer New item added per current observation
	Fin Tube - Electric	Entire Building	45	LF	5	2-5 years	Paint required and need some repair.
	Unit Heater - Electric	Mechanical Room	2	EA	7	10+ years	Quantity change per current observation Installed new in 2021
	Unit Heater - Gas	Mechanical Room	1	EA	7	6-10 years	
_Tempera	ature Control						
·	Pneumatic System	Entire Building	77,140	SF	7	10+ years	Installed new system in 2021
	Thermostats - Pneumatic	Entire Building	12	EA	7	10+ years	Installed new system in 2021
	Thermostats - Pneumatic	Entire Building	34	EA	7	10+ years	Installed new system in 2021
_Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	Installed new in 2021
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	

Category: Plumbing Building: Main

	. y		_			_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,140	SF	6	6-10 years	

Campus Name: Oglesby Page : 6 of 26 Assessment Date: 05/10/2022



Catego	ry : Plumbing	Building : Main					
0	Ham. Toma	Lagation	O	HOM	Dank	Recommend	Commonts
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building	77,140 77,140 77,140	SF SF SF	6 6 6	6-10 years 6-10 years 6-10 years	
Pumps	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	4	1-2 years	Pump needs replacement
	Pumps - Sump-Duplex	Mechanical Room	1	EA	4	1-2 years	Need some repair. Other pump moved to condensate pump.

Category: Room **Building: Main**

2roup	Itam - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Froup	Item - Type	Location	Quantity	OOM	Kalik	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	001	1	EA	7	6-10 years	
	Ceiling - Exposed	001	600	SF	6	10+ years	
	Doors - Wood Doors inclu hw	001	1	EA	6	10+ years	
	Floor - Tile	001	600	SF	6	10+ years	
	Lighting - Pendent/Surface	001	10	EA	6	10+ years	
	Power Distribution	001	8	EA	6	10+ years	
	Walls - Plaster/Drywall	001	1,306	SF	6	10+ years	
	Ceiling - Exposed	001A Teacher Lounge	420	SF	6	10+ years	
	Doors - Wood Doors inclu hw	001A Teacher Lounge	1	EA	6	10+ years	
	Floor - Tile	001A Teacher Lounge	420	SF	6	10+ years	
	Lighting - Wall Mounted	001A Teacher Lounge	4	EA	6	6-10 years	
	Power Distribution	001A Teacher Lounge	10	EA	7	10+ years	
	Walls - Masonry	001A Teacher Lounge	504	SF	6	10+ years	
	Walls - Plaster/Drywall	001A Teacher Lounge	150	SF	6	10+ years	
	Ceiling - Plaster/Drywall	007A Office	326	SF	6	10+ years	
	Doors - Wood Doors inclu hw	007A Office	1	EA	6	10+ years	
	Floor - Tile	007A Office	326	SF	6	10+ years	
	Lighting - Pendent/Surface	007A Office	4	EA	7	6-10 years	
	Power Distribution	007A Office	8	EA	7	10+ years	
	Walls - Masonry	007A Office	565	SF	6	10+ years	
	Walls - Plaster/Drywall	007A Office	250	SF	6	10+ years	
	AC Unit	103 Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	103 Main Office	610	SF	6	10+ years	
	Ceiling - Plaster/Drywall	103 Main Office	30	SF	5	0-1 year	Crack in ceiling
	Doors - Transom Window	103 Main Office	8	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	103 Main Office	1	ĒΑ	6	10+ years	
	Floor - Tile	103 Main Office	640	SF	6	10+ years	
	Lighting - Pendent/Surface	103 Main Office	7	ĒΑ	7	6-10 years	
	Power Distribution	103 Main Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	103 Main Office	1,520	SF	6	10+ years	

Campus Name: Oglesby Page : 7 of 26 Assessment Date: 05/10/2022



Category : Room			В	uilding	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	103A Principal's Office	1	EA	4	0-1 year	Unit doesn't work
	Ceiling - Lay-in	103A Principal's Office	235	SF	6	10+ years	
	Doors - Steel Doors incl hw	103A Principal's Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	103A Principal's Office	2	EA	6	10+ years	
	Floor - Tile	103A Principal's Office	235	SF	6	10+ years	
	Lighting - Pendent/Surface	103A Principal's Office	4	EA	7	6-10 years	
	Power Distribution	103A Principal's Office	10	EA	7	10+ years	
	Storage/ Closet	103A Principal's Office	50	SF	5	10+ years	
	Walls - Plaster/Drywall	103A Principal's Office	490	SF	6	10+ years	
	AC Unit	103B Adj. Office	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	103B Adj. Office	380	SF	6	10+ years	
	Ceiling - Plaster/Drywall	103B Adj. Office	50	SF	5	0-1 year	Damaged ceiling
	Doors - Wood Doors inclu hw	103B Adj. Office	1	EA	6	10+ years	Barriagoa ooming
	Floor - Tile	103B Adj. Office	430	SF	6	10+ years	
	Lighting - Pendent/Surface	103B Adj. Office	6	EA	6	6-10 years	
	Power Distribution	103B Adj. Office	12	EA	7	10+ years	
	Storage/ Closet	103B Adj. Office	40	SF	5	10+ years 10+ years	
	Malla Diagter/Drawell			SF SF			
	Walls - Plaster/Drywall	103B Adj. Office	840		6	10+ years	
	AC Unit	2nd for Conference room. Next to room 203	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd for Conference room. Next to room 203	410	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd for Conference room. Next to room 203	37	SF	6	10+ years	
	Doors - Transom Window	2nd for Conference room. Next to room 203	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd for Conference room. Next to room 203	1	EA	6	10+ years	
	Floor - Carpet	2nd for Conference room. Next to room 203	285	SF	6	6-10 years	
	Floor - Carpet	2nd for Conference room. Next to room 203	10	SF	4	0-1 year	Damaged
	Floor - Wood	2nd for Conference room. Next to room 203	147	SF	6	10+ years	
	Floor - Wood	2nd for Conference room. Next to room 203	5	SF	4	0-1 year	Scratched and damaged
	Lighting - Lay-in	2nd for Conference room. Next to room 203	7	EA	7	6-10 years	
	Power Distribution	2nd for Conference room. Next to room 203	18	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd for Conference room. Next to room 203	1,332	SF	6	10+ years	
	Work SInk	2nd for Conference room. Next to room 203	1	EA	5	0-1 year	Stuck running



Catego	ry : Room		В	uilding	: Main		7040 0 Green Officer, Officeago, ie 00020
			_	9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Basement, Engineer's Office	8	SF	7	6-10 years	Repaired
	Ceiling - Lay-in	Basement, Engineer's Office	247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement, Engineer's Office	2	EA	6	10+ years	
	Floor - Tile	Basement, Engineer's Office	255	SF	6	10+ years	
	Lighting - Lay-in	Basement, Engineer's Office	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement, Engineer's Office	2	EA	7	6-10 years	
	Walls - Masonry	Basement, Engineer's Office	280	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement, Engineer's Office	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Security Office in main office	116	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Security Office in main office	3	EA	6	10+ years	
	Floor - Tile	Security Office in main office	116	SF	6	10+ years	
	Lighting - Pendent/Surface	Security Office in main office	2	ĒΑ	6	6-10 years	
	Power Distribution	Security Office in main office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Security Office in main office	430	SF	6	10+ years	
	Traile Tractor, 21, Trail	Coodiny Cines in main cines	100	O.	Ŭ	io. youro	
Auditoriu	um & Theater						
	Balcony Seating	1st Floor	40	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,699	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	-
	Floor - Carpet	1st Floor	2,754	SF	6	6-10 years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	10	EA	6	6-10 years	
	Main Floor Seating	1st Floor	200	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	835	SF	6	10+ years	
	Stage Curtain	1st Floor	2	EA	7	6-10 years	Updated to match current observations
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	Updated to match current observations
	Stage-Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,680	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Water damage and cracking
Gvmnas	ia						
_GyiiiiaS	Ceiling - Plaster/Drywall	3rd Floor	3,879	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Tile	3rd Floor	3,804	SF	6	10+ years	
	Floor - Tile	3rd Floor	75	SF	4	0-1 year	Broken and cracked tiles
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	6	EA	7	6-10 years	Distriction and ordered thes
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	13	EA	5	0-10 years	Does not work.
	Scoreboards	3rd Floor	13	EA	7	6-10 years	DOGS HOL WOLK.
	Ocorebodius	314 1 1001	1	LA	,	0-10 years	



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sound System	3rd Floor	1	EA	7	6-10 years	Updated to match current observations
	Walls - Plaster/Drywall	3rd Floor	5,135	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	15	SF	4	0-1 year	Extreme water damage
Kitchen							
	Ceiling - Plaster/Drywall	Basement	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	720	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EΑ	6	6-10 years	
	Serving Line	Basement	10	LF	6	10+ years	
	Storage/ Closet	Basement	57	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,000	SF	6	10+ years	
Library							
	AC Unit	Basement	1	EA	7	6-10 years	
	Casework	Basement	120	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,245	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	10+ years	
	Floor - Tile	Basement	1,241	SF	6	10+ years	
	Floor - Tile	Basement	, 4	SF	4	0-1 year	Cracking.
	Lighting - Pendent/Surface	Basement	21	ĒΑ	6	6-10 years	3
	Walls - Plaster/Drywall	Basement	1,640	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	Basement	1,105	SF	6	10+ years	
	Floor - Tile	Basement	1,105	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	16	ĒΑ	6	6-10 years	
	Market Board	Basement	10	LF	6	6-10 years	
	Serving Line	Basement	10	LF	6	10+ years	
	Walls - Masonry	Basement	2,762	SF	6	10+ years	
MDF_ID	F						
	Doors - Store Front	MDF/IDF room in room 200	2	EA	6	10+ years	
	Finishes	MDF/IDF room in room 200	250	SF	7	10+ years	Updated to match current observations
	Window AC Unit	MDF/IDF room in room 200	2	EA	7	6-10 years	SSSSI VALIDITO
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	15	SF	5	10+ years	Paint needed.
	Janitor's Closet	2nd Floor	15	SF	5	10+ years	Sink stuck dripping. Hole in ceiling, damage around sink.
	Janitor's Closet	3rd Floor	15	SF	7	10+ years	

Campus Name: Oglesby Page : 10 of 26 Assessment Date: 05/10/2022



Catego	ategory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake Plenums	Basement	826	SF	5	10+ years	
	Air Tunnel	Basement	3,610	SF	5	10+ years	
	Boiler Room	Basement	3,208	SF	5	10+ years	
	Coal Room	Basement	1,150	SF	5	10+ years	
	Janitor's Closet	Basement	629	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,156	SF	5	10+ years	
	Storage Room	Basement	927	SF	5	10+ years	
Restroor	n						
	Accessories	3rd floor Girls restroom	250	SF	7	6-10 years	Updated to match current observations
	Ceiling - Plaster/Drywall	3rd floor Girls restroom	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor Girls restroom	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor Girls restroom	250	SF	6	10+ years	
	Floor Drain	3rd floor Girls restroom	1	EΑ	7	10+ years	
	Hand Dryer	3rd floor Girls restroom	1	EΑ	7	6-10 years	
	Lavatory	3rd floor Girls restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor Girls restroom	4	EA	6	6-10 years	
	Partitions	3rd floor Girls restroom	1	EA	5	0-1 year	Screwed shut.
	Partitions	3rd floor Girls restroom	4	EA	5	10+ years	Ociewed Sildt.
	Walls - Tile Ceramic/ Porcelain	3rd floor Girls restroom	770	SF	6	10+ years	
	Water Closet	3rd floor Girls restroom	4	EA	6	-	
	Water Closet	3rd floor Girls restroom	1	EA	4	10+ years	Out of order.
	Accessories		250	SF	7	0-1 year	Out of order.
	Ceiling - Plaster/Drywall	3rd floor boys restroom		SF SF		6-10 years	
	•	3rd floor boys restroom	250		6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys restroom	250	SF	7	10+ years	
	Floor Drain	3rd floor boys restroom	1	EΑ	7	10+ years	
	Hand Dryer	3rd floor boys restroom	1	EA	7	6-10 years	
	Lavatory	3rd floor boys restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys restroom	4	EA	7	10+ years	
	Partitions	3rd floor boys restroom	2	EA	7	10+ years	Updated to match current observations
	Urinals	3rd floor boys restroom	3	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd floor boys restroom	770	SF	7	10+ years	
	Water Closet	3rd floor boys restroom	2	ĒΑ	6	10+ years	
	Accessories	Boy's Toilet in Basement	950	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Boy's Toilet in Basement	950	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boy's Toilet in Basement	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	950	SF	6	10+ years	
	Floor Drain	Boy's Toilet in Basement	3	EA	7	10+ years	
	Lavatory	Boy's Toilet in Basement	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boy's Toilet in Basement	9	EA	7	6-10 years	
	Partitions	Boy's Toilet in Basement	3	EA	, 5	,	
	raiuuUiis	Duy's Tullet III Dasement	3	ĽA	Э	10+ years	

Campus Name: Oglesby Page : 11 of 26 Assessment Date: 05/10/2022



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	Boy's Toilet in Basement	1	EΑ	4	0-1 year	Missing partition
	Urinals	Boy's Toilet in Basement	8	EΑ	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	2,349	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	26	SF	4	0-1 year	Cracking.
	Water Closet	Boy's Toilet in Basement	4	EA	6	10+ years	3
	Accessories	Girl's Toilet in Basement next to Lunchroom	768	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Girl's Toilet in Basement next to Lunchroom	768	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girl's Toilet in Basement next to Lunchroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girl's Toilet in Basement next to Lunchroom	768	SF	6	10+ years	
	Floor Drain	Girl's Toilet in Basement next to Lunchroom	2	EA	7	10+ years	
	Lavatory	Girl's Toilet in Basement next to Lunchroom	1	EA	6	10+ years	
	Lavatory	Girl's Toilet in Basement next to Lunchroom	1	EA	4	0-1 year	Damaged
	Lighting - Pendent/Surface	Girl's Toilet in Basement next to Lunchroom	9	EA	7	6-10 years	
	Partitions	Girl's Toilet in Basement next to Lunchroom	12	EA	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girl's Toilet in Basement next to Lunchroom	1,920	SF	6	10+ years	
	Water Closet	Girl's Toilet in Basement next to Lunchroom	12	EA	6	10+ years	
	Accessories	Men's staff restroom, 2nd Floor	59	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's staff restroom, 2nd Floor	59	SF	6	10+ years	Restroom was not accessible - locked. Components of this room are ranked based on similar rooms.
	Doors - Wood Doors inclu hw	Men's staff restroom, 2nd Floor	1	EA	6	6-10 years	Restroom was not accessible - locked. Components of this room are ranked based on similar rooms.
	Floor - Tile Ceramic/ Porcelain	Men's staff restroom, 2nd Floor	59	SF	6	6-10 years	Restroom was not accessible - locked. Components of this room are ranked based on similar rooms.
	Hand Dryer	Men's staff restroom, 2nd Floor	1	EA	5	2-5 years	Tanked based off sillillar 100HS.
	Lavatory	Men's staff restroom, 2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Men's staff restroom, 2nd Floor	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Men's staff restroom, 2nd Floor	95	SF	6	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	Men's staff restroom, 2nd Floor	204	SF	6	10+ years	
	Water Closet	Men's staff restroom, 2nd Floor	204	SF EA	6	6-10 years	
	Accessories	Restroom in 107	48	SF	5	6-10 years	
	Accessories	iveorionii ii ioi	40	SI	5	0-10 years	



Catego	ry : Room		Building : Main								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Ceiling - Plaster/Drywall	Restroom in 107	48	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Restroom in 107	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	Restroom in 107	48	SF	6	10+ years					
	Lavatory	Restroom in 107	1	EA	6	10+ years					
	Lighting - Pendent/Surface	Restroom in 107	1	EA	7	6-10 years					
	Partitions	Restroom in 107	1	EA	5	10+ years					
	Walls - Tile Ceramic/ Porcelain	Restroom in 107	255	SF	7	10+ years					
	Walls - Tile Ceramic/ Porcelain	Restroom in 107	25	SF	4	0-1 year	Tiles buckling around water closet.				
	Water Closet	Restroom in 107	1	EA	6	10+ years					
	Accessories	Restroom in Principals Office	40	SF	5	6-10 years					
	Ceiling - Plaster/Drywall	Restroom in Principals Office	40	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Restroom in Principals Office	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	Restroom in Principals Office	40	SF	6	10+ years					
	Lavatory	Restroom in Principals Office	1	EA	6	10+ years					
	Lighting - Pendent/Surface	Restroom in Principals Office	1	EA	7	6-10 years					
	Walls - Tile Ceramic/ Porcelain	Restroom in Principals Office	260	SF	7	10+ years					
	Water Closet	Restroom in Principals Office	1	EA	6	10+ years					
	Accessories	Restroom in boiler room	27	SF	5	6-10 years					
	Ceiling - Exposed	Restroom in boiler room	27	SF	6	10+ years					
	Doors - Wood Doors inclu hw Floor - Tile	Restroom in boiler room	1 27	EA SF	6	10+ years					
		Restroom in boiler room			5	10+ years					
	Lavatory	Restroom in boiler room	1	EΑ	6	10+ years					
	Lighting - Wall Mounted Walls - Plaster/Drywall	Restroom in boiler room	1 220	EA SF	7 6	6-10 years					
	Water Closet	Restroom in boiler room Restroom in boiler room	220	EA	6	10+ years					
	Accessories	Restroom in room 201	56	SF	7	10+ years	Updated to match current				
						10+ years	observations				
	Ceiling - Plaster/Drywall	Restroom in room 201	56	SF	5	0-1 year	Water damage				
	Doors - Transom Window	Restroom in room 201	15	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Restroom in room 201	1	EA	6	10+ years					
	Floor - Tile	Restroom in room 201	56	SF	6	6-10 years	Updated to match current observations				
	Lavatory	Restroom in room 201	1	EA	6	10+ years					
	Lighting - Pendent/Surface	Restroom in room 201	1	EA	6	6-10 years					
	Partitions	Restroom in room 201	1	EA	7	10+ years	Updated to match current observations				
	Walls - Plaster/Drywall	Restroom in room 201	209	SF	6	10+ years					
	Walls - Tile Ceramic/ Porcelain	Restroom in room 201	140	SF	6	10+ years					
	Water Closet	Restroom in room 201	1	EA	6	10+ years					
	Accessories	Restroom inside 101 classroom	48	SF	5	6-10 years					
	Ceiling - Plaster/Drywall	Restroom inside 101 classroom	48	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Restroom inside 101 classroom	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	Restroom inside 101 classroom	48	SF	6	10+ years					
	Lavatory	Restroom inside 101 classroom	1	EA	6	10+ years					
						-					

Campus Name: Oglesby Page : 13 of 26 Assessment Date: 05/10/2022



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Restroom inside 101 classroom	1	EA	7	6-10 years			
	Partitions	Restroom inside 101 classroom	1	EA	5	10+ years			
	Walls - Tile Ceramic/ Porcelain	Restroom inside 101 classroom	280	SF	7	10+ years			
	Water Closet	Restroom inside 101 classroom	1	EA	6	10+ years			
	Accessories	Women's staff restroom, 2nd Floor	59	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Women's staff restroom, 2nd Floor	56	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Women's staff restroom, 2nd Floor	3	SF	5	0-1 year	Water damage.		
	Doors - Wood Doors inclu hw	Women's staff restroom, 2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Women's staff restroom, 2nd Floor	59	SF	6	10+ years			
	Hand Dryer	Women's staff restroom, 2nd Floor	1	EA	7	6-10 years			
	Lavatory	Women's staff restroom, 2nd Floor	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Women's staff restroom, 2nd Floor	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Women's staff restroom, 2nd Floor	87	SF	6	10+ years			
	Walls - Plaster/Drywall	Women's staff restroom, 2nd Floor	8	SF	5	0-1 year	Plaster damage		
	Walls - Tile Ceramic/ Porcelain	Women's staff restroom, 2nd Floor	204	SF	6	10+ years	-		
	Water Closet	Women's staff restroom, 2nd Floor	1	EA	6	10+ years			
•				: 1 - 1 :	B. G *				

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #003 (Regular Classroom)						
	AC Units	Basement	1	EA	5	6-10 years	
	Casework	Basement	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	870	SF	6	10+ years	
	Chalk Board	Basement	70	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	862	SF	6	10+ years	
	Floor - Tile	Basement	8	SF	4	0-1 year	Crack tile/hole in floor.
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Marker Board	Basement	10	LF	6	6-10 years	
	Storage/ Closet	Basement	193	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,130	SF	6	10+ years	
_Classroo	m #005 (Store Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	590	SF	6	10+ years	
	Chalk Board	Basement	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	580	SF	6	10+ years	
	Floor - Tile	Basement	10	SF	4	0-1 year	Damaged tile
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	-
	Marker Board	Basement	10	LF	6	6-10 years	
	Walls - Masonry	Basement	600	SF	7	10+ years	

Campus Name: Oglesby Page : 14 of 26 Assessment Date: 05/10/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement	600	SF	6	10+ years	
_Classroc	m #005A (Regular Classroom)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	590	SF	6	10+ years	
	Chalk Board	Basement	70	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	9	SF	7	10+ years	Repaired.
	Floor - Tile	Basement	581	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Walls - Masonry	Basement	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	760	SF	6	10+ years	
_Classroo	m #007 (Art Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	903	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	Basement	903	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	6	6-10 years	
	Storage/ Closet	Basement	217	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	2,257	SF	6	10+ years	
Classroo	m #100 (Kindergarten)						
Oldosioc	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years	
	Chalk Board	1st Floor	70	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,105	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Broken tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	z. e. c.
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,645	SF	6	10+ years	
_Classroo	m #101 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3	SF	7	10+ years	Repaired
	Ceiling - Plaster/Drywall	1st Floor	1,112	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,110	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	0-1 year	Cracked tile
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,620	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroc	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,075	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	5	0-1 year	Water damage
	Chalk Board	1st Floor	70	LF	4	2-5 years	water damage
	Doors - Transom Window	1st Floor	8	SF	6		
			0			10+ years	
	Doors - Wood Doors inclu hw	1st Floor	·	EA	6	10+ years	
	Floor - Tile	1st Floor	1,095	SF	7	10+ years	0 1 147
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Cracked tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	2-5 years	
	Walls - Plaster/Drywall	1st Floor	1,660	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	5	0-1 year	Water damage
Classroc	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years	
	Chalk Board	1st Floor	70	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,115	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,720	SF	6	10+ years	
21	#405 (Office)						
Jassroc	om #105 (Office)	4 . 🖂				0.40	
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years	
	Chalk Board	1st Floor	70	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,115	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,670	SF	6	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	30	SF	5	0-1 year	Crack ceiling
	Chalk Board	1st Floor	70	LF	4	2-5 years	g
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,040	SF	6	10+ years	
	Floor - Tile	1st Floor	75	SF	4	0-1 year	Cracked tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Cracked the
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,695	SF	6	10+ years	
Classro	om #107 (Kindergarten)						
Classio	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	•	
	Doors - Transom Window			SF		10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor 1st Floor	8	Sr EA	6 6	10+ years 10+ years	
	Floor - Tile	1st Floor	· · · · · · · · · · · · · · · · · · ·	SF	7		
			1,115			10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA SF	6	6-10 years	
	Storage/ Closet	1st Floor	167	SF SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,620	SF	6	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	876	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Floor - Tile	2nd Floor	30	SF	4	0-1 year	Cracking and broken tiles
		2nd Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface				•		
	Lighting - Pendent/Surface Storage/ Closet	2nd Floor 2nd Floor	96 2,160	SF SF	7	10+ years	Updated quantity



Catego	Category : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,231	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,181	SF	7	10+ years	
	Floor - Tile	2nd Floor	50	SF	4	0-1 year	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	· ·
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	219	SF	5	10+ years	Damage to paint and coat racks/chair molding.
	Walls - Plaster/Drywall	2nd Floor	2,100	SF	6	10+ years	· ·
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,082	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,086	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	215	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	2nd Floor	2,517	SF	6	10+ years	
_Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,153	SF	6	10+ years	Updated to match current observations
	Chalk Board	2nd Floor	54	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	21	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,153	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	2nd Floor	2,562	SF	6	10+ years	Updated quantity



Category : Classroom			В	uilding	: Main		
Group	Itom Type	Location	Quantity	UOM	Rank	Recommend	Comments
	Item - Type	Location	Quantity	UOW	Kank	Replacement	Comments
lassroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,086	SF	6	10+ years	Updated to match current observations
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,086	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,570	SF	6	10+ years	
assroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracking
	Doors - Transom Window	2nd Floor	7	SF	6	10+ years	- Constanting
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	1,150	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	Plaster damage from coat hook
	Walls - Plaster/Drywall	2nd Floor	2,487	SF	6	10+ years	r laster damage from coat floor
	Walls - Plaster/Drywall	2nd Floor	12	SF	5	1-2 years	Chipping plaster
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	·	211ú F1001	3	SI	5	1-2 years	water damage
lassroo	m #206 (Regular Classroom) AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,215	SF	6	•	
	Ceiling - Plaster/Drywall	2nd Floor	1,215 5	SF	5	10+ years 0-1 year	Cracking
	Doors - Transom Window	2nd Floor	7	SF	6	•	Cracking
						10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	EA SF	6	10+ years	
	Floor - Tile	2nd Floor	1,100		6	6-10 years	One alsie a tile a
	Floor - Tile	2nd Floor	120	SF	4	0-1 year	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	-
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	Broken tiles
	Walls - Plaster/Drywall	2nd Floor	2,412	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracking
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	0-1 year	Holes through plaster



Category : Classroom			В	uilding	: Main		
_					ъ.	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #207 (Regular Classroom)						
21033100	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
	Doors - Transom Window		1,220	SF	6	,	
		2nd Floor			_	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,204	SF	6	10+ years	
	Floor - Tile	2nd Floor	16	SF	4	0-1 year	Broken tile.
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	7	10+ years	Updated to match current
	ŭ					•	observations
	Walls - Plaster/Drywall	2nd Floor	2,423	SF	6	10+ years	
`laceroo	m #300 (Regular Classroom)						
ilassiluu	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,245	SF	6	10+ years	
	Chalk Board	3rd Floor		LF	4		
			48			2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,245	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	6-10 years	Missing plaster
	Walls - Plaster/Drywall	3rd Floor	2,540	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3	SF	5	0-1 year	Cracking plaster
lassroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,231	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	1,231	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
				SF	, 5	,	Diagtor damage
	Storage/ Closet	3rd Floor	217			10+ years	Plaster damage
	Walls - Plaster/Drywall	3rd Floor	2,442	SF	6	10+ years	
lassroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,086	SF	6	10+ years	



Category : Classroom		В	uilding	: Main			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,086	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	7	10+ years	Updated to match current
				-	-	, , , , , , , , , , , , , , , , , , , ,	observations
	Walls - Plaster/Drywall	3rd Floor	2,517	SF	6	10+ years	obodivations
lassroc	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,153	SF	6	10+ years	Updated to match current
	Gelling - Flaster/Drywali	314 1 1001	1,100	Oi	U	10+ years	observations
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Cracking along wall
						•	Cracking along wall
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,163	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	7	10+ years	Updated to match current observations
	Walls - Plaster/Drywall	3rd Floor	2,562	SF	6	10+ years	
lassroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Cracking along wall
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	Cracking along wan
	Floor - Tile	3rd Floor	1,100	SF	6	10+ years	Updated to match current
	Floor - Tile	314 F1001	1,100	Si	U	10+ years	•
	Floor - Tile	3rd Floor	50	SF	F	0.1.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	observations
			50		5	0-1 year	Cracking and broken tiles
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	10+ years	Water damage
	Walls - Plaster/Drywall	3rd Floor	1,430	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Plaster damage
assroc	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1,100	EA	6	10+ years	
	Floor - Wood Bools inclu hw	3rd Floor	1,150	SF	7	10+ years	
	1 1001 - VV00U	310 1 1001	1,150	OI.	1	TOT years	

Campus Name: Oglesby Page : 21 of 26 Assessment Date: 05/10/2022



Category : Classroom							
				uilding		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,509	SF	6	10+ years	
Classroc	om #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,220	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	4	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	Damage to door around latch.
	Floor - Wood	3rd Floor	1,220	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EΑ	5	0-1 year	Does not work.
	Marker Board	3rd Floor	36	LF	7	6-10 years	Dece net work.
	Storage/ Closet	3rd Floor	4	SF	5	10+ years	Water damage in corners
	Walls - Plaster/Drywall	3rd Floor	2,625	SF	6	10+ years	Water damage in comers
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Water damage.
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Cracking
Classroc	om #307 (Regular Classroom)						
21400101	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,217	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	Water damage
	Floor - Wood Books meld hw	3rd Floor	1,220	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	6-10 years	Corner plaster cracking
	Walls - Plaster/Drywall		2,416	SF	_	•	Corner plaster cracking
		3rd Floor			6 5	10+ years	Water demand
	Walls - Plaster/Drywall	3rd Floor	7	SF	5	0-1 year	Water damage
Catego	ry : Interior		В	uilding	: Main	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		Location	Quantity	COIVI	Italik	Replacement	Comments
JULIUUL	Ceiling - Lay-in	1st Floor	2,613	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2,613	SF	4	0-1 year	Water damage.
	Drinking Fountains - Double Fountain	1st Floor	14	EA	7		vvater uarriage.
	Floor - Tile/Sheet		2 627	SF	7 7	10+ years	
		1st Floor	2,627			10+ years	
	Lighting - Lay-in	1st Floor	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,290	SF	6	10+ years	



Catego	Category : Interior			uilding	: Main	Ţ	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	2,437	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,437	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,050	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,433	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year	Water damage
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,437	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	33	EA	7	6-10 years	
	Student Lockers - Three Tiers	3rd Floor	72	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,050	SF	6	10+ years	
	Ceiling - Exposed	Basement	2,682	SF	5	10+ years	Paint cracking and peeling.
	Drinking Fountains - Single Fountain	Basement	2	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	2,682	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement	40	EA	6	6-10 years	
	Student Lockers - One Tier	Basement	14	EA	6	10+ years	
	Walls - Masonry	Basement	6,705	SF	6	10+ years	
Safety	0 15 1 20 15					0.10	0
	Camera Viewing Station	1st Floor	4	EA	7	6-10 years	Out of date, not available right now.
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	10	EA	7	6-10 years	
Stairs							
Otalis	Ceiling - Plaster/Drywall	East	2,290	SF	7	10+ years	
	Floor - Tile	East	1,052	SF	7	10+ years	
	Floor - Tile	East	4	SF	4	0-1 year	Damaged tile
	Handrails	East	380	ĹF	7	10+ years	3
	Lighting - Pendent/Surface	East	12	EA	7	10+ years	
	Lighting - Wall Mounted	East	4	EA	7	10+ years	
	Stairs - Asphalt	East	190	LF	7	10+ years	
	Walls - Plaster/Drywall	East	8,056	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Entire building	2,290	SF	6	10+ years	
	Floor - Tile	Entire building	1,056	SF	6	10+ years	
	Handrails	Entire building	380	LF	5	10+ years	
	Lighting - Pendent/Surface	Entire building	12	EA	7	6-10 years	
	Lighting - Wall Mounted	Entire building	4	EA	7	6-10 years	
	Stairs - Asphalt	Entire building	190	LF	6	10+ years	
	Walls - Plaster/Drywall	Entire building	8,056	SF	6	10+ years	
		-					



Category : Site	Building : Site

Category : Site		Building : Site							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Civil/Dra	inage								
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	13	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	10+ years			
Fencing									
·	Fencing - New Standard Ornamental	Entire Site	1,477	LF	6	10+ years			
	Fencing - New Standard Ornamental	Entire Site	8	LF	4	0-1 year	Bent fencing		
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	20	LF	7	10+ years	New fencing		
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	135	LF	7	6-10 years	New fencing		
Londooo									
Landsca	Pe Benches	Entire Site	2	EA	6	6-10 years			
	Landscape - Grass	Entire Site	20,420	SF	6	10+ years			
	Landscape - Grass	Entire Site	2,000	SF	5	0-1 year	Bare soil		
	Lighting - Pole Mounted	Entire Site	2,000	EA	6	6-10 years	Bare son		
	Parkway trees	Entire Site	34	EA	6	10+ years			
	Parkway trees	Entire Site	1	EA	5	0-1 year	Landscape tree, not parkway-Tree		
	raikway iiees	Entire Site	ı	LA	3	0-1 year	trunk broken and leaning on fence.		
	Planting Beds/ Area	Entire Site	3,825	SF	6	10+ years	•		
	Planting Beds/ Area	Entire Site	100	SF	4	0-1 year	Broken planters		
	Play Area - Hardscape- Concrete	Entire Site	6,760	SF	4	0-1 year	Large cracks, open joints, vegetation		
	·					•	growth.		
	Play Area - Synthetic Turf	Entire Site	9,850	SF	7	10+ years			
	Trash Receptacles	Entire Site	3	EA	6	6-10 years			
Parking	Lot								
- anang	Concrete Curbs	NE	680	LF	6	10+ years			
	Interior Plantings	NE	1,399	LF	6	10+ years			
	Interior Plantings	NE	1	LF	4	0-1 year	Missing tree		
	Surface - Asphalt	NE	24,000	SF	6	6-10 years	3		
	Surface - Asphalt	NE	500	SF	4	0-1 year	Potholes, alligatored surface.		
	Trash Enclosure - Masonry	NE	1,185	SF	5	0-1 year	Deteriorated mortar, displaced		
	,		.,	-		,	masonry, open joints. Coping is		
							loose.		
	Vehicular Screening	NE	80	LF	6	10+ years			
Playgrou	ind								
. iayyiwi	Equipment - School Age 5-12	SE	1	EA	5	0-1 year	Missing components, worn out		
						-	surfaces, some corrosion.		
	Surface - Poured Surface	SE	2,624	SF	4	0-1 year	Damaged surface throughout		



Catego	ry : Site		, 3,				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	500	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	50	LF	4	0-1 year	Broken/cracking.
	Sidewalks - Perimeter Sidewalks	Entire Site	15,524	SF	6	10+ years	-
	Sidewalks - Perimeter Sidewalks	Entire Site	1,200	SF	4	0-1 year	Broken, upheaved
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Oglesby Page: 25 of 26 Assessment Date: 05/10/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

,			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	Basement	007	007	903	144	60	Υ	N
Kindergarten	Kindergarten	1st Floor	107	107	1,115	200	100	N	N
Kindergarten	Regular Classroom	1st Floor	100	100	1,115	175	88	N	Υ
Office	Regular Classroom	1st Floor	105	105	1,115	150	75	N	Υ
Pre School	Kindergarten	1st Floor	101	101	1,115	200	88	N	N
Regular Classroom	Office	2nd Floor	207	207	1,220	130	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	1,115	100	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	1,115	100	75	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	1,115	125	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	876	120	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,231	205	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,086	135	40	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	1,153	175	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	1,086	66	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,150	175	70	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,220	135	30	N	Y
Regular Classroom	Regular Classroom	3rd Floor	300	300	1,245	175	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	1,231	205	75	N	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	1,086	135	30	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	1,163	175	70	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,150	135	30	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	1,150	175	70	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	1,220	135	30	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	1,220	225	75	N	Υ
Regular Classroom	Regular Classroom	Basement	003	003	870	80	40	N	Υ
Regular Classroom	Regular Classroom	Basement	005A	005A	590	40	30	N	N
Store Room	Regular Classroom	Basement	005	005	590	60	30	N	N