



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1927	2	78,700
Annex	1971	2	18,000
Campus Total			96,700

Catego	ry : Exterior		В	uilding			
			0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Entire Building	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	12	EA	7	10+ years	
Entrance	}						
	Entrance Control - Audio and Video	#1- SE- Main Accessible	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#1- SE- Main Accessible	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1- SE- Main Accessible	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1- SE- Main Accessible	90	LF	6	10+ years	
	Power Door Operator and Controls	#1- SE- Main Accessible	2	EA	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1- SE- Main Accessible	50	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2- SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2- SE	1	EA	6	10+ years	
	Exterior Stairs - Stone	#2- SE	50	LF	4	0-1 year	Displaced stairs
	Exterior Doors - Exterior FRP Door	#3- SW	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#3- SW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#3- SW	6	LF	6	10+ years	
	Entrance Control - Audio and Video	#4- SW	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#4- SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4- SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4- SW	14	LF	7	10+ years	
	Exterior Stairs - Concrete	#4- SW	4	LF	5	1-2 years	Spalled and cracked concrete
	Power Door Operator and Controls	#4- SW	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#4- SW	45	LF	6	10+ years	

Campus Name: Otoole Page : 1 of 39 Assessment Date: 05/19/2022



Catego	ry : Exterior		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	#4- SW	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4- SW	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5- NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5- NW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5- NW	16	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5.1	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#6- NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6- NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6- NE	60	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6- NE	36	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7- NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7- NE	1	EA	6	10+ years	
	Exterior Stairs - Stone	#7- NE	100	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#7.5- E	1	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	#7.5- E	1	ΕA	6	10+ years	
	Ramps - Concrete	#7.5- E	35	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#8- SW- Boiler House	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#8- SW- Boiler House	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#9- E- Boiler House	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#9- E- Boiler House	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9.1- E- Chiller	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9.2- NE- Chiller	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9.3- NE- Chiller	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9.4- NW- Chiller	1	EA	6	10+ years	
	Extend Book Extend Gloci Book	70.1 1444 Chillon	'		Ü	101 youro	
_Foundati	on						
	Foundation - Concrete	Entire Building	1,161	LF	7	10+ years	
	Foundation - Concrete	Entire Building	13	LF	6	10+ years	Seapage
	Superstructure - Concrete	Entire Building	78,700	SF	7	10+ years	. 0
	·	G				·	
_Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	7	10+ years	New LED
	Exterior Lighting - Wall Mounted	Entire Building	19	EA	6	6-10 years	
_Roof Svs	otom						
_13001 3YS	Access Ladder - Metal	Boiler House Roof	4	Ε^	E	0.1.400*	Over 20' with no fall protection
			1	EA	5	0-1 year	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler House Roof	74	LF	4	2-5 years	Appears to be capped and not used
	Chimney - Metal Flue	Boiler House Roof	102	LF	7	10+ years	
	Coping - Terra Cotta	Boiler House Roof	208	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Boiler House Roof	30	LF	7	10+ years	
	Downspouts - Interior Downspouts	Boiler House Roof	18	LF	6	10+ years	
	Parapet - 16" - 30" Height	Boiler House Roof	190	LF	6	10+ years	

Campus Name: Otoole Page : 2 of 39 Assessment Date: 05/19/2022



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet > 30"	Boiler House Roof	18	LF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Boiler House Roof	110	SF	7	10+ years	
	Roof - Modified Bitumen	Boiler House Roof	2,702	SF	6	10+ years	
	Roof Hatch - Metal	Boiler House Roof	1	EA	7	10+ years	
	Roof Structure - Concrete	Boiler House Roof	2,702	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Boiler House Roof	110	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Terra Cotta	Low E Roof	30	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low E Roof	15	LF	6	10+ years	Corrected quantities
	Parapet - 16" - 30" Height	Low E Roof	30	LF	6	10+ years	•
	Roof - Modified Bitumen	Low E Roof	84	SF	6	10+ years	
	Roof Structure - Concrete	Low E Roof	84	SF	7	10+ years	
	Access Ladder - Metal	Main Upper Roof	3	ĒΑ	7	10+ years	
	Access Ladder - Metal	Main Upper Roof	1	ΕA	4	0-1 year	Not secured at bottom
	Access Ladder - Metal	Main Upper Roof	3	EA	3	1-2 years	Hatches have been removed
	Access Ladder - Wood	Main Upper Roof	3	EA	3	1-2 years	Hatches have been removed
	Coping - Terra Cotta	Main Upper Roof	1,122	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Upper Roof	20	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Upper Roof	288	LF	6	10+ years	Combined quantities
	Parapet - 16" - 30" Height	Main Upper Roof	30	LF	7	10+ years	Combined quantities
	Parapet - Parapet > 30"	Main Upper Roof	1,092	LF	7	10+ years	
	Roof - Asphalt Shingle	Main Upper Roof	4,275	SF	6	6-10 years	
	Roof - Modified Bitumen	Main Upper Roof	24,557	SF	7	10+ years	Bubbling, cracks, alligatoring, patches
	1001 - Modified Bitaliferi	Main Opper 1000	24,001	Oi	'	10+ years	throughout
	Roof Hatch - Metal	Main Upper Roof	2	EA	7	10+ years	tinoughout
	Roof Structure - Concrete	Main Upper Roof	24,557	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Upper Roof	4,275	SF	7	10+ years	
	Noor Structure - Steel with Glay The Arch	ман оррег Коог	4,273	OI .	,	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	135	SF	6	10+ years	Changed quantities
	Cheek-Wall - Stone	Entire Building	15	SF	5	2-5 years	Door 2
	Cornice - Cast Stone	Entire Building	1,122	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	3,744	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	40,192	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	4	0-1 year	Open joints, cracks, water damage
	Exterior Walls - Stone-Cast	Entire Building	3,362	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4	SF	4	1-2 years	
	Exterior Walls - Terra Cotta	Entire Building	1,200	SF	7	10+ years	No issues observed
Windows		Fusing Building	4.440	05		40	
	Guard - Guards perforated	Entire Building	4,116	SF	7	10+ years	
	Lintels - Steel	Entire Building	722	LF	6	10+ years	
	Lintels - Terra Cotta Windows - Casement Aluminum Double-	Entire Building Entire Building	49 1,600	LF SF	6 6	10+ years	
						10+ years	

Campus Name: Otoole Page : 3 of 39 Assessment Date: 05/19/2022



pane Windows - Louver Windows - Sash Aluminum Double-pane Category : Electrical Building : Main France Commend Group Item - Type Location Quantity UOM Rank Replacement Center Commend Center	Comments Comments Serve AC generator and emergency systems, serves main building
Windows - Louver Windows - Sash Aluminum Double-pane Entire Building 20 SF 7 10+ years 6,594 SF 6 10+ years Category : Electrical Building : Main Group Item - Type Location Quantity UOM Rank Replacement C Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S System Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Windows - Sash Aluminum Double-pane Entire Building 6,594 SF 6 10+ years Category : Electrical Building : Main Group Item - Type Location Quantity UOM Rank Replacement C Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Category : Electrical Group Item - Type Location Quantity UOM Rank Replacement C Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Group Item - Type Location Quantity UOM Rank Replacement C Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Group Item - Type Location Quantity UOM Rank Replacement C Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Emergency System Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S sy Security System - CCTV Entire Building 78,700 SF 5 6-10 years	Serve AC generator and emergency
Automatic Transfer Switch Boiler Room 3 EA 6 10+ years S sy Security System - CCTV Entire Building 78,700 SF 5 6-10 years	
Security System - CCTV Entire Building 78,700 SF 5 6-10 years	
Security System - Intrusion Detection Entire Building 78,700 SF 5 6-10 years	
	unctional
Exit Signs - Corridors and Stairs Entire Building 16 EA 5 6-10 years B ex gl	Building has AC generator, light from exit light causes iPad camera to show plare. Fixture is functional
iF	Functional, good. Glare is seen by Pad when taking a photo of a light axture
Exit Signs - Lunchroom Entire Building 3 EA 5 6-10 years FI	unctional
Emergency Battery Packs - Corridors and Entire Building 2 EA 6 6-10 years Stairs	
Emergency A/C Power - Auditoium and Entire Building 2,495 SF 6 10+ years Aisle Lighting	
	Building has a EM panel
Emergency A/C Power - Gym Entire Building 2,764 SF 6 10+ years	
Emergency A/C Power - Lunchrooms Entire Building 1,434 SF 6 10+ years	
Emergency Generator- Outdoor- Diesel - 60 North Courtyard 1 EA 5 6-10 years S	Serves main building only, tested nonthly
Main Service	
Main Electrical Service - 2000 A Electrical Room 1 EA 6 10+ years S 120/208/3PH	Serves main building only
	Connected to main and addition ouilding
Power Distribution	
Lighting and Power Panels - 100 A Entire Building 1 EA 7 10+ years	
Lighting and Power Panels - 100 A Entire Building 1 EA 7 10+ years	
Lighting and Power Panels - 100 A Entire Building 1 EA 7 10+ years	
Lighting and Power Panels - 100 A Entire Building 1 EA 7 10+ years	
	Older panel, occasionally trips

Assessment Date: 05/19/2022 Campus Name: Otoole Page : 4 of 39



Catego	ry : Electrical		В	uilding	: Main		3330 C Seciely AVENUE, Officage, IE 00030
Culogo			_	uag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	4	2-5 years	Deteriorated, occasionally trips
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Live, exposed conracts
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	•
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	ŭ				,	
Catogo	ry : Fire Protection		B	uilding	· Main		
Catego	Ty: The Frotection			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		Location	Quantity	OOM	Raine	Replacement	Commonic
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
	Fire Alarm Strobe Lights	Entire Building	78,700	SF	6	6-10 years	S
	Fire Alarm_System	Entire Building	78,700	SF	6	6-10 years	Connected to annex
Catogo	ry : Mechanical		B	uilding	· Main		
Calego	i y . Mechanicai			ununig	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc	•						
	Condensing Unit- Roof Mounted - Less than 5 tons	Mezzanine	1	EA	6	6-10 years	Mini split system, condensing unit, serves boiler building, engineer's office, difficult to access in a mezzanine area
	Chemical Pot Feeder	Site North	1	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Roof	Site North	1	EA	5	10+ years	Serves main building
	Mounted - 101 - 200 tons Glycol Feed	Site North	1	EA	6	10+ years	Manually fed
	Pipes - Dual Temperature Pipe- Steel	Site North	100	LF	6	10+ years	
	Pressure Fill System	Site North	1	EA	6	10+ years	
	,		-		-	, , , , , , , , , , , , , , , , , , , ,	
_Air Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	10+ years	AHU 2, in tunnel plenum, serves north end of main building
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	10+ years	
						,	

Campus Name: Otoole Page : 5 of 39 Assessment Date: 05/19/2022



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Basement	11	EA	5	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	Pa
	Zone Dampers	Basement	28	EA	5	10+ years	Recent conversion, from pneumatic actuators to a DDC actuators
	Air Handling Unit- Built Up- Single Zone- Dual Temperature Coils - 8001 - 15000 cfm	Basement	1	EA	6	10+ years	Serves gym, recently serviced
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - 15001 - 25000 cfm	Basement	1	EA	6	10+ years	AHU 3, serves south end of the main buildings
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Basement	6	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	
	Zone Dampers	Basement	18	EA	5	10+ years	Recent conversion from pneumatic actuators to DDC actuators
	Air Handling Unit- Built Up- Single Zone- Dual Temperature Coils - 8001 - 15000 cfm	Basement	1	EA	6	10+ years	Serves auditorium area, recently serviced
	Air Intake	Basement	1	EA	6	10+ years	
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement	100	LF	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Basement	2	EA	6	10+ years	Located in crawlspace, difficult to access
	Fan Coil Unit- Celing Mounted - Electric	Boiler Room	1	EA	5	6-10 years	Serves boiler building engineer's office, mini split HVAC system, in locked office room, photo through a window, served by condensing unit in nearby mezzanine area
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Roof	2	EA	6	10+ years	Serves AHU 2, AHU 3, north and south air tunnel, 2010 installation
_Boiler Sy	estems						
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 2001 - 3000	Boiler Room	2	EA	6	10+ years	B1, B2, serves main building

Campus Name: Otoole Page : 6 of 39 Assessment Date: 05/19/2022



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	MBH						
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Manually fed
	Water Fill System	Boiler Room	1	EA	6	10+ years	Pressure fill system
	•					•	•
as Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	10+ years	2015 installation, serve boilers
leating	Devices						
	Unit Heater - Hot Water	Entire Building	2	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	70	LF	5	10+ years	No leaks
	Wall Heater - Electric	Entire Building	7	EA	6	10+ years	
Mechani	cal Plumbing						
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	6	10+ years	Serve main building, recently
		E 0 B 110	000	. –	•	40	resealed, floor mounted
	Hydronic Supply and Return - Copper	Entire Building	600	LF	6	10+ years	Dual temperature, no laks
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Circulating pump,
Tempera	ture Control						
	DDC System	Entire Building	78,700	SF	6	10+ years	Software recently updated, Alerton serves main building
	Electric Thermostat	Entire Building	8	EA	6	10+ years	Serve 2 unit heaters and 6 cabinet heaters
	Thermostats - DDC	Entire Building	43	EA	6	10+ years	Hodioro
	Thermostats - DDC	Entire Building	3	EΑ	4	2-5 years	No calibrated, no signal
		g	· ·		-	_ 0 ,00.0	. To camprated, the eight
/entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	In mechanical rooms
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Roof Mounted Duct Work	Entire Building	200	LF	6	6-10 years	Stainless steel
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	Ctair 11000 01001
	Typo II Exhaust 11000- Walling Mitchell	Entire Daliding	'	L A	J	TOT years	

Campus Name: Otoole Page: 7 of 39 Assessment Date: 05/19/2022



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves main building, 2017 installation
Piping							
, 0	Domestic Piping-Hot Water Return Lines	Entire Building	78,700	SF	6	6-10 years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	78,700	SF	6	6-10 years	Water pressure is sometimes low on top floor
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	78,700	SF	6	6-10 years	•
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	78,700	SF	6	6-10 years	1927 installation
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	78,700	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	78,700	SF	6	6-10 years	There are a few pipe clamps.
	Sanitary Piping	Entire Building	78,700	SF	6	6-10 years	
	Storm Piping	Entire Building	78,700	SF	6	10+ years	
	Vent Piping	Entire Building	78,700	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	4	2-5 years	Older, corroded, not reliable. Serves main building
	Pumps - Sump-Duplex	Entire Building	1	EA	5	6-10 years	Not painted cover
	Pumps - Sump-Simplex	Entire Building	4	EA	6	10+ years	Under elevator, in tunnel, mechanical room

Category: Room **Building: Main**

roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
dminist	rative Suites/Offices					•	
	Ceiling - Lay-in	1.75 level - Gym Office	253	SF	6	10+ years	
	Ceiling - Lay-in	1.75 level - Gym Office	16	SF	5	2-5 years	Missing ceiling tiles
	Doors - Wood Doors inclu hw	1.75 level - Gym Office	1	EA	6	10+ years	
	Floor - Terrazzo	1.75 level - Gym Office	78	SF	6	10+ years	
	Floor - Tile	1.75 level - Gym Office	161	SF	6	10+ years	
	Floor - Tile	1.75 level - Gym Office	30	SF	5	1-2 years	Damaged tiles
	Lighting - Lay-in	1.75 level - Gym Office	1	EA	6	2-5 years	5
	Lighting - Lay-in	1.75 level - Gym Office	3	EA	6	6-10 years	
	Power Distribution	1.75 level - Gym Office	2	EA	6	10+ years	
	Storage/ Closet	1.75 level - Gym Office	145	SF	7	10+ years	
	Walls - Concrete Block	1.75 level - Gym Office	135	SF	6	10+ years	
	Walls - Plaster/Drywall	1.75 level - Gym Office	338	SF	6	10+ years	



Category : Room			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1.75 level - Gym Office	252	SF	6	10+ years	
	Ceiling - Lay-in	1st - 111 Counselor's Office	728	SF	7	10+ years	
	Doors - Transom Window	1st - 111 Counselor's Office	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - 111 Counselor's Office	1	EA	7	10+ years	
	Floor - Wood	1st - 111 Counselor's Office	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st - 111 Counselor's Office	9	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - 111 Counselor's Office	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st - 111 Counselor's Office	1	EA	5	1-2 years	Missing cover
	Power Distribution	1st - 111 Counselor's Office	6	EA	7	10+ years	•
	Walls - Plaster/Drywall	1st - 111 Counselor's Office	1,099	SF	7	10+ years	
	AC Unit	1st - 134 Main Office		EA	7	6-10 years	
	Ceiling - Lay-in	1st - 134 Main Office	322	SF	6	10+ years	
	Doors - Transom Window	1st - 134 Main Office	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - 134 Main Office	1	ĒΑ	7	10+ years	
	Floor - Tile	1st - 134 Main Office	312	SF	6	10+ years	
	Floor - Tile	1st - 134 Main Office	10	SF	5	1-2 years	
	Lighting - Lay-in	1st - 134 Main Office	6	EA	7	10+ years	
	Power Distribution	1st - 134 Main Office	8	EA	6	10+ years	
	Storage/ Closet	1st - 134 Main Office	161	SF	5	10+ years	Peeling paint by the door
	Walls - Plaster/Drywall	1st - 134 Main Office	760	SF	7	10+ years	r ceiling paint by the door
	Ceiling - Lay-in	1st - 146 Staff Lounge	86	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 146 Staff Lounge	1	EA	6	10+ years	
	Floor - Tile	1st - 146 Staff Lounge	86	SF	6	10+ years	
	Lighting - Lay-in	1st - 146 Staff Lounge	3	EA	7	6-10 years	
	Lighting - Lay-iii Lighting - Pendent/Surface	1st - 146 Staff Lounge	1	EA	7	6-10 years	
	Power Distribution	1st - 146 Staff Lounge	6	EA	6	•	
	Walls - Plaster/Drywall	1st - 146 Staff Lounge	172	SF	7	6-10 years 10+ years	
		1st - Principal Office	123	SF	6	10+ years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st - Principal Office	123	EA	6	,	
	Floor - Tile		123	SF	-	10+ years	
		1st - Principal Office		Sr EA	6 7	10+ years	
	Lighting - Pendent/Surface	1st - Principal Office	2			10+ years	
	Power Distribution	1st - Principal Office	2	EA	6	10+ years	
	Walls - Plaster/Drywall	1st - Principal Office	451	SF	7	10+ years	
	Ceiling - Lay-in	216 Office	364	SF	6	10+ years	
	Doors - Transom Window	216 Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	216 Office	1	EA	6	10+ years	
	Floor - Wood	216 Office	364	SF	6	10+ years	
	Lighting - Lay-in	216 Office	4	EΑ	7	6-10 years	
	Power Distribution	216 Office	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	216 Office	753	SF	6	10+ years	
	Ceiling - Lay-in	227 Teacher's Lounge	393	SF	6	10+ years	
	Ceiling - Plaster/Drywall	227 Teacher's Lounge	93	SF	6	10+ years	
	Doors - Transom Window	227 Teacher's Lounge	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	227 Teacher's Lounge	1	EA	6	10+ years	



atego	ry : Room		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	227 Teacher's Lounge	486	SF	6	10+ years	
	Lighting - Pendent/Surface	227 Teacher's Lounge	6	EA	6	6-10 years	
	Power Distribution	227 Teacher's Lounge	4	EA	6	6-10 years	
	Storage/ Closet	227 Teacher's Lounge	98	SF	7	10+ years	
	Walls - Plaster/Drywall	227 Teacher's Lounge	847	SF	6	10+ years	
	Ceiling - Lay-in	227 Teachers lounge storage	478	SF	6	10+ years	
	Doors - Wood Doors inclu hw	227 Teachers lounge storage	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	227 Teachers lounge storage	478	SF	6	10+ years	
	Lighting - Pendent/Surface	227 Teachers lounge storage	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	227 Teachers lounge storage	478	SF	6	10+ years	
	Work SInk	227 Teachers lounge storage	1	EA	7	10+ years	
	AC Unit	Engineer's office boiler Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's office boiler Room	77	SF	7	10+ years	
	Doors - Store Front	Engineer's office boiler Room	1	EA	6	10+ years	
	Floor - Tile	Engineer's office boiler Room	77	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's office boiler Room	2	EA	7	6-10 years	
	Power Distribution	Engineer's office boiler Room	4	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	Engineer's office boiler Room	275	SF	7	10+ years	
	Work SInk	Engineer's office boiler Room	1	EΑ	7	10+ years	
	Balcony Seating	1st - 125 Auditorium	102	EA	7	10+ years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	1st - 125 Auditorium	2,322	SF EA	7	10+ years	
	Floor - Concrete	1st - 125 Auditorium 1st - 125 Auditorium	4 1,032	SF	6 7	10+ years	
	Floor - Terrazzo	1st - 125 Auditorium	1,032	SF	6	10+ years	
				SF SF		10+ years	
	Floor - Tile	1st - 125 Auditorium	1,118		6	10+ years	
	Lighting - Chandelier, Incandescent	1st - 125 Auditorium	6	EΑ	7	10+ years	
	Lighting - Lay-in	1st - 125 Auditorium	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st - 125 Auditorium	5	EA	7	10+ years	
	Lighting - Wall Mounted	1st - 125 Auditorium	15	EA	7	10+ years	
	Main Floor Seating	1st - 125 Auditorium	275	EA	7	10+ years	
	Sound System	1st - 125 Auditorium	1	EA	7	10+ years	
	Stage	1st - 125 Auditorium	553	SF	6	10+ years	
	Stage Curtain	1st - 125 Auditorium	7	EA	5	1-2 years	
	Stage Lift	1st - 125 Auditorium	1	EA	7	10+ years	
	Stage Lighting System	1st - 125 Auditorium	1	EA	7	6-10 years	Rank changed to match current observation
	Stage-Stairs - Wood	1st - 125 Auditorium	10	LF	6	10+ years	
	Stairs - Terrazzo	1st - 125 Auditorium	5	LF	6	10+ years	
	Storage/ Closet	1st - 125 Auditorium	98	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - 125 Auditorium	5,569	SF	7	10+ years	

Campus Name: Otoole Page : 10 of 39 Assessment Date: 05/19/2022



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st - 144 Gym	2,764	SF	6	10+ years	
	Ceiling - Lay-in	1st - 144 Gym	8	SF	5	1-2 years	Missing Tiles
	Doors - Wood Doors inclu hw	1st - 144 Gym	2	EA	6	10+ years	
	Floor - Wood	1st - 144 Gym	2,764	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	1st - 144 Gym	12	EA	7	10+ years	
	Storage/ Closet	1st - 144 Gym	624	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - 144 Gym	3,717	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st - 144 Gym	1,530	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st - 115 Kitchen	1,001	SF	6	10+ years	
	Doors - Transom Window	1st - 115 Kitchen	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - 115 Kitchen	1	EA	7	10+ years	
	Floor - Tile	1st - 115 Kitchen	516	SF	6	10+ years	
	Floor - Tile Quarry	1st - 115 Kitchen	485	SF	6	10+ years	
	Lighting - Lay-in	1st - 115 Kitchen	13	ĒA	7	10+ years	
	Serving Line	1st - 115 Kitchen	46	LF	6	10+ years	
	Storage/ Closet	1st - 115 Kitchen	59	SF	7	10+ years	
	Storage/ Closet	1st - 115 Kitchen	30	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - 115 Kitchen	1,330	SF	6	10+ years	
	vvalio i laotoli Diywali	Tot TTO Tatorion	1,000	O.	O	101 youro	
Library							
,	AC Unit	1st - 101 Library	2	EA	7	6-10 years	
	Casework	1st - 101 Library	94	LF	6	10+ years	
	Ceiling - Lay-in	1st - 101 Library	1,470	SF	6	10+ years	
	Doors - Side-lite	1st - 101 Library	60	SF	6	10+ years	
	Doors - Transom Window	1st - 101 Library	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - 101 Library	2	ĒΑ	6	10+ years	
	Floor - Tile	1st - 101 Library	1,470	SF	6	10+ years	
	Lighting - Pendent/Surface	1st - 101 Library	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - 101 Library	5	EA	6	6-10 years	
	Lighting - Wall Mounted	1st - 101 Library	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st - 101 Library	1,416	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st - 112 Lunchroom	720	SF	6	10+ years	
	Chalk Board	1st - 112 Lunchroom	34	LF	4	2-5 years	
	Doors - Transom Window	1st - 112 Lunchroom	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw		1	Sr EA	7		
	Floor - Tile	1st - 112 Lunchroom	670	SF		10+ years	
		1st - 112 Lunchroom			6	10+ years	Crackad tiles
	Floor - Tile	1st - 112 Lunchroom	50	SF	4	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	1st - 112 Lunchroom	12	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main				
						Recommend			
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	1st - 112 Lunchroom	943	SF	7	10+ years			
	Ceiling - Lay-in	1st - 114 Lunchroom	714	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st - 114 Lunchroom	2	EA	7	10+ years			
	Floor - Tile	1st - 114 Lunchroom	714	SF	6	10+ years			
	Lighting - Lay-in	1st - 114 Lunchroom	12	EA	7	10+ years			
	Walls - Plaster/Drywall	1st - 114 Lunchroom	1,101	SF	7	10+ years			
/IDF_ID	F								
	Doors - Steel Doors incl hw	229	1	EA	6	10+ years			
	Finishes	229	216	SF	7	10+ years			
	Window AC Unit	229	1	EA	7	6-10 years			
∕lechani	ical/ Service Rooms								
	Janitor's Closet	1st Floor	65	SF	7	10+ years			
	Storage Room	1st Floor	417	SF	7	10+ years			
	Janitor's Closet	2nd Floor	60	SF	7	10+ years			
	Janitor's Closet	2nd Floor	60	SF	5	10+ years			
	Storage Room	2nd Floor	80	SF	7	10+ years			
	Air Intake Plenums	Basement	953	SF	7	10+ years			
	Air Tunnel	Basement	3,456	SF	7	10+ years			
	Boiler Room	Basement	2,129	SF	7	10+ years			
	Crawl Space - Unfinished	Basement	13,968	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	103	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	3,523	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	50	SF	7	10+ years			
	Storage Room	Basement	367	SF	7	10+ years			
Restrooi	m								
	Accessories	1.75 level - Staff bath at gym office	28	SF	7	6-10 years	Not accessible (engineer couldn't locate the key)		
	Ceiling - Lay-in	1.75 level - Staff bath at gym office	28	SF	6	10+ years	• •		
	Doors - Wood Doors inclu hw	1.75 level - Staff bath at gym office	1	EA	6	10+ years			
	Floor - Tile	1.75 level - Staff bath at gym office	28	SF	6	10+ years			
	Lavatory	1.75 level - Staff bath at gym office	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1.75 level - Staff bath at gym office	1	EA	6	6-10 years			
	Walls - Concrete Block	1.75 level - Staff bath at gym office	67	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	1.75 level - Staff bath at gym office	48	SF	6	10+ years			
	Water Closet	1.75 level - Staff bath at gym office	1	EA	6	10+ years			
	Accessories	1st - Boys	179	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st - Boys	179	SF	7	10+ years			
	Doors - Transom Window	1st - Boys	9	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st - Boys	129	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st - Boys	50	SF	4	1-2 years			
	TIOUT - THE OCIAITHO TOLOGIAIT	13t - D0y3	50	Ji	4	1-2 years			



atego	ategory : Room		В	uilding	: Main				
						Recommend			
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	1st - Boys	1	EA	7	10+ years			
	Hand Dryer	1st - Boys	1	EA	7	10+ years			
	Lavatory	1st - Boys	3	EA	7	10+ years			
	Lighting - Pendent/Surface	1st - Boys	5	EA	7	10+ years			
	Partitions	1st - Boys	2	EA	7	10+ years			
	Urinals	1st - Boys	4	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st - Boys	278	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st - Boys	278	SF	7	10+ years			
	Water Closet	1st - Boys	2	EA	7	10+ years			
	Accessories	1st - Girls across from assembly	289	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st - Girls across from assembly	289	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st - Girls across from assembly	289	SF	7	10+ years			
	Floor Drain	1st - Girls across from assembly	1	EΑ	7	10+ years			
	Hand Dryer	1st - Girls across from assembly	1	EA	7	10+ years			
	Lavatory	1st - Girls across from assembly	3	EA	7	10+ years			
	Lighting - Pendent/Surface	1st - Girls across from assembly	5	EA	7	10+ years			
	Partitions	1st - Girls across from assembly	4	EA	7	10+ years			
	Partitions	1st - Girls across from assembly	1	EA	5	1-2 years	Damaged partition		
	Partitions	1st - Girls across from assembly	1	ΕA	5	1-2 years	Missing door		
	Walls - Plaster/Drywall	1st - Girls across from assembly	378	SF	7	10+ years	g a.c		
	Walls - Structural Glazed Tile	1st - Girls across from assembly	378	SF	7	10+ years			
	Water Closet	1st - Girls across from assembly	6	EA	7	10+ years			
	Accessories	1st - Unisex across from gym	299	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st - Unisex across from gym	299	SF	7	10+ years			
	Doors - Transom Window	1st - Unisex across from gym	9	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st - Unisex across from gym	299	SF	6	10+ years			
	Floor Drain	1st - Unisex across from gym	1	EA	7	10+ years			
	Hand Dryer	1st - Unisex across from gym	1	EA	7	10+ years			
	Lavatory	1st - Unisex across from gym	2	EA	6	10+ years			
	Lighting - Pendent/Surface	1st - Unisex across from gym	5	EA	7	•			
	Partitions	1st - Unisex across from gym	5	EA	7	10+ years 10+ years			
	Partitions	1st - Unisex across from gym	1	EA	5		Missing door		
	Walls - Plaster/Drywall	•	382	SF	7	1-2 years	Missing door		
	Walls - Flaster/Drywan Walls - Structural Glazed Tile	1st - Unisex across from gym	382	SF	7	10+ years			
		1st - Unisex across from gym	100	SF	7	10+ years			
	Walls - Tile	1st - Unisex across from gym		EA		10+ years			
	Water Closet	1st - Unisex across from gym	6	SF	6	10+ years			
	Accessories	1st - Unisex in kitchen	32		7	6-10 years			
	Ceiling - Lay-in	1st - Unisex in kitchen	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st - Unisex in kitchen	1	EA	6	10+ years			
	Floor - Tile	1st - Unisex in kitchen	32	SF	6	10+ years			
	Lavatory	1st - Unisex in kitchen	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st - Unisex in kitchen	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st - Unisex in kitchen	230	SF	7	10+ years			
	Water Closet	1st - Unisex in kitchen	1	EA	6	10+ years			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st - inside 105	83	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside 105	83	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 105	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - inside 105	83	SF	7	10+ years	
	Floor Drain	1st - inside 105	1	EA	7	10+ years	
	Hand Dryer	1st - inside 105	1	EA	7	6-10 years	
	Lavatory	1st - inside 105	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - inside 105	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st - inside 105	166	SF	7	10+ years	
	Water Closet	1st - inside 105	1	EA	7	10+ years	
	Accessories	1st - inside 134A Principle	25	SF	7	6-10 years	
	Ceiling - Lay-in	1st - inside 134A Principle	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st - inside 134A Principle	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - inside 134A Principle	25	SF	6	10+ years	
	Lavatory	1st - inside 134A Principle	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st - inside 134A Principle	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st - inside 134A Principle	212	SF	7	10+ years	
	Water Closet	1st - inside 134A Principle	1	EA	7	10+ years	
	Accessories	1st - inside engineer office	15	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st - inside engineer office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - inside engineer office	1	EA	6	10+ years	
	Floor - Tile	1st - inside engineer office	15	SF	6	10+ years	
	Lighting - Pendent/Surface	1st - inside engineer office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st - inside engineer office	208	SF	7	10+ years	
	Water Closet	1st - inside engineer office	1	EA	7	10+ years	
	Accessories	1st - unisex next to 146	105	SF	7	6-10 years	
	Ceiling - Lay-in	1st - unisex next to 146	105	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st - unisex next to 146	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - unisex next to 146	105	SF	6	10+ years	
	Floor Drain	1st - unisex next to 146	1	EA	7	10+ years	
	Hand Dryer	1st - unisex next to 146	1	EA	7	6-10 years	
	Lavatory	1st - unisex next to 146	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st - unisex next to 146	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st - unisex next to 146	207	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st - unisex next to 146	207	SF	7	10+ years	
	Water Closet	1st - unisex next to 146	1	EA	7	10+ years	
	Accessories	2nd Floor	311	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	311	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	311	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	-		-			- ,	



Catego	ory : Room		В	uilding	: Main		, , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	2nd Floor	591	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	254	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	2nd Floor	273	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	273	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	273	SF	6	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	ĒΑ	7	10+ years	
	Lavatory	2nd Floor	2	ΕA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	4	EA	6	10+ years	
	Walls - Masonry	2nd Floor	553	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years	
	Water Closet	2nd Floor	237	EA	6	10+ years	
	Accessories	2nd Floor	273	SF	7	6-10 years	
			273	SF		<u>-</u>	
	Ceiling - Plaster/Drywall	2nd Floor		SF SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	273		6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	4	EA	6	10+ years	
	Walls - Masonry	2nd Floor	553	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor	311	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	311	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	311	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	6	EΑ	7	10+ years	
	Walls - Masonry	2nd Floor	591	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	253	SF	6	10+ years	
	Walls - Tile	2nd Floor	100	SF	7	10+ years	
	Water Closet	2nd Floor	6	ĒΑ	6	10+ years	
	Ceiling - Plaster/Drywall	Boiler Room	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	ĒΑ	6	6-10 years	
	Floor - Concrete	Boiler Room	15	SF	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Boiler Room	200	SF	7	10+ years	
	Water Closet	Boiler Room	1	EA	7	6-10 years	
	vvator Oloset	Doller Room	'	L/\	,	o- To years	



Catego	ry : Room		В	uilding	: Main		Occidy Avenue, Officago, in 60000
0	Name Trans	Landin	0	LIOM	DI-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #100 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	735	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Broken cover
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	958	SF	7	10+ years	
Classroo	om #102 (Kindergarten)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	683	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	683	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	909	SF	7	10+ years	
_Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	947	SF	7	10+ years	
Classroo	om #104 (Store Room)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	705	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	10	SF	6	10+ years	
	Floor - Wood	1st Floor	705	SF	6	10+ years	
		 -			-	- ,	



Catego	ory : Classroom		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EΑ	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	934	SF	7	10+ years	
Classroo	om #105 (Kindergarten)						
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,417	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	1,417	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	62	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,319	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Kindergarten)						
	Casework	1st Floor	32	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	767	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	767	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	983	SF	7	10+ years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	721	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	5	1-2 years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	11	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	945	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #110 (Lunch Room)						
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	720	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		330 0 decicy Avenue, officago, ie 60030
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	939	SF	6	10+ years	
_Classroo	om #113 (Store Room)						
	Ceiling - Lay-in	1st Floor	468	SF	6	10+ years	
	Doors - Transom Window	1st Floor	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	468	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	802	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
Classice	Casework	2nd Floor	10	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	•	
	Floor - Wood Doors Inclu IIW	2nd Floor	735	SF		10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6 6	10+ years 6-10 years	
		2nd Floor		LF	7		
	Marker Board		20	SF		6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	5F	6	10+ years	
Classroo	om #201N (Store Room)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	540	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	540	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	2-5 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	17	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	863	SF	6	10+ years	
Classroo	om #201S (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
			·		-	- , , J	

Campus Name: Otoole Page: 18 of 39 Assessment Date: 05/19/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	577	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	670	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	886	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	ĒA	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
Classroo	om #203 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	945	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	6	6-10 years	
	gg 1 01140114 0 411400	2.10 1 1001	· ·	_, .	Ŭ	3 . o youro	

Campus Name: Otoole Page: 19 of 39 Assessment Date: 05/19/2022



Catego	ry : Classroom		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	942	SF	6	10+ years	
_Classro	om #205 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	2-5 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	946	SF	6	10+ years	
Classro	om #206 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
Classro	om #207 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	2-5 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
Classro	om #208 (Regular Classroom)						
CidooiU	Casework	2nd Floor	10	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	642	SF	6 6	10+ years 10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	93	SF SF	6	•	
	Cenning - Flaster/Drywall	ZIIU FIUUI	93	ЭF	O	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years	
	Marker Board	2nd Floor	35	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	942	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
			735	SF	6	•	
	Floor - Wood	2nd Floor				10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	2-5 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Boors inclu riw	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years	
	Lighting - Pendent/Surface Lighting - Pendent/Surface	2nd Floor 2nd Floor	1	EA	6		
	Marker Board	2nd Floor 2nd Floor	25	LF	7	2-5 years	
						6-10 years	
	Walls - Plaster/Drywall	2nd Floor	930	SF	6	10+ years	

Campus Name: Otoole Page : 21 of 39 Assessment Date: 05/19/2022



Catego	ry : Classroom		В	uilding	: Main		330 3 Seeley AVENUE, Chicago, IL 60036
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	11040 (D I. Ol)						
_Classroc	om #212 (Regular Classroom)	0 15	10			10	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	45	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	940	SF	6	10+ years	
_Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	642	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	93	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	946	SF	6	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	735	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	946	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
Ciassiuu	Casework	2nd Floor	10	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	643	SF	6	10+ years 10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	93	SF SF	6	10+ years 10+ years	
	Chalk Board	2nd Floor 2nd Floor	25	SF LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	25	SF	6	2-5 years 10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	9	SF EA	6	•	
	Floor - Wood Doors Inclu nw	2nd Floor 2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	12	SF EA	6	10+ years 6-10 years	
				LF	6 7	•	
	Marker Board	2nd Floor	20	ᄕ	′	6-10 years	



Building: Main Category : Classroom

Recommend Group Location Quantity UOM Rank Replacement Comments Item - Type

Walls - Plaster/Drywall 2nd Floor SF 10+ years 642 6

Category: Interior **Building: Main**

Categor	ry : Interior		Б	uilding	: wam		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	5,489	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	480	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	7	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	6	EΑ	7	10+ years	
	Floor - Terrazzo	1st Floor	1,323	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	5,368	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	1-2 years	Broken tiles
	Lighting - Lay-in	1st Floor	66	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	6	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	261	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	10,248	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	895	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	5,728	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	5	EΑ	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	5,728	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	70	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	322	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	8,713	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Peeling paint
Safety							
	Camera Viewing Station	Entire building	3	EΑ	7	6-10 years	
	Metal Dedector	Entire building	1	EA	7	6-10 years	
	Security Cameras	Entire building	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	NE stair up to assembly balcony	76	SF	7	10+ years	
	Floor - Terrazzo	NE stair up to assembly balcony	14	SF	7	10+ years	
	Handrails	NE stair up to assembly balcony	24	LF	7	10+ years	
	Lighting - Wall Mounted	NE stair up to assembly balcony	1	EA	7	10+ years	
	Stairs - Terrazzo	NE stair up to assembly balcony	16	LF	7	10+ years	
	Walls - Plaster/Drywall	NE stair up to assembly balcony	413	SF	7	10+ years	
	Ceiling - Lay-in	North East stair 6	252	SF	7	10+ years	
	Floor - Terrazzo	North East stair 6	112	SF	6	10+ years	
	Handrails	North East stair 6	67	LF	5	10+ years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Terrazzo	North East stair 6	27	LF	6	10+ years	
	Stairs - Terrazzo	North East stair 6	1	LF	5	1-2 years	Damaged tread
	Walls - Plaster/Drywall	North East stair 6	755	SF	6	10+ years	
	Ceiling - Lay-in	North West Stair 4	252	SF	7	10+ years	
	Floor - Terrazzo	North West Stair 4	112	SF	6	10+ years	
	Handrails	North West Stair 4	67	LF	5	10+ years	
	Lighting - Pendent/Surface	North West Stair 4	3	EA	6	10+ years	
	Stairs - Terrazzo	North West Stair 4	25	LF	6	10+ years	
	Stairs - Terrazzo	North West Stair 4	3	LF	4	1-2 years	Cracked treads
	Walls - Plaster/Drywall	North West Stair 4	755	SF	6	10+ years	
	Ceiling - Lay-in	South East	252	SF	6	10+ years	
	Floor - Terrazzo	South East	112	SF	6	10+ years	
	Handrails	South East	67	LF	5	10+ years	
	Lighting - Pendent/Surface	South East	3	EA	7	6-10 years	
	Stairs - Terrazzo	South East	28	LF	6	10+ years	
	Walls - Plaster/Drywall	South East	755	SF	6	10+ years	
	Ceiling - Lay-in	Southwest Stair 3	252	SF	6	10+ years	
	Floor - Terrazzo	Southwest Stair 3	112	SF	6	10+ years	
	Handrails	Southwest Stair 3	67	LF	5	10+ years	
	Lighting - Pendent/Surface	Southwest Stair 3	3	EA	6	10+ years	
	Stairs - Terrazzo	Southwest Stair 3	28	LF	6	10+ years	
	Stairs - Terrazzo	Southwest Stair 3	2	LF	5	1-2 years	Broken treads
	Walls - Plaster/Drywall	Southwest Stair 3	755	SF	6	10+ years	
	Ceiling - Lay-in	West	252	SF	7	10+ years	
	Floor - Terrazzo	West	112	SF	6	10+ years	
	Handrails	West	67	LF	5	10+ years	
	Lighting - Pendent/Surface	West	3	EA	6	10+ years	
	Stairs - Terrazzo	West	28	LF	6	10+ years	
	Walls - Plaster/Drywall	West	755	SF	6	10+ years	
	Ceiling - Plaster/Drywall	down from 2nd to Gym Office	38	SF	6	10+ years	
	Floor - Terrazzo	down from 2nd to Gym Office	18	SF	6	10+ years	
	Handrails	down from 2nd to Gym Office	14	LF	5	10+ years	
	Lighting - Pendent/Surface	down from 2nd to Gym Office	1	EA	6	10+ years	
	Stairs - Terrazzo	down from 2nd to Gym Office	7	LF	6	10+ years	
	Walls - Plaster/Drywall	down from 2nd to Gym Office	148	SF	6	10+ years	
Vertical (Conveyance						
	Elevator - Elevator - Roped Holeless Hydraulic	Entire Building	1	EA	7	10+ years	

Campus Name: Otoole Page : 24 of 39 Assessment Date: 05/19/2022



Category : Exterior Building : Annex

	ry : Exterior			ullaing	. ,		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Entrance Control - Audio and Video	#10- S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10- S	2	EA	6	6-10 years	Assessed based on current conditi
	Exterior Doors - Side lite	#10- S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10- S	2	EA	6	10+ years	
	Power Door Operator and Controls	#10- S	1	EA	7	10+ years	
	Entrance Control - Audio and Video	#11- N	1	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	#11- N	2	EA	6	10+ years	
	Exterior Doors - Side lite	#11- N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11- N	2	EA	6	10+ years	
	Power Door Operator and Controls	#11- N	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#12- S- Elev Mech Rm	1	EA	6	6-10 years	Surface rust . Assessed based on
						,	current condition
oundati	on						
	Foundation - Concrete	Entire Building	390	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	18,000	SF	7	10+ years	
	Caparation Control	g	. 0,000	•	-	. o . y ca. c	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	10+ years	
Roof Sys	stem						
,	Coping - Metal	Elevator Roof	60	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Elevator Roof	14	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Elevator Roof	10	LF	6	10+ years	
	Parapet - 16" - 30" Height	Elevator Roof	60	LF	6	10+ years	
	Roof - Modified Bitumen	Elevator Roof	108	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Elevator Roof	108	SF	7	10+ years	
	Concrete Topping	Elevator 11001	100	O.	•	101 years	
	Access Ladder - Metal	Main Roof	1	EA	4	0-1 year	Poor configuration, little clearance
	Coping - Metal	Main Roof	390	LF	6	10+ years	1 oor corniguration, little clearance
	Downspouts - Interior Downspouts	Main Roof	144	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	7,790	SF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	1,200	SF	5		Ponding, poor slope, bubbles,
	Rooi - Modified Bitumen	Main Rooi	1,200	SF	5	0-1 year	cracking
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	-
	Roof Structure - Concrete	Main Roof	8,990	SF	7	10+ years	
Valls							
	Exterior Walls - Precast Panel Wall	Entire Building	1,716	SF	6	10+ years	Combined quantities
				SF			1 wase
	Exterior Walls - Prefabricated Metal Panel	Entire Building	9,360	2F	6	10+ years	

Campus Name: Otoole Page : 25 of 39 Assessment Date: 05/19/2022



Categoi	ry : Exterior		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Windows							
	Curtain wall - Glazed Single Pane	Entire Building	875	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	336	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	175	SF	6	10+ years	
	Windows - Casement Aluminum	Entire Building	700	SF	6	10+ years	
Categoi	ry : Electrical		В	uilding	: Annex	(
				- J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	ncy System						
	Automatic Transfer Switch	1st Floor	1	EA	6	6-10 years	Serves annex, functional, older
	Emergency Battery Packs - Corridors and	Entire Building	6	EA	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	Glare seen at photo is due to light
							fixture shinning into lens of iPad
							camera, light fixtures are good
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Batteries installed, functional
	Security System - CCTV	Entire Building	18,000	SF	5	6-10 years	Exterior cameras only
	Security System - Intrusion Detection	Entire Building	18,000	SF	6	6-10 years	•
	Emergency A/C Power - Corridors and	Entire Building	2,451	SF	6	10+ years	
	Stairs	•					
	Emergency A/C Power - Students Toilets	Entire Building	3,500	SF	6	10+ years	Building has an EM panel
Main Ser	rvice						
Maiii Gei	Main Electrical Service - 1600 A	Electrical Room	1	EA	6	6-10 years	Serves Annex, functional
	120/208/3PH	Licetifed Room	'	L/ \	O	o to years	Gerves / timex, functional
	Independent Electrical Service for	Entire Building	1	EA	6	6-10 years	Served by ATS and there is a secon
	emergency power	Entire ballaring	'	L/ \	O	o to years	meter, serves annex
	PA System	Entire Building	18,000	SF	4	2-5 years	Difficult to use, connected to main
	1 / Gystem	Entire ballaring	10,000	O.	7	2 o years	building
Power Di	istribution					40	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Functional
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	1970 installation. Panel rated 7 have a 10+ years of life
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	Within switchgear cabinet
	mani Pistribution i aneis - Oreater tridii 000	Little Dallaling	1		,	ioi yeais	Triami Switchige ar Cabinet

Campus Name: Otoole Page : 26 of 39 Assessment Date: 05/19/2022



atego	ry : Electrical		В	uilding	: Annex		
	Name Toma	Lasadian	0	LIOM	D I-	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
atego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves annex
	Fire Alarm Strobe Lights	Entire Building	18,000	SF	6	10+ years	
	Fire Alarm_System	Entire Building	18,000	SF	6	10+ years	Connected to main building
Catego	ry : Mechanical		В	uildina	: Annex		
	, y		_	uug	. ,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
leating I	Devices					·	
ŭ	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	4	2-5 years	Deteriorated, not reliable
		·				•	
Tempera	ture Control						
	Electric Controls	Entire Building	18,000	SF	5	6-10 years	Serves 20 univents. No DDC, no
							pneumatics
Jnit Ven	tilation						
Jille V Cil	Unit Ventilators- Floor Mounted- Electric	Entire Building	10	EA	5	6-10 years	
	Heating & DX Cooling Coil W/ Self	Zitare Bananig		_, .	Ŭ	o io jouio	
	Contained Compressor						
	Unit Ventilators- Floor Mounted- Electric	Entire Building	10	EA	4	2-5 years	Require frequent maintenance
	Heating & DX Cooling Coil W/ Self	Zitare Bananig		_, .		2 o you.o	rtoquiro iroquorit mainteriarios
	Contained Compressor						
/entilatio							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	5	6-10 years	Serve restrooms, located above
	Exhaust Fone Boof Mounted 1501 0000	Entire Building	1	Ε.	-	6.10 years	ceilings, roof vented
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	
	O. W.						
Catego	ry : Plumbing		В	uilding	: Annex		
``	Hom Tune	Logotion	O	LICA	Denle	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		Ast Floor				0.5.	Orange de differential de la constantial de la c
	Electric Heater - 20 - 50 KW	1st Floor	1	EA	4	2-5 years	Corroded, functional, not reliable

Campus Name: Otoole Page : 27 of 39 Assessment Date: 05/19/2022



Catego	ry : Plumbing		В	uilding	: Annex		
_	<u> </u>			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	18,000	SF	6	10+ years	Pressure is good
	Domestic Piping-Hot Water Return Risers	Entire Building	18,000	SF	6	10+ years	No pipe clamps
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	18,000	SF	6	10+ years	No pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	18,000	SF	6	10+ years	1970 installation, functional
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	18,000	SF	6	10+ years	Functional, good
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	18,000	SF	6	10+ years	No leaks
	Sanitary Piping	Entire Building	18,000	SF	6	10+ years	Functional
	Storm Piping	Entire Building	18,000	SF	6	10+ years	
	Vent Piping	Entire Building	18,000	SF	6	10+ years	
Pumps							
	Pumps - Sump-Simplex	1st Floor	1	EA	5	6-10 years	Under elevator, pump not accessible, per engineer, functional

Category : Room **Building: Annex**

						Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
inist	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor - Teacher's Lounge	195	SF	4	1-2 years	Water damage tiles
	Doors - Steel Doors incl hw	1st Floor - Teacher's Lounge	1	EΑ	7	10+ years	-
	Floor - Tile	1st Floor - Teacher's Lounge	195	SF	6	10+ years	Rank changed to match curren observation
	Lighting - Lay-in	1st Floor - Teacher's Lounge	5	EA	6	10+ years	
	Power Distribution	1st Floor - Teacher's Lounge	6	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor - Teacher's Lounge	502	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Main Office	190	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Main Office	30	SF	4	1-2 years	
	Doors - Side-lite	1st Floor - Main Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office	210	SF	6	10+ years	
	Lighting - Lay-in	1st Floor - Main Office	4	EA	6	10+ years	
	Power Distribution	1st Floor - Main Office	6	EA	6	10+ years	
	Storage/ Closet	1st Floor - Main Office	110	SF	5	1-2 years	Water damage ceiling tiles
	Walls - Vinyl Coated Gypsum Panel	1st Floor - Main Office	520	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Principal's Office	110	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor - Principal's Office	110	SF	5	1-2 years	Damaged carpet
	Lighting - Lay-in	1st Floor - Principal's Office	2	EA	7	10+ years	-
	Power Distribution	1st Floor - Principal's Office	4	EA	6	10+ years	
	Walls - Metal Panel	1st Floor - Principal's Office	378	SF	7	10+ years	

Campus Name: Otoole Page : 28 of 39 Assessment Date: 05/19/2022



Catego	ry : Room		B	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library	Casework	2nd Floor	70	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	775	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	T Grid missing in ceiling
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	I Grid Hilssing III Celling
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	775	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	500	SF	6	10+ years	
	Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel	2nd Floor	500	SF	6		
	waiis - vinyi Coated Gypsum Panei	2na F100r	500	SF	б	10+ years	
/lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	155	SF	7	10+ years	Rank changed to match current observation
	Mechanical/ Service Rooms	1st Floor	52	SF	7	10+ years	Rank changed to match current observation
	Mechanical/ Service Rooms	2nd Floor	155	SF	5	10+ years	
Restroon	n						
	Accessories	1st Floor	170	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	166	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	1-2 years	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	•
	Floor - Tile Ceramic/ Porcelain	1st Floor	170	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	10+ years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	470	SF	7	10+ years	
	Water Closet	1st Floor	4	ĒΑ	7	10+ years	
	Accessories	1st Floor	230	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	230	SF	4	1-2 years	Most of the ceilings has missing tile
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	and the second s
	Floor - Tile Ceramic/ Porcelain	1st Floor	230	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	4	EA	7	10+ years	
	Cilials	1301 1001	7	SF	7	10+ years	

Campus Name: Otoole Page : 29 of 39 Assessment Date: 05/19/2022



Catego	ategory : Room			uilding	: Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor - Room 103	55	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Room 103	53	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Room 103	2	SF	4	1-2 years	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor - Room 103	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Room 103	55	SF	7	10+ years	
	Floor Drain	1st Floor - Room 103	1	EA	7	10+ years	
	Lavatory	1st Floor - Room 103	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Room 103	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Room 103	266	SF	7	10+ years	
	Water Closet	1st Floor - Room 103	1	EA	7	10+ years	
	Accessories	1st Floor - Teacher's Lounge	20	SF	5	1-2 years	
	Ceiling - Lay-in	1st Floor - Teacher's Lounge	20	SF	4	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	1st Floor - Teacher's Lounge	1	EA	7	10+ years	3
	Floor - Tile Ceramic/ Porcelain	1st Floor - Teacher's Lounge	20	SF	7	10+ years	
	Lavatory	1st Floor - Teacher's Lounge	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Teacher's Lounge	1	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor - Teacher's Lounge	160	SF	7	10+ years	
	Water Closet	1st Floor - Teacher's Lounge	1	EA	6	10+ years	
	Accessories	2nd Floor	57	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	57	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	57	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EΑ	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	272	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	250	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	226	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Water damage and missing tiles
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Trator damage and missing mes
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	4	EΑ	6	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	6	10+ years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	570	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	2nd Floor	250	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	226	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Warped and water damaged tiles
			21	٥.	Ü	. 2 ,00.0	pos and mater damaged thee

Campus Name: Otoole Page : 30 of 39 Assessment Date: 05/19/2022



Catego	ry : Room		В	uilding	: Annex	(
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	6	10+ years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	570	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	Teacher's lounge	20	SF	7	6-10 years	
	Ceiling - Lay-in	Teacher's lounge	20	SF	4	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	Teacher's lounge	1	ĒΑ	7	10+ years	3
	Floor - Tile Ceramic/ Porcelain	Teacher's lounge	20	SF	7	10+ years	
	Lavatory	Teacher's lounge	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Teacher's lounge	1	EΑ	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Teacher's lounge	160	SF	7	10+ years	
	Water Closet	Teacher's lounge	1	EA	7	10+ years	
	water closet	reacher 3 lourige	ı	LA	,	10+ years	
Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Item - Type om #100 (Vacant)	Location	•		Rank	Replacement	Comments
	om #100 (Vacant) Casework	Location 1st Floor	10	LF	Rank 6	Replacement 10+ years	Comments
•	om #100 (Vacant)		•	LF SF		•	Comments
•	om #100 (Vacant) Casework	1st Floor	10	LF SF SF	6	10+ years	Damaged tiles
•	om #100 (Vacant) Casework Ceiling - Lay-in	1st Floor 1st Floor	10 397	LF SF	6 6	10+ years 10+ years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in	1st Floor 1st Floor 1st Floor	10 397 47	LF SF SF	6 6 4	10+ years 10+ years 1-2 years 10+ years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite	1st Floor 1st Floor 1st Floor 1st Floor	10 397 47 8	LF SF SF SF	6 6 4 7	10+ years 10+ years 1-2 years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 397 47 8 1	LF SF SF SF EA	6 6 4 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 397 47 8 1 434	LF SF SF SF EA SF	6 6 4 7 7 7 6	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 6-10 years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 397 47 8 1 434 6	LF SF SF EA SF EA	6 6 4 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 6-10 years	
•	om #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board	1st Floor	10 397 47 8 1 434 6	LF SF SF EA SF EA LF	6 6 4 7 7 7 6 7	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 6-10 years	
Classroo	cm #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel	1st Floor	10 397 47 8 1 434 6 10 375	LF SF SF SF EA SF EA LF SF	6 6 4 7 7 7 6 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
Classroo	cm #100 (Vacant) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF EA SF EA LF SF	6 6 4 7 7 7 6 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel 2m #101 - K1 (Vacant) Ceiling - Lay-in	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF EA SF EA LF SF SF	6 6 4 7 7 7 6 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel m #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF SF EA LF SF SF SF	6 6 4 7 7 7 6 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF SF EA LF SF SF SF SF	6 6 4 7 7 7 6 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF EA SF EA LF SF SF SF SF	6 6 4 7 7 7 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 2-5 years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	1st Floor	985 40 8 2 1,025	LF SF SF EA SF EA LF SF SF SF SF SF SF	6 6 4 7 7 7 6 7 7 7 4 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor	10 397 47 8 1 434 6 10 375 375	LF SF SF EA SF EA LF SF SF SF SF EA	6 6 4 7 7 7 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	1st Floor	985 40 8 2 1,025 15 20	LF SF SF EA SF EA LF SF SF SF EA SF LF	6 6 4 7 7 7 6 7 7 7 4 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Damaged tiles
Classroo	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel Om #101 - K1 (Vacant) Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	1st Floor	10 397 47 8 1 434 6 10 375 375 375	LF SF SF EA SF EA LF SF SF SF SF EA	6 6 4 7 7 7 6 7 7 7 4 7 7 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Damaged tiles

Campus Name: Otoole Page: 31 of 39 Assessment Date: 05/19/2022



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Vinyl Coated Gypsum Panel	1st Floor	576	SF	7	10+ years	
Classroo	om #102 - EC1 (Vacant)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	876	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	4	1-2 years	Water damage tiles
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	•
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Lighting - Lay-in	1st Floor	5	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	540	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	540	SF	7	10+ years	
	Walls Villy Coaled Gypsull Faller	13(1100)	040	O.	,	101 years	
lassroc	m #103 - K2 (Vacant)	4 / 🗗				40	
	Ceiling - Lay-in	1st Floor	1,111	SF	6	10+ years	Mississ and water dames at the
	Ceiling - Lay-in	1st Floor	24	SF SF	4	1-2 years	Missing and water damage tiles
	Doors - Side-lite	1st Floor	8		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,135	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	606	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	606	SF	6	10+ years	
Classroc	m #104 - FC2 (Vacant)						
	Ceiling - Lay-in	1st Floor	1,066	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,066	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	4	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	588	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	588	SF	7	10+ years	
laceroo	om #106 - EC3 (Store Room)						
nassiuu	Ceiling - Lay-in	1st Floor	850	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	20	SF	4	1-2 years	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	vvater damage tiles
	Pools - Mood Pools Illoid IIM	13(1100)	ı	ĽA	1	TOT years	

Campus Name: Otoole Page : 32 of 39 Assessment Date: 05/19/2022



atego	ry : Classroom		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	870	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	530	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	530	SF	7	10+ years	
assroc	om #200 (Vacant)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	427	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Missing tile
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	whoshing the
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	435	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	
	Lighting - Lay-in Lighting - Lay-in	2nd Floor	4	EA	_	-	
					6	2-5 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	375	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	375	SF	6	10+ years	
assroc	om #201 - LE3 (Vacant)						
	Ceiling - Lay-in	2nd Floor	1,040	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	-
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	7	ĒA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	ĒΑ	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EΑ	5	0-1 year	Missing diffuser
	Marker Board	2nd Floor	20	LF	7	6-10 years	Wildeling diffusion
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	1,166	SF	6	10+ years	
	,		,			,	
assroc	om #202 - LE1 (Vacant)						
	Casework	2nd Floor	65	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,000	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,000	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	8	EA	6	2-5 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	72	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	570	SF	6	10+ years	
	vvano i lastor/Drywan	21011001	370	O.	U	101 yours	

Campus Name: Otoole Page : 33 of 39 Assessment Date: 05/19/2022



Category : Classroom			В	uilding			
_				_			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	570	SF	6	10+ years	
Classroo	m #203 - LE4 (Vacant)						
	Ceiling - Lay-in	2nd Floor	1,125	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,125	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	7	EA	6	2-5 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	5	1-2 years	Damaged assembly
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	1,208	SF	6	10+ years	
Classroo	m #204 - LE2 (Vacant)						
SIASSIUU	Casework	2nd Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,025	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	1,023	SF		10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor	1	EA	6 6	,	
	Floor - Tile			SF	6	10+ years	
		2nd Floor	1,025			10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	575	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	575	SF	6	10+ years	
Classroo	m #205 (Vacant)						
	Ceiling - Lay-in	2nd Floor	647	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	28	SF	5	1-2 years	Water damaged and missing tiles
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	ğ ğ
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	675	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	8	ĒΑ	6	10+ years	
	Lighting - Lay-in	2nd Floor	2	EΑ	5	1-2 years	Damaged diffuser
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	935	SF	6	10+ years	
Categor	ry : Interior		R	uildina	: Annex		
Julegoi	y . Interior			ununig	. Alliex	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	0.11	4 . 🗔	4.005	05	-	40	
	Ceiling - Lay-in	1st Floor	1,065	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	150	SF	4	0-1 year	Heavy mold growth

Campus Name: Otoole Page : 34 of 39 Assessment Date: 05/19/2022



Category : Interior			В	uilding	: Annex	· · · · · · · · · · · · · · · · · · ·	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	900	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	165	SF	5	0-1 year	Water damage tiles
	Lighting - Lay-in	1st Floor	7	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,175	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,086	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,086	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	1,186	SF	6	10+ years	
Stairs							
	Ceiling - Lay-in	Stair 1	150	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Stair 1	752	SF	7	10+ years	
	Handrails	Stair 1	86	LF	7	10+ years	
	Lighting - Lay-in	Stair 1	2	EΑ	6	10+ years	
	Stairs - Concrete	Stair 1	18	LF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Stair 1	2,470	SF	7	10+ years	
	Ceiling - Lay-in	Stair 2	150	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Stair 2	752	SF	5	10+ years	
	Handrails	Stair 2	36	LF	5	10+ years	
	Lighting - Lay-in	Stair 2	2	EA	6	10+ years	
	Stairs - Concrete	Stair 2	18	LF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Stair 2	24,700	SF	6	10+ years	
_Vertical (Conveyance						
<u> </u>	Elevator - Hydraulic Elevator	1st Floor	1	EA	4	0-1 year	Not working

Campus Name: Otoole Page : 35 of 39 Assessment Date: 05/19/2022





Category: Site **Building: Site**

Jatego	ry : Site		Building : Site							
						Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Civil/Dra	inage									
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	6	10+ years				
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years				
	•					·				
encina										
	Fencing - Chain Link	Entire Site	640	LF	6	10+ years				
	Fencing - Chain Link	Entire Site	30	LF	5	1-2 years	Missing gates			
	Fencing - New Standard Ornamental	Entire Site	855	LF	6	10+ years	meenig gatee			
	Fencing - New Standard Ornamental	Entire Site	10	LF	5	1-2 years	Bent section			
	r choing - New Standard Chiamonia	Zinii o ono	10		Ü	. L youro	Dom cochem			
andsca	pe									
	Landscape - Grass	Entire Site	12,215	SF	6	10+ years				
	Landscape - Hardscape- Concrete	Entire Site	840	SF	6	10+ years				
	Parkway trees	Entire Site	48	EA	7	10+ years				
	Parkway trees	Entire Site	3	EA	4	1-2 years	Missing			
	Planting Beds/ Area	Entire Site	790	SF	6	10+ years				
	Play Area - Hardscape- Asphalt	Entire Site	55,932	SF	6	10+ years				
	Play Area - Hardscape- Asphalt	Entire Site	5,846	SF	4	0-1 year	Missing, damaged paving			
	Retaining Wall - Concrete	Entire Site	1,600	SF	6	10+ years				
Parking	Lot									
arking	Surface - Asphalt	SW Lot	20,425	SF	6	2-5 years	Raveling, alligator cracking			
	Surface - Asphalt	SW Lot	5,000	SF	4	0-1 year	Combined quantities, potholes,			
	Carraco / toprian	O. 120.	3,000	O.		o i you	damaged pavement			
	Trash Enclosure - Chain Links	SW Lot	486	SF	7	10+ years	damagea pavement			
	Trash Enclosure - Chain Links	SW Lot	600	SF	4	0-1 year	Combined quantities, missing			
	Tracin Englescard Chain Enime	O. 100	000	О.	•	o i you.	fencing			
							•			
Playgro∟										
	Equipment - Pre K 3-5	East	1	EA	7	10+ years				
	Equipment - Pre K 3-5	East	1	EA	7	10+ years				
	Equipment - School Age 5-12	East	1	EA	7	10+ years				
	Equipment - School Age 5-12	East	1	EA	7	10+ years				
	Surface - Poured Surface	East	1,800	SF	6	10+ years				
	Surface - Poured Surface	East	1,800	SF	6	10+ years				
Sidewall	(S									
	Sidewalks - Internal Walks	Entire Site	150	LF	6	10+ years				
							Combined quantities			
	Sidewalks - Perimeter Sidewalks	Entire Site			4					
	Sidewalks - Perimeter Sidewalks	Entire Site	20,770 200	SF SF	6	10+ years 0-1 year	Combined quantitie Cracking, damaged			

Campus Name: Otoole Page : 36 of 39 Assessment Date: 05/19/2022



Category : Site	В	Building : Site					
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Signage							
Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years		
Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years		
Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years		
Sign							

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Otoole Page: 37 of 39 Assessment Date: 05/19/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	2nd Floor	203	203	735	155	15	Υ	N
Kindergarten	Art Room	1st Floor	106	106	767	150	0	Υ	N
Kindergarten	Kindergarten	1st Floor	105	105	1,417	240	80	Y	N
Kindergarten	Regular Classroom	1st Floor	102	102	683	150	50	Y	Υ
Lunch Room	Regular Classroom	1st Floor	110	110	720	150	50	Y	N
Regular Classroom	Regular Classroom	1st Floor	100	100	735	150	50	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	730	150	50	Y	N
Regular Classroom	Regular Classroom	1st Floor	109	109	725	150	50	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201S	201S	670	155	15	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	735	155	15	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	735	155	15	Υ	N
Store Room	Regular Classroom	1st Floor	104	104	705	150	50	Υ	N
Store Room	Regular Classroom	1st Floor	113	-	468	76	25	Υ	N
Store Room	Regular Classroom	2nd Floor	201N	201N	540	74	3	Υ	N
	· · · · · ·	•			•				•
Building : Annex									
Store Room	Regular Classroom	1st Floor	106 - EC3		870	92	46	N	N
Vacant	Regular Classroom	1st Floor	100		434	92	46	N	N
Vacant	Regular Classroom	1st Floor	101 - K1		1,025	72	36	N	N
Vacant	Regular Classroom	1st Floor	102 - EC1		900	138	69	N	N
Vacant	Regular Classroom	1st Floor	103 - K2		1,135	48	24	N	N
Vacant	Regular Classroom	1st Floor	104 - EC2		1,066	160	80	N	N
Vacant	Regular Classroom	2nd Floor	200		435	92	46	N	N
Vacant	Regular Classroom	2nd Floor	201 - LE3		1,050	138	69	N	N
Vacant	Regular Classroom	2nd Floor	202 - LE1		1,000	115	58	N	N
Vacant	Regular Classroom	2nd Floor	203 - LE4		1,125	138	69	N	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Vacant	Regular Classroom	2nd Floor	204 - LE2		1,025	138	69	N	N
Vacant	Regular Classroom	2nd Floor	205		675	92	46	N	N

Campus Name: Otoole Page : 39 of 39 Assessment Date: 05/19/2022