

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1917 | 3 | 75,104 |
| Campus Total | | | 75,104 |

Category : Exterior Building : Main

| | y i =xionio: | | | uug | | Recommend | |
|---------|---------------------------------------|----------|----------|-----|------|-------------|---|
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ntrance | } | | | | | | |
| | Entrance Control - Audio | 1 | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 1 | 4 | EΑ | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 1 | 15 | LF | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 1 | 3 | LF | 5 | 0-1 year | Cracked/missing at corner of handrail. |
| | Power Door Operator and Controls | 1 | 1 | EΑ | 4 | 0-1 year | Does not work. |
| | Ramp Handrail - Steel_Ramp Handrail | 1 | 65 | LF | 7 | 10+ years | |
| | Ramps - Concrete | 1 | 25 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 1 | 5 | LF | 5 | 0-1 year | Cracking at end of ramp. |
| | Stair Handrail - Steel_Stair Handrail | 1 | 12 | LF | 7 | 10+ years | Paint |
| | Entrance Control - Audio and Video | 2 | 1 | EΑ | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 2 | 3 | EΑ | 6 | 10+ years | |
| | Exterior Doors - Side lite | 2 | 4 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 2 | 6 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 2 | 15 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 3 | 4 | EΑ | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 3 | 45 | LF | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 3 | 3 | LF | 5 | 0-1 year | Pieces missing to far left (when looking at doors) of stairs. |
| | Exterior Doors - Exterior Steel Door | 4 | 2 | EA | 6 | 10+ years | , |
| | Exterior Doors - Transom Lite | 4 | 2 | EΑ | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 5 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 5 | 1 | EΑ | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 5 | 6 | LF | 5 | 0-1 year | Cracking and chipping. |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------|---|---------------------------------|----------|---------|--------|------------------------|----------------------------------|
| | | | | | _ | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exterior Doors - Exterior Steel Door | Boiler Room Northwest | 1 | EΑ | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Boiler Room Northwest | 1 | EΑ | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Kitchen West | 1 | EA | 6 | 10+ years | |
| Foundati | on | | | | | | |
| | Foundation - Masonry | Entire Building | 848 | LF | 7 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 75,104 | SF | 6 | 10+ years | |
| | | | | | | | |
| _ighting | Exterior Lighting - Parapet or Roof Mounted | Entire Building | F | EA | 7 | 10 | |
| | Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted | Entire Building Entire Building | 5 7 | EA | 7 7 | 10+ years 10+ years | |
| | | | 1 | | | | Weather Wylneroble Deplese Long |
| | Exterior Lighting - Wall Mounted | Entire Building | 1 | EA | 5 | 0-1 year | Weather Vulnerable- Replace Lens |
| Roof Sys | stem | | | | | | |
| | Access Ladder - Metal | A | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | A | 292 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | A | 114 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | Α | 292 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | A | 4,343 | SF | 6 | 6-10 years | |
| | Roof Structure - Steel with Clay Tile Arch | Α | 4,343 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | В | 2 | EA | 7 | 10+ years | |
| | Access Ladder - Metal | В | 3 | EA | 5 | 2-5 years | |
| | Access Ladder - Metal | В | 1 | EΑ | 4 | 0-1 year | Not properly secured to wall. |
| | Coping - Stone | В | 872 | LF | 6 | 10+ years | . tot propony cocarea to train |
| | Downspouts - Interior Downspouts | В | 282 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | В | 872 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | В | 17,622 | SF | 5 | 2-5 years | Patching throughout. |
| | Roof Hatch - Metal | В | 3 | EA | 7 | 10+ years | r atoming throughout. |
| | Roof Structure - Steel with Clay Tile Arch | В | 17,622 | SF | 7 | 10+ years | |
| | Coping - Stone | C | 166 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | C | 60 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | C | 166 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | C | 3,658 | SF | 6 | 6-10 years | |
| | Roof Structure - Steel with Clay Tile Arch | C | 3,658 | SF | 7 | | |
| | | | | | | 10+ years | |
| | Chimney - Brick Chimney- Stainless Steel Liner | D | 55 | LF | 6 | 10+ years | |
| | Coping - Stone | D | 236 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | D | 24 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | D | 24 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | D | 236 | LF | 6 | 10+ years | |
| | Roof - Metal | D | 80 | SF | 5 | 0-1 year | Rusting with minor ponding. |
| | Roof - Modified Bitumen | D | 5,006 | SF | 5 | 6-10 years | 5 - 1 - 3 |
| | Roof Structure - Steel with Clay Tile Arch | D | 5,086 | SF | 7 | 10+ years | |



| | ory : Exterior | | B | uilding | : Main | | |
|---------|---|---|--|----------------------------------|---------------------------------|--|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Coping - Stone | E | 62 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | E | 24 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | E | 62 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | E | 240 | SF | 4 | 0-1 year | Dirt build up with minor vegetation growth developing. |
| | Roof Structure - Steel with Clay Tile Arch | Е | 240 | SF | 7 | 10+ years | growth developing. |
| Walls | | | | | | | |
| | Cornice - Metal Projecting | Entire Building | 718 | LF | 7 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 25,767 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 4,762 | SF | 6 | 10+ years | |
| Windows | S | | | | | | |
| | Guard - Guards perforated | Entire Building | 3,679 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 327 | LF | 6 | 10+ years | |
| | Lintels - Stone | Entire Building | 576 | LF | 6 | 10+ years | |
| | Skylite - Glass Single-Pane | Entire Building | 80 | SF | 4 | 0-1 year | Glass cracked. |
| | Windows - Decorative | Entire Building | 549 | SF | 6 | 10+ years | |
| | Windows - Insulated Panel | Entire Building | 64 | SF | 6 | 10+ years | |
| | Windows - Louver | Entire Building | 100 | SF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 8,205 | SF | 6 | 10+ years | |
| Catego | ory : Electrical | | В | uilding | : Main | | |
| Group | Hom. Time | Location | Overstitus | UOM | Rank | Recommend Replacement | Commonto |
| | Item - Type | Location | Quantity | UCIVI | Kalik | Replacement | Comments |
| | 0 | | | | | | |
| • | ncy System | Fating Desirations | 75.404 | 0.5 | • | 0.40 | |
| • | Security System - CCTV | Entire Building | 75,104 | SF | 6 | 6-10 years | |
| | Security System - CCTV Security System - Intrusion Detection | Entire Building | 75,104 | SF | 6 | 6-10 years | |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium | Entire Building Entire Building | 75,104 13 | SF EA | 6 2 | 6-10 years 0-1 year | No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs | Entire Building Entire Building Entire Building | 75,104 13 20 | SF EA EA | 6 2 2 | 6-10 years 0-1 year 0-1 year | No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym | Entire Building Entire Building Entire Building Entire Building | 75,104 13 20 2 | SF EA EA | 6 2 2 2 | 6-10 years 0-1 year 0-1 year 0-1 year | No batteries or AC generator No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and | Entire Building Entire Building Entire Building | 75,104 13 20 | SF EA EA | 6 2 2 | 6-10 years 0-1 year 0-1 year | No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym | Entire Building Entire Building Entire Building Entire Building | 75,104 13 20 2 | SF EA EA | 6 2 2 2 | 6-10 years 0-1 year 0-1 year 0-1 year | No batteries or AC generator No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 75,104 13 20 2 4,997 | SF EA EA EA SF | 6 2 2 2 6 | 6-10 years 0-1 year 0-1 year 0-1 year 6-10 years | No batteries or AC generator No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym | Entire Building | 75,104 13 20 2 4,997 16,336 | SF EA EA SF SF | 6 2 2 2 6 6 | 6-10 years 0-1 year 0-1 year 0-1 year 6-10 years 6-10 years | No batteries or AC generator No batteries or AC generator |
| • | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 75,104 13 20 2 4,997 | SF EA EA EA SF | 6 2 2 2 6 | 6-10 years 0-1 year 0-1 year 0-1 year 6-10 years | No batteries or AC generator No batteries or AC generator |
| | Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets | Entire Building | 75,104 13 20 2 4,997 16,336 2,777 2,274 | SF EA EA SF SF SF | 6 2 2 2 6 6 6 | 6-10 years 0-1 year 0-1 year 0-1 year 6-10 years 6-10 years 6-10 years | No batteries or AC generator No batteries or AC generator Building has EM panel |



| Catego | ry : Electrical | | В | uilding | : Main | | |
|--------------------------|---|--------------------------------------|---------------|------------------|-----------|---------------------------------|---|
| _ | | | | | | Recommend | |
| ∃roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| /lain Se | | | | | | | |
| | Main Electrical Service - 1600 A 120/208/3PH | Boiler Room | 1 | EA | 4 | 0-1 year | Older panel, rusted. |
| | PA System | Entire Building | 75,104 | SF | 5 | 2-5 years | Need occasional repair or replacement of speakers, function |
| | Independent Electrical Service for emergency power | Mechanical Room | 1 | EA | 6 | 10+ years | Second feed, no AC generator. |
| Power D | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 12 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 8 | EA | 6 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 2 | EΑ | 4 | 0-1 year | Previously not assessed, corroded |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 6 | 10+ years | Recently upgraded, functional |
| Catego | ry : Fire Protection | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ire Alaı | ·m | | | | | Ī | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 7 | 10+ years | Recently installed |
| | Fire Alarm Strobe Lights | Entire Building | 75,104 | SF | 6 | 6-10 years | Tested annually, functional |
| | Fire Alarm_System | Entire Building | 75,104 | SF | 6 | 10+ years | Recently installed fire alarm panel |
| C-4 | ry : Mechanical | Ü | | uilding | . Main | • | |
| | | | | unung | . IVIAIII | Recommend | |
| Jatego | ry : meenamear | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Group | Item - Type litioning | | Quantity | | Rank | • | Comments |
| Group | Item - Type | Location Lower Roof | Quantity 1 | UOM EA | Rank 6 | Replacement 6-10 years | Serves fan coil unit in kitchen |
| Group Air Cond | Item - Type ditioning Condensing Unit- Roof Mounted - Less | | • | | | • | |
| Group Air Cond | Item - Type ditioning Condensing Unit- Roof Mounted - Less than 5 tons | | • | | | • | Serves fan coil unit in kitchen For cooling only, served by condensing unit on roof, serves |
| Group Air Cond | Item - Type ditioning Condensing Unit- Roof Mounted - Less than 5 tons | Lower Roof | 1 | EA | 6 | 6-10 years | For cooling only, served by condensing unit on roof, serves kitchen. Serves classrooms. Deteriorated, requiring frequent maintenance, |
| Group Air Cond | Item - Type ditioning Condensing Unit- Roof Mounted - Less than 5 tons dling Systems Fan Coil Unit- Floor Mounted - Electric Air Handling Unit- Built Up-Multi Zone-Steam Coils - Greater than 35000 cfm | Lower Roof Kitchen Mechanical Room | 1 1 | EA EA | 6 4 | 6-10 years 6-10 years 1-2 years | For cooling only, served by condensing unit on roof, serves kitchen. Serves classrooms. Deteriorated, |
| Group Air Cond | Item - Type ditioning Condensing Unit- Roof Mounted - Less than 5 tons dling Systems Fan Coil Unit- Floor Mounted - Electric Air Handling Unit- Built Up-Multi Zone- | Lower Roof Kitchen | 1 | EA | 6 | 6-10 years 6-10 years | For cooling only, served by condensing unit on roof, serves kitchen. Serves classrooms. Deteriorated, requiring frequent maintenance, |



| Catego | Category : Mechanical | | В | uilding | : Main | | |
|----------|---|-----------------------|----------|---------|--------|-------------|--|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Zone Dampers | Mechanical Room | 17 | EA | 4 | 1-2 years | Manually adjusted, recently reconditioned |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm | South Mechanical Room | 1 | EA | 5 | 6-10 years | Serves south side of building |
| | Air Intake | South Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Auxiliaries - 25001 - 35000 cfm | South Mechanical Room | 1 | EA | 4 | 1-2 years | Frequent maintenance needed, functional |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | South Mechanical Room | 100 | LF | 5 | 1-2 years | Needs to be painted and ballanced, functional |
| | Zone Dampers | South Mechanical Room | 23 | EA | 4 | 1-2 years | Manually operated, with visible corrosion. Do not maintain temperature well, most are functional |
| Boiler S | ystems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 4 | 1-2 years | Leaks and corroded. |
| | Chemical Feed System | Boiler Room | 1 | EA | 5 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 5 | 6-10 years | |
| | Condensate Pump | Boiler Room | 2 | EA | 5 | 2-5 years | Cylindrical tank, recently repaired |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 5 | 6-10 years | , , , , |
| | Non Condensing - Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 5 | 1-2 years | Boiler periodically retubed, descaled, functional, refractory bricks need to be reconstructed. Corroded. |
| | Piping - Condensate Pipe- Steel | Boiler Room | 250 | LF | 5 | 6-10 years | 20.1000 |
| | Piping - Steam Pipe- Steel | Boiler Room | 250 | LF | 5 | 6-10 years | |
| | Steam Traps | Boiler Room | 23 | ĒA | 5 | 6-10 years | Steam traps periodically tested and adjusted |
| _Heating | Devices | | | | | | |
| | Wall Heater - Electric | 1st Floor | 1 | EA | 4 | 1-2 years | Deteriorated, not reliable, functional |
| | Radiators - Steam | Entire Building | 13 | EA | 5 | 1-2 years | Some have deteriorated paint, difficult to control temperature. |
| | Fin Tube - Steam | Entire Building | 48 | LF | 5 | 6-10 years | Functional, cleaned, leak repaired |
| | Unit Heater - Electric | Entire Building | 1 | EA | 7 | 6-10 years | Functional, cleaned |
| | Unit Heater - Gas | Entire Building | 1 | EΑ | 5 | 2-5 years | Functional, cleaned |
| | Unit Heater - Steam | Entire Building | 2 | EA | 5 | 2-5 years | Functional, cleaned |
| _Tempera | ature Control | | | | | | |
| | Electric Thermostat | Entire Building | 5 | EA | 5 | 6-10 years | Serves kitchen fan coil unit and 4 unit heaters, previously not assessed |
| | Pneumatic System | Entire Building | 75,104 | SF | 4 | 1-2 years | Does not function well, manually operated, leaks |
| | Thermostats - Pneumatic | Entire Building | 20 | EA | 5 | 2-5 years | Functional, calibration needed |
| | | | | | | | |

Campus Name: Parkside Page : 5 of 28 Assessment Date: 09/20/2021



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|------------|---|-----------------|----------|---------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Thermostats - Pneumatic | Entire Building | 20 | EA | 4 | 1-2 years | Leak, repair or replacement needed |
| | | | | | | | |
| Ventilatio | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 3 | EA | 6 | 6-10 years | Recently installed |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | Recently installed |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | 2, lower and upper roof |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 4 | 1-2 years | Noisy, deteriorated |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 2 | 0-1 year | Missing fire supression system |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| | _ | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | er | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Entire Building | 1 | EA | 4 | 1-2 years | Older than 15 years. |
| | Gas Heater - Less than 150000 BTU/HR | Entire Building | 1 | EA | 6 | 6-10 years | Serves kitchen |
| | Hot Water Storage Tank_Gas - Less than 200 Gallons | Entire Building | 1 | EA | 6 | 6-10 years | |
| Piping | | | | | | | |
| - 1 0 | Domestic Piping-Hot Water Return Lines | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old. Leaks occasionally repaired |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old. Leaks occasionally repaired |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old, leaks occasionally repaired |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old, corroded pipes. Leaks occasionally repaired |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old, leaks occasionally repaired |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 75,104 | SF | 4 | 2-5 years | More than 100 years old. Leaks occasionally repaired |
| | Sanitary Piping | Entire Building | 75,104 | SF | 5 | 6-10 years | Leaks repaired |
| | Storm Piping | Entire Building | 75,104 | SF | 5 | 6-10 years | Drain cleaned |
| | Vent Piping | Entire Building | 75,104 | SF | 5 | 6-10 years | |
| Pumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | Mechanical Room | 1 | EA | 5 | 6-10 years | |



| Catego | ry : Room | | В | uilding | : Main | | 56 S East Ellu AVENUE, Chicago, il 60049 |
|-----------|-----------------------------|------------------------------------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Administ | rative Suites/Offices | | | | | | |
| | AC Unit | 102A Office-Under Construction | 1 | EA | 7 | 6-10 years | Office was under construction during time of onsite and ranking to match that all items will be replaced. |
| | Ceiling - Plaster/Drywall | 102A Office-Under Construction | 320 | SF | 7 | 10+ years | Office was under construction during time of onsite and ranking to match that all items will be replaced. |
| | Doors - Transom Window | 102A Office-Under Construction | 10 | SF | 7 | 10+ years | Office was under construction during time of onsite and ranking to match that all items will be replaced. |
| | Doors - Wood Doors inclu hw | 102A Office-Under Construction | 1 | EA | 7 | 10+ years | · |
| | Floor - Tile | 102A Office-Under Construction | 320 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 102A Office-Under Construction | 5 | EA | 7 | 10+ years | |
| | Power Distribution | 102A Office-Under Construction | 10 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 102A Office-Under Construction | 976 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 307 Office | 550 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 307 Office | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 307 Office | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 307 Office | 550 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 307 Office | 7 | EA | 7 | 6-10 years | |
| | Power Distribution | 307 Office | 4 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 307 Office | 30 | SF | 7 | 10+ years | Walls repaired and repainted. |
| | Walls - Plaster/Drywall | 307 Office | 1,065 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 308A | 286 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 308A | 4 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 308A | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 308A | 286 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 308A | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 308A | 4 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 308A | 10 | SF | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 308A | 755 | SF | 6 | 10+ years | |
| | AC Unit | Engineer's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineer's Office | 123 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Engineer's Office | 123 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Engineer's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Engineer's Office | 6 | EA | 6 | 10+ years | |
| | Walls - Masonry | Engineer's Office | 185 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Engineer's Office | 185 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Kitchen Office -Under Construction | 87 | SF | 7 | 10+ years | Office was under construction during time of onsite and ranking to match that all items will be replaced. |
| | Doors - Transom Window | Kitchen Office -Under Construction | 24 | SF | 7 | 10+ years | Office was under construction during time of onsite and ranking to match |

Campus Name: Parkside Page: 7 of 28 Assessment Date: 09/20/2021



| atego | ry : Room | | В | uilding | : Main | | |
|----------|-----------------------------|------------------------------------|----------|---------|--------|-------------|----------------------------------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | that all items will be replaced. |
| | Doors - Wood Doors inclu hw | Kitchen Office -Under Construction | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Kitchen Office -Under Construction | 87 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen Office -Under Construction | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Kitchen Office -Under Construction | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Kitchen Office -Under Construction | 437 | SF | 7 | 10+ years | |
| | AC Unit | Main Office | 4 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Main Office | 883 | SF | 6 | 10+ years | |
| | Doors - Side-lite | Main Office | 14 | SF | 6 | 10+ years | |
| | Doors - Transom Window | Main Office | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Main Office | 3 | EA | 6 | 10+ years | |
| | Floor - Tile | Main Office | 883 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Main Office | 12 | EA | 7 | 6-10 years | |
| | Power Distribution | Main Office | 10 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | Main Office | 1,566 | SF | 6 | 10+ years | |
| | AC Unit | Principal's Office | 1 | ĒΑ | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Principal's Office | 183 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | Principal's Office | 183 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Principal's Office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | Principal's Office | 8 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | Principal's Office | 703 | SF | 6 | 10+ years | |
| | walle Flactor/Brywall | i inicipal e emee | | O. | Ü | ioi youro | |
| uditoriu | ım & Theater | | | | | | |
| | Balcony Seating | 1st Floor | 248 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 4,435 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 20 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 4,285 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 73 | ĒΑ | 7 | 6-10 years | |
| | Main Floor Seating | 1st Floor | 264 | EA | 7 | 10+ years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Stage Curtain | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Stage-Stairs - Asphalt | 1st Floor | 40 | LF | 6 | 10+ years | |
| | Stairs - Wood | 1st Floor | 24 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 8,428 | SF | 7 | 10+ years | |
| | Walls - Flastel/Drywall | 1St Floor | 0,420 | SI | , | 10+ years | |
| vmnas | ia | | | | | | |
| | AC Unit | 205A Gymnasium | 4 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 205A Gymnasium | 2,777 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 205A Gymnasium | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 205A Gymnasium | 4 | EA | 5 | 10+ years | |
| | Floor - Wood Boors med nw | 205A Gymnasium | 2,777 | SF | 6 | 10+ years | |
| | I IOOI VVOOG | 200A Gymnasiam | ۷,111 | Oi. | U | 10+ years | |

Campus Name: Parkside Page: 8 of 28 Assessment Date: 09/20/2021



| Catego | ry : Room | | В | uilding | : Main | | |
|----------------|---|----------------|----------|-----------|--------|------------------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Metal Halide/ High Pressure | 205A Gymnasium | 15 | EA | 6 | 10+ years | |
| | Sodium | | | | _ | | |
| | Walls - Plaster/Drywall | 205A Gymnasium | 5,107 | SF | 6 | 10+ years | |
| IV:talaaa | | | | | | | |
| <u>Kitchen</u> | Ceiling - Lay-in | Kitchen | 1,405 | SF | 5 | 6-10 years | |
| | Ceiling - Lay-in | Kitchen | 32 | SF | 4 | 0-10 years 0-1 year | Water damage. |
| | Doors - Steel Doors incl hw | Kitchen | 2 | EA | 6 | 10+ years | water damage. |
| | Doors - Wood Doors inclu hw | Kitchen | 2 | EA | 6 | • | |
| | Floor - Tile Quarry | | 1,437 | SF | 7 | 10+ years 10+ years | |
| | | Kitchen | | EA | 7 | | |
| | Lighting - Pendent/Surface Storage/ Closet | Kitchen | 21 | SF | | 10+ years | |
| | | Kitchen | 10 | | 7 | 10+ years | |
| | Walls - Concrete Block | Kitchen | 126 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Kitchen | 1,297 | SF | 7 | 10+ years | |
| Library | | | | | | | |
| • | AC Unit | 207 Library | 2 | EA | 7 | 6-10 years | |
| | Casework | 207 Library | 39 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 207 Library | 908 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 207 Library | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 207 Library | 908 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 207 Library | 14 | ĒΑ | 7 | 6-10 years | |
| | Storage/ Closet | 207 Library | 120 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 207 Library | 1,473 | SF | 7 | 10+ years | |
| MDF_ID | E | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Finishes | 2nd Floor | 325 | SF | 7 | 10+ years | |
| | Window AC Unit | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Window AC Unit | 2nd Floor | 1 | EA | 5 | 2-5 years | Not able to keep up with heat load in |
| | Wildow AC Offic | 2110 1 1001 | ' | LA | 3 | 2-5 years | this room. |
| | | | | | | | |
| _iviecnani | cal/ Service Rooms | 1et Floor | 105 | <u>сг</u> | | 2 5 1/2272 | |
| | Boiler Room | 1st Floor | 125 | SF SF | 5 | 2-5 years | |
| | Coal Room | 1st Floor | 666 | SF SF | 5 | 2-5 years | |
| | Janitor's Closet | 1st Floor | 13 | | 5 | 2-5 years | Deer is lasked |
| | Janitor's Closet | 1st Floor | 13 | SF | 5 | 2-5 years | Door is locked |
| | Mechanical/ Service Rooms | 1st Floor | 337 | SF | 7 | 10+ years | Deint available and a self- |
| | Mechanical/ Service Rooms | 1st Floor | 227 | SF | 5 | 6-10 years | Paint cracking and peeling throughout. |
| | Mechanical/ Service Rooms | 1st Floor | 256 | SF | 5 | 6-10 years | |
| | Mechanical/ Service Rooms | 1st Floor | 586 | SF | 5 | 6-10 years | Paint cracking and peeling |
| | | | | | | - | throughout. |
| | | | | | | | |



| atego | ry : Room | | В | uilding | : Main | | |
|---------|---------------------------------|--|----------|---------|--------|-------------|--|
| _ | | | | _ | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage Room | 1st Floor | 102 | SF | 7 | 10+ years | |
| | Vaults | 1st Floor | 260 | SF | 5 | 6-10 years | |
| | Janitor's Closet | 2nd Floor | 135 | SF | 5 | 2-5 years | Locked |
| | Janitor's Closet | 2nd Floor | 12 | SF | 4 | 0-1 year | Water damage to ceiling and walls |
| | Storage Room | 2nd Floor | 110 | SF | 7 | 10+ years | Locked |
| | Janitor's Closet | 3rd Floor | 12 | SF | 5 | 6-10 years | Flooring missing. |
| estroor | n | | | | | | |
| | Accessories | 1st Floor - Girl's Toilet Under Construction | 377 | SF | 7 | 6-10 years | Restroom under construction during time of assessment, items will be ranked as replaced. |
| | Ceiling - Plaster/Drywall | 1st Floor - Girl's Toilet Under Construction | 377 | SF | 7 | 10+ years | Restroom under construction durin time of assessment, items will be ranked as replaced. |
| | Doors - Wood Doors inclu hw | 1st Floor - Girl's Toilet Under Construction | 2 | EA | 7 | 10+ years | Restroom under construction durin time of assessment, items will be ranked as replaced. |
| | Floor - Tile | 1st Floor - Girl's Toilet Under Construction | 40 | SF | 7 | 10+ years | ramod do replaced. |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor - Girl's Toilet Under Construction | 337 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor - Girl's Toilet Under Construction | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor - Girl's Toilet Under Construction | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor - Girl's Toilet Under Construction | 6 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor - Girl's Toilet Under Construction | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - Girl's Toilet Under Construction | 558 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor - Girl's Toilet Under Construction | 558 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor - Girl's Toilet Under Construction | 8 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Boy's Restroom - Under Construction | 375 | SF | 7 | 6-10 years | Restroom under construction durir time of assessment, items will be ranked as replaced. |
| | Ceiling - Plaster/Drywall | 1st Floor Boy's Restroom - Under Construction | 375 | SF | 7 | 10+ years | Restroom under construction durir time of assessment, items will be ranked as replaced. |
| | Doors - Transom Window | 1st Floor Boy's Restroom - Under Construction | 40 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Boy's Restroom - Under | 2 | EA | 7 | 10+ years | Restroom under construction during |

Campus Name: Parkside Page : 10 of 28 Assessment Date: 09/20/2021



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|--|----------|---------|--------|-----------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Огоир | пош туро | Construction | Quantity | COM | Rank | Replacement | time of assessment, items will be ranked as replaced. |
| | Floor - Tile | 1st Floor Boy's Restroom - Under Construction | 40 | SF | 7 | 10+ years | is in the second |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boy's Restroom - Under Construction | 335 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Boy's Restroom - Under Construction | 2 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor Boy's Restroom - Under Construction | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Boy's Restroom - Under Construction | 6 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor Boy's Restroom - Under Construction | 2 | EA | 7 | 6-10 years | |
| | Urinals | 1st Floor Boy's Restroom - Under Construction | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor Boy's Restroom - Under Construction | 517 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor Boy's Restroom - Under Construction | 517 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Boy's Restroom - Under Construction | 2 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Teacher's Toilet - Boy's Restroom | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Teacher's Toilet - Boy's Restroom | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Teacher's Toilet - Boy's Restroom | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor Teacher's Toilet - Boy's Restroom | 30 | SF | 7 | 6-10 years | |
| | Lavatory | 1st Floor Teacher's Toilet - Boy's Restroom | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor Teacher's Toilet - Boy's Restroom | 1 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Teacher's Toilet - Boy's Restroom | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor Teacher's Toilet - Boy's Restroom | 200 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor Teacher's Toilet - Boy's Restroom | 1 | EA | 7 | 6-10 years | |
| | Accessories | 1st Floor Teacher's Toilet - Near Girl's RR | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Teacher's Toilet - Near Girl's RR | 30 | SF | 6 | 10+ years | |



| atego | ry : Room | | В | uilding | : Main | | |
|-------|---------------------------------|--|----------|----------|--------|------------------------|---|
| | | | | | _ | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 1st Floor Teacher's Toilet - Near Girl's RR | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor Teacher's Toilet - Near Girl's RR | 30 | SF | 7 | 10+ years | |
| | Lavatory | 1st Floor Teacher's Toilet - Near Girl's RR | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor Teacher's Toilet - Near Girl's RR | 1 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Teacher's Toilet - Near Girl's RR | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor Teacher's Toilet - Near Girl's RR | 200 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor Teacher's Toilet - Near Girl's RR | 1 | EA | 7 | 6-10 years | |
| | Accessories | 2nd Floor Boy's Restroom | 381 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boy's Restroom | 381 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor Boy's Restroom | 4 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Boy's Restroom | 3 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor Boy's Restroom | 6 | SF | 7 | 6-10 years | Repaired. |
| | Floor - Tile | 2nd Floor Boy's Restroom | 34 | SF | 6 | 6-10 years | Перапец. |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boy's Restroom | 141 | SF | 7 | 10+ years | Repaired. |
| | Floor - Tile Ceramic/ Porcelain | | 200 | SF | 6 | | Repaired. |
| | | 2nd Floor Boy's Restroom | | | | 10+ years | |
| | Floor Drain | 2nd Floor Boy's Restroom | 2 | EΑ | 7 | 10+ years | |
| | Lavatory | 2nd Floor Boy's Restroom | 2 | EΑ | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Boy's Restroom | 5 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Boy's Restroom | 2 | EΑ | 5 | 6-10 years | |
| | Urinals | 2nd Floor Boy's Restroom | 6 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Boy's Restroom | 444 | SF | 7 | 10+ years | No water damage or cracked tiles observed |
| | Walls - Structural Glazed Tile | 2nd Floor Boy's Restroom | 300 | SF | 5 | 2-5 years | |
| | Walls - Structural Glazed Tile | 2nd Floor Boy's Restroom | 144 | SF | 4 | 0-1 year | Missing. |
| | Water Closet | 2nd Floor Boy's Restroom | 2 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor Girl's Toilet | 379 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girl's Toilet | 100 | SF | 7 | 10+ years | No water damage observed |
| | Ceiling - Plaster/Drywall | 2nd Floor Girl's Toilet | 279 | SF | 7 | 10+ years | G |
| | Doors - Wood Doors inclu hw | 2nd Floor Girl's Toilet | 4 | EA | 5 | 2-5 years | |
| | Floor - Tile | 2nd Floor Girl's Toilet | 40 | SF | 6 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Girl's Toilet | 339 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor Girl's Toilet | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor Girl's Toilet | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Girl's Toilet | 6 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Girl's Toilet | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Girl's Toilet 2nd Floor Girl's Toilet | 6 494 | SF | 7 7 | 10+ years 10+ years | |
| | | | | SF SF | 7 | | |
| | Walls - Structural Glazed Tile | 2nd Floor Girl's Toilet | 494 | SF. | 1 | 10+ years | |



| atego | ry : Room | | В | uilding | : Main | | |
|-------|---------------------------------|---|----------|----------|--------|------------------------|-----------------------------------|
| | | | | | | Recommend | |
| oup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | 2nd Floor Girl's Toilet | 8 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor Men's Teacher Toilet | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Men's Teacher Toilet | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Men's Teacher Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor Men's Teacher Toilet | 30 | SF | 6 | 10+ years | |
| | Lavatory | 2nd Floor Men's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor Men's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Men's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor Men's Teacher Toilet | 221 | SF | 5 | 0-1 year | Small cracks, paint peeling and |
| | • | | | | | · | cracking throughout. |
| | Water Closet | 2nd Floor Men's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Accessories | 2nd Floor Women's Teacher Toilet | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Women's Teacher Toilet | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Women's Teacher Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor Women's Teacher Toilet | 30 | SF | 6 | 10+ years | |
| | Lavatory | 2nd Floor Women's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor Women's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Women's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor Women's Teacher Toilet | 200 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor Women's Teacher Toilet | 1 | EA | 7 | 6-10 years | |
| | Accessories | 3rd Floor Boy's Toilet | 381 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Boy's Toilet | 191 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Boy's Toilet | 190 | SF | 7 | 10+ years | Ceiling repaired |
| | Doors - Transom Window | 3rd Floor Boy's Toilet | 40 | SF | 6 | 10+ years | coming repaired |
| | Doors - Wood Doors inclu hw | 3rd Floor Boy's Toilet | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor Boy's Toilet | 41 | SF | 4 | 0-1 year | Separating and dirty around water |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor Boy's Toilet | 300 | SF | 7 | 10+ years | closets. |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor Boy's Toilet | 40 | SF | 4 | 0-1 year | Missing near lavatory |
| | Floor Drain | 3rd Floor Boy's Toilet | 2 | EA | 7 | 10+ years | missing floar lavatory |
| | Lavatory | 3rd Floor Boy's Toilet | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor Boy's Toilet | 6 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor Boy's Toilet | 2 | EA | 5 | 6-10 years | |
| | Urinals | 3rd Floor Boy's Toilet | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor Boy's Toilet 3rd Floor Boy's Toilet | 447 | SF | 6 | 10+ years 10+ years | |
| | | | | SF | | | Danairad |
| | Walls - Structural Glazed Tile | 3rd Floor Boy's Toilet | 2 | SF SF | 7 | 10+ years | Repaired. |
| | Walls - Structural Glazed Tile | 3rd Floor Boy's Toilet | 445 | | 6 | 10+ years | |
| | Water Closet | 3rd Floor Boy's Toilet | 2 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor Girl's Restroom | 381 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Girl's Restroom | 381 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor Girl's Restroom | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor Girl's Restroom | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor Girl's Restroom | 42 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor Girl's Restroom | 339 | SF | 6 | 10+ years | |

Campus Name: Parkside Page: 13 of 28 Assessment Date: 09/20/2021



| Catego | ry : Room | | В | uilding | : Main | | · • • · |
|--------|--------------------------------|--|----------|---------|--------|-------------|-----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor Drain | 3rd Floor Girl's Restroom | 1 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor Girl's Restroom | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor Girl's Restroom | 6 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor Girl's Restroom | 8 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor Girl's Restroom | 437 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor Girl's Restroom | 437 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor Girl's Restroom | 8 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor Teacher's Toilet Near Boy's RR | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Teacher's Toilet Near Boy's RR | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor Teacher's Toilet Near Boy's RR | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor Teacher's Toilet Near Boy's RR | 30 | SF | 6 | 10+ years | |
| | Lavatory | 3rd Floor Teacher's Toilet Near Boy's RR | 1 | EA | 7 | 10+ years | Repaired. |
| | Lighting - Pendent/Surface | 3rd Floor Teacher's Toilet Near Boy's RR | 1 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor Teacher's Toilet Near Boy's RR | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor Teacher's Toilet Near Boy's RR | 221 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor Teacher's Toilet Near Boy's RR | 1 | EA | 7 | 10+ years | Repaired. |
| | Accessories | 3rd Floor Teacher's Toilet Near Girl's RR | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Teacher's Toilet Near Girl's RR | 30 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | SF | 6 | 10+ years | |
| | Lavatory | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | EA | 7 | 10+ years | Repaired. |
| | Lighting - Pendent/Surface | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | EA | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor Teacher's Toilet Near Girl's RR | 200 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor Teacher's Toilet Near Girl's RR | 1 | EA | 7 | 10+ years | Repaired. |
| | Accessories | Kitchen's Toilet | 30 | SF | 7 | 6-10 years | |



| Catego | ry : Room | В | uilding | : Main | | | |
|--------|---------------------------------|--------------------|----------|--------|------|-------------|----------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | Kitchen's Toilet | 74 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Kitchen's Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Kitchen's Toilet | 50 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Kitchen's Toilet | 24 | SF | 4 | 0-1 year | Cracked tiles. |
| | Lavatory | Kitchen's Toilet | 1 | EA | 7 | 6-10 years | Repaired. |
| | Lighting - Pendent/Surface | Kitchen's Toilet | 1 | EA | 7 | 6-10 years | |
| | Partitions | Kitchen's Toilet | 2 | EΑ | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | Kitchen's Toilet | 323 | SF | 6 | 10+ years | |
| | Water Closet | Kitchen's Toilet | 2 | EΑ | 7 | 10+ years | Repaired. |
| | Accessories | Principal's Toilet | 55 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Principal's Toilet | 55 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Principal's Toilet | 55 | SF | 6 | 10+ years | |
| | Lavatory | Principal's Toilet | 1 | EΑ | 7 | 10+ years | Repaired. |
| | Lighting - Pendent/Surface | Principal's Toilet | 1 | EΑ | 7 | 6-10 years | |
| | Partitions | Principal's Toilet | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Principal's Toilet | 290 | SF | 6 | 10+ years | |
| | Water Closet | Principal's Toilet | 1 | EA | 7 | 10+ years | Repaired. |

Category : Classroom **Building: Main**

| Graun | Itom Type | Location | Quantity | ПОМ | Donk | Recommend | Comments |
|-----------|-----------------------------|-----------|----------|-----|------|-------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Classroo | om #101 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 787 | SF | 6 | 10+ years | Paint cracking and peeling throughout. |
| | Chalk Board | 1st Floor | 5 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 807 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 46 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 20 | SF | 7 | 10+ years | Prior rank updated to match current observation- No water damage observed. |
| | Walls - Plaster/Drywall | 1st Floor | 1,492 | SF | 6 | 10+ years | |
| Classroo | om #102 (Art Room) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | This classroom was under construction during the site visit and ranks will be based on newer installation. |

Campus Name: Parkside Page : 15 of 28 Assessment Date: 09/20/2021



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Ceiling - Plaster/Drywall | 1st Floor | 907 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 5 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 7 | 10+ years | Under Construction |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 7 | 10+ years | Under construction |
| | Floor - Tile | 1st Floor | 907 | SF | 7 | 6-10 years | Under construction |
| | Lighting - Pendent/Surface | 1st Floor | 14 | ĒΑ | 7 | 10+ years | Under construction |
| | Marker Board | 1st Floor | 15 | LF | 7 | 6-10 years | Under construction |
| | Walls - Plaster/Drywall | 1st Floor | 1,573 | SF | 7 | 10+ years | Under construction |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | Under construction |
| Classroc | om #103 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 809 | SF | 5 | 0-1 year | Paint patches, cracking, and paint peeling/chipping throughout. |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | 10+ years | h |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 809 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,494 | SF | 6 | 10+ years | Minor paint peeling. |
| Classroo | om #105 (Pre School) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 61 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,306 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,306 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | ĒΑ | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 60 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,859 | SF | 6 | 10+ years | |
| Classroc | om #106 (Office) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 6 | LF | 5 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 806 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 17 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 806 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | ĒΑ | 6 | 10+ years | |
| | Marker Board | 1st Floor | 23 | LF | 6 | , | |

Campus Name: Parkside Page : 16 of 28 Assessment Date: 09/20/2021



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|-----------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage/ Closet | 1st Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,463 | SF | 6 | 10+ years | |
| Classroo | m #107 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 806 | SF | 6 | 10+ years | Paint chipping and peeling. |
| | Chalk Board | 1st Floor | 14 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 806 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 77 | SF | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,169 | SF | 6 | 10+ years | Paint chipping and peeling. |
| Classroo | m #109 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 804 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 804 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 40 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 71 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,508 | SF | 6 | 10+ years | |
| Classroo | m #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 805 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 805 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 23 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 20 | SF | 7 | 10+ years | No drywall damage observed |
| | Walls - Plaster/Drywall | 2nd Floor | 1,148 | SF | 6 | 10+ years | . ,g |
| Classroo | m #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | 50 0 Last End AVENUE, Officago, IE 00043 |
|----------|-----------------------------|------------------------|----------|----------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 2nd Floor | 9 | LF | 5 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 806 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 806 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,396 | SF | 6 | 10+ years | |
| Classroo | om #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 807 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 10 | EA | 6 | 10+ years | |
| | Floor - Wood Books inclu hw | 2nd Floor | 807 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 23 | LF | 6 | , | |
| | Storage/ Closet | 2nd Floor 2nd Floor | | SF | 5 | 6-10 years | |
| | | 2nd Floor 2nd Floor | 77 | SF SF | 5 6 | 10+ years | |
| | Walls - Plaster/Drywall | 211d F1001 | 1,170 | SF | 0 | 10+ years | |
| Classroo | om #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| | Casework | 2nd Floor | 46 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 978 | SF | 7 | 10+ years | Repaired. |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 978 | SF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 6 | 10+ years | |
| | Storage/ Closet | 2nd Floor | 78 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 400 | SF | 7 | 10+ years | No damaged walls observed |
| | Walls - Plaster/Drywall | 2nd Floor | 1,092 | SF | 6 | 10+ years | S |
| Classroo | om #205 (Office) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 550 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 535 | SF | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 15 | SF | 4 | 0-1 year | Cracked/chipped. |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | EA | 7 | 10+ years | C. action, of hippod. |
| | Lighting I chachivounde | 2110 1 1001 | O | LA | • | TOT years | |
| | | | | | | | |



| Catego | ory : Classroom | | В | uilding | : Main | | 50 0 Last Ella Avelvoe, Ollicago, le 00045 |
|---------|-----------------------------|-------------|----------|---------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | 2nd Floor | 1,134 | SF | 7 | 10+ years | |
| Classro | om #206 (Office) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 46 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 978 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | ĒΑ | 5 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 978 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | ĒΑ | 6 | 10+ years | |
| | Storage/ Closet | 2nd Floor | 78 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,492 | SF | 6 | 10+ years | |
| Classro | om #208 (Music Room) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 806 | SF | 6 | 10+ years | No water damage observed, ceiling |
| | coming induction bry wan | 2.10 1.1001 | | | ŭ | .o. youro | paint is cracking and peeling. |
| | Chalk Board | 2nd Floor | 32 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 806 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 23 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,380 | SF | 6 | 10+ years | |
| Classro | om #209 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 808 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 808 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 17 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,382 | SF | 5 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classro | om #301 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Casework | 3rd Floor | 9 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 40 | SF | 7 | 10+ years | Ceiling has been repaired and |
| | - | | | | | - | - |

Campus Name: Parkside Page : 19 of 28 Assessment Date: 09/20/2021



| aiegu | ry : Classroom | | В | uilding | : Main | | |
|--------|---|---|--|--|--|--|--|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | painted |
| | Ceiling - Plaster/Drywall | 3rd Floor | 785 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 825 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 46 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 77 | SF | 7 | 10+ years | Repaired. |
| | Walls - Plaster/Drywall | 3rd Floor | 1,223 | SF | 6 | 10+ years | • |
| assro | om #302 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 908 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 908 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,100 | SF | 7 | • | |
| | walls - Flasiel/Divwall | 314 F1001 | 1,100 | | 1 | 10+ years | |
| | | Oud Flags | 400 | CE | 7 | 10 | Damasus usas unitedant base base |
| | Walls - Plaster/Drywall | 3rd Floor | 128 | SF | 7 | 10+ years | Damage near window has been repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) | | | | | • | |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework | 3rd Floor 3rd Floor | 1 9 | EA LF | 7 6 | 6-10 years 10+ years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall | 3rd Floor 3rd Floor 3rd Floor | 1 9 820 | EA LF SF | 7 6 6 | 6-10 years 10+ years 10+ years | |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window | 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 9 820 10 | EA LF SF SF | 7 6 6 6 | 6-10 years 10+ years 10+ years 10+ years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 9 820 10 1 | EA LF SF SF EA | 7 6 6 6 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 9 820 10 1 820 | EA LF SF SF EA SF | 7 6 6 6 6 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 9 820 10 1 820 14 | EA LF SF SF EA SF EA | 7 6 6 6 6 6 7 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board | 3rd Floor | 1 9 820 10 1 820 14 46 | EA LF SF SF EA SF EA LF | 7 6 6 6 6 6 7 7 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years | repaired and painted. |
| assroo | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 9 820 10 1 820 14 46 77 | EA LF SF SF EA SF EA LF SF | 7 6 6 6 6 6 7 7 5 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years | repaired and painted. |
| assroo | Walls - Plaster/Drywall om #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board | 3rd Floor | 1 9 820 10 1 820 14 46 | EA LF SF SF EA SF EA LF | 7 6 6 6 6 6 7 7 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years | repaired and painted. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall | 3rd Floor | 1 9 820 10 1 820 14 46 77 | EA LF SF SF EA LF SF SF | 7 6 6 6 6 6 7 7 5 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years | repaired and painted. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #304 (Regular Classroom) Casework | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF EA SF EA LF SF SF | 7 6 6 6 6 6 7 7 5 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years | repaired and painted. Repaired. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #304 (Regular Classroom) Casework Ceiling - Plaster/Drywall | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF SF EA LF SF SF | 7 6 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years | repaired and painted. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #304 (Regular Classroom) Casework | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF EA SF EA LF SF SF | 7 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years | repaired and painted. Repaired. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #304 (Regular Classroom) Casework Ceiling - Plaster/Drywall | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF SF EA LF SF SF | 7 6 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years | repaired and painted. Repaired. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF EA SF EA LF SF SF SF | 7 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years | repaired and painted. Repaired. |
| | Walls - Plaster/Drywall m #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #304 (Regular Classroom) Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF EA SF EA LF SF SF SF | 7 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | repaired and painted. Repaired. Ceiling repaired |
| | Walls - Plaster/Drywall Dom #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall Dom #304 (Regular Classroom) Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile | 3rd Floor | 9 820 10 1 820 14 46 77 1,219 9 50 848 10 1 | EA LF SF EA SF EA LF SF SF SF SF SF | 7 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years | repaired and painted. Repaired. |
| | Walls - Plaster/Drywall Dom #303 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall Dom #304 (Regular Classroom) Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw | 3rd Floor | 1 9 820 10 1 820 14 46 77 1,219 | EA LF SF EA SF EA LF SF SF SF | 7 6 6 6 6 7 7 5 6 | 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | repaired and painted. Repaired. Ceiling repaired |

Campus Name: Parkside Page : 20 of 28 Assessment Date: 09/20/2021



| Catego | ry : Classroom | | В | uilding | : Main | | • |
|----------|-----------------------------|------------------------|----------|------------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 20 | SF | 7 | 10+ years | Repaired. |
| | Walls - Plaster/Drywall | 3rd Floor | 1,200 | SF | 6 | 10+ years | |
| Classroc | om #305 (Store Room) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 555 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 500 | SF | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 55 | SF | 4 | 0-1 year | Chipping. |
| | Lighting - Pendent/Surface | 3rd Floor | 7 | EA | 7 | 6-10 years | 11 3 |
| | Marker Board | 3rd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,100 | SF | 6 | 10+ years | |
| Classroo | om #306 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 16 | SF | 6 | 10+ years | Ceiling patched, needs repainting. |
| | Ceiling - Plaster/Drywall | 3rd Floor | 800 | SF | 6 | 10+ years | Coming patorioa, ricodo ropairiting. |
| | Chalk Board | 3rd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 10 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 816 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 78 | SF | 5 | 2-5 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,215 | SF | 6 | 10+ years | |
| Classroo | om #308 (Regular Classroom) | | | | | | |
| <u> </u> | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 562 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 10 | EA | 6 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 562 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | o 24 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor 3rd Floor | | SF | | | |
| | | | 56 | SF SF | 5 6 | 2-5 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,030 | 3 F | О | 10+ years | |
| Classroc | nm #309 (Computer Lab) | 0.15 | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Casework | 3rd Floor | 9 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 28 | SF | 7 | 10+ years | Ceiling has been patched, repaired and painted. |

Campus Name: Parkside Page : 21 of 28 Assessment Date: 09/20/2021



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|---------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 3rd Floor | 800 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 17 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 828 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 60 | SF | 7 | 10+ years | |
| | Storage/ Closet | 3rd Floor | 17 | SF | 5 | 2-5 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 50 | SF | 7 | 10+ years | Walls have been repaired and painted. |
| | Walls - Plaster/Drywall | 3rd Floor | 1,176 | SF | 7 | 10+ years | • |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #310 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 18 | SF | 6 | 10+ years | Repaired, paint cracking and peeling. |
| | Ceiling - Plaster/Drywall | 3rd Floor | 800 | SF | 6 | 10+ years | Paint chipping and peeling. |
| | Chalk Board | 3rd Floor | 39 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 800 | SF | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 18 | SF | 4 | 0-1 year | Chipping. |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 77 | SF | 5 | 2-5 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,217 | SF | 6 | 10+ years | |
| Classroo | om #311 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 9 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 828 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 40 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 828 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 71 | SF | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 35 | SF | 7 | 10+ years | Painted. |
| | Walls - Plaster/Drywall | 3rd Floor | 1,250 | SF | 7 | 10+ years | |

Campus Name: Parkside Page : 22 of 28 Assessment Date: 09/20/2021



| Category : Classroom | | Building : Main | | | | 56 5 East End AVENUE, Chicago, it 600 | |
|----------------------|--------------------------------------|--|---------------|-----------------|----------|---|-------------------------------|
| | | | _ | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| lassroo | om #312 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 894 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 878 | SF | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 16 | SF | 4 | 0-1 year | Chipped. |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | ĒΑ | 7 | 6-10 years | 5PF 5.0. |
| | Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,215 | SF | 6 | 10+ years | |
| | | | ., | | | , | |
| Classroo | om #314 (Science Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 20 | SF | 7 | 10+ years | Ceiling has been repaired and |
| | , | | | | | | repainted. |
| | Ceiling - Plaster/Drywall | 3rd Floor | 885 | SF | 6 | 10+ years | • |
| | Chalk Board | 3rd Floor | 45 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 905 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | ĒΑ | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 50 | SF | 7 | 10+ years | Walls have been repaired and |
| | | | | - | | , | repainted. |
| | Walls - Plaster/Drywall | 3rd Floor | 1,175 | SF | 6 | 10+ years | |
| 2-4 | mar Interior | | 5 | : 1 - 1 : | . 84 - : | | |
| Catego | ry : Interior | | D | Building : Main | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | - | | , | | | | |
| 20111001 | Ceiling - Plaster/Drywall | 1st Floor | 4,966 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 11 | ĒΑ | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 108 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | 1st Floor | 14 | EA | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 1st Floor | 4,751 | SF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 39 | EA | 7 | 6-10 years | |
| | Stairs - Concrete Stairs | 1st Floor | 136 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 7,132 | SF | 6 | 10+ years | |
| | | | 7,102 | | | | |
| | | 1st Floor West | 715 | SF | h | 1()+ Vears | |
| | Ceiling - Plaster/Drywall | 1st Floor West | 715 2 | SF FA | 6 6 | 10+ years | |
| | | 1st Floor West 1st Floor West 1st Floor West | 715 2 2 | SF EA EA | 6 6 | 10+ years 10+ years 10+ years | |



| Category : Interior | | | В | uilding | : Main | | - |
|---------------------|--------------------------------------|---------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Asphalt Floor | 1st Floor West | 126 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor West | 589 | SF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor West | 6 | EA | 7 | 6-10 years | |
| | Stairs - Concrete Stairs | 1st Floor West | 22 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor West | 2,359 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 3,786 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 2nd Floor | 3,786 | SF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 32 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 6,190 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 3,786 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 3rd Floor | 4 | EΑ | 7 | 6-10 years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 3,786 | SF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 32 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 6,672 | SF | 6 | 10+ years | |
| | • | | | | | - | |
| Safety | | | | | | | |
| | Camera Viewing Station | Throughout Building | 3 | EΑ | 7 | 6-10 years | |
| | Metal Dedector | Throughout Building | 1 | EA | 7 | 6-10 years | |
| | Security Cameras | Throughout Building | 16 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| Oldilo | Ceiling - Plaster/Drywall | North | 606 | SF | 6 | 10+ years | |
| | Floor - Asphalt | North | 254 | SF | 7 | 10+ years | |
| | Floor - Tile | North | 616 | SF | 6 | 10+ years | |
| | Handrails | North | 140 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | North | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | North | 6 | EΑ | 7 | 6-10 years | |
| | Lighting - Wall Mounted | North | 1 | EA | 7 | 6-10 years | |
| | Stairs - Asphalt | North | 402 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | North | 2,997 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | North West | 739 | SF | 6 | 10+ years | |
| | Floor - Tile | North West | 618 | SF | 7 | 10+ years | |
| | Handrails | North West | 92 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | North West | 8 | EA | 7 | 6-10 years | |
| | Stairs - Asphalt | North West | 228 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | North West | 2,195 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | South | 606 | SF | 6 | 10+ years | |
| | Floor - Asphalt | South | 254 | SF | 7 | 10+ years | |
| | Floor - Tile | South | 616 | SF | 6 | 10+ years | |
| | Handrails | South | 140 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | South | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | South | 6 | EA | 7 | 6-10 years | |
| | | 2.2 | · · | | • | 3 . 0 , 0 | |



| Category : Interior | | | Building : Main | | | | | | |
|---------------------|----------------------------|------------|-----------------|-----|------|-------------|----------|--|--|
| | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Lighting - Wall Mounted | South | 1 | EΑ | 7 | 6-10 years | | | |
| | Stairs - Asphalt | South | 402 | LF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | South | 2,997 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | South West | 739 | SF | 6 | 10+ years | | | |
| | Floor - Tile | South West | 618 | SF | 6 | 10+ years | | | |
| | Handrails | South West | 92 | LF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | South West | 10 | EA | 7 | 6-10 years | | | |
| | Stairs - Asphalt | South West | 228 | LF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | South West | 2,195 | SF | 6 | 10+ years | | | |

Campus Name: Parkside Page : 25 of 28 Assessment Date: 09/20/2021





Category: Site **Building: Site**

| Catego | ry . Site | | <u>D</u> | ullaing | Site | | |
|------------|---|-------------|----------|---------|------|---------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Civil/Drai | inage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 7 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Catch Basin | Entire Site | 1 | EA | 4 | 0-1 year | Compounded by dumpster weight. |
| | Civil/ Drainage - Site Manhole | Entire Site | 7 | EA | 6 | 10+ years | Compounded by dumpster weight. |
| | Civily Brainage Cite Manifold | Littire one | , | | J | 101 years | |
| Fencing | | | | | | | |
| | Fencing - New Standard Ornamental | Entire Site | 1,418 | LF | 6 | 6-10 years | Paint chipping and peeling throughout. |
| | Fencing - Old Standard Ornamental | Entire Site | 77 | LF | 4 | 0-1 year | Bent. |
| Landsca | oe . | | | | | | |
| | Landscape - Grass | Entire Site | 6,240 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 21,753 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 200 | SF | 4 | 0-1 year | Cracking and pieces missing. |
| | Parkway trees | Entire Site | 25 | EA | 7 | 10+ years | eraciming and process innouning. |
| | Parkway trees | Entire Site | 2 | ΕA | 4 | 0-1 year | Missing from planters in parkway. |
| | Planting Beds/ Area | Entire Site | 1,650 | SF | 6 | 6-10 years | g piae.e paay. |
| | Play Area - Hardscape- Asphalt | Entire Site | 7,241 | SF | 6 | 6-10 years | Paint fading. |
| | Trash Receptacles | Entire Site | 2 | EA | 6 | 6-10 years | r ann raamg. |
| | Walking Path - Hardscape- Asphalt | Entire Site | 2,560 | SF | 6 | 10+ years | |
| Parking I | ot | | | | | | |
| _ armig_ | Concrete Curbs | North | 470 | LF | 4 | 0-1 year | Cracking, pieces missing, and mulch falling out. |
| | Interior Plantings | North | 10 | LF | 7 | 10+ years | iaming out |
| | Surface - Asphalt | North | 2,184 | SF | 4 | 0-1 year | Cracking and potholes. |
| | Surface - Asphalt | North | 17,985 | SF | 4 | 0-1 year | Cracking with vegetation growth. |
| | Trash Enclosure - Chain Links | North | 960 | SF | 6 | 10+ years | Vegetation growth. |
| | Vehicular Screening | North | 39 | LF | 6 | 10+ years | vegetation growth. |
| Discourse | | | | | | | |
| Playgrou | | O | 4 | | | 0.4 | Danie wed allide |
| | Equipment - School Age 5-12 | South | 1 | EA | 5 | 0-1 year | Damaged slide. |
| | Surface - Square Rubber Mats | South | 2,303 | SF | 4 | 0-1 year | Gaps in mats, vegetation growth. |
| Sidewalk | s | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 300 | LF | 4 | 0-1 year | Cracking and uneven. |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 12,705 | SF | 7 | 10+ years | - |
| Signage | | | | | | | |
| g-11190 | Flag Pole - Building Mounted Flag Pole | East | 1 | EA | 7 | 10+ years | |
| | Marquee - Free Standing Back lighted w/ | East | 1 | EA | 6 | 10+ years | |
| | a. qaaa i raa atanang baak nginta w | | • | | Ŭ | , , , , , , , | |

Campus Name: Parkside Page : 26 of 28 Assessment Date: 09/20/2021



Parkside Elementary Community Academy

6938 S East End AVENUE, Chicago, IL 60649

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

LED

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Parkside Page: 27 of 28 Assessment Date: 09/20/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|-------------------|-------------------|---------------|--------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | · | | • | | | | | |
| Art Room | Regular Classroom | 1st Floor | 102 | 102 | 907 | 182 | 86 | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 209 | 209 | 885 | 162 | 84 | N | N |
| Computer Lab | Regular Classroom | 3rd Floor | 309 | 309 | 905 | 162 | 84 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 101 | 101 | 884 | 162 | 84 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 109 | 109 | 875 | 162 | 84 | N | N |
| Music Room | Regular Classroom | 2nd Floor | 208 | 208 | 883 | 162 | 84 | N | N |
| Office | Office | 2nd Floor | 205 | 205 | 550 | 54 | 28 | N | N |
| Office | Regular Classroom | 1st Floor | 106 | 106 | 883 | 162 | 84 | N | N |
| Office | Store Room | 2nd Floor | 206 | 206 | 1,056 | 189 | 42 | N | N |
| Pre School | Library | 1st Floor | 105 | 105 | 1,366 | 120 | 60 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 886 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 883 | 162 | 84 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 882 | 162 | 84 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 883 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 884 | 162 | 84 | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 1,056 | 189 | 42 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 902 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 908 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 897 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 898 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 894 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 618 | 108 | 24 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | 310 | 895 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 311 | 311 | 899 | 162 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 312 | 312 | 894 | 162 | 84 | Υ | N |
| Science Classroom | Regular Classroom | 3rd Floor | 314 | 314 | 905 | 162 | 84 | N | N |
| Store Room | Office | 3rd Floor | 305 | 305 | 555 | 54 | 28 | N | N |