

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1962	1	43,063
Modular 1 (4-Classroom)	2003	1	4,947
Campus Total			48,010

Category : Exterior Building : Main
Recommend

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	<u> </u>		<u> </u>				
	Entrance Control - Audio and Video	#1 - Main - S	1	EA	6	6-10 years	Enclosure/Protective cabinet in Failed state. Rust/Corrosion. From what I could visibly surmise The audio/video deal looks fine
	Exterior Doors - Side lite	#1 - Main - S	6	EΑ	6	10+ years	
	Exterior Doors - Store Front	#1 - Main - S	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - S	7	EA	6	10+ years	
	Exterior Doors - Store Front	#11 - Courtyard North	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11 - Courtyard North	1	EΑ	6	10+ years	
	Exterior Doors - Store Front	#12 - courtyard, S door	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#12 - courtyard, S door	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 - SE	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#2 - SE	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#2 - SE	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - E	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#3 - E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - E	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4 - NE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - NE	1	EA	6	10+ years	
	Ramps - Concrete	#4 - NE	3	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5 - NE	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - NE	18	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5 - NE	6	LF	5	10+ years	



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior FRP Door	#6 - NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - NE	18	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#6 - NE	3	LF	6	10+ years	
	Ramps - Steel or Aluminum	#6 - NE	5	LF	6	2-5 years	Rust/Corrosion
	Exterior Doors - Exterior FRP Door	#7 - SW	2	EA	6	10+ years	
	Exterior Doors - Side lite	#7 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - SW	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#7 - SW	8	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	#8 - NW	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	#8 - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 - NW	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - NW	8	LF	6	10+ years	
oundati	ion						
	Foundation - Concrete	Entire Building	1,059	LF	7	10+ years	
	Superstructure - Steel	Entire Building	43,063	SF	7	10+ years	
ghting							
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
oof Sys	stem						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	18	LF	6	10+ years	
	Coping - Metal	Main Roof	729	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	131	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	27,947	SF	5	2-5 years	Cracks/soft Spots -
			,			,	deterioration/detachment from substrate
	Roof Hatch - Metal	Main Roof	1	EA	5	6-10 years	Substrate
	Roof Structure - Steel / Metal Deck/	Main Roof	27,947	SF	7	10+ years	
	Concrete Topping		,		-	•	
	Coping - Metal	South Courtyard	56	LF	6	6-10 years	
	Downspouts - Interior Downspouts	South Courtyard	15	LF	6	6-10 years	
	Roof - Modified Bitumen	South Courtyard	784	SF	5	2-5 years	Bubbling deterioration/detachment from substrate in spots
	Roof Structure - Steel / Metal Deck/ Concrete Topping	South Courtyard	784	SF	7	6-10 years	nom outsitute in spote
	Access Ladder - Metal	Upper E roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Upper E roof	31	LF	6	10+ years	
	Chimney - Metal Flue	Upper E roof	31	LF	6	10+ years	
	Chimney - Metal Flue	Upper E roof	28	LF	6	10+ years	
	Coping - Metal	Upper E roof	729	LF	6	10+ years	
				LF LF	6		
	Downspouts - Interior Downspouts	Upper E roof	72	ᄕ	Ю	10+ years	

Campus Name: Pirie Page : 2 of 27 Assessment Date: 03/09/2022



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
·	Roof - Modified Bitumen	Upper E roof	8,244	SF	5	2-5 years	Bubbling/soft Spots - deterioration/detachment from substrate in spots
	Roof Hatch - Metal	Upper E roof	1	EA	7	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper E roof	8,244	SF	7	10+ years	
	Coping - Metal	Upper W roof	339	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper W roof	40	LF	6	10+ years	
	Roof - Modified Bitumen	Upper W roof	6,872	SF	5	2-5 years	Cracks and soft Spots - deterioration/detachment from substrate in spots. Tree drip line over hanging roof
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper W roof	6,872	SF	7	10+ years	
Walls							
	Cornice - Metal Projecting	Entire Building	2,252	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	13,883	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	105	SF	5	2-5 years	Joints are receding but not "open joints" found
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	238	SF	6	10+ years	•
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	238	SF	5	10+ years	
Windows							
	Clerestory - Glass Double-Pane	Entire Building	850	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	456	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	1,035	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	42	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,248	SF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	2,952	SF	6	10+ years	
Catego	ry : Electrical		R	uilding	· Main		
Calego	iy. Licoti loai			unung	. Maiii	Decemmend	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	Emergency Battery Packs - Corridors and Stairs	1st Floor	13	EA	6	6-10 years	
	Emergency Battery Packs - Gym	1st Floor	4	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	1st Floor	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	12	EA	2	0-1 year	No batteries, no AC generator



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Gym	1st Floor	4	EA	2	0-1 year	No battery, no AC generator
	Exit Signs - Lunchroom	1st Floor	2	EA	2	0-1 year	No batteries, no AC generator
	Automatic Transfer Switch	Boiler Room	1	EA	6	10+ years	Functional
	Emergency A/C Power - Corridors and	Entire Building	7,046	SF	6	6-10 years	Building has EM panel
	Stairs	· ·				-	
	Emergency A/C Power - Gym	Entire Building	4,352	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,200	SF	6	6-10 years	Previously not assessed
	Security System - CCTV	Entire Building	43,063	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	43,063	SF	5	6-10 years	
ain Se	rvice						
	PA System	1st Floor	43,063	SF	5	6-10 years	Connected to modular building,
							functional
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves main building
	Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	Meter and ATS
	emergency power	Electrical Noom	·	LA	U	10+ years	Weter and ATO
ower D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
		<u> </u>				•	Functional nanela rate d7
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	10+ years	Functional panels rated7
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	Functional panels rated 7
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
re Alar	m						
	Fire Alarm Panel	Boiler Room and Entire Building	1	EA	6	6-10 years	Serves main building
	Fire Alarm Strobe Lights	Boiler Room and Entire Building	43,063	SF	6	6-10 years	g
	Fire Alarm_System	Boiler Room and Entire Building	43,063	SF	6	6-10 years	
	The Alann_Oystein		,		5	6-10 years	Older,functional
	Fire Dump Controller	Poilor Poom and Entire Puilding	1				Oluei lui lui lui lai
	Fire Pump Controller	Boiler Room and Entire Building	1	EA	3	o io years	, , , , , , , , , , , , , , , , , , , ,
ump Ro	oom Assembly						,
<u>⁰ump R</u> o	·	Boiler Room and Entire Building Boiler Room	1	EA EA	6	6-10 years	Functional, passes fire marshal
ump Ro	oom Assembly						,
·	oom Assembly Fire Pump - Less than 25hp	Boiler Room	1	EA	6	6-10 years	Functional, passes fire marshal inspection, serves main building
·	oom Assembly Fire Pump - Less than 25hp Jockey Pump	Boiler Room Boiler Room	1	EA EA	6	6-10 years 6-10 years	Functional, passes fire marshal inspection, serves main building
·	oom Assembly Fire Pump - Less than 25hp Jockey Pump r System Sprinkler Heads	Boiler Room Boiler Room Entire Building	1 1 43,063	EA EA	6 6	6-10 years 6-10 years 6-10 years	Functional, passes fire marshal inspection, serves main building Functional Passes fire marshall test
·	oom Assembly Fire Pump - Less than 25hp Jockey Pump	Boiler Room Boiler Room	1	EA EA	6	6-10 years 6-10 years	Functional, passes fire marshal inspection, serves main building Functional

Campus Name: Pirie Page : 4 of 27 Assessment Date: 03/09/2022



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Fire Protection		В	uilding	: Main		
					_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond	-	Location	Quantity	COM	Italik	Replacement	Comments
7 III OOTIC	Chemical Pot Feeder	Boiler Room and Roof	1	EA	5	6-10 years	Recently serviced, not cleaned
	Chiller-Water Cooled- Cetrifugal - Less than 100 tons	Boiler Room and Roof	4	EA	5	6-10 years	Serves main building
	Cooling Tower - Closed Cell	Boiler Room and Roof	1	EA	5	6-10 years	Recently serviced
	Glycol Feed	Boiler Room and Roof	1	EA	6	6-10 years	Manually fed
	Pipes - Dual Temperature Pipe- Steel	Boiler Room and Roof	300	LF	6	10+ years	Minor leaks occasionally repaired. There are a few pipe clamps
	Pressure Fill System	Boiler Room and Roof	1	EA	5	6-10 years	Previously not assessed
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	10+ years	serves evaporating unit in MDF room, mini split system. 2019 installation
_Air Hand	Iling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	Boiler Room	1	EA	5	6-10 years	Serves lunchroom area, in mezzanine area of boiler room, difficult to access
	Air Intake	Boiler Room	1	EA	5	6-10 years	Functional, difficult to access
Boiler Sy	ystems						
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	Functional, not painted
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	5	6-10 years	Manually fed
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	6-10 years	Serves main building
	Piping - Dual Temperature Pipes- Steel	Boiler Room	250	LF	6	6-10 years	
	Water Fill System	Boiler Room	1	ĒA	5	6-10 years	Pressure fill, previously not assessed
Heating	Devices						
J	Fin Tube - Hot Water	1st Floor	15	LF	5	6-10 years	In restroom, previously not assessed
	Unit Heater - Hot Water	Boiler Room	2	EA	5	6-10 years	Functional, cleaned
	Wall Heater - Electric	Electrical Room	2	EA	6	10+ years	Functional
	Cabinet Heaters - With Hot Water Coil	Entire Building	16	EA	5	6-10 years	Some have deteriorated paint
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	5	6-10 years	Motors recently replaced, ceiling mounted, circulating pumps

Campus Name: Pirie Page : 5 of 27 Assessment Date: 03/09/2022



XIII S	Schools						650 E 85th STREET, Chicago, IL 60619
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Condenser Pump - 10 - 20 HP	Boiler Room	2	EA	5	6-10 years	Pump bearing resealed. Serves
	Condensor Famp To ZoTii	Bollot Room	_	_, 、	Ū	o ro youro	cooling tower condenser water
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	5	6-10 years	Seals repacked , floor mounted, serve boiler, chiller
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	6-10 years	·
Tempera	ature Control						
•	DDC System	Entire Building	43,063	SF	6	6-10 years	Software not updated, Metasys
	Electric Thermostat	Entire Building	5	EA	5	6-10 years	Serve unit heaters, exhaust fan, previously not assessed, single zone AHU
	Thermostats - DDC	Entire Building	31	EA	6	6-10 years	Some not calibrated, serve 31 unit ventilators
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual	Entire Building	21	EA	5	6-10 years	
	Temperature Coils (Hot/Chilled) Water		40		•	0.40	NA
	Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	10	EA	6	6-10 years	Mounted above ceilings, difficult to access, in corridors
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof & 1st floor	7	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof & 1st floor	12	EA	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof & 1st floor	1	EA	2	0-1 year	No fire suppression, water supply only
	Type II Exhaust Hood- Warming Kitchen	Roof & 1st floor	2	EA	5	6-10 years	Above warming oven, above removed dishwasher, previously not assessed
Catego	ry : Plumbing		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves main building, 2007 installation, functional
Piping							
· -	Domestic Piping-Hot Water Return Lines	Entire Building	43,063	SF	6	10+ years	Minor leaks are occasionally repaired
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	43,063	SF	6	10+ years	1962 installation, functional
	Sanitary Piping	Entire Building	43,063	SF	6	10+ years	1962 installation
	Storm Piping	Entire Building	43,063	SF	6	10+ years	



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Plumbing	: Plumbing Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Vent Piping	Entire Building	43,063	SF	6	10+ years	
Pumps	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	6	6-10 years	Domestic Hot water circulating pump. No cold water pressure booster pump

Category : Room Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices	Location	Quantity	COM	Italik	Replacement	Comments
_Adminisi		1 at fix aget of kitchen tageher's	1,057	SF	6	10	
	Ceiling - Splined	1st flr east of kitchen, teacher's lounge	1,057	SF	6	10+ years	
	Ceiling - Splined	1st flr east of kitchen, teacher's	5	SF	5	1-2 years	Missing tiles
	Ceiling - Spilined	lounge	3	OI.	3	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	1st flr east of kitchen, teacher's	1	EA	6	10+ years	
	Boole Wood Boole mold III	lounge	•	_, 、	Ū	ioi youro	
	Floor - Tile	1st flr east of kitchen, teacher's	1,012	SF	7	10+ years	
		lounge	,-			, , , , ,	
	Floor - Tile	1st flr east of kitchen, teacher's	30	SF	4	1-2 years	Damaged tiles
		lounge					· ·
	Lighting - Lay-in	1st flr east of kitchen, teacher's	2	EA	7	6-10 years	
		lounge					
	Lighting - Pendent/Surface	1st flr east of kitchen, teacher's	12	EA	7	6-10 years	
		lounge					
	Power Distribution	1st flr east of kitchen, teacher's	8	EA	7	10+ years	
		lounge			_		
	Walls - Concrete Block	1st flr east of kitchen, teacher's	1,141	SF	7	10+ years	
	0.11	lounge	4 000	0=		4.0	
	Ceiling - Splined	1st flr main office	1,023	SF	6	10+ years	
	Doors - Side-lite	1st flr main office	60	SF	7	10+ years	
	Doors - Transom Window	1st flr main office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr main office	1 000	EA SF	7	10+ years	
	Floor - Tile	1st flr main office 1st flr main office	1,023	SF EA	7 7	10+ years	
	Lighting - Pendent/Surface Power Distribution	1st fir main office	24 20	EA EA	7	6-10 years	
	Storage/ Closet	1st fir main office	240	SF	7	10+ years 10+ years	
	Walls - Concrete Block	1st fir main office	2,794	SF	7	10+ years	
	Work SInk	1st fir main office	2,734	EA	7	10+ years	
	Ceiling - Splined	Assistant principals	391	SF	7	10+ years	
	Doors - Transom Window	Assistant principals	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Assistant principals	2	EA	7	10+ years	
	Floor - Tile	Assistant principals	391	SF	7	10+ years	
	Lighting - Pendent/Surface	Assistant principals	6	EA	7	6-10 years	
	Power Distribution	Assistant principals	4	EΑ	7	10+ years	
		Severation Errorade and	•		-	,	

Campus Name: Pirie Page: 7 of 27 Assessment Date: 03/09/2022



Catego	ry : Room	-	В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	Assistant principals	25	SF	7	10+ years	
	Walls - Concrete Block	Assistant principals	540	SF	7	10+ years	
	Ceiling - Splined	Case manager office	270	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Case manager office	2	EA	7	10+ years	
	Floor - Tile	Case manager office	270	SF	7	6-10 years	
	Lighting - Pendent/Surface	Case manager office	4	EA	7	6-10 years	
	Walls - Concrete Block	Case manager office	666	SF	7	10+ years	
	Ceiling - Splined	Counselor office	120	SF	7	10+ years	
	Doors - Side-lite	Counselor office	27	SF	7	10+ years	
	Doors - Transom Window	Counselor office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor office	2	EA	7	10+ years	
	Floor - Tile	Counselor office	120	SF	7	6-10 years	
	Lighting - Pendent/Surface	Counselor office	2	EA	7	6-10 years	
	Walls - Concrete Block	Counselor office	396	SF	7	10+ years	
	Ceiling - Splined	Engineer's Office	58	SF	7	10+ years	
	Doors - Steel Doors incl hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Concrete	Engineer's Office	58	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	2	EA	7	10+ years	
	Walls - Concrete Block	Engineer's Office	126	SF	7	10+ years	
	Ceiling - Exposed	Janitor's Lounge	97	SF	7	10+ years	
	Doors - Steel Doors incl hw	Janitor's Lounge	2	EA	6	6-10 years	
	Floor - Epoxy/ Painted	Janitor's Lounge	97	SF	4	2-5 years	Worn through
	Lighting - Pendent/Surface	Janitor's Lounge	2	EA	7	6-10 years	Ğ
	Power Distribution	Janitor's Lounge	6	EA	7	10+ years	
	Walls - Concrete Block	Janitor's Lounge	146	SF	7	10+ years	
	Ceiling - Splined	Nurse Office	400	SF	7	10+ years	
	Doors - Transom Window	Nurse Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse Office	3	EA	7	10+ years	
	Floor - Carpet	Nurse Office	395	SF	7	10+ years	
	Floor - Carpet	Nurse Office	5	SF	6	1-2 years	Carpet threshold dirty
	Lighting - Pendent/Surface	Nurse Office	7	EA	7	6-10 years	
	Power Distribution	Nurse Office	6	EA	7	10+ years	
	Storage/ Closet	Nurse Office	30	SF	7	10+ years	
	Walls - Concrete Block	Nurse Office	896	SF	7	10+ years	
	Work SInk	Nurse Office	1	EA	7	10+ years	
	Ceiling - Splined	Principal Office	231	SF	7	10+ years	
	Doors - Transom Window	Principal Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal Office	2	ĒΑ	7	10+ years	
	Floor - Tile	Principal Office	231	SF	7	10+ years	
	Lighting - Pendent/Surface	Principal Office	4	ĒA	7	6-10 years	
	Power Distribution	Principal Office	10	EA	7	10+ years	
	Storage/ Closet	Principal Office	30	SF	7	10+ years	
	Walls - Concrete Block	Principal Office	344	SF	7	10+ years	
		·				•	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Gymnasi	a Ceiling - Exposed	1st Floor	4,352	SF	7	10	
	•		4,352	SF EA	7	10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	1st Floor	· · · · · · · · · · · · · · · · · · ·	SF	7	10+ years	
	Floor - Tile	1st Floor 1st Floor	375 25	SF SF	4	10+ years 0-1 year	Entire tile needs to be replaced
	Floor - Wood			SF SF	7		Entire tile needs to be replaced
		1st Floor 1st Floor	3,952	EA	-	10+ years	
	Lighting - Metal Halide/Sodium Vapor		12		7 7	6-10 years	
	Scoreboards	1st Floor	1	EΑ	7	10+ years	
	Sound System	1st Floor	1	EA		10+ years	
	Stage	1st Floor	481	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	304	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,981	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,981	SF	7	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	1,016	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	1,016	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Storage/ Closet	1st Floor	102	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,074	SF	7	10+ years	
Lookor/S	hower Room						
LUCKEI/S	Accessories	1st flr NE corner	152	SF	7	6-10 years	
	Ceiling - Splined (Moister Resistance)	1st fir NE corner	152	SF	6	10+ years	
	Doors - Transom Window	1st fir NE corner	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st fir NE corner	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st fir NE corner	152	SF	6	10+ years	
	Lavatory	1st fir NE corner	102	EA	7	10+ years	
	Lighting - Lay-in	1st fir NE corner	1	EA	7	6-10 years	
	Lighting - Lay-III Lighting - Pendent/Surface	1st fir NE corner	1	EA	7	6-10 years	
	Partitions	1st fir NE corner	1	EA	7	10+ years	
	Student Lockers - One Tier	1st fir NE corner	5	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st fir NE corner	5 526	SF	7		
	Water Closet	1st fir NE corner	526	SF EA	7	10+ years	
	vvaler Gluser	15t III INE COITIEI	1	EA	,	10+ years	
م مصرا	Multipurpaga Paam						
_Lunch &	Multipurpose Room						



650 E 85th STREET, Chicago, IL 60619

Catego	ategory : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	1st Floor	1,850	SF	7	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	43	EA	7	6-10 years	
	Storage/ Closet	1st Floor	236	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	551	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,653	SF	7	10+ years	
MDF_ID	F						
	Doors - Steel Doors incl hw	1st floor south of kitchen	1	EA	7	10+ years	
	Finishes	1st floor south of kitchen	143	SF	7	10+ years	
	Other Cooling Unit	1st floor south of kitchen	1	EA	7	10+ years	Ductless split
/lechani	ical/ Service Rooms						
COHOLI	Boiler Room	1st Floor	1,394	SF	7	10+ years	
	Janitor's Closet	1st Floor	138	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	320	SF	7	10+ years	
	Storage Room	1st Floor	592	SF	7	10+ years	Water damaged ceiling tile 4 sq ft
	Mechanical/ Service Rooms	Chiller Room	165	SF	7	10+ years	water damaged ceiling the 4 sq it
Restroor	m						
CSHOOL	Accessories	1st flr inside nurse's office	22	SF	7	6-10 years	
	Ceiling - Splined	1st flr inside nurse's office	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside nurse's office	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside nurse's office	22	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside nurse's office	_ <u>-</u> _	ĒΑ	7	10+ years	
	Walls - Structural Glazed Tile	1st flr inside nurse's office	160	SF	7	10+ years	
	Water Closet	1st flr inside nurse's office	1	EA	7	10+ years	
	Accessories	1st flr inside principal's office	22	SF	7	6-10 years	
	Ceiling - Splined	1st flr inside principal's office	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	22	SF	7	10+ years	
	Lavatory	1st flr inside principal's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st fir inside principal's office	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr inside principal's office	160	SF	7	10+ years	
	Water Closet	1st fir inside principal's office		SF EA	7 7	•	
			1	SF		10+ years	
	Accessories	1st flr inside teacher's lounge	29		7	6-10 years	
	Ceiling - Splined	1st flr inside teacher's lounge	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside teacher's lounge	29	SF	7	10+ years	

Campus Name: Pirie Page : 10 of 27 Assessment Date: 03/09/2022



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside teacher's lounge	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr inside teacher's lounge	176	SF	7	10+ years	
	Water Closet	1st flr inside teacher's lounge	1	EΑ	7	10+ years	
	Accessories	1st flr inside teacher's lounge	29	SF	5	2-5 years	Bathroom currently under renovation
	Ceiling - Splined	1st flr inside teacher's lounge	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside teacher's lounge	29	SF	7	10+ years	
	Lavatory	1st flr inside teacher's lounge	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside teacher's lounge	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr inside teacher's lounge	176	SF	7	10+ years	
	Water Closet	1st flr inside teacher's lounge	1	EΑ	7	10+ years	
	Accessories	In Room 115, Library	21	SF	7	6-10 years	
	Ceiling - Splined	In Room 115, Library	21	SF	7	10+ years	
	Doors - Transom Window	In Room 115, Library	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 115, Library	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 115, Library	21	SF	7	10+ years	
	Lavatory	In Room 115, Library	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 115, Library	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 115, Library	81	SF	6	10+ years	
	Water Closet	In Room 115, Library	1	EA	7	10+ years	
	Accessories	In Room 116	21	SF	7	6-10 years	
	Ceiling - Splined	In Room 116	21	SF	7	10+ years	
	Doors - Transom Window	In Room 116	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 116	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 116	21	SF	7	10+ years	
	Lavatory	In Room 116	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	In Room 116	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 116	81	SF	7	10+ years	
	Water Closet	In Room 116	1	EA	7	10+ years	
	Accessories	Janitor's Area	88	SF	7	6-10 years	
	Ceiling - Splined	Janitor's Area	88	SF	7	10+ years	
	Doors - Steel Doors incl hw	Janitor's Area	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	Janitor's Area	88	SF	4	2-5 years	Worn through
	Floor Drain	Janitor's Area	1	EA	7	10+ years	
	Lavatory	Janitor's Area	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Janitor's Area	2	EA	7	6-10 years	
	Partitions	Janitor's Area	1	EA	7	10+ years	
	Showers	Janitor's Area	1	EA	4	1-2 years	Not working
	Walls - Structural Glazed Tile	Janitor's Area	166	SF	6	10+ years	•
	Water Closet	Janitor's Area	1	EA	6	10+ years	
	Accessories	North	267	SF	5	2-5 years	
	Ceiling - Splined	North	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years	
						,	





Catego	Category : Room		В	uilding	: Main		<u> </u>	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile Ceramic/ Porcelain	North	267	SF	7	10+ years		
	Floor Drain	North	1	EΑ	7	10+ years		
	Lavatory	North	3	EA	7	10+ years		
	Lighting - Pendent/Surface	North	6	EA	7	6-10 years		
	Partitions	North	4	EA	7	10+ years		
	Urinals	North	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	North	586	SF	7	10+ years		
	Water Closet	North	4	EA	7	10+ years		
	Accessories	North	267	SF	7	6-10 years		
	Ceiling - Splined	North	267	SF	7	10+ years		
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	North	267	SF	7	10+ years		
	Floor Drain	North	1	EA	7	10+ years		
	Lavatory	North	3	EA	7	10+ years		
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years		
	Partitions	North	8	EA	7	10+ years		
	Walls - Structural Glazed Tile	North	586	SF	7	10+ years		
	Water Closet	North	8	EA	7	10+ years		
	Accessories	South	267	SF	7	6-10 years		
	Ceiling - Splined	South	267	SF	7	10+ years		
	Doors - Wood Doors inclu hw	South	1	EΑ	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	South	267	SF	7	10+ years		
	Floor Drain	South	1	EA	7	10+ years		
	Lavatory	South	3	EA	7	10+ years		
	Lighting - Lay-in	South	1	EΑ	7	6-10 years		
	Lighting - Lay-in	South	1	EA	6	0-1 year	Relamp	
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years		
	Partitions	South	1	EA	7	10+ years		
	Urinals	South	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	South	586	SF	7	10+ years		
	Water Closet	South	1	EA	7	10+ years		
	Accessories	South	267	SF	7	6-10 years		
	Ceiling - Splined	South	267	SF	7	10+ years		
	Doors - Wood Doors inclu hw	South	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	South	267	SF	7	10+ years		
	Floor Drain	South	1	EA	7	10+ years		
	Lavatory	South	2	EA	7	10+ years		
	Lavatory	South	1	EA	5	2-5 years		
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years		
	Lighting - Pendent/Surface	South	1	EA	6	0-1 year	Relamp	
	Partitions	South	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	South	586	SF	7	10+ years		
	Water Closet	South	4	EA	7	10+ years		



Catego	ry : Classroom		В	uilding	: Main		
0	liana Tuna	l aastle:-	0	11014	Devil	Recommend	Commonts
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #101 (Regular Classroom)						
	Ceiling - Splined	1st Floor	768	SF	6	10+ years	
	Ceiling - Splined	1st Floor	15	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
Classroo	m #102 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	783	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,152	SF	6	10+ years	
Classroo	m #103 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	783	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,152	SF	7	10+ years	
Classroo	m #104 (Regular Classroom)						
		1st Floor	783	SF	6	101 2000	
	Ceiling - Splined Doors - Side-lite	1st Floor 1st Floor	783 7	SF SF	6 7	10+ years 10+ years	
	Doors - Side-life Doors - Transom Window	1st Floor	8	SF SF	7	,	
	Doors - Wood Doors inclu hw	1st Floor	0	SF EA	6	10+ years 10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years 10+ years	
	Lighting - Lay-in	1st Floor	763	SF EA	6	6-10 years	
	Lighting - Lay-iii Lighting - Pendent/Surface	1st Floor	7	EA	7	10+ years	
	Lighting - I endent/Sunace	13111001	1	LA	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,152	SF	7	10+ years	
Classroo	om #105 (Store Room)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
				О.	· ·	. o · you.o	
Classroo	om #106 (Store Room)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
Classroo	om #107 (Science Classroom)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	201	SF	7	10+ years	
	Ceiling - Splined	1st Floor	604	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	7	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	6-10 years	Corrected quantities
Classroo	om #108 (Regular Classroom)						
	,						



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Splined	1st Floor	804	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	788	SF	7	10+ years	
	Floor - Tile	1st Floor	16	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classroo	om #109 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Splined	1st Floor	804	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #110 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Splined	1st Floor	603	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #111 (Computer Lab)						
	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Flaster/Brywani Ceiling - Splined	1st Floor	603	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	C.I.S.II BOOK	1001			•	_ 0 youro	



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Classroom		В	uilding	: Main		650 E 65111 STREET, CHICAGO, IL 60619
J J .	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	804	SF	5	2-5 years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
_Classroo	om #112 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	134	SF	6	10+ years	
	Ceiling - Splined	1st Floor	670	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #113 (Regular Classroom)						
	Casework	1st Floor	8	LF	4	1-2 years	Delaminating
	Ceiling - Plaster/Drywall	1st Floor	134	SF	6	10+ years	Bolammating
	Ceiling - Splined	1st Floor	670	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years	
	Storage/ Closet	1st Floor	9	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	, 5	10+ years 10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classis	om #444 (Dogular Classes)					•	
Classro	om #114 (Regular Classroom)	4-4-51-		. –		0.5.	Delegation
	Casework	1st Floor	8	LF	4	2-5 years	Delaminating
	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Splined	1st Floor	595	SF	6	10+ years	And the second second
	Ceiling - Splined	1st Floor	8	SF	5	1-2 years	Missing and damaged
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	

Campus Name: Pirie Page : 16 of 27 Assessment Date: 03/09/2022




Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroc	om #115 (Library)						
	Ceiling - Splined	1st Floor	1,203	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,203	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Storage/ Closet	1st Floor	16	SF	5	10+ years	Corrected quantities
	Walls - Concrete Block	1st Floor	1,072	SF	7	10+ years	Corrected quantities
	Walls - Metal Panel	1st Floor	358	SF	6	10+ years	
Classroc	om #116 (Art Room)						
	Casework	1st Floor	24	LF	4	1-2 years	Delaminating
	Ceiling - Splined	1st Floor	1,203	SF	6	10+ years	Dolamianig
	Chalk Board	1st Floor	9	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,203	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1,203	EA	7	,	
	Storage/ Closet	1st Floor	12	SF	, 5	6-10 years	
	Walls - Concrete Block	1st Floor		SF	7	10+ years	
			1,072			10+ years	
	Walls - Metal Panel	1st Floor	358	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroc	om #117 (Music Room)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	



GroupItem - TypeLocationQuantityUOMRankReplaceWalls - Concrete Block1st Floor864SF710+ yr	nmend cement Comments years years
Walls - Concrete Block1st Floor864SF710+Walls - Metal Panel1st Floor288SF510+	years
Walls - Metal Panel 1st Floor 288 SF 5 10+	
	years
Classroom #118 (Regular Classroom)	
Ceiling - Splined 1st Floor 783 SF 6 10+	years
Chalk Board 1st Floor 24 LF 4 2-5 y	, years
	years
	years
·	years
·	years
	years
	years
	vears
	years
Classroom #119 (Regular Classroom)	
	years
	/ears
	years
· · · · · · · · · · · · · · · · · · ·	years
· · · · · · · · · · · · · · · · · · ·	years
· · · · · · · · · · · · · · · · · · ·	years
· · · · · · · · · · · · · · · · · · ·	years
· ·	years
· · · · · · · · · · · · · · · · · · ·	years
Classroom #120 (Regular Classroom)	
	years
· ·	years
	years
· · · · · · · · · · · · · · · · · · ·	years
	years
	years
	years
	years
ullet	years
· · · · · · · · · · · · · · · · · · ·	years
Classroom #121 (Regular Classroom)	
	years
	/ears
	years
	years
20010 Harisoni William 15t Floor 0 Of 7 TOT	youro



Catego	ategory : Classroom			uilding			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
lassroc	m #122 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
					_		
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
atego	Walls - Metal Panel ry : Interior	1st Floor		SF uilding		10+ years	
atego						Recommend	
_		1st Floor Location				•	Comments
roup	ry : Interior		В	uilding	: Main	Recommend	Comments
roup	ry : Interior Item - Type	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
roup	ry : Interior Item - Type Ceiling - Lay-in	Location 1st Floor	Quantity 7,026	UOM SF	: Main Rank	Recommend Replacement	
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in	Location 1st Floor 1st Floor	Quantity 7,026 20	UOM SF SF	: Main Rank	Recommend Replacement 10+ years 0-1 year	Comments Missing tiles
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite	Location 1st Floor 1st Floor 1st Floor	Quantity 7,026	UOM SF SF SF SF	Rank 7 4 7	Recommend Replacement 10+ years 0-1 year 10+ years	
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	7,026 20 16 4	UOM SF SF SF EA	7 4 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years	
roup	Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	7,026 20 16 4	UOM SF SF SF EA SF	Rank 7 4 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years	
roup	Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain	Location 1st Floor	7,026 20 16 4	UOM SF SF SF EA SF EA	7 4 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years	
roup	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain	Location 1st Floor	7,026 20 16 4 12 2	UOM SF SF SF EA SF EA SF EA	7 4 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 6-10 years	
roup	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet	Location 1st Floor	7,026 20 16 4	UOM SF SF SF EA SF EA	7 4 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
Catego Group Corridor	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	Location 1st Floor	7,026 20 16 4 12 2 1 7,046 64	UOM SF SF SF EA SF EA SF EA EA	7 4 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years	
roup	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers	Location 1st Floor	7,026 20 16 4 12 2 1 7,046 64 180	UOM SF SF SF EA SF EA EA EA	7 4 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	
roup	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	Location 1st Floor	7,026 20 16 4 12 2 1 7,046 64	UOM SF SF SF EA SF EA SF EA EA	7 4 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years	
corridor	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block	Location 1st Floor	7,026 20 16 4 12 2 1 7,046 64 180 9,167	UOM SF SF SF EA SF EA EA SF EA SF EA	7 4 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
roup	Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block	Location 1st Floor	7,026 20 16 4 12 2 1 7,046 64 180 9,167	UOM SF SF SF EA SF EA EA SF EA SF EA	7 4 7 7 7 7 7 7 7	Recommend Replacement 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	





2.090	ry : Exterior		Building : Modular 1 (4-Classroom) Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	#10 - W	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9 - E	2	EA	6	10+ years	
oundati	on						
	Foundation - Masonry	Entire Building	280	LF	7	10+ years	
	Superstructure - Steel	Entire Building	4,947	SF	7	10+ years	
ghting							
, ,	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
oof Sys	stem .						
,	Coping - Metal	Main Roof	280	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	44	LF	6	10+ years	
	Roof - PVC Membrane	Main Roof	4,947	SF	5	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	4,947	SF	7	10+ years	
/alls							
	Exterior Walls - Wood Siding	Entire Building	3,075	SF	5	6-10 years	
	Exterior Walls - Wood Siding	Entire Building	7	SF	4	1-2 years	Material deterioration/Open and unprotected edges - peeling paint/exposed joints/bowing of damaged panel. Cracked panel in other area.
/indows		Fatin Duildian	050	0.5		40	
	Guard - Guards perforated Windows - Sash Aluminum Double-pane	Entire Building Entire Building	256 256	SF SF	6 6	10+ years 10+ years	
atego	ry : Electrical		В	uildina	: Modul	ar 1 (4-Classro	om)
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nerger	cy System						
	Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs	1st Floor Entire Building	4,947 6	SF EA	6 6	6-10 years 6-10 years	2003 installation
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	5	6-10 years	Functional



650 E 85th STREET, Chicago, IL 60619

	SCHOOIS		_				650 E 85th STREET, Chicago, IL 60619
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	oom)
			A 41:			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	1st Floor	4,200	SF	5	6-10 years	Connected to main building, previously not assessed
	Main Electrical Service - 1000 A 120/208/3PH	Site - East	1	EA	6	10+ years	Serves modular building, 2003 installation, previously not assessed
Power D	vistribution						
T OWEL D	Lighting and Power Panels - 100 A	Mechanical Room	2	EA	7	10+ years	Functional panels rated 7, 2003 installation
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Exterior facade	1	EA	7	10+ years	Recently installed, serves modular building
	Fire Alarm Strobe Lights	Exterior facade	4,947	SF	7	10+ years	Previously not assessed
	Fire Alarm_System	Exterior facade	4,947	SF	7	10+ years	Recently installed, serves modular building
Sprinkle	r System						
	Sprinkler Heads	Entire Building	4,947	SF	7	10+ years	2003 installation
	Sprinkler Piping	Entire Building	4,947	SF	6	10+ years	2003 installation
	Wet Sprinkler System	Entire Building	4,947	SF	6	10+ years	2003 installation, using city pressure
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ature Control		4			Tio place in the	
тетрета	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Serves 4 exterior univent, p
Unit Ver	itilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	4	EA	5	6-10 years	2003 installation, functional
Ventilation							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	5	EA	6	10+ years	Roof not accessible, previously not assessed, 2003 installation

Campus Name: Pirie Page : 21 of 27 Assessment Date: 03/09/2022



650 E 85th STREET, Chicago, IL 60619

Category : Plumbing			В	Building : Modular 1 (4-Classroom)					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Hot Wat	er								
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	6-10 years	Serves modular building		
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	4,947	SF	6	10+ years	Functional, 2003 installation		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	4,947	SF	6	10+ years	2003 installation		
	(Horizontal Lines)	Fatina Dailalia a	4.047	0.5	0	40	Francticus I 0000 in stallation		
	Sanitary Piping	Entire Building	4,947	SF	6	10+ years	Functional, 2003 installation		
	Storm Piping	Entire Building	4,947	SF	6	10+ years	Functional		
	Vent Piping	Entire Building	4,947	SF	6	10+ years	Functional		
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)		
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #201 (Kindergarten)								
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	875	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years			
	Storage/ Closet	1st Floor	65	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	1,095	SF	7	10+ years			
Classroo	om #202 (Pre School)								
Ciassioc	Ceiling - Lay-in	1st Floor	877	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	20	SF	4	1-2 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	897	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Storage/ Closet	1st Floor	87	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	1,143	SF	7	10+ years			
	Talle Model and	.3.1 1001	1,140	٥.	•	.o. youro			
Classroo	om #203 (Store Room)								
	Ceiling - Lay-in	1st Floor	867	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damaged		
	Chalk Board	1st Floor	12	LF	4	2-5 years	-		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	875	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years			
	Storage/ Closet	1st Floor	65	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	1,095	SF	7	10+ years			

Campus Name: Pirie Page : 22 of 27 Assessment Date: 03/09/2022




Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassro	om #204 (District Office)						
	Ceiling - Lay-in	1st Floor	897	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	897	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	ΕA	7	6-10 years	
	Storage/ Closet	1st Floor	87	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	1,143	SF	7	10+ years	
	Traile Interact arter		.,	О.	•	.o. you.o	
atego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	Í
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
/lechan	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	52	SF	7	10+ years	
						-	
Restrooi	n						
	Accessories	1st Floor	155	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	155	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	155	SF	7	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	1	ΕA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	2	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	436	SF	7	-	
	Water Closet	1st Floor	430	EA	7	10+ years	
	Accessories	1st Floor	176	SF	7	10+ years	
			176	SF SF		6-10 years	
	Ceiling - Lay-in	1st Floor	_		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	176	SF	7	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	470	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	
`ataa-	ry - Interior		ь	uildina	· Modul	ar 1 (4-Classro	om)
Catego Group	ry : Interior Item - Type	Location	Quantity	UOM		Recommend	
	ITAM - IVAA	Location	Quantity	UUW	Rank	Recommend	Comments



650 E 85th STREET, Chicago, IL 60619

		Replacement						
Corridor								
Ceiling - Lay-in	1st Floor	544	SF	7	10+ years			
Doors - Steel Doors incl hw	1st Floor	4	EΑ	7	10+ years			
Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years			
Floor - Tile/Sheet	1st Floor	544	SF	7	10+ years			
Lighting - Lay-in	1st Floor	7	EA	7	6-10 years			
Walls - Vinyl Coated Gypsum Panel	1st Floor	1,472	SF	7	10+ years			

Campus Name: Pirie Page : 24 of 27 Assessment Date: 03/09/2022





Category : Site Building : Site

Category . Site				unung	. Oite		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
	Citin Diamage Cite mainless		· ·		Ū	,	
Fencing							
_r ending	Fencing - Chain Link	Entire Site	158	LF	6	10+ years	
	Fencing - Chain Link Fencing - Chain Link	Entire Site	60	LF	5	2-5 years	
		Entire Site Entire Site		LF	-		
	Fencing - New Standard Ornamental		1,149		6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	12	LF	5	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	12	LF	5	1-2 years	
_Landsca	pe						
	Benches	Entire Site	2	EA	6	10+ years	
	Benches	Entire Site	1	EA	5	2-5 years	
	Benches	Entire Site	1	EA	5	2-5 years	
	Landscape - Grass	Entire Site	38,787	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	710	SF	5	2-5 years	Cracks/uneven/settling/heaving
	Landscape - Hardscape- Pavers	Entire Site	32	SF	6	10+ years	g
	Parkway trees	Entire Site	24	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	10,064	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	11,557	SF	5	6-10 years	Top course replacement
	Play Area - Hardscape- Asphalt	Entire Site	1,050	SF	4	1-2 years	Buckling/uneven/major cracks/Trip
	riay Area - Hardscape- Aspirali	Littile Oile	1,000	Oi	7	1-2 years	hazards with organic/vegetative
							growth within
	Play Area - Hardscape- Asphalt	Entire Site	1,050	SF	4	1-2 years	Buckling/uneven/major Cracks-trip
	Flay Alea - Haluscape- Aspilali	Littile Site	1,030	SF	4	1-2 years	hazards with organic/vegetative
							growth within
	Trash Receptacles	Entire Site	E	EA	6	10+ years	growth within
		Entire Site	5 10,902	SF	6 4		Obsolete data/Non - found: removed
	Walking Path - Crushed Stone	Entire Site	10,902	SF	4	0-1 year	
							or grown over. Only 90' +/- of asphalt
							remains
Parking	Lot						
	Concrete Curbs	Parking Lot- East	73	LF	6	10+ years	
	Concrete Curbs	Parking Lot- East	7	LF	4	0-1 year	
	Interior Plantings	Parking Lot- East	30	LF	6	6-10 years	
	Surface - Asphalt	Parking Lot- East	7,267	SF	4	1-2 years	Significant Damage - major
	·	3	•			•	Cracks/Broken/Uneven
	Surface - Concrete	Parking Lot- East	255	SF	5	2-5 years	Broken/cracked
	Trash Enclosure - Chain Links	Parking Lot- East	566	SF	5	2-5 years	Hinge failing - gate drags ground.
	Vehicular Screening	Parking Lot- East	151	LF	5	10+ years	Shrubbery/Fencing
	Vehicular Screening	Parking Lot- East	20	LF	5	1-2 years	Shrubbery/fence - bent/damaged
		g	20		Ü	; 00.0	

Campus Name: Pirie Page: 25 of 27 Assessment Date: 03/09/2022



650 E 85th STREET, Chicago, IL 60619

Category : Site		В	uilding				
	Mana Tana	Landin	0		Danila	Recommend	0
Group	Vehicular Screening	Location Parking Lot- East	Quantity 20	LF	Rank 5	1-2 years	fence panel each side of lot entry drive Shrubbery/Fence - bent/damaged fence panel each side of lot entry drive
Playgrou	ınd						
	Equipment - School Age 5-12	West	1	EA	6	2-5 years	
	Surface - Square Rubber Mats	West	2,397	SF	4	1-2 years	Buckling/Gaps/holes in Mats
Sidewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	506	LF	6	10+ years	See Courtyard in Landscaping
	Sidewalks - Internal Walks	Entire Site	50	LF	5	2-5 years	,
	Sidewalks - Perimeter Sidewalks	Entire Site	4,675	SF	6	10+ years	Quantity Adjusted
	Sidewalks - Perimeter Sidewalks	Entire Site	3,000	SF	5	1-2 years	Quantity Adjusted: Major deterioration/significant Damage - Broken/Cracks/heaving/settling and dis-shelved
Signage							
	Flag Pole - Flag Pole	SE site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	SE site	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Pirie Page: 26 of 27 Assessment Date: 03/09/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

75

875

37

Ν

Ν



Store Room

Classroom Summary

Kindergarten

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main		•	•	•		•	•	•	
Art Room	Kindergarten	1st Floor	116	112	1,203	157	96	Υ	N
Computer Lab	Regular Classroom	1st Floor	111	115	804	147	0	N	N
Library	Kindergarten	1st Floor	115	111	1,203	140	96	N	Υ
Music Room	Regular Classroom	1st Floor	117	117	783	45	13	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	783	45	13	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	783	30	9	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	783	30	9	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	783	30	9	N	N
Regular Classroom	Regular Classroom	1st Floor	108	110	804	75	0	N	N
Regular Classroom	Regular Classroom	1st Floor	109	113	804	75	0	N	N
Regular Classroom	Regular Classroom	1st Floor	110	116	804	147	0	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	114	804	72	0	N	N
Regular Classroom	Regular Classroom	1st Floor	113	109	804	75	0	N	N
Regular Classroom	Regular Classroom	1st Floor	114	108	804	147	0	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	119	119	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	120	120	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	121	121	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	783	45	13	N	N
Science Classroom	Regular Classroom	1st Floor	107	107	804	147	0	N	Υ
Store Room	Regular Classroom	1st Floor	105	105	783	30	9	N	N
Store Room	Regular Classroom	1st Floor	106	106	783	45	13	N	Υ
Building : Modular 1 (4-Cla	ssroom)								
District Office	Regular Classroom	1st Floor	204	204	897	75	37	N	N
Kindergarten	Kindergarten	1st Floor	201	201	875	75	37	N	N
Pre School	Kindergarten	1st Floor	202	202	897	75	37	N	N
Ci D	1.0		 	 		 -	 	.	

Campus Name: Pirie	Page : 27 of 27	Assessment Date: 03/09/2022

1st Floor

203

203