

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1905 | 3 | 38,332 |
| Annex | 2020 | 2 | 19,100 |
| Campus Total | | | 57,432 |

| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------|--------------------------------------|-----------------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Cell Equ | ipment | | | | | | |
| | Cell Equipment - Antenna | Entire Building | 4 | EA | 7 | 10+ years | |
| | Cell Equipment - Cabinets | Entire Building | 2 | EA | 7 | 10+ years | |
| Entrance | 2 | | | | | | |
| | Entrance Control - Audio and Video | #1 - Main - E | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #1 - Main - E | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | #1 - Main - E | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #1 - Main - E | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Stone | #1 - Main - E | 28 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #5 - W | 1 | EA | 6 | 10+ years | Door marked #9 on site |
| | Exterior Doors - Transom Lite | #5 - W | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #5 - W | 3 | LF | 3 | 0-1 year | Cracked/Missing/Broken - Trip Hazard |
| | Exterior Doors - Exterior Steel Door | #6 - NW | 1 | EA | 6 | 10+ years | Door marked #10 on site |
| | Exterior Doors - Side lite | #6 - NW | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Stone | #6 - NW | 6 | LF | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #7 - NE | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #7 - NE | 3 | EA | 6 | 10+ years | Door Marked #11 on site |
| | Exterior Doors - Transom Lite | #7 - NE | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #7 - NE | 9 | LF | 6 | 10+ years | |
| | Exterior Doors - Side lite | #8 - Sidelight | 1 | EA | 6 | 2-5 years | |
| | Exterior Doors - Exterior Steel Door | #8 Door | 1 | EA | 6 | 2-5 years | |
| | Exterior Doors - Side lite | #8 Door | 1 | EA | 6 | 2-5 years | |



| Catego | ry : Exterior | | Building : Main | | | | | |
|----------|--|-----------------------------------|-----------------|-----|--------|-------------|----------------------------------|--|
| _ | | | | | | Recommend | _ | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Exterior Doors - Exterior Steel Door | N fire escape upper floors | 2 | EA | 6 | 10+ years | 3rd | |
| | Exterior Doors - Transom Lite | N fire escape upper floors | 2 | EA | 6 | 10+ years | | |
| Fire Esc | ape | | | | | | | |
| | Fire Escape | N elevation | 98 | LF | 5 | 2-5 years | | |
| oundat | ion | | | | | | | |
| | Foundation - Concrete | Entire Building | 86 | LF | 7 | 10+ years | | |
| | Foundation - Masonry | Entire Building | 432 | LF | 7 | 10+ years | | |
| | Superstructure - Slab on Grade | Entire Building | 32,081 | SF | 7 | 10+ years | | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 1,396 | SF | 7 | 10+ years | | |
| ighting | | | | | | | | |
| <u></u> | Exterior Lighting - Wall Mounted | Entire Building | 10 | EA | 6 | 10+ years | | |
| Roof Sys | stem | | | | | | | |
| | Coping - Metal | Elevator Roof (Construction Zone) | 62 | LF | 6 | 10+ years | | |
| | Downspouts - Interior Downspouts | Elevator Roof (Construction Zone) | 60 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | Elevator Roof (Construction Zone) | 62 | LF | 6 | 10+ years | | |
| | Roof - Modified Bitumen | Elevator Roof (Construction Zone) | 452 | SF | 6 | 10+ years | | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Elevator Roof (Construction Zone) | 452 | SF | 7 | 10+ years | | |
| | Access Ladder - Metal | Lower Roofs | 1 | EA | 7 | 10+ years | | |
| | Chimney - Metal Flue | Lower Roofs | 20 | LF | 6 | 10+ years | | |
| | Coping - Clay Tile | Lower Roofs | 195 | LF | 6 | 10+ years | | |
| | Coping - Clay Tile | Lower Roofs | 6 | LF | 5 | 0-1 year | Damaged, cracked | |
| | Coping - Metal | Lower Roofs | 48 | LF | 6 | 10+ years | Damageu, clackeu | |
| | Downspouts - Interior Downspouts | Lower Roofs | 140 | LF | 6 | 10+ years | Displaced/Missing Baskets Covers | |
| | Parapet - 16" - 30" Height | Lower Roofs | 53 | LF | 6 | | Displaced/Missing Baskets Covers | |
| | Parapet - Parapet < 16" Height | Lower Roofs | 196 | LF | 5 | 6-10 years | | |
| | Roof - Asphalt Gravel Ballast | Lower Roofs | 4,539 | SF | 5 | 6-10 years | | |
| | • | | | SF | 5 6 | 2-5 years | | |
| | Roof - Metal | Lower Roofs Lower Roofs | 48 509 | SF | 6 | 10+ years | | |
| | Roof - Modified Bitumen | | | | - | 10+ years | | |
| | Roof Structure - Steel with Clay Tile Arch | Lower Roofs | 5,096 | SF | 7 | 10+ years | | |
| | Access Ladder - Metal | Main Roof | 2 | EA | 7 | 10+ years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Main Roof | 60 | LF | 5 | 2-5 years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Main Roof | 40 | LF | 4 | 1-2 years | Brick/Mortar - Cracked | |
| | Coping - Clay Tile | Main Roof | 383 | LF | 6 | 10+ years | | |
| | Downspouts - Exterior Downspouts | Main Roof | 12 | LF | 6 | 10+ years | | |
| | Downspouts - Interior Downspouts | Main Roof | 672 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | Main Roof | 373 | LF | 6 | 10+ years | | |
| | | | 515 | | 0 | ior years | | |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|---------|---|-----------------|----------|---------|--------|--------------------------|--|
| | , | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Parapet - 16" - 30" Height | Main Roof | 10 | LF | 5 | 2-5 years | |
| | Roof - Asphalt Shingle | Main Roof | 5,481 | SF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Main Roof | 2,491 | SF | 6 | 10+ years | |
| | Roof Hatch - Metal | Main Roof | · 1 | EA | 5 | 2-5 years | Aged/Outdated - Rust |
| | Roof Structure - Heavy Timber | Main Roof | 7,972 | SF | 7 | 10+ years | 5 |
| | Parapet - 16" - 30" Height | Main Roof | 20 | LF | 5 | 2-5 years | Leaks/cracked - Joints Compromise |
| | | | | | | | at End/Edge of Shingle Roof where Parapet begins. |
| | Roof - Asphalt Shingle | Main Roof | 30 | SF | 5 | 2-5 years | r drupet begins. |
| | Roof Structure - Heavy Timber | Main Roof | 30 | SF | 7 | 10+ years | |
| | Roof Official Proavy Hinber | | 00 | 01 | , | Tor years | |
| Valls | | | | | | | |
| | Cheek-Wall - Stone | Entire Building | 12 | SF | 6 | 10+ years | |
| | Cornice - Masonry Projecting Limestone | Entire Building | 113 | LF | 5 | 2-5 years | |
| | Cornice - Metal Projecting | Entire Building | 113 | LF | 4 | 1-2 years | Rust/Corrosion/Missing Component - Loose and Detaching in Spots |
| | Exterior Walls - Brick | Entire Building | 4,384 | SF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 9,500 | SF | 5 | 6-10 years | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 104 | SF | 6 | 2-5 years | |
| | Exterior Walls - Stone-Cast | Entire Building | 1,071 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 15 | SF | 5 | 2-5 years | Rust/corrosion/deterioration at Cornice - Projecting "Metal" at North |
| | Exterior Walls - Stone-Cut | Entire Building | 452 | SF | 6 | 10+ years | Facade |
| Vindows | | | | | | | |
| | Guard - Guards perforated | Entire Building | 1,272 | SF | 6 | 10+ years | Quantity adjusted |
| | Guard - Guards wire guard | Entire Building | ., | SF | 5 | 2-5 years | See Windows Main East |
| | Lintels - Brick | Entire Building | 30 | LF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 266 | LF | 6 | 6-10 years | |
| | Lintels - Stone | Entire Building | 122 | LF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 3,057 | SF | 6 | 10+ years | |
| | Guard - Guards wire guard | Main East | 30 | SF | 6 | 2-5 years | |
| | Windows - Louver | Main East | 30 | SF | 7 | 2-5 years | Scrape/Paint - Louver |
| | Guard - Guards perforated | Main West | 12 | SF | 4 | 0-1 year | Guard Cut/Ripped |
| Catego | ry : Electrical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| - | | | Quantity | | Nalik | Replacement | ooninging |
| merger | ncy System Automatic Transfer Switch | Electrical Room | 1 | EA | 4 | 2-5 years | Deteriorated, not reliable, functional |
| | Emergency A/C Power - Corridors and | Entire Building | 6,452 | SF | 6 | 6-10 years | , , , , , , , , , , , , , , , , , , , |




| Catego | ry : Electrical | | В | uilding | : Main | | |
|-----------|---|-----------------|----------|---------|--------|-------------|--------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Stairs | | 4 000 | 05 | 0 | 0.40 | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,028 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,111 | SF | 6 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 19 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 23 | EA | 6 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 2 | 0-1 year | No battery pack |
| | Security System - CCTV | Entire Building | 38,332 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 38,332 | SF | 6 | 6-10 years | |
| Main Se | rvice | | | | | | |
| | Main Electrical Service - 1200 A | Electrical Room | 1 | EA | 6 | 10+ years | Serves main building |
| | 120/208/3PH | | | Ξ. | | 0.5 | |
| | Independent Electrical Service for | Electrical Room | 1 | EA | 4 | 2-5 years | ATS and meter, serves main building |
| | emergency power | | | | | | ATS panel is deteriorated, more than |
| | | | | ~- | | | 50 years old, functional |
| | PA System | Entire Building | 38,332 | SF | 6 | 6-10 years | Connected to annex |
| Power D | listribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 10 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 7 | EA | 7 | 10+ years | 7 found |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | Previously not assessed |
| Catego | ry : Fire Protection | | в | uilding | • Main | | |
| Galego | | | | unung | . mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | | | , | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | Serves main building and annex |
| | Fire Alarm Strobe Lights | Entire Building | 38,332 | SF | 6 | 6-10 years | berves main building and armex |
| | Fire Alarm_System | Entire Building | 38,332 | SF | 6 | 6-10 years | Serves main building, connected to |
| | hie Alam_oystem | | 00,002 | 0i | U | o to years | annex building |
| _Sprinkle | r System | | | | | | |
| | Dry Sprinkler System | Entire Building | 38,332 | SF | 6 | 6-10 years | Fire pump located in 2020 annex. Dry |
| | bry optimiter bystern | Entre Duliding | 50,552 | 0 | 0 | 0-10 years | system components in main building |
| | Sprinkler Heads | Entire Building | 38,332 | SF | 7 | 10+ years | system components in main building |
| | Sprinkler Piping | Entire Building | 38,332 | SF | 6 | 6-10 years | |
| | | | 30,332 | ЗГ | 0 | 0-10 years | |



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|-----------|--|---------------------------|----------|---------|--------|-------------|--|
| _ | | | • | | | | - |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Cond | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 3 | EA | 5 | 6-10 years | Previously no assessed, serve evaporator fan coil units |
| Air Hand | ling Systems | | | | | | |
| | Fan Coil Unit- Celing Mounted - Electric | 1st Floor | 3 | EA | 6 | 6-10 years | 4th unit in MDF room not assessed, see interior assessment |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | Attic | 1 | EA | 6 | 6-10 years | Serves air handler AHU 1 |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm | Basement | 1 | EA | 5 | 6-10 years | AHU 1, serves main building |
| | Air Intake | Basement | 1 | EA | 6 | 6-10 years | |
| | Auxiliaries - 25001 - 35000 cfm | Basement | 1 | EA | 5 | 6-10 years | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Basement | 100 | LF | 6 | 6-10 years | |
| | Zone Dampers | Basement | 22 | EA | 6 | 6-10 years | |
| Boiler Sy | stems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Chemical Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Condensate Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP | Boiler Room | 2 | EA | 6 | 6-10 years | Recently retubed |
| | Piping - Condensate Pipe- Steel | Boiler Room | 250 | LF | 5 | 6-10 years | Minor leaks occasionally repaired. Functional |
| | Piping - Steam Pipe- Steel | Boiler Room | 250 | LF | 5 | 6-10 years | There are a few pipe clamps, functional |
| | Steam Traps | Boiler Room | 11 | EA | 5 | 6-10 years | Steam traps are periodically inspected and serviced |
| leating I | | | | | | | |
| | Radiators - Steam | 2nd Floor | 1 | EA | 5 | 6-10 years | Previously not assessed |
| | Fin Tube - Steam | 2nd floor Teachers Lounge | 5 | LF | 5 | 6-10 years | |
| | Wall Heater - Electric | Entire Building | 8 | EA | 6 | 10+ years | |
| | Wall Heater - Electric | Entire Building | 2 | EA | 5 | 6-10 years | |
| | Cabinet Heaters - With Electric Coil | Entire Building | 6 | EA | 6 | 6-10 years | Ceiling mounted |
| | Unit Heater - Electric | Entire Building | 3 | EA | 5 | 6-10 years | - |
| | Unit Heater - Electric | Entire Building | 4 | EA | 4 | 2-5 years | Serviced. Still works, not reliable |
| | Unit Heater - Steam | Entire Building | 1 | EA | 5 | 6-10 years | , |



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|------------|---|--------------------------------------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Unit Heater - Steam | Entire Building | 2 | EA | 4 | 2-5 years | Functional, not reliable |
| Tempera | ture Control | | | | | | |
| | DDC System | Entire Building | 38,332 | SF | 6 | 6-10 years | Serves main building, 2010 software upgrade |
| | Electric Controls | Entire Building | 38,332 | SF | 5 | 6-10 years | Remote electrical controls, serve evaporator fan coil units |
| | Electric Thermostat | Entire Building | 5 | EA | 5 | 6-10 years | Serves unit heaters |
| | | 5 | 1 | EA | 4 | | Old, difficult to control temperature, |
| | Electric Thermostat | Entire Building | I | EA | 4 | 2-5 years | serves unit heater, not calibrated |
| | Thermostats - DDC | Entire Building | 22 | EA | 6 | 6-10 years | Control 22 zone dampers |
| Ventilatio | on | | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | 2nd floor - Teachers Restroom & Roof | 1 | EA | 6 | 6-10 years | Thru window |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2nd floor - Teachers Restroom & Roof | 2 | EA | 6 | 6-10 years | |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 38,332 | SF | 6 | 6-10 years | Portions of pipes replaced with copper pipes |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 38,332 | SF | 4 | 2-5 years | Many clamps |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 38,332 | SF | 4 | 2-5 years | Occasionally repaired |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 38,332 | SF | 4 | 2-5 years | Many clamps |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 38,332 | SF | 4 | 2-5 years | Many clamps |
| | Domestic Piping-Hot/Cold Water Supply | Entire Building | 38,332 | SF | 4 | 2-5 years | Many clamps, occasional leaks |
| | (from Risers to Fixtures) | Entire Building | 20 222 | oг | F | 6 10 10000 | |
| | Sanitary Piping | Entire Building | 38,332 | SF | 5 | 6-10 years | |
| | Storm Piping | Entire Building | 38,332 | SF | 5 | 6-10 years | |
| | Vent Piping | Entire Building | 38,332 | SF | 6 | 6-10 years | |
| oumps | | | | | | | |
| | Pumps - Sump-Simplex | 1st Floor | 1 | EA | 6 | 10+ years | Under elevator, previously not assessed in main building |
| Catego | ry : Room | | В | uilding | : Main | | |
| | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments |





| 66116618 | | | | | 10 | 556 5 Langley AVENUE, Chicago, IL 0002 |
|-----------------------------|---|-------|----------|---|-------------|---|
| | | | | | Replacement | |
| AC Unit | 2nd Floor - Room 208, Teacher's Office | 1 | EA | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor - Room 208, Teacher's Office | 397 | SF | 7 | 10+ years | |
| Doors - Steel Doors incl hw | 2nd Floor - Room 208, Teacher's Office | 1 | EA | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 2nd Floor - Room 208, Teacher's Office | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 2nd Floor - Room 208, Teacher's Office | 397 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor - Room 208, Teacher's Office | 6 | EA | 7 | 10+ years | |
| Power Distribution | 2nd Floor - Room 208, Teacher's Office | 6 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | 2nd Floor - Room 208, Teacher's Office | 516 | SF | 7 | 10+ years | |
| Work SInk | 2nd Floor - Room 208, Teacher's Office | 1 | EA | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | 3rd Floor - Room 307, Next to Stage | 106 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor - Room 307, Next to Stage | 150 | SF | 6 | 0-1 year | |
| Doors - Wood Doors inclu hw | 3rd Floor - Room 307, Next to Stage | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 3rd Floor - Room 307, Next to Stage | 256 | SF | 6 | 6-10 years | |
| Lighting - Pendent/Surface | 3rd Floor - Room 307, Next to Stage | 4 | EA | 6 | 6-10 years | |
| Power Distribution | 3rd Floor - Room 307, Next to Stage | 4 | EA | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 3rd Floor - Room 307, Next to Stage | 474 | SF | 7 | 10+ years | |
| AC Unit | 3rd Floor, Conference Room | 4/4 | EA | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor, Conference Room | 405 | SF | 6 | 6-10 years | |
| Doors - Steel Doors incl hw | 3rd Floor, Conference Room | 405 | EA | 7 | | |
| | | | | | 6-10 years | |
| Doors - Wood Doors inclu hw | 3rd Floor, Conference Room | 1 | EA SF | 7 | 6-10 years | |
| Floor - Carpet | 3rd Floor, Conference Room | 405 | | 6 | 6-10 years | |
| Lighting - Pendent/Surface | 3rd Floor, Conference Room | 10 | EA | 7 | 6-10 years | |
| Power Distribution | 3rd Floor, Conference Room | 16 | EA | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 3rd Floor, Conference Room | 1,294 | SF | 6 | 10+ years | Observed stars stilling Dauly |
| Ceiling - Plaster/Drywall | Basement - Engineer's Office | 113 | SF | 7 | 6-10 years | Observed clean ceiling. Rank changed to update current observation. |
| Doors - Wood Doors inclu hw | Basement - Engineer's Office | 1 | EA | 7 | 6-10 years | |
| Floor - Tile | Basement - Engineer's Office | 113 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | Basement - Engineer's Office | 2 | EA | 7 | 6-10 years | |
| Power Distribution | Basement - Engineer's Office | 4 | EA | 7 | 10+ years | |
| Walls - Masonry | Basement - Engineer's Office | 103 | SF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | Basement - Engineer's Office | 137 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | Basement - Room 010, Staff Lounge | 103 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | Basement - Room 010, Staff Lounge | 1 | EA | 7 | 10+ years | |
| Floor - Tile | Basement - Room 010, Staff Lounge | 103 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | Basement - Room 010, Staff Lounge | 1 | EA | 7 | 10+ years | Rank changed to update current |

observation.



| | chools | | | | | 10 | 538 S Langley AVENUE, Chicago, IL 6062 |
|----------|---------------------------------|--|--------------------|----|---|-------------|--|
| | | | | | | Replacement | |
| | Power Distribution | Basement - Room 010, Staff Lounge | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Basement - Room 010, Staff Lounge | 120 | SF | 7 | 10+ years | |
| | Walls - Masonry | Basement - Room 010, Staff Lounge | 40 | SF | 7 | 10+ years | |
| | | | | | | | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | 003 Faculty Lounge | 480 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 003 Faculty Lounge | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 003 Faculty Lounge | 480 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 003 Faculty Lounge | 6 | EA | 7 | 10+ years | |
| | Market Board | 003 Faculty Lounge | 10 | LF | 7 | 10+ years | |
| | Walls - Masonry | 003 Faculty Lounge | 81 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 003 Faculty Lounge | 720 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 1,028 | SF | 7 | 6-10 years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 1,028 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Basement | 14 | EA | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 1,593 | SF | 7 | 10+ years | |
| | Wallo Macolity | Basement | 1,000 | 01 | , | ior youro | |
| MDF IDF | = | | | | | | |
| _ | Doors - Wood Doors inclu hw | In Classroom 203 | 1 | EA | 7 | 10+ years | |
| | Finishes | In Classroom 203 | 158 | SF | 7 | 10+ years | Observed painted walls. |
| | Window AC Unit | In Classroom 203 | 1 | EA | 7 | 6-10 years | |
| | | | | | | | |
| Mechanic | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 10 | SF | 7 | 6-10 years | Observed painted walls. |
| | Janitor's Closet | 2nd Floor | 10 | SF | 7 | 10+ years | · |
| | Janitor's Closet | 3rd Floor | 10 | SF | 7 | 10+ years | |
| | Boiler Room | Basement | 1,195 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 350 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 150 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 1,066 | SF | 5 | 6-10 years | |
| | Mechanical/ Service Rooms | Basement - Fan Room | 254 | SF | 7 | 10+ years | |
| | | | | | | - | |
| Restroom | | | | | | | |
| | Accessories | 1st Floor - in 101 | 44 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor - in 101 | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor - in 101 | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor - in 101 | 44 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor - in 101 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor - in 101 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor - in 101 | 1 | EA | 7 | 10+ years | |
| | • | | | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor - in 101 | 1 | | | TOF years | |
| | Lighting - Wall Mounted | 1st Floor - in 101 1st Floor - in 101 | 1 1 | EA | 7 | 10+ years | |
| | | | 1 1 160 | | | • | |
| | Lighting - Wall Mounted | 1st Floor - in 101 | 1 1 160 1 | EA | 7 | 10+ years | |



| 36110613 | | | | | 10: | 536 S Langley AVENUE, Chicago, IL 6062 |
|---|-------------|-----|----|---|-------------|--|
| | | | | | Replacement | |
| Ceiling - Plaster/Drywall | 2nd Floor | 198 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Floor - Tile Ceramic/ Porcelain | 2nd Floor | 198 | SF | 7 | 6-10 years | |
| Floor Drain | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Hand Dryer | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Lavatory | 2nd Floor | 2 | EA | 7 | 10+ years | Observed clean lavatories. Rank |
| Lavalory | 21011001 | Z | LA | ' | IUT years | changed to update current |
| | | | | | | observation. |
| Lighting Developt/Curfage | Orad Elegan | F | | 7 | 0.10 | ODServation. |
| Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | 6-10 years | |
| Partitions | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| Urinals | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 139 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | 2nd Floor | 139 | SF | 7 | 10+ years | |
| Water Closet | 2nd Floor | 3 | EA | 7 | 10+ years | |
| Accessories | 3rd Floor | 201 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | 3rd Floor | 201 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 3rd Floor | 200 | SF | 6 | 6-10 years | |
| Floor - Tile | 3rd Floor | 2 | SF | 4 | 0-1 year | Damaged |
| Floor Drain | 3rd Floor | 1 | ĒA | 7 | 6-10 years | |
| Hand Dryer | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Lavatory | 3rd Floor | 2 | EA | 7 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | - 5 | EA | 6 | 6-10 years | |
| Partitions | 3rd Floor | 5 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | 3rd Floor | 202 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | 3rd Floor | 202 | SF | 7 | 10+ years | |
| Walls - The Ceramic Torcelain Water Closet | 3rd Floor | 5 | EA | 7 | 10+ years | |
| | | 245 | SF | | | |
| Accessories | Basement | | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | Basement | 245 | | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| Floor - Tile Ceramic/ Porcelain | Basement | 245 | SF | 7 | 10+ years | |
| Floor Drain | Basement | 1 | EA | 7 | 10+ years | |
| Hand Dryer | Basement | 1 | EA | 7 | 6-10 years | |
| Lavatory | Basement | 2 | EA | 7 | 10+ years | |
| Lighting - Pendent/Surface | Basement | 5 | EA | 7 | 10+ years | |
| Partitions | Basement | 2 | EA | 7 | 10+ years | |
| Urinals | Basement | 3 | EA | 7 | 10+ years | |
| Walls - Concrete Block | Basement | 172 | SF | 7 | 10+ years | |
| Walls - Structural Glazed Tile | Basement | 86 | SF | 7 | 10+ years | |
| Walls - Tile Ceramic/ Porcelain | Basement | 86 | SF | 7 | 10+ years | |
| Water Closet | Basement | 2 | EA | 7 | 10+ years | |
| Accessories | Basement | 246 | SF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | Basement | 246 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | Basement | 1 | ĒA | 6 | 6-10 years | |
| Floor - Tile Ceramic/ Porcelain | Basement | 246 | SF | 7 | 6-10 years | |
| Floor Drain | Basement | 1 | EA | 7 | 10+ years | |
| Hand Dryer | Basement | 1 | EA | 7 | 6-10 years | |
| | Duschieft | 1 | LA | ' | o io years | |



| | | | | | 105 | 538 S Langley AVENUE, Chicago, IL 60628 |
|---|--|---------|----------|--------|------------------------|---|
| | | | | | Replacement | |
| Lavatory | Basement | 2 | EA | 7 | 6-10 years | |
| Lighting - Pendent/Surface | Basement | 4 | EA | 7 | 6-10 years | Observed fixtures functioning and properly working. Rank changed to update current observation. |
| Partitions | Basement | 5 | EA | 7 | 6-10 years | |
| Walls - Concrete Block | Basement | 191 | SF | 7 | 10+ years | |
| Walls - Masonry | Basement | 191 | SF | 7 | 6-10 years | |
| Water Closet | Basement | 5 | EA | 7 | 10+ years | |
| Accessories | Basement - Room 009 | 78 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | Basement - Room 009 | 78 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Basement - Room 009 | 1 78 | EA SF | 7 | 10+ years | |
| Floor - Tile | Basement - Room 009 | | | 7 | 10+ years | |
| Lavatory Lighting - Pendent/Surface | Basement - Room 009 | 1 1 | EA | 7 7 | 10+ years | |
| Partitions | Basement - Room 009 Basement - Room 009 | 2 | EA EA | 7 | 10+ years 10+ years | |
| Walls - Concrete Block | Basement - Room 009 | 61 | SF | 7 | 10+ years | |
| Walls - Concrete Block Walls - Masonry | Basement - Room 009 | 61 | SF | 7 | 10+ years | |
| Water Closet | Basement - Room 009 | 2 | EA | 7 | 10+ years | |
| Accessories | Basement inside Boiler Room | 32 | SF | 7 | 6-10 years | |
| | Existing | - | | | - | |
| Ceiling - Plaster/Drywall | Basement inside Boiler Room Existing | 32 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | Basement inside Boiler Room Existing | 1 | EA | 7 | 10+ years | |
| Floor - Concrete | Basement inside Boiler Room Existing | 32 | SF | 7 | 10+ years | |
| Lavatory | Basement inside Boiler Room Existing | 1 | EA | 6 | 2-5 years | Works- needs support leg |
| Lighting - Pendent/Surface | Basement inside Boiler Room Existing | 1 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall | Basement inside Boiler Room Existing | 192 | SF | 7 | 10+ years | Observed painted walls. |
| Water Closet | Basement inside Boiler Room Existing | 1 | EA | 7 | 10+ years | |
| Accessories | Basement- Men's Next to Unisex | 81 | SF | 7 | 6-10 years | New Asset |
| Ceiling - Plaster/Drywall | Basement- Men's Next to Unisex | 81 | SF | 7 | 10+ years | New Asset |
| Doors - Wood Doors inclu hw | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Floor - Tile | Basement- Men's Next to Unisex | 81 | SF | 6 | 10+ years | New Asset |
| Floor Drain | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Lavatory | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Lighting - Pendent/Surface | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Partitions | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Urinals | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Walls - Concrete Block | Basement- Men's Next to Unisex | 220 | SF | 7 | 10+ years | |
| Walls - Masonry | Basement- Men's Next to Unisex | 140 | SF | 7 | 10+ years | |
| Water Closet | Basement- Men's Next to Unisex | 1 | EA | 7 | 10+ years | New Asset |
| Accessories | In Principal's Office | 45 | SF | 7 | 6-10 years | |

Campus Name: Poe





| up | Item - Type m #001 (Music Room) | Location | Quantity | UOM | Rank | Replacement | Comments |
|----|------------------------------------|---|----------|---------|------|-------------|----------|
| | ry : Classroom | Location | | uilding | | Recommend | Commonia |
| | | | | | | , youro | |
| | Water Closet | Unisex Room in Basement | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Unisex Room in Basement | 77 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Unisex Room in Basement | 1 | EA | 7 | 10+ years | |
| | Lavatory | Unisex Room in Basement | 1 | EA | 7 | 10+ years | |
| | Floor Drain | Unisex Room in Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete | Unisex Room in Basement | 53 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Unisex Room in Basement | 1 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Unisex Room in Basement | 53 | SF | 7 | 10+ years | |
| | Accessories | Unisex Room in Basement | 53 | SF | 7 | 10+ years | |
| | | Custodian Office | | | | | |
| | waiis - r lasiei/Drywall | Locker room- Demolished Now | 100 | 0 | ' | ior years | |
| | Walls - Plaster/Drywall | Room 0-02, Custodian Restroom/ | 166 | SF | 7 | 10+ years | |
| | | Custodian Office | | | | | |
| | Walls - Metal Panel | Room 0-02, Custodian Restroom/ Locker room- Demolished Now | 166 | SF | 7 | 10+ years | |
| | Walls Matal Band | Custodian Office | 160 | сг | 7 | 10, 10000 | |
| | | Locker room- Demolished Now | | | | | |
| | Lighting - Pendent/Surface | Room 0-02, Custodian Restroom/ | 5 | EA | 7 | 10+ years | |
| | Lighting Dondont/Surface | Custodian Office | - | | 7 | 10, 10000 | |
| | | Locker room- Demolished Now | | | | | |
| | Lavatory | Room 0-02, Custodian Restroom/ | 2 | EA | 7 | 10+ years | |
| | Lavatory | | 2 | | 7 | 101 10000 | |
| | | Custodian Office | | | | | |
| | | Locker room- Demolished Now | 205 | 35 | 1 | iut years | |
| | Floor - Wood | Room 0-02, Custodian Restroom/ | 265 | SF | 7 | 10+ years | |
| | | Custodian Office | | | | | |
| | | Locker room- Demolished Now | 2 | LA | I | ior years | |
| | Doors - Wood Doors inclu hw | Room 0-02, Custodian Restroom/ | 2 | EA | 7 | 10+ years | |
| | | Custodian Office | | | | | |
| | | Locker room- Demolished Now | 200 | 0. | • | 101 youro | |
| | Ceiling - Exposed | Room 0-02, Custodian Restroom/ | 265 | SF | 7 | 10+ years | |
| | | Custodian Office | | | | | |
| | 1000000000 | Locker room- Demolished Now | 200 | 01 | ' | ior years | |
| | Accessories | Room 0-02, Custodian Restroom/ | 265 | SF | 7 | 10+ years | |
| | Water Closet | In Principal's Office | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | In Principal's Office | 252 | SF | 7 | 10+ years | |
| | Partitions | In Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | In Principal's Office | 1 | EA | 7 | 10+ years | |
| | Lavatory | In Principal's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | In Principal's Office | 45 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Principal's Office | 1 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | In Principal's Office | 45 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | B | uilding | : Main | | |
|----------|-----------------------------|-----------|-----------|---------|--------|------------------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Units | Basement | 1 | EA | 7 | 6-10 years | |
| | Casework | Basement | 12 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 988 | SF | 7 | 10+ years | Observed painted ceiling. |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Basement | 988 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 13 | EA | 6 | 10+ years | |
| | Marker Board | Basement | 22 | LF | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 1,280 | SF | 7 | 10+ years | Observed painted walls. |
| | Work Sink | Basement | 1 | EA | 7 | 10+ years | |
| Classroo | om #004 (Store Room) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 372 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 1-2 years | Damaged hardware |
| | Floor - Tile/Sheet | Basement | 372 | SF | 7 | 10+ years | - |
| | Lighting - Pendent/Surface | Basement | 4 | EA | 7 | 10+ years | |
| | Marker Board | Basement | 8 | LF | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 135 | SF | 7 | 10+ years | 15 ft length |
| | Walls - Plaster/Drywall | Basement | 693 | SF | 7 | 10+ years | 1 |
| Classroo | om #101 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 834 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 834 | SF | 7 | 6-10 years | Observed clean floor. Rank changed to update current observation. |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 30 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 174 | SF | 7 | 10+ years | Classroom Storage Room |
| | Walls - Plaster/Drywall | 1st Floor | 1,534 | SF | 7 | 10+ years | Classicolin Clorage Room |
| Classroo | om #102 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 834 | SF | 6 | 6-10 years | Panted |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 826 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 8 | SF | 4 | 1-2 years | Damaged flooring |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | 10+ years | Damagea nooning |
| | Marker Board | 1st Floor | 25 | LA | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 25 150 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,543 | SF | 7 | 10+ years 10+ years | |
| Classro | om #103 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | | 15111001 | 1 | LA | 1 | U-TO years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 1st Floor | 832 | SF | 7 | 10+ years | Observed painted ceiling. Rank changed to update current observation. |
| | Ceiling - Plaster/Drywall | 1st Floor | 2 | SF | 6 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 824 | SF | 7 | 10+ years | Observed clean floor. Rank changed to update current observation. |
| | Floor - Tile | 1st Floor | 10 | SF | 4 | 1-2 years | Damaged flooring |
| | Lighting - Pendent/Surface | 1st Floor | 17 | EA | 7 | 6-10 years | 3 |
| | Marker Board | 1st Floor | 30 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 161 | SF | 7 | 10+ years | Classroom Storage Closet |
| | Walls - Plaster/Drywall | 1st Floor | 1,534 | SF | 7 | 10+ years | Rank changed to update current observation. |
| Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 834 | SF | 5 | 0-1 year | Peeling throughout |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 834 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 11 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 5 | 0-1 year | Damaged & missing lenses |
| | Marker Board | 2nd Floor | 27 | LF | 6 | 6-10 years | с с |
| | Storage/ Closet | 2nd Floor | 161 | SF | 5 | 0-1 year | Observed peeling paint throughout. |
| | Walls - Plaster/Drywall | 2nd Floor | 1,543 | SF | 5 | 0-1 year | Peeling throughout |
| Classroo | om #203 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,523 | SF | 7 | 10+ years | Observed painted ceiling. Rank changed to update current observation. |
| | Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 6 | 6-10 years | |
| | Floor - Carpet | 2nd Floor | 1,523 | SF | 7 | 6-10 years | Rank changed to update current observation. New carpet. |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | 6-10 years | Observed new fixture. Rank changed to update current observation. |
| | Walls - Concrete Block | 2nd Floor | 1,844 | SF | 7 | 10+ years | |
| Classroo | om #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 834 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 834 | SF | 7 | 6-10 years | Observed clean floor. Rank changed to update current observation. |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | 6-10 years | Quantity changed to include 2 fixtures in Storage Room. Rank changed to update current observation. |
| | Marker Board | 2nd Floor | 35 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 137 | SF | 7 | 10+ years | Storage Room in Classroom |
| | Walls - Plaster/Drywall | 2nd Floor | 1,543 | SF | 7 | 10+ years | Observed painted walls. Rank changed to update current observation. |
| Classroo | om #205 (Art Room) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 834 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 831 | SF | 6 | 6-10 years | Observed clean floor. Rank changed to update current observation. |
| | Floor - Tile | 2nd Floor | 3 | SF | 4 | 1-2 years | Damaged tiles |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | 6-10 years | Observed working fixtures. Quantity changed to include 2 fixtures in Storage Room. Rank changed to update current observation. |
| | Marker Board | 2nd Floor | 35 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,543 | SF | 7 | 6-10 years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #301 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 824 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 10 | SF | 5 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 834 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 27 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,543 | SF | 7 | 10+ years | |
| Classroo | om #303 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 834 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 834 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 50 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,543 | SF | 7 | 10+ years | |



| Category : Classroom | | В | uilding | : Main | 1 | | |
|----------------------|--------------------------------------|-------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | om #304 (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 841 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 9 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 24 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 825 | SF | 7 | 10+ years | |
| | | | | | | | |
| Classroo | om #305 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 830 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 834 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 50 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,543 | SF | 7 | 10+ years | |
| | - | | | | | - | |
| Classroo | om #308 (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 986 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 986 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 6 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 24 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 860 | SF | 7 | 10+ years | |
| ^atero | ry : Interior | | B | uilding | • Main | | |
| oalego | | | | unung | . mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,402 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors include hw | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | 10+ years | Only 2 |
| | Floor - Asphalt Floor | 1st Floor | 1,402 | SF | 7 | 6-10 years | - 5 |
| | Lighting - Pendent/Surface | 1st Floor | 28 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 3,320 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor - By Elevator | 220 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | 1st Floor - By Elevator | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor - By Elevator | 220 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor - By Elevator | 5 | SF | 4 | • | |
| | Lighting - Pendent/Surface | 1st Floor - By Elevator | | EA | 4 | 1-2 years | |
| | | | 3 | SF | | 10+ years | |
| | Walls - Concrete Block | 1st Floor - By Elevator | 310 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - By Elevator | 660 | 55 | 7 | 10+ years | |
| | | | | | | | |



| Catego | Category : Interior | | В | uilding | : Main | | | |
|--------|--------------------------------------|-------------------------|----------|---------|--------|-------------|---|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,375 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | Doors - Wood Doors include hw | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 3 | EA | 7 | 6-10 years | | |
| | Floor - Asphalt Floor | 2nd Floor | 1,375 | SF | 7 | 6-10 years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 18 | EA | 7 | 6-10 years | | |
| | Lighting - Wall Mounted | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Student Lockers - Three Tiers | 2nd Floor | 8 | EA | 7 | 10+ years | | |
| | Student Lockers - Two Tiers | 2nd Floor | 61 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 3,200 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor - By Elevator | 217 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors include hw | 2nd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | 2nd Floor - By Elevator | 100 | SF | 7 | 10+ years | | |
| | Floor - Tile/Sheet | 2nd Floor - By Elevator | 117 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | 2nd Floor - By Elevator | 320 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor - By Elevator | 680 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,375 | SF | 7 | 10+ years | | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 3 | EA | 7 | 10+ years | | |
| | Floor - Tile/Sheet | 3rd Floor | 1,375 | SF | 7 | 6-10 years | | |
| | Lighting - Pendent/Surface | 3rd Floor | 19 | EA | 7 | 6-10 years | | |
| | Lighting - Wall Mounted | 3rd Floor | 2 | EA | 7 | 6-10 years | | |
| | Student Lockers - Three Tiers | 3rd Floor | 32 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 3rd Floor | 320 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,880 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 3rd Floor - By Elevator | 217 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 3rd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors include hw | 3rd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile/Sheet | 3rd Floor - By Elevator | 100 | SF | 7 | 10+ years | | |
| | Floor - Tile/Sheet | 3rd Floor - By Elevator | 113 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor - By Elevator | 1 | EA | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 3rd Floor - By Elevator | 4 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | 3rd Floor - By Elevator | 320 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor - By Elevator | 680 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Basement | 572 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | Basement | 1,716 | SF | 7 | 6-10 years | | |
| | Doors - Wood Doors include hw | Basement | 10 | EA | 7 | 6-10 years | | |
| | Drinking Fountains - Single Fountain | Basement | 3 | EA | 7 | 6-10 years | | |
| | Floor - Concrete Epoxy/ Painted | Basement | 2,288 | SF | 5 | 2-5 years | Visible cracks but flooring is sealdnature of the material | |
| | Lighting - Lay-in | Basement | 2 | EA | 7 | 6-10 years | | |
| | Lighting - Pendent/Surface | Basement | 19 | EA | 7 | 6-10 years | | |



| Catego | ry : Interior | | В | uilding | : Main | | |
|--------|-------------------------------|-----------|----------|---------|--------|-------------|--------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Wall Mounted | Basement | 2 | EA | 7 | 10+ years | |
| | Stairs - Terrazzo | Basement | 10 | LF | 7 | 6-10 years | |
| | Student Lockers - Three Tiers | Basement | 12 | EA | 7 | 10+ years | |
| | Walls - Masonry | Basement | 2,115 | SF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 2,115 | SF | 7 | 6-10 years | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Security Cameras | 1st Floor | 6 | EA | 7 | 6-10 years | Observed 6 cameras |
| | Camera Viewing Station | exterior | 1 | EA | 7 | 10+ years | |
| | Security Cameras | exterior | 4 | EA | 7 | 10+ years | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | East | 200 | SF | 7 | 10+ years | |
| | Floor - Asphalt | East | 316 | SF | 7 | 10+ years | |
| | Handrails | East | 102 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | East | 9 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | East | 2 | EA | 7 | 10+ years | |
| | Stairs - Asphalt | East | 200 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | East | 1,310 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | North | 292 | SF | 6 | 6-10 years | |
| | Floor - Asphalt | North | 292 | SF | 6 | 6-10 years | |
| | Handrails | North | 88 | LF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | North | 3 | EA | 6 | 6-10 years | |
| | Stairs - Asphalt | North | 32 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | North | 453 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | South | 393 | SF | 6 | 6-10 years | |
| | Floor - Asphalt | South | 393 | SF | 7 | 6-10 years | |
| | Handrails | South | 124 | LF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | South | 2 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | South | 2 | EA | 7 | 6-10 years | |
| | Stairs - Asphalt | South | 32 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | South | 609 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | West | 600 | SF | 7 | 10+ years | |
| | Floor - Asphalt | West | 150 | SF | 7 | 10+ years | |
| | Handrails | West | 100 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | West | 3 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | West | 4 | EA | 7 | 10+ years | |
| | Stairs - Asphalt | West | 360 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | West | 1,230 | SF | 7 | 10+ years | |



Category : Exterior Building : Annex Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Entrance 2 FΑ 7 Exterior Doors - Store Front Annex #2 10+ years 75 LF 7 Ramp Handrail - Steel Ramp Handrail Annex #2 10+ years Ramps - Concrete LF Annex #2 40 7 10+ years Exterior Doors - Exterior Steel Door Annex #3 2 ΕA 7 10+ years 75 LF Ramp Handrail - Steel Ramp Handrail Annex #3 7 10+ years LF 7 Ramps - Concrete Annex #3 40 10+ years Entrance Control - Audio and Video Annex #4 1 EΑ 7 10+ years Exterior Doors - Store Front Annex #4 2 ΕA 7 10+ vears Power Door Operator and Controls Annex #4 1 EΑ 7 10+ years LF 7 Ramp Handrail - Steel_Ramp Handrail Annex #4 65 10+ vears LF Ramps - Concrete Annex #4 30 7 10+ years 7 Exterior Doors - Exterior Steel Door Annex #5 EΑ 10+ years 1 Ramp Handrail - Steel Ramp Handrail Annex #5 75 LF 7 10+ years LF Ramps - Concrete Annex #5 35 7 10+ years Entrance Control - Audio and Video Annex #6 1 ΕA 7 10+ years Exterior Doors - Exterior Steel Door Annex #6 2 FΑ 7 10+ years Entrance Control - Audio and Video Annex #7 1 ΕA 7 10+ vears Exterior Doors - Store Front Annex #7 2 FΑ 7 10+ vears Exterior Doors - Transom Lite Annex #7 2 ΕA 7 10+ years 7 Exterior Doors - Exterior Steel Door Annex #8 - Roof Access Door 1 EΑ 10+ years Exterior Stairs - Steel or Aluminum Annex #8 - Roof Access Door LF 7 24 10+ years Roof Ladder/Stair LF Stair Handrail - Steel_Stair Handrail Annex #8 - Roof Access Door 12 7 10+ years Roof Ladder/Stair Foundation Foundation - Concrete LF 7 Annex 337 10+ years Superstructure - Slab on Grade Annex 9,940 SF 7 10+ years Liahtina Exterior Lighting - Wall Mounted Annex 19 ΕA 7 10+ years Roof System Access Ladder - Metal Annex - Roof C ΕA 7 1 10+ years LF Coping - Metal Annex - Roof C 130 7 10+ years **Downspouts - Interior Downspouts** Annex - Roof C 150 LF 7 10+ years Parapet - Parapet > 30" LF Annex - Roof C 130 7 10+ vears Roof - Modified Bitumen SF Annex - Roof C 750 7 10+ years Roof Structure - Steel / Metal Deck/ Annex - Roof C 750 SF 7 10+ years Concrete Topping Access Ladder - Metal Annex Roof A EA 7 10+ years 1 LF Coping - Metal Annex Roof A 324 7 10+ years LF 7 **Downspouts** - Interior Downspouts Annex Roof A 126 10+ years



| Catego | ry : Exterior | | В | uilding | : Annex | , | |
|---------|--------------------------------------|--------------|----------|---------|---------|-------------|-------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Parapet - 16" - 30" Height | Annex Roof A | 324 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Annex Roof A | 6,440 | SF | 7 | 10+ years | 90x75 |
| | Roof Structure - Steel / Metal Deck/ | Annex Roof A | 6,440 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| | Access Ladder - Metal | Annex Roof B | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | Annex Roof B | 120 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Annex Roof B | 55 | LF | 7 | 10+ years | |
| | Parapet - Parapet > 30" | Annex Roof B | 120 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Annex Roof B | 1,750 | SF | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | Annex Roof B | 1,750 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Annex | 20,924 | SF | 7 | 10+ years | |
| Windows | | | | | | | |
| | Clerestory - Glass Double-Pane | Annex | 196 | SF | 7 | 10+ years | |
| | Guard - Guards wire guard | Annex | 128 | SF | 7 | 10+ years | |
| | Lintels - Steel | Annex | 179 | LF | 7 | 10+ years | Door Lintels - Included |
| | Storefront Windows | Annex | 164 | SF | 7 | 10+ years | |
| | Windows - Casement Aluminum Double- | Annex | 92 | SF | 7 | 10+ years | |
| | pane | | | | | , | |
| Catego | ry : Electrical | | В | uildina | : Annex | : | |

| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------|---|-----------------|----------|-----|------|--------------------------|-------------------|
| mergei | ncy System | | | | | | |
| 0 | Exit Signs - Corridors and Stairs | Entire Building | 5 | EA | 7 | 6-10 years | 2020 installation |
| | Exit Signs - Gym | Entire Building | 3 | EA | 7 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 4 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 2 | EA | 7 | 6-10 years | 2020 installation |
| | Emergency Battery Packs - Gym | Entire Building | 6 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 4 | EA | 7 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 7 | 10+ years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 2,000 | SF | 7 | 10+ years | 2020 installation |
| | Emergency A/C Power - Gym | Entire Building | 8,000 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 4,500 | SF | 7 | 10+ years | |
| | Security System - CCTV | Entire Building | 19,100 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 19,100 | SF | 6 | 6-10 years | |

Main Service



| Catego | ry : Electrical | | В | uilding | : Annex | | · · · · · |
|-----------|--|-----------------|----------|--------------|---------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Main Electrical Service - 1200 A 277/480/3PH | Electrical Room | 1 | EA | 7 | 10+ years | Serves annex |
| | PA System | Entire Building | 19,100 | SF | 7 | 6-10 years | Connects to main building, 2020 installation |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 1 | EA | 7 | 10+ years | |
| | amp | g | • | _/ ` | - | i o i goulo | |
| | Transformers - 277/480 - 120/208 | Entire Building | 2 | EA | 7 | 10+ years | |
| Catego | ry : Fire Protection | | В | uilding | : Annex | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | m | | | | | | |
| | Fire Alarm Strobe Lights | Electrical Room | 19,100 | SF | 7 | 10+ years | |
| | Fire Alarm_System | Electrical Room | 19,100 | SF | 7 | 10+ years | Serves annex, connected to main |
| | | | -, | - | | -) | building |
| | Fire Pump Controller | Electrical Room | 1 | EA | 7 | 10+ years | |
| Pump Ro | pom Assembly | | | | | | |
| | Fire Pump - 25-50 hp | Entire Building | 1 | EA | 7 | 10+ years | Feeds Main Building and replaces |
| | | C | | | | | older pump |
| | Jockey Pump | Entire Building | 1 | EA | 7 | 10+ years | |
| Sprinkler | r System | | | | | | |
| | Sprinkler Heads | Entire Building | 19,100 | SF | 7 | 10+ years | |
| | Sprinkler Piping | Entire Building | 19,100 | SF | 7 | 10+ years | |
| | Wet Sprinkler System | Entire Building | 19,100 | SF | 7 | 10+ years | |
| Catego | ry : Mechanical | | В | uildina | : Annex | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | lling Systems | | | | | | |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 8 | EA | 7 | 10+ years | Located high above tall ceilings, no accessible |
| | Roof Top Unit-Single Zone-Roof Mounted- | Roof | 1 | EA | 7 | 10+ years | RTU 1 serves kitchen anc cafeteria |
| | Gas Heating and DX Cooling Coil - 5 - 10 | | | _ / ` | · | 101 900.0 | floor 1 |
| | tons Roof Top Unit-Single Zone-Roof Mounted- | Roof | 1 | EA | 7 | 10+ years | RTU 2 serves gym, floor 2 |
| | Gas Heating and DX Cooling Coil - 5 - 10 | | | | | - | |
| | | | | | | | |



| | ry : Mechanical | | В | uilding | : Annex | | |
|--------------------|--|--|--|--|--------------------------------------|--|---------------------------------|
| _ | | | | | | Recommend | - |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | tons | | | | | | |
| pating | Devices | | | | | | |
| cauny | Unit Heater - Electric | 1st Floor | 2 | EA | 6 | 10+ years | 2020 installation |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EA | 7 | 10+ years | 2020 installation |
| | Radiator Panels - Electric | Entire Building | 8 | EA | 7 | 10+ years | Serve restrooms |
| | Unit Heater - Electric | Mechanical Room | 1 | EA | 7 | 10+ years | In gym storage room |
| | | | | | | , | 3, |
| empera | ture Control | | | | | | |
| | DDC System | Entire Building | 19,100 | SF | 6 | 10+ years | 2020 installation, serves annex |
| | Electric Thermostat | Entire Building | 2 | EA | 6 | 10+ years | |
| | Thermostats - DDC | Entire Building | 8 | EA | 6 | 10+ years | Serve 8 fan power boxes |
| / <u>t</u> : - t: | | | | | | | |
| entilatio | Exhaust Fans- Indoor - 500 - 1500 CFM | Roof | 4 | EA | 6 | 10+ years | In utility rooms |
| | Roof Mounted Duct Work | Roof | 5 | LF | 7 | 10+ years | |
| | Type II Exhaust Hood- Warming Kitchen | Roof | 1 | EA | 7 | 10+ years | |
| | | | | | | , | |
| atego | ry : Plumbing | | В | uilding | : Annex | | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| lot Wate | | Looalion | Quantity | 00111 | | Replacement | oon monto |
| | Gas Heater - Less than 150000 BTU/HR | Mechanical Room | 2 | EA | 7 | 6-10 years | Also serves main building, 2020 |
| | | | _ | | | e re yeare | installation |
| iping | | | _ | | | | |
| iping | Domestic Piping-Hot Water Return Lines | Entire Building | 19,100 | SF | 7 | 10+ years | |
| iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers | Entire Building Entire Building | | SF SF | 7 | 10+ years 10+ years | |
| ?iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to | Entire Building | 19,100 | SF | | 10+ years | |
| 'iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures | Entire Building Entire Building Entire Building | 19,100 19,100 19,100 | SF SF SF | 7 7 | 10+ years 10+ years 10+ years | |
| 'iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply | Entire Building Entire Building | 19,100 19,100 | SF SF | 7 | 10+ years 10+ years | |
| 'iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 | SF SF SF SF | 7 7 7 | 10+ years 10+ years 10+ years 10+ years | |
| Piping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply | Entire Building Entire Building Entire Building | 19,100 19,100 19,100 | SF SF SF | 7 7 | 10+ years 10+ years 10+ years | |
| iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 19,100 | SF SF SF SF | 7 7 7 | 10+ years 10+ years 10+ years 10+ years 10+ years | |
| iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply | Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 | SF SF SF SF SF | 7 7 7 7 | 10+ years 10+ years 10+ years 10+ years | |
| 2iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 19,100 | SF SF SF SF SF | 7 7 7 7 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 19,100 19,100 | SF SF SF SF SF SF SF | 7 7 7 7 7 7 7 7 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| 'iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 19,100 19,100 19,100 | SF SF SF SF SF SF | 7 7 7 7 7 7 7 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| iping | Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping | Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building | 19,100 19,100 19,100 19,100 19,100 19,100 19,100 19,100 | SF SF SF SF SF SF SF | 7 7 7 7 7 7 7 7 | 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |



| Category : Plumbing | | | В | Building : Annex | | | | |
|---------------------|-----------------------------------|-------------------------|----------|------------------|---------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Caterro | ry : Room | | в | uildina | : Annex | | | |
| Jaicgo | | | 5 | unung | . Annea | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Administ | rative Suites/Offices | | | | | | | |
| | Ceiling - Lay-in | Gym office 213 | 70 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Gym office 213 | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | Gym office 213 | 70 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Gym office 213 | 1 | ĒA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Gym office 213 | 340 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Kitchen Office 022 | 108 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Kitchen Office 022 | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile/Sheet | Kitchen Office 022 | 108 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Kitchen Office 022 | 2 | EA | 7 | 10+ years | | |
| | Power Distribution | Kitchen Office 022 | 4 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Kitchen Office 022 | 378 | SF | 7 | 10+ years | | |
| | | | 010 | 0. | • | ior youro | | |
| Gvmnasi | а | | | | | | | |
| , | Bleacher Seating | 2nd floor Gymnasium 216 | 2 | EA | 7 | 10+ years | | |
| | Ceiling - Exposed | 2nd floor Gymnasium 216 | 5,848 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd floor Gymnasium 216 | 4 | EA | 7 | 10+ years | | |
| | Floor - Sport Flooring | 2nd floor Gymnasium 216 | 5,848 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd floor Gymnasium 216 | 24 | EA | 7 | 10+ years | | |
| | Scoreboards | 2nd floor Gymnasium 216 | 1 | EA | 7 | 10+ years | | |
| | Storage/ Closet | 2nd floor Gymnasium 216 | 587 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd floor Gymnasium 216 | 2,812 | SF | 7 | 10+ years | | |
| | | | 2,012 | 0. | • | ior yeare | | |
| Kitchen | | | | | | | | |
| | Ceiling - Lay-in | Ground Floor | 756 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Ground Floor | 4 | EA | 7 | 10+ years | | |
| | Floor - Tile Ceramic/ Porcelain | Ground Floor | 756 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Ground Floor | 12 | EA | 7 | 10+ years | | |
| | Storage/ Closet | Ground Floor | 169 | SF | 7 | 10+ years | | |
| | Walls - Vinyl Coated Gypsum Panel | Ground Floor | 1,080 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Servery | 392 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Servery | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile Ceramic/ Porcelain | Servery | 392 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Servery | 4 | EA | 7 | 10+ years | | |
| | Serving Line | Servery | 20 | LF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Servery | 238 | SF | 7 | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | Servery | 511 | SF | 7 | 10+ years | | |

Locker/Shower Room



| Catego | ry : Room | | R | uilding | : Annex | | 538 S Langley AVENUE, Chicago, IL 60628 |
|-------------------|--|--|----------|---------|---------|------------------------|---|
| Julego | , , , , , , , , , , , , , , , , , , , | | | anang | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | In Kitchen | 104 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | In Kitchen | 104 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | In Kitchen | 2 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | In Kitchen | 10 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | In Kitchen | 378 | SF | 7 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | Ground Floor | 1,536 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Ground Floor | 4 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Ground Floor | 5 | EA | 7 | 10+ years | |
| | Floor - Tile | Ground Floor | 1,536 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Ground Floor | 24 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Ground Floor | 2,000 | SF | 7 | 10+ years | |
| Mechani | cal/ Service Rooms | | | | | | |
| - Wite of Ital II | Storage Room | 016 Storage | 222 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 020 Mechanical Ground Floor | 162 | SF | 7 | 10+ years | |
| | Storage Room | 025 Storage in Kitchen | 175 | SF | 7 | 10+ years | |
| | Janitor's Closet | Jan Closet 012 Ground Floor | 62 | SF | 7 | 10+ years | |
| Restroor | n | | | | | | |
| 1000000 | Ceiling - Plaster/Drywall | 2nd floor Gymnasium 212 | 85 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd floor Gymnasium 212 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd floor Gymnasium 212 | 85 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd floor Gymnasium 212 | 1 | ĒA | 7 | 10+ years | |
| | Hand Dryer | 2nd floor Gymnasium 212 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd floor Gymnasium 212 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd floor Gymnasium 212 | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd floor Gymnasium 212 | 114 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd floor Gymnasium 212 | 266 | SF | 7 | 10+ years | |
| | Water Closet | 2nd floor Gymnasium 212 | 1 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd floor gymnasium 211 | 85 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd floor gymnasium 211 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd floor gymnasium 211 | 85 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd floor gymnasium 211 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd floor gymnasium 211 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd floor gymnasium 211 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd floor gymnasium 211 | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd floor gymnasium 211 | 114 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd floor gymnasium 211 | 266 | SF | 7 | 10+ years | |
| | Walls - The Ceramic/ Porcelain Water Closet | 2nd floor gymnasium 211 2nd floor gymnasium 211 | ∠00 1 | EA | 7 | 10+ years 10+ years | |
| | Accessories | Ground Floor | 230 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Ground Floor | 230 | SF | 7 | • | |
| | Cennig - Flaster/Drywall | | 230 | SF | 1 | 10+ years | |



| Category : Room | | | В | | | | |
|-----------------|--|------------------------------|----------|---------|---------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile Ceramic/ Porcelain | Ground Floor | 230 | SF | 7 | 10+ years | |
| | Floor Drain | Ground Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Ground Floor | 2 | EA | 7 | 10+ years | |
| | Lavatory | Ground Floor | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Ground Floor | 3 | EA | 7 | 10+ years | |
| | Partitions | Ground Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Ground Floor | 132 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Ground Floor | 462 | SF | 7 | 10+ years | |
| | Water Closet | Ground Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | Ground Floor | 230 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Ground Floor | 230 | SF | 7 | 10+ vears | |
| | Floor - Tile Ceramic/ Porcelain | Ground Floor | 230 | SF | 7 | 10+ years | |
| | Floor Drain | Ground Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Ground Floor | 2 | EA | 7 | 10+ years | |
| | Lavatory | Ground Floor | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Ground Floor | 3 | EA | 7 | 10+ years | |
| | Partitions | Ground Floor | 2 | EA | 7 | 10+ years | |
| | Urinals | Ground Floor | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Ground Floor | 132 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Ground Floor | 462 | SF | 7 | 10+ years | |
| | Water Closet | Ground Floor | 2 | EA | 7 | 10+ years | |
| | Accessories | Ground Floor Unisex Restroom | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Ground Floor Unisex Restroom | 54 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Ground Floor Unisex Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Ground Floor Unisex Restroom | 54 | SF | 7 | 10+ years | |
| | Floor Drain | Ground Floor Unisex Restroom | 1 | EA | 7 | 10+ years | |
| | Lavatory | Ground Floor Unisex Restroom | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Ground Floor Unisex Restroom | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Ground Floor Unisex Restroom | 60 | SF | 7 | | |
| | Walls - Tile Ceramic/ Porcelain | Ground Floor Unisex Restroom | | SF | | 10+ years | |
| | Walls - The Ceramic/ Porcelain Water Closet | Ground Floor Unisex Restroom | 210 1 | EA | 7 7 | 10+ years | |
| | | Kitchen Unisex | 49 | SF | 7 | 10+ years | |
| | Accessories | | - | SF | | 6-10 years | |
| | Ceiling - Plaster/Drywall | Kitchen Unisex | 49 | | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Kitchen Unisex | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Kitchen Unisex | 49 | SF | 7 | 10+ years | |
| | Floor Drain | Kitchen Unisex | 1 | EA | 7 | 10+ years | |
| | Lavatory | Kitchen Unisex | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen Unisex | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Kitchen Unisex | 84 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Kitchen Unisex | 168 | SF | 7 | 10+ years | |
| | Water Closet | Kitchen Unisex | 1 | EA | 7 | 10+ years | |
| atego | ry : Interior | | В | uilding | : Annex | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments |

| | | | 10538 S Langley AVENUE, Replacement | | | | | | |
|---------|--------------------------------------|-----------------------------------|--|----|---|-------------|-------------|--|--|
| orridor | | | | | | Replacement | | | |
| | Ceiling - Lay-in | 3rd Floor Annex Stair 1 vestibule | 175 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 3rd Floor Annex Stair 1 vestibule | 2 | EA | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 3rd Floor Annex Stair 1 vestibule | 175 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor Annex Stair 1 vestibule | 2 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 3rd Floor Annex Stair 1 vestibule | 270 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | | 80 | SF | 7 | • | | | |
| | • | 3rd Floor Annex Stair 1 vestibule | | SF | | 10+ years | | | |
| | Ceiling - Lay-in | C03 Corridor | 264 | EA | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | C03 Corridor | 2 | | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | C03 Corridor | 264 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | C03 Corridor | 3 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | C03 Corridor | 760 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Ground Floor | 785 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Ground Floor | 12 | EA | 7 | 10+ years | Rated doors | | |
| | Drinking Fountains - Single Fountain | Ground Floor | 3 | EA | 7 | 10+ years | | | |
| | Floor - Carpet | Ground Floor | 320 | SF | 7 | 6-10 years | | | |
| | Floor - Tile/Sheet | Ground Floor | 465 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Ground Floor | 7 | EA | 7 | 10+ years | | | |
| | Lighting - Wall Mounted | Ground Floor | 2 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Ground Floor | 1,250 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Ground Floor | 846 | SF | 7 | 10+ years | | | |
| | Walls - Tile Ceramic/ Porcelain | Ground Floor | 53 | SF | 7 | 10+ years | | | |
| afety | | | | | | | | | |
| | Security Cameras | Entire Building | 12 | EA | 7 | 6-10 years | | | |
| airs | | | | | | | | | |
| | Ceiling - Lay-in | Stair 1 | 388 | SF | 7 | 10+ years | | | |
| | Floor - Tile | Stair 1 | 452 | SF | 7 | 6-10 years | | | |
| | Handrails | Stair 1 | 252 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Stair 1 | 2 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Stair 1 | 6 | EA | 7 | 10+ years | | | |
| | Stairs - Rubber | Stair 1 | 63 | LF | 7 | 10+ years | | | |
| | Walls - Concrete Block | Stair 1 | 4,010 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Stair 2 | 624 | SF | 7 | 10+ years | Μ | | |
| | Ceiling - Plaster/Drywall | Stair 2 | 50 | SF | 6 | 10+ years | | | |
| | Floor - Tile | Stair 2 | 221 | SF | 7 | 10+ years | | | |
| | Handrails | Stair 2 | 85 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Stair 2 | 6 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Stair 2 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Wall Mounted | Stair 2 | 2 | EA | 7 | 10+ years | | | |
| | Stairs - Rubber | Stair 2 | 120 | LF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Stair 2 | 1,775 | SF | 7 | 10+ years | | | |

Vertical Conveyance

A 11. - -_ **~**1



| | | | | | | - , |
|-------------------------------|-----------|---|----|---|-------------|-----|
| | | | | | Replacement | |
| Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 7 | 10+ years | |



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement Comments Group Rank Civil/Drainage FΑ 6 Civil/ Drainage - Catch Basin Entire Site 1 10+ years 3 ΕA 6 Civil/ Drainage - Catch Basin **Entire Site** 10+ years Civil/ Drainage - Site Manhole 7 Entire Site ΕA 6 10+ years Fencina Fencing - Chain Link LF Entire Site 237 6 10+ years LF Fencing - Chain Link **Entire Site** 8 5 2-5 years Fencing - Iron and Concrete Post **Entire Site** 221 LF 4 0-1 year Broken/Missing Concrete/Exposed Iron Post - Deteriorated Fencing - New Standard Ornamental Entire Site 64 LF 6 10+ years Fencing - Old Standard Ornamental **Entire Site** 679 LF 0-1 year Detached from 4 Post/Rust/Corrosion/Deterioration -Obsolete Landscape Landscape - Grass Entire Site 13,828 SF 6 10+ years Parkway trees Entire Site 34 EΑ 6 10+ years SF Planting Beds/ Area Entire Site 4.487 6 10+ years SF 7 Play Area - Hardscape- Asphalt Entire Site 9.373 10+ years "Play Area - Concrete Hardscape" Play Area - Hardscape- Asphalt SF **Entire Site** 1.361 6 10+ years Play Area - Synthetic Turf **Entire Site** 10.788 SF 7 10+ years Trash Receptacles 5 ΕA 7 10+ years Entire Site Parking Lot Lighting - Pole Mounted Entire Site 16 ΕA 6 10+ years SF Broken/Cracks/Missing and Surface - Asphalt **Entire Site** 6.238 4 0-1 year Deteriorating SF Broken/Cracks/Potholes/Missing and Surface - Asphalt Entire Site 4.490 4 0-1 year Deteriorating Surface - Concrete Entire Site 2,391 SF 5 2-5 years Failing Surface - Concrete Entire Site SF 6-10 years Broken/Gaps/Heaving - Trip Hazards 120 4 SF Trash Enclosure - Chain Links 612 6 Entire Site 10+ years Playground Equipment - School Age 5-12 North 1 EΑ 6 10+ years Surface - Poured Surface 2,425 SF 5 Holes, damaged throughout North 0-1 year Sidewalks Sidewalks - Internal Walks Entire Site LF 691 6 10+ years Sidewalks - Internal Walks Entire Site LF 5 0-1 year 65 Broken/Cracks/Heaving



| Category : Site | | Building : Site | | | | | | |
|-----------------|--|-----------------|----------|-----|-----------|-------------|--------------------------|--|
| | | | | | Recommend | d | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 10,563 | SF | 6 | 10+ years | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 1,050 | SF | 4 | 0-1 year | Broken/Cracked/Displaced | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 430 | SF | 4 | 0-1 year | Broken/Cracks | |
| Signage | | | | | | | | |
| | Flag Pole - Building Mounted Flag Pole | East | 1 | EA | 6 | 10+ years | | |
| | Monument - Building Mounted Cut Letter Sign | East | 1 | EA | 6 | 10+ years | Added/Annex | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area | Glazed Window Area | Operable Window Area | Window Stop | Smart- Board |
|---|-------------------|---------------|----------------|------------------------------|-------|--------------------------|----------------------------|----------------|-----------------|
| Current Usage Intended Usage Room Location Number Number (SF) Area Area Stop Building : Main | | | | | | | | | |
| Art Room | Regular Classroom | 2nd Floor | 205 | 204 | 834 | 96 | 56 | Y | N |
| Computer Lab | Library | 2nd Floor | 203 | 203 | 1,523 | 72 | 28 | N | Y |
| Kindergarten | Kindergarten | 1st Floor | 101 | 100 | 834 | 96 | 56 | N | Y |
| Music Room | Music Room | Basement | 001 | 001 | 988 | 72 | 36 | | |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 101 | 834 | 96 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 102 | 834 | 102 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 200 | 834 | 96 | 56 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 203 | 834 | 102 | 54 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 300 | 834 | 96 | 56 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 301 | 834 | 108 | 60 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | NA | 841 | 72 | 36 | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 304 | 834 | 96 | 56 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | NA | 986 | 72 | 36 | | |
| Store Room | Regular Classroom | Basement | 004 | 004 | 372 | 0 | 0 | | |