

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1900	3	33,794
Addition	1936	3	15,869
Campus Total			49,663

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Entrance Control - Audio and Video	#1 - Main - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 - Main - S	3	EA	5	0-1 year	Rusting around edges of doors.
	Exterior Doors - Side lite	#1 - Main - S	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 - Main - S	3	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - Southeast	1	EA	6	6-10 years	
	Exterior Stairs - Stone	#3 - Southeast	6	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#3A - Southeast OVH	1	EA	6	6-10 years	
	Door					•	
	Exterior Doors - Exterior Wood Door	#4 - N	1	EA	4	0-1 year	Rotting and splitting.
	Exterior Doors - Side lite	#4 - N	2	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - N	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#5 - NW	3	EA	4	0-1 year	Doors rotting and rusting on edges.
	Exterior Doors - Side lite	#5 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - NW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5 - NW	12	LF	6	10+ years	
_Foundat	ion						
	Foundation - Masonry	Entire Building	440	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	33,794	SF	7	10+ years	
_Lighting							

Campus Name: Prescott Page : 1 of 24 Assessment Date: 09/29/2021



Exte Roof System Chin Copi Dow Para Roof Roof Cone Chin Copi Copi	nney - Metal Flue ing - Clay Tile rappouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal raspouts - Exterior Downspouts	Location Entire Building Low roof #1 Low roof #2 - boiler room Low roof #2 - boiler room	Quantity 10 19 135 6 80 781 781	UOM EA LF LF LF SF SF	Rank 7 6 7 7 6	Recommend Replacement 10+ years 6-10 years 10+ years 10+ years	Comments
Exte Roof System Chin Copi Dow Para Roof Roof Cone Chin Copi Copi	erior Lighting - Wall Mounted Inney - Metal Flue Ing - Clay Tile Inspouts - Exterior Downspouts Inspouts - 16" - 30" Height Inspouts - Steel / Metal Deck/ Inspouts - Steel / Metal Deck/ Inspouts - Metal Flue Ing - Clay Tile Ing - Metal Inspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	19 135 6 80 781 781	LF LF LF SF	7 6 7 7 7	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Comments
Roof System Chin Copi Dow Para Roof Roof Cone Chin Copi	nney - Metal Flue ing - Clay Tile rnspouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	19 135 6 80 781 781	LF LF LF LF SF	6 7 7 7	6-10 years 10+ years 6-10 years 10+ years	
Chin Copi Dow Para Root Con Chin Copi Copi	ing - Clay Tile rnspouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	135 6 80 781 781	LF LF LF SF	7 7 7	10+ years 6-10 years 10+ years	
Chin Copi Dow Para Root Con Chin Copi Copi	ing - Clay Tile rnspouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	135 6 80 781 781	LF LF LF SF	7 7 7	10+ years 6-10 years 10+ years	
Copi Dow Para Roof Con Chin Copi Copi	ing - Clay Tile rnspouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	135 6 80 781 781	LF LF LF SF	7 7 7	10+ years 6-10 years 10+ years	
Dow Para Roof Roof Con Chin Copi Copi	rnspouts - Exterior Downspouts apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #1 Low roof #1 Low roof #1 Low roof #2 - boiler room	6 80 781 781	LF LF SF	7 7	6-10 years 10+ years	
Para Root Root Cond Chin Copi Copi	apet - 16" - 30" Height f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal rnspouts - Exterior Downspouts	Low roof #1 Low roof #1 Low roof #2 - boiler room	80 781 781	LF SF	7	10+ years	
Roof Roof Con Chin Copi Copi	f - Modified Bitumen f Structure - Steel / Metal Deck/ crete Topping nney - Metal Flue ing - Clay Tile ing - Metal nspouts - Exterior Downspouts	Low roof #1 Low roof #2 - boiler room	781	SF			
Cone Chin Copi Copi	crete Topping nney - Metal Flue ing - Clay Tile ing - Metal nspouts - Exterior Downspouts	Low roof #2 - boiler room	_			10+ years	Minor ponding stains.
Cone Chin Copi Copi	crete Topping nney - Metal Flue ing - Clay Tile ing - Metal nspouts - Exterior Downspouts		_		7	10+ years	2 1 3 1 1 1
Chin Copi Copi	nney - Metal Flue ing - Clay Tile ing - Metal nspouts - Exterior Downspouts		_			, , , , , ,	
Copi Copi	ing - Clay Tile ing - Metal nspouts - Exterior Downspouts		58	LF	7	10+ years	
Copi	ing - Metal rnspouts - Exterior Downspouts	LOW TOOL #Z - DOUGH TOOM	68	LF	7	10+ years	
Dow	nspouts - Exterior Downspouts	Low roof #2 - boiler room	36	LF	7	6-10 years	
DOW		Low roof #2 - boiler room	14	LF	6	6-10 years	
	apet - 16" - 30" Height	Low roof #2 - boiler room	68	LF	7	10+ years	
	f - Modified Bitumen	Low roof #2 - boiler room	1,007	SF	6	10+ years	Minor ponding observed.
	f Structure - Steel / Metal Deck/	Low roof #2 - boiler room	1.007	SF	7	10+ years	- F
	crete Topping		.,551		•	,	
	ess Ladder - Metal	Low roof #3	7	EA	7	10+ years	Verizon Installed
	ing - Clay Tile	Low roof #3	24	LF	7	10+ years	
	ing - Stone	Low roof #3	26	LF	7	10+ years	
	Inspouts - Exterior Downspouts	Low roof #3	14	LF	7	6-10 years	
	apet - 16" - 30" Height	Low roof #3	50	LF	7	10+ years	
	f - Modified Bitumen	Low roof #3	406	SF	6	10+ years	Minor ponding observed.
	f Structure - Steel with Clay Tile Arch	Low roof #3	406	SF	7	10+ years	g esserves.
	ing - Terra Cotta	Main Roof	441	LF	6	10+ years	
	Inspouts - Exterior Downspouts	Main Roof	60	LF	6	6-10 years	
	apet - 16" - 30" Height	Main Roof	101	LF	7	10+ years	
	apet - Parapet < 16" Height	Main Roof	163	LF	7	10+ years	
	apet - Parapet > 30"	Main Roof	177	LF	7	10+ years	
	f - Modified Bitumen	Main Roof	7,900	SF	6	10+ years	Minor ponding.
	f Structure - Steel with Clay Tile Arch	Main Roof	7,900	SF	7	10+ years	e. perianig
Walls							
	nice - Masonry Projecting Limestone	Entire Building	263	LF	6	10+ years	
	nice - Metal Projecting	Entire Building	263	LF	6	10+ years	
	erior Walls - Brick	Entire Building	18,524	SF	6	10+ years	
	erior Walls - Brick	Entire Building	400	SF	6	10+ years	Graffiti.
Exte	erior Walls - Stone-Cast	Entire Building	620	SF	6	10+ years	
Exte	erior Walls - Stone-Cut	Entire Building	1,052	SF	6	10+ years	
Windows							
	rd - Guards wire guard	Entire Building	783	SF	6	6-10 years	



Categor	y : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Brick	Entire Building	47	LF	6	10+ years	
	Lintels - Steel	Entire Building	246	LF	6	10+ years	
	Lintels - Stone	Entire Building	72	LF	6	10+ years	
	Windows - Louver	Entire Building	9	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,429	SF	6	6-10 years	
ategoi	ry : Electrical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
mergen	cy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Served disconnected UPS. No independent service
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,786	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,200	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,936	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	With batteries
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	With battery
	Exit Signs - Lunchroom	Entire Building	7	EA	6	6-10 years	With batteries
1ain Ser	vice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Also serves addition building
	PA System	Entire Building	33,794	SF	5	6-10 years	Connected to addition, previously n assessed
ower Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Repaired.
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	Not assessed previously
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	3 found (one added to corroded/old panel)
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	0-1 year	Older. Corroded.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	10+ years	1 found, other panel is 400 Amp
	Transformers - 120/240 - 120/208	Entire Building	1	EA	5	6-10 years	Previously, not assessed, octogana
ategoi	y : Fire Protection		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Campus Name: Prescott Page : 3 of 24 Assessment Date: 09/29/2021



	ry : Fire Protection			uilding	. IVIGIII		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	33,794	SF	6	10+ years	
	Fire Alarm_System	Entire Building	33,794	SF	6	10+ years	
	Fire Pump Controller	Entire Building	1	EA	5	6-10 years	Older and functional
Dumn D	oom Assembly						
-ump Ki	Fire Pump - Less than 25hp	Basement	1	EA	5	6-10 years	Serves main building
	riie ruiiip - Less tilali 2511p	Dasement	'	LA	3	0-10 years	Serves main building
Sprinkle	System						
	Dry Sprinkler System	Entire Building	33,794	SF	6	10+ years	
	Sprinkler Heads	Entire Building	33,794	SF	7	10+ years	Passed fire Marshall inspection
	Sprinkler Piping	Entire Building	33,794	SF	4	1-2 years	Passed fire marshal inspection. Morthan 50 years old.
Catego	ry : Mechanical		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	5	6-10 years	In cafeteria
Boiler Sy	ystems						
201101 0)	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	10+ years	
	Pressure Boiler - 76 - 100 HP	Boiler Room	_	L/\	J	101 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Chemical Feeder	Boiler Room	1	EΑ	6	10+ years	
	Combustion Dampers	Boiler Room	2	EΑ	6	10+ years	
	Condensate Pump	Boiler Room	_ 1	EΑ	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	10+ years	Serves main and addition buildinga
	Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	L/ \	J	101 years	Cerves main and addition ballanga
	Piping - Condensate Pipe- Steel	Boiler Room	1,000	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	1,000	LF	5	10+ years	
	Steam Traps	Boiler Room	22	EA	5	6-10 years	
	Steam Traps	Boiler Room	4	EA	5	6-10 years	Do not leak.
O D:	ata.						
Gas Boo		Boiler Room		EA	5	6 10 22000	
	Gas Booster	DOILEL KOOLLI	2	ĽΑ	5	6-10 years	
Heating	Devices						
	Wall Heater - Electric	Basement	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	3	EA	5	6-10 years	No temperature control
	ature Control						



Cotogo	ry : Mechanical			uilding	. Main	.002 .	V Wrightwood AVENUE, Chicago, IL 6061
Catego	y : Mechanicai		D	ullaing	. wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Electric Thermostat	Entire Building	Qualitity 1	EA	6	6-10 years	Serves fan coil unit in
	Electric Thermostat	Entire building	'	EA	О	6-10 years	
	Du accesa di a Occada da	Fatina Buildia a	00.704	0.5	_	4.0	cafeteria/classroom area
	Pneumatic System	Entire Building	33,794	SF	5	1-2 years	Some zones are manually controlled
	Thermostats - Pneumatic	Entire Building	17	EA	5	1-2 years	Requires frequent maintenance and
							calibration. 17 dampers serve the
							main building.
Ventilatio		F C D 7 P					T 1 (1 1 (1100
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	To exhaust hydrogen from UPS,
	Exhaust Fore Indeed 500 4500 CFM	Cotine Duilding	1	Ε.	_	C 40	previously not assessed
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	I	EA	5	6-10 years	Difficult to access
Catego	ry : Plumbing		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Older than 15 years. Serves main
						-	and addition buildings, burners
							recently cleaned.
							•
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	33,794	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	33,794	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	33,794	SF	6	10+ years	
	Fixtures	•				•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,794	SF	6	10+ years	
	(Horizontal Lines)	3	,			, , , , , ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,794	SF	6	10+ years	
	(Risers)	9	,	-	•	, , , , , , , , , , , , , , , , , , , ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	33,794	SF	6	10+ years	
	(from Risers to Fixtures)	Zitare Bananig	33,731	0.	·	ioi youro	
	Sanitary Piping	Entire Building	33,794	SF	6	10+ years	
	Storm Piping	Entire Building	33,794	SF	6	10+ years	
	Vent Piping	Entire Building	33,794	SF	6	6-10 years	
	ventriping	Little Ballaling	55,754	Oi	O	0-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	Serves main and addition buildings
Oat a	Daam		-	!lal!	. Ma!		
atego	ry : Room		В	uilding	. wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Gym Office - 3rd floor	131	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office - 3rd floor	1	EA	6	10+ years	
	Floor - Wood	Gym Office - 3rd floor	131	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office - 3rd floor	1	EA	7	6-10 years	
	Power Distribution	Gym Office - 3rd floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Office - 3rd floor	225	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Office 302- previous Wardrobe Room in Classroom 301	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office 302- previous Wardrobe Room in Classroom 301	1	EA	7	10+ years	
	Floor - Wood	Office 302- previous Wardrobe Room in Classroom 301	300	SF	7	10+ years	
	Lighting - Pendent/Surface	Office 302- previous Wardrobe Room in Classroom 301	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Office 302- previous Wardrobe Room in Classroom 301	870	SF	7	10+ years	
Gymnas							
	Ceiling - Plaster/Drywall	3rd Floor	2,332	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	2,332	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	15	EA	7	6-10 years	
	Stage	3rd Floor	396	SF	6	10+ years	
	Stage Curtain	3rd Floor	6	EA	7	10+ years	
	Stage Lighting System	3rd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,768	SF	6	10+ years	
	Ceiling - Splined	Boy's Play Room in Basement	868	SF	4	0-1 year	Tiles out of place throughout.
	Floor - Sport Flooring	Boy's Play Room in Basement	868	SF	7	10+ years	•
	Lighting - Pendent/Surface	Boy's Play Room in Basement	6	EA	7	6-10 years	
	Walls - Masonry	Boy's Play Room in Basement	1,320	SF	6	10+ years	
	Walls - Masonry	Boy's Play Room in Basement	25	SF	5	0-1 year	Cracked/pieces missing by stairs.
Kitchen							
	Ceiling - Plaster/Drywall	Basement	291	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	291	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Serving Line	Basement	12	LF	6	10+ years	
	Walls - Masonry	Basement	562	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	100	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	Basement	1,936	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,936	SF	5	10+ years	



Catego	ry : Room		B	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement	28	EA	7	6-10 years	
	Walls - Masonry	Basement	2,034	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	2,034	SF	6	10+ years	
	•		,			,	
/IDF_ID	F						
_	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Finishes	2nd Floor	198	SF	5	10+ years	Paint chipping and peeling on walls.
	Window AC Unit	2nd Floor	1	EA	5	6-10 years	
/ochoni	cal/ Service Rooms						
lechanii	Boiler Room	NE corner of basement	979	SF	5	10+ years	Paint chipping and peeling really bad
	Delier Reem	THE GOTTON OF BUGGINGTH	0.0	O.	Ü	ror youro	throughout ceiling.
	Coal Room	NE corner of basement	362	SF	7	10+ years	-
	Mechanical/ Service Rooms	NE corner of basement	506	SF	5	10+ years	
	Storage Room	NE corner of basement	318	SF	5	10+ years	
	Storage Room	Storeroom next to the gym	192	SF	5	10+ years	
estroor	m						
	Accessories	Basement north end	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement north end	253	SF	6	10+ years	Paint chipping and peeling.
	Doors - Wood Doors inclu hw	Basement north end	1	ĒΑ	6	10+ years	· a oppg aa poog.
	Floor - Tile Ceramic/ Porcelain	Basement north end	247	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement north end	6	SF	4	0-1 year	Damaged floor - missing tiles observed.
	Floor Drain	Basement north end	1	EA	7	10+ years	0.001100.
	Hand Dryer	Basement north end	2	EΑ	7	10+ years	
	Lavatory	Basement north end	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	Basement north end	4	EΑ	6	6-10 years	
	Partitions	Basement north end	2	EΑ	7	10+ years	
	Urinals	Basement north end	5	EΑ	6	10+ years	
	Walls - Plaster/Drywall	Basement north end	224	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement north end	448	SF	6	10+ years	
	Water Closet	Basement north end	2	EA	6	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
	<u> </u>			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #001 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	5	0-1 year	Door hits elevated metal threshold.
	Floor - Tile	Basement	688	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	6	6-10 years	



				anamg	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	Basement	10	LF	6	10+ years	
	Storage/ Closet	Basement	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	688	SF	6	10+ years	
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
	Work Sink	1st Floor	1, 100	EA	7	10+ years	
Classroo	nm #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor		LF	7	•	
	Storage/ Closet	1st Floor	20 198	SF	7	6-10 years 6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
Classros	om #103 (Kindergarten)						
Classioo	` ,	1st Floor	4	ГΛ	7	C 40	
	AC Units		1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	896	SF	6	10+ years	0 1 10 11 12
	Floor - Tile	1st Floor	4	SF	4	0-1 year	Cracked & chipped tiles
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,486	SF	6	10+ years	
lassroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,486	SF	6	10+ years	
lassroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	5	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,800	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,800	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	ĒΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	198	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,212	SF	6	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	875	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	875	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,650	SF	6	10+ years	
lassroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	177	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,486	SF	6	10+ years	



						1002 V	V Wrightwood AVENUE, Chicago, IL 60614
Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	198	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,486	SF	6	10+ years	
	vvalis i laster/brywan	010 1 1001	1,400	Oi.	O	101 years	
_Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	177	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,486	SF	6	10+ years	
	Walls - Flaster/Drywall	310 1 1001	1,400	31	O	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
~							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•			•			·	Comments
•	Ceiling - Plaster/Drywall	1st Floor	1,706	SF	6	10+ years	
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain	1st Floor 1st Floor	1,706	SF EA	6 7	10+ years 6-10 years	Drinking fountains work
•	Ceiling - Plaster/Drywall	1st Floor	1,706	SF	6	10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor	1,706 3 1,706	SF EA SF	6 7 7	10+ years 6-10 years 10+ years	Drinking fountains work
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor	1,706 3 1,706	SF EA SF	6 7 7 7	10+ years 6-10 years 10+ years 6-10 years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,706 3 1,706 16 2,922	SF EA SF EA SF	6 7 7 7 6	10+ years 6-10 years 10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,706 3 1,706 16 2,922 1,706	SF EA SF EA SF SF	6 7 7 7 6 6	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain	1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	1,706 3 1,706 16 2,922 1,706 2	SF EA SF EA SF SF EA	6 7 7 7 6 6 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706	SF EA SF EA SF EA SF	6 7 7 7 6 6 7 5	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16	SF EA SF EA SF EA SF EA	6 7 7 7 6 6 7 5	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 6-10 years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922	SF EA SF EA SF EA SF EA SF	6 7 7 7 6 6 7 5 6	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3nd Floor 3rd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713	SF EA SF EA SF EA SF EA SF SF	6 7 7 7 6 6 7 5 6 6 6	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713 713	SF EA SF EA SF EA SF EA SF SF SF	6 7 7 7 6 6 7 5 6 6 6 7	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713 713 5	SF EA SF EA SF EA SF EA SF EA	6 7 7 7 6 6 7 5 6 6 7 6	10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713 713 5 1,682	SF EA SF EA SF EA SF EA SF SF EA SF SF SF SF SF SF SF SF SF SF SF SF SF	6 7 7 7 6 6 7 5 6 6 7 6	10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor Basement	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713 713 5	SF EA	6 7 7 7 6 6 7 5 6 6 6 7 6 6	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor Basement Basement	1,706 3 1,706 16 2,922 1,706 2 1,706 16 2,922 713 713 5 1,682 2,037 4	SF A	6 7 7 7 6 6 7 5 6 6 6 7 6 6 6 7 6	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor Basement Basement Basement	1,706 3 1,706 16 2,922 1,706 16 2,922 713 713 5 1,682 2,037 4 2,037	SFASFASFASFASFASFASFASF	6 7 7 7 6 6 7 5 6 6 6 7 6 6 7	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
•	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement Basement Basement	1,706 3 1,706 16 2,922 1,706 16 2,922 713 713 5 1,682 2,037 4 2,037 8	SFASFASFASFASFASFASFASFA	6 7 7 6 6 7 5 6 6 6 7 6 6 7 6	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Stairs - Concrete Stairs	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement Basement Basement Basement Basement	1,706 3 1,706 16 2,922 1,706 16 2,922 713 713 5 1,682 2,037 4 2,037 8 30	SFA SF EA SFA SFA SFA SFA SFA SFA SFA SFA SFA SF	6 7 7 6 6 6 7 5 6 6 6 7 6 6 6 7 6 6 6 7 6 6 6 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good
	Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Exposed Doors - Wood Doors include hw Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor Basement Basement Basement Basement	1,706 3 1,706 16 2,922 1,706 16 2,922 713 713 5 1,682 2,037 4 2,037 8	SFASFASFASFASFASFASFASFA	6 7 7 6 6 7 5 6 6 6 7 6 6 7 6	10+ years 6-10 years 10+ years	Drinking fountains work Observed flooring to be in good



atego	ry : Interior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
airs							
	Ceiling - Plaster/Drywall	North	595	SF	6	10+ years	
	Floor - Tile	North	312	SF	6	10+ years	
	Handrails	North	204	LF	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years	
	Stairs - Terrazzo	North	85	LF	6	10+ years	
	Stairs - Terrazzo	North	5	LF	4	0-1 year	Cracked/missing at top of stairs.
	Walls - Plaster/Drywall	North	3,492	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	595	SF	6	10+ years	
	Floor - Tile	South	312	SF	6	10+ years	Dirty at landings.
	Handrails	South	204	LF	7	10+ years	
	Lighting - Pendent/Surface	South	7	EΑ	6	6-10 years	
	Stairs - Terrazzo	South	80	LF	6	10+ years	
	Stairs - Terrazzo	South	10	LF	4	0-1 year	Crack, and missing at top of stail
	Walls - Plaster/Drywall	South	3,492	SF	6	10+ years	-





Category: Exterior **Building: Addition** Recommend Location **UOM** Replacement Group Item - Type Quantity Rank Comments Cell Equipment N/A 9 EΑ 7 Cell Equipment - Antenna 10+ years Cell Equipment - Cabinets N/A 7 EΑ 7 10+ years Cell Equipment - Generator N/A EΑ 10+ years Entrance Exterior Doors - Exterior Steel Door #2 - E FΑ 5 2 0-1 year Rusting on lower portion of door. Exterior Doors - Exterior Steel Door Fire escape Doors East 3 FΑ 4 0-1 year Doors Mis-Matched, Aged/Worn. Rusting. Fire Escape Fire Escape Southeast 282 LF Significant amount of rusting. 5 0-1 year _Foundation Foundation - Concrete **Entire Building** 204 LF 7 10+ years Superstructure - Concrete 15,869 SF 7 **Entire Building** 10+ years Liahtina Exterior Lighting - Wall Mounted **Entire Building** 5 EΑ 7 10+ years

tem		0.4			40	
Coping - Stone	Low E roof	84	LF	7	10+ years	
Downspouts - Interior Downspouts	Low E roof	28	LF	5	2-5 years	Downspouts leaks in heavy dow pours.
Parapet - 16" - 30" Height	Low E roof	84	LF	7	10+ years	
Roof - Modified Bitumen	Low E roof	793	SF	7	10+ years	
Roof Structure - Steel with Clay Tile Arch	Low E roof	793	SF	7	10+ years	
Coping - Stone	Low N roof	43	LF	7	10+ years	
Downspouts - Interior Downspouts	Low N roof	28	LF	6	6-10 years	
Parapet - 16" - 30" Height	Low N roof	43	LF	7	10+ years	
Roof - Modified Bitumen	Low N roof	470	SF	6	10+ years	
Roof Structure - Steel with Clay Tile Arch	Low N roof	470	SF	7	10+ years	
Access Ladder - Metal	Main Roof	1	EΑ	7	6-10 years	
Coping - Terra Cotta	Main Roof	216	LF	6	10+ years	
Downspouts - Interior Downspouts	Main Roof	120	LF	6	6-10 years	

Main Roof

Main Roof

Main Roof

Main Roof

Walls

Parapet - Parapet > 30"

Roof - Modified Bitumen

Roof Structure - Steel with Clay Tile Arch

Roof Hatch - Metal

LF

SF

EΑ

SF

216

3.534

3.534

7

7

7

7

10+ years

10+ years

10+ years

10+ years



Category : Exterior

William H Prescott Elementary School 1632 W Wrightwood AVENUE, Chicago, IL 60614

Building: Addition

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cornice - Masonry Projecting Limestone	Entire Building	83	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	83	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	12,578	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	424	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	848	SF	7	10+ years	
Windows	3						
	Guard - Guards wire guard	Entire Building	435	SF	6	6-10 years	
	Lintels - Steel	Entire Building	224	LF	6	10+ years	
	Lintels - Stone	Entire Building	16	LF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	40	SF	4	0-1 year	Cracked glass.
	Windows - Sash Aluminum Double-pane	Entire Building	1,645	SF	6	6-10 years	-
Catego	ry : Electrical		В	uilding	: Additi	on	
Craun	Itam Tuna	Location	Oventity	HOM	Donk	Recommend Replacement	Comments
Group	Item - Type ncy System	Location	Quantity	UOM	Rank	Replacement	Comments
Lillergei	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	1,489	SF	6	10+ years	
	Stairs		45.000	05	•	0.40	
	Security System - CCTV	Entire Building	15,869	SF	6	6-10 years	Not assessed previously
	Security System - Intrusion Detection	Entire Building	15,869	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
Main Se	rvice						
	PA System	Entire Building	15,869	SF	5	6-10 years	Connected to main building
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additi	on	
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire Alarm Panel	Entire Building	1	ΓΛ		10	Convey addition and main building
		Entire Building		EA SF	6	10+ years	Serves addition and main building
	Fire Alarm Strobe Lights	Entire Building	15,869		6	10+ years	Company of all a frame are also be attached as
	Fire Alarm_System	Entire Building	15,869	SF	5	10+ years	Served also from main building
Sprinkle	System						
•	Dry Sprinkler System	Entire Building	5,290	SF	6	6-10 years	Common corridors only.
	7 F		-,		-	,	
Campus I	Name: Prescott		Page : 13 of 24				Assessment Date: 09/29/202
			5				



Piping

Fixtures

Domestic Piping-Hot Water Return Lines

Domestic Piping-Hot Water Return Risers

Domestic Piping-Hot Water from Risers to

Domestic Piping-Hot/Cold Water Supply

Category: Fire Protection

William H Prescott Elementary School 1632 W Wrightwood AVENUE, Chicago, IL 60614

Building: Addition

	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sprinkler Heads	Entire Building	5,290	SF	7	6-10 years	Corridors.
	Sprinkler Piping	Entire Building	5,289	SF	6	6-10 years	Corridors.
Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	Iling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	10+ years	Serves main and addition buildings
	Air Intake	Basement	2	EA	6	10+ years	Common return
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	4	1-2 years	Fan corroded.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	60	LF	6	10+ years	Common return
	Zone Dampers	Basement	32	EA	5	0-1 year	Some dampers are manually operated. 15 dampers serve the addition building. 17 dampers serve the main building.
_Heating							
	Radiators - Steam	Entire Building	6	EA	5	6-10 years	Not painted
	Wall Heater - Electric	Entire Building	6	EA	5	2-5 years	
_Tempera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	10+ years	Serves exhaust fan in electrical room
	Pneumatic System	Entire Building	15,869	SF	5	1-2 years	Older, not reliable, some zones manually controlled
	Thermostats - Pneumatic	Entire Building	15	EA	5	2-5 years	Not calibrated, 15 dampers serve addition building.
_Ventilati	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additi		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Campus Name: Prescott Page: 14 of 24 Assessment Date: 09/29/2021

SF

SF

SF

SF

6

6

6

6

15,869

15,869

15,869

15,869

10+ years

10+ years

10+ years

10+ years

Entire Building

Entire Building

Entire Building

Entire Building



Catego	ry : Plumbing	Building : Addition						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	(Horizontal Lines)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,869	SF	6	10+ years		
	(Risers)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,869	SF	6	10+ years		
	(from Risers to Fixtures)							
	Sanitary Piping	Entire Building	15,869	SF	6	10+ years		
	Storm Piping	Entire Building	15,869	SF	6	10+ years		
	Vent Piping	Entire Building	15,869	SF	6	6-10 years		
		· ·				•		

Category: Room **Building: Addition**

	1 y . 1 (00111		Danding . Addition							
			Recommend							
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
dminist	rative Suites/Offices									
	AC Unit	1st flr Main Office Suite	2	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	1st flr Main Office Suite	1,060	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st flr Main Office Suite	6	EA	6	10+ years				
	Floor - Carpet	1st flr Main Office Suite	1,060	SF	6	6-10 years				
	Lighting - Pendent/Surface	1st flr Main Office Suite	16	EA	7	6-10 years				
	Power Distribution	1st flr Main Office Suite	24	EA	6	10+ years				
	Storage/ Closet	1st flr Main Office Suite	70	SF	7	10+ years				
	Walls - Plaster/Drywall	1st flr Main Office Suite	2,754	SF	6	10+ years	Patching throughout.			
	Ceiling - Exposed	Basement NE corner, engineer's office	133	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Basement NE corner, engineer's office	1	EA	6	10+ years				
	Floor - Concrete Epoxy/ Painted	Basement NE corner, engineer's office	133	SF	5	10+ years				
	Lighting - Pendent/Surface	Basement NE corner, engineer's office	1	EA	6	6-10 years				
	Power Distribution	Basement NE corner, engineer's office	6	EA	6	10+ years				
	Storage/ Closet	Basement NE corner, engineer's office	22	SF	7	10+ years				
	Walls - Masonry	Basement NE corner, engineer's office	500	SF	6	10+ years				
	Walls - Masonry	Basement NE corner, engineer's office	60	SF	5	0-1 year	Cracking.			
	Work Sink	Basement NE corner, engineer's office	1	EA	7	10+ years				
	Ceiling - Exposed	Basement Teacher's Lounge	825	SF	6	6-10 years	Paint chipping and peeling throughout.			
	Doors - Wood Doors inclu hw	Basement Teacher's Lounge	1	EA	5	6-10 years	-			
	Floor - Concrete Epoxy/ Painted	Basement Teacher's Lounge	825	SF	7	10+ years				
	Lighting - Pendent/Surface	Basement Teacher's Lounge	4	EA	7	6-10 years				

Campus Name: Prescott Page : 15 of 24 Assessment Date: 09/29/2021



Catego	Category : Room			uilding	: Additi	on	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Basement Teacher's Lounge	4	EA	7	10+ years	
	Walls - Masonry	Basement Teacher's Lounge	1,160	SF	6	6-10 years	
	Work SInk	Basement Teacher's Lounge	1	EA	7	10+ years	
	Ceiling - Exposed	Basement south end - Suite 007 Rooms	415	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement south end - Suite 007 Rooms	829	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement south end - Suite 007 Rooms	5	EA	6	10+ years	
	Floor - Carpet	Basement south end - Suite 007 Rooms	200	SF	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement south end - Suite 007 Rooms	415	SF	5	10+ years	
	Floor - Tile	Basement south end - Suite 007 Rooms	629	SF	5	2-5 years	Worn.
	Lighting - Pendent/Surface	Basement south end - Suite 007 Rooms	17	EA	6	6-10 years	
	Power Distribution	Basement south end - Suite 007 Rooms	12	EA	6	10+ years	
	Walls - Masonry	Basement south end - Suite 007 Rooms	1,443	SF	6	10+ years	
	Walls - Metal Panel	Basement south end - Suite 007 Rooms	411	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement south end - Suite 007 Rooms	722	SF	6	10+ years	
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	71	SF	5	10+ years	Paint chipping and peeling throughout, patches.
	Janitor's Closet	2nd Floor	71	SF	5	10+ years	Paint cracking and peeling throughout, floor deteriorated.
	Janitor's Closet	3rd Floor	71	SF	7	10+ years	
	Air Intake Plenums	Basement	847	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	476	SF	5	10+ years	Walls cracking off.
	Storage Room	Basement	699	SF	5	10+ years	S
Restroor	m						
	Accessories	1st Floor	273	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	273	SF	6	10+ years	Minor paint chipping.
	Floor - Tile Ceramic/ Porcelain	1st Floor	273	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	

Campus Name: Prescott Page : 16 of 24 Assessment Date: 09/29/2021



Catego	ry : Room		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	441	SF	6	10+ years	
	Water Closet	1st Floor	6	EA	6	10+ years	
	Accessories	1st flr inside principal's office	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside principal's office	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	35	SF	6	10+ years	
	Lavatory	1st flr inside principal's office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st flr inside principal's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr inside principal's office	220	SF	6	10+ years	
	Water Closet	1st flr inside principal's office	1	EA	6	10+ years	
	Accessories	2nd Floor	273	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	273	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	268	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	5	SF	4	0-1 year	Missing tiles.
	Floor Drain	2nd Floor	1	EA	7	10+ years	3
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	4	ĒΑ	7	10+ years	
	Urinals	2nd Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	442	SF	6	10+ years	
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	2nd Floor	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	42	SF	6	10+ years	
	Lavatory	2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	-	
	Walls - Plaster/Drywall	2nd Floor	194	SF	6	10+ years	
	Water Closet	2nd Floor	194	EA	7	10+ years	
		3rd Floor	273	SF	7	10+ years	
	Accessories		273 273	SF SF		6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor		SF SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	273		6	10+ years	
	Floor Drain	3rd Floor	1	EΑ	7	10+ years	
	Hand Dryer	3rd Floor	2	EΑ	7	6-10 years	
	Lavatory	3rd Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	3	EΑ	7	6-10 years	
	Partitions	3rd Floor	7	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	441	SF	6	10+ years	
	Water Closet	3rd Floor	7	EA	6	10+ years	
	Accessories	Basement NE Corner Office 005E	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement NE Corner Office 005E	48	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Additi	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement NE Corner Office 005E	1	EA	7	10+ years	
	Floor - Tile	Basement NE Corner Office 005E	48	SF	6	10+ years	
	Lavatory	Basement NE Corner Office 005E	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement NE Corner Office 005E	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement NE Corner Office 005E	308	SF	7	10+ years	
	Accessories	Basement inside Office 105E	22	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement inside Office 105E	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement inside Office 105E	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement inside Office 105E	22	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement inside Office 105E	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement inside Office 105E	170	SF	7	10+ years	
	Water Closet	Basement inside Office 105E	1	EA	6	10+ years	
	Accessories	In Classroom 005	22	SF	7	6-10 years	
	Ceiling - Exposed	In Classroom 005	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Classroom 005	1	EA	6	10+ years	
	Floor - Tile	In Classroom 005	22	SF	6	6-10 years	
	Lighting - Pendent/Surface	In Classroom 005	1	EA	6	6-10 years	
	Walls - Masonry	In Classroom 005	44	SF	6	10+ years	
	Water Closet	In Classroom 005	1	EA	6	10+ years	
	Accessories	Restroom inside 101	5	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Restroom inside 101	19	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom inside 101	19	SF	6	10+ years	
	Lighting - Pendent/Surface	Restroom inside 101	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Restroom inside 101	160	SF	6	10+ years	
	Water Closet	Restroom inside 101	1	EA	6	10+ years	
	Accessories	Unisex Room, 3rd Floor	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Room, 3rd Floor	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex Room, 3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Room, 3rd Floor	42	SF	6	10+ years	
	Lavatory	Unisex Room, 3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Unisex Room, 3rd Floor	1	EA	7	6-10 years	
	Partitions	Unisex Room, 3rd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Unisex Room, 3rd Floor	194	SF	6	10+ years	
	Water Closet	Unisex Room, 3rd Floor	1	EA	6	10+ years	
	Accessories	Women's Room, 1st Floor	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Room, 1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, 1st Floor	42	SF	6	10+ years	
	Lavatory	Women's Room, 1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's Room, 1st Floor	1	EA	7	6-10 years	
	Partitions	Women's Room, 1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's Room, 1st Floor	194	SF	6	10+ years	
	Water Closet	Women's Room, 1st Floor	1	EA	6	10+ years	
						•	

Campus Name: Prescott Page : 18 of 24 Assessment Date: 09/29/2021



Catego	ry : Classroom		В	uilding	: Additi		Winghtwood AVENOE, Officago, in 00014
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #005 (Regular Classroom)						
	Ceiling - Exposed	Basement	345	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	345	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	10+ years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Storage/ Closet	Basement	24	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	814	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
Classroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	800	SF	6	10+ years	
	Floor - Tile	1st Floor	16	SF	4	0-1 year	Chipped.
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years	
_Classroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years	
Classroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	5	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	

Campus Name: Prescott Page : 19 of 24 Assessment Date: 09/29/2021



Jaiego	ry : Classroom	Building : Addition					
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	6-10 years	
Classroc	nm #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	5	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	Very minor paint chipping.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	vory minor paint ompping.
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	
Classroc	om #305 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	
Closoror	om #306 (Regular Classroom)						
JIA55100		Ord Flags	2		7	0.40	
	AC Units	3rd Floor	2	EA LF	7	6-10 years	
	Casework	3rd Floor	8		6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	
Classroc	nm #307 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	

Campus Name: Prescott Page : 20 of 24 Assessment Date: 09/29/2021



Catego	ry : Classroom	Building : Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	
	Wireless System	3rd Floor	1	EΑ	7	10+ years	
	-					•	

Category: Interior Building: Addition

	y : intorio:		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor	7		•						
Comadi	Ceiling - Plaster/Drywall	1st Floor	369	SF	6	10+ years			
	Doors - Wood Doors include hw	1st Floor	2	EΑ	6	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	1	ΕA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	369	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	3	ĒΑ	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	369	SF	6	10+ years	Paint chipping and peeling.		
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	369	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	3	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	369	SF	6	10+ years			
	Doors - Wood Doors include hw	3rd Floor	2	EA	6	10+ years			
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	365	SF	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	4	SF	4	0-1 year	Cracked tiles		
	Lighting - Pendent/Surface	3rd Floor	3	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years			
	Ceiling - Exposed	Basement	382	SF	6	10+ years			
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement	387	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	5	EA	7	6-10 years			
	Stairs - Concrete Stairs	Basement	24	LF	6	10+ years			
	Walls - Masonry	Basement	1,161	SF	6	10+ years			

Campus Name: Prescott Page : 21 of 24 Assessment Date: 09/29/2021





Category: Site **Building: Site**

atego	ry : Site		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	East	15,200	SF	7	10+ years	
	•					·	
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	6-10 years	
	•					•	
Fencing							
	Fencing - Chain Link	Entire Site	77	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	566	LF	4	0-1 year	Rusting throughout.
andsca	pe						
	Benches	Entire Site	3	EA	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	8,480	SF	4	0-1 year	Cracking and potholes.
	Parkway trees	Entire Site	10	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	383	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	1,786	SF	4	0-1 year	Cracking and holes throughout.
Darkina I	at .						
Parking I	Surface - Asphalt	Parking Lot- East	7,724	SF	4	0-1 year	Cracking and potholes.
	Surface - Asphalt	Parking Lot- East	3,845	SF	4	0-1 year 0-1 year	Cracking and potholes due to
	Surface - Aspirali	r arking Lot- Last	3,043	OI.	7	0-1 year	construction.
	Trash Enclosure - Chain Links	Parking Lot- East	56	SF	7	6-10 years	construction.
	Tradit Ethologica Chain Elinio	Tanking Lot Labt	00	O.	•	o to youro	
Playgrou	ind						
, ,	Equipment - Combo 3-12	North	1	EA	6	6-10 years	
	Surface - Poured Surface	North	2,678	SF	6	6-10 years	
						•	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	70	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,800	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	41	SF	4	0-1 year	Uneven concrete due to tree.
٥.							
Signage	Flog Dolo - Flog Dolo	Cita Foot Couth Foot and Fatages		EA	7	10	Dor building Engineer building
	Flag Pole - Flag Pole	Site East, South East and Entrance	1	EA	/	10+ years	Per building Engineer building
		1 & 2					mounted removed - Flag Pole
	Margues - Free Standing Book Lighted	Site Feet South Feet and Entrese	4	⊏^	e	6 10 40000	Installed. Paint/
	Marquee - Free Standing Back Lighted	Site East, South East and Entrance 1 & 2	1	EA	6	6-10 years	raiiii/
	Monument - Building Mounted Cut Letter	Site East, South East and Entrance	2	EA	6	10+ years	
			,	E A	n	10+ 74215	



William H Prescott Elementary School

1632 W Wrightwood AVENUE, Chicago, IL 60614

Category : Site Building : Site

Group Item - Type Location Quantity UOM Rank Replacement Comments
Sign 1 & 2

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Prescott Page : 23 of 24 Assessment Date: 09/29/2021



Classroom Summary

·			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	<u> </u>		•	•		•	•	•	
Kindergarten	Kindergarten	1st Floor	101	101	900	85	9	Y	N
Kindergarten	Kindergarten	Basement	001	001	688	120	20	N	N
Kindergarten	Regular Classroom	1st Floor	103	103	900	85	9	Y	N
Kindergarten	Regular Classroom	1st Floor	104	104	900	121	15	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	900	85	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	900	85	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,800	136	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	202,203	875	150	75		
Regular Classroom	Regular Classroom	2nd Floor	204	204	900	121	15	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	900	85	9	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	900	121	15	Υ	N
Building : Addition									
Computer Lab	Regular Classroom	3rd Floor	307	307	816	180	90	N	N
Regular Classroom	Library	2nd Floor	205	205	816	180	90	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	816	180	90	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	816	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	816	180	90	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	816	180	90	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	816	180	90	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	816	180	90	N	N
Regular Classroom	Regular Classroom	Basement	005	005	345	32	16		