

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1907	3	80,075
Campus Total			80,075

Category : Exterior Building : Main

Recommend		
Location Quantity UOM Rank Replacement C	Location Quan	Comments
#1 W 1 EA 7 10+ years E	and Video #1 W	Entrance control in good condition
#1 W 3 EA 6 10+ years		
#1 W 3 EA 6 10+ years	n Lite #1 W	
#1 W 20 LF 5 0-1 year C	#1 W	Cracked stone, missing pieces.
#2 W 3 EA 6 10+ years	AMP Door #2 W	
#2 W 3 EA 6 10+ years	n Lite #2 W	
#2 W 20 LF 5 6-10 years M	#2 W	Minor cracking.
#3 W 3 EA 6 10+ years	AMP Door #3 W	
#3 W 3 EA 6 10+ years	n Lite #3 W	
#3 W 20 LF 5 6-10 years	e #3 W	
#3.5 S 1 EA 6 10+ years	Steel Door #3.5 S	
#3.5 S 4 LF 6 10+ years	#3.5 S	
#4 E 1 EA 7 10+ years	and Video #4 E	
#4 E 2 EA 6 10+ years	Steel Door #4 E	
#4 E 25 LF 6 10+ years	#4 E	
#4.2 SE 1 EA 6 10+ years	Steel Door #4.2 SE	
#4.2 SE 3 LF 6 10+ years	#4.2 SE	
#4.5 Northeast 1 EA 6 10+ years	Steel Door #4.5 Northeast	
#4.5 Northeast 3 LF 6 10+ years	#4.5 Northeast	
#4.7 NE 1 EA 6 10+ years	Steel Door #4.7 NE	
#4.7 NE 3 LF 6 10+ years		
#5 E 1 EA 6 10+ years	and Video #5 E	
#5 E 2 EA 6 10+ years	Steel Door #5 E	
#5 E 6 LF 6 10+ years	#5 E	
#5 E 2 EA 6 10+ years	Steel Door #5 E	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundati	on						
r oundan	Foundation - Concrete	Entire Building	953	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	80,000	SF	7	10+ years	
	Supercurature Steel With Stay The 7th Sh	Entire Ballating	00,000	O.	•	Tot youro	
Lighting							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	7	10+ years	
Roof Sys	etem						
	Chimney - Brick Chimney- Concrete/ Mortar	East Low Roof	40	LF	6	10+ years	
	Liner		_			, , , , ,	
	Chimney - Brick Chimney- Concrete/ Mortar	East Low Roof	25	LF	5	0-1 year	Large cracks and open Joints.
	Liner					•	·
	Chimney - Metal Flue	East Low Roof	21	LF	6	10+ years	
	Coping - Terra Cotta	East Low Roof	167	LF	6	10+ years	
	Downspouts - Interior Downspouts	East Low Roof	45	LF	6	10+ years	
	Parapet - 16" - 30" Height	East Low Roof	167	LF	6	10+ years	
	Roof - Modified Bitumen	East Low Roof	2,625	SF	5	2-5 years	No access to this roof
	Roof Structure - Steel with Clay Tile Arch	East Low Roof	2,625	SF	7	10+ years	
	Access Ladder - Wood	Main Roof	2	EA	4	0-1 year	Unsafe homemade wood ladder. Large gaps between two ladders. To ladder takes up much of the hatch area.
	Coping - Clay Tile	Main Roof	280	LF	6	10+ years	a.ca.
	Coping - Terra Cotta	Main Roof	770	LF	6	10+ years	Verified dimension
	Downspouts - Interior Downspouts	Main Roof	660	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	244	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	489	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	19,015	SF	6	2-5 years	
	Roof - Modified Bitumen	Main Roof	800	SF	4	0-1 year	Soft spots, ponding, blistering.
	Roof Hatch - Metal	Main Roof	1	EA	4	0-1 year	Corroded hatch, Damaged latch
	Roof Structure - Steel with Clay Tile Arch	Main Roof	19,815	SF	7	10+ years	Corroded riaters, Damaged laters
	Coping - Terra Cotta	NW Low Roof	28	LF	6	10+ years	
	Downspouts - Interior Downspouts	NW Low Roof	15	LF	6	10+ years	
	Parapet - Parapet > 30"	NW Low Roof	28	LF	6	10+ years	
	Roof - Modified Bitumen	NW Low Roof	160	SF	6	6-10 years	No current leaks reported
	Roof Structure - Steel / Metal Deck/	NW Low Roof	160	SF	7	10+ years	No current leaks reported
	Concrete Topping	INVV LOW IVOOI	100	J.	,	10+ years	
	Coping - Terra Cotta	SW Low Roof	28	LF	6	10+ years	
	Downspouts - Interior Downspouts	SW Low Roof	15	LF	6	10+ years	
	Parapet - Parapet > 30"	SW Low Roof	28	LF	6	10+ years	
	Roof - Modified Bitumen	SW Low Roof	160	SF	6	6-10 years	Repaired



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Roof Structure - Steel with Clay Tile Arch	SW Low Roof	160	SF	7	10+ years	
	Coping - Terra Cotta	West Middle Low Roof	42	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Middle Low Roof	26	LF	6	10+ years	
	Parapet - 16" - 30" Height	West Middle Low Roof	14	LF	6	10+ years	
	Parapet - Parapet > 30"	West Middle Low Roof	28	LF	6	10+ years	
	Roof - Modified Bitumen	West Middle Low Roof	240	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	West Middle Low Roof	240	SF	7	10+ years	
Valls							
vans	Exterior Walls - Brick	Entire Building	22,300	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	11,160	SF	5	10+ years	Open Joints and flush pointed
		•				•	masonry
	Exterior Walls - Brick	Entire Building	40	SF	4	0-1 year	Cracked brick, open joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,720	SF	5	10+ years	Corroding metal
	Exterior Walls - Terra Cotta	Entire Building	4,700	SF	5	10+ years	Open Joints throughout the building
	Exterior Walls - Terra Cotta	Entire Building	250	SF	4	0-1 year	Cracked and chipped terra-cotta
Vindows	S						
	Guard - Guards perforated	Entire Building	1,540	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,405	LF	6	10+ years	
	Lintels - Steel	Entire Building	15	LF	4	0-1 year	Boiler room door lentils 3.5, 4.5 ar
							4.7. Corroded, deflected Lintel
	Windows - Louver	Entire Building	12	SF	6	10+ years	
	Windows - Wood- Single-pane	Entire Building	11,400	SF	4	0-1 year	Rotted wood, leaking air and wate
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System	_					
	UPS - Greater than 60	Basement	2	EA	5	2-5 years	
	UPS - Less than 30 KW	Basement	1	EA	5	2-5 years	
	Automatic Transfer Switch	Electrical Room	2	EA	7	6-10 years	
	Exit Signs - Auditoium	Entire Building	12	EA	7	6-10 years	Repaired.
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	7	6-10 years	Repaired.
	Exit Signs - Gym	Entire Building	2	EA	7	6-10 years	Repaired.
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	Repaired.
	Security System - CCTV	Entire Building	80,075	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	80,075	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,662	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	8,058	SF	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Gym	Entire Building	3,230	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,417	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	6	6-10 years	New item added per current observation
	Emergency Battery Packs - Corridors and Stairs	Entire Building	8	EA	6	2-5 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	2-5 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	2-5 years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	New item added per current observation
Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	6-10 years	
	PA System	Entire Building	80,075	SF	5	2-5 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EΑ	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Amps change per current observati
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	New item added per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	Quantity change per current observation
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Expose breakers
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	2-5 years	Quantity change per current observation
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	6	2-5 years	Quantity change per current observation
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	3	1-2 years	Not reliable and older system.
	Fire Alarm_System	Mechanical Room	80,075	SF	4	1-2 years	No strobe light and older system.

Campus Name: Pullman Page : 4 of 27 Assessment Date: 05/16/2022



Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Electrical Room Mechanical Room	1	EA EA	6 5	6-10 years 6-10 years	Serves all classrooms north and south. Coil leaking needs repair.
	Air Intake	Mechanical Room	2	EA	6	6-10 years	Working with pneumatic system Per building engineer - replace new actuators in 2020
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	200	LF	6	6-10 years	Paint required.
	Zone Dampers	Mechanical Room	34	EA	6	6-10 years	Working with pneumatic system Per building engineer - replace new actuators in 2020
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves auditorium.
	Air Intake	Mechanical Room	2	EA	6	6-10 years	Working with pneumatic system Per building engineer - replace new actuators in 2020.
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	4	EA	6	6-10 years	Working with pneumatic system Per building engineer - replace new actuators in 2020
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	2-5 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	2	EA	6	2-5 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	Rusty.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	2-5 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	2-5 years	
	Steam Traps	Boiler Room	8	EA	5	6-10 years	

Campus Name: Pullman Page : 5 of 27 Assessment Date: 05/16/2022



Catego	ry : Mechanical		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-leating	Devices						
	Wall Heater - Electric	1st and 2nd Floor	1	EA	6	6-10 years	
	Wall Heater - Electric	1st and 2nd Floor	3	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	4	0-1 year	Older units and coil not working.
	Radiators - Steam	Entire Building	2	EA	7	10+ years	New item added per current observation 2nd and 3rd floors Installed new in 2020
	Unit Heater - Electric	Entire Building, Boiler room, Electrical Room	2	EA	6	2-5 years	
	Unit Heater - Electric	Entire Building, Boiler room, Electrical Room	7	EA	6	6-10 years	
	Unit Heater - Gas	Entire Building, Boiler room, Electrical Room	1	EA	5	1-2 years	Control needs replacement
empera	ature Control						
	Electric Thermostat	Entire Building	10	EA	7	6-10 years	Quantity change per current observation Serves all electric heaters.
	Pneumatic System	Entire Building	80,075	SF	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	33	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	1	EA	4	0-1 year	Removed.
entilati	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
			_				

Category: Plumbing

Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Rusty unit. Need recirculate pump for water pressure. Older than 15 years.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	80,075	SF	4	2-5 years	Older pipes and water pressure and flow not reaching out to the 2nd and 3rd floor toilet
	Domestic Piping-Hot Water Return Risers	Entire Building	80,075	SF	4	2-5 years	Older pipes and water pressure and flow not reaching out to the 2nd and 3rd floor toilet



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	80,075	SF	4	2-5 years	Older pipes and water pressure and flow not reaching out to the 2nd and 3rd floor toilet
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	80,075	SF	4	1-2 years	Older pipes and water pressure and flow not reaching out to the 2nd and 3rd floor toilet
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	80,075	SF	4	2-5 years	Older pipes and water pressure and flow not reaching out to the 2nd and 3rd floor toilet
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	80,075	SF	4	2-5 years	Rusty and older pipes
	Sanitary Piping	Entire Building	80,075	SF	4	2-5 years	Rusty and older pipe
	Storm Piping	Entire Building	80,075	SF	4	2-5 years	Rusty and older pipes
	Vent Piping	Entire Building	80,075	SF	4	2-5 years	Rusty and older pipe
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	2-5 years	
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	2-5 years	No pump in pit. It is connected with the condensation tank and with the sewer pipe.

Category : Room **Building: Main**

Croun	Itam Tuna	Lagation	Ouantitu	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOIVI	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	003 - Engineer	450	SF	6	10+ years	
	Doors - Wood Doors inclu hw	003 - Engineer	1	EΑ	7	10+ years	
	Floor - Concrete	003 - Engineer	450	SF	5	10+ years	
	Lighting - Pendent/Surface	003 - Engineer	4	EA	7	10+ years	
	Power Distribution	003 - Engineer	2	EA	7	10+ years	
	Walls - Plaster/Drywall	003 - Engineer	502	SF	6	10+ years	
	Walls - Plaster/Drywall	003 - Engineer	20	SF	4	0-1 year	Crack paint/damaged plaster
	Walls - Structural Glazed Tile	003 - Engineer	84	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	003 - Engineer	344	SF	7	10+ years	
	Work SInk	003 - Engineer	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Lounge	87	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Lounge	1	SF	4	0-1 year	Unfinished wiring
	Doors - Transom Window	3rd Floor - Teacher's Lounge	9	SF	7	10+ years	· ·
	Doors - Wood Doors inclu hw	3rd Floor - Teacher's Lounge	1	EA	7	10+ years	
	Floor - Carpet	3rd Floor - Teacher's Lounge	88	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor - Teacher's Lounge	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Lounge	115	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Speech Room	228	SF	7	10+ years	
	Doors - Side-lite	Basement - Speech Room	24	SF	7	10+ years	

Campus Name: Pullman Page : 7 of 27 Assessment Date: 05/16/2022



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Basement - Speech Room	1	EA	7	10+ years	
	Floor - Tile	Basement - Speech Room	222	SF	7	10+ years	
	Floor - Tile	Basement - Speech Room	6	SF	4	0-1 year	Chipped tile
	Lighting - Pendent/Surface	Basement - Speech Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Speech Room	262	SF	7	10+ years	
	Ceiling - Lay-in	Basement - Teacher's Lounge	761	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile	Basement - Teacher's Lounge	761	SF	7	10+ years	
	Lighting - Lay-in	Basement - Teacher's Lounge	13	EA	7	10+ years	
	Power Distribution	Basement - Teacher's Lounge	16	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Teacher's Lounge	1,522	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement Mechanical Room - Break Room	70	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement Mechanical Room - Break Room	50	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	Basement Mechanical Room - Break Room	2	EA	7	10+ years	
	Floor - Tile	Basement Mechanical Room - Break Room	120	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement Mechanical Room - Break Room	2	EA	7	10+ years	
	Power Distribution	Basement Mechanical Room - Break Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Mechanical Room - Break Room	130	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement Mechanical Room - Break Room	30	SF	4	0-1 year	Cracked wall
	Ceiling - Exposed	Kitchen	254	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years	
	Floor - Tile	Kitchen	254	SF	4	0-1 year	Uneven floor, cracking.
	Lighting - Pendent/Surface	Kitchen	3	EA	7	10+ years	oneven hoor, cracking.
	Power Distribution	Kitchen	6	EΑ	7	10+ years	
	Walls - Masonry	Kitchen	317	SF	6	10+ years	
	AC Unit	Main Office - 1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office - 1st Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - 1st Floor	1	EA	7	10+ years	
	Floor - Tile	Main Office - 1st Floor	800	SF	7	6-10 years	
	Lighting - Lay-in	Main Office - 1st Floor	6	EA	7	6-10 years	
	Power Distribution	Main Office - 1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office - 1st Floor	860	SF	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal's Office	236	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	24	SF	4	0-1 year	Water damage.
	Doors - Transom Window	Principal's Office	27	SF	7	10+ years	
		•				·	



Jacogo	ry : Room		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Wood Doors inclu hw	Principal's Office	3	EΑ	7	10+ years	
	Floor - Carpet	Principal's Office	260	SF	7	6-10 years	
	Lighting - Lay-in	Principal's Office	6	EA	7	6-10 years	
	Storage/ Closet	Principal's Office	60	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	295	SF	7	10+ years	
uditoriu	ım & Theater						
	Balcony Seating	1st Floor	110	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,662	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,000	SF	4	0-1 year	Crack ceiling
	Doors - Wood Doors inclu hw	1st Floor	6	EA	7	10+ years	Ordok coming
	Floor - Tile	1st Floor	2,253	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	4	0-10 years 0-1 year	Damaged tile
	Floor - Wood	1st Floor	1,399	SF	7	•	Damaged tile
		1st Floor		EA		10+ years	
	Lighting - Pendent/Surface		32		7	6-10 years	
	Main Floor Seating	1st Floor	380	EA	7	10+ years	
	Stage	1st Floor	418	SF	7	10+ years	
	Stage Curtain	1st Floor	2	EΑ	7	10+ years	
	Stage Lighting System	1st Floor	2	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	8	LF	7	10+ years	
	Walls - Masonry	1st Floor	1,707	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,407	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	5	0-1 year	Damaged wall
iymnasi							
	Ceiling - Plaster/Drywall	3rd Floor	3,160	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	70	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	10+ years	
	Floor - Wood	3rd Floor	3,230	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	9	EA	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	3	EA	4	0-1 year	Cracking covers
	Scoreboards	3rd Floor	1	EA	7	10+ years	· ·
	Walls - Metal Panel	3rd Floor	1,615	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,422	SF	7	10+ years	
itchen							
	Ceiling - Exposed	Basement	321	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	321	SF	4	0-1 year	Uneven floor, cracking.
	Lighting - Pendent/Surface	Basement	4	EA	7	10+ years	chief and moon, ordering.
	Serving Line	Basement	8	LF	7	10+ years	
	Walls - Masonry	Basement	189	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	189	SF	7	10+ years	

Campus Name: Pullman Page : 9 of 27 Assessment Date: 05/16/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lunch 8	Multipurpose Room						
LUNCHA	Ceiling - Lay-in	Basement	1,399	SF	7	10+ years	
	Ceiling - Lay-in	Basement	1,599	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	Basement	4	EA	7	10+ years	water damage.
	Floor - Tile	Basement	=	SF	7		
			1,417			10+ years	
	Lighting - Pendent/Surface	Basement	18	EA	7	10+ years	
	Walls - Masonry	Basement	1,708	SF	7	10+ years	D
	Walls - Masonry	Basement	20	SF	5	0-1 year	Damaged wall
	Ceiling - Plaster/Drywall	Basement - Play Room	968	SF	6	10+ years	
	Chalk Board	Basement - Play Room	10	LF	4	2-5 years	
	Doors - Side-lite	Basement - Play Room	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Play Room	1	EA	7	10+ years	
	Floor - Wood	Basement - Play Room	968	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - Play Room	17	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Play Room	1,094	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
	Finishes	Basement	171	SF	5	10+ years	Peeling paint on ceiling
	Other Cooling Unit	Basement	1	EA	5	1-2 years	Split system - air conditioner. Need
	cure cosmig cim	2400	•		· ·	/ 505	to be serviced
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	42	SF	7	10+ years	
	Janitor's Closet	1st Floor	42	SF	4	0-1 year	Water damage throughout.
	Janitor's Closet	2nd Floor	42	SF	7	10+ years	
	Janitor's Closet	2nd Floor	42	SF	5	10+ years	Holes in walls.
	Janitor's Closet	3rd Floor	42	SF	7	10+ years	Updated quantity
	Janitor's Closet	3rd Floor	42	SF	7	10+ years	
	Air Intake Plenums	Basement	200	SF	5	10+ years	Spalling wall
	Air Tunnel	Basement	1,129	SF	7	10+ years	
	Boiler Room	Basement	1,111	SF	5	10+ years	
	Coal Room	Basement	170	SF	5	10+ years	
	Coal Room	Basement	75	SF	5	10+ years	Spalling wall
	Mechanical/ Service Rooms	Basement	2,725	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	50	SF	5	10+ years	Spalling wall.
	Storage Room	Basement	2,904	SF	5	10+ years	Peeling paint
	Storage Room	Basement	40	SF	5	10+ years	Spalling wall.
Restroor	m						
_176911001	Accessories	1st Floor	335	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	305	SF	7	10+ years	
	5 ,					,	

Campus Name: Pullman Page : 10 of 27 Assessment Date: 05/16/2022



Category : Room		В	uilding	: Main			
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	30	SF	5	0-1 year	Cracked.
	Floor - Tile Ceramic/ Porcelain	1st Floor	335	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	204	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	102	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	102	SF	7	10+ years	
	Water Closet	1st Floor	5	ĒΑ	7	10+ years	
	Accessories	1st Floor	328	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	328	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	328	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EΑ	7	6-10 years	
	Partitions	1st Floor	2	EΑ	7	10+ years	
	Urinals	1st Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	199	SF	7	10+ years	
	Walls - Plaster/Drywaii Walls - Structural Glazed Tile	1st Floor	199	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor Restroom / Lounge	211	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Restroom / Lounge	211	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Restroom / Lounge	2	EA	7	10+ years	
	Floor - Tile	1st Floor Restroom / Lounge	211	SF	7	6-10 years	
	Lavatory	1st Floor Restroom / Lounge	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor Restroom / Lounge	2	EA	7	6-10 years	
	Partitions	1st Floor Restroom / Lounge	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Restroom / Lounge	420	SF	7	10+ years	
	Water Closet	1st Floor Restroom / Lounge	420	EA	7		
	Accessories	2nd Floor	335	SF	7	10+ years 6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	335	SF	7	•	
	Floor - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	335	SF	7	10+ years	
		2nd Floor	333	EA	7	6-10 years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor	5	EA		10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	5 1	EA EA	7 5	6-10 years	Missing sover
	Lighting - Pendent/Surface		-			0-1 year	Missing cover
	Partitions Walls - Plaster/Drywall	2nd Floor 2nd Floor	5 204	EA SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Structural Glazed Tile		204 102	SF SF	7 7	10+ years	
		2nd Floor		SF SF		10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	102		7	10+ years	
	Water Closet	2nd Floor	5	EA	7	10+ years	
	Accessories	2nd Floor	328	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	328	SF	6	10+ years	



Catego	Category : Room			uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	2nd Floor	328	SF	7	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	199	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	199	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor Restroom / Lounge	211	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Restroom / Lounge	205	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Restroom / Lounge	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor Restroom / Lounge	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Restroom / Lounge	211	SF	7	6-10 years	
	Lavatory	2nd Floor Restroom / Lounge	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	2nd Floor Restroom / Lounge	3	EA	7	6-10 years	
	Partitions	2nd Floor Restroom / Lounge	1	EA	5	0-1 year	Missing slats
	Walls - Plaster/Drywall	2nd Floor Restroom / Lounge	420	SF	7	10+ years	-
	Water Closet	2nd Floor Restroom / Lounge	1	EA	7	10+ years	
	Accessories	3rd Floor	335	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	335	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	335	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	Updated to match current observations
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	10+ years	
	Partitions	3rd Floor	5	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	204	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	102	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	102	SF	7	10+ years	
	Water Closet	3rd Floor	5	EA	7	10+ years	
	Accessories	3rd Floor	328	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	328	SF	6	10+ years	
	Floor - Concrete	3rd Floor	328	SF	7	10+ years	Updated to match current observations
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	10+ years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	199	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	199	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
						•	

Campus Name: Pullman Page : 12 of 27 Assessment Date: 05/16/2022



ategory : Room			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Floor - Teacher's Lounge	128	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Lounge	127	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Lounge	1	SF	4	0-1 year	Unfinished wiring
	Doors - Wood Doors inclu hw	3rd Floor - Teacher's Lounge	1	EA	6	10+ years	Security plate loose
	Floor - Tile	3rd Floor - Teacher's Lounge	128	SF	7	10+ years	
	Lavatory	3rd Floor - Teacher's Lounge	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor - Teacher's Lounge	1	EA	7	10+ years	
	Partitions	3rd Floor - Teacher's Lounge	1	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Lounge	155	SF	7	10+ years	
	Water Closet	3rd Floor - Teacher's Lounge	1	ĒΑ	7	10+ years	
	Accessories	Engineer's Office	39	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	39	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years	rrater damager
	Floor - Concrete	Engineer's Office	39	SF	5	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	159	SF	7	10+ years	
	Walls - Structural Glazed Tile	Engineer's Office	42	SF	7	-	
						10+ years	
	Water Closet	Engineer's Office	1	EA	7	10+ years	
	Accessories	In Office 206	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Office 206	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Office 206	1	EA	7	10+ years	
	Floor - Tile	In Office 206	34	SF	6	6-10 years	
	Floor - Tile	In Office 206	2	SF	4	0-1 year	Broken tiles
	Lavatory	In Office 206	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Office 206	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Office 206	89	SF	7	10+ years	
	Water Closet	In Office 206	1	EΑ	7	10+ years	
	Accessories	Restroom in Principal office	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in Principal office	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom in Principal office	1	ĒΑ	7	10+ years	
	Floor - Tile	Restroom in Principal office	80	SF	7	6-10 years	
	Lavatory	Restroom in Principal office	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	Restroom in Principal office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom in Principal office	210	SF	6	10+ years	
	Water Closet	Restroom in Principal office	1	EA	7	10+ years	
	Accessories	next to Boiler Room	24	SF	7	6-10 years	
		next to Boiler Room		SF SF			Water demage
	Ceiling - Plaster/Drywall		24		5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	next to Boiler Room	1	EA	6	10+ years	
	Floor - Concrete	next to Boiler Room	24	SF	5	10+ years	
	Lavatory	next to Boiler Room	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	next to Boiler Room	1	EA	7	10+ years	
	Walls - Plaster/Drywall	next to Boiler Room	114	SF	6	10+ years	
	Walls - Plaster/Drywall	next to Boiler Room	30	SF	5	0-1 year	Damaged wall
	Water Closet	next to Boiler Room	1	EΑ	7	10+ years	

Campus Name: Pullman Page : 13 of 27 Assessment Date: 05/16/2022



Catego	ry : Room		В	uilding	: Main		o i offestville Avertoe, officago, le 00020
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Classroom		В	uilding	· Main		
Guiogo			_	anamg	· mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #001 (Store Room)		•			•	
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	761	SF	7	10+ years	
	Chalk Board	Basement	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood	Basement	761	SF	6	10+ years	
	Lighting - Lay-in	Basement	15	ĒΑ	7	10+ years	
	Marker Board	Basement	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,522	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
_Classroo	om #002 (Lunch Room)						
	Ceiling - Plaster/Drywall	Basement	723	SF	7	10+ years	
	Chalk Board	Basement	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	723	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	10+ years	
	Marker Board	Basement	12	LF	7	6-10 years	
	Walls - Masonry	Basement	631	SF	7	10+ years	
	Walls - Metal Panel	Basement	78	SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall	Basement Basement	210 50	SF SF	7 5	10+ years 0-1 year	Damaged plaster
	vvalis - Flastel/Diywali	Dasement	30	SI	5	0-1 year	Damageu plastei
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	924	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	40	SF	4	1-2 years	Cracked tile
	Floor - Tile/Sheet	1st Floor	884	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	991	SF	6	10+ years	
_Classroo	om #102 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	7	10+ years	



Category : Classroom			В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	898	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Cracked tile		
	Chalk Board	1st Floor	8	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Carpet	1st Floor	910	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	14	ĒΑ	7	6-10 years			
	Storage/ Closet	1st Floor	174	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,294	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Cracked wall		
lassroc	om #103 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	924	SF	7	10+ years			
	Chalk Board	1st Floor	32	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
			1		7	•			
	Doors - Wood Doors inclu hw	1st Floor	· · · · · · · · · · · · · · · · · · ·	EA		10+ years			
	Floor - Wood	1st Floor	922	SF	7	10+ years	Mississons also also		
	Floor - Wood	1st Floor	2	SF	4	0-1 year	Missing wooden plank		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Storage/ Closet	1st Floor	120	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	991	SF	7	10+ years			
lassroc	om #104 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	910	SF	7	10+ years			
	Chalk Board	1st Floor	30	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years			
	Floor - Wood	1st Floor	910	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	14	ĒΑ	7	10+ years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	174	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	910	SF	7	10+ years			
lassroc	om #106 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	1st Floor	910	SF	7	10+ years			
	Chalk Board	1st Floor	24	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7				
		1st Floor	1			10+ years			
	Doors - Wood Doors inclu hw		•	EA SF	7	10+ years			
	Floor - Wood	1st Floor	910	5F	7	10+ years			

Campus Name: Pullman Page : 15 of 27 Assessment Date: 05/16/2022



Category : Classroom		В	uilding	: Main			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	174	SF	5	10+ years	Water damage ceiling.
	Walls - Plaster/Drywall	1st Floor	1,304	SF	6	10+ years	
lassroc	om #107 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,216	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	['] 16	SF	4	0-1 year	Cracked tile.
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Wood	1st Floor	1,232	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,199	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	5	•	Water demage
	walls - Flastel/Drywall	151 F1001	100	SF	5	0-1 year	Water damage.
lassroc	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	910	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	910	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,304	SF	7	10+ years	
lassroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	924	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Books includition	1st Floor	924	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7		
		1st Floor	991	SF SF	7	10+ years	
	Walls - Plaster/Drywall	1St Floor	991	SF	,	10+ years	
lassroc	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	924	SF	7	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	



Category : Classroom			В	uilding	: Main		
				9		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	924	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	120	SF	5	10+ years	Cracking plaster
	Walls - Plaster/Drywall	2nd Floor	991	SF	6	10+ years	Craciang places
lassroc	om #202 (Regular Classroom)						
iciooi oc	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	910	SF	7	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	Covered
				SF			Covered
	Doors - Transom Window	2nd Floor	9		7	10+ years	Loose bordware
	Doors - Wood Doors inclu hw	2nd Floor		EA SF	6	10+ years	Loose hardware.
	Floor - Tile	2nd Floor	895		7	6-10 years	
	Floor - Wood	2nd Floor	15	SF	4	0-1 year	Wood board sagging
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	B 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Lighting - Lay-in	2nd Floor	1	EA	5	0-1 year	Broken light switch
	Lighting - Lay-in	2nd Floor	1	EA	5	0-1 year	Does not work.
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	910	SF	7	10+ years	
lassroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	924	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Chipped
	Floor - Wood	2nd Floor	912	SF	7	6-10 years	• •
	Floor - Wood	2nd Floor	12	SF	4	0-1 year	Wood seal damage
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	Updated quantity
	Marker Board	2nd Floor	8	LF	7	6-10 years	opaatoa quay
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	991	SF	7	10+ years	
lassroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	910	SF	7	10+ years	
	Doors - Transom Window	2nd Floor		SF SF	7		
			18 2	SF EA	<i>7</i> 6	10+ years	Looso socurity plata
	Doors - Wood Doors inclu hw	2nd Floor		SF		10+ years	Loose security plate
	Floor - Wood	2nd Floor	910		7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Updated quantity

Campus Name: Pullman Page : 17 of 27 Assessment Date: 05/16/2022



Item - Type Marker Board Storage/ Closet Walls - Plaster/Drywall	Location 2nd Floor 2nd Floor	Quantity	UOM		Recommend	
Marker Board Storage/ Closet	2nd Floor		HOM			
Storage/ Closet		40		Rank	Replacement	Comments
	2nd Floor	12	LF	7	6-10 years	
Walls - Plaster/Drywall		174	SF	7	10+ years	
	2nd Floor	1,304	SF	7	10+ years	
n #205 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Lay-in	2nd Floor	1,232	SF	7	10+ years	
Chalk Board	2nd Floor	30	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Wood	2nd Floor	1,232	SF	7	10+ years	
Lighting - Lay-in				7	-	
	2nd Floor	8			•	
Storage/ Closet	2nd Floor	120		7	,	
	2nd Floor	1,299	SF	7	10+ years	
n #206 (Office)						
AC Units	2nd Floor	1	EA	7	6-10 years	
		900		7		
			SF	4		Water damage and broken.
	2nd Floor	30		4		3
		1			•	
		905				
						Cracking and chipped tiles
						Gradining and dripped med
					•	
	2nd Floor	4	SF	5	0-1 year	Cracking
n #207 (Regular Classroom)						
	2nd Floor	1	EA	7	6-10 years	
	2nd Floor					
					•	
					,	
					,	
		_				
					-	
	Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall 1 #206 (Office) AC Units Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall Walls - Plaster/Drywall 207 (Regular Classroom) AC Units Casework Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall	Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board AC Units Ceiling - Lay-in Doors - Transom Window Storage/ Closet AC Units Doors - Transom Window Doors - Transom Window Doors - Transom Window Doors - Tile Lighting - Lay-in Marker Board Doors - Tile Lighting - Lay-in Marker Board Doors - Tile Ceiling - Lay-in Cores - Tile Cores - Transom Window Cores - Transom	Chalk Board 2nd Floor 30 Doors - Transom Window 2nd Floor 9 Doors - Wood Doors inclu hw 2nd Floor 1 Floor - Wood 2nd Floor 1,232 Lighting - Lay-in 2nd Floor 14 Marker Board 2nd Floor 120 Storage/ Closet 2nd Floor 120 Walls - Plaster/Drywall 2nd Floor 1,299 ***206 (Office) 1 2nd Floor 1 AC Units 2nd Floor 1 20 Ceiling - Lay-in 2nd Floor 10 20 Chalk Board 2nd Floor 10 20 Chalk Board 2nd Floor 30 30 Doors - Wood Doors inclu hw 2nd Floor 9 30 Doors - Wood Doors inclu hw 2nd Floor 9 30 Floor - Tile 2nd Floor 9 5 Lighting - Lay-in 2nd Floor 14 4 Marker Board 2nd Floor 174 4 Walls - Plaster/Dr	Chalk Board 2nd Floor 30 LF Doors - Transom Window 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Floor - Wood 2nd Floor 1,232 SF Lighting - Lay-in 2nd Floor 14 EA Marker Board 2nd Floor 120 SF Walls - Plaster/Drywall 2nd Floor 120 SF Walls - Plaster/Drywall 2nd Floor 1 EA Ceiling - Lay-in 2nd Floor 10 SF Ceiling - Lay-in 2nd Floor 10 SF Ceiling - Lay-in 2nd Floor 30 LF Doors - Wood Doors inclu hw 2nd Floor 1 EA Floor - Tile 2nd Floor 1 EA Floor - Tile 2nd Floor 5 SF Floor - Tile 2nd Floor 5 SF Lighting - Lay-in 2nd Floor 14 EA Marker Board 2nd Floor 174 SF	Chalk Board 2nd Floor 30 LF 4 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 Floor - Wood 2nd Floor 1,232 SF 7 Lighting - Lay-in 2nd Floor 14 EA 7 Marker Board 2nd Floor 8 LF 7 Storage/ Closet 2nd Floor 120 SF 7 Walls - Plaster/Drywall 2nd Floor 120 SF 7 Walls - Plaster/Drywall 2nd Floor 1 EA 7 AC Units 2nd Floor 90 SF 7 Ceiling - Lay-in 2nd Floor 90 SF 7 Ceiling - Lay-in 2nd Floor 90 SF 7 Doors - Wood Doors inclu hw 2nd Floor 9 SF 7 Doors - Wood Doors inclu hw 2nd Floor 90 SF 7 Floor - Tile 2nd Floor	Chalk Board

Campus Name: Pullman Page : 18 of 27 Assessment Date: 05/16/2022



Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	910	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	910	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,304	SF	7	10+ years	
Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	924	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	924	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	991	SF	7	10+ years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	916	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Cracked tiles
	Chalk Board	3rd Floor	38	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	924	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	981	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Cracking plaster
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	40	LF	4	2-5 years	Covered, but still used
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
		·	•	SF	7	, , , , , , , , ,	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	174	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,304	SF	6	10+ years	
`laceroo	om #303 (Regular Classroom)						
21233100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	906	SF	7	10+ years	
	Ceiling - Lay-in Ceiling - Lay-in	3rd Floor		SF	4		Missing and sagging tiles
			18	SF LF		0-1 year	Missing and sagging tiles
	Chalk Board	3rd Floor	25		4	2-5 years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	924	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Light switch not flush with switch plate, plaster damage around plate
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	986	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Damage around light switch.
Classroo	om #304 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	902	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	40	LF	4	2-5 years	Water damage
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7		
						10+ years	
	Floor - Wood	3rd Floor	910	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Storage/ Closet	3rd Floor	174	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,304	SF	7	10+ years	
lassroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	7	10+ years	
	Casework	3rd Floor	2	LF	5	0-1 year	Missing drawer
	Ceiling - Lay-in	3rd Floor	1,224	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Cracking tile
	Chalk Board	3rd Floor	12	LF	4	2-5 years	Č
	Doors - Transom Window	3rd Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,227	SF	7	10+ years	

Campus Name: Pullman Page : 20 of 27 Assessment Date: 05/16/2022



Category : Classroom		В	uilding	: Main			
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Broken and chipped/cracked
	Lighting - Lay-in	3rd Floor	17	EA	7	10+ years	••
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Broken switch
	Marker Board	3rd Floor	12	LF	7	6-10 years	2. one enne
	Walls - Plaster/Drywall	3rd Floor	1,279	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	0-1 year	Water damage
	Walls - Plaster/Drywall	3rd Floor	12	SF	5	0-1 year	Hole through plaster and paint
	Walls - Flaster/Drywall	314 1 1001	12	Oi	3	0-1 year	damage
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	0-1 year	Molding loose
	Work Sink	3rd Floor	1	EA	7	•	Wolding 1003e
	WORK SILIK	310 F1001	I	EA	,	10+ years	
Classroc	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	910	SF	7	10+ years	
	Chalk Board	3rd Floor	40	ĹF	4	2-5 years	
	Doors - Transom Window	3rd Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	910	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	174	SF	7	10+ years	
			1,289	SF	=	-	
	Walls - Plaster/Drywall	3rd Floor		SF SF	6	10+ years	\Matax damaga
	Walls - Plaster/Drywall	3rd Floor	15	SF	4	0-1 year	Water damage
Classroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Missing tiles
	Chalk Board	3rd Floor	20	LF	4	2-5 years	whoshing thos
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	918	SF	6	10+ years	Seal wearing
	Floor - Wood	3rd Floor	6	SF	4	0-1 year	Loose board
		3rd Floor		EA	7		Loose board
	Lighting - Lay-in Marker Board	3rd Floor	14 36	LF	7	10+ years	
				SF		6-10 years	
	Storage/ Closet	3rd Floor	120		5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	987	SF	7	10+ years	D
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	0-1 year	Damaged.
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	910	SF	7	10+ years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	2 = 56.6	5.455.	10		•	_ 0 , 000	

Campus Name: Pullman Page : 21 of 27 Assessment Date: 05/16/2022



Category : Classroom			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity			Replacement	Comments
	Doors - Transom Window	3rd Floor		9 S	F 7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor		1 E.	A 7	10+ years	
	Floor - Wood	3rd Floor	91	0 S	F 7	10+ years	
	Lighting - Lay-in	3rd Floor	1		A 7	10+ years	
	Marker Board	3rd Floor	1.	4 LI	F 7	6-10 years	
	Storage/ Closet	3rd Floor	17-			10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,29			10+ years	
	Walls - Plaster/Drywall	3rd Floor	1			0-1 year	Cracking
Classroo	nm #309 (Computer Lab)						
21433100	AC Units	3rd Floor		1 E.	A 7	6-10 years	
	Ceiling - Lay-in	3rd Floor	92			10+ years	
	Doors - Transom Window	3rd Floor		9 S		10+ years	
	Doors - Wood Doors inclu hw	3rd Floor		1 E		10+ years	
	Floor - Wood	3rd Floor	92			10+ years	
		3rd Floor	1.				
	Lighting - Lay-in					10+ years	
	Marker Board	3rd Floor	1.			6-10 years	Disease demons available and halos
	Storage/ Closet	3rd Floor	12			6-10 years	Plaster damage, cracking and holes through wall
	Walls - Plaster/Drywall	3rd Floor	94			10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	0 S	F 5	0-1 year	Cracking
	Wireless System	3rd Floor		1 E.	A 7	10+ years	-
Catego	ry : Interior			Buildi	ing : Main		
						Recommend	
Group	Item - Type	Location	Quantity	UC	M Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,55	9 S	F 7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	17	5 S	F 7	10+ years	
	Doors - Wood Doors include hw	1st Floor		6 E		10+ years	
	Drinking Fountains - Double Fountain	1st Floor		2 E		10+ years	
	Floor - Asphalt Floor	1st Floor	2,73			10+ years	
	Lighting - Lay-in	1st Floor	2			6-10 years	
	Stairs - Terrazzo	1st Floor				10+ years	
	Walls - Plaster/Drywall	1st Floor	2,77			10+ years	
	Ceiling - Lay-in	2nd Floor	2,52			10+ years	
	Ceiling - Lay-in	2nd Floor		8 S		0-1 year	Cracked tile
	Drinking Fountains - Double Fountain	2nd Floor		2 E		10+ years	Ordonod tilo
	Floor - Asphalt Floor	2nd Floor	2,33			6-10 years	
							Cracking floor
	Floor - Asphalt Floor	2nd Floor	20			0-1 year	Cracking floor
	Lighting - Lay-in	2nd Floor	2 50			6-10 years	
	Walls - Plaster/Drywall	2nd Floor	2,56			10+ years	
	Walls - Plaster/Drywall	2nd Floor		6 S		0-1 year	Cracking plaster
	Ceiling - Lay-in	3rd Floor	2,50	2 S	F 7	10+ years	
O N	Name: Pullman		Page : 22 of 27				Assessment Date: 05/16/20

Campus Name: Pullman Page : 22 of 27 Assessment Date: 05/16/2022



Category : Interior		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	24	SF	5	10+ years	Cracking tiles
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	3rd Floor	2,534	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	27	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,563	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Cracking and some water damage
	Ceiling - Plaster/Drywall	Basement	1,534	SF	6	10+ years	ů ů
	Doors - Transom Window	Basement	48	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	3	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	1,534	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	27	ĒA	7	10+ years	
	Stairs - Concrete Stairs	Basement	80	LF	7	10+ years	
	Walls - Masonry	Basement	866	SF	7	10+ years	
	Walls - Masonry	Basement	70	SF	5	0-1 year	Cracking/chipping.
	Walls - Metal Panel	Basement	602	SF	7	10+ years	G. acig, cppg.
	Trans Metal Farior	Bassment	002	O.	•	io. youro	
Safety							
	Security Cameras	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	4	0-1 year	Does not work
Stairs							
StallS	Ceiling - Plaster/Drywall	North West	468	SF	7	10+ years	
	Floor - Asphalt	North West	468	SF	6	10+ years	
	Handrails	North West	192	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	14	EA	7	10+ years	
	Lighting - Pendent/Surface	North West	4	EA	5	0-1 year	Damaged fixture
	Lighting - Wall Mounted	North West	3	EA	6	10+ years	o
	Stairs - Asphalt	North West	184	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	410	SF	7	10+ years	
	Walls - Plaster/Drywall	North West	150	SF	7	6-10 years	Repaired
	Ceiling - Plaster/Drywall	South West	268	SF	6	10+ years	•
	Ceiling - Plaster/Drywall	South West	200	SF	5	0-1 year	Water damage.
	Floor - Asphalt	South West	468	SF	7	6-10 years	
	Handrails	South West	192	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	12	ĒΑ	7	6-10 years	
	Stairs - Asphalt	South West	184	LF	7	10+ years	
	Walls - Plaster/Drywall	South West	560	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	120	SF	7	10+ years	
	Floor - Tile	West	120	SF	7	6-10 years	
	Handrails	West	32	LF	7	10+ years	
	Lighting - Pendent/Surface	West	4	EA	7	6-10 years	
	Stairs - Asphalt	West	26	LF	7	10+ years	
					•	jouro	

Campus Name: Pullman Page : 23 of 27 Assessment Date: 05/16/2022



Building : Main **Category: Interior**

Recommend UOM Group Item - Type Location Quantity Rank Replacement Comments Walls - Plaster/Drywall SF 10+ years West 154 7

Campus Name: Pullman Page : 24 of 27 Assessment Date: 05/16/2022





Category: Site **Building: Site**

Catego	ry : Site		В	ullaing	: Site			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Civil/Dra	inage							
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	10+ years	Engineer affirmed that all manholes	
	Olvin Brainago Ollo Marinolo	Entiro ono	10		Ü	ioi youio	are in proper working order	
							are in proper working craci	
Fencina								
rending	Fencing - Chain Link	Entire Site	211	LF	6	10+ years		
	Fencing - Chain Link	Entire Site	155	LF	4	0-1 year	Damage to fence posts and fence.	
	Telicing - Chain Link	Little Site	100	L!	7	0-1 year	Posts are either missing or out of	
							alignment, chain-link it's loose.	
	Fencing - Guard Rail	Entire Site	50	LF	6	6-10 years	North Parking Lot.	
		Entire Site Entire Site	673	LF			North Parking Lot.	
	Fencing - Iron and Concrete Post			LF	6	10+ years	Mississ separate are all posts	
	Fencing - Iron and Concrete Post	Entire Site	48	LF	4	0-1 year	Missing concrete around posts,	
							corrosion.	
Landsca	20							
Lanusca	Benches	Entire Site	2	EA	6	10+ years		
	Landscape - Hardscape- Asphalt	Entire Site	100	SF	4	0-1 year	Alligatored surface, large cracks and	
	Landodpo Hardodpo Aophan	Entiro ono	100	O.	•	o i youi	potholes. Vegetation growth.	
	Landscape - Hardscape- Asphalt	Entire Site	1,500	SF	4	0-1 year	Large depression creates deep	
	Landodpo Hardodpo Aophan	Entiro ono	1,000	O.	•	o i youi	ponding in the play area.	
	Parkway trees	Entire Site	23	EA	6	10+ years	portaing in the play area.	
	Parkway trees	Entire Site	3	EA	5	0-1 year	Trees growing onto the roof.	
	Planting Beds/ Area	Entire Site	300	SF	6	10+ years	rrees growing onto the root.	
	Play Area - Hardscape- Asphalt	Entire Site	21,450	SF	6	10+ years		
	Trash Receptacles	Entire Site	3	EA	6	10+ years		
	Trasif Neceptacles	Little Site	3	LA	O	10+ years		
Parking I	ot							
	Surface - Asphalt	Parking Lot- North	7.100	SF	6	10+ years		
	Surface - Asphalt	Parking Lot- South	7,120	SF	6	10+ years		
	Surface - Asphalt	Parking Lot- South	200	SF	4	0-1 year	Alligatored surface and large cracks.	
				-		. , ,		
Playgrou	nd							
	Equipment - Pre K 3-5	West	1	EA	6	10+ years		
	Equipment - School Age 5-12	West	1	EA	6	10+ years		
	Surface - Poured Surface	West	5,540	SF	7	10+ years		
	Surface - Poured Surface	West	100	SF	4	0-1 year	Tears and holes in the surface.	
0:-1 "	_							
Sidewalk		Entiro Cito	040			10		
	Sidewalks - Internal Walks	Entire Site	246	LF	6	10+ years	Dustres James and a minding of	
	Sidewalks - Internal Walks	Entire Site	256	LF	4	0-1 year	Broken, large areas missing, large	

Campus Name: Pullman Page : 25 of 27 Assessment Date: 05/16/2022



Category : Site			Building : Site				
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							cracks, spalled
	Sidewalks - Perimeter Sidewalks	Entire Site	5,900	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	4	0-1 year	Broken concrete, missing areas of surface, large cracks
_Signage							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	
	Sign					·	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Pullman Page: 26 of 27 Assessment Date: 05/16/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Olassiooni Gammary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	mionaca ccago	110111001	Trainio.	(0. /	700	71.00	J Clop	200.0	
Computer Lab	Regular Classroom	3rd Floor	309	309	925	280	84	N	N
Faculty Lounge	Regular Classroom	1st Floor	107	107	1,232	200	60	N	N
Kindergarten	Kindergarten	1st Floor	101	101	924	280	84	N	N
Library	Regular Classroom	1st Floor	102	102	910	252	140	N	N
Lunch Room	Regular Classroom	Basement	002		723	92	46		
Office	Regular Classroom	2nd Floor	206	206	910	108	60	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	924	200	60	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	910	144	80	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	910	252	140	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	910	252	140	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	924	280	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	924	280	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	910	252	140	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	924	200	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	910	144	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,232	280	184	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	924	200	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	910	252	140	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	924	280	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	924	280	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	910	252	140	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	924	200	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	1,232	280	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	910	144	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	924	200	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	910	252	140	N	N
Store Room	Faculty Lounge	Basement	001		761	118	59		
Store Room	Regular Classroom	3rd Floor	304	304	910	144	80	N	N