



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1893	4	84,500
Addition 1	1915	1	6,930
Addition 2	1996	2	23,876
Campus Total			115,306

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	#1 W - Main Entrance	1	EA	5	2-5 years	
	Entrance Control - Audio and Video	#1 W - Main Entrance	1	EA	7	6-10 years	Uncovered/unenclosed
	Exterior Doors - Exterior Wood Door	#1 W - Main Entrance	2	EA	5	6-10 years	Rot/deterioration at center door
							frame/Mullion. Weather Guard/Door sweep missing.
	Exterior Doors - Transom Lite	#1 W - Main Entrance	2	EA	6	10+ years	1 3
	Exterior Doors - Exterior Steel Door	#10 E	1	EA	6	6-10 years	Deteriorating concrete stair
	Exterior Doors - Exterior Steel Door	#11 E	1	EA	7	10+ years	· ·
	Exterior Doors - Exterior Steel Door	#21 S	1	EA	5	10+ years	Steel Door/Wood Frame - Frame weathered Deteriorating, Door: Peeling paint.
	Exterior Doors - Transom Lite	#21 S	1	EA	4	1-2 years	Wood Composition deterioration of Frame/Sash
	Exterior Doors - Exterior Steel Door	#6 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 E	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 E	1	EA	6	6-10 years	
	Entrance Control - Audio	#8 E	1	EA	5	2-5 years	Unprotected- Weathered/corrosion
	Exterior Doors - Exterior Steel Door	#8 E	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#9 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 E	10	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Fire Escape - North	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Fire Escape - North	4	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	Fire Escape - South	3	EA	6	10+ years	Peeling paint
	Exterior Doors - Transom Lite	Fire Escape - South	3	EA	6	10+ years	Rust/Corrosion Prevalent
Fire Esc	ape						
	Fire Escape	North/South	122	LF	6	6-10 years	South - Corrosion/Scrape/Paint
	Fire Escape	North/South	120	LF	6	6-10 years	North - Corrosion/Scrape/Paint
Foundat	ion						
	Foundation - Masonry	Entire Building, Boiler Room	1,149	LF	7	10+ years	
	Foundation - Masonry	Entire Building, Boiler Room	154	LF	5	10+ years	Open mortar joints
	Superstructure - Steel with Clay Tile Arch	Entire Building, Boiler Room	84,500	SF	7	10+ years	,
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	25	EA	7	6-10 years	
Roof Sys	stem						
,	Access Ladder - Metal	High Roof	1	EA	7	10+ years	
	Coping - Metal	High Roof	325	LF	7	10+ years	
	Roof - Metal	High Roof	280	SF	6	10+ years	
	Roof - Modified Bitumen	High Roof	3,846	SF	6	10+ years	Some buckling - detaching from substrate
	Roof Hatch - Metal	High Roof	1	EA	7	10+ years	Substrate
	Roof Structure - Heavy Timber	High Roof	4,126	SF	7	10+ years	
	Coping - Stone	Lower Roofs	405	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Lower Roofs	64	LF	7	10+ years	
	Parapet - Parapet > 30"	Lower Roofs	405	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Lower Roofs	3,554	SF	6	10+ years	
	Roof - EPDM/ Synthetic Rubber	Lower Roofs	278	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Lower Roofs	3,832	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	60	LF	7	10+ years	
	Liner Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	26	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Main Roof	460	LF	7	10+ years	
	Roof - Asphalt Shingle	Main Roof	21,980	SF	6	10+ years	
	Roof Structure - Heavy Timber	Main Roof	21,980	SF	7	10+ years	
	Suddid Hoary Fillion		21,000	٥.	•	io. youro	
<i>Nalls</i>	Exterior Walla Prink	Entire Puilding	40.040	- CF	7	101.240000	
	Exterior Walls - Brick	Entire Building	18,012	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	8,000	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	7,660	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	5,000	SF	7	10+ years	



Categor	y : Exterior		R	uilding	· Main		31 S Kimbark AVENUE, Chicago, IL 60637
Jacogoi	y i Emolioi			ananig	. man	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о а р						Tio piaco in one	
Windows							
	Guard - Guards wire guard	Entire Building	2,002	SF	6	6-10 years	
	Lintels - Stone	Entire Building	949	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,121	SF	6	6-10 years	
Catagor	n Electrical		ь	المائدة	. Main		
Categor	ry : Electrical		Ь	uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	cy System		•				
<u>go</u>	Emergency Battery Packs - Corridors and	Entire Building	49	EA	6	6-10 years	
	Stairs	g		_, ,	· ·	0 .0 ,00.0	
	Emergency Battery Packs - Gym	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	5	6-10 years	
	Exit Signs - Gym	Entire Building	8	ΕA	5	6-10 years	
	Security System - CCTV	Entire Building	84,500	SF	6	6-10 years	White cameras, recently installed
	Security System - Intrusion Detection	Entire Building	84,500	SF	5	6-10 years	Older
	Emergency A/C Power - Corridors and	Entire Building, Basement	17,480	SF	6	6-10 years	Older
	Stairs	Entire building, basement	17,400	SF	O	6-10 years	
	Emergency A/C Power - Gym	Entire Building, Basement	2,611	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building, Basement	1,202	SF	6	6-10 years	
	Automatic Transfer Switch	Mechanical Room	1	EA	6	10+ years	Functional
	Automatic Transfer Switch	Mechanical Room	1	EΑ	4	2-5 years	Older, corroded
Main Ser						0.10	0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves main and addition 2 building
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	Serves main and addition 1 building
	120/208/3PH					-	_
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	Serves main and addition 1 building
	PA System	Entire Building	84,500	SF	5	6-10 years	Connected to addition 1 and addition
	•	S	,			,	2
Power Dis	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	7	10+ years	Functional, reliable
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	i dilatai, foliabio
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building Entire Building	3	EA	4	2-5 years	Panel trips occasionally, not live,
	Lighting and Fower Fallets - 100 A	Little building	3	EA	4	2-0 years	repaired
		Forting Desiletings	0	Ε.Δ	7	10	1 2 2
	Lighting and Power Panels - Above 100 A	Entire Building	6	EΑ	7	10+ years	

Campus Name: Ray Page : 3 of 45 Assessment Date: 02/16/2022



Catego	ry : Electrical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Older and corroded, not live, repaire
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	2-5 years	Deteriorated, occasionally trips. Not live, repaired
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	-, -, -,
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	Serves main addition, 1 and addition 2 buildings
	Fire Alarm Strobe Lights	Mechanical Room	84,500	SF	6	10+ years	3.
	Fire Alarm_System	Mechanical Room	84,500	SF	6	6-10 years	Connected to addition 1 and addition 2 buildings
	Fire Pump Controller	Mechanical Room	1	EA	5	6-10 years	In pump room, serves main building No sprinklers in auditorium addition building
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	6-10 years	Serves main building
	Jockey Pump	Mechanical Room	1	EA	6	6-10 years	·
Sprinkler	System						
-	Combination Wet and Dry Sprinkler System	Entire Building	84,500	SF	6	6-10 years	Dry in the attic
	Sprinkler Heads	Entire Building	200	SF	7	10+ years	Inspected by fire marshall, functiona A few deteriorated sprinkler heads were recently replaced.
	Sprinkler Heads	Entire Building	84,290	SF	7	10+ years	
	Sprinkler Piping	Entire Building	84,500	SF	6	6-10 years	Serves main building
atego	ry : Mechanical		В	uilding	: Main		
`*a	Itam Tuna	Loostion	Ougatitus	ПОМ	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ur Cond	itioning	Deed				0.40	On alamad mark in the 21
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	On sloped roof, not accessible, serves MDF room evaporating unit.
	Name: Ray		Page : 4 of 45				Assessment Date: 02/16/20

Campus Name: Ray Page : 4 of 45 Assessment Date: 02/16/2022



Group	Item - Type Heat Pump- Ceiling Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons	Location Site North	Quantity 3	UOM EA	Rank	Recommend Replacement 6-10 years	Comments
·	Heat Pump- Ceiling Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons					Replacement	
	Heat Pump- Ceiling Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons						
						0-10 years	Ground mounted. Serve 3 ceiling mounted carrier units, split HVAC systems. Previously not assessed, serve one ceiling mounted evaporating unit per floor, 3 total.
Air Handlin	na Sveteme						
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	3	EA	5	6-10 years	1 per floor, served by 3 outdoor Carrier split system units that are located in a courtyard. Previously not assessed
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2, serves classrooms, north side in main building
	Air Intake	Mechanical Room	1	EA	5	6-10 years	ŭ
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	10+ years	Common return
	Zone Dampers	Mechanical Room	22	EA	5	6-10 years	Cleaned, lubricated, functional
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, serves south end of main building
	Air Intake	Mechanical Room	1	EA	6	6-10 years	ŭ
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EΑ	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	Common return
	Zone Dampers	Mechanical Room	18	EA	5	6-10 years	Adjusted, lubricated, cleaned
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3, serves addition 1 auditorium, from main building
	Air Intake	Mechanical Room	1	EA	6	6-10 years	•
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EΑ	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	10+ years	Painted, connected to addition 1 auditorium
Boiler Syst	tems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	Repaired
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	1 tank, 4 pumps
;	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	6-10 years	Serves main and addition 1 auditorium buildings
	Piping - Condensate Pipe- Steel	Boiler Room	1,300	LF	5	6-10 years	Minor leaks are occasionally repaired. Connect to addition 1 building

Campus Name: Ray Page : 5 of 45 Assessment Date: 02/16/2022



	schools				84.1	56	631 S Kimbark AVENUE, Chicago, IL 60637
Catego	ry : Mechanical		В	uilding	: Main		
0	N T	1	0		D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments There are nine clares Connect to
	Piping - Steam Pipe- Steel	Boiler Room	1,300	LF	5	6-10 years	There are pipe clamps. Connect to
	Ctoom Trong	Dailer Daam	50	Ε.	_	0.40	addition 1 auditorium building
	Steam Traps	Boiler Room	50	EA	5	6-10 years	Some steam traps are leaking
	5 .						
Heating							
	Fin Tube - Electric	1st Floor	16	LF	5	6-10 years	In care room, previously not assessed
	Wall Heater - Electric	Entire Building	13	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	4	2-5 years	Corroded, not reliable, older
	Radiators - Steam	Entire Building	7	EA	5	6-10 years	,
	Unit Heater - Electric	Entire Building, Boiler Room	4	EA	6	6-10 years	
	Unit Heater - Gas	Entire Building, Boiler Room	1	EA	5	6-10 years	
	Unit Heater - Steam	Entire Building, Boiler Room	1	EA	5	6-10 years	In music room, previously not
	Onit Heater - Steam	Entire building, boller 100m	'	LA	3	0-10 years	assessed
Tempera	ature Control						
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Serve unit heaters, fans
	Pneumatic System	Entire Building	84,500	SF	4	2-5 years	Operating in mostly manual mode, a
							compressor repaired
	Thermostats - Pneumatic	Entire Building	10	EA	5	6-10 years	Calibration needed
	Thermostats - Pneumatic	Entire Building	30	EA	4	2-5 years	Leak, not repaired
Unit Ven							
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	North Facade	2	EA	5	6-10 years	Per engineer, only 2
Ventilatio	an.						
Ventuali	Exhaust Fans- Indoor - 500 - 1500 CFM	Attic	2	EA	5	6-10 years	Difficult and not safe to access, dark
	Exhaust Fans- Indoor - 500 - 1500 CFM	Attic	2	EA	5	0-10 years	attic
	Exhaust Fans- Roof Mounted - 500 - 1500	Attic	1	EA	5	6-10 years	On sloped roof, difficult to access,
	CFM	Attic	'	LA	3	0-10 years	previously not assessed
Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat			•				
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves main building, functional, burners cleaned
D: :							
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	84,500	SF	6	6-10 years	

Campus Name: Ray Page : 6 of 45 Assessment Date: 02/16/2022



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Risers	Entire Building	84,500	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	84,500	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	84,500	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	84,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	84,500	SF	6	6-10 years	Minor leaks occasionally repaired, 1893 installation
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,600	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	84,500	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	84,500	SF	6	10+ years	There are a few pipe clamps. Sections replaced by copper pipes
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	84,500	SF	6	6-10 years	1893 installation. Sections of pipe replaced by copper
	Sanitary Piping	Entire Building	84,500	SF	6	6-10 years	Recently water jet cleaned
	Storm Piping	Entire Building	84,500	SF	6	6-10 years	
	Vent Piping	Entire Building	84,500	SF	6	6-10 years	
_Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	Serves main building
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	6-10 years	Under north elevator

Category : Room **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	trative Suites/Offices						
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	884	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Main Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office	884	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Main Office	8	EΑ	7	6-10 years	
	Power Distribution	1st Floor - Main Office	12	EΑ	7	10+ years	
	Storage/ Closet	1st Floor - Main Office	5	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	2,134	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Teacher's Room 105	290	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Teacher's Room 105	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Teacher's Room 105	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Teacher's Room 105	286	SF	7	10+ years	
	Floor - Tile	1st Floor - Teacher's Room 105	4	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor - Teacher's Room 105	5	EA	7	6-10 years	•
	Power Distribution	1st Floor - Teacher's Room 105	16	EA	7	10+ years	

Campus Name: Ray Page : 7 of 45 Assessment Date: 02/16/2022



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor - Teacher's Room 105	950	SF	7	10+ years	
	Work SInk	1st Floor - Teacher's Room 105	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Teachers Room 111	290	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Teachers Room 111	1	EΑ	7	10+ years	
	Doors - Transom Window	1st Floor - Teachers Room 111	10	SF	7	10+ years	
	Floor - Tile	1st Floor - Teachers Room 111	285	SF	7	10+ years	
	Floor - Tile	1st Floor - Teachers Room 111	5	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	1st Floor - Teachers Room 111	5	EA	7	6-10 years	
	Power Distribution	1st Floor - Teachers Room 111	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Teachers Room 111	940	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Teachers Room 111	10	SF	5	1-2 years	Damaged plaster
	Work Sink	1st Floor - Teachers Room 111	1	ĒΑ	7	10+ years	3-1
	Ceiling - Plaster/Drywall	208 Office	344	SF	7	10+ years	
	Doors - Transom Window	208 Office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208 Office	1	EA	7	10+ years	
	Floor - Tile	208 Office	338	SF	7	10+ years	
	Floor - Tile	208 Office	6	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	208 Office	6	EA	7	6-10 years	Damagea tiles
	Power Distribution	208 Office	12	EA	7	10+ years	
	Walls - Plaster/Drywall	208 Office	780	SF	7	10+ years	
	AC Unit	2nd Floor - Room 213	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Room 213	312	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - Room 213	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Room 213	2	EA	7	10+ years	
	Floor - Wood	2nd Floor - Room 213	312	SF	7	10+ years	
		2nd Floor - Room 213	7	EA			
	Lighting - Pendent/Surface Power Distribution	2nd Floor - Room 213	12	EA	7 7	6-10 years 10+ years	
	Walls - Plaster/Drywall	2nd Floor - Room 213	1,139	SF	7	•	
	Ceiling - Plaster/Drywall	2nd Floor - Room 213 2nd Floor - Teacher's Room 205	285	SF SF	7	10+ years	
				SF SF		10+ years	Cracked
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor - Teacher's Room 205	5 8	SF SF	5	0-1 year	Cracked
	Doors - Wood Doors inclu hw	2nd Floor - Teacher's Room 205 2nd Floor - Teacher's Room 205	0	EA	7 7	10+ years	
				SF		10+ years	
	Floor - Tile	2nd Floor - Teacher's Room 205	285	SF SF	7	10+ years	Damagad tiles
	Floor - Tile	2nd Floor - Teacher's Room 205	5		4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor - Teacher's Room 205	5	EΑ	7	6-10 years	
	Power Distribution	2nd Floor - Teacher's Room 205	14	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teacher's Room 205	940	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teacher's Room 205	10	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Room 211	270	SF	7	10+ years	Dealingaries
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Room 211	20	SF	6	1-2 years	Peeling paint
	Doors - Steel Doors incl hw	2nd Floor - Teachers Room 211	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor - Teachers Room 211	10	SF	7	10+ years	
	Floor - Tile	2nd Floor - Teachers Room 211	254	SF	7	10+ years	
	Floor - Tile	2nd Floor - Teachers Room 211	36	SF	4	0-1 year	Cracked, chipped

Campus Name: Ray Page: 8 of 45 Assessment Date: 02/16/2022



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor - Teachers Room 211	5	EA	7	6-10 years	
	Power Distribution	2nd Floor - Teachers Room 211	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teachers Room 211	950	SF	7	10+ years	
	Work SInk	2nd Floor - Teachers Room 211	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Room 305	290	SF	7	10+ years	
	Doors - Transom Window	3rd Floor - Teacher's Room 305	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Teacher's Room 305	1	EA	7	10+ years	
	Floor - Tile	3rd Floor - Teacher's Room 305	286	SF	7	10+ years	
	Floor - Tile	3rd Floor - Teacher's Room 305	4	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor - Teacher's Room 305	5	EA	7	6-10 years	-
	Power Distribution	3rd Floor - Teacher's Room 305	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Room 305	950	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Room 311	290	SF	7	10+ years	
	Doors - Transom Window	3rd Floor - Teacher's Room 311	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Teacher's Room 311	1	EA	7	10+ years	
	Floor - Tile	3rd Floor - Teacher's Room 311	272	SF	7	10+ years	
	Floor - Tile	3rd Floor - Teacher's Room 311	18	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor - Teacher's Room 311	5	EA	7	6-10 years	
	Power Distribution	3rd Floor - Teacher's Room 311	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Room 311	950	SF	7	10+ years	
	Work Sink	3rd Floor - Teacher's Room 311	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - Work Room between 307 and 309	306	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Work Room between 307 and 309	2	EA	7	10+ years	
	Floor - Wood	3rd Floor - Work Room between 307 and 309	306	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor - Work Room between 307 and 309	8	EA	7	6-10 years	
	Power Distribution	3rd Floor - Work Room between 307 and 309	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Work Room between 307 and 309	924	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Caring room 002A	250	SF	7	10+ years	
	Doors - Side-lite	Caring room 002A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Caring room 002A	1	EA	7	10+ years	
	Floor - Tile	Caring room 002A	250	SF	7	10+ years	
	Lighting - Pendent/Surface	Caring room 002A	6	EA	7	6-10 years	
	Power Distribution	Caring room 002A	6	EA	7	10+ years	
	Walls - Concrete Block	Caring room 002A	240	SF	7	10+ years	
	Walls - Plaster/Drywall	Caring room 002A	200	SF	7	10+ years	
	AC Unit	Engineers Office, basement SW of boiler room	1	EA	5	1-2 years	Missing cover
	Ceiling - Plaster/Drywall	Engineers Office, basement SW of	168	SF	7	10+ years	

Campus Name: Ray Page : 9 of 45 Assessment Date: 02/16/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		boiler room					
	Doors - Wood Doors inclu hw	Engineers Office, basement SW of	1	EA	7	10+ years	
	F1 - T1	boiler room	404	0=	_	40	
	Floor - Tile	Engineers Office, basement SW of	164	SF	7	10+ years	
	Flore Tile	boiler room	4	0.5	_	4.0	Desire tiles
	Floor - Tile	Engineers Office, basement SW of	4	SF	5	1-2 years	Broken tiles
	Lighting Bondont/Surface	boiler room Engineers Office, basement SW of	2	EA	7	10 . vooro	
	Lighting - Pendent/Surface	boiler room	2	EA	1	10+ years	
	Power Distribution	Engineers Office, basement SW of	4	EA	7	10+ years	
	Fower Distribution	boiler room	4	LA	,	10+ years	
	Walls - Plaster/Drywall	Engineers Office, basement SW of	404	SF	6	10+ years	
	vvalis - i lastei/Drywali	boiler room	404	Oi	O	10+ years	
	Ceiling - Plaster/Drywall	Floor 1.5 - Counselor Office 107	278	SF	7	10+ years	
	Doors - Side-lite	Floor 1.5 - Counselor Office 107	30	SF	7	10+ years	
	Doors - Transom Window	Floor 1.5 - Counselor Office 107	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Floor 1.5 - Counselor Office 107	1	ĒΑ	7	10+ years	
	Floor - Tile	Floor 1.5 - Counselor Office 107	278	SF	7	10+ years	
	Lighting - Pendent/Surface	Floor 1.5 - Counselor Office 107	5	EA	7	6-10 years	
	Power Distribution	Floor 1.5 - Counselor Office 107	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Floor 1.5 - Counselor Office 107	653	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Main Office - Conference Room	216	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Conference Room	2	EA	7	10+ years	
	Floor - Tile	Main Office - Conference Room	216	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Conference Room	2	EA	7	6-10 years	
	Power Distribution	Main Office - Conference Room	4	EA	7	10+ years	
	Storage/ Closet	Main Office - Conference Room	6	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office - Conference Room	660	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Principal's Office	164	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office	164	SF	7	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	4	EA	7	6-10 years	
	Power Distribution	Principal's Office	8	EA	7	10+ years	
	Storage/ Closet	Principal's Office	23	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	635	SF EA	7	10+ years	
	AC Unit	Room 113 - Assistant Principal	1	SF	7	6-10 years	
	Ceiling - Plaster/Drywall Doors - Transom Window	Room 113 - Assistant Principal Room 113 - Assistant Principal	312 8	SF SF	7 7	10+ years	
	Doors - Wood Doors inclu hw	Room 113 - Assistant Principal	° 1	Sr EA	7	10+ years 10+ years	
	Floor - Wood Doors Inclu IIW	Room 113 - Assistant Principal	312	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 113 - Assistant Principal	6	EA	7	6-10 years	
	Power Distribution	Room 113 - Assistant Principal	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 113 - Assistant Principal	1,139	SF	7	10+ years	

Campus Name: Ray Page : 10 of 45 Assessment Date: 02/16/2022



July 30.	ry : Room		В	uilding	: Main		
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Gymnasi	a						
	Ceiling - Plaster/Drywall	Basement	2,596	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	15	SF	7	10+ years	
	Doors - Transom Window	Basement	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	7	10+ years	
	Floor - Wood	Basement	2,611	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	22	EA	7	6-10 years	
	Sound System	Basement	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	5,582	SF	7	10+ years	
_ocker/S	hower Room						
	Ceiling - Plaster/Drywall	Old Gym locker/shower in basement used for storage	610	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Old Gym locker/shower in basement used for storage	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Old Gym locker/shower in basement used for storage	610	SF	7	10+ years	
	Floor Drain	Old Gym locker/shower in basement used for storage	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Old Gym locker/shower in basement used for storage	2	EA	7	6-10 years	
	Lighting - Wall Mounted	Old Gym locker/shower in basement used for storage	1	EA	7	6-10 years	
	Partitions	Old Gym locker/shower in basement used for storage	6	EA	7	10+ years	
	Showers	Old Gym locker/shower in basement used for storage	1	EA	7	10+ years	
	Walls - Concrete Block	Old Gym locker/shower in basement used for storage	175	SF	7	10+ years	
	Walls - Plaster/Drywall	Old Gym locker/shower in basement used for storage	827	SF	7	10+ years	
	Walls - Plaster/Drywall	Old Gym locker/shower in basement used for storage	30	SF	4	1-2 years	Damaged missing plaster
unch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement 006 - Staff Lunchroom	1,019	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement 006 - Staff Lunchroom	183	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement 006 - Staff Lunchroom	3	EA	7	10+ years	
	Floor - Tile	Basement 006 - Staff Lunchroom	1,202	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement 006 - Staff Lunchroom	18	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	Basement 006 - Staff Lunchroom	1,910	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement 006 - Staff Lunchroom	40	SF	7	10+ years	



Category : Room			Building : Main			2		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Joup	icii i ype	Location	Quantity	OON	Nank	Replacement	Comments	
ADF_IDE	=							
	Doors - Wood Doors inclu hw	2nd floor 203	2	EA	7	10+ years		
	Finishes	2nd floor 203	290	SF	7	10+ years		
	Finishes	2nd floor 203	50	SF	4	0-1 year	Damaged tile and sub floor	
	Other Cooling Unit	2nd floor 203	2	EA	7	6-10 years		
/lechanic	cal/ Service Rooms							
	Janitor's Closet	1st Floor	10	SF	7	10+ years		
	Air Intake Plenums	Basement	212	SF	7	10+ years		
	Boiler Room	Basement	1,431	SF	7	10+ years		
	Boiler Room	Basement	100	SF	5	1-2 years	Spalling walls	
	Coal Room	Basement	332	SF	7	10+ years	. 3	
	Coal Room	Basement	60	SF	5	1-2 years	Spalling walls	
	Janitor's Closet	Basement	53	SF	7	10+ years	-13	
	Mechanical/ Service Rooms	Basement	90	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	2,160	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	60	SF	7	10+ years		
						, , , , ,		
Restroom		00T D				0.10		
	Accessories	007 Basement boys, inside boys play room	306	SF	7	6-10 years		
	Ceiling - Exposed	007 Basement boys, inside boys play room	306	SF	7	10+ years		
	Floor - Tile	007 Basement boys, inside boys play room	306	SF	6	10+ years		
	Floor Drain	007 Basement boys, inside boys play room	1	EA	7	10+ years		
	Hand Dryer	007 Basement boys, inside boys play room	2	EA	7	10+ years		
	Lavatory	007 Basement boys, inside boys	2	EA	7	10+ years		
	Lighting - Pendent/Surface	play room 007 Basement boys, inside boys	3	EA	7	6-10 years		
	Partitions	play room 007 Basement boys, inside boys	2	EA	7	10+ years		
	Urinals	play room 007 Basement boys, inside boys	3	EA	7	10+ years		
	Walls - Concrete Block	play room 007 Basement boys, inside boys	90	SF	7	10+ years		
	Walls - Plaster/Drywall	play room 007 Basement boys, inside boys	736	SF	7	10+ years		
	Walls - Structural Glazed Tile	play room 007 Basement boys, inside boys	225	SF	7	10+ years		



Catego	Category : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		play room	_		_		
	Water Closet	007 Basement boys, inside boys	2	EA	7	10+ years	
		play room	450	05	-	0.40	
	Accessories	1st Floor	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	127	SF	7	10+ years	5
	Ceiling - Plaster/Drywall	1st Floor	25	SF	5	0-1 year	Damaged plaster
	Floor - Tile	1st Floor	15	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	137	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	600	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	151	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	151	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	150	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1	SF	5	1-2 years	Missing tiles
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	800	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor - Principal's Office	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Principal's Office	42	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal's Office	30	SF	7	10+ years	
	Lavatory	1st Floor - Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal's Office	1	EA	7	10+ years	
	Partitions	1st Floor - Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office	458	SF	7	10+ years	
	Water Closet	1st Floor - Principal's Office	1	EA	7	10+ years	
	Accessories	1st Floor - Room 101	66	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Room 101	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Room 101	1	EA	6	10+ years	Missing door knob
	Floor - Tile Ceramic/ Porcelain	1st Floor - Room 101	56	SF	7	10+ years	
						-	



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Room 101	10	SF	5	1-2 years	Missing tiles		
	Lavatory	1st Floor - Room 101	1	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor - Room 101	1	EA	7	10+ years			
	Partitions	1st Floor - Room 101	2	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - Room 101	15	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - Room 101	462	SF	7	10+ years			
	Water Closet	1st Floor - Room 101	2	EA	7	10+ years			
	Accessories	1st Floor - Teacher's Room 111	21	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor - Teacher's Room 111	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Teacher's Room 111	1	EΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - Teacher's Room 111	19	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - Teacher's Room 111	2	SF	5	1-2 years	Broken tiles		
	Lighting - Wall Mounted	1st Floor - Teacher's Room 111	1	ĒΑ	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor - Teacher's Room 111	180	SF	6	10+ years			
	Water Closet	1st Floor - Teacher's Room 111	1	EA	7	10+ years			
	Accessories	2nd Floor	184	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	184	SF	6	10+ years			
	Floor - Tile	2nd Floor	28	SF	7	•			
	Floor - Tile	2nd Floor	4	SF		10+ years	Domogod tiles		
				SF SF	4	0-1 year	Damaged tiles		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	148		7	10+ years	Dama and Olas		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	4	SF	4	0-1 year	Damaged tiles		
	Floor Drain	2nd Floor	1	EΑ	7	10+ years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	600	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	200	SF	7	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	2nd Floor	151	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	141	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Peeling paint		
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Damaged tiles		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	149	SF	7	10+ years	-		
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years			
	Hand Dryer	2nd Floor	2	ΕA	7	6-10 years			
	Lavatory	2nd Floor	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years			
	Partitions	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	100	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	800	SF	6	10+ years			
	vvalis i lastei/Drywali	2110 T 1001	300	Oi.	U	TOT years			

Campus Name: Ray Page : 14 of 45 Assessment Date: 02/16/2022



Catego	Category : Room		В	uilding	: Main			
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	2nd Floor	4	EA	7	10+ years		
	Accessories	2nd Floor - Teacher's Room 211	21	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Teacher's Room 211	11	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor - Teacher's Room 211	10	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	2nd Floor - Teacher's Room 211	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Teacher's Room 211	21	SF	7	10+ years		
	Lighting - Wall Mounted	2nd Floor - Teacher's Room 211	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor - Teacher's Room 211	175	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor - Teacher's Room 211	5	SF	5	0-1 year	Cracked	
	Water Closet	2nd Floor - Teacher's Room 211	1	EA	7	10+ years		
	Accessories	3rd Floor	184	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	184	SF	6	10+ years		
	Floor - Tile	3rd Floor	29	SF	7	10+ years		
	Floor - Tile	3rd Floor	3	SF	4	0-1 year	Damaged tile	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	152	SF	7	10+ years	zamagea me	
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	1	EA	7	6-10 years		
	Lavatory	3rd Floor	1	EA	7	10+ years		
	Lavatory	3rd Floor	1	EA	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	0-1 year	Relamp fixture	
	Partitions	3rd Floor	2	EA	5	10+ years	Relamp lixture	
	Urinals	3rd Floor	4	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	100	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	600	SF	7	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	200	SF	7	10+ years		
	Water Closet	3rd Floor	1	EA	7	10+ years		
	Water Closet	3rd Floor	1	EA	6	0-1 year	Damaged flush valve	
	Accessories	3rd Floor	151	SF	7	6-10 years	Damaged hush valve	
	Ceiling - Plaster/Drywall	3rd Floor	203	SF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	203	SF	6	10+ years		
	Floor - Tile	3rd Floor	68	SF	7	10+ years		
	Floor - Tile	3rd Floor	4	SF	4	0-1 year	Damaged tiles	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	149	SF	7	10+ years	Damaged tiles	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	2	SF	4	0-1 year	Damaged tiles	
	Floor Drain	3rd Floor	1	EA	7	10+ years	Damaged tiles	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years		
	Lavatory	3rd Floor	2	EA	7			
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years 10+ years		
	Partitions	3rd Floor	4	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	400	SF	7	-		
		3rd Floor 3rd Floor	390	SF SF		10+ years		
	Walls - Plaster/Drywall Walls - Plaster/Drywall	3rd Floor 3rd Floor	10	SF SF	6 5	10+ years	Damaged gypsum	
	Water Closet	3rd Floor	4	Sr EA	5 7	0-1 year	Damaged gypsum	
	vvaldi Ciusel	SIU FIOOI	4	EA	,	10+ years		

Campus Name: Ray Page : 15 of 45 Assessment Date: 02/16/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Floor - Teacher's Room 311	21	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Teacher's Room 311	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Teacher's Room 311	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor - Teacher's Room 311	21	SF	7	10+ years	
	Lighting - Wall Mounted	3rd Floor - Teacher's Room 311	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Room 311	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Room 311	15	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor - Teacher's Room 311	5	SF	5	0-1 year	Damaged gyp
	Water Closet	3rd Floor - Teacher's Room 311	1	EA	7	10+ years	
	Accessories	Basement	500	SF	7	6-10 years	
	Ceiling - Exposed	Basement	500	SF	7	10+ years	
	Floor - Tile	Basement	500	SF	7	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	4	EA	7	6-10 years	
	Lavatory	Basement	4	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	7	EA	7	10+ years	
	Partitions	Basement	11	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	450	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	504	SF	7	10+ years	
	Water Closet	Basement	11	EA	7	10+ years	
	Accessories	Basement - Engineer's Office	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Office	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	EA	7	10+ years	
	Floor - Concrete	Basement - Engineer's Office	30	SF	7	10+ years	
	Lavatory	Basement - Engineer's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement - Engineer's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	198	SF	7	10+ years	
	Water Closet	Basement - Engineer's Office	1	EA	7	10+ years	
	Accessories	Toilet in boys area in room 007	95	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet in boys area in room 007	95	SF	7	10+ years	
	Floor - Tile	Toilet in boys area in room 007	95	SF	7	10+ years	
	Lavatory	Toilet in boys area in room 007	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet in boys area in room 007	3	EA	7	6-10 years	
	Partitions	Toilet in boys area in room 007	1	EA	7	10+ years	
	Student Lockers - One Tier	Toilet in boys area in room 007	4	EA	7	10+ years	
	Walls - Concrete Block	Toilet in boys area in room 007	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Toilet in boys area in room 007	321	SF	7	10+ years	
	Walls - Plaster/Drywall	Toilet in boys area in room 007	311	SF	5	1-2 years	Damaged plaster
	Walls - Structural Glazed Tile	Toilet in boys area in room 007	54	SF	7	10+ years	
	Water Closet	Toilet in boys area in room 007	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		or o Kimbark Avenoe, Officago, ie 00007
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #002 (Store Room)					-	
	Ceiling - Plaster/Drywall	Basement	956	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	956	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	16	ĒΑ	6	6-10 years	
	Storage/ Closet	Basement	587	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,325	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
_Classroo	om #004 (Library)						
	Casework	Basement	8	LF	7	10+ years	
	Ceiling - Exposed	Basement	1,574	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	200	SF	7	10+ years	
	Doors - Transom Window	Basement	2	SF	7	10+ years	
	Floor - Tile	Basement	1,769	SF	6	10+ years	
	Floor - Tile	Basement	5	SF	5	1-2 years	Broken tiles
	Lighting - Pendent/Surface	Basement	25	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,482	SF	6	10+ years	
_Classroo	om #007 (Play Room)						
	Casework	Basement	16	LF	7	10+ years	
	Ceiling - Exposed	Basement	809	SF	7	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	Basement	809	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	18	EA	7	6-10 years	
	Storage/ Closet	Basement	178	SF	7	10+ years	
	Walls - Masonry	Basement	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	856	SF	7	10+ years	
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	855	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Floor - Tile	1st Floor	855	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,326	SF	7	10+ years	
_Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
						-	



Group III	tem - Type Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 1,054 1 8 1,054	UOM SF EA	Rank 7	Recommend Replacement 10+ years	Comments
	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Pendent/Surface Marker Board	1st Floor 1st Floor 1st Floor 1st Floor	1,054 1 8	SF			Comments
[Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Pendent/Surface Marker Board	1st Floor 1st Floor 1st Floor	1 8		7	10+ vears	
E F L N S	Doors - Transom Window Floor - Tile Lighting - Pendent/Surface Marker Board	1st Floor 1st Floor	8	EA		ioi years	
F L N S	Floor - Tile Lighting - Pendent/Surface Marker Board	1st Floor			7	10+ years	
L N S	Lighting - Pendent/Surface Marker Board	1st Floor		SF	7	10+ years	
L N S	Lighting - Pendent/Surface Marker Board		1.054	SF	7	10+ years	
N S	Marker Board		16	ĒΑ	7	6-10 years	
S		1st Floor	10	LF	7	6-10 years	
	SIOIAOE/ CIOSEI	1st Floor	4	SF	7	10+ years	
•	Walls - Plaster/Drywall	1st Floor	1,497	SF	7	10+ years	
Classroom	#104 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	897	SF	7	10+ years 10+ years	
	Doors - Transom Window	1st Floor 1st Floor	897 8	SF SF	7 7		
						10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	897	SF	6	10+ years	
	ighting - Pendent/Surface	1st Floor	14	EΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
V	Walls - Plaster/Drywall	1st Floor	1,323	SF	7	10+ years	
	#106 (Regular Classroom)						
F	AC Units	1st Floor	3	EΑ	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,054	SF	7	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
Γ	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
Γ	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
F	Floor - Wood	1st Floor	1,054	SF	6	10+ years	
	ighting - Pendent/Surface	1st Floor	['] 16	EΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,497	SF	7	10+ years	
_Classroom	#112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	897	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
			o 1	EA	7		
	Doors - Wood Doors inclu hw	1st Floor				10+ years	
	Floor - Wood	1st Floor	897	SF	6	10+ years	
L	ighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
V	Walls - Plaster/Drywall	1st Floor	1,323	SF	7	10+ years	

Campus Name: Ray Page : 18 of 45 Assessment Date: 02/16/2022



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
. .	**************************************						
Classroc	om #114 (Regular Classroom)	=					
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,054	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,054	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,497	SF	7	10+ years	
	,		, -			, , , , , ,	
lassroc	m #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,056	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	1,056	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,454	SF	7	10+ years	
	Walls - Flaster/Drywall	13(1100)	1,404	Oi	,	10+ years	
Classroc	om #201 (Kindergarten)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,056	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Floor - Wood	2nd Floor	1,056	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
			16	LF	7		
	Marker Board	2nd Floor		SF		6-10 years	
	Storage/ Closet	2nd Floor	4		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,454	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1,034	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	•	
	און אוטטון פוטטם און אוטטון פוטטם - אוטטם דיסטופ	ZIIU FIUUI	I	EA	1	10+ years	



Catego	ory : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	1,054	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,497	SF	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	897	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors med riw	2nd Floor 2nd Floor	897	SF	6	•	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
				LF		6-10 years	
	Marker Board	2nd Floor	16		7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,054	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	['] 16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,497	SF	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	20	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	1,348	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	-	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	Sr EA	7	10+ years	
				SF		10+ years	
	Floor - Wood	2nd Floor	1,348	SF EA	7 7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20			6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4 700	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,726	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
						,	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,290	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,290	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,718	SF	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	1,054	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,497	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	897	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	897	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,323	SF	7	10+ years	
_Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Books inclu fiw	2nd Floor	1,054	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	1,034	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	4	SF	7	10+ years	
	DIDIQUE/ CIUSEL	ZHU FIUUI	4	JГ	1	IUT YEAIS	



Catego	ory : Classroom		В	uilding	: Main		or o nimbark Avenoe, omeago, ie ooor
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,497	SF	6	10+ years	
Classro	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,056	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Bools inclu flw	2nd Floor	1,056	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,454	SF	7	10+ years	
	Walls - Flastel/Drywall	2110 F1001	1,454	SF	,	10+ years	
_Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,091	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,091	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years	
Classro	om #302 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,116	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,116	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years	
Classic	am #202 (Office)						
Classio	om #303 (Office)	0-d Fl ::	25		7	40	
	Casework	3rd Floor	35	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	377	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	377	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	913	SF	7	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	913	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,413	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
01	(1996 (Denviler Olegania)						
Classroc	om #306 (Regular Classroom)	0.151	22			40	
	Casework	3rd Floor	32	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,445	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,438	SF	7	10+ years	
	Floor - Tile	3rd Floor	7	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,503	SF	7	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	32	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,091	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,091	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,503	SF	7	10+ years	
Classroo	om #309 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	1,100	SF	7	10+ years	
	Cenning - Flaster/Drywaii	SIU FIOOI	1,100	SI-	′	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,100	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	1,100	SF	7	10+ years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years	
	Work Sink	3rd Floor	5	EA	7	10+ years	
Classroc	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	993	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ΕA	6	10+ years	
	Floor - Tile	3rd Floor	983	SF	6	6-10 years	
	Floor - Tile/Sheet	3rd Floor	10	SF	4	0-10 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	Damaged tiles
		3rd Floor	26	LF	7	6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor	1,528	SF	6	10+ years	
	walls - Flasten Diywall	314 1 1001	1,320	Oi	Ü	10+ years	
Classroc	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	913	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	910	SF	7	10+ years	
	Floor - Tile	3rd Floor	3	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	•
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,413	SF	7	10+ years	
lassroc	om #313 (Regular Classroom)						
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	377	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	377	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	•	
	IVIAINEI DUAIU	31U F1001	ð	ᆫᆮ	1	6-10 years	



XXXXX	Schools					56	331 S Kimbark AVENUE, Chicago, IL 6063
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
Classroc	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,116	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	. 8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	1,116	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years	
	Walls Tlastel/BlyWall	01011001	1,000	Oi.	,	101 years	
Classroc	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,091	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,091	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor	Ceiling - Plaster/Drywall	1st Floor	3,654	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EΑ	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,604	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	1st Floor	43	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	77	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,241	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,654	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	25	SF	7	10+ years	
	Doors - Side-life Doors - Transom Window	2nd Floor	160	SF	7	10+ years	
	DOOLS - LIGHSOHI WILIOW	ZIIU FIUUI	160	SF	′	TUT years	



Catego	ry : Interior		В	uilding	: Main		STORINDAR AVENUE, Officago, IE 00007
Guiogo			_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Wood Doors include hw	2nd Floor	2	EΑ	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,654	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	45	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	77	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10,241	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3,654	SF	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,644	SF	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	10	SF	4	0-1 year	Cracked tiles
	Lighting - Pendent/Surface	3rd Floor	45	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	126	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	9,709	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	5,282	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years	
	Drinking Fountains - Double Fountain	Basement	2	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	5,242	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	. 4	EA	7	6-10 years	
	Stairs - Terrazzo	Basement	8	LF	7	10+ years	
	Student Lockers - Two Tiers	Basement	77	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	8,239	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	77	SF	7	10+ years	
						j	
Safety							
	Camera Viewing Station	1st Floor	3	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
_Stairs							
	Ceiling - Plaster/Drywall	North stairs	236	SF	7	10+ years	
	Floor - Asphalt	North stairs	542	SF	7	10+ years	D
	Floor - Asphalt	North stairs	144	SF	5	1-2 years	Deterioration
	Handrails	North stairs	72	LF	7	10+ years	
	Lighting - Wall Mounted	North stairs	6	EA	7	6-10 years	
	Stairs - Terrazzo	North stairs	78	LF	7	10+ years	
	Walls - Plaster/Drywall	North stairs	2,608	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South Stair	236	SF	6	10+ years	
	Floor - Terrazzo	South Stair	686	SF	7	10+ years	
	Handrails	South Stair	72	LF.	7	10+ years	
	Lighting - Wall Mounted	South Stair	6	EA	7	6-10 years	
	Stairs - Terrazzo	South Stair	78	LF	7	10+ years	
	Walls - Plaster/Drywall	South Stair	2,608	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West Stair	170	SF	7	10+ years	
	Floor - Terrazzo	West Stair	590	SF	7	10+ years	
	Handrails	West Stair	60	LF	7	10+ years	

Campus Name: Ray Page : 26 of 45 Assessment Date: 02/16/2022



Catego	ry : Interior		Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Lighting - Wall Mounted	West Stair	4	EA	7	6-10 years		
	Stairs - Terrazzo	West Stair	60	LF	7	10+ years		
	Walls - Plaster/Drywall	West Stair	1,975	SF	7	10+ years		
_Vertical	Conveyance							
	Elevator - Hydraulic Elevator	1st to 3rd floors	1	EA	7	10+ years		

Campus Name: Ray Page : 27 of 45 Assessment Date: 02/16/2022



Category : Exterior			Building : Addition 1					
					Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Exterior Doors - Exterior Wood Door	#2 W	4	EA	5	2-5 years	Weather guard/Door sweep Damaged - Metallurgical reaction causing corrosion at bottom of door/mullion.	
	Exterior Doors - Exterior Wood Door	#3 W	2	EA	5	2-5 years		
	Exterior Doors - Transom Lite	#3 W	1	EA	7	10+ years		
	Exterior Stairs - Concrete	#3 W	6	LF	5	2-5 years	Broken/missing corner of concrete	
	Exterior Doors - Exterior Wood Door	#4 W	2	EA	5	10+ years	· ·	
	Exterior Doors - Transom Lite	#4 W	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#4 W	6	LF	5	2-5 years	Broken/cracked: Missing edge at corner. Missing/broken/Chipped at setting	
	Exterior Doors - Exterior Steel Door	#5 N Exit	2	EA	7	10+ years		
	Exterior Stairs - Concrete	#5 N Exit	6	LF	5	2-5 years		
	Exterior Doors - Exterior Steel Door	CY - 1	1	EA	6	10+ years	Damaged Stone Sill/Stair	
oundation	on							
	Foundation - Concrete	Entire Building	377	LF	7	10+ years		
	Superstructure - Steel with Clay Tile Arch	Entire Building	6,930	SF	7	10+ years		
		· ·				•		
ighting	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	6-10 years		
	Exterior Lightning - waii Mounted	Entire Building	0	LA	,	0-10 years		
oof Sys								
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Lower Roof	12	LF	7	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Lower Roof	15	LF	7	10+ years		
	Coping - Stone	Lower Roof	116	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Lower Roof	60	LF	7	10+ years		
	Parapet - Parapet > 30"	Lower Roof	116	LF	7	10+ years		
	Roof - Asphalt Gravel Ballast	Lower Roof	760	SF	6	10+ years		
	Roof - Metal	Lower Roof	390	SF	7	10+ years		
	Roof - Modified Bitumen	Lower Roof	230	SF	6	10+ years	Added Asset - West Lower Roof	
	Roof - Modified Bitumen	Lower Roof	730	SF	6	6-10 years		
	Roof Structure - Steel / Metal Deck/	Lower Roof	2,110	SF	7	10+ years		
	Concrete Topping		, -			,		
	Coping - Stone	Main Roof	130	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	75	LF	6	10+ years		
	Roof - Asphalt Shingle	Main Roof	7,583	SF	6	6-10 years		
	Roof - Modified Bitumen	Main Roof	730	SF	6	6-10 years	Minor buckling - Detaching from	
	Nooi - Moullieu Ditumen	IVIAIII NUUI	730	SF	O	o-10 years	wind buckling - Detaching in	

Campus Name: Ray Page : 28 of 45 Assessment Date: 02/16/2022



XIII.	Schools					56	331 S Kimbark AVENUE, Chicago, IL 60637
Catego	ry : Exterior		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							substrate in spots
	Roof Structure - Steel with Clay Tile Arch	Main Roof	8,313	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	2,926	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,300	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	300	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	478	SF	5	10+ years	
Windows	5						
	Guard - Guards wire guard	Entire Building	829	SF	6	6-10 years	
	Lintels - Steel	Entire Building	143	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	829	SF	6	6-10 years	
Catama	m Flactrical		ь	به ما المانية	. A al al:4:	- · · 4	
Catego	ry : Electrical		<u>D</u>	unaing	: Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ncy System	Location	Quantity	COM	Italik	Replacement	Comments
_Lineigei	Emergency A/C Power - Auditoium and	1st Floor	4,445	SF	6	6-10 years	
	Aisle Lighting	13(1100)	т,тт0	Oi	O	0-10 years	
	Exit Signs - Auditoium	1st Floor	6	EA	5	6-10 years	Functional, glass plates replaced
	Emergency Battery Packs - Auditoium and	Entire Building	4	EA	6	6-10 years	7 3 1
	Aisle Lighting	· ·				•	
	Emergency Battery Packs - Corridors and	Entire Building	1	EA	6	6-10 years	
	Stairs						
Main Se	rvice						
<u>IVIAIII SE</u>	PA System	Entire Building	6,930	SF	6	6-10 years	Connected to main and addition 1
	PA System	Entire Building	0,930	SI	O	0-10 years	building
							2 dilaning
Power D	istribution						
	Lighting and Power Panels - 100 A	1st Floor	1	EA	7	10+ years	Functional, served from main
	1:1:: 15 5 1 11 100 1	=			_	40	building. Functional panels rated 7
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	10+ years	Functional, served from main
							building. Functional panel rated 7
Catego	ry : Fire Protection		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	6,930	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	6,930	SF	5	6-10 years	Connected to main building

Campus Name: Ray Page : 29 of 45 Assessment Date: 02/16/2022



Catego	ry : Fire Protection	В	Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Catego	ry : Mechanical		В					
				- J		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Boiler Sv	vstems		-			-		
	Piping - Condensate Pipe- Steel	Entire Building	75	LF	5	6-10 years	Connected to main building	
	Piping - Steam Pipe- Steel	Entire Building	75	LF	5	6-10 years	Connected to main building, served by boiler in main building	
	Steam Traps	Entire Building	3	EA	6	6-10 years	-,g	
leating	Devices							
	Radiators - Steam	1st Floor	1	EA	5	6-10 years		
	Unit Heater - Electric	1st Floor	1	EA	5	6-10 years	Near door, functional	
	Cabinet Heaters - With Steam Coil	Basement	1	EA	5	6-10 years	In auditorium	
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Functional	
i empera	ature Control							
	Pneumatic System	Entire Building, Basement	6,930	SF	4	2-5 years	Served from main building, leaks	
	Thermostats - Pneumatic	Entire Building, Basement	1	EA	4	2-5 years	Leaks	
atego	ry : Room		В	uilding	: Addition	on 1		
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Auditoriu	ım & Theater							
	Ceiling - Splined	Basement	4,445	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	4	EA	7	10+ years		
			4 4 4 5	~-	_	40		

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Location	Quantity	OOM	IVAIIK	Replacement	Comments
_Auditorii	um & Theater						
	Ceiling - Splined	Basement	4,445	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	7	10+ years	
	Floor - Wood	Basement	4,445	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	Basement	8	EA	7	10+ years	
	Lighting - Wall Mounted	Basement	10	EA	7	10+ years	
	Main Floor Seating	Basement	624	EA	7	10+ years	
	Sound System	Basement	2	EA	7	10+ years	
	Stage	Basement	500	SF	6	10+ years	Rank changed to match current
							observation
	Stage Curtain	Basement	5	EA	7	10+ years	
	Stage Lighting System	Basement	1	EA	7	10+ years	
	Stage-Stairs - Asphalt	Basement	48	LF	7	10+ years	
	Storage/ Closet	Basement	2	SF	5	6-10 years	
	Walls - Plaster/Drywall	Basement	5,498	SF	7	10+ years	
Restroo	m						
	Accessories	1st Floor	64	SF	4	0-1 year	Missing components, abandoned
	Ceiling - Plaster/Drywall	1st Floor	64	SF	6	10+ years	

Campus Name: Ray Page : 30 of 45 Assessment Date: 02/16/2022



Catego	ry : Room	В	Building : Addition 1				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Epoxy/ Painted	1st Floor	64	SF	4	1-2 years	Damaged finish
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	4	0-1 year	Missing components, abandoned
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Partitions	1st Floor	1	EA	5	2-5 years	
	Urinals	1st Floor	1	EA	6	0-1 year	Missing flush valve
	Walls - Plaster/Drywall	1st Floor	210	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	3	0-1 year	Missing components

Category: Classroom **Building: Addition 1**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #001 (Play Room)						
	Casework	Basement	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	600	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	580	SF	6	10+ years	
	Floor - Tile	Basement	20	SF	4	0-1 year	Missing tiles
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	5	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,000	SF	7	10+ years	

Campus Name: Ray Page : 31 of 45 Assessment Date: 02/16/2022





Category : Exterior **Building: Addition 2**

Galogo	y . Exterior		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•		Location	Quantity	COIVI	IVALIK	Replacement	Comments	
_Entrance								
	Entrance Control - Audio and Video	#12 E	1	EA	7	6-10 years		
	Exterior Doors - Side lite	#12 E	2	EA	7	10+ years		
	Exterior Doors - Store Front	#12 E	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#12 E	3	EA	7	10+ years		
	Power Door Operator and Controls	#12 E	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#13 E	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#14 E	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#15 E	2	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#16 E	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#17 E	1	EA	6	10+ years		
	Exterior Doors - Side lite	#18 W	2	EA	7	10+ years		
	Exterior Doors - Store Front	#18 W	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#18 W	3	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#19 W	1	EΑ	7	10+ years		
	Exterior Doors - Side lite	#20 W	2	EΑ	7	10+ years		
	Exterior Doors - Store Front	#20 W	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#20 W	3	EA	7	10+ years		
						•		
Foundati	on							
	Foundation - Concrete	Entire Building	585	LF	7	10+ years		
	Superstructure - Steel	Entire Building	23,876	SF	7	10+ years		
	Superstructure - Steel	Little Building	25,070	OI	,	10+ years		
Link the e								
Lighting	E c 1 1 1 c NAVIIA C 1	E C D TE		Ε.Δ		0.40	0 (1 A I)	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	6-10 years	Quantity Adjusted	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	4	0-1 year	Missing and/or heat from bulb melted	
							fixture's plastic cover	
Roof Sys								
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	30	LF	7	10+ years		
	Liner							
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	20	LF	7	10+ years		
	Liner							
	Coping - Metal	Main Roof	580	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	90	LF	7	10+ years		
	Roof - Asphalt Shingle	Main Roof	18,100	SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	Main Roof	18,100	SF	7	10+ years		
	Concrete Topping		•			•		
	5							
Walls								
774110	Canopy - Concrete/ Stucco	Entire Building	396	SF	7	10+ years		
	Exterior Walls - Brick	Entire Building	11,156	SF	7	10+ years		
	EXIGIO Walls - DION	Little building	11,130	Ji	,	TOT years		

Campus Name: Ray Page : 32 of 45 Assessment Date: 02/16/2022



William H Ray Elementary School

Catego	ry : Exterior		Building : Addition 2					
220110	Hom Type	Location	Quantitu	HOM	Donk	Recommend	Comments	
roup	Item - Type Exterior Walls - Stone-Cast	Location Entire Building	Quantity 1,460	UOM SF	Rank 7	Replacement 10+ years	Comments	
	Exterior Walls - Storie-Cast	Littire Building	1,400	OI.	,	10+ years		
/indows								
	Lintels - Steel	Entire Building	429	LF	7	10+ years		
	Windows - Sash Aluminum Double-pane	Entire Building	2,226	SF	7	10+ years		
atego	ry : Electrical		В	uilding	: Additi	on 2		
						Recommend		
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
merger	CCTV	Entire Building	22.076			6.10 voore		
	Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building	23,876 23,876	SF SF	5 5	6-10 years 6-10 years		
	Emergency Battery Packs - Corridors and	Entire Building Entire Building, 1st Floor	25,676	EA	6	6-10 years		
	Stairs	Zinino Dananig, Tect Teel		_, `	Ü	o io youio		
	Emergency Battery Packs - Multipurpose Room	Entire Building, 1st Floor	5	EA	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building, 1st Floor	8	EA	6	6-10 years	Functional	
	Exit Signs - Multipurpose Room	Entire Building, 1st Floor	8	EA	6	6-10 years	Functional	
	Emergency A/C Power - Corridors and Stairs	Entire Building, 1st floor	4,191	SF	6	10+ years		
	Emergency A/C Power - Multipurpose Room	Entire Building, 1st floor	3,132	SF	6	10+ years		
lain Ser	vice							
	PA System	Entire Building	23,876	SF	5	6-10 years	Connected to main and addition 1 building	
ower D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	EM panel	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	·	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years		
atego	ry : Fire Protection		В	uilding	: Additi	on 2		
	_					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ire Aları		Fatina Duildina	00.070	<u> </u>		0.40		
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	23,876 23,876	SF SF	6 5	6-10 years 6-10 years	Connected to main building	
	i ile Alaini_System	Little bullding	23,070	ЗF	ວ	0-10 years	Connected to main building	
prinkler	System							
	Dry Sprinkler System	Entire Building	23,876	SF	7	10+ years	1996 installation, using city pressur	

Campus Name: Ray Page : 33 of 45 Assessment Date: 02/16/2022



Catego	Category : Fire Protection			uilding	on 2		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sprinkler Heads	Entire Duilding	22.076	SF	7	10+ years	Using air compressor
		Entire Building	23,876	SF SF	7		
	Sprinkler Piping	Entire Building	23,876	SF	,	10+ years	
Catego	ry : Mechanical		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Ground Mounted - Less than 5 tons	Site - East	2	EA	5	6-10 years	One unit being currently repaired. Bullet hole in coil
	Condensing Unit- Roof Mounted - Less than 5 tons	Site - East	1	EA	5	6-10 years	Not accessible on sloped roof, serves IDF room
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	2nd Floor	1	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 4000-8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, Serves cafeteria, 1996 installation, functional
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 8001-12000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2, Serves library, 1996 installation
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
Boiler Sv	stems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EΑ	6	6-10 years	
	Non Condensing- Water Tube- Flexible	Boiler Room	2	ΕA	6	6-10 years	B1, B2, serve addition 2
	Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH				-	5 12 , 5 5	_ ,,,
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Manually fed
Heating I	Devices						
Ü	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	150	LF	5	6-10 years	
	PTAC - Electric Heating and Self Contained Cooling	Entire Building	1	EA	4	2-5 years	Requires frequent repair, not reliable, older, in office, with internal temperature control
	I.D. L.						
Mechani	cal Plumbing						

Campus Name: Ray Page : 34 of 45 Assessment Date: 02/16/2022



Catego	ory : Mechanical		5631 S Kimbark AVENUE, Chicago, IL 6 Building: Addition 2						
Outogo	i y . incondinodi								
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Hot Water Pump - Less than 10	Boiler Room	4	EA	5	6-10 years	Seals recently repacked, 2 for boilers 2 for air handlers. Functional		
	Hydronic Supply and Return - Copper	Entire Building	1,000	LF	6	10+ years			
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	6-10 years	1996 installation		
Tempera	ature Control								
	DDC System	Entire Building	23,876	SF	5	6-10 years	Software not updated recently		
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	Serve cabinet heaters		
	Thermostats - DDC	Entire Building	7	EA	6	6-10 years	Controls 7 univents		
Unit Ver	ntilation								
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	7	EA	5	6-10 years	Require frequent repairs, functional		
Ventilati	on								
ventilati	Exhaust Fans- Indoor - Less than 500 CFM	Mechanical Room, Roof, 1st Floor Warming Kitchen	2	EA	5	6-10 years	Serves kitchen		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Mechanical Room, Roof, 1st Floor Warming Kitchen	1	EA	6	6-10 years	Not accessible on sloped roof		
Catego	ory : Plumbing		В	uilding	: Additi	on 2			
	· ·					Recommend			

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er		•			•	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Functional, serves addition 2, 2007 installation
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	23,876	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	23,876	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	23,876	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	23,876	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	23,876	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	23,876	SF	6	10+ years	1996 installation
	Sanitary Piping	Entire Building	23,876	SF	6	10+ years	
	Storm Piping	Entire Building	23,876	SF	6	10+ years	
	Vent Piping	Entire Building	23,876	SF	6	10+ years	

Campus Name: Ray Page : 35 of 45 Assessment Date: 02/16/2022



William H Ray Elementary School

5631 S Kimbark AVENUE, Chicago, IL 60637

Category: Plumbing Building: Addition 2 Recommend Location Quantity Item - Type Replacement Comments Group UOM Rank <u>Pumps</u> Pumps - Sump-Simplex 1st Floor 1 EΑ 6 6-10 years Under south elevator

Category : Room Building : Addition 2

Category : Room		Building : Addition 2							
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	rative Suites/Offices	Location	Quantity	OCIVI	Italik	Replacement	Comments		
шшы		1st Floor - Room 423	131	SF	7	10 Lyoars			
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st Floor - Room 423	131	EA	7	10+ years			
	Floor - Tile	1st Floor - Room 423	131	SF	7	10+ years 10+ years			
	Lighting - Lay-in	1st Floor - Room 423	3	EA	7	•			
	Walls - Concrete Block	1st Floor - Room 423	538	SF	7	10+ years			
		2nd Floor - Conference Room 502	260	SF	7	10+ years			
	Ceiling - Lay-in Doors - Side-lite	2nd Floor - Conference Room 502 2nd Floor - Conference Room 502	32	SF SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Conference Room 502	32	EA	7	10+ years			
	Floor - Tile	2nd Floor - Conference Room 502 2nd Floor - Conference Room 502	260	SF	7	10+ years			
		2nd Floor - Conference Room 502 2nd Floor - Conference Room 502			7	10+ years			
	Lighting - Lay-in		6 8	EA EA	7	6-10 years			
	Power Distribution Walls - Concrete Block	2nd Floor - Conference Room 502 2nd Floor - Conference Room 502		SF	7	10+ years			
			656 334	SF SF		10+ years			
	Ceiling - Lay-in	2nd floor - 513			7	10+ years			
	Doors - Side-lite	2nd floor - 513	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd floor - 513	2	EA	7	10+ years			
	Floor - Tile	2nd floor - 513	334	SF	7	10+ years			
	Lighting - Lay-in	2nd floor - 513	6	EA	7	6-10 years			
	Power Distribution	2nd floor - 513	6	EA	7	10+ years			
	Walls - Concrete Block	2nd floor - 513	548	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd floor - 513	205	SF	7	10+ years			
	Work SInk	2nd floor - 513	1	EA	7	10+ years			
	Ceiling - Lay-in	Kitchen manager office	232	SF	7	10+ years			
	Ceiling - Lay-in	Kitchen manager office	8	SF	5	1-2 years	Water damage tile		
	Doors - Side-lite	Kitchen manager office	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Kitchen manager office	1	EA	7	10+ years			
	Floor - Tile	Kitchen manager office	240	SF	7	10+ years			
	Lighting - Lay-in	Kitchen manager office	3	EA	7	6-10 years			
	Power Distribution	Kitchen manager office	6	EA	7	10+ years			
	Walls - Concrete Block	Kitchen manager office	650	SF	7	10+ years			
hen									
	Ceiling - Lay-in	1st Floor	1,763	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Tile	1st Floor	1,763	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years			
	Serving Line	1st Floor	13	LF	7	10+ years			

 Campus Name: Ray
 Page : 36 of 45
 Assessment Date: 02/16/2022



Catego	Category : Room			Building : Addition 2				
				J		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	1st Floor	1,668	SF	7	10+ years		
Librani								
Library	Ceiling - Lay-in	513 Music room	1,940	SF	7	10+ years		
	Doors - Wood Doors inclu hw	513 Music room	1,940	EA	7	•		
	Floor - Carpet	513 Music room	1,940	SF	7	10+ years 6-10 years		
	Lighting - Lay-in	513 Music room	1,940	EA	7	•		
	Walls - Concrete Block	513 Music room		SF	7	10+ years		
	vvalis - Concrete Block	513 Music room	1,788	SF	,	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	3,132	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	3,132	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	26	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	2,298	SF	7	10+ years		
			,			,		
_MDF_ID								
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Finishes	2nd Floor	150	SF	7	10+ years		
	Other Cooling Unit	2nd Floor	0	EA	7	6-10 years	PTAC	
_Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	25	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	240	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	120	SF	7	10+ years		
	Janitor's Closet	2nd Floor	25	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	120	SF	7	10+ years		
Restroor	n Accessories	1st Floor - Across 413	125	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - Across 413	125	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Across 413	123	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Across 413	125	SF	7	10+ years		
	Floor Drain	1st Floor - Across 413	123	EA	7	10+ years		
	Hand Dryer	1st Floor - Across 413	1	EA	7	6-10 years		
		1st Floor - Across 413	1	EA	7	•		
	Lavatory Lighting - Lay-in	1st Floor - Across 413	2	EA	7	10+ years 10+ years		
	Partitions	1st Floor - Across 413	1	EA	7	•		
			1	EA EA	7	10+ years		
	Urinals Walls - Concrete Block	1st Floor - Across 413	· · · · · · · · · · · · · · · · · · ·	SF	7 7	10+ years		
		1st Floor - Across 413	187	SF SF	-	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor - Across 413	187		7	10+ years		
	Water Closet Accessories	1st Floor - Across 413 1st Floor - Across 420	1 125	EA SF	7 7	10+ years 6-10 years		

Campus Name: Ray Page : 37 of 45 Assessment Date: 02/16/2022



Catego	Category : Room			uilding	: Additi	on 2	
_	Group Item - Type Location					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor - Across 420	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Across 420	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Across 420	130	SF	7	10+ years	
	Floor Drain	1st Floor - Across 420	1	EA	7	10+ years	
	Hand Dryer	1st Floor - Across 420	1	EΑ	7	6-10 years	
	Lavatory	1st Floor - Across 420	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Across 420	2	EA	7	10+ years	
	Partitions	1st Floor - Across 420	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Across 420	187	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Across 420	187	SF	7	10+ years	
	Water Closet	1st Floor - Across 420	2	EA	7	10+ years	
	Accessories	1st Floor - Kitchen	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Kitchen	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Kitchen	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Kitchen	45	SF	7	10+ years	
	Floor Drain	1st Floor - Kitchen	1	EA	7	10+ years	
	Lavatory	1st Floor - Kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Kitchen	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Kitchen	111	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Kitchen	111	SF	7	10+ years	
	Water Closet	1st Floor - Kitchen	1	EA	7	10+ years	
	Accessories	1st floor classroom 405	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor classroom 405	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor classroom 405	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor classroom 405	45	SF	6	10+ years	
	Floor Drain	1st floor classroom 405	1	ĒΑ	7	10+ years	
	Lavatory	1st floor classroom 405	1	EA	6	10+ years	
	Lighting - Lay-in	1st floor classroom 405	2	EA	6	6-10 years	
	Walls - Concrete Block	1st floor classroom 405	111	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor classroom 405	111	SF	6	10+ years	
	Water Closet	1st floor classroom 405	1	ĒΑ	6	10+ years	
	Accessories	1st floor classroom 411-413	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor classroom 411-413	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor classroom 411-413	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor classroom 411-413	38	SF	6	10+ years	
	Floor Drain	1st floor classroom 411-413	1	EΑ	7	10+ years	
	Lavatory	1st floor classroom 411-413	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor classroom 411-413	2	EΑ	7	6-10 years	
	Walls - Concrete Block	1st floor classroom 411-413	101	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor classroom 411-413	101	SF	7	10+ years	
	Water Closet	1st floor classroom 411-413	1	EA	7	10+ years	
	Accessories	2nd Floor - NW	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - NW	65	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - NW	1	EA	7	•	
	POOLS - MOOR POOLS HIGH HM	ZIIU FIUUI - INVV	I	ĽA	1	10+ years	



Category : Room

William H Ray Elementary School 5631 S Kimbark AVENUE, Chicago, IL 60637

Building: Addition 2

oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	Floor - Tile Ceramic/ Porcelain	2nd Floor - NW	65	SF	7	10+ years	
	Floor Drain	2nd Floor - NW	1	EA	7	10+ years	
	Lavatory	2nd Floor - NW	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - NW	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - NW	111	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - NW	111	SF	7	10+ years	
	Water Closet	2nd Floor - NW	1	EA	7	10+ years	
tego	ry : Classroom		В	uilding	: Additi	on 2	
	Itam Tuna	Location	Quantity	HOM	Donk	Recommend	Comments
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	m #405 (Pre School)						
	Casework	1st Floor	9	LF	7	10+ years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	975	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	975	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,123	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
assroc	m #411 (Pre School)						
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,005	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	10	SF	5	1-2 years	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	ŭ
	Floor - Tile	1st Floor	1,015	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,147	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
assroc	m #413 (Pre School)						
	Casework	1st Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,010	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	5	SF	5	1-2 years	Water damage tile
	Floor - Tile	1st Floor	1,015	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,137	SF	7	10+ years	
	Walls - Concrete Block			01	,	IUT YEARS	

Campus Name: Ray Page : 39 of 45 Assessment Date: 02/16/2022



Group		Category : Classroom		Building : Addition 2					
Group						Recommend			
O. Gup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #503 (Art Room)								
	Ceiling - Lay-in	2nd Floor	973	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years			
	Floor - Tile	2nd Floor	973	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	1,123	SF	7	10+ years			
	Work Sink	2nd Floor	2	EA	7	10+ years			
	Work On it	2110 1 1001	_	_, ,	•	ioi youlo			
Classroo	m #510 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	514	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	514	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	251	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	660	SF	7	10+ years			
	walls - Flastel/Drywall	ZHU FIOOI	000	SI	,	10+ years			
Classroo	m #511 (Office)								
	Ceiling - Lay-in	2nd Floor	514	SF	7	10+ years			
	Chalk Board	2nd Floor	16	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	514	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	5	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	251	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	660	SF	7	10+ years			
Classes	#F42 (Demiler Classes)								
Classiool	m #512 (Regular Classroom)	0-15	4.047	0.5	7	40			
	Ceiling - Lay-in	2nd Floor	1,017	SF	7	10+ years	10/		
	Ceiling - Lay-in	2nd Floor	10	SF	5	1-2 years	Water damage tiles		
	Chalk Board	2nd Floor	16	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years			
	Floor - Tile	2nd Floor	1,027	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years			
	Marker Board	2nd Floor	5	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	634	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	503	SF	7	10+ years			
_Classroo	m #516 (Computer Lab)								
	Ceiling - Lay-in	2nd Floor	998	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	998	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years			
	Lighting - Lay-III	ZIIU FIUUI	10	EA	′	0-10 years			



Category : Classroom			В	Building : Addition 2				
_						Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,113	SF	7	10+ years		
atego	ry : Interior		В	uilding	: Additi			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Corridor	nem Type	Location	Quantity	COM	Rain	Replacement	Comments	
orridor	Ceiling - Lay-in	1st Floor	2,291	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	, 10	SF	5	1-2 years	Water damage tiles	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	7	10+ years	Transcrating mass	
	Drinking Fountains - Single Water Cooler	1st Floor	_ 1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	2,301	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	2,516	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	968	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,800	SF	7	10+ years		
	Doors - Wood Doors include hw	2nd Floor	2	EA	7	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	1	EΑ	7	6-10 years		
	Floor - Tile/Sheet	2nd Floor	1,800	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Student Lockers - Two Tiers	2nd Floor	16	EΑ	7	10+ years		
	Walls - Concrete Block	2nd Floor	2,310	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	700	SF	7	10+ years		
	walls Tlaster/Drywall	2110 1 1001	700	Oi.	,	101 years		
Stairs								
	Ceiling - Lay-in	Stair 1	84	SF	7	10+ years		
	Floor - Tile	Stair 1	45	SF	7	10+ years		
	Handrails	Stair 1	65	LF	7	10+ years		
	Lighting - Lay-in	Stair 1	3	EA	7	6-10 years		
	Stairs - Rubber	Stair 1	23	LF	7	10+ years		
	Walls - Concrete Block	Stair 1	422	SF	7	10+ years		
	Ceiling - Lay-in	Stair 2	85	SF	6	10+ years		
	Floor - Tile	Stair 2	45	SF	7	10+ years		
	Handrails	Stair 2	65	LF	7	10+ years		
	Lighting - Lay-in	Stair 2	2	EA	7	6-10 years		
	Stairs - Rubber	Stair 2	23	LF	6	10+ years		
	Walls - Concrete Block	Stair 2	422	SF	7	10+ years		
/ertical (Conveyance							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years		



Category : Site Building : Site

	y : Site			uilding	. Oile		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	Southeast	6,965	SF	4	1-2 years	Cracks/Broken/Holes - Trip hazards
	Surface - Natural	Southeast	43,903	SF	6	10+ years	·
						_	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	12	EA	7	10+ years	
						, , , , , ,	
Fencina							
	Fencing - Chain Link	Entire Site	33	LF	5	2-5 years	
	Fencing - Chain Link	Entire Site	419	LF	5	6-10 years	
	Fencing - Chain Link	Entire Site	419	LF	5	10+ years	
	Fencing - Chain Link	Entire Site	47	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1.048	LF	6	10+ years	
			1,010		•	, , , , , , , , , , , , , , , , , , , ,	
Landscar	oe .						
'	Benches	Entire Site	26	EA	7	10+ years	
	Landscape - Grass	Entire Site	8,222	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	819	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	3,334	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,279	SF	4	0-1 year	Broken/Cracked/Heaving. Total disarray
	Lighting - Pole Mounted	Entire Site	2	EA	6	10+ years	dioditay
	Parkway trees	Entire Site	31	ΕA	7	10+ years	
	Planting Beds/ Area	Entire Site	9,264	SF	6	10+ years	
	Planting Beds/ Area	Entire Site	6,439	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	15,142	SF	5	2-5 years	Cracked/Open Seams in Asphalt -
						•	Uneven
	Play Area - Hardscape- Asphalt	Entire Site	8,146	SF	5	2-5 years	Cracks/Open gaps/Seams in asphal
	Retaining Wall - Masonry	Entire Site	212	SF	7	10+ years	
	Trash Receptacles	Entire Site	6	EA	7	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	1,852	SF	6	10+ years	Cracks/jagged edges - uneven
Parking L	ot						
-	Lighting - Pole Mounted	East	5	EA	7	6-10 years	
	Surface - Asphalt	East	20,063	SF	5	2-5 years	
	Surface - Asphalt	East	300	SF	4	1-2 years	Cracked/Broken
Playgrou	nd						
y gi uu	Equipment - Pre K 3-5	North side of east courtyard	1	EA	5	2-5 years	Per Site Engineer - "I have to those
	-qp.//ork / 10 / 10 /	. Total oldo of oddi odditydid		_, 、	J	_ 0 ,0010	things constantly"



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	North side of east courtyard	2,520	SF	7	10+ years	
	Equipment - Combo 3-12	Southside of east courtyard	1	EA	5	10+ years	Per Site Engineer - "I fix those things constantly"
	Surface - Poured Surface	Southside of east courtyard	3,176	SF	7	10+ years	•
	Equipment - Pre K 3-5	West side of north courtyard	1	EA	5	2-5 years	Per Site Engineer - constant repair
	Surface - Poured Surface	West side of north courtyard	1,630	SF	7	10+ years	
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	38	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	11,979	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,200	SF	4	0-1 year	Broken/Cracked/Heaved and displacement
Signage							
0 0	Flag Pole - Flag Pole	Southwest	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Southwest	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Southwest	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Ray Page: 43 of 45 Assessment Date: 02/16/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable	14.0°	01
Command Haana	Intended Heave	Doom Loostion	Room	Room	Area	Window	Window	Window	Smart-
Current Usage Building : Main	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Kindergarten	1st Floor	101	101	855	144	72	N	N
Kindergarten	Kindergarten	2nd Floor	201	201	1,056	168	84	N	N
Library	Play Room	Basement	004	NA	1,774	108	54	N	N
Office	Regular Classroom	3rd Floor	303	303	377	23	10	N	N
Play Room	Play Room	Basement	007	NA	809	48	36	N	N
	Other Instructional Use	3rd Floor	313	313	377	23	10	1	N
Regular Classroom				102				N	
Regular Classroom	Regular Classroom	1st Floor	102	102	1,054	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	104 106	104	897	168 120	84	N N	N N
Regular Classroom	Regular Classroom	1st Floor			1,054		60		
Regular Classroom	Regular Classroom	1st Floor	112	112	897	168	84	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	1,054	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	1,056	168	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,054	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	897	168	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,054	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	1,348	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	1,290	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	1,054	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	897	168	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	1,054	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	1,056	168	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	1,091	168	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	1,116	168	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	913	129	147	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	1,445	94	81		
Regular Classroom	Regular Classroom	3rd Floor	307	307	1,091	94	81	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	993	59	53	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	913	129	147	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	1,116	118	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	315	1,091	141	126	N	N
Science Lab Level 3	Regular Classroom	3rd Floor	309	309	1,100	94	84	N	N
Store Room	Regular Classroom	Basement	002	15	956	60	30	N	N
Building : Addition 2									
Art Room	Science Classroom	2nd Floor	503	208	973	88	90	N	N
Computer Lab	Computer Lab	2nd Floor	516	N/A	998	132	135	N	Υ
Office	Office	2nd Floor	511	211	514	44	45	N	N
Pre School	Pre School	1st Floor	405	109	975	88	90	N	N



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Pre School	Pre School	1st Floor	411	111	1,015	88	90	Ν	N
Pre School	Pre School	1st Floor	413	113	1,015	88	90	Ν	N
Regular Classroom	Library	2nd Floor	512	212	1,027	88	90	Ν	N
Regular Classroom	Office	2nd Floor	510	210	514	44	45	Ν	N

Building : Addition 1									
Play Room	Store Room	Basement	001	001	600	40	20	Z	N