

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	4	219,500
Addition 1	1930	3	33,906
Addition 2	1930	3	37,798
Campus Total			291,204

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance)						
	Entrance Control - Audio and Video	10 - Main	2	EA	6	6-10 years	
	Exterior Doors - Exterior AMP Door	10 - Main	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	10 - Main	2	EA	6	10+ years	
	Entrance Control - Audio and Video	4 - East	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	4 - East	10	EA	6	6-10 years	
	Exterior Doors - Transom Lite	4 - East	10	EA	6	10+ years	
	Exterior Stairs - Concrete	4 - East	300	LF	6	10+ years	
	Power Door Operator and Controls	4 - East	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	4 - East	120	LF	6	10+ years	
	Ramps - Concrete	4 - East	120	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	4 - East	80	LF	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	1,214	LF	7	10+ years	
	Foundation - Concrete	Entire Building	100	LF	4	0-1 year	Stepped cracking, displacement, sinking floor
	Superstructure - Steel with Clay Tile Arch	Entire Building	218,186	SF	7	10+ years	3
	Superstructure - Steel with Clay Tile Arch	Entire Building	558	SF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	1,032	SF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	282	SF	6	10+ years	





Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	E - S Center	2	EA	7	10+ years	
	Coping - Clay Tile	E - S Center	196	LF	6	10+ years	
	Coping - Metal	E - S Center	827	LF	5	2-5 years	
	Coping - Metal	E - S Center	200	LF	4	0-1 year	Missing, corroded
	Coping - Terra Cotta	E - S Center	269	LF	6	10+ years	
	Downspouts - Exterior Downspouts	E - S Center	196	LF	6	10+ years	
	Downspouts - Exterior Downspouts	E - S Center	40	LF	4	0-1 year	Broken
	Downspouts - Interior Downspouts	E - S Center	480	LF	6	10+ years	
	Parapet - 16" - 30" Height	E - S Center	1,242	LF	6	10+ years	
	Parapet - 16" - 30" Height	E - S Center	150	LF	4	0-1 year	Displaced brick, deteriorated
	Roof - Modified Bitumen	E - S Center	39,719	SF	5	2-5 years	,
	Roof Hatch - Metal	E - S Center	2	ĒΑ	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	E - S Center	39,719	SF	7	10+ years	
	Access Ladder - Metal	F - Low Center N	1	ĒΑ	7	10+ years	
	Downspouts - Exterior Downspouts	F - Low Center N	50	LF	5	6-10 years	
	Roof - Modified Bitumen	F - Low Center N	17,368	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	F - Low Center N	17,368	SF	7	10+ years	
	Coping - Metal	G - East High	200	LF	5	2-5 years	
	Coping - Terra Cotta	G - East High	138	LF	6	10+ years	
	Parapet - 16" - 30" Height	G - East High	338	LF	6	10+ years	
	Roof - Modified Bitumen	G - East High	7,372	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	G - East High	7,372	SF	7	10+ years	
	Coping - Stone	H - Low SEast	94	LF	6	10+ years	
	Downspouts - Exterior Downspouts	H - Low SEast	35	LF	6	6-10 years	
	Parapet - Parapet > 30"	H - Low SEast	94	LF	6	10+ years	
	Roof - Modified Bitumen	H - Low SEast	2,914	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	H - Low SEast	2,914	SF	7	10+ years	
	Coping - Terra Cotta	I - High Metal	286	LF	7	10+ years	
	Downspouts - Exterior Downspouts	I - High Metal	40	LF	6	10+ years	
	Parapet - 16" - 30" Height	I - High Metal	158	LF	7	10+ years	
	Parapet - 16" - 30" Height	I - High Metal	40	LF	7	10+ years	
	Parapet - Parapet > 30"	I - High Metal	128	LF	7	10+ years	
	Roof - Metal	I - High Metal	5,184	SF	7	10+ years	
	Roof - Modified Bitumen	I - High Metal	1,320	SF	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	I - High Metal	6,504	SF	7	10+ years	
	Access Ladder - Metal	J - Center	3	EA	7	10+ years	
	Coping - Clay Tile	J - Center	88	LF	6	10+ years	
	Coping - Metal	J - Center	217	LF	6	10+ years	
	Coping - Terra Cotta	J - Center	24	LF	6	10+ years	
	Coping Terra Colla	0 Conton	24	LI	U	10+ years	





Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	J - Center	40	LF	6	10+ years	
	Parapet - 16" - 30" Height	J - Center	329	LF	6	10+ years	
	Roof - Modified Bitumen	J - Center	9,564	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	J - Center	9,564	SF	7	10+ years	
	Access Ladder - Metal	K - Center low	4	EA	7	10+ years	
	Coping - Clay Tile	K - Center low	24	LF	6	10+ years	
	Downspouts - Exterior Downspouts	K - Center low	50	LF	6	10+ years	
	Parapet - 16" - 30" Height	K - Center low	24	LF	6	10+ years	
	Roof - Metal	K - Center low	300	SF	6	6-10 years	
	Roof - Modified Bitumen	K - Center low	2,000	SF	7	10+ years	
	Roof - Modified Bitumen	K - Center low	6,076	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	K - Center low	8,376	SF	7	10+ years	
	Access Ladder - Metal	L - East low	1	EA	7	10+ years	
	Coping - Stone	L - East low	94	LF	6	10+ years	
	Downspouts - Exterior Downspouts	L - East low	35	LF	6	6-10 years	
	Parapet - Parapet > 30"	L - East low	94	LF	6	10+ years	
	Roof - Modified Bitumen	L - East low	2,914	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	L - East low	2,914	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	64	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,330	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	30,296	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	959	SF	5	2-5 years	Efflorescence
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	768	SF	7	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	3,350	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	300	SF	4	0-1 year	Water damage, loose stone strapped
	Exterior Walls - Terra Cotta	Entire Building	6,751	SF	6	10+ years	Water damage, 1003e stone strapped
	Exterior Walls - Terra Cotta	Entire Building	1,175	SF	5	10+ years	
_Windows							
	Guard - Guards perforated	Entire Building	10,462	SF	6	10+ years	
	Lintels - Brick	Entire Building	22	LF	6	10+ years	
	Lintels - Steel	Entire Building	2,778	LF	6	10+ years	
	Lintels - Stone	Entire Building	40	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	24,915	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,445	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						





Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	13,061	SF	2	0-1 year	Non functional
	Emergency A/C Power - Corridors and Stairs	Entire Building	41,541	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	8,466	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	11,500	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,344	SF	6	10+ years	
	Emergency A/C Power - Pool	Entire Building	3,160	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	3,144	SF	6	10+ years	
	Exit Signs - Auditoium	Entire Building	10	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	37	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	9	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Pool	Entire Building	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	219,500	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	219,500	SF	6	6-10 years	
//ain Ser	vice						
	PA System	Entire Building	219,500	SF	6	6-10 years	
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Mechanical Room	2	EA	4	1-2 years	Corrosion
Power Di	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	40	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	4	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	2	EA	6	6-10 years	
atego	ry : Fire Protection		В	uilding	: Main		
	Ham. Toma	1	0	11015	D!	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Aları							
	Fire Alarm Strobe Lights	Entire Building	219,500	SF	6	10+ years	
	Fire Alarm_System	Entire Building	219,500	SF	6	10+ years	





Catego	Category : Mechanical			uilding	: Main		
Cuc	Hom Time	Lagation				Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond		D (0.10	
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	6	6-10 years	Lower roof, near dehumidification air handler
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	
_Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	5	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	2	EA	5	6-10 years	
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room	1	EA	5	6-10 years	
	Temperature Coils - 25001 - 35000 cfm	Modrial Inda Probin	·	_, `	Ü	o ro youro	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EΑ	5	6-10 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	6	10+ years	
	Missing or Existing Shaft	Wechanical Room	100	LI	U	10+ years	
	Zone Dampers	Mechanical Room	9	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	10+ years	AHU 7 (North Building)
	Double Delivery-Dual Temperature Coils - 15000 - 30000 cfm	Mechanical Room	l	LA	3	10+ years	Alto / (Notti Bulluling)
	Air Handling Unit- Built Up-Multi Zone- Double Delivery-Dual Temperature Coils -	Mechanical Room	1	EA	5	10+ years	AHU 3, Serves South end of building
	15000 - 30000 cfm Air Handling Unit- Built Up-Multi Zone- Double Delivery-Dual Temperature Coils - 30001 - 45000 cfm	Mechanical Room	1	EA	5	10+ years	AHU 2, serves main classrooms
	Air Intake	Mechanical Room	3	EA	5	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Mechanical Room	2	EA	5	6-10 years	
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room	1	EA	5	10+ years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	6	10+ years	
	Missing or Existing Shaft				-	·	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	50	LF	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	50	LF	5	6-10 years	
	Zone Dampers	Mechanical Room	112	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone- Hot Water and Chilled Water Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	

Campus Name: Senn HS Page : 5 of 95 Assessment Date: 07/18/2022



Catego	ry : Mechanical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	50	LF	5	6-10 years	
	Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	3	EA	5	6-10 years	
	Outdoor Return Fans- Air Handling Unit	Roof	4	EΑ	6	10+ years	
	Type - Greater than 20000 CFM		·		•	, , , , , , , , , , , , , , , , , , , ,	
	Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM	Roof	1	EA	6	10+ years	
	Dehumidification Unit- Outdoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm	Roof	1	EA	6	6-10 years	Serves the pool
Heating	·						
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	94	LF	6	10+ years	
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	1,800	LF	6	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	6	EA	6	6-10 years	
Tempera	ature Control						
	DDC System	Entire Building	219,500	SF	4	1-2 years	System completely non operational
	Electric Thermostat	Entire Building	8	EA	5	6-10 years	System completely non operational
	Thermostats - DDC	Entire Building	120	EA	7	10+ years	
	Thermostats - DDC	Entire Building	4	EA	6	6-10 years	
Ventilation	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	7	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	4	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	3	0-1 year	Missing cover





Group

Category : Mechanical

CFM

Item - Type

Item - Type Administrative Suites/Offices Ceiling - Lay-in

Floor - Tile

Doors - Transom Window

Doors - Wood Doors inclu hw

Doors - Wood Doors inclu hw

Lab Exhaust Hood

Exhaust Fans- Roof Mounted - 500 - 1500

5900 N Glenwood AVENUE, Chicago, IL 60660

	Roof Mounted Duct Work	Entire Building	714	LF	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
, ,	Domestic Piping-Hot Water Return Lines	Entire Building	219,500	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	219,500	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	219,500	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	219,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	219,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	219,500	SF	6	10+ years	
	Sanitary Piping	Entire Building	219,500	SF	6	10+ years	
	Storm Piping	Entire Building	219,500	SF	6	10+ years	
Pool Sys	stems						
	Pool Drain Piping	Mechanical Room	30	LF	6	10+ years	
	Pool Filtration System including Pump	Mechanical Room	1	EA	5	6-10 years	
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	7	10+ years	
	Pool Supply and Return Piping	Mechanical Room	80	LF	6	10+ years	
Pumps							
	Pumps - Sump-Simplex	Basement	1	EA	6	10+ years	No access to it but reported as being functional
Catego	ry : Room		В	uilding	: Main		

Location

Location

117A Counselor Office

Entire Building

Entire Building

Building: Main

Rank

6

6

UOM

EΑ

EΑ

Quantity

6

Recommend

10+ years

6-10 years

Recommend

6-10 years

6-10 years 6-10 years

6-10 years

6-10 years

Replacement Comments

Newly replaced

Replacement Comments

Campus Name: Senn HS Page: 7 of 95 Assessment Date: 07/18/2022

Quantity

700

11

700

3

UOM

SF

SF

EΑ

EΑ

SF

Rank

7

6

7

7





Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	117A Counselor Office	24	EA	7	6-10 years	
	Power Distribution	117A Counselor Office	26	EA	7	6-10 years	
	Storage/ Closet	117A Counselor Office	76	SF	7	6-10 years	
	Walls - Plaster/Drywall	117A Counselor Office	1,020	SF	7	6-10 years	
	Work SInk	117A Counselor Office	1	EA	7	10+ years	
	Ceiling - Lay-in	117D Counselor Office	110	SF	7	6-10 years	
	Doors - Transom Window	117D Counselor Office	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	117D Counselor Office	1	EA	7	10+ years	
	Floor - Tile	117D Counselor Office	110	SF	6	6-10 years	
	Lighting - Lay-in	117D Counselor Office	2	EA	7	6-10 years	Quantity changed to match current observations
	Power Distribution	117D Counselor Office	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	117D Counselor Office	485	SF	7	6-10 years	
	Ceiling - Lay-in	117F	100	SF	7	10+ years	
	Doors - Side-lite	117F	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117F	1	ĒΑ	7	10+ years	
	Floor - Tile	117F	100	SF	7	6-10 years	Changed to match current observations
	Lighting - Lay-in	117F	2	EA	7	10+ years	
	Power Distribution	117F	8	ΕA	7	10+ years	
	Walls - Plaster/Drywall	117F	430	SF	7	10+ years	
	Ceiling - Lay-in	117c	100	SF	7	10+ years	
	Doors - Side-lite	117c	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	117c	1	EA	7	10+ years	
	Floor - Tile	117c	100	SF	7	6-10 years	Changed to match current observations
	Lighting - Lay-in	117c	2	EA	7	10+ years	
	Power Distribution	117c	8	EA	7	10+ years	
	Walls - Plaster/Drywall	117c	430	SF	7	10+ years	
	Ceiling - Lay-in	123A Conference Room	280	SF	7	10+ years	
	Doors - Transom Window	123A Conference Room	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123A Conference Room	2	ĒΑ	7	10+ years	
	Floor - Tile	123A Conference Room	280	SF	7	10+ years	
	Lighting - Lay-in	123A Conference Room	6	EA	7	6-10 years	
	Power Distribution	123A Conference Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	123A Conference Room	630	SF	7	10+ years	
	Ceiling - Lay-in	123B Counselor Office	98	SF	6	6-10 years	Quantity changed to match current observations
	Doors - Transom Window	123B Counselor Office	11	SF	6	6-10 years	2200174410110
	Doors - Wood Doors inclu hw	123B Counselor Office	1	EA	7	6-10 years	
	Floor - Tile	123B Counselor Office	98	SF	7	10+ years	Newly replaced
	Lighting - Lay-in	123B Counselor Office	2	EA	7	6-10 years	Quantity changed to match current
	Power Distribution		6			•	observations
	Fower Distribution	123B Counselor Office	6	EA	6	6-10 years	Quantity changed to match current

Campus Name: Senn HS Page : 8 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Walls - Plaster/Drywall	123B Counselor Office	310	SF	7	6-10 years	Quantity changed to match current observations
	Ceiling - Lay-in	123C	120	SF	7	10+ years	
	Doors - Side-lite	123C	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123C	1	EA	7	10+ years	
	Floor - Tile	123C	120	SF	7	6-10 years	Changed to match current observations
	Lighting - Lay-in	123C	2	EA	7	10+ years	
	Power Distribution	123C	8	EA	7	10+ years	
	Walls - Plaster/Drywall	123C	430	SF	7	10+ years	
	Ceiling - Lay-in	123D	96	SF	7	10+ years	
	Doors - Side-lite	123D	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123D 123D	1	EA			
					7	10+ years	Charactel to meetals accorded
	Floor - Tile	123D	96	SF	7	6-10 years	Changed to match current observations
	Lighting - Lay-in	123D	2	EA	7	10+ years	
	Power Distribution	123D	6	EA	7	10+ years	
	Walls - Plaster/Drywall	123D	435	SF	7	10+ years	
	Ceiling - Lay-in	123E Reception Area	120	SF	7	10+ years	
	Doors - Transom Window	123E Reception Area	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123E Reception Area	1	EA	7	10+ years	
	Floor - Tile	123E Reception Area	120	SF	7	10+ years	
	Lighting - Lay-in	123E Reception Area	4	ĒΑ	7	10+ years	
	Power Distribution	123E Reception Area	6	ΕA	7	10+ years	
	Walls - Plaster/Drywall	123E Reception Area	400	SF	7	10+ years	
	Ceiling - Lay-in	125 - Dean's Office	210	SF	6	6-10 years	
	Doors - Side-lite	125 - Dean's Office	42	SF	6	10+ years	
	Doors - Store Front	125 - Dean's Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	125 - Dean's Office	2	EA	7	10+ years	
	Floor - Tile	125 - Dean's Office	210	SF	5	6-10 years	
	Lighting - Lay-in	125 - Dean's Office	12	EA	6	6-10 years	
	Power Distribution		11	EA	6		
		125 - Dean's Office		SF		6-10 years	
	Walls - Plaster/Drywall	125 - Dean's Office	657		7	6-10 years	
	AC Unit	129 discipline office	1	EA	7	6-10 years	
	Ceiling - Lay-in	129 discipline office	291	SF	6	10+ years	
	Doors - Wood Doors inclu hw	129 discipline office	2	EA	7	10+ years	
	Floor - Tile/Sheet	129 discipline office	291	SF	7	10+ years	
	Lighting - Lay-in	129 discipline office	6	EA	6	6-10 years	
	Power Distribution	129 discipline office	8	EA	7	10+ years	
	Storage/ Closet	129 discipline office	81	SF	5	10+ years	
	Walls - Plaster/Drywall	129 discipline office	595	SF	6	10+ years	
	Ceiling - Lay-in	130 South Office in Main Office	67	SF	6	10+ years	
	Ceiling - Lay-in	130 South Office in Main Office	8	SF	4	0-1 year	Broken





Category : Room			В	uilding	: Main		Building : Main							
_				_		Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments							
	Doors - Side-lite	130 South Office in Main Office	20	SF	7	10+ years								
	Doors - Wood Doors inclu hw	130 South Office in Main Office	1	EA	6	10+ years								
	Floor - Tile/Sheet	130 South Office in Main Office	75	SF	7	10+ years								
	Power Distribution	130 South Office in Main Office	2	EA	7	10+ years								
	Walls - Metal Panel	130 South Office in Main Office	103	SF	7	10+ years								
	Walls - Plaster/Drywall	130 South Office in Main Office	198	SF	6	10+ years								
	AC Unit	131 South Office in Main Office	1	EA	7	6-10 years								
	Ceiling - Lay-in	131 South Office in Main Office	117	SF	7	10+ years								
	Doors - Side-lite	131 South Office in Main Office	25	SF	7	10+ years								
	Doors - Wood Doors inclu hw	131 South Office in Main Office	2	EA	6	10+ years								
	Floor - Tile/Sheet	131 South Office in Main Office	117	SF	7	10+ years								
	Lighting - Lay-in	131 South Office in Main Office	4	EA	7	6-10 years								
	Power Distribution	131 South Office in Main Office	4	EA	7	10+ years								
	Walls - Plaster/Drywall	131 South Office in Main Office	377	SF	7	10+ years								
	AC Unit	131B South Office in Main Office	1	EA	7	6-10 years								
	Ceiling - Lay-in	131B South Office in Main Office	196	SF	7	10+ years								
	Doors - Side-lite	131B South Office in Main Office	50	SF	7	10+ years								
	Doors - Wood Doors inclu hw	131B South Office in Main Office	1	EA	7	10+ years								
	Floor - Tile/Sheet	131B South Office in Main Office	196	SF	7	10+ years								
	Lighting - Lay-in	131B South Office in Main Office	6	EA	7	6-10 years								
	Power Distribution	131B South Office in Main Office	5	EA	7	10+ years								
	Walls - Plaster/Drywall	131B South Office in Main Office	461	SF	6	10+ years								
	Walls - Plaster/Drywall	131B South Office in Main Office	6	SF	5	0-1 year	Cracking							
	AC Unit	132 Office in Main Office	1	EA	7	6-10 years								
	Ceiling - Lay-in	132 Office in Main Office	64	SF	6	10+ years								
	Ceiling - Lay-in	132 Office in Main Office	16	SF	4	0-1 year	Water damage							
	Doors - Side-lite	132 Office in Main Office	10	SF	7	10+ years								
	Doors - Wood Doors inclu hw	132 Office in Main Office	1	EA	7	10+ years								
	Floor - Tile/Sheet	132 Office in Main Office	80	SF	7	10+ years								
	Power Distribution	132 Office in Main Office	3	EA	7	10+ years								
	Walls - Metal Panel	132 Office in Main Office	80	SF	7	10+ years								
	Walls - Plaster/Drywall	132 Office in Main Office	165	SF	7	10+ years								
	AC Unit	133 Office in Main Office	1	EA	7	6-10 years								
	Ceiling - Lay-in	133 Office in Main Office	63	SF	6	10+ years								
	Ceiling - Lay-in	133 Office in Main Office	12	SF	4	0-1 year	Water damage							
	Doors - Side-lite	133 Office in Main Office	50	SF	7	10+ years	-							
	Doors - Wood Doors inclu hw	133 Office in Main Office	1	EA	7	10+ years								
	Floor - Tile/Sheet	133 Office in Main Office	75	SF	7	10+ years								
	Power Distribution	133 Office in Main Office	3	EA	7	10+ years								
	Walls - Metal Panel	133 Office in Main Office	77	SF	7	10+ years								
	Walls - Plaster/Drywall	133 Office in Main Office	161	SF	7	10+ years								
	AC Unit	134 Office in Main Office	1	EA	7	6-10 years								
	Ceiling - Lay-in	134 Office in Main Office	125	SF	6	10+ years								
	Doors - Side-lite	134 Office in Main Office	20	SF	7	10+ years								
						<i>j</i>								

Campus Name: Senn HS Page : 10 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	134 Office in Main Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	134 Office in Main Office	125	SF	7	10+ years	
	Lighting - Lay-in	134 Office in Main Office	4	EA	7	6-10 years	
	Power Distribution	134 Office in Main Office	6	EA	7	10+ years	
	Walls - Metal Panel	134 Office in Main Office	120	SF	7	10+ years	
	Walls - Plaster/Drywall	134 Office in Main Office	297	SF	6	10+ years	
	AC Unit	135 Main Office	3	EA	7	6-10 years	
	Ceiling - Lay-in	135 Main Office	940	SF	6	10+ years	
	Doors - Transom Window	135 Main Office	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	135 Main Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	135 Main Office	2	EA	6	10+ years	
	Floor - Tile/Sheet	135 Main Office	940	SF	7	10+ years	
	Lighting - Lay-in	135 Main Office	26	EA	6	6-10 years	
	Power Distribution	135 Main Office	10	EA	7	10+ years	
	Storage/ Closet	135 Main Office	55	SF	5	10+ years	Cracking in the wall
	Walls - Plaster/Drywall	135 Main Office	1,221	SF	6	10+ years	everening in the train
	AC Unit	135A North Office in Main Office	1	ĒΑ	7	6-10 years	
	Ceiling - Lay-in	135A North Office in Main Office	174	SF	6	10+ years	
	Doors - Wood Doors inclu hw	135A North Office in Main Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	135A North Office in Main Office	2	EΑ	6	10+ years	
	Floor - Carpet	135A North Office in Main Office	174	SF	6	6-10 years	
	Lighting - Lay-in	135A North Office in Main Office	6	EA	6	6-10 years	
	Power Distribution	135A North Office in Main Office	4	EA	6	10+ years	
	Storage/ Closet	135A North Office in Main Office	15	SF	5	10+ years	
	Walls - Plaster/Drywall	135A North Office in Main Office	490	SF	7	10+ years	
	Walls - Plaster/Drywall	135A North Office in Main Office	10	SF	5	0-1 year	Water damage by the sink
	Work Sink	135A North Office in Main Office	1	EA	7	10+ years	Water damage by the sink
	AC Unit	137 Principal's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	137 Principal's Office	338	SF	6	10+ years	
	Doors - Transom Window	137 Principal's Office	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	137 Principal's Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	137 Principal's Office	2	EA	6	10+ years	
	Floor - Tile/Sheet	137 Principal's Office	338	SF	7	10+ years	
	Lighting - Lay-in	137 Principal's Office	12	EA	7	6-10 years	
	Power Distribution	137 Principal's Office	8	EA	7	10+ years	
	Storage/ Closet	137 Principal's Office	15	SF	7	10+ years	
	Walls - Plaster/Drywall	137 Principal's Office	782	SF	6	10+ years	
	AC Unit	139 conference room	1	EA	7		
	Ceiling - Lay-in	139 conference room	465	SF	6	6-10 years 10+ years	
	Doors - Transom Window	139 conference room	11	SF	7	,	
	Doors - Wood Doors inclu hw		1	Sr EA	7	10+ years	
		139 conference room		SF	6	10+ years	
	Floor - Tile	139 conference room	465	_		10+ years	
	Lighting - Lay-in	139 conference room	8 8	EA EA	7 7	6-10 years	
	Power Distribution	139 conference room	8	EA	1	10+ years	

Campus Name: Senn HS Page : 11 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	139 conference room	676	SF	7	10+ years	Newly refinished
	Ceiling - Plaster/Drywall	190G Kitchen Office	155	SF	6	10+ years	•
	Doors - Wood Doors inclu hw	190G Kitchen Office	1	EΑ	6	10+ years	
	Floor - Tile	190G Kitchen Office	155	SF	7	10+ years	
	Lighting - Pendent/Surface	190G Kitchen Office	3	ĒΑ	7	6-10 years	
	Power Distribution	190G Kitchen Office	8	ΕA	7	10+ years	
	Storage/ Closet	190G Kitchen Office	145	SF	5	10+ years	
	Walls - Plaster/Drywall	190G Kitchen Office	583	SF	7	10+ years	Newly refinished
	AC Unit	196 teacher's lounge	1	EA	5	6-10 years	rtomy romnomed
	Ceiling - Lay-in	196 teacher's lounge	1,236	SF	6	10+ years	
	Ceiling - Lay-in	196 teacher's lounge	32	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	196 teacher's lounge	3	EA	6	10+ years	Water damage
	Floor - Terrazzo	196 teacher's lounge	236	SF	6	10+ years	
	Floor - Tile	196 teacher's lounge	932	SF	6	10+ years	
	Floor - Tile	196 teacher's lounge	100	SF	4	•	Missing/Cracking
				EA		1-2 years	wissing/Cracking
	Lighting - Lay-in	196 teacher's lounge	30		6	6-10 years	
	Power Distribution	196 teacher's lounge	2	EA	6	10+ years	
	Storage/ Closet	196 teacher's lounge	210	SF	5	6-10 years	
	Walls - Plaster/Drywall	196 teacher's lounge	1,600	SF	6	10+ years	NA
	Ceiling - Lay-in	196A office in teacher's lounge	24	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	196A office in teacher's lounge	52	SF	6	10+ years	
	Doors - Store Front	196A office in teacher's lounge	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	196A office in teacher's lounge	1	EA	6	10+ years	
	Floor - Terrazzo	196A office in teacher's lounge	76	SF	6	10+ years	
	Lighting - Lay-in	196A office in teacher's lounge	2	EA	7	6-10 years	
	Power Distribution	196A office in teacher's lounge	4	EA	6	10+ years	
	Walls - Plaster/Drywall	196A office in teacher's lounge	300	SF	6	10+ years	
	AC Unit	231 Health Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	231 Health Office	265	SF	6	10+ years	
	Doors - Transom Window	231 Health Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	231 Health Office	1	EA	7	10+ years	
	Floor - Wood	231 Health Office	265	SF	7	10+ years	
	Lighting - Lay-in	231 Health Office	6	EA	7	6-10 years	
	Power Distribution	231 Health Office	4	EΑ	6	10+ years	
	Walls - Plaster/Drywall	231 Health Office	768	SF	6	10+ years	
	Work Sink	231 Health Office	1	EA	7	10+ years	
	Ceiling - Lay-in	231A-1&2 Exam Rooms in Health	246	SF	6	10+ years	
		Office		٠.	·	.o. youro	
	Doors - Wood Doors inclu hw	231A-1&2 Exam Rooms in Health	2	EA	7	10+ years	
	200.0 11000 20010 III0I0 IIW	Office	_	_, 、	•	io. youro	
	Floor - Wood	231A-1&2 Exam Rooms in Health	246	SF	5	10+ years	
	11001 11000	Office	240	Oi	J	10+ years	
	Lighting - Lay-in	231A-1&2 Exam Rooms in Health	8	EA	6	6-10 years	Changed to match current
	Lighting - Lay-III	Office	0	LA	U	0-10 years	observation
		Office					ODSGIVATION

Campus Name: Senn HS Page : 12 of 95 Assessment Date: 07/18/2022





New Commans	Category : Room			В	uilding	: Main	•		
Power Distribution							Recommend		
Malls - Plaster/Dywall	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Walls - Plaster/Drywall		Power Distribution		4	EA	6	10+ years		
AC Unit		Walls - Plaster/Drywall		544	SF	6	10+ years		
Ceiling - Lay-in 231B Office 129 SF 6 10+ years Water damage Ceiling - Lay-in 231B Office 15 SF 7 10+ years Water damage Doors - Wood Doors inclu hw 231B Office 15 SF 7 10+ years 10+ years Floor - Wood 231B Office 12 SF 7 10+ years 8-6 -10 years 6-610 years 6-610 years 6-610 years 6-610 years 6-610 years 6-610 years 8-6 -10 years 9-6 -10 years <td></td> <td>AC Unit</td> <td></td> <td>1</td> <td>EA</td> <td>7</td> <td>6-10 years</td> <td></td>		AC Unit		1	EA	7	6-10 years		
Ceiling - Lay-in 2318 Office 15 SF 7 10+ years							•		
Doors - Transom Window 2318 Office 15 5F 7 10+ years							•	Water damage	
Doors - Wood Doors inclu hw 2318 Office 12							•	Trator damage	
Floor - Wood							•		
Lighting - Lay-in 231B Office 2 EA 6 6 10-1 years							•		
Power Distribution							•		
Walls - Plaster/Drywall		Power Distribution							
AC Unit							•		
Ceiling - Lay-in 258 Office 900 SF 7 10- years Doors - Transom Window 258 Office 11 SF 7 10+ years Doors - Wood Doors inclu hw 258 Office 1 EA 7 10+ years Floor - Wood 258 Office 15 EA 6 6-10 years Power Distribution 258 Office 10 EA 7 10+ years Power Distribution 258 Office 10 EA 7 10+ years Ceiling - Lay-in 258 Office 10 SF 6 10+ years Ceiling - Lay-in 258 Office 10 SF 6 10+ years Doors - Wood Doors inclu hw 258A Office 10 SF 7 10+ years Floor - Wood 258A Office 10 SF 7 10+ years Walls - Plaster/Drywall 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258B Office 4 EA 7 10+ years									
Doors - Transom Window 258 Office 11 SF 7 10 - years							•		
Doors - Wood Doors inclu hw 258 Office 1							•		
Floor - Wood							•		
Lighting - Lay-in 258 Office 15							•		
Power Distribution 258 Office 10 EA 7 10+ years Walls - Plaster/Drywall 258 Office 968 SF 7 10+ years Ceiling - Lay-in 258A Office 100 SF 6 10+ years Doors - Wood Doors inclu hw 258A Office 1 EA 7 10+ years Floor - Wood 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258B Office 40 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Doors - Wood Doors inclu hw 258B Office 120 SF 6 10+ years Lighting - Lay-in 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 378 SF 6 10+ years </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Floor was prepared to be waxed</td>								Floor was prepared to be waxed	
Walls - Plaster/Drywall 258 Office 968 SF 7 10+ years Celling - Lay-in 258A Office 100 SF 6 10+ years Floor - Wood Doors inclu hw 258A Office 100 SF 7 10+ years Lighting - Lay-in 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258A Office 4 EA 7 10+ years Ceiling - Lay-in 258B Office 400 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Floor - Wood Doors inclu hw 258B Office 1 EA 7 10+ years Floor - Wood Doors inclu hw 258B Office 120 SF 6 10+ years Power Distribution 258B Office 378 SF 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6							6-10 years		
Ceiling - Lay-in 258A Office 100 SF 6 10+ years Doors - Wood Doors inclu hw 258A Office 1 EA 7 10+ years Lighting - Lay-in 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258A Office 40 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Ceilor - Wood 258B Office 120 SF 7 10+ years Floor - Wood 258B Office 1 EA 7 10+ years Lighting - Lay-in 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor AV Room 1 EA 7 6-10 years <tr< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>,</td><td></td></tr<>							,		
Doors - Wood Doors inclu hw 258A Office 1 EA 7 10+ years Floor - Wood 258A Office 100 SF 7 10+ years Lighting - Lay-in 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258A Office 400 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Ploor - Wood 258B Office 1 EA 7 10+ years Floor - Wood 258B Office 120 SF 6 10+ years Lighting - Lay-in 258B Office 4 EA 7 6-10 years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor AV Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor AV Room 72 SF 6 10+ years <t< td=""><td></td><td>Walls - Plaster/Drywall</td><td></td><td></td><td></td><td>7</td><td>10+ years</td><td></td></t<>		Walls - Plaster/Drywall				7	10+ years		
Floor - Wood		Ceiling - Lay-in	258A Office	100	SF	6	10+ years		
Lighting - Lay-in 258A Office 4 EA 7 6-10 years Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258A Office 400 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Doors - Wood Doors inclu hw 258B Office 120 SF 7 10+ years Ploor - Wood 258B Office 120 SF 6 10+ years Ploor - Wood 258B Office 120 SF 6 10+ years Power Distribution 258B Office 120 SF 6 10+ years Power Distribution 258B Office 120 SF 6 10+ years Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years Power Distribution 258B Office 378 SF 6 10+ years Power Distribution 258B Office 378 SF 6 10+ years Power Distribution 258B Office 378 SF 6 10+ years Power Distribution 258B Office 378 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 1 EA 7 6-10 years Power Distribution 2000 Ploor AVV Room 1 EA 7 10+ years Power Distribution 2000 Ploor AVV Room 22 SF 6 10+ years Ploor - Tile 2000 Ploor AVV Room 22 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 9 EA 7 6-10 years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Power Distribution 2000 Ploor AVV Room 236 SF 6 10+ years Ploor Power Distribution 2000 Ploor AVV Room 2000 Ploor SP 8 6 10+ years Ploor Power Distribution 2000 Ploor Ploo		Doors - Wood Doors inclu hw	258A Office	1		7	10+ years		
Power Distribution 258A Office 4 EA 7 10+ years Walls - Plaster/Drywall 258A Office 400 SF 6 10+ years Ceiling - Lay-in 258B Office 120 SF 7 10+ years Floor - Wood 258B Office 1 EA 7 10+ years Lighting - Lay-in 258B Office 120 SF 6 10+ years Power Distribution 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 8 EA 6 10+ years Power Distribution 258B Office 8 EA 6 10+ years AC Unit 2nd Floor AV Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor AV Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor AV Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor AV Room 9 EA 7 6-10 ye		Floor - Wood	258A Office	100	SF	7	10+ years		
Power Distribution258A Office4EA710+ yearsWalls - Plaster/Drywall258A Office400SF610+ yearsCeiling - Lay-in258B Office120SF710+ yearsDoors - Wood Doors inclu hw258B Office1EA710+ yearsFloor - Wood258B Office1EA76-10 yearsLighting - Lay-in258B Office8EA610+ yearsPower Distribution258B Office8EA610+ yearsWalls - Plaster/Drywall258B Office378SF610+ yearsAC Unit2nd Floor A/V Room1EA76-10 yearsCeiling - Lay-in2nd Floor A/V Room72SF610+ yearsDoors - Wood Doors inclu hw2nd Floor A/V Room1EA710+ yearsFloor - Tile2nd Floor A/V Room72SF610+ yearsLighting - Pendent/Surface2nd Floor A/V Room9EA76-10 yearsPower Distribution2nd Floor A/V Room9EA76-10 yearsWalls - Plaster/Drywall2nd Floor A/V Room236SF610+ yearsAC Unit2nd Floor Control Room1EA710+ yearsDoors - Wood Doors inclu hw2nd Floor Control Room72SF610+ years		Lighting - Lay-in	258A Office	4	EA	7	6-10 years		
Walls - Plaster/Drywall258A Office400SF610+ yearsCeiling - Lay-in258B Office120SF710+ yearsDoors - Wood Doors inclu hw258B Office1EA710+ yearsFloor - Wood258B Office120SF610+ yearsLighting - Lay-in258B Office4EA76-10 yearsPower Distribution258B Office8EA610+ yearsWalls - Plaster/Drywall258B Office378SF610+ yearsAC Unit2nd Floor AV Room1EA76-10 yearsCeiling - Lay-in2nd Floor AV Room72SF610+ yearsDoors - Wood Doors inclu hw2nd Floor AV Room1EA710+ yearsFloor - Tile2nd Floor AV Room72SF610+ yearsLighting - Pendent/Surface2nd Floor AV Room9EA76-10 yearsPower Distribution2nd Floor AV Room9EA710+ yearsWalls - Plaster/Drywall2nd Floor AV Room236SF610+ yearsAC Unit2nd Floor Control Room1EA76-10 yearsCeiling - Lay-in2nd Floor Control Room72SF610+ yearsDoors - Wood Doors inclu hw2nd Floor Control Room1EA710+ years			258A Office	4	EA	7	•		
Ceiling - Lay-in 258B Office 120 SF 7 10+ years Doors - Wood Doors inclu hw 258B Office 1 1 EA 7 10+ years Floor - Wood 258B Office 120 SF 6 10+ years Lighting - Lay-in 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 1 EA 7 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 9 EA 7 6-10 years Walls - Plaster/Drywall 2nd Floor A/V Room 9 EA 7 6-10 years AC Unit 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor A/V Room 236 SF 6 10+ years Ceiling - Lay-in 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 6-10 years			258A Office	400	SF	6	•		
Doors - Wood Doors inclu hw Floor - Wood Flo							•		
Floor - Wood 258B Office 120 SF 6 10+ years Lighting - Lay-in 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 72 SF 6 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 72 SF 6 10+ years									
Lighting - Lay-in 258B Office 4 EA 7 6-10 years Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 72 SF 6 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors Inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors Inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors Inclu hw 2nd Floor Control Room 1 EA 7 10+ years Poors - Wood Doors - Wood Doors Inclu hw 2nd Floor Control Room 2 20 20 20 20 20 20 20 20 20 20 20 20 2				-					
Power Distribution 258B Office 8 EA 6 10+ years Walls - Plaster/Drywall 258B Office 378 SF 6 10+ years AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 1 EA 7 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 9 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 6 EA 7 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 6-10 years							•		
Walls - Plaster/Drywall AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 1 EA 7 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 1 EA 7 6-10 years Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 1 EA 7 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years							•		
AC Unit 2nd Floor A/V Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 1 EA 7 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years							-		
Ceiling - Lay-in 2nd Floor A/V Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor A/V Room 1 EA 7 10+ years Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years		,					,		
Doors - Wood Doors inclu hw Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years The power Distribution 1 EA 7 6-10 years									
Floor - Tile 2nd Floor A/V Room 72 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years							-		
Lighting - Pendent/Surface 2nd Floor A/V Room 9 EA 7 6-10 years Power Distribution 2nd Floor A/V Room 6 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years							•		
Power Distribution2nd Floor A/V Room6EA710+ yearsWalls - Plaster/Drywall2nd Floor A/V Room236SF610+ yearsAC Unit2nd Floor Control Room1EA76-10 yearsCeiling - Lay-in2nd Floor Control Room72SF610+ yearsDoors - Wood Doors inclu hw2nd Floor Control Room1EA710+ years									
Walls - Plaster/Drywall 2nd Floor A/V Room 236 SF 6 10+ years AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years The policy of the po									
AC Unit 2nd Floor Control Room 1 EA 7 6-10 years Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years				-			-		
Ceiling - Lay-in 2nd Floor Control Room 72 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years							•		
Doors - Wood Doors inclu hw 2nd Floor Control Room 1 EA 7 10+ years									
•						-			
Floor - Tile 2nd Floor Control Room 72 SF 6 10+ vears							•		
		Floor - Tile	2nd Floor Control Room	72	SF	6	10+ years		

Campus Name: Senn HS Page : 13 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	2nd Floor Control Room	1	EA	6	6-10 years			
	Power Distribution	2nd Floor Control Room	6	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor Control Room	236	SF	6	10+ years			
	Ceiling - Splined	325A - Practice Room	85	SF	6	10+ years			
	Doors - Wood Doors inclu hw	325A - Practice Room	1	EA	7	10+ years			
	Floor - Wood	325A - Practice Room	85	SF	7	10+ years			
	Lighting - Pendent/Surface	325A - Practice Room	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	325A - Practice Room	135	SF	6	10+ years			
	Ceiling - Splined	325B - Practice Room	85	SF	6	10+ years			
	Doors - Wood Doors inclu hw	325B - Practice Room	1	EA	6	10+ years			
	Floor - Wood	325B - Practice Room	85	SF	6	10+ years			
	Lighting - Pendent/Surface	325B - Practice Room	2	EA	6	6-10 years			
	Power Distribution	325B - Practice Room	2	EA	7	10+ years			
	Walls - Plaster/Drywall	325B - Practice Room	135	SF	6	10+ years			
	Ceiling - Splined	325C - Practice Room	85	SF	6	10+ years			
	Doors - Wood Doors inclu hw	325C - Practice Room	1	EA	6	10+ years			
	Floor - Wood	325C - Practice Room	85	SF	6	10+ years			
	Lighting - Pendent/Surface	325C - Practice Room	1	EA	7	6-10 years			
	Power Distribution	325C - Practice Room	1	EA	7	10+ years			
	Walls - Plaster/Drywall	325C - Practice Room	135	SF	6	10+ years			
	Ceiling - Plaster/Drywall	325D - Practice Room	85	SF	6	10+ years			
	Doors - Wood Doors inclu hw	325D - Practice Room	1	EA	6	10+ years			
	Floor - Wood	325D - Practice Room	85	SF	6	10+ years			
	Lighting - Pendent/Surface	325D - Practice Room	1	EA	7	6-10 years			
	Power Distribution	325D - Practice Room	2	EA	7	10+ years			
	Walls - Plaster/Drywall	325D - Practice Room	135	SF	6	10+ years			
	AC Unit	371 Students Services	1	EA	7	6-10 years			
	Ceiling - Lay-in	371 Students Services	698	SF	6	10+ years			
	Ceiling - Lay-in	371 Students Services	42	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	371 Students Services	_ 1	EA	7	10+ years			
	Floor - Wood	371 Students Services	740	SF	6	10+ years			
	Lighting - Lay-in	371 Students Services	21	EA	7	6-10 years			
	Power Distribution	371 Students Services	4	EA	7	10+ years			
	Walls - Plaster/Drywall	371 Students Services	1,420	SF	7	10+ years			
	AC Unit	373 - Principal's Office	1	EA	7	6-10 years			
	Ceiling - Lay-in	373 - Principal's Office	225	SF	6	10+ years			
	Doors - Wood Doors inclu hw	373 - Principal's Office	1	EA	7	10+ years			
	Floor - Tile	373 - Principal's Office	225	SF	7	10+ years			
	Lighting - Lay-in	373 - Principal's Office	3	EΑ	7	6-10 years			
	Power Distribution	373 - Principal's Office	4	EA	6	10+ years			
	Walls - Plaster/Drywall	373 - Principal's Office	711	SF	6	10+ years			
	Ceiling - Lay-in	375 - Special Education	219	SF	6	10+ years			
	Ceiling - Lay-in	375 - Special Education	6	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	375 - Special Education	1	EA	7	10+ years			

Campus Name: Senn HS Page : 14 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Main						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	375 - Special Education	225	SF	7	10+ years			
	Lighting - Lay-in	375 - Special Education	6	EA	7	6-10 years			
	Lighting - Metal Halide/Sodium Vapor	375 - Special Education	6	EA	7	6-10 years			
	Power Distribution	375 - Special Education	14	EA	6	10+ years			
	Walls - Plaster/Drywall	375 - Special Education	711	SF	6	10+ years			
	Ceiling - Lay-in	377A - Teacher's Lounge	650	SF	7	10+ years			
	Doors - Wood Doors inclu hw	377A - Teacher's Lounge	1	EA	7	10+ years			
	Floor - Tile/Sheet	377A - Teacher's Lounge	650	SF	7	10+ years			
	Lighting - Lay-in	377A - Teacher's Lounge	14	EΑ	7	6-10 years			
	Power Distribution	377A - Teacher's Lounge	18	EA	6	10+ years			
	Storage/ Closet	377A - Teacher's Lounge	65	SF	7	10+ years			
	Walls - Plaster/Drywall	377A - Teacher's Lounge	467	SF	7	10+ years			
	Work SInk	377A - Teacher's Lounge	1	EΑ	7	10+ years			
	AC Unit	377B - Office	1	EA	7	6-10 years			
	Ceiling - Lay-in	377B - Office	180	SF	6	10+ years			
	Doors - Wood Doors inclu hw	377B - Office	1	EA	7	10+ years			
	Floor - Tile	377B - Office	180	SF	5	10+ years	Damaged tiles throughout		
	Lighting - Pendent/Surface	377B - Office	6	ĒA	7	6-10 years			
	Power Distribution	377B - Office	20	EA	6	10+ years			
	Storage/ Closet	377B - Office	8	SF	5	10+ years			
	Walls - Plaster/Drywall	377B - Office	489	SF	6	10+ years			
	AC Unit	379 Office	1	EΑ	7	6-10 years			
	Ceiling - Lay-in	379 Office	576	SF	6	10+ years			
	Doors - Wood Doors inclu hw	379 Office	2	EA	7	10+ years			
	Floor - Carpet	379 Office	576	SF	6	6-10 years			
	Lighting - Lay-in	379 Office	15	EA	7	6-10 years			
	Power Distribution	379 Office	17	EΑ	6	10+ years			
	Storage/ Closet	379 Office	22	SF	5	10+ years			
	Walls - Plaster/Drywall	379 Office	1,217	SF	6	10+ years			
	Ceiling - Lay-in	379A - Office	164	SF	6	10+ years			
	Ceiling - Lay-in	379A - Office	12	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	379A - Office	1	EA	7	10+ years	vvator damago		
	Floor - Carpet	379A - Office	176	SF	6	6-10 years			
	Lighting - Lay-in	379A - Office	4	EA	7	6-10 years			
	Power Distribution	379A - Office	6	EA	6	10+ years			
	Walls - Plaster/Drywall	379A - Office	531	SF	6	10+ years			
	AC Unit	379B - Office	1	EA	7	6-10 years			
	Ceiling - Lay-in	379B - Office	180	SF	6	10+ years			
	Doors - Wood Doors inclu hw	379B - Office	100	EA	6	10+ years			
	Floor - Carpet	379B - Office	180	SF	6	•			
	Lighting - Lay-in	379B - Office	160	EA	7	6-10 years			
		379B - Office				6-10 years			
	Power Distribution Walls - Plaster/Drywall	379B - Office	6 489	EA SF	6 6	10+ years			
	Ceiling - Plaster/Drywall	Gym office	237	SF SF	6	10+ years			
	Ceiling - Flastel/Drywall	Gym onice	237	SF	О	10+ years			

Campus Name: Senn HS Page : 15 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		on Gerwood Avenoe, Onedgo, ie ooooo
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Gym office	1	EA	6	10+ years	
	Floor - Wood	Gym office	237	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym office	4	EA	7	6-10 years	
	Power Distribution	Gym office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym office	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym office	30	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	Kitchenette	90	SF	7	10+ years	
	Floor - Tile	Kitchenette	90	SF	7	10+ years	
	Lighting - Lay-in	Kitchenette	2	EA	7	10+ years	
	Power Distribution	Kitchenette	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchenette	300	SF	7	10+ years	
	Work SInk	Kitchenette	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Pool Office	65	SF	6	10+ years	
	Doors - Steel Doors incl hw	Pool Office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Pool Office	65	SF	7	10+ years	
	Lighting - Pendent/Surface	Pool Office	1	EA	5	1-2 years	No light switch
	Power Distribution	Pool Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Pool Office	322	SF	6	10+ years	
Auditoriu	um & Theater						
	Ceiling - Exposed	180 Harold Ramis Theatre	1,311	SF	6	10+ years	
	Doors - Transom Window	180 Harold Ramis Theatre	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	180 Harold Ramis Theatre	2	ĒΑ	7	10+ years	
	Floor - Tile	180 Harold Ramis Theatre	1,311	SF	6	10+ years	
	Lighting - Pendent/Surface	180 Harold Ramis Theatre	26	ĒA	6	6-10 years	
	Stage	180 Harold Ramis Theatre	334	SF	6	10+ years	
	Stage Curtain	180 Harold Ramis Theatre	2	EΑ	5	6-10 years	
	Stage Lighting System	180 Harold Ramis Theatre	1	EA	5	6-10 years	
	Stage-Stairs - Wood	180 Harold Ramis Theatre	18	LF	6	10+ years	
	Storage/ Closet	180 Harold Ramis Theatre	207	SF	5	10+ years	
	Walls - Plaster/Drywall	180 Harold Ramis Theatre	2,802	SF	6	10+ years	
	Balcony Seating	1st Floor	218	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	13,161	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	22	EΑ	7	10+ years	
	Floor - Carpet	1st Floor	3,630	SF	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor	7,631	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	1,900	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	51	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	79	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	36	EA	7	6-10 years	
	Main Floor Seating	1st Floor	557	ĒΑ	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	1,963	SF	6	10+ years	
	Stage Curtain	1st Floor	9	EA	7	6-10 years	Changed to match current

Campus Name: Senn HS Page : 16 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	70	LF	6	10+ years	Covered with carpet
	Walls - Plaster/Drywall	1st Floor	10,572	SF	6	10+ years	
_Gvmnas	ia						
	Bleacher Seating	Small Gym	120	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Small Gym	8,535	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Small Gym	5	ĒΑ	7	10+ years	
	Floor - Wood	Small Gym	8,535	SF	7	10+ years	
	Lighting - Pendent/Surface	Small Gym	40	ĒΑ	7	10+ years	
	Scoreboards	Small Gym	1	EA	7	10+ years	
	Storage/ Closet	Small Gym	169	SF	7	10+ years	
	Walls - Plaster/Drywall	Small Gym	2,200	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	189 - Servery (on plan)	2,400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	189 - Servery (on plan)	86	SF	6	10+ years	Changed to match current observations
	Doors - Wood Doors inclu hw	189 - Servery (on plan)	13	EA	6	10+ years	
	Floor - Tile Quarry	189 - Servery (on plan)	2,486	SF	6	10+ years	
	Lighting - Lay-in	189 - Servery (on plan)	56	EA	6	6-10 years	
	Walls - Concrete Block	189 - Servery (on plan)	430	SF	7	10+ years	
	Walls - Masonry	189 - Servery (on plan)	900	SF	6	10+ years	
	Walls - Plaster/Drywall	189 - Servery (on plan)	620	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	189 - Servery (on plan)	230	SF	6	10+ years	
	Ceiling - Lay-in	189A - Kitchen (on plan)	1,240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	189A - Kitchen (on plan)	585	SF	6	10+ years	
	Doors - Steel Doors incl hw	189A - Kitchen (on plan)	2	EA	6	10+ years	
	Doors - Transom Window	189A - Kitchen (on plan)	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	189A - Kitchen (on plan)	2	EA	6	10+ years	
	Floor - Terrazzo	189A - Kitchen (on plan)	500	SF	6	10+ years	
	Floor - Tile Quarry	189A - Kitchen (on plan)	1,325	SF	6	10+ years	
	Lighting - Pendent/Surface	189A - Kitchen (on plan)	36	EA	6	6-10 years	
	Storage/ Closet	189A - Kitchen (on plan)	200	SF	5	10+ years	
	Walls - Concrete Block	189A - Kitchen (on plan)	430	SF	6	10+ years	
	Walls - Masonry	189A - Kitchen (on plan)	1,740	SF	6	10+ years	
	Walls - Plaster/Drywall	189A - Kitchen (on plan)	228	SF	6	10+ years	
	Ceiling - Splined	190H - Dishwashing	370	SF	6	10+ years	
	Ceiling - Splined	190H - Dishwashing	30	SF	4	0-1 year	Water damage/Missing
	Floor - Terrazzo	190H - Dishwashing	400	SF	5	10+ years	
	Lighting - Pendent/Surface	190H - Dishwashing	10	ĒΑ	7	6-10 years	
	Walls - Masonry	190H - Dishwashing	500	SF	6	10+ years	
		•			4	,	Cracking
	Walls - Masonry	190H - Dishwashing	200	SF		0-1 year	Cracking

Campus Name: Senn HS Page : 17 of 95 Assessment Date: 07/18/2022





Category : Room			В	uilding	: Main			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	190H - Dishwashing	175	SF	6	10+ years		
	Ceiling - Lay-in	190J - Canteen	342	SF	6	10+ years		
	Ceiling - Lay-in	190J - Canteen	18	SF	4	0-1 year	Broken	
	Doors - Wood Doors inclu hw	190J - Canteen	4	EA	6	10+ years		
	Floor - Tile Quarry	190J - Canteen	360	SF	6	10+ years		
	Lighting - Lay-in	190J - Canteen	9	EA	6	6-10 years		
	Serving Line	190J - Canteen	32	LF	7	10+ years		
	Walls - Plaster/Drywall	190J - Canteen	900	SF	6	10+ years	Changed to match current observations	
Library								
	AC Unit	225 Library	3	EA	7	6-10 years		
	Casework	225 Library	676	LF	6	10+ years		
	Ceiling - Lay-in	225 Library	3,894	SF	7	10+ years		
	Ceiling - Lay-in	225 Library	28	SF	4	0-1 year	Water damage	
	Doors - Transom Window	225 Library	24	SF	6	10+ years		
	Doors - Wood Doors inclu hw	225 Library	6	EA	7	10+ years		
	Floor - Tile	225 Library	3,922	SF	7	10+ years		
	Lighting - Lay-in	225 Library	109	EA	6	6-10 years		
	Lighting - Pendent/Surface	225 Library	12	EΑ	7	6-10 years		
	Storage/ Closet	225 Library	75	SF	7	10+ years		
	Walls - Plaster/Drywall	225 Library	4,546	SF	6	10+ years		
Locker/S	Shower Room							
	Accessories	1st Floor Mens Pool	694	SF	7	6-10 years		
	Benches, ped mounted	1st Floor Mens Pool	36	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor Mens Pool	694	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor Mens Pool	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Mens Pool	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Mens Pool	694	SF	7	10+ years		
	Floor Drain	1st Floor Mens Pool	5	EA	7	10+ years		
	Hand Dryer	1st Floor Mens Pool	5	EA	7	6-10 years		
	Lavatory	1st Floor Mens Pool	2	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor Mens Pool	17	EΑ	7	10+ years		
	Partitions	1st Floor Mens Pool	1	EA	7	10+ years		
	Showers	1st Floor Mens Pool	4	EA	7	10+ years	Quantity changed to match current observations	
	Student Lockers - One Tier	1st Floor Mens Pool	18	EA	7	10+ years		
	Student Lockers - Two Tier	1st Floor Mens Pool	48	EA	7	10+ years		
	Urinals	1st Floor Mens Pool	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor Mens Pool	1,460	SF	7	10+ years		
	Water Closet	1st Floor Mens Pool	1	ĒΑ	7	10+ years		
	Accessories	1st Floor Womens Pool	967	SF	7	6-10 years		
	Benches, ped mounted	1st Floor Womens Pool	132	LF	7	10+ years	Changed to match current	
	/1				-	· ,	3	

Campus Name: Senn HS Page : 18 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					_		observations and
	Ceiling - Plaster/Drywall	1st Floor Womens Pool	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Womens Pool	567	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Womens Pool	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Womens Pool	967	SF	7	10+ years	
	Floor Drain	1st Floor Womens Pool	3	EA	7	10+ years	
	Hand Dryer	1st Floor Womens Pool	5	EA	7	6-10 years	Quantity changed to match current observations
	Lavatory	1st Floor Womens Pool	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Womens Pool	17	EA	7	10+ years	
	Partitions	1st Floor Womens Pool	2	EA	7	10+ years	
	Showers	1st Floor Womens Pool	4	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor Womens Pool	26	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor Womens Pool	48	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Womens Pool	2,200	SF	7	10+ years	
	Water Closet	1st Floor Womens Pool	2	ĒΑ	7	10+ years	
	Accessories	Unisex inside small gym office	115	SF	7	6-10 years	
	Benches, ped mounted	Unisex inside small gym office	4	ĹF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex inside small gym office	115	SF	7	10+ years	
	Doors - Steel Doors incl hw	Unisex inside small gym office	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex inside small gym office	115	SF	7	10+ years	
	Floor Drain	Unisex inside small gym office	2	EΑ	7	10+ years	
	Lavatory	Unisex inside small gym office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex inside small gym office	2	ĒΑ	7	6-10 years	
	Partitions	Unisex inside small gym office	1	EA	7	10+ years	
	Showers	Unisex inside small gym office	1	EA	7	6-10 years	
	Walls - Concrete Block	Unisex inside small gym office	140	SF	7	10+ years	
	Walls - Plaster/Drywall	Unisex inside small gym office	304	SF	7	10+ years	
	Walls - Plaster/Drywall	Unisex inside small gym office	6	SF	4	0-1 year	Cracking
	Water Closet	Unisex inside small gym office	1	EA	7	10+ years	Graciang
	Accessories	Unisex pool	84	SF	7	6-10 years	
	Benches, ped mounted	Unisex pool	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex pool	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex pool	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex pool	84	SF	7	10+ years	
	Floor Drain	Unisex pool	1	EA	7	10+ years	
	Hand Dryer	Unisex pool	1	EΑ	7	6-10 years	
	Lavatory	Unisex pool	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex pool	2	EA	7	10+ years	
	Showers	Unisex pool	1	EA	7	10+ years	
	Student Lockers - One Tier	Unisex pool	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex pool	342	SF	7	10+ years	
	Water Closet	Unisex pool	1	EA	7	10+ years	
	TTALOI OIOGOL	Offisox pool	'		,	TOT years	

Campus Name: Senn HS Page : 19 of 95 Assessment Date: 07/18/2022



Nicholas Senn High School 5900 N Glenwood AVENUE, Chicago, IL 60660 **Building: Main** Category : Room

em - Type ultipurpose Room C Unit	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ıltipurpose Room		Quantity	UOM	Kank	Replacement	Comments
						Commonto
.C Unit						
	115 Social Center	1	EA	7	6-10 years	Quantity changed to match current observations
eiling - Lay-in	115 Social Center	1,344	SF	7	10+ years	
oors - Transom Window	115 Social Center	22	SF	7	10+ years	
loors - Wood Doors inclu hw	115 Social Center	2	EA	7	10+ years	Quantity changed to match current observations
loor - Tile	115 Social Center	1,344		7	10+ years	
ighting - Lay-in	115 Social Center	24		7	10+ years	
torage/ Closet	115 Social Center	8		7	10+ years	
Valls - Plaster/Drywall	115 Social Center	1,410	SF	7	10+ years	
ceiling - Lay-in	190 Cafeteria	11,434	SF	6	10+ years	
	190 Cafeteria	64	SF	4		Water stains
Poors - Wood Doors inclu hw	190 Cafeteria	10	ĒΑ	6		
		-		-		
				_		Changed to match current
		_			•	observations
valis - Plaster/Drywali	190 Careteria	5,000	SF	6	10+ years	
oors - Wood Doors inclu hw	261B	1	EA	7	10+ years	
inishes	261B	105	SF	5		
Vindow AC Unit	261B	1	EA	7	6-10 years	
/ Service Rooms						
	117F	135	SF	7	10+ years	
			SF			
•						
					-	
					,	
	•				-	
					•	
lechanical/ Service Rooms	Pool Mechanical Room and Laundry	485	SF	7	10+ years	
iight view of the control of the con	ghting - Lay-in orage/ Closet alls - Plaster/Drywall eiling - Lay-in eiling - Lay-in eiling - Lay-in cors - Wood Doors inclu hw oor - Terrazzo oor - Tile Quarry ghting - Lay-in orage/ Closet falls - Plaster/Drywall cors - Wood Doors inclu hw nishes indow AC Unit Service Rooms orage Room r Intake Plenums orage Room unitor's Closet echanical/ Service Rooms orage Room orage Room echanical/ Service Rooms orage Room echanical/ Service Rooms orage Room	ghting - Lay-in orage/ Closet alls - Plaster/Drywall eiling - Lay-in orose - Wood Doors inclu hw orose - Closet alls - Plaster/Drywall eiling - Lay-in bors - Wood Doors inclu hw oor - Terrazzo oor - Tile Quarry ghting - Lay-in orage/ Closet alls - Plaster/Drywall elling - Lay-in orage/ Closet 190 Cafeteria 19	ghting - Lay-in 115 Social Center 24 orage/ Closet 115 Social Center 8 alls - Plaster/Drywall 115 Social Center 1,410 alling - Lay-in 190 Cafeteria 11,434 eiling - Lay-in 190 Cafeteria 64 oors - Wood Doors inclu hw 190 Cafeteria 200 oor - Tile Quarry 190 Cafeteria 220 oor - Tile Quarry 190 Cafeteria 220 orage/ Closet 190 Cafeteria 220 alls - Plaster/Drywall 190 Cafeteria 5,000 alls - Plaster/Drywall 190 Cafeteria 5,000 cors - Wood Doors inclu hw 261B 1 nishes 261B 1 orage Room 1 1 orage Rooms 11TE 15 orage Room 117E 135 orage Room 118A - South 239 orage Room 131A Vault in Main Office 176 nitor's Closet 1st Floor 1,150 echanical/ Service Rooms 1st Floor <t< td=""><td>ghting - Lay-in orage/ Closet 115 Social Center 24 EA orage/ Closet 115 Social Center 8 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 190 Cafeteria 11,434 SF alls - Plaster/Drywall 190 Cafeteria 11,434 SF alls - Plaster/Drywall 190 Cafeteria 10 EA A SF alls - Plaster/Drywall 190 Cafeteria 10 EA A SF alls - Plaster/Drywall 190 Cafeteria 11,300 SF alls - Plaster/Drywall 190 Cafeteria 120 SF alls - Plaster/Drywall 190 Cafeteria 120 SF alls - Plaster/Drywall 190 Cafeteria 5,000 SF alls - Plaster/Drywall 190 Cafeteria 1,00 SF alls - Plaster/Drywall 1,00 SF alls - Plaster/Drywall 1,00 S</td><td>ghting - Lay-in 115 Social Center 24 EA 7 orage/ Closet 115 Social Center 8 SF 7 alls - Plaster/Drywall 115 Social Center 1,410 SF 7 alling - Lay-in 190 Cafeteria 11,434 SF 6 alors - Wood Doors inclu hw 190 Cafeteria 64 SF 4 bors - Wood Doors inclu hw 190 Cafeteria 200 SF 6 oor - Tile Quarry 190 Cafeteria 11,300 SF 6 ghting - Lay-in 190 Cafeteria 120 SF 6 orage/ Closet 190 Cafeteria 120 SF 7 falls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 Doors - Wood Doors inclu hw 261B 1 EA 7 alls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 Doors - Wood Doors inclu hw 261B 1 EA 7 alls - Plaster/Drywall 190 Cafeteria 5,000 SF</td></t<> <td>ghting - Lay-in 115 Social Center 24 EA 7 10+ ýears orage/ Closet 115 Social Center 8 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Lay-in 190 Cafeteria 1,434 SF 6 10+ years alls - Lay-in 190 Cafeteria 64 SF 4 0-1 year oor - Terrazzo 190 Cafeteria 10 EA 6 10+ years oor - Terrazzo 190 Cafeteria 200 SF 6 10+ years oor - Tile Quarry 190 Cafeteria 11,300 SF 6 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years alls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage Room 117E 135 SF 5 10+ years orage Room 117E 135 SF 7 10+ years orage Room 117E 135 SF 7 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 15 Floor 14 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 25 SF 5 10+ years orage</td>	ghting - Lay-in orage/ Closet 115 Social Center 24 EA orage/ Closet 115 Social Center 8 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 115 Social Center 1.410 SF alls - Plaster/Drywall 190 Cafeteria 11,434 SF alls - Plaster/Drywall 190 Cafeteria 11,434 SF alls - Plaster/Drywall 190 Cafeteria 10 EA A SF alls - Plaster/Drywall 190 Cafeteria 10 EA A SF alls - Plaster/Drywall 190 Cafeteria 11,300 SF alls - Plaster/Drywall 190 Cafeteria 120 SF alls - Plaster/Drywall 190 Cafeteria 120 SF alls - Plaster/Drywall 190 Cafeteria 5,000 SF alls - Plaster/Drywall 190 Cafeteria 1,00 SF alls - Plaster/Drywall 1,00 SF alls - Plaster/Drywall 1,00 S	ghting - Lay-in 115 Social Center 24 EA 7 orage/ Closet 115 Social Center 8 SF 7 alls - Plaster/Drywall 115 Social Center 1,410 SF 7 alling - Lay-in 190 Cafeteria 11,434 SF 6 alors - Wood Doors inclu hw 190 Cafeteria 64 SF 4 bors - Wood Doors inclu hw 190 Cafeteria 200 SF 6 oor - Tile Quarry 190 Cafeteria 11,300 SF 6 ghting - Lay-in 190 Cafeteria 120 SF 6 orage/ Closet 190 Cafeteria 120 SF 7 falls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 Doors - Wood Doors inclu hw 261B 1 EA 7 alls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 Doors - Wood Doors inclu hw 261B 1 EA 7 alls - Plaster/Drywall 190 Cafeteria 5,000 SF	ghting - Lay-in 115 Social Center 24 EA 7 10+ ýears orage/ Closet 115 Social Center 8 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Plaster/Drywall 115 Social Center 1,410 SF 7 10+ years alls - Lay-in 190 Cafeteria 1,434 SF 6 10+ years alls - Lay-in 190 Cafeteria 64 SF 4 0-1 year oor - Terrazzo 190 Cafeteria 10 EA 6 10+ years oor - Terrazzo 190 Cafeteria 200 SF 6 10+ years oor - Tile Quarry 190 Cafeteria 11,300 SF 6 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years orage/ Closet 190 Cafeteria 120 SF 7 10+ years alls - Plaster/Drywall 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage/ Closet 190 Cafeteria 5,000 SF 6 10+ years orage Room 117E 135 SF 5 10+ years orage Room 117E 135 SF 7 10+ years orage Room 117E 135 SF 7 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 131A Vault in Main Office 176 SF 5 10+ years orage Room 15 Floor 14 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 15 Floor 15 SF 5 10+ years orage Room 25 SF 5 10+ years orage

Campus Name: Senn HS Page : 20 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pool & N	atatorium						
	Ceiling - Lay-in	118	1,607	SF	7	6-10 years	
	Ceiling - Lay-in	118	40	SF	5	1-2 years	Missing
	Ceiling - Plaster/Drywall	118	1,513	SF	7	10+ years	3
	Doors - Steel Doors incl hw	118	4	ĒΑ	7	6-10 years	
	Lighting - Metal Halide/ High Pressure	118	12	EA	7	6-10 years	
	Sodium					, , , , , , , , , , , , , , , , , , , ,	
	Pool Basin	118	1,513	SF	7	10+ years	
	Pool Deck	118	1,647	SF	7	10+ years	
	Pool Deck Drains	118	6	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	118	1,506	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	118	1,506	SF	7	10+ years	
Prep Ro	om Casework	350A - Prep Room	25	LF	7	10+ years	
	Ceiling - Lay-in	350A - Frep Room	286	SF	7	10+ years	
	Ceiling - Lay-in	350A - Prep Room	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	350A - Prep Room	1	EA	7	10+ years	Water damage
	Floor - Tile	350A - Prep Room	292	SF	7	10+ years	
	Lighting - Lay-in	350A - Prep Room	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	350A - Prep Room	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	350A - Prep Room	529	SF	7	10+ years	
	Work Sink	350A - Prep Room	1	EA	7	10+ years	
	Casework	352A Prep Room	27	LF	7	10+ years	
	Ceiling - Plaster/Drywall	352A Prep Room	131	SF	7	10+ years	
	Doors - Steel Doors incl hw	352A Prep Room	131	EA	7	10+ years	
	Floor - Tile	352A Prep Room	131	SF	7	10+ years	
	Lighting - Pendent/Surface	352A Prep Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	352A Prep Room	459	SF	7	•	
	Work Sink	352A Prep Room	459	EA	7	10+ years 10+ years	
	Casework	356A Prep Room	36	LF	7	10+ years	
	Ceiling - Lay-in	356A Prep Room	216	SF	7	10+ years	
	Doors - Steel Doors incl hw	356A Prep Room	1	EA	7	10+ years	
	Floor - Tile	356A Prep Room	216	SF	7	•	
		356A Prep Room	4	EA	7	10+ years 6-10 years	
	Lighting - Lay-in Walls - Plaster/Drywall	356A Prep Room	657	SF	7	10+ years	
	Work Sink	356A Prep Room					
	Casework	356A Prep Room 358A	1 36	EA LF	7 7	10+ years	
	Casework Ceiling - Plaster/Drywall	358A	216	SF	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	358A 358A			7	•	
		358A 358A	1 216	EA SF		10+ years	
	Floor - Tile			SF EA	7 7	10+ years	
	Lighting - Pendent/Surface	358A	4	SF	7 6	6-10 years	
	Walls - Plaster/Drywall	358A	657	3 F	О	10+ years	

Campus Name: Senn HS Page : 21 of 95 Assessment Date: 07/18/2022





Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	358A	1	EA	7	10+ years	
	Casework	364A Prep Room	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	364A Prep Room	228	SF	7	10+ years	
	Doors - Wood Doors inclu hw	364A Prep Room	1	EA	7	10+ years	
	Floor - Tile	364A Prep Room	228	SF	7	10+ years	
	Lighting - Pendent/Surface	364A Prep Room	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	364A Prep Room	639	SF	7	10+ years	
	Work Sink	364A Prep Room	1	EA	7	10+ years	
	Casework	366B	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	366B	144	SF	7	10+ years	
	Floor - Tile	366B	144	SF	7	10+ years	
	Lighting - Pendent/Surface	366B	1	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	366B	534	SF	7	10+ years	
	Work Sink	366B	1	ĒΑ	7	10+ years	
		3332	•		•	,	
Restroo	n						
	Accessories	125A Unisex Toilet in Dean's Office	69	SF	7	10+ years	
	Ceiling - Plaster/Drywall	125A Unisex Toilet in Dean's Office	69	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	125A Unisex Toilet in Dean's Office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	125A Unisex Toilet in Dean's Office	69	SF	6	10+ years	
	Hand Dryer	125A Unisex Toilet in Dean's Office	1	ĒΑ	7	10+ years	
	Lavatory	125A Unisex Toilet in Dean's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	125A Unisex Toilet in Dean's Office	1	EA	6	6-10 years	
	Partitions	125A Unisex Toilet in Dean's Office	1	EA	7	6-10 years	Changed to match current observations
	Walls - Plaster/Drywall	125A Unisex Toilet in Dean's Office	310	SF	7	6-10 years	
	Walls - Plaster/Drywall	125A Unisex Toilet in Dean's Office	6	SF	5	0-1 year	Water damage
	Water Closet	125A Unisex Toilet in Dean's Office	1	EA	6	6-10 years	water damage
	Accessories	137A Principal's Toilet	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	137A Principal's Toilet	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	137A Principal's Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	137A Principal's Toilet	15	SF	6	10+ years	
	Floor - Wood	137A Principal's Toilet	30	SF	7	10+ years	
	Lavatory	137A Principal's Toilet	1	EA	7	10+ years	
	Lighting - Pendent/Surface	137A Principal's Toilet	1	EA	7	6-10 years	
	Lighting - Fendent/Surface Lighting - Wall Mounted	137A Principal's Toilet	1	EA	7	6-10 years	
	Partitions	137A Principal's Toilet	1	EA	7	10+ years	
	Walls - Plaster/Drywall	137A Principal's Toilet	' - '	SF	6	-	
	•	•	304	Sr EA	7	10+ years	
	Water Closet	137A Principal's Toilet	1	SF		10+ years	
	Accessories	190E Womens Lockers off Kitchen	282	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	190E Womens Lockers off Kitchen	282		6	10+ years	
	Doors - Wood Doors inclu hw	190E Womens Lockers off Kitchen	3	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	190E Womens Lockers off Kitchen	282	SF	6	10+ years	
	Lavatory	190E Womens Lockers off Kitchen	1	EA	7	10+ years	

Campus Name: Senn HS Page : 22 of 95 Assessment Date: 07/18/2022





Category : Room		-	Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	190E Womens Lockers off Kitchen	3	EA	6	6-10 years				
	Lighting - Wall Mounted	190E Womens Lockers off Kitchen	1	EA	6	6-10 years				
	Student Lockers - One Tier	190E Womens Lockers off Kitchen	12	EA	7	10+ years				
	Walls - Plaster/Drywall	190E Womens Lockers off Kitchen	1,301	SF	7	10+ years	Newly refinished			
	Water Closet	190E Womens Lockers off Kitchen	1	EA	6	10+ years				
	Accessories	1st Floor Boys	558	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor Boys	558	SF	6	10+ years				
	Doors - Side-lite	1st Floor Boys	14	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	558	SF	7	10+ years				
	Floor Drain	1st Floor Boys	1	EA	7	10+ years				
	Hand Dryer	1st Floor Boys	1	EA	7	6-10 years				
	Lavatory	1st Floor Boys	4	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor Boys	8	EA	7	6-10 years				
	Partitions	1st Floor Boys	5	EA	7	10+ years				
	Urinals	1st Floor Boys	9	EA	7	10+ years				
	Walls - Masonry	1st Floor Boys	1,240	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor Boys	413	SF	7	10+ years				
	Water Closet	1st Floor Boys	5	EA	7	10+ years				
	Accessories	1st Floor South - Single User Toilet	42	SF	7	6-10 years				
		Room in Girls Toilet Room								
	Ceiling - Plaster/Drywall	1st Floor South - Single User Toilet	42	SF	7	10+ years				
	·	Room in Girls Toilet Room				•				
	Doors - Wood Doors inclu hw	1st Floor South - Single User Toilet	1	EA	6	10+ years				
		Room in Girls Toilet Room								
	Floor - Tile Ceramic/ Porcelain	1st Floor South - Single User Toilet	42	SF	6	10+ years				
		Room in Girls Toilet Room				•				
	Lavatory	1st Floor South - Single User Toilet	1	EA	7	10+ years				
		Room in Girls Toilet Room								
	Lighting - Pendent/Surface	1st Floor South - Single User Toilet	1	EA	7	6-10 years				
		Room in Girls Toilet Room				•				
	Walls - Concrete Block	1st Floor South - Single User Toilet	151	SF	6	10+ years				
		Room in Girls Toilet Room				-				
	Walls - Structural Glazed Tile	1st Floor South - Single User Toilet	151	SF	7	10+ years				
		Room in Girls Toilet Room				·				
	Water Closet	1st Floor South - Single User Toilet	1	EA	6	10+ years				
		Room in Girls Toilet Room				·				
	Accessories	1st Floor South at Auditorium	450	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor South at Auditorium	450	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor South at Auditorium	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor South at Auditorium	450	SF	6	10+ years				
	Floor Drain	1st Floor South at Auditorium	1	ĒΑ	7	10+ years				
	Lavatory	1st Floor South at Auditorium	3	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor South at Auditorium	8	EA	7	6-10 years				
						•				

Campus Name: Senn HS Page : 23 of 95 Assessment Date: 07/18/2022





Catego	egory : Room			Building : Main					
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	1st Floor South at Auditorium	6	EA	7	10+ years			
	Walls - Concrete Block	1st Floor South at Auditorium	1,260	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor South at Auditorium	1,260	SF	6	10+ years			
	Water Closet	1st Floor South at Auditorium	[′] 6	EA	7	10+ years			
	Accessories	1st Floor West	220	SF	7	6-10 years	Changed to match current		
						,	observations		
	Ceiling - Plaster/Drywall	1st Floor West	220	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor West	1	EA	7	10+ years	Quantity changed to match current		
	20010 11000 20010 111010 1111		•	`	•	.o. youro	observations		
	Floor - Tile Ceramic/ Porcelain	1st Floor West	220	SF	6	10+ years			
	Floor Drain	1st Floor West	1	EA	7	10+ years			
	Hand Dryer	1st Floor West	1	EΑ	7	6-10 years			
	Lavatory	1st Floor West	3	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor West	5	EA	7	6-10 years			
	Partitions	1st Floor West	4	EA	7	10+ years			
	Showers	1st Floor West	1	EA	7	10+ years			
	Walls - Concrete Block	1st Floor West	139	SF	7	-			
			418	SF		10+ years			
	Walls - Structural Glazed Tile	1st Floor West			7	10+ years			
	Water Closet	1st Floor West	4	EA SF	6	10+ years			
	Accessories	2nd Floor Boys East	477		7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor Boys East	477	SF	7	10+ years			
	Doors - Side-lite	2nd Floor Boys East	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor Boys East	1	EA	7	10+ years			
	Floor - Tile	2nd Floor Boys East	477	SF	7	10+ years	Changed to match current observation		
	Floor Drain	2nd Floor Boys East	1	EA	7	10+ years			
	Hand Dryer	2nd Floor Boys East	1	EA	7	6-10 years			
	Lavatory	2nd Floor Boys East	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor Boys East	9	EA	7	6-10 years			
	Partitions	2nd Floor Boys East	4	EΑ	7	10+ years			
	Urinals	2nd Floor Boys East	8	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor Boys East	351	SF	7	10+ years			
	Walls - Masonry	2nd Floor Boys East	351	SF	7	10+ years			
	Water Closet	2nd Floor Boys East	4	EA	7	10+ years			
	Accessories	2nd Floor Boys West	371	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor Boys West	371	SF	7	10+ years			
	Doors - Side-lite	2nd Floor Boys West	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor Boys West	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys West	371	SF	7	10+ years			
	Floor Drain	2nd Floor Boys West	1	EA	7	10+ years			
	Hand Dryer	2nd Floor Boys West	1	EA	7	6-10 years			
	Lavatory	2nd Floor Boys West	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor Boys West	5	EA	7	6-10 years			
	Partitions	2nd Floor Boys West	3	EA	7	10+ years			
	i aradons	Ziid i looi boys West	3		,	TOT years			

Campus Name: Senn HS Page : 24 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	2nd Floor Boys West	5	EA	7	10+ years	Changed to match current observation
	Walls - Concrete Block	2nd Floor Boys West	385	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Boys West	335	SF	7	10+ years	
	Water Closet	2nd Floor Boys West	3	EA	7	10+ years	
	Accessories	2nd Floor East	261	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor East	261	SF	7	10+ years	
	Doors - Transom Window	2nd Floor East	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor East	1	EA	7	10+ years	
	Floor - Tile	2nd Floor East	261	SF	6	10+ years	
	Hand Dryer	2nd Floor East	1	ĒΑ	7	6-10 years	
	Lavatory	2nd Floor East	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor East	5	EA	7	6-10 years	
	Partitions	2nd Floor East	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor East	606	SF	6	10+ years	
	Walls - Masonry	2nd Floor East	202	SF	6	10+ years	
	Water Closet	2nd Floor East	5	ĒA	7	10+ years	
	Accessories	2nd Floor East - Single User Toilet	42	SF	7	6-10 years	
		Room in Girls Toilet Room				,	
	Ceiling - Plaster/Drywall	2nd Floor East - Single User Toilet	42	SF	7	10+ years	
	,	Room in Girls Toilet Room				, , , , , ,	
	Doors - Wood Doors inclu hw	2nd Floor East - Single User Toilet	1	EA	6	10+ years	
		Room in Girls Toilet Room				, , , , ,	
	Floor - Concrete Epoxy/ Painted	2nd Floor East - Single User Toilet	42	SF	5	10+ years	
	, ,	Room in Girls Toilet Room				,	
	Lavatory	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	7	6-10 years	
	Partitions	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor East - Single User Toilet Room in Girls Toilet Room	139	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor East - Single User Toilet Room in Girls Toilet Room	139	SF	6	10+ years	
	Water Closet	2nd Floor East - Single User Toilet Room in Girls Toilet Room	1	EA	6	10+ years	
	Accessories	2nd Floor East Single User Unisex in Teachers Work Room	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor East Single User Unisex in Teachers Work Room	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor East Single User Unisex in Teachers Work Room	1	EA	7	10+ years	
	Floor - Tile	2nd Floor East Single User Unisex	56	SF	6	10+ years	

Campus Name: Senn HS Page : 25 of 95 Assessment Date: 07/18/2022



Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments in Teachers Work Room 2nd Floor East Single User Unisex EΑ Floor Drain 1 7 10+ years in Teachers Work Room 2nd Floor East Single User Unisex EΑ Lavatory 6 10+ years in Teachers Work Room Lighting - Pendent/Surface 2nd Floor East Single User Unisex 1 EΑ 7 6-10 years in Teachers Work Room Walls - Concrete Block 2nd Floor East Single User Unisex 299 SF 5 10+ years in Teachers Work Room Water Closet 2nd Floor East Single User Unisex FΑ 1 6 10+ years in Teachers Work Room Accessories 2nd Floor East Womens in Teachers 190 SF 7 6-10 years Work Room 2nd Floor East Womens in Teachers Ceiling - Plaster/Drywall 414 SF 5 10+ years Water damage through Work Room Doors - Wood Doors inclu hw 2nd Floor East Womens in Teachers FΑ 1 6 10+ years Work Room Floor - Tile 2nd Floor East Womens in Teachers 190 SF 6 10+ years Work Room 2nd Floor East Womens in Teachers Floor - Wood 224 SF 6 10+ years Work Room 2nd Floor East Womens in Teachers Floor Drain EΑ 7 10+ years Work Room 2nd Floor East Womens in Teachers FΑ 6 Lavatory 10+ years Work Room Lighting - Pendent/Surface 2nd Floor East Womens in Teachers 1 FΑ 6 6-10 years Work Room **Partitions** 2nd Floor East Womens in Teachers 2 EΑ 7 10+ years Work Room Walls - Concrete Block 2nd Floor East Womens in Teachers 288 SF 6 10+ years Work Room Walls - Masonry 2nd Floor East Womens in Teachers 288 SF 5 10+ vears Work Room Water Closet 2nd Floor East Womens in Teachers 2 FΑ 6 10+ years Work Room SF 7 Accessories 2nd Floor West 349 6-10 years Ceiling - Plaster/Drywall SF 2nd Floor West 349 7 10+ years Doors - Side-lite SF 7 2nd Floor West 11 10+ years Doors - Wood Doors inclu hw 2nd Floor West 1 EΑ 7 10+ years Floor - Tile SF 2nd Floor West 349 7 10+ years Floor Drain 2nd Floor West EΑ 7 10+ years 1 FΑ 7 Hand Drver 2nd Floor West 1 6-10 years Lavatory 2nd Floor West 2 EΑ 10+ years Lighting - Pendent/Surface 2nd Floor West 6 EΑ 7 6-10 years





Catego	ry : Room		Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Partitions	2nd Floor West	7	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor West	495	SF	6	10+ years		
	Walls - Masonry	2nd Floor West	165	SF	6	10+ years		
	Water Closet	2nd Floor West	7	EA	7	10+ years		
	Accessories	2nd Floor West - Multi User Toilet	121	SF	7	6-10 years		
		Room in Boys Toilet Room						
	Ceiling - Plaster/Drywall	2nd Floor West - Multi User Toilet	121	SF	7	10+ years		
		Room in Boys Toilet Room						
	Doors - Wood Doors inclu hw	2nd Floor West - Multi User Toilet	1	EA	7	10+ years		
		Room in Boys Toilet Room						
	Floor - Tile Ceramic/ Porcelain	2nd Floor West - Multi User Toilet	121	SF	7	10+ years		
		Room in Boys Toilet Room						
	Lavatory	2nd Floor West - Multi User Toilet	1	EA	7	10+ years		
		Room in Boys Toilet Room						
	Lighting - Pendent/Surface	2nd Floor West - Multi User Toilet	2	EA	7	6-10 years		
		Room in Boys Toilet Room						
	Partitions	2nd Floor West - Multi User Toilet	2	EA	7	10+ years		
		Room in Boys Toilet Room						
	Walls - Masonry	2nd Floor West - Multi User Toilet	265	SF	7	10+ years		
		Room in Boys Toilet Room			_			
	Walls - Plaster/Drywall	2nd Floor West - Multi User Toilet	265	SF	7	10+ years		
		Room in Boys Toilet Room	_		_			
	Water Closet	2nd Floor West - Multi User Toilet	2	EA	7	10+ years		
		Room in Boys Toilet Room	=0	0=	_	0.40		
	Accessories	2nd Floor West - Single User Toilet	50	SF	7	6-10 years		
	Osilian Disstan/Danasali	Room in Girls Toilet Room	50	0.	•	40		
	Ceiling - Plaster/Drywall	2nd Floor West - Single User Toilet	50	SF	6	10+ years		
	Dagge Wood Dagge include:	Room in Girls Toilet Room	4	Γ.	•	10	No cocce/door is domested	
	Doors - Wood Doors inclu hw	2nd Floor West - Single User Toilet	1	EA	6	10+ years	No access/door is damaged	
		Room in Girls Toilet Room					Judgement was made based on	
	Floor Congrete Engly/ Deinted	and Floor West Cingle Hear Toilet	50	SF	E	10	previous Assessment	
	Floor - Concrete Epoxy/ Painted	2nd Floor West - Single User Toilet Room in Girls Toilet Room	50	SF	5	10+ years		
	Loyotony		4	EA	6	10		
	Lavatory	2nd Floor West - Single User Toilet Room in Girls Toilet Room	1	EA	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor West - Single User Toilet	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	Room in Girls Toilet Room	ı	EA	,	6-10 years		
	Partitions	2nd Floor West - Single User Toilet	1	EA	7	10+ years		
	Partitions	Room in Girls Toilet Room	ı	EA	,	10+ years		
	Walls - Concrete Block	2nd Floor West - Single User Toilet	124	SF	6	10+ years		
	Walls - Collete block	Room in Girls Toilet Room	124	SI	O	10+ years		
	Walls - Structural Glazed Tile	2nd Floor West - Single User Toilet	124	SF	6	10+ years		
	vvans - Structural Glazeu Tile	Room in Girls Toilet Room	124	J-	O	TOT YEARS		
	Water Closet	2nd Floor West - Single User Toilet	1	EA	7	10+ years		
	Trator Olooti	Zild i looi Wost - Olligie Osei Tollet			,	TOT years		

Campus Name: Senn HS Page : 27 of 95 Assessment Date: 07/18/2022





Catego	ory : Room		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Room in Girls Toilet Room	-			<u>-</u>	
	Accessories	3rd Floor Boys East	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boys East	245	SF	5	10+ years	Water damage throughout
	Doors - Side-lite	3rd Floor Boys East	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boys East	1	EA	7	10+ years	
	Floor - Tile	3rd Floor Boys East	245	SF	7	10+ years	Changed to match current
	Floor Drain	3rd Floor Boys East	1	EA	4	10+ years	observation Cover is damaged
	Lavatory	3rd Floor Boys East	3	EΑ	7	10+ years	cover le damaged
	Lighting - Pendent/Surface	3rd Floor Boys East	5	EA	7	6-10 years	
	Partitions	3rd Floor Boys East	3	EA	7	10+ years	
	Urinals	3rd Floor Boys East	7	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor Boys East	392	SF	7	10+ years	
	Walls - Masonry	3rd Floor Boys East	392	SF	6	10+ years	
	Water Closet	3rd Floor Boys East		EA	_		
			3 245	SF	7	10+ years	
	Accessories	3rd Floor Boys West			7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boys West	245	SF	7	10+ years	
	Doors - Side-lite	3rd Floor Boys West	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boys West	1	EA	7	10+ years	
	Floor - Tile	3rd Floor Boys West	245	SF	7	10+ years	Changed to match current observation
	Floor Drain	3rd Floor Boys West	1	EA	7	10+ years	
	Lavatory	3rd Floor Boys West	2	EA	7	10+ years	Changed to match current observation
	Lighting - Pendent/Surface	3rd Floor Boys West	5	EA	5	6-10 years	Cover missing
	Partitions	3rd Floor Boys West	2	EA	7	10+ years	Changed to match current observation
	Urinals	3rd Floor Boys West	5	EA	7	10+ years	Changed to match current observation
	Walls - Concrete Block	3rd Floor Boys West	392	SF	7	10+ years	Observation
	Water Closet	3rd Floor Boys West	2	EA	7	10+ years	Changed to match current observation
	Accessories	3rd Floor East	231	SF	7	6-10 years	observation
	Ceiling - Plaster/Drywall	3rd Floor East	231	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor East	231	EA	7	10+ years	
	Floor - Tile	3rd Floor East	231	SF	7		
				EA		10+ years	Cavaria damanad
	Floor Drain	3rd Floor East	1		4	10+ years	Cover is damaged
	Hand Dryer	3rd Floor East	1	EΑ	7	6-10 years	
	Lavatory	3rd Floor East	2	EA	6	10+ years	Oi- mile mile sim m
	Lighting - Pendent/Surface	3rd Floor East	7	EΑ	5	6-10 years	Cover is missing
	Partitions	3rd Floor East	4	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor East	354	SF	7	10+ years	
	Walls - Masonry	3rd Floor East	354	SF	6	10+ years	
	Water Closet	3rd Floor East	4	EA	7	10+ years	

Campus Name: Senn HS Page : 28 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		В	uilding	: Main		, , ,
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Floor East - Single User Toilet	27	SF	7	6-10 years	
		Room in Boys Toilet Room					
	Ceiling - Plaster/Drywall	3rd Floor East - Single User Toilet	27	SF	7	10+ years	
		Room in Boys Toilet Room					
	Doors - Steel Doors incl hw	3rd Floor East - Single User Toilet	1	EA	7	10+ years	Changed to match current
		Room in Boys Toilet Room					observation
	Floor - Tile	3rd Floor East - Single User Toilet	27	SF	7	10+ years	
		Room in Boys Toilet Room			_		
	Lavatory	3rd Floor East - Single User Toilet	1	EA	7	10+ years	
	11.1.1.	Room in Boys Toilet Room			_	0.40	
	Lighting - Pendent/Surface	3rd Floor East - Single User Toilet	1	EA	5	6-10 years	Cover missing
	Linkson - Mall Marrata d	Room in Boys Toilet Room	4	_^	7	0.40	Oh and and the mantale assument
	Lighting - Wall Mounted	3rd Floor East - Single User Toilet	1	EA	7	6-10 years	Changed to match current
	Walls - Concrete Block	Room in Boys Toilet Room 3rd Floor East - Single User Toilet	90	SF	7	10	observation
	Walls - Concrete block	Room in Boys Toilet Room	80	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor East - Single User Toilet	160	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room in Boys Toilet Room	100	SI	,	10+ years	
	Water Closet	3rd Floor East - Single User Toilet	1	EA	7	10+ years	
	Water Closet	Room in Boys Toilet Room	'	LA	,	10+ years	
	Accessories	3rd Floor East - Single User Toilet	24	SF	7	6-10 years	
	710000001100	Room in Girls Toilet Room		O.	•	o io youro	
	Ceiling - Plaster/Drywall	3rd Floor East - Single User Toilet	24	SF	7	10+ years	
		Room in Girls Toilet Room		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	3rd Floor East - Single User Toilet	1	EA	6	10+ years	
		Room in Girls Toilet Room				•	
	Floor - Concrete Epoxy/ Painted	3rd Floor East - Single User Toilet	24	SF	5	10+ years	
		Room in Girls Toilet Room					
	Lavatory	3rd Floor East - Single User Toilet	1	EA	6	10+ years	
		Room in Girls Toilet Room					
	Lighting - Pendent/Surface	3rd Floor East - Single User Toilet	1	EA	7	6-10 years	
		Room in Girls Toilet Room					
	Walls - Concrete Block	3rd Floor East - Single User Toilet	119	SF	6	10+ years	
		Room in Girls Toilet Room			_		
	Walls - Masonry	3rd Floor East - Single User Toilet	60	SF	6	10+ years	
		Room in Girls Toilet Room			•	4.0	
	Water Closet	3rd Floor East - Single User Toilet	1	EA	6	10+ years	
	A	Room in Girls Toilet Room	004	C.E.	7	0.40	
	Accessories	3rd Floor West	231	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor West	231	SF EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor West	2	SF	6	10+ years	
	Floor - Tile Floor Drain	3rd Floor West 3rd Floor West	231	SF EA	6 7	10+ years 10+ years	
	Hand Dryer	3rd Floor West	1 1	EA	7	6-10 years	
	Hallu Diyel	Sid Fibbl West	ı	LA	'	0-10 years	

Campus Name: Senn HS Page : 29 of 95 Assessment Date: 07/18/2022





Category : Room

Item - Type					Recommend	
item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lavatory	3rd Floor West	2	EA	6	10+ years	
Lighting - Pendent/Surface	3rd Floor West	7	EΑ	7	6-10 years	
Partitions	3rd Floor West	4	EA	7	10+ years	
Walls - Concrete Block	3rd Floor West	354	SF	6	10+ years	
Walls - Structural Glazed Tile	3rd Floor West	354	SF	6	10+ years	
Water Closet	3rd Floor West	4	EΑ	6		
Accessories	3rd Floor West Unisex	24	SF	7		
	3rd Floor West Unisex	24	SF	6		
	3rd Floor West Unisex	1		7		
	3rd Floor West Unisex	24		7		
• •						
		· · · · · · · · · · · · · · · · · · ·		-	•	
		•				
					•	
					,	
Water Gloset	Station West Offisex	'	LA	,	10+ years	
y : Classroom		В	uilding	: Main		
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
m #158/160 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	1,822	SF	6	10+ years	
Chalk Board	1st Floor	10	LF	4	2-5 years	
Doors - Transom Window	1st Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Floor - Weight/ Fitness Room Floor Matting	1st Floor	1,822	SF	6		
	1st Floor	55	EA	6		
	1st Floor	20	LF	7		
Walls - Plaster/Drywall	1st Floor	1,120	SF	6	10+ years	
					10+ years	
					2-5 years	
Doors - Transom Window	1st Floor	18	SF			
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile		730	SF	7	10+ years	
Lighting - Lay-in	1st Floor	21	EA	6	6-10 years	
Marker Board	1st Floor	24	LF	7	6-10 years	
Walls - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
m #466 (Danca Boom)						
	1at Floor	4 400	C.E.		10	
Doors - Transom Window	1st Floor	18	SF EA	7 7	10+ years 10+ years	
Doors - Wood Doors inclu hw	1st Floor	2				
	Lighting - Pendent/Surface Partitions Walls - Concrete Block Walls - Structural Glazed Tile Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Lavatory Lighting - Pendent/Surface Walls - Masonry Walls - Plaster/Drywall Water Closet y: Classroom Item - Type m #158/160 (Regular Classroom) Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Weight/ Fitness Room Floor Matting Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #162 (Regular Classroom) Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #166 (Dance Room) Ceiling - Lay-in	Lighting - Pendent/Surface Partitions Walls - Concrete Block Walls - Structural Glazed Tile Water Closet Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Walls - Masory Walls - Plaster/Drywall Lighting - Lay-in Ceiling - Lay-in Chalk Board Water Closet Wood Doors inclu hw Sir Floor West Unisex Accessories Ard Floor West Unisex Ard Fl	Lighting - Pendent/Surface 3rd Floor West 7 Partitions 3rd Floor West 4 Walls - Concrete Block 3rd Floor West 354 Walls - Structural Glazed Tile 3rd Floor West 354 Water Closet 3rd Floor West 4 Accessories 3rd Floor West Unisex 24 Ceiling - Plaster/Drywall 3rd Floor West Unisex 24 Doors - Wood Doors inclu hw 3rd Floor West Unisex 1 Floor - Concrete Epoxyl Painted 3rd Floor West Unisex 24 Layatory 3rd Floor West Unisex 1 Lighting - Pendent/Surface 3rd Floor West Unisex 1 Hulls - Masonry 3rd Floor West Unisex 1 Walls - Plaster/Drywall 3rd Floor West Unisex 56 Walls - Plaster/Drywall 3rd Floor West Unisex 56 Water Closet 3rd Floor West Unisex 56 Water Closet 3rd Floor West Unisex 56 Water Closet 3rd Floor West Unisex 1 ****Drophymal 3rd Floor West Unisex 1 <td< td=""><td>Lighting - Pendent/Surface 3rd Floor West 7 EA Partitions 3rd Floor West 4 EA Walls - Concrete Block 3rd Floor West 354 SF Walls - Structural Glazed Tile 3rd Floor West 354 SF Walls - Structural Glazed Tile 3rd Floor West 34 SF Walls - Closet 3rd Floor West 4 EA Accessories 3rd Floor West Unisex 24 SF Ceiling - Plaster/Drywall 3rd Floor West Unisex 24 SF Doors - Wood Doors inclu hw 3rd Floor West Unisex 1 EA Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF Lavatory 3rd Floor West Unisex 1 EA Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Wa</td><td>Lighting - Pendent/Surface 3rd Floor West 7 EA 7 Partitions 3rd Floor West 4 EA 7 Walls - Concrete Block 3rd Floor West 354 SF 6 Walls - Structural Glazed Tile 3rd Floor West 34 SF 6 Walls - Structural Glazed Tile 3rd Floor West 34 EA 6 Walls - Structural Glazed Tile 3rd Floor West 34 EA 6 Accessories 3rd Floor West Unisex 24 SF 7 Ceiling - Plaster/Drywall 3rd Floor West Unisex 24 SF 7 Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF 7 Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF 7 Lavatory 3rd Floor West Unisex 24 SF 7 Lavatory 3rd Floor West Unisex 1 EA 7 Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF 7 Walls - Plaster/Drywall</td></td<> <td>Lighting - Pendent/Surface 3rd Floor West 7 EA 7 6-10 years Partitions 3rd Floor West 4 EA 7 10-years Walls - Concrete Block 3rd Floor West 354 SF 6 10+years Walls - Structural Glazed Tile 3rd Floor West 354 SF 6 10+years Walls - Structural Glazed Tile 3rd Floor West 354 SF 6 10+years Walls - Concrete Epoxyl 3rd Floor West Unisex 24 SF 7 6-10 years Accessories 3rd Floor West Unisex 24 SF 7 6-10 years Doors - Wood Doors inclu thw 3rd Floor West Unisex 24 SF 7 10+ years Floor - Concrete Epoxyl Painted 3rd Floor West Unisex 24 SF 7 10+ years Loyating - Pendent/Surface 3rd Floor West Unisex 1 EA 7 10+ years Walls - Masonry 3rd Floor West Unisex 56 SF 7 10+ years Walls - Plaster/Dywall</td>	Lighting - Pendent/Surface 3rd Floor West 7 EA Partitions 3rd Floor West 4 EA Walls - Concrete Block 3rd Floor West 354 SF Walls - Structural Glazed Tile 3rd Floor West 354 SF Walls - Structural Glazed Tile 3rd Floor West 34 SF Walls - Closet 3rd Floor West 4 EA Accessories 3rd Floor West Unisex 24 SF Ceiling - Plaster/Drywall 3rd Floor West Unisex 24 SF Doors - Wood Doors inclu hw 3rd Floor West Unisex 1 EA Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF Lavatory 3rd Floor West Unisex 1 EA Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF Wa	Lighting - Pendent/Surface 3rd Floor West 7 EA 7 Partitions 3rd Floor West 4 EA 7 Walls - Concrete Block 3rd Floor West 354 SF 6 Walls - Structural Glazed Tile 3rd Floor West 34 SF 6 Walls - Structural Glazed Tile 3rd Floor West 34 EA 6 Walls - Structural Glazed Tile 3rd Floor West 34 EA 6 Accessories 3rd Floor West Unisex 24 SF 7 Ceiling - Plaster/Drywall 3rd Floor West Unisex 24 SF 7 Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF 7 Floor - Concrete Epoxy/ Painted 3rd Floor West Unisex 24 SF 7 Lavatory 3rd Floor West Unisex 24 SF 7 Lavatory 3rd Floor West Unisex 1 EA 7 Walls - Plaster/Drywall 3rd Floor West Unisex 56 SF 7 Walls - Plaster/Drywall	Lighting - Pendent/Surface 3rd Floor West 7 EA 7 6-10 years Partitions 3rd Floor West 4 EA 7 10-years Walls - Concrete Block 3rd Floor West 354 SF 6 10+years Walls - Structural Glazed Tile 3rd Floor West 354 SF 6 10+years Walls - Structural Glazed Tile 3rd Floor West 354 SF 6 10+years Walls - Concrete Epoxyl 3rd Floor West Unisex 24 SF 7 6-10 years Accessories 3rd Floor West Unisex 24 SF 7 6-10 years Doors - Wood Doors inclu thw 3rd Floor West Unisex 24 SF 7 10+ years Floor - Concrete Epoxyl Painted 3rd Floor West Unisex 24 SF 7 10+ years Loyating - Pendent/Surface 3rd Floor West Unisex 1 EA 7 10+ years Walls - Masonry 3rd Floor West Unisex 56 SF 7 10+ years Walls - Plaster/Dywall

Building: Main

Campus Name: Senn HS Page : 30 of 95 Assessment Date: 07/18/2022





Catego	ategory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	1,488	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	42	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Wall Mirrors	1st Floor	400	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,804	SF	7	10+ years	
_Classroo	om #172 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	528	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	528	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,025	SF	6	10+ years	
Classro	om #174 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	528	SF	6	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	528	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	945	SF	6	10+ years	
Classroo	om #176 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	68	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	730	SF	5	6-10 years	
	Lighting - Lay-in	1st Floor	21	EA	5 6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	6		
	walls - Plaster/Drywall	1St Floor	1,120	SF	О	10+ years	
_Classroo	om #219 (Regular Classroom)						
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,000	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	30	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,030	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,441	SF	7	10+ years	

Campus Name: Senn HS Page : 31 of 95 Assessment Date: 07/18/2022



Catego	egory : Classroom			uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	### (Q							
lassroo	m #221 (Computer Lab)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	14	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,488	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,498	SF	7	10+ years		
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Chipped tiles	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years		
	Marker Board	2nd Floor	50	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,490	SF	7	10+ years		
	Wireless System	2nd Floor	1	EA	7	6-10 years		
lassroo	m #222 (Faculty Lounge)							
1000100	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	699	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage	
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	water damage	
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years		
	Floor - Wood Doors inclu flw	2nd Floor	705	SF	7	10+ years		
		2nd Floor	21	EA	7	6-10 years		
	Lighting - Lay-in Walls - Plaster/Drywall	2nd Floor 2nd Floor						
			1,140	SF	6	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
assroo	m #230 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	10+ years		
	Casework	2nd Floor	15	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,145	SF	7	10+ years		
	Chalk Board	2nd Floor	26	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	21	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Wood	2nd Floor	1,145	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	65	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,293	SF	6	10+ years		
	Work Sink	2nd Floor	1,233	EA	7	10+ years		
lassroo	m #233 (Regular Classroom)							
	Casework	2nd Floor	10	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	1,130	SF	6	10+ years		

Campus Name: Senn HS Page : 32 of 95 Assessment Date: 07/18/2022



Sategory : Classroom

Suilding : Main

Catego	tegory : Classroom		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,130	SF	5	10+ years	Cracks in the tiles
	Lighting - Lay-in	2nd Floor	34	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,441	SF	6	10+ years	
Classroo	om #234 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,030	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,030	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,440	SF	6	10+ years	
Classro	om #236 (Regular Classroom)						
Cidooros	Casework	2nd Floor	7	LF	5	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	10+ years	Wood floor needs to be refinished
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	Troca neer neede to be remnerted
	Walls - Plaster/Drywall	2nd Floor	2,160	SF	6	10+ years	
Classro	om #260 (Regular Classroom)						
Classiul	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	712	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	18	SF	4	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	water damage
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
01	•					•	
_Classroo	om #261 (Regular Classroom)	0.151				0.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	

Campus Name: Senn HS Page : 33 of 95 Assessment Date: 07/18/2022





	: Classroom			Building : Main			5500 N GICHWOOD AVENUE, Officago, IE 60000		
Group Ite						Recommend			
	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Ce	eiling - Lay-in	2nd Floor	724	SF	7	10+ years			
Ce	eiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage		
	oors - Transom Window	2nd Floor	15	SF	7	10+ years	· ·		
Do	oors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
FI	loor - Wood	2nd Floor	730	SF	7	10+ years			
	ghting - Lay-in	2nd Floor	18	ĒΑ	7	6-10 years			
	arker Board	2nd Floor	24	LF	7	6-10 years			
	/alls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years			
Classroom #	#262 (Regular Classroom)								
	C Units	2nd Floor	2	EA	7	6-10 years			
		2nd Floor	7	LF	7	10+ years			
	asework	2nd Floor 2nd Floor		SF		•			
	eiling - Lay-in	2nd Floor 2nd Floor	730	SF SF	7	10+ years			
	oors - Transom Window		15		7	10+ years			
	oors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	loor - Wood	2nd Floor	730	SF	7	10+ years			
	ghting Lay-in	2nd Floor	21	EΑ	7	6-10 years			
	arker Board	2nd Floor	24	LF	7	6-10 years			
W	/alls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years			
Classroom #	#264 (Regular Classroom)								
AC	C Units	2nd Floor	2	EA	7	6-10 years			
	asework	2nd Floor	7	LF	7	10+ years			
	eiling - Lay-in	2nd Floor	724	SF	7	10+ years			
	eiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage		
	halk Board	2nd Floor	12	LF	4	2-5 years	g-		
	oors - Transom Window	2nd Floor	15	SF	7	10+ years			
	oors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years			
	loor - Wood	2nd Floor	730	SF	7	10+ years			
	ghting - Lay-in	2nd Floor	21	EA	6	6-10 years			
	arker Board	2nd Floor	24	LF	7	6-10 years			
	/alls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years			
Classroom #	#266 (Regular Classroom)								
	C Units	2nd Floor	2	EA	7	6 10 40000			
			2		7	6-10 years			
	asework	2nd Floor	7	LF	7	10+ years			
	eiling - Lay-in	2nd Floor	726	SF	7	10+ years	December 1415		
	eiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Buckled tile		
	oors - Transom Window	2nd Floor	15	SF	7	10+ years			
	oors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	loor - Wood	2nd Floor	730	SF	7	10+ years			
	ghting - Lay-in	2nd Floor	21	EA	6	6-10 years			
Ma	arker Board	2nd Floor	30	LF	7	6-10 years			

Campus Name: Senn HS Page : 34 of 95 Assessment Date: 07/18/2022





Catego	ategory : Classroom		В				
July	. ,		_	uilding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
	,					j	
Classroc	m #272 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,424	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	1,424	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	['] 45	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,672	SF	6	10+ years	
OI							
Jassroc	m #273 (Regular Classroom) Casework	2nd Floor	7	LF	6	10± voors	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	727	SF	6	10+ years 10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4		Water demage
	Doors - Transom Window	2nd Floor		SF		0-1 year	Water damage
	Doors - Wood Doors inclu hw				6 7	10+ years	
		2nd Floor	1	EA		10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
Classroo	om #275 (Regular Classroom)						
	Casework	2nd Floor	7	LF	5	10+ years	
	Ceiling - Lay-in	2nd Floor	724	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	3.0
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EΑ	6	6-10 years	
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
`lacoroo	om #276 (Computer Lab)						
1100010C	Casework	2nd Floor	7	LF	6	10 L Voors	
					6	10+ years	
	Ceiling - Lay-in	2nd Floor	727	SF	6	10+ years	Motor domago
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	

Campus Name: Senn HS Page : 35 of 95 Assessment Date: 07/18/2022



Classroom #319 (Regular Classroom)

Building: Main Category: Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Classroom #277 (Regular Classroom) Casework 2nd Floor 7 LF 6 10+ years 2nd Floor 730 SF 6 10+ years Ceiling - Lay-in Doors - Transom Window 2nd Floor SF 6 10+ years 15 Doors - Wood Doors inclu hw 2nd Floor FΑ 7 10+ years 1 Floor - Wood 2nd Floor 730 SF 6 10+ years Lighting - Lay-in 2nd Floor 18 FΑ 7 6-10 years LF Marker Board 2nd Floor 36 6-10 years 6 SF Walls - Plaster/Drywall 2nd Floor 1,120 10+ years Classroom #278 (Regular Classroom) 2nd Floor LF Casework 7 6 10+ years Ceiling - Lav-in 2nd Floor 730 SF 6 10+ years Doors - Transom Window 2nd Floor SF 15 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 7 10+ years Floor - Tile 2nd Floor 730 SF 7 10+ years 2nd Floor EΑ 7 6-10 years Lighting - Lay-in 18 Marker Board 2nd Floor 28 LF 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1.120 SF 10+ years Classroom #280 (Regular Classroom) Casework 2nd Floor 7 LF 6 10+ years SF Ceiling - Lay-in 2nd Floor 930 6 10+ years SF Doors - Transom Window 2nd Floor 21 6 10+ years Doors - Wood Doors inclu hw 2nd Floor EΑ 7 10+ years 1 Floor - Tile 2nd Floor 930 SF 7 10+ years Lighting - Lay-in 2nd Floor 32 EΑ 7 6-10 years Marker Board 2nd Floor 32 LF 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1.120 SF 10+ years Classroom #281 (Regular Classroom) Casework 2nd Floor 7 LF 6 10+ years 2nd Floor SF Ceiling - Lay-in 724 6 10+ years SF Ceiling - Lay-in 2nd Floor 6 4 0-1 year Water damage Doors - Transom Window 2nd Floor 15 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 7 10+ years SF Floor - Wood 2nd Floor 730 6 10+ years Lighting - Lay-in 2nd Floor EΑ 7 6-10 years 21 Marker Board LF 2nd Floor 24 6 6-10 years Walls - Plaster/Drywall 2nd Floor 1.120 SF 6 10+ years

Campus Name: Senn HS Page: 36 of 95 Assessment Date: 07/18/2022



Building: Main Category: Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Casework LF 3rd Floor 33 10+ years 7 Ceiling - Lav-in 3rd Floor 1.124 SF 7 10+ years Ceiling - Lay-in 3rd Floor SF 4 0-1 year Damaged tile Doors - Wood Doors inclu hw EΑ 7 3rd Floor 1 10+ years SF Floor - Wood 3rd Floor 1,130 7 10+ years 7 Lighting - Lay-in 3rd Floor 30 EΑ 6-10 years Marker Board 3rd Floor 16 LF 7 6-10 years Walls - Plaster/Drywall SF 3rd Floor 1.439 7 10+ years Work Sink 3rd Floor 1 EΑ 7 10+ years The deficiency was fixed Classroom #320 (Regular Classroom) AC Units 3rd Floor 1 EΑ 7 6-10 years Casework 3rd Floor 120 LF 7 10+ years SF Ceiling - Splined 3rd Floor 1.030 7 10+ years Ceiling - Splined 3rd Floor SF 0-1 vear 20 4 Missing tiles Chalk Board 3rd Floor 20 LF 4 2-5 years Doors - Wood Doors inclu hw FΑ 7 3rd Floor 1 10+ years Floor - Wood 3rd Floor 1,050 SF 7 10+ years Lighting - Pendent/Surface 7 3rd Floor 30 EΑ 6-10 years Marker Board 3rd Floor 20 LF 7 6-10 years SF Walls - Plaster/Drywall 3rd Floor 1.484 10+ years Classroom #322 (Regular Classroom) Casework 3rd Floor LF 7 16 10+ years Ceiling - Lay-in 3rd Floor 718 SF 7 10+ years SF Ceiling - Lay-in 3rd Floor 12 0-1 year 4 Water damage Doors - Wood Doors inclu hw 3rd Floor 1 EΑ 7 10+ years Floor - Wood 3rd Floor 730 SF 7 10+ years Lighting - Lay-in 3rd Floor 23 FΑ 7 6-10 years 28 LF Marker Board 3rd Floor 7 6-10 years Walls - Plaster/Drywall SF 7 3rd Floor 1,140 10+ years Classroom #325 (Music Room) LF Casework 3rd Floor 80 6 10+ years SF Ceiling - Lav-in 3rd Floor 2.395 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 6 EΑ 7 10+ vears Floor - Wood 2,395 SF 3rd Floor 6 10+ years Lighting - Lay-in 3rd Floor 43 EΑ 6 6-10 years 6 LF 6 6-10 years Marker Board 3rd Floor Walls - Plaster/Drywall 3,213 SF 6 3rd Floor 10+ years Classroom #326 (Computer Lab) Ceiling - Plaster/Drywall 7 3rd Floor 1,495 SF 10+ years



Classroom #334 (Regular Classroom)
Casework

Ceiling - Lay-in

5900 N Glenwood AVENUE, Chicago, IL 60660 **Building: Main** Category: Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw FΑ 3rd Floor 7 10+ years Changed to match current observation Floor - Tile 3rd Floor 1.495 SF 7 10+ years Lighting - Pendent/Surface 42 EΑ 7 6-10 years 3rd Floor LF 7 Marker Board 3rd Floor 32 6-10 years SF Walls - Plaster/Drywall 7 3rd Floor 1,093 10+ years Wireless System EΑ 7 6-10 years 3rd Floor 1 Classroom #328 (Regular Classroom) Casework 3rd Floor LF 7 5 10+ years Ceiling - Lay-in 3rd Floor 721 SF 10+ years 6 Ceiling - Lay-in 3rd Floor SF 0-1 year Water damage LF Chalk Board 3rd Floor 60 4 2-5 years Doors - Wood Doors inclu hw 3rd Floor 1 EΑ 6 10+ years 3rd Floor 730 SF 6 Floor - Wood 10+ years Lighting - Lay-in 3rd Floor 20 FΑ 7 6-10 years Walls - Plaster/Drywall SF 3rd Floor 1.138 6 10+ years Walls - Plaster/Drywall SF 3rd Floor 0-1 year Water damage Classroom #330 (Regular Classroom) 7 LF Casework 3rd Floor 6 10+ years SF Ceiling - Lay-in 3rd Floor 730 6 10+ years LF Chalk Board 3rd Floor 32 4 2-5 years Doors - Wood Doors inclu hw EΑ 7 3rd Floor 1 10+ years Floor - Wood 3rd Floor 730 SF 5 10+ years 3rd Floor 21 EΑ 7 6-10 years Lighting - Lay-in LF Marker Board 3rd Floor 14 6 6-10 years SF Walls - Plaster/Drywall 3rd Floor 1.140 10+ years Classroom #332 (Regular Classroom) AC Units 3rd Floor 2 7 EΑ 6-10 years 8 LF Casework 3rd Floor 6 10+ years Ceiling - Lay-in 3rd Floor 730 SF 6 10+ years LF Chalk Board 3rd Floor 18 4 2-5 years 7 Doors - Wood Doors inclu hw 3rd Floor EΑ 10+ years 1 Floor - Wood 3rd Floor 730 SF 5 10+ years 7 6-10 years Lighting - Lay-in 3rd Floor 21 EΑ Marker Board 3rd Floor 30 LF 6 6-10 years SF 7 Walls - Plaster/Drywall 3rd Floor 1.140 10+ years

Campus Name: Senn HS Page : 38 of 95 Assessment Date: 07/18/2022

7

712

LF

SF

6

6

10+ years

10+ years

3rd Floor

3rd Floor





Catego	ry : Classroom		R	uilding	· Main		o in Gleriwood Avende, Chicago, il 60660
Outego	19 : 01033100111			unung	· Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Ceiling - Lay-in	3rd Floor	18	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	37	LF	4	2-5 years	water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	3rd Floor	730	SF	, 5		
				EA	-	10+ years	
	Lighting - Lay-in Walls - Plaster/Drywall	3rd Floor	21	SF	7 6	6-10 years	
	walls - Plaster/Drywall	3rd Floor	1,140	SF	О	10+ years	
Classroo	om #335 (Computer Lab)						
	Casework	3rd Floor	7	LF	5	10+ years	
	Ceiling - Lay-in	3rd Floor	1,121	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	9	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	14	LF	4	2-5 years	Ğ
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,130	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	27	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,200	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	139	SF	5	0-1 year	Water damage
	Wireless System	3rd Floor	100	EA	7	6-10 years	water damage
	Wheless System	314 1 1001		LA	,	0-10 years	
Classroo	om #350 (Science Lab Level 1)						
	Casework	3rd Floor	111	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	1,300	SF	6	10+ years	
	Gas Line	3rd Floor	16	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	17	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Science Lab Fume Hood Science Lab Shower	3rd Floor 3rd Floor	1	EΑ	7 7	10+ years	
			1 242	EA		10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,313	SF	7	10+ years	
	Work Sink	3rd Floor	8	EA	7	10+ years	
Classro	om #351 (Regular Classroom)						
Classion	` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	3rd Floor	10	1.5	7	10	
	Casework		19	LF SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	920		7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	920	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,133	SF	7	10+ years	

Campus Name: Senn HS Page : 39 of 95 Assessment Date: 07/18/2022



Building: Main Category : Classroom Recommend Group Item - Type Location Quantity Replacement Comments UOM Rank

Jup	Rom Type	Location	- au.i.i.y	• • • • • • • • • • • • • • • • • • • •			~~
	Work Sink	3rd Floor	1	EA	7	10+ years	
assroon	n #352 (Science Lab Level 3)						
001001	Casework	3rd Floor	52	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	990	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	990	SF	7	10+ years	
	Gas Line	3rd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	_ 29	EΑ	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,001	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
sroon	n #353/355 (Art Room)						
	Casework	3rd Floor	46	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,840	SF	7	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,840	SF	7	10+ years	Changed to match current observation
	Kiln	3rd Floor	1	EA	7	10+ years	observation
	Lighting - Lay-in	3rd Floor	48	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,888	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
ssroon	n #356 (Science Lab Level 1)						
	Casework	3rd Floor	209	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	919	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	18	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Eye Wash Station	3rd Floor	_ 1	ΕA	7	10+ years	
	Floor - Tile	3rd Floor	937	SF	7	10+ years	
	Gas Line	3rd Floor	16	EΑ	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years	
	Science Lab Shower	3rd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,157	SF	6	10+ years	
	Work Sink	3rd Floor	10	EΑ	7	10+ years	

Campus Name: Senn HS Page : 40 of 95 Assessment Date: 07/18/2022



Catego	ry : Classroom		В	uilding	: Main			
Group	Itom - Tuno	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments	
Classroc	om #358 (Science Lab Level 3)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	37	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,198	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	18	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,216	SF	7	10+ years		
	Gas Line	3rd Floor	1	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	24	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Science Lab Shower	3rd Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,309	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	om #361 (Art Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	60	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,566	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	[′] 18	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Wood	3rd Floor	1,584	SF	7	10+ years		
	Instructional Surface	3rd Floor	7	LF	7	10+ years		
	Lighting - Lay-in	3rd Floor	30	EA	7	6-10 years		
	Marker Board	3rd Floor	44	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,455	SF	7	10+ years		
	Work Sink	3rd Floor	1	ĒΑ	7	10+ years		
Classroo	om #363 (Regular Classroom)							
	Casework	3rd Floor	6	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	816	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Wood	3rd Floor	816	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	24	EA	7	6-10 years		
	Marker Board	3rd Floor	15	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,051	SF	7	10+ years		
Classroo	om #364 (Science Lab Level 3)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	60	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,032	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EA	6	10+ years		
	Lyo wash olalion	314 1 1001	'	LA	J	TOT years		





Category : Classroom		В	Building : Main					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	3rd Floor	1,032	SF	7	10+ years		
	Gas Line	3rd Floor	1	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years		
	Marker Board	3rd Floor	41	LF	7	6-10 years		
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years		
	Science Lab Shower	3rd Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,183	SF	7	10+ years		
	Work Sink	3rd Floor	3	ĒΑ	7	10+ years		
Classro	om #366 (Science Lab Level 3)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	84	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	840	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Water damage	
	Ceiling - Eay-iii Ceiling - Plaster/Drywall	3rd Floor	204	SF	7	10+ years	water damage	
	Doors - Wood Doors inclu hw	3rd Floor	204	EA	7	-		
	Eye Wash Station		1	EA		10+ years		
		3rd Floor	•	SF	6	10+ years		
	Floor - Tile	3rd Floor	1,050		7	10+ years		
	Gas Line	3rd Floor	1	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	30	EΑ	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	180	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,228	SF	6	10+ years		
	Work Sink	3rd Floor	3	EA	7	10+ years		
_Classro	om #367 (Regular Classroom)							
	Casework	3rd Floor	7	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	713	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Wood	3rd Floor	725	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	ĒΑ	7	6-10 years		
	Marker Board	3rd Floor	17	LF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	879	SF	6	10+ years		
Classro	om #372 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Wood Doors Inclu IIW	3rd Floor	750	SF	, 5	10+ years		
		3rd Floor 3rd Floor		SF EA				
	Lighting - Lay-in		21	LF	6	6-10 years		
	Marker Board	3rd Floor	25		6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,061	SF	7	10+ years		



Category : Classroom			В	uilding	: Main		o N Sichwood Avenue, Onleago, ie 00000
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #374 (Regular Classroom)						
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	50	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	750	SF	5	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,063	SF	6	10+ years	
Classroo	om #376 (Regular Classroom)						
	Casework	3rd Floor	7	LF	5	10+ years	
	Ceiling - Lay-in	3rd Floor	747	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	ŭ
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,063	SF	6	10+ years	
_Classroo	om #378 (Regular Classroom)						
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	729	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	21	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	· ·
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,063	SF	6	10+ years	
Classroo	om #380 (Regular Classroom)						
	Casework	3rd Floor	7	LF	5	10+ years	
	Ceiling - Lay-in	3rd Floor	930	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	30	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	-
	Floor - Wood	3rd Floor	930	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	32	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,115	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	4	0-1 year	Water damage
Classroo	om #425 (Band Room)						
	,						





Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	4th Floor	10	LF	5	10+ years	
	Ceiling - Splined	4th Floor	2,371	SF	6	10+ years	
	Ceiling - Splined	4th Floor	76	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	4th Floor	8	EA	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EΑ	5	10+ years	
	Floor - Wood	4th Floor	2,447	SF	6	10+ years	
	Instrument Storage Casework	4th Floor	63	LF	7	10+ years	
	Lighting - Pendent/Surface	4th Floor	63	EΑ	6	6-10 years	
	Storage/ Closet	4th Floor	315	SF	5	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,595	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
		Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	129B Link from 129 to Main Office	96	SF	6	10+ years	
	Doors - Transom Window	129B Link from 129 to Main Office	11	SF	7	10+ years	
	Doors - Wood Doors include hw	129B Link from 129 to Main Office	2	EA	6	10+ years	
	Floor - Tile/Sheet	129B Link from 129 to Main Office	96	SF	7	10+ years	
	Lighting - Lay-in	129B Link from 129 to Main Office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	129B Link from 129 to Main Office	406	SF	6	10+ years	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	129B Link from 129 to Main Office	96	SF	6	10+ years	
	Doors - Transom Window	129B Link from 129 to Main Office	11	SF	7	10+ years	
	Doors - Wood Doors include hw	129B Link from 129 to Main Office	2	EA	6	10+ years	
	Floor - Tile/Sheet	129B Link from 129 to Main Office	96	SF	7	10+ years	
	Lighting - Lay-in	129B Link from 129 to Main Office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	129B Link from 129 to Main Office	406	SF	6	10+ years	
	Walls - Plaster/Drywall	129B Link from 129 to Main Office	6	SF	5	0-1 year	Cracking
	Ceiling - Lay-in	1st Floor Vestibule	1,800	SF	6	10+ years	
	Doors - Transom Window	1st Floor Vestibule	90	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor Vestibule	20	EA	6	10+ years	
	Floor - Terrazzo	1st Floor Vestibule	1,800	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Vestibule	19	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Vestibule	1,733	SF	7	10+ years	
	Ceiling - Lay-in	1st South	1,943	SF	6	10+ years	
	Ceiling - Lay-in	1st South	8	SF	4	0-1 year	Broken
	Ceiling - Plaster/Drywall	1st South	325	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st South	1	EA	7	10+ years	
	Floor - Terrazzo	1st South	2,276	SF	5	10+ years	
	Lighting - Lay-in	1st South	17	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st South	6	EA	6	6-10 years	
	Stairs - Concrete Stairs	1st South	18	LF	6	10+ years	
	Walls - Plaster/Drywall	1st South	3,470	SF	6	10+ years	
	Walls - Plaster/Drywall	1st South	100	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	1st West	5,926	SF	6	10+ years	
	Ceiling - Lay-in	1st West	24	SF	4	0-1 year	Water damage
	Doors - Wood Doors include hw	1st West	4	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st West	1	EA	5	10+ years	
	Floor - Terrazzo	1st West	5,950	SF	5	10+ years	
	Lighting - Lay-in	1st West	53	EA	6	6-10 years	

Campus Name: Senn HS Page : 44 of 95 Assessment Date: 07/18/2022





Category : Interior

Category : Interior		Building : Main								
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	1st West	9	EA	6	6-10 years				
	Student Lockers - One Tier	1st West	236	EA	6	10+ years				
	Walls - Plaster/Drywall	1st West	7,468	SF	6	10+ years				
	Ceiling - Lay-in	1st floor East corridor	6,056	SF	6	10+ years				
	Ceiling - Lay-in	1st floor East corridor	8	SF	4	0-1 year	Water stains			
	Doors - Steel Doors incl hw	1st floor East corridor	2	EA	7	10+ years				
	Doors - Wood Doors include hw	1st floor East corridor	6	EA	6	10+ years				
	Doors - Wood Doors include hw	1st floor East corridor	6	EA	6	10+ years				
	Drinking Fountains - Single Water Cooler	1st floor East corridor	1	EA	7	10+ years				
	Floor - Terrazzo	1st floor East corridor	6,034	SF	5	10+ years				
	Floor - Tile/Sheet	1st floor East corridor	30	SF	4	1-2 years	Missing cracking			
	Lighting - Lay-in	1st floor East corridor	17	EA	6	6-10 years				
	Lighting - Pendent/Surface	1st floor East corridor	6	EA	6	6-10 years				
	Stairs - Concrete Stairs	1st floor East corridor	18	LF	6	10+ years				
	Student Lockers - One Tier	1st floor East corridor	250	EA	6	10+ years				
	Walls - Plaster/Drywall	1st floor East corridor	2,795	SF	6	10+ years				
	Walls - Structural Glazed Tile	1st floor East corridor	5,590	SF	6	10+ years				
	Ceiling - Lay-in	2nd East	6,057	SF	7	10+ years				
	Ceiling - Lay-in	2nd East	12	SF	4	0-1 year	Damaged tiles			
	Drinking Fountains - Single Water Cooler	2nd East	2	EA	7	10+ years	•			
	Floor - Tile/Sheet	2nd East	6,069	SF	7	10+ years				
	Lighting - Lay-in	2nd East	79	EA	7	6-10 years				
	Student Lockers - One Tier	2nd East	360	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd East	9,984	SF	7	10+ years				
	Ceiling - Lay-in	2nd South	30	SF	4	0-1 year	Water damage			
	Ceiling - Plaster/Drywall	2nd South	2,246	SF	7	10+ years	Ç			
	Floor - Tile/Sheet	2nd South	2,276	SF	7	10+ years				
	Lighting - Lay-in	2nd South	30	EA	7	6-10 years				
	Student Lockers - One Tier	2nd South	240	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd South	4,157	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd South	20	SF	5	0-1 year	Water damage			
	Ceiling - Lay-in	2nd West	4,005	SF	7	10+ years	•			
	Ceiling - Lay-in	2nd West	18	SF	4	0-1 year	Damaged tiles			
	Drinking Fountains - Single Water Cooler	2nd West	1	EA	7	10+ years	•			
	Floor - Tile/Sheet	2nd West	4,023	SF	7	10+ years				
	Lighting - Lay-in	2nd West	57	EA	6	6-10 years				
	Student Lockers - One Tier	2nd West	205	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd West	6,517	SF	7	10+ years				
	Ceiling - Lay-in	3rd East	4,023	SF	7	10+ years				
	Drinking Fountains - Single Water Cooler	3rd East	. 2	EA	7	10+ years				
	Floor - Tile/Sheet	3rd East	4,023	SF	7	10+ years				
	Lighting - Lay-in	3rd East	67	ĒΑ	7	6-10 years				
	Student Lockers - One Tier	3rd East	360	EA	7	10+ years				
	Walls - Plaster/Drywall	3rd East	4,367	SF	6	10+ years				
	,		,	-	-	- <i>j</i> · · ·				

Campus Name: Senn HS Page : 45 of 95 Assessment Date: 07/18/2022





Catego	ry : Interior		R	uilding	: Main	3000	on Gleriwood Avenue, Chicago, it 60660
Guiogo	. y . intorior			anamg	· Wani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd North (small corridor)	1,320	SF	7	10+ years	
	Floor - Tile/Sheet	3rd North (small corridor)	1,320	SF	7	10+ years	
	Lighting - Lay-in	3rd North (small corridor)	17	ĒA	7	6-10 years	
	Student Lockers - One Tier	3rd North (small corridor)	102	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd North (small corridor)	2,640	SF	7	10+ years	
	Ceiling - Lay-in	3rd South	1,952	SF	7	10+ years	
	Floor - Tile/Sheet	3rd South	1,932	SF	7	10+ years	
	Floor - Tile/Sheet	3rd South	20	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	3rd South	30	EΑ	7	6-10 years	
	Student Lockers - One Tier	3rd South	242	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd South	2,946	SF	7	10+ years	
	Ceiling - Lay-in	3rd West	4,297	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd West	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd West	4,297	SF	7	10+ years	
	Lighting - Lay-in	3rd West	55	EA	7	6-10 years	
	Student Lockers - One Tier	3rd West	212	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd West	4,288	SF	7	10+ years	
	Ceiling - Lay-in	Corridor in Main Office 135	284	SF	6	10+ years	
	Ceiling - Lay-in	Corridor in Main Office 135	16	SF	4	1-2 years	Broken
	Doors - Steel Doors incl hw	Corridor in Main Office 135	10	EA	7	10+ years	Diokeii
	Doors - Transom Window	Corridor in Main Office 135	11	SF	7	10+ years	
	Doors - Wood Doors include hw	Corridor in Main Office 135	1	EA	7	10+ years	
	Floor - Tile/Sheet	Corridor in Main Office 135	300	SF	7	10+ years	
	Lighting - Lay-in	Corridor in Main Office 135	20	EA	7	6-10 years	
	Walls - Metal Panel	Corridor in Main Office 135	300	SF	7	10+ years	
	Walls - Plaster/Drywall	Corridor in Main Office 135	852	SF	6	10+ years	
	Walls - Flastel/Drywall	Corndor in Main Office 133	032	SF	O	10+ years	
Cofoty							
Safety	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	
	Metal Dedector	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	5	EA	7	6-10 years	
	Security Cameras	Entire Building	55	EA	7	6-10 years	
	Security Carrieras	Littile Building	33	LA	,	0-10 years	
Stairs							
Cidilo	Ceiling - Lay-in	North East	282	SF	6	10+ years	Changed to match current
	Calling Lawin	Novib Foot	40	C.E.	4	0.4	observation
	Ceiling - Lay-in	North East	18	SF	4	0-1 year	Water damage
	Floor - Asphalt	North East	234	SF	5	10+ years	Changed to match current observation
	Floor - Tile	North East	187	SF	5	10+ years	
	Handrails	North East	218	LF	5	10+ years	
	Lighting - Lay-in	North East	3	EA	6	6-10 years	
	Lighting - Wall Mounted	North East	12	EA	7	6-10 years	
	Stairs - Asphalt	North East	341	LF	6	10+ years	Changed to match current

Campus Name: Senn HS Page : 46 of 95 Assessment Date: 07/18/2022





Category : Interior			В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observation
	Walls - Plaster/Drywall	North East	2,098	SF	6	10+ years	
	Ceiling - Lay-in	North West	488	SF	6	10+ years	
	Floor - Asphalt	North West	306	SF	5	10+ years	
	Floor - Tile	North West	265	SF	6	10+ years	
	Handrails	North West	165	LF	5	10+ years	
	Lighting - Pendent/Surface	North West	8	EA	7	6-10 years	
	Stairs - Asphalt	North West	440	LF	6	10+ years	Changed to match current observation
	Walls - Plaster/Drywall	North West	3,734	SF	6	10+ years	
	Ceiling - Lay-in	South East	200	SF	7	10+ years	Changed to match current observation
	Floor - Asphalt	South East	234	SF	7	10+ years	Changed to match current observation
	Floor - Tile	South East	187	SF	7	10+ years	
	Handrails	South East	218	LF	7	10+ years	
	Lighting - Lay-in	South East	2	EA	6	6-10 years	
	Lighting - Metal Halide/ High Pressure Sodium	South East	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	South East	12	EA	7	6-10 years	Changed to match current observation
	Stairs - Concrete	South East	341	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	2,098	SF	6	10+ years	
	Ceiling - Lay-in	South West	297	SF	6	10+ years	
	Floor - Asphalt	South West	426	SF	7	10+ years	
	Floor - Tile	South West	346	SF	7	10+ years	
	Handrails	South West	151	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	9	EA	7	6-10 years	
	Stairs - Asphalt	South West	436	LF	7	10+ years	Changed to match current observation
	Walls - Plaster/Drywall	South West	3,152	SF	6	10+ years	
	Ceiling - Lay-in	West	910	SF	7	10+ years	
	Floor - Asphalt	West	487	SF	7	10+ years	
	Floor - Terrazzo	West	306	SF	7	10+ years	
	Floor - Tile	West	646	SF	7	10+ years	
	Handrails	West	306	LF	7	10+ years	
	Lighting - Pendent/Surface	West	22	EA	7	6-10 years	
	Stairs - Asphalt	West	977	LF	7	10+ years	
	Walls - Concrete Block	West	170	SF	7	10+ years	
	Walls - Plaster/Drywall	West	3,740	SF	7	10+ years	



Category : Exterior Building : Addition 1

Gaiogo.	y . Exterior		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	/	Location	Quantity	OOM	Italik	Replacement	Comments
_Entrance						2.12	
	Exterior Doors - Exterior Steel Door	1 - East	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	1 - East	2	EA	6	10+ years	
	Exterior Stairs - Stone	1 - East	160	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	11 - West	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	11 E - N Storage	1	EA	5	2-5 years	
	Exterior Doors - Overhead Rolling/ Garage Door	11 E - N Storage	1	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	11A - NW AutoShop	1	EA	6	10+ years	
	Door	AAD NIM Assts Otsass	4	_^	0	0.40	
	Exterior Doors - Exterior Steel Door	11B - NW Auto Storage	1	EA LF	6	6-10 years	
	Exterior Stairs - Stone	11B - NW Auto Storage	3		6	10+ years	
	Exterior Doors - Exterior Steel Door	11C - N Boiler Room	2 25	EA LF	5	2-5 years	
	Exterior Stairs - Concrete	11C - N Boiler Room		LF LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	11C - N Boiler Room	35	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	11D - N Mechanical Room	1		6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	11D - N Mechanical Room	30	LF	5	1-2 years	Loose post
	Ramps - Concrete	11D - N Mechanical Room	15	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	12 - North	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	12 - North	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	12 - North	70	LF	5	10+ years	
	Exterior Stairs - Stone	12 - North	8	LF	6	10+ years	
	Entrance Control - Audio and Video	12A - N Clinic Loading	1	EΑ	6	6-10 years	
	Exterior Doors - Overhead Rolling/ Garage Door	12A - N Clinic Loading	1	EA	6	10+ years	
	Exterior Doors - Side lite	12A - N Clinic Loading	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	12A - N Clinic Loading	1	EA	6	10+ years	
	Exterior Stairs - Concrete	12A - N Clinic Loading	25	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	12B - N Electrical Outbuilding	4	EΑ	6	10+ years	
	Entrance Control - Audio and Video	2 - East	1	ΕA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	2 - East	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	2 - East	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2 - East	80	LF	6	10+ years	
	Exterior Stairs - Concrete	2 - East	16	LF	5	1-2 years	Spalling
	Power Door Operator and Controls	2 - East	1	EA	4	1-2 years	Door closer not working
	Ramp Handrail - Steel_Ramp Handrail	2 - East	88	LF	6	10+ years	3
	Ramps - Concrete	2 - East	44	LF	5	1-2 years	Spalling
	Stair Handrail - Steel_Stair Handrail	2 - East	30	LF	6	10+ years	. 5
	Exterior Doors - Exterior Steel Door	3 - East	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	3 - East	3	EA	6	10+ years	
	Exterior Stairs - Stone	3 - East	40	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Roof	1	ĒΑ	6	10+ years	
						,	

Campus Name: Senn HS Page : 48 of 95 Assessment Date: 07/18/2022





Category : Exterior			Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Foundati	on Foundation - Concrete	Entire Building	931	LF	7	10+ years		
	Superstructure - Concrete	Entire Building Entire Building	33,906	SF	7	10+ years 10+ years		
	Superstructure - Concrete	Littile Building	33,900	OI.	,	10+ years		
_Lighting								
<u> </u>	Exterior Lighting - Parapet or Roof Mounted	Entire Building	5	EA	6	6-10 years		
	Exterior Lighting - Wall Mounted	Entire Building	15	EΑ	6	6-10 years		
	<u> </u>	· ·				•		
Roof Sys								
	Access Ladder - Metal	A	2	EA	7	10+ years		
	Coping - Metal	A	120	LF	5	2-5 years		
	Coping - Stone	A	484	LF	6	10+ years		
	Coping - Terra Cotta	Α	147	LF	6	10+ years		
	Downspouts - Exterior Downspouts	A	3	LF	5	2-5 years		
	Downspouts - Interior Downspouts	A	340	LF	6	10+ years		
	Parapet - 16" - 30" Height	A	751	LF	6	10+ years		
	Parapet - 16" - 30" Height	A	10	LF	5	2-5 years		
	Roof - Modified Bitumen	Α	20,642	SF	5	2-5 years		
	Roof Hatch - Metal	Α	1	ĒΑ	7	10+ years		
	Roof Hatch - Metal	A	1	ĒΑ	5	1-2 years	Closer damaged	
	Roof Structure - Steel with Clay Tile Arch	A	20,642	SF	7	10+ years		
	Chimney - Brick Chimney- Concrete/ Mortar	В	60	LF	6	10+ years		
	Liner	_			ŭ	. o · you.o		
	Chimney - Brick Chimney- Concrete/ Mortar	В	30	LF	5	2-5 years		
	Liner	_			· ·	_ 0 ,00.0		
	Coping - Terra Cotta	В	175	LF	6	10+ years		
	Downspouts - Interior Downspouts	В	114	LF	6	10+ years		
	Parapet - 16" - 30" Height	В	137	LF	6	10+ years		
	Parapet - Parapet < 16" Height	В	38	LF	6	10+ years		
	Parapet - Parapet > 30"	В	194	LF	6	10+ years		
	Roof - Modified Bitumen	В	2,448	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	В	2,448	SF	7	10+ years		
	Coping - Metal	D - Low West	140	LF	6	10+ years		
	Coping - Stone	D - Low West	249	LF	6	10+ years		
	Downspouts - Interior Downspouts	D - Low West	43	LF	6	10+ years		
	Parapet - 16" - 30" Height	D - Low West	43 55	LF LF	6	10+ years 10+ years		
	Parapet - 16" - 30" Height	D - Low West	30	LF	6	10+ years		
	Parapet - 16 - 30 Height Parapet - Parapet > 30"	D - Low West	194	LF LF				
					6	10+ years		
	Roof - Modified Bitumen	D - Low West	9,932	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	D - Low West	9,932	SF	7	10+ years		
\\/=!!-								
_Walls								

Campus Name: Senn HS Page : 49 of 95 Assessment Date: 07/18/2022





5900 N Glenwood AVENUE, Chicago, IL 6066

atego	ry : Exterior		В	uildina	: Addition	on 1	
			_			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Cheek-Wall - Stone	Entire Building	48	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	790	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	21,956	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,790	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	3,422	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	520	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	3,298	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	200	SF	5	10+ years	
/indows	3						
	Guard - Guards perforated	Entire Building	4,654	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	150	SF	5	10+ years	
	Lintels - Steel	Entire Building	1,016	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	140	LF	6	10+ years	
	Windows - Louver	Entire Building	16	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	12,845	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	600	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Additio	on 1	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nerger	ncy System						
	Automatic Transfer Switch	1st Floor	3	EA	7	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	14,997	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	748	SF	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Security System - CCTV	Entire Building	33,906	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	33,906	SF	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - 101 - 150 KW	North Courtyard	1	ĒΑ	6	6-10 years	The cabinet displays signs of corrosion
ain Sei	vice						
	PA System	Entire Building	33,906	SF	5	6-10 years	Connected to the main building
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	11	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp						

Campus Name: Senn HS Page : 50 of 95 Assessment Date: 07/18/2022





n - Type n Distribution Panels - Less than 400 Fire Protection n - Type Alarm Panel Alarm Strobe Lights Alarm_System Mechanical n - Type	Location Entire Building Location Entire Building Entire Building Entire Building Location	Quantity 1 B Quantity 1 33,906 33,906	UOM EA uilding UOM EA SF SF	Rank 6	Recommend Replacement 6-10 years on 1 Recommend Replacement 10+ years 10+ years	Comments Corroded cabinet Comments
n Distribution Panels - Less than 400 Fire Protection 1 - Type Alarm Panel Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Location Entire Building Entire Building Entire Building	1 Quantity 1 33,906 33,906	EA UOM EA SF SF	6 Rank 6 6	6-10 years on 1 Recommend Replacement 10+ years 10+ years	Corroded cabinet
n Distribution Panels - Less than 400 Fire Protection 1 - Type Alarm Panel Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Location Entire Building Entire Building Entire Building	Quantity 1 33,906 33,906	UOM EA SF SF	: Addition	Recommend Replacement 10+ years 10+ years	
Alarm Panel Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Entire Building Entire Building	Quantity 1 33,906 33,906	UOM EA SF SF	Rank 6 6	Recommend Replacement 10+ years 10+ years	Comments
Alarm Panel Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Entire Building Entire Building	Quantity 1 33,906 33,906	UOM EA SF SF	Rank 6 6	Recommend Replacement 10+ years 10+ years	Comments
Alarm Panel Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Entire Building Entire Building	1 33,906 33,906	EA SF SF	6 6	10+ years 10+ years	Comments
Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Entire Building	33,906 33,906	SF SF	6	10+ years	
Alarm Strobe Lights Alarm_System Mechanical 1 - Type	Entire Building Entire Building	33,906 33,906	SF SF	6	10+ years	
Alarm_System Mechanical 1 - Type	Entire Building	33,906	SF			
flechanical n - Type	, and the second			6		
ı - Type	Location	В	uildina		10+ years	
ı - Type	Location	_	unuma	: Additio	on 1	
- -	Location				Recommend	
ng		Quantity	UOM	Rank	Replacement	Comments
densing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
n 5 tons	D (•	_ ^	•	40	
ler-Water Cooled- Cetrifugal - 201-300	Roof	2	EA	6	10+ years	
oling Tower - Closed Cell	Roof	2	EA	6	10+ years	
col Feed	Roof	1	EA	6	10+ years	
es - Chilled Water Pipe- Steel	Roof	320	LF	6	10+ years	
densing Unit- Ground Mounted - Less n 5 tons	Site North	1	EA	6	6-10 years	
ystems						
Handling Unit- Package Single Zone- oor- Dual Temperature Coils - Less than 0 cfm	3rd Floor	1	EA	6	10+ years	
ntake	3rd Floor	1	EA	6	10+ years	
		3				
Handling Unit- Built Up- Single Zone w/ Funnel- Dual Temperature Coils -	Mechanical Room	1	EA	6	6-10 years	
ntake	Mechanical Room	1	EA	6	10+ vears	
iliaries - Greater than 35000 cfm	Mechanical Room	1		6		
eat Boxes - Reheat Boxes with Hot	Mechanical Room	8	EA	6	10+ years	
	Mechanical Room	100	LF	6	10+ years	
urn Duct Work - Masonry and Ducts-	Machanical Poom	36	FA	6	10+ years	
urn Duct Work - Masonry and Ducts- sing or Existing Shaft			EA	6		
or Ir Ir Ir	or- Dual Temperature Coils - Less than of cfm Intake Coil Unit- Celing Mounted - Electric Handling Unit- Built Up- Single Zone w/ Funnel- Dual Temperature Coils - Less than 35000 cfm Intake Handling Ha	or- Dual Temperature Coils - Less than of cfm or of that and the coil Unit- Celing Mounted - Electric and the coil Unit- Built Up- Single Zone w/ funnel- Dual Temperature Coils - atter than 35000 cfm or of that and the coil of the c	or- Dual Temperature Coils - Less than of cfm Intake 3rd Floor 1 Coil Unit- Celing Mounted - Electric Entire Building 3 Handling Unit- Built Up- Single Zone w/ Funnel- Dual Temperature Coils - Steer than 35000 cfm Intake Mechanical Room 1 Haries - Greater than 35000 cfm Mechanical Room 1 Haries - Greater than 35000 cfm Mechanical Room 1 Heat Boxes - Reheat Boxes with Hot Mechanical Room 8 Her Coil Mechanical Room 100 Her Duct Work - Masonry and Ducts- Ling or Existing Shaft Mechanical Room 100	or- Dual Temperature Coils - Less than of cfm Intake 3rd Floor 1 EA Coil Unit- Celing Mounted - Electric Entire Building 3 EA Handling Unit- Built Up- Single Zone w/ Mechanical Room 1 EA Funnel- Dual Temperature Coils - Intake Mechanical Room 1 EA Haringies - Greater than 35000 cfm Mechanical Room 1 EA Hater Boxes - Reheat Boxes with Hot Mechanical Room 8 EA Her Coil Irrn Duct Work - Masonry and Ducts- Iring or Existing Shaft ED Dampers Mechanical Room 36 EA	or- Dual Temperature Coils - Less than of cfm Intake 3rd Floor 1 EA 6 Coil Unit- Celing Mounted - Electric Entire Building 3 EA 5 Idandling Unit- Built Up- Single Zone w/ Mechanical Room 1 EA 6 Intunel- Dual Temperature Coils - Idate than 35000 cfm Intake Mechanical Room 1 EA 6 Idiaries - Greater than 35000 cfm Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 8 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 EA 6 Idiaries - Reheat Boxes with Hot Mechanical Room 1 BEA 6 Idiari	or- Dual Temperature Coils - Less than of cfm Intake 3rd Floor 1 EA 6 10+ years Coil Unit- Celing Mounted - Electric Entire Building 3 EA 5 6-10 years Handling Unit- Built Up- Single Zone w/ Mechanical Room 1 EA 6 6-10 years Funnel- Dual Temperature Coils - Fater than 35000 cfm Intake Mechanical Room 1 EA 6 10+ years Feater than 35000 cfm Intake Mechanical Room 1 EA 6 6-10 years Feater Boxes - Reheat Boxes with Hot Mechanical Room 8 EA 6 10+ years Feater Coil Firm Duct Work - Masonry and Ducts- Firm Duct Work - Masonry and Ducts

Campus Name: Senn HS Page : 51 of 95 Assessment Date: 07/18/2022





Catego	Category : Mechanical			Building : Addition 1					
				9		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Indoor- Hot Water and Chilled Water Coils -								
	4000-8000 cfm								
	Air Intake	Mezzanine	1	EA	6	10+ years			
	Air Intake	Mezzanine	1	EA	6	10+ years			
	Outdoor Return Fans- inline Centrifugal -	Roof	1	EA	6	10+ years			
	10001 - 20000 CFM								
_Boiler Sy	vstems								
	Boiler Auxiliary- Condensing Hot Water -	Boiler Room	5	EA	6	10+ years			
	3001 - 4000 HP								
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years			
	Condensing- Hot Water Boiler - 3001 - 4000	Boiler Room	5	EA	6	10+ years			
	MBH								
	Dual Temperature Pump	Boiler Room	2	EA	6	10+ years			
	Glycol Feed System	Boiler Room	1	EA	6	10+ years			
Heating									
	Unit Heater - Electric	1st Floor	1	EA	6	10+ years			
	Unit Heater - Hot Water	1st Floor	3	EA	6	10+ years			
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years			
	Fin Tube - Hot Water	Entire Building	44	LF	6	10+ years			
	Wall Heater - Electric	Entire Building	6	EA	6	2-5 years	Repaired		
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years			
Mechani	cal Plumbing								
	Condenser Pump - 21 - 50 HP	Boiler Room	2	EA	6	10+ years			
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years			
	Dual Temperature Pump - Greater than 50	Entire Building	3	ĒΑ	6	10+ years			
	HP	g	· ·	_, .		,			
T	Aura Cantral								
_rempera	ature Control Electric Thermostat	Entire Building	3	EA	6	6-10 years			
	Thermostats - DDC	Entire Building	36	EA	6	6-10 years			
	memostats - DDC	Littile Building	30	LA	O	0-10 years			
_Ventilatio									
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof	1	EA	6	10+ years			
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof	1	EA	6	10+ years			
	Exhaust Fans- Indoor - Greater than 8000	Roof	1	EA	6	10+ years			
	CFM								
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	6	EA	6	10+ years			
	CFM								
	Roof Mounted Duct Work	Roof	328	LF	7	10+ years			

Campus Name: Senn HS Page : 52 of 95 Assessment Date: 07/18/2022





Catego	ry : Plumbing		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Water	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	10+ years	
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Boiler Room	2	EA	6	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	33,906	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	33,906	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	33,906	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	33,906	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	33,906	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	33,906	SF	7	10+ years	
	Sanitary Piping	Entire Building	33,906	SF	6	10+ years	
	Storm Piping	Entire Building	33,906	SF	6	10+ years	
	Vent Piping	Entire Building	33,906	SF	6	10+ years	
Pumps							
-	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Duplex	Entire Building	1	EA	6	10+ years	

Category : Room **Building: Addition 1**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Lay-in	144 Clinic Reception Room	148	SF	7	10+ years	
	Doors - Wood Doors inclu hw	144 Clinic Reception Room	1	EA	7	10+ years	
	Floor - Tile	144 Clinic Reception Room	148	SF	7	10+ years	
	Lighting - Lay-in	144 Clinic Reception Room	8	EA	7	6-10 years	Quantity changed to match current observations
	Power Distribution	144 Clinic Reception Room	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	144 Clinic Reception Room	573	SF	7	10+ years	
	AC Unit	145 - Office	1	EΑ	7	6-10 years	
	Ceiling - Lay-in	145 - Office	683	SF	6	10+ years	
	Doors - Transom Window	145 - Office	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	145 - Office	4	EA	6	10+ years	
	Floor - Wood	145 - Office	683	SF	7	10+ years	
	Lighting - Lay-in	145 - Office	17	EA	7	6-10 years	
	Power Distribution	145 - Office	12	EA	7	10+ years	
	Storage/ Closet	145 - Office	201	SF	5	10+ years	

Page : 53 of 95 Campus Name: Senn HS Assessment Date: 07/18/2022





Catego	ry : Room		Building : Addition 1							
J						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	145 - Office	1,572	SF	6	10+ years				
	Ceiling - Lay-in	145A - Office	200	SF	6	10+ years				
	Doors - Wood Doors inclu hw	145A - Office	2	EA	6	10+ years				
	Floor - Wood	145A - Office	200	SF	7	10+ years				
	Lighting - Lay-in	145A - Office	5	EA	6	6-10 years				
	Power Distribution	145A - Office	6	EA	7	10+ years				
	Walls - Plaster/Drywall	145A - Office	575	SF	6	10+ years				
	AC Unit	145B - Office	1	ĒΑ	7	6-10 years				
	Ceiling - Lay-in	145B - Office	216	SF	6	10+ years				
	Doors - Wood Doors inclu hw	145B - Office	1	EΑ	7	10+ years				
	Floor - Wood	145B - Office	216	SF	7	10+ years				
	Lighting - Lay-in	145B - Office	6	EA	7	6-10 years				
	Power Distribution	145B - Office	8	EA	7	10+ years				
	Walls - Plaster/Drywall	145B - Office	568	SF	7	10+ years				
	Ceiling - Plaster/Drywall	145C - Office	117	SF	7	•				
	Doors - Transom Window	145C - Office	117	SF	7	10+ years				
						10+ years				
	Doors - Wood Doors inclu hw	145C - Office	1	EA	6	10+ years				
	Floor - Wood	145C - Office	117	SF	7	10+ years	01 14 41			
	Lighting - Pendent/Surface	145C - Office	1	EA	7	6-10 years	Changed to match current observations			
	Power Distribution	145C - Office	4	EA	7	10+ years				
	Walls - Plaster/Drywall	145C - Office	532	SF	7	10+ years				
	AC Unit	147 Office	1	EA	5	6-10 years				
	Ceiling - Lay-in	147 Office	195	SF	6	10+ years				
	Ceiling - Lay-in	147 Office	8	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	147 Office	2	EA	6	10+ years				
	Floor - Wood	147 Office	203	SF	6	10+ years				
	Lighting - Lay-in	147 Office	6	EA	6	6-10 years				
	Power Distribution	147 Office	10	EA	7	10+ years				
	Walls - Plaster/Drywall	147 Office	542	SF	7	10+ years				
	Ceiling - Splined	148 Office	818	SF	6	10+ years				
	Doors - Steel Doors incl hw	148 Office	1	EA	6	10+ years				
	Doors - Wood Doors inclu hw	148 Office	2	EA	6	10+ years				
	Floor - Wood	148 Office	818	SF	7	10+ years				
	Lighting - Pendent/Surface	148 Office	21	EA	6	6-10 years				
	Power Distribution	148 Office	26	EA	7	10+ years				
	Walls - Plaster/Drywall		1,983	SF	7	•				
		148 Office				10+ years				
	Work Sink	148 Office	1	EA SF	7	6-10 years				
	Ceiling - Splined	148A Office	117		6	10+ years				
	Doors - Wood Doors inclu hw	148A Office	1	EA	7	10+ years				
	Floor - Wood	148A Office	117	SF	6	10+ years				
	Lighting - Pendent/Surface	148A Office	1	EA	7	10+ years	Quantity changed to match current observations			
	Power Distribution	148A Office	6	EA	7	10+ years				

Campus Name: Senn HS Page : 54 of 95 Assessment Date: 07/18/2022





Category : Room

Building : Addition 1

Catego	ry : Room		Building : Addition 1						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	148A Office	346	SF	7	10+ years			
	Ceiling - Splined	148B Office	185	SF	6	10+ years			
	Doors - Wood Doors inclu hw	148B Office	1	EA	7	10+ years			
	Floor - Wood	148B Office	185	SF	7	10+ years			
	Lighting - Pendent/Surface	148B Office	6	EA	7	6-10 years			
	Power Distribution	148B Office	12	EA	7	10+ years			
	Walls - Plaster/Drywall	148B Office	373	SF	7	10+ years			
	Ceiling - Splined	148C Office	201	SF	6	10+ years			
	Doors - Wood Doors inclu hw	148C Office	1	EA	7	10+ years			
	Floor - Wood	148C Office	201	SF	6	10+ years			
	Lighting - Pendent/Surface	148C Office	6	EA	7	6-10 years			
	Power Distribution	148C Office	16	EA	7	10+ years			
	Storage/ Closet	148C Office	6	SF	7	10+ years			
	Walls - Plaster/Drywall	148C Office	394	SF	7	10+ years			
	Ceiling - Splined	148D - Office	172	SF	6	10+ years			
	Doors - Wood Doors inclu hw	148D - Office	1	EA	7	10+ years			
	Floor - Wood	148D - Office	172	SF	7	10+ years			
	Lighting - Pendent/Surface	148D - Office	8	EA	6	6-10 years			
	Power Distribution	148D - Office	16	EA	7	10+ years			
	Walls - Plaster/Drywall	148D - Office	357	SF	7	10+ years			
	Ceiling - Exposed	193A Break Room in Boiler Room	216	SF	5	10+ years	Water damage throughout		
	Doors - Wood Doors inclu hw	193A Break Room in Boiler Room	1	EA	6	10+ years			
	Floor - Tile	193A Break Room in Boiler Room	216	SF	6	10+ years			
	Lighting - Pendent/Surface	193A Break Room in Boiler Room	2	EA	7	6-10 years			
	Power Distribution	193A Break Room in Boiler Room	_6	EA	7	10+ years			
	Storage/ Closet	193A Break Room in Boiler Room	75	SF	5	10+ years			
	Walls - Masonry	193A Break Room in Boiler Room	945	SF	6	10+ years			
	Work SInk	193A Break Room in Boiler Room	1	EΑ	7	10+ years			
	AC Unit	195 - Engineers Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	195 - Engineers Office	328	SF EA	6 7	10+ years			
	Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain	195 - Engineers Office	1	SF	6	10+ years			
	Lighting - Pendent/Surface	195 - Engineers Office 195 - Engineers Office	328 12	EA	7	10+ years 6-10 years			
	Power Distribution	<u> </u>	16	EA	7	•			
	Walls - Plaster/Drywall	195 - Engineers Office 195 - Engineers Office	638	SF	6	10+ years			
	AC Unit	1954 Engineer's Office	1	EA	7	10+ years 6-10 years			
	Ceiling - Plaster/Drywall	195A Engineer's Office	194	SF	6	10+ years			
	Doors - Wood Doors inclu hw	195A Engineer's Office	1	EA	6	10+ years			
	Floor - Tile	195A Engineer's Office	194	SF	6	10+ years			
	Lighting - Pendent/Surface	195A Engineer's Office	6	EA	7	6-10 years			
	Power Distribution	195A Engineer's Office	8	EA	7	10+ years			
	Walls - Plaster/Drywall	195A Engineer's Office	369	SF	6	10+ years			
	AC Unit	238B IT Work Room	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	238B IT Work Room	684	SF	7	10+ years			
	g	2002	001	٥.	•	. c . youro			

Campus Name: Senn HS Page : 55 of 95 Assessment Date: 07/18/2022





Category : Room

Building : Addition 1

Catego	ry:Room		Building : Addition 1								
			Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Doors - Wood Doors inclu hw	238B IT Work Room	2	EΑ	6	10+ years					
	Floor - Concrete Epoxy/ Painted	238B IT Work Room	684	SF	5	10+ years					
	Lighting - Pendent/Surface	238B IT Work Room	4	EA	5	6-10 years	Covers are missing				
	Power Distribution	238B IT Work Room	34	EA	7	10+ years	3				
	Storage/ Closet	238B IT Work Room	32	SF	5	10+ years					
	Walls - Plaster/Drywall	238B IT Work Room	1,400	SF	7	10+ years					
	Ceiling - Plaster/Drywall	339 Office	512	SF	7	10+ years					
	Doors - Wood Doors inclu hw	339 Office	1	ĒΑ	7	10+ years					
	Floor - Tile	339 Office	512	SF	7	10+ years	Changed to match current				
						, , , , , , , , , , , , , , , , , , , ,	observation				
	Lighting - Pendent/Surface	339 Office	8	EA	7	6-10 years					
	Power Distribution	339 Office	4	EA	7	10+ years					
	Walls - Masonry	339 Office	174	SF	7	10+ years					
	Walls - Plaster/Drywall	339 Office	1,398	SF	7	10+ years					
	Ceiling - Lay-in	Behavioral Health Office in Clinic	61	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Behavioral Health Office in Clinic	1	ĒΑ	7	10+ years					
	Floor - Tile	Behavioral Health Office in Clinic	61	SF	7	10+ years					
	Lighting - Lay-in	Behavioral Health Office in Clinic	2	ĒΑ	7	6-10 years					
	Power Distribution	Behavioral Health Office in Clinic	4	EA	7	10+ years					
	Walls - Plaster/Drywall	Behavioral Health Office in Clinic	320	SF	7	10+ years					
	Ceiling - Splined	Dental Clinic	458	SF	6	10+ years					
	Doors - Wood Doors inclu hw	Dental Clinic	1	ĒΑ	7	10+ years					
	Floor - Tile	Dental Clinic	458	SF	7	10+ years					
	Lighting - Pendent/Surface	Dental Clinic	9	ĒΑ	7	6-10 years					
	Power Distribution	Dental Clinic	20	EΑ	7	10+ years					
	Walls - Plaster/Drywall	Dental Clinic	1,090	SF	7	10+ years					
	Work SInk	Dental Clinic	4	EA	7	10+ years					
	Ceiling - Plaster/Drywall	Exam Room 1 in Clinic	106	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Exam Room 1 in Clinic	1	EA	7	10+ years					
	Floor - Tile	Exam Room 1 in Clinic	106	SF	7	10+ years					
	Lighting - Lay-in	Exam Room 1 in Clinic	2	EA	7	6-10 years					
	Power Distribution	Exam Room 1 in Clinic	6	EΑ	7	10+ years					
	Walls - Plaster/Drywall	Exam Room 1 in Clinic	327	SF	7	10+ years					
	Work Sink	Exam Room 1 in Clinic	1	EA	7	10+ years					
	Ceiling - Lay-in	Exam Room 2 in Clinic	106	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Exam Room 2 in Clinic	1	EA	7	10+ years					
	Floor - Tile	Exam Room 2 in Clinic	106	SF	7	10+ years					
	Lighting - Lay-in	Exam Room 2 in Clinic	2	EA	7	6-10 years					
	Power Distribution	Exam Room 2 in Clinic	6	EA	7	10+ years					
	Walls - Plaster/Drywall	Exam Room 2 in Clinic	327	SF	7	10+ years					
	Work Sink	Exam Room 2 in Clinic	1	EA	7	10+ years					
	Ceiling - Lay-in	Laboratory in Clinic	125	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Laboratory in Clinic	125	SF EA	7 7	10+ years 10+ years					
	Floor - Tile	Laboratory in Clinic	125	SF	7	-					
	FIOUI - THE	Laboratory in Clinic	125	ЭГ	′	10+ years					

Campus Name: Senn HS Page : 56 of 95 Assessment Date: 07/18/2022





Catego	ory : Room		Building : Addition 1						
	_					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	Laboratory in Clinic	3	EA	7	6-10 years			
	Power Distribution	Laboratory in Clinic	8	EA	7	10+ years			
	Walls - Plaster/Drywall	Laboratory in Clinic	505	SF	7	10+ years			
	Work SInk	Laboratory in Clinic	1	EA	7	10+ years			
	Ceiling - Lay-in	Staff Room in Clinic	74	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Staff Room in Clinic	1	EA	7	10+ years			
	Floor - Tile	Staff Room in Clinic	74	SF	7	10+ years			
	Lighting - Lay-in	Staff Room in Clinic	2	EA	7	6-10 years			
	Power Distribution	Staff Room in Clinic	8	EA	7	10+ years			
	Walls - Plaster/Drywall	Staff Room in Clinic	340	SF	7	10+ years			
_MDF_ID)F								
	Doors - Steel Doors incl hw	238A	1	EA	7	10+ years			
	Finishes	238A	155	SF	5	10+ years			
	Window AC Unit	238A	2	EA	7	6-10 years			
_Mechan	ical/ Service Rooms								
	Boiler Room	1st Floor	3,834	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	102	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	559	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	3,175	SF	5	10+ years			
	Mechanical/ Service Rooms	1st Floor	2,073	SF	5	10+ years			
	Storage Room	1st Floor	423	SF	7	10+ years			
	Storage Room	1st Floor	343	SF	5	10+ years			
	Storage Room	1st Floor	2,307	SF	5	10+ years			
	Janitor's Closet	2nd Floor	14	SF	5	10+ years			
	Mechanical/ Service Rooms	2nd Floor	1,260	SF	5	10+ years			
	Storage Room	2nd Floor	901	SF	5	10+ years			
	Janitor's Closet	3rd Floor	14	SF	5	10+ years			
	Storage Room	3rd Floor	166	SF	5	10+ years			
	Air Tunnel	Basement	2,730	SF	5	10+ years			
	Mechanical/ Service Rooms	Basement	1,100	SF	7	10+ years			
	Storage Room	Storage in Clinic	64	SF	7	10+ years			
Restroo	m								
	Accessories	1st Floor	256	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	256	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	230	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	256	SF	6	10+ years			
	Floor Drain	1st Floor		EA	7	10+ years			
	Hand Dryer	1st Floor	1	EA EA	7				
			1			6-10 years			
	Lavatory	1st Floor	2	EΑ	7 7	10+ years			
	Lighting - Pendent/Surface	1st Floor	4	EA	1	6-10 years			

Campus Name: Senn HS Page : 57 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Addition 1						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	1st Floor	1	EA	7	10+ years			
	Urinals	1st Floor	4	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	255	SF	7	10+ years			
	Walls - Masonry	1st Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	415	SF	6	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	1st Floor Unisex	50	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Unisex	50	SF	4	0-1 year	Extensive water damage throughout		
	Doors - Wood Doors inclu hw	1st Floor Unisex	1	EA	7	10+ years			
	Floor - Tile	1st Floor Unisex	50	SF	6	10+ years			
	Floor Drain	1st Floor Unisex	1	EΑ	7	10+ years			
	Lavatory	1st Floor Unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor Unisex	1	EΑ	7	6-10 years			
	Walls - Concrete Block	1st Floor Unisex	59	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor Unisex	233	SF	7	10+ years			
	Water Closet	1st Floor Unisex	1	EA	7	10+ years			
	Accessories	2nd Floor	256	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	256	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	256	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EΑ	7	10+ years			
	Hand Dryer	2nd Floor	1	EΑ	7	6-10 years			
	Lavatory	2nd Floor	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	6-10 years			
	Partitions	2nd Floor	1	EA	7	10+ years			
	Urinals	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	255	SF	7	10+ years			
	Walls - Masonry	2nd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	415	SF	6	10+ years			
	Water Closet	2nd Floor	1	EΑ	7	10+ years			
	Accessories	3rd Floor	256	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	256	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years			
	Floor - Tile	3rd Floor	256	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	6-10 years			
	Lavatory	3rd Floor	2	EΑ	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years			
	Partitions	3rd Floor	1	EA	7	10+ years			
	Urinals	3rd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	255	SF	7	10+ years			
	Walls - Masonry	3rd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	415	SF	6	10+ years			
	Water Closet	3rd Floor	1	EA	7	10+ years			
						,			

Campus Name: Senn HS Page : 58 of 95 Assessment Date: 07/18/2022





Catego	ry : Room	Building : Addition 1							
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	Engineer's Toilet in 195	47	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Engineer's Toilet in 195	47	SF	5	10+ years			
	Doors - Wood Doors inclu hw	Engineer's Toilet in 195	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Engineer's Toilet in 195	47	SF	5	10+ years			
	Floor Drain	Engineer's Toilet in 195	1	EA	7	10+ years			
	Lavatory	Engineer's Toilet in 195	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Engineer's Toilet in 195	1	EA	7	6-10 years			
	Showers	Engineer's Toilet in 195	1	EA	4	0-1 year	Not in use		
	Walls - Plaster/Drywall	Engineer's Toilet in 195	181	SF	5	10+ years			
	Water Closet	Engineer's Toilet in 195	1	EA	6	10+ years			
	Accessories	Engineer's Toilet in 195A	48	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Engineer's Toilet in 195A	48	SF	5	10+ years	Peeling paint throughout		
	Doors - Wood Doors inclu hw	Engineer's Toilet in 195A	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Engineer's Toilet in 195A	48	SF	5	10+ years			
	Floor Drain	Engineer's Toilet in 195A	1	EA	7	6-10 years			
	Lavatory	Engineer's Toilet in 195A	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Engineer's Toilet in 195A	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Engineer's Toilet in 195A	1	EA	7	6-10 years			
	Showers	Engineer's Toilet in 195A	1	EA	4	0-1 year	No fixtures		
	Walls - Plaster/Drywall	Engineer's Toilet in 195A	184	SF	6	10+ years			
	Water Closet	Engineer's Toilet in 195A	1	EA	7	10+ years			
	Accessories	Unisex Clinic Toilet	54	SF	7	6-10 years			
	Ceiling - Lay-in	Unisex Clinic Toilet	54	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Unisex Clinic Toilet	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Unisex Clinic Toilet	54	SF	7	10+ years			
	Floor Drain	Unisex Clinic Toilet	1	EA	7	10+ years			
	Hand Dryer	Unisex Clinic Toilet	1	EA	7	6-10 years			
	Lavatory	Unisex Clinic Toilet	1	EA	7	10+ years			
	Lighting - Lay-in	Unisex Clinic Toilet	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Unisex Clinic Toilet	148	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Unisex Clinic Toilet	148	SF	7	10+ years			
	Water Closet	Unisex Clinic Toilet	1	EA	7	10+ years			

Category: Classroom **Building: Addition 1**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #146 (Office)						
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Splined	1st Floor	596	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	596	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,218	SF	7	10+ years	

Campus Name: Senn HS Page : 59 of 95 Assessment Date: 07/18/2022





49 (Faculty Lounge) ling - Splined ors - Transom Window ors - Wood Doors inclu hw or - Concrete nting - Pendent/Surface rage/ Closet lls - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted nting - Pendent/Surface	Location 1st Floor	1,180 33 2 1,180 18 152 1,778	SF SF EA SF EA SF SF	6 7 6 5 6 5 6	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
49 (Faculty Lounge) ling - Splined ors - Transom Window ors - Wood Doors inclu hw or - Concrete nting - Pendent/Surface rage/ Closet lls - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,180 33 2 1,180 18 152 1,778	SF SF EA SF EA SF	6 7 6 5 6 5	10+ years 10+ years 10+ years 10+ years 6-10 years	Comments
ling - Splined ors - Transom Window ors - Wood Doors inclu hw or - Concrete onting - Pendent/Surface rage/ Closet Ills - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	33 2 1,180 18 152 1,778	SF EA SF EA SF	7 6 5 6 5	10+ years 10+ years 10+ years 6-10 years	
ling - Splined ors - Transom Window ors - Wood Doors inclu hw or - Concrete onting - Pendent/Surface rage/ Closet Ills - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	33 2 1,180 18 152 1,778	SF EA SF EA SF	7 6 5 6 5	10+ years 10+ years 10+ years 6-10 years	
ors - Transom Window ors - Wood Doors inclu hw or - Concrete inting - Pendent/Surface rage/ Closet lls - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	33 2 1,180 18 152 1,778	SF EA SF EA SF	7 6 5 6 5	10+ years 10+ years 10+ years 6-10 years	
ors - Wood Doors inclu hw or - Concrete inting - Pendent/Surface rage/ Closet ills - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2 1,180 18 152 1,778	EA SF EA SF	6 5 6 5	10+ years 10+ years 6-10 years	
or - Concrete Inting - Pendent/Surface Inting - Pendent/Surface Interpretation of the second of the	1st Floor 1st Floor 1st Floor 1st Floor	1,180 18 152 1,778	SF EA SF	5 6 5	10+ years 6-10 years	
nting - Pendent/Surface rage/ Closet lls - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor	18 152 1,778	EA SF	6 5	6-10 years	
rage/ Closet Ils - Plaster/Drywall 86 ROTC (Store Room) Iling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor 1st Floor	152 1,778	SF	5		
Ils - Plaster/Drywall 86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor 1st Floor	1,778			10+ vears	
86 ROTC (Store Room) ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted	1st Floor	,	SF	6	- J	
ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted		407		U	10+ years	Peeling paint throughout
ling - Plaster/Drywall ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted		407				
ors - Wood Doors inclu hw or - Concrete Epoxy/ Painted		447	SF	6	10+ years	
or - Concrete Epoxy/ Painted	13111001	1	EA	6	10+ years	
	1st Floor	497	SF	5	10+ years	
ming - i chuchivouriace	1st Floor	8	EA	5 7	6-10 years	
rker Board	1st Floor	5	LF	6	6-10 years	
lls - Masonry	1st Floor	1,193	SF	6	10+ years	
			SF	7	•	
lls - Plaster/Drywall	1st Floor	216	SF	/	10+ years	
35 (Office)						
Units	2nd Floor	1	EA	7	6-10 years	
ling - Lay-in	2nd Floor	217	SF	6	10+ years	
ors - Transom Window	2nd Floor	11	SF	7	10+ years	
ors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
or - Wood	2nd Floor	217	SF	7	10+ years	
nting - Lay-in	2nd Floor	4	EΑ	7	6-10 years	
lls - Plaster/Drywall	2nd Floor	707	SF	5	10+ years	Water damage throughout
30 (Office)						
,	2nd Floor	512	OE.	7	10 L VOORO	
					-	
					•	
					•	
		_			•	
					•	
lls - Plaster/Drywall	2nd Floor	1,398	SF	7	10+ years	
40 (Regular Classroom)	2nd Floor	9	LF	6	10+ years	
40 (Regular Classroom) sework					•	
sework				4		
,				•		
lir or or or rk	ework	ang - Plaster/Drywall 2nd Floor s - Transom Window 2nd Floor s - Wood Doors inclu hw 2nd Floor c - Tile/Sheet 2nd Floor ing - Pendent/Surface 2nd Floor er Board 2nd Floor s - Masonry 2nd Floor s - Plaster/Drywall 2nd Floor 0 (Regular Classroom) ework 2nd Floor and Floor 2nd Floor 2nd Floor 2nd Floor	ng - Plaster/Drywall 2nd Floor 512 s - Transom Window 2nd Floor 44 s - Wood Doors inclu hw 2nd Floor 2 c - Tile/Sheet 2nd Floor 512 ing - Pendent/Surface 2nd Floor 8 er Board 2nd Floor 12 s - Masonry 2nd Floor 174 s - Plaster/Drywall 2nd Floor 1,398 O (Regular Classroom) 9 ework 2nd Floor 9 ng - Lay-in 2nd Floor 726	ng - Plaster/Drywall 2nd Floor 512 SF s - Transom Window 2nd Floor 44 SF s - Wood Doors inclu hw 2nd Floor 2 EA r - Tile/Sheet 2nd Floor 512 SF ing - Pendent/Surface 2nd Floor 8 EA er Board 2nd Floor 12 LF s - Masonry 2nd Floor 174 SF s - Plaster/Drywall 2nd Floor 1,398 SF O (Regular Classroom) 9 LF ework 2nd Floor 9 LF ng - Lay-in 2nd Floor 726 SF	ng - Plaster/Drywall 2nd Floor 512 SF 7 s - Transom Window 2nd Floor 44 SF 7 s - Wood Doors inclu hw 2nd Floor 2 EA 7 c - Tile/Sheet 2nd Floor 512 SF 7 ing - Pendent/Surface 2nd Floor 8 EA 7 eer Board 2nd Floor 12 LF 7 s - Masonry 2nd Floor 174 SF 7 s - Plaster/Drywall 2nd Floor 1,398 SF 7 O (Regular Classroom) 9 LF 6 ework 2nd Floor 9 LF 6 ng - Lay-in 2nd Floor 726 SF 6	ng - Plaster/Drywall 2nd Floor 512 SF 7 10+ years s - Transom Window 2nd Floor 44 SF 7 10+ years s - Wood Doors inclu hw 2nd Floor 2 EA 7 10+ years s - Tile/Sheet 2nd Floor 512 SF 7 10+ years ing - Pendent/Surface 2nd Floor 8 EA 7 6-10 years ser Board 2nd Floor 12 LF 7 6-10 years s - Masonry 2nd Floor 174 SF 7 10+ years s - Plaster/Drywall 2nd Floor 1,398 SF 7 10+ years ework 2nd Floor 9 LF 6 10+ years ework 2nd Floor 726 SF 6 10+ years

Campus Name: Senn HS Page : 60 of 95 Assessment Date: 07/18/2022





Catego	ry : Classroom		В	uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classroo	om #241 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	726	SF	7	10+ years	
	Chalk Board	2nd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	 1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classras	om #242 (Regular Classroom)						
Classion	` ` ` ` ,	0 15				40	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	671	SF	6	10+ years	
	Chalk Board	2nd Floor	33	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	_1	EA	6	10+ years	
	Floor - Wood	2nd Floor	671	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #243 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Damaged tiles
	Chalk Board	2nd Floor	44	LF	4	2-5 years	•
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	726	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #244 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	726	SF	6	10+ years	
	Johning - Lay-III	ZIIU I IUUI	720	OI.	O	10+ years	





Catego	ry : Classroom		В	uilding	: Additi		5 N Gierwood Avenoe, Onicago, ie 00000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
_Classroo	om #245 (Special Program)						
	Casework	2nd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	367	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	367	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	858	SF	7	10+ years	
Classroo	om #246 East (Special Program)						
	AC Units	2nd Floor	2	EA	5	0-1 year	Missing covers
	Casework	2nd Floor	11	LF	6	10+ years	WildSirig GOVCIS
	Ceiling - Lay-in	2nd Floor	594	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	594	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,028	SF	7	10+ years	
Classroo	om #246 West (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	490	SF	6	10+ years	
	Chalk Board	2nd Floor	490	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu riw	2nd Floor	490	SF	7	10+ years 10+ years	
	Lighting - Lay-in	2nd Floor	490 12	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	955	SF	6		
	Walls - Plaster/Drywall Wireless System	2nd Floor 2nd Floor	955 1	SF EA	6 7	10+ years	
	WITE ESS SYSTEIN	ΖΠά ΓΙΟΟΙ	ı	EA	,	6-10 years	





Catego	ry : Classroom		В	uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #247 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	726	SF	7	10+ years	
	Chalk Board	2nd Floor	44	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	726	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classroo	om #248 East (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	658	SF	6	10+ years	
	Chalk Board	2nd Floor	19	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	658	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,147	SF	6	10+ years	
Classroo	om #248 West (Special Program)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	490	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	490	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	955	SF	7	10+ years	
Classroo	om #249 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	816	SF	6	10+ years	
	Chalk Board	2nd Floor	37	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	816	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,100	SF	6	10+ years	
	•		• • •			,	







Catego	ry : Classroom		В	uilding	: Additi		O N Gleriwood AVENDE, Chicago, iL 60660
o ano go	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #336 (Art Room)		-			•	
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,767	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	30	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	1	EΑ	7	10+ years	Trate: damage
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	1,797	SF	5	10+ years	
	Lighting - Lay-in	3rd Floor	36	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	167	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,554	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	m #337 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	220	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	223	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	642	SF	7	10+ years	
Classroo	m #340 (Regular Classroom)						
<u> </u>	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	29	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	5	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,299	SF	6	10+ years	
_Classroc	m #343 East (Computer Lab)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	982	SF	7	10+ years	
	Chalk Board	3rd Floor	37	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	





Catego	ry : Classroom		Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Wood	3rd Floor	982	SF	5	10+ years	Floor needs to be refinished	
	Lighting - Lay-in	3rd Floor	15	EA	6	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,178	SF	7	10+ years		
Classroc	om #343 West (Computer Lab)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	9	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	508	SF	7	10+ years		
	Chalk Board	3rd Floor	8	ĹF	4	2-5 years		
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years		
	Floor - Wood	3rd Floor	508	SF	5	10+ years	Floor needs to be refinished	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	. ISSI NOGGO TO DO TOMINISMO	
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	882	SF	7	10+ years		
	Wireless System	3rd Floor	1	EA	7	6-10 years		
	Wheless System	314 F1001	ı	EA	,	6-10 years		
lassroc	m #344 (Art Room)							
	Casework	3rd Floor	33	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	1,122	SF	6	10+ years		
	Chalk Board	3rd Floor	33	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Wood	3rd Floor	1,122	SF	5	10+ years		
	Lighting - Lay-in	3rd Floor	33	EA	6	6-10 years		
	Marker Board	3rd Floor	24	LF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,295	SF	6	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroc	om #345 (Special Program)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	10	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	361	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Water damage	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	vvater damage	
	Doors - Wood Doors inclu hw	3rd Floor	24 1	EA	7	2-5 years 10+ years		
	Floor - Wood Doors inclu riw	3rd Floor		SF	, 5	•	Wood floor needs to be refinished	
			367			10+ years	wood floor fleeds to be refinished	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	796	SF	6	10+ years		
Classroc	nm #346 Fast (Regular Classroom)							
	Casework	3rd Floor	9	LF	6	10+ years		





Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	718	SF	6	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	718	SF	7	10+ years	Floor was just waxed
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	·
	Walls - Plaster/Drywall	3rd Floor	1,010	SF	6	10+ years	
Classroo	om #346 West (Vacant)						
	Ceiling - Lay-in	3rd Floor	470	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	470	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	812	SF	7	10+ years	
Classroc	om #347 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	743	SF	6	10+ years	
	Chalk Board	3rd Floor	38	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	743	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,022	SF	7	10+ years	
Classroc	om #348 (Regular Classroom)						
	Casework	3rd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,194	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Buckled tile
	Chalk Board	3rd Floor	30	LF	4	2-5 years	200.000
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor		EA	6	10+ years	
	Floor - Wood	3rd Floor	1,200	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	33	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,344	SF	7	10+ years	
Classroo	om #349 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	810	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Buckled tile
	Chalk Board	3rd Floor	47	LF	4	2-5 years	Duoniou tiio
	Shair Board	314 1 1001	47	LI	7	2-0 years	

Campus Name: Senn HS Page : 66 of 95 Assessment Date: 07/18/2022





Category : Classroom

Building : Addition 1

	.,							
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Wood	3rd Floor	816	SF	5	10+ years		
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,100	SF	6	10+ years		

Category: Interior Building: Addition 1

Group Item - Type Corridor Ceiling - Lay-in Drinking Fountains - Single Water Co	Location First Floor Corridors	Quantity	UOM	Rank	Recommend Replacement	Comments
_Corridor Ceiling - Lay-in		Quantity	UOM	Rank	Replacement	Comments
Ceiling - Lay-in	First Floor Corridors					Commonto
	First Floor Corridors					
Drinking Fountains - Single Water Co		5,633	SF	6	10+ years	
	poler First Floor Corridors	2	EA	7	10+ years	
Floor - Terrazzo	First Floor Corridors	2,503	SF	7	10+ years	
Floor - Tile/Sheet	First Floor Corridors	3,130	SF	7	10+ years	
Lighting - Lay-in	First Floor Corridors	80	EA	7	6-10 years	
Student Lockers - One Tier	First Floor Corridors	125	EA	7	10+ years	
Walls - Masonry	First Floor Corridors	2,023	SF	6	10+ years	
Walls - Plaster/Drywall	First Floor Corridors	6,349	SF	7	10+ years	
Ceiling - Plaster/Drywall	First Floor Vestibule	332	SF	6	10+ years	
Floor - Terrazzo	First Floor Vestibule	332	SF	6	10+ years	
Lighting - Pendent/Surface	First Floor Vestibule	14	EA	7	6-10 years	Quantity changed to match current observations
Walls - Masonry	First Floor Vestibule	643	SF	6	10+ years	observations
Walls - Plaster/Drywall	First Floor Vestibule	916	SF	7	10+ years	
Ceiling - Lay-in	Health Clinic	148	SF	7	10+ years	
Doors - Wood Doors include hw	Health Clinic	4	EA	7	10+ years	
Floor - Tile/Sheet	Health Clinic	148	SF	7	10+ years	
Lighting - Lay-in	Health Clinic	3	EA	7	6-10 years	
Walls - Plaster/Drywall	Health Clinic	650	SF	7	10+ years	
Ceiling - Lay-in	Second Floor Corridors	2,831	SF	6	10+ years	
Ceiling - Lay-in	Second Floor Corridors	39	SF	4	0-1 year	Water damage
Ceiling - Plaster/Drywall	Second Floor Corridors	26	SF	7	10+ years	vvator damage
Drinking Fountains - Single Water Co		2	EA	7	10+ years	
Floor - Terrazzo	Second Floor Corridors	334	SF	7	10+ years	
Floor - Tile/Sheet	Second Floor Corridors	2,581	SF	7	10+ years	
Floor - Tile/Sheet	Second Floor Corridors	_,001	SF	4	0-1 year	Damaged tile
Lighting - Lay-in	Second Floor Corridors	37	EΑ	7	6-10 years	zamagea me
Student Lockers - One Tier	Second Floor Corridors	140	EA	7	10+ years	
Walls - Masonry	Second Floor Corridors	2,056	SF	6	10+ years	
Walls - Plaster/Drywall	Second Floor Corridors	2,166	SF	7	10+ years	
Ceiling - Lay-in	Third Floor Corridor	2,795	SF	6	10+ years	
Ceiling - Lay-in	Third Floor Corridor	75	SF	4	0-1 year	Water damage
Ceiling - Plaster/Drywall	Third Floor Corridor	26	SF	7	10+ years	
Drinking Fountains - Single Water Co		2	EA	7	10+ years	

Campus Name: Senn HS Page: 67 of 95 Assessment Date: 07/18/2022





Catego	ory : Interior		В	uilding	: Additi	on 1	<u> </u>
J				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	Third Floor Corridor	334	SF	7	10+ years	
	Floor - Tile/Sheet	Third Floor Corridor	2,572	SF	7	10+ years	
	Lighting - Lay-in	Third Floor Corridor	42	EA	7	6-10 years	
	Student Lockers - One Tier	Third Floor Corridor	147	EA	7	10+ years	
	Walls - Masonry	Third Floor Corridor	2,056	SF	6	10+ years	
	Walls - Plaster/Drywall	Third Floor Corridor	1,657	SF	6	10+ years	
Safety							
	Camera Viewing Station	Office 145A	1	EA	7	6-10 years	
	Security Cameras	Office 145A	6	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	Northeast Staircase	136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northeast Staircase	162	SF	7	10+ years	
	Floor - Terrazzo	Northeast Staircase	260	SF	7	10+ years	
	Handrails	Northeast Staircase	123	LF	7	10+ years	
	Lighting - Lay-in	Northeast Staircase	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Northeast Staircase	4	EA	7	6-10 years	
	Stairs - Terrazzo	Northeast Staircase	352	LF	7	10+ years	
	Walls - Masonry	Northeast Staircase	1,002	SF	6	10+ years	
	Walls - Masonry	Northeast Staircase	2	SF	4	0-1 year	Damaged base mold
	Walls - Plaster/Drywall	Northeast Staircase	1,507	SF	7	10+ years	
	Ceiling - Lay-in	Northwest Staircase	182	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest Staircase	505	SF	6	10+ years	
	Floor - Terrazzo	Northwest Staircase	418	SF	7	10+ years	
	Handrails	Northwest Staircase	128	LF	7	10+ years	
	Lighting - Lay-in	Northwest Staircase	7	EA	7	6-10 years	
	Lighting - Pendent/Surface	Northwest Staircase	6	EA	7	6-10 years	
	Stairs - Terrazzo	Northwest Staircase	499	LF	7	10+ years	
	Walls - Masonry	Northwest Staircase	1,085	SF	6	10+ years	
	Walls - Plaster/Drywall	Northwest Staircase	1,327	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Service Stair from rm 194 to rm 336	136	SF	5	10+ years	Water damage throughout
	Floor - Asphalt	Service Stair from rm 194 to rm 336	136	SF	6	10+ years	Metal floor
	Handrails	Service Stair from rm 194 to rm 336	92	LF	5	10+ years	
	Lighting - Pendent/Surface	Service Stair from rm 194 to rm 336	1	EA	6	6-10 years	
	Stairs - Asphalt	Service Stair from rm 194 to rm 336	193	LF	6	10+ years	Metal staircase
	Walls - Plaster/Drywall	Service Stair from rm 194 to rm 336	2,107	SF	5	10+ years	Water damage throughout
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	Changed to match current observation



Category : Exterior Building : Addition 2

tegory . Exterior		Recommend							
our Hom Type	Location	Ouantitu	HOM	Donk		Comments			
oup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
rance	_								
Exterior Doors - Exterior Steel Door	5 - East	3	EA	6	6-10 years				
Exterior Doors - Transom Lite	5 - East	3	EA	6	10+ years				
Exterior Stairs - Stone	5 - East	40	LF	5	10+ years				
Exterior Doors - Exterior Steel Door	6 - North	3	EA	6	6-10 years				
Exterior Doors - Transom Lite	6 - North	3	EA	6	10+ years				
Exterior Stairs - Stone	6 - North	67	LF	5	10+ years				
Exterior Stairs - Stone	6 - North	14	LF	4	0-1 year	Broken trip hazard			
Exterior Doors - Exterior Steel Door	7 - East	2	EA	6	6-10 years				
Exterior Doors - Transom Lite	7 - East	2	EA	6	10+ years				
Exterior Stairs - Stone	7 - East	152	LF	5	10+ years				
Exterior Stairs - Stone	7 - East	8	LF	4	0-1 year	Cracked			
Exterior Doors - Exterior Steel Door	8 - South	2	EA	6	6-10 years				
Exterior Doors - Transom Lite	8 - South	2	EA	6	10+ years				
Exterior Stairs - Stone	8 - South	20	LF	5	6-10 years				
Exterior Doors - Exterior Steel Door	9 - West	6	EA	6	10+ years				
Exterior Doors - Transom Lite	9 - West	4	EΑ	6	6-10 years				
					,				
ndation									
Foundation - Concrete	Entire Building	822	LF	7	10+ years				
Superstructure - Concrete	Entire Building	37,798	SF	7	10+ years				
	g	21,122	-	-	, , , , , , , , , , , , , , , , , , , ,				
ting									
Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	6-10 years				
Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	6-10 years				
3 . 3	3				, , , , , ,				
System									
Coping - Stone	M - West Center Low	47	LF	6	10+ years				
Downspouts - Exterior Downspouts	M - West Center Low	70	LF	6	10+ years				
Parapet - Parapet < 16" Height	M - West Center Low	60	LF	6	10+ years				
Parapet - Parapet > 30"	M - West Center Low	47	LF	6	10+ years				
Roof - Modified Bitumen	M - West Center Low	3,000	SF	7	10+ years				
Roof - Modified Bitumen	M - West Center Low	5,128	SF	4	0-1 year	Leaks, failed flashing			
Roof Structure - Steel with Clay Tile Arch	M - West Center Low	8,128	SF	7	10+ years	,			
Access Ladder - Metal	N - Southwest	1	ĒΑ	7	10+ years				
Access Ladder - Metal	N - Southwest	1	EA	4	0-1 year	Dangerous ladder, not attached			
		•		·	-	bottom rung missing			
Coping - Terra Cotta	N - Southwest	216	LF	6	10+ years				
Coping - Terra Cotta	N - Southwest	20	LF	6	10+ years				
Downspouts - Exterior Downspouts	N - Southwest	96	LF	6	10+ years				
Downspouts - Interior Downspouts	N - Southwest	100	LF	6	10+ years				
Parapet - Parapet < 16" Height	N - Southwest	20	LF	6	10+ years				

Campus Name: Senn HS Page : 69 of 95 Assessment Date: 07/18/2022







Group							
Group	- No. 1985					Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet > 30"	N - Southwest	216	LF	6	10+ years	
	Roof - Modified Bitumen	N - Southwest	5,000	SF	5	1-2 years	Cracking, worn
	Roof - Modified Bitumen	N - Southwest	5,880	SF	4	0-1 year	Flashing failing, leaks, bubbling
	Roof Hatch - Metal	N - Southwest	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	N - Southwest	10,880	SF	7	10+ years	
	Access Ladder - Metal	O - South Lower	2	EA	7	10+ years	
	Coping - Metal	O - South Lower	87	LF	6	10+ years	
	Parapet - 16" - 30" Height	O - South Lower	87	LF	6	10+ years	
	Roof - Modified Bitumen	O - South Lower	3,206	SF	5	2-5 years	
	Roof - Modified Bitumen	O - South Lower	500	SF	4	1-2 years	Cracks, leaks, plant growth
	Roof Hatch - Metal	O - South Lower	1	EA	7	10+ years	Gracito, realto, plant grantin
	Roof Structure - Steel with Clay Tile Arch	O - South Lower	3,706	SF	7	10+ years	
	Access Ladder - Metal	P - East	3,700	EA	7	10+ years	
	Coping - Metal	P - East	377	LF	6	10+ years	
	Coping - Metal Coping - Terra Cotta	P - East	88	LF	6	10+ years	
	Downspouts - Exterior Downspouts	P - East	288	LF	6	,	
				LF		10+ years	
	Parapet - 16" - 30" Height	P - East	465		6	10+ years	
	Roof - Metal	P - East	180	SF	7	10+ years	B 111: (3 10 1:
	Roof - Modified Bitumen	P - East	15,030	SF	4	1-2 years	Bubbling, failed flashing
	Roof Hatch - Metal	P - East	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	P - East	15,030	SF	7	10+ years	
<i>N</i> alls							
	Cheek-Wall - Stone	Entire Building	95	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	852	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,852	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	611	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	3,579	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	297	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	8,212	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	231	SF	3	0-1 year	Strapped areas
Windows							
	Guard - Guards perforated	Entire Building	5,097	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	100	SF	5	10+ years	
	Lintels - Steel	Entire Building	1,249	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	13,194	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	477	SF	6	10+ years	
Categor	y : Electrical		В	uilding	: Additio	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments





Catego	ry : Electrical		Building : Addition 2					
			<u> </u>					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	6	6-10 years		
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years		
	Exit Signs - Gym	Entire Building	5	EA	6	6-10 years		
	Emergency A/C Power - Corridors and	Entire Building	11,294	SF	6	6-10 years		
	Stairs	3	,			,		
	Emergency A/C Power - Gym	Entire Building	13,380	SF	6	6-10 years		
	Emergency A/C Power - Students Toilets	Entire Building	1,205	SF	6	6-10 years		
	Security System - CCTV	Entire Building	37,798	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	37,798	SF	6	6-10 years		
	Security System - CCTV	Entire Building	37,798	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	37,798	SF	6	6-10 years		
	Security System - Initiasion Detection	Littile Building	31,190	OI.	U	0-10 years		
lain Se								
	PA System	Entire Building	37,798	SF	5	6-10 years	Connected to the main building	
ower D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	6	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years		
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years		
	amp Main Distribution Panels - Less than 400	Entiro Building	2	EA	7	10 L Vooro		
		Entire Building	2	EA	,	10+ years		
	amp Transformers - 120/240 - 120/208	Entire Building	1	EA	4	2-5 years	Beyond service life	
	w Fina Bratastian	•	-	ااما!	. A al al!4!		·	
atego	ry : Fire Protection			Building				
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
ire Alar	· · · · · · · · · · · · · · · · · · ·		•			'		
	Fire Alarm Strobe Lights	Entire Building	37,798	SF	6	10+ years		
	Fire Alarm_System	Entire Building	37,798	SF	6	10+ years		
	Tile Alami_System	Littile Building	31,190	OI.	U	10+ years		
Category : Mechanical			В	Building				
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
•	· ·	Location	Quantity	00	Italik	Replacement	Comments	
шпапс	ling Systems	4 ot 5 le e v		Г^		0.40		
	Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 8001 - 15000 cfm	1st Floor	1	EA	6	6-10 years		
	Air Intake	1st Floor	1	EA	6	6-10 years		
	Auxiliaries - 8001 - 15000 cfm	1st Floor	1	EA	6	6-10 years		
	Return Duct Work - Masonry and Ducts-	1st Floor	150	LF	6	6-10 years		
	Missing or Existing Shaft				-	,		
	Zone Dampers	1st Floor	5	EA	6	6-10 years		
	Jama: Cann LIC		Dogo : 71 of 05				Assessment Date: 07/19	

Assessment Date: 07/18/2022 Campus Name: Senn HS Page: 71 of 95





Catego	ry : Mechanical		Building : Addition 2						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Greater than 35000 cfm	Mechanical Room	1	EA	6	6-10 years			
	Air Intake	Mechanical Room	1	EA	6	6-10 years			
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	6	6-10 years			
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical Room	10	EA	6	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	6-10 years			
	Zone Dampers	Mechanical Room	39	EA	6	6-10 years			
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	2	EA	6	10+ years	No data plates available		
Heating	Devices								
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	10+ years			
	Fin Tube - Hot Water	Entire Building	40	LF	6	10+ years			
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years			
Mechani	cal Plumbing								
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years			
	Dual Temperature Pump - Less than 10	Entire Building	2	EA	6	10+ years			
Tempera	ature Control								
	DDC System	Entire Building	37,798	SF	4	1-2 years	System is completely non functional		
	Thermostats - DDC	Entire Building	42	EA	6	10+ years			
	Thermostats - DDC	Entire Building	2	EA	6	6-10 years	Temperature sensors are working		
Ventilation	on								
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years			
	Lab Exhaust Hood	Entire Building	1	EA	6	10+ years			
	Roof Mounted Duct Work	Entire Building	20	LF	7	10+ years			
Catego	Category : Plumbing			uilding					
	_				_	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	37,798	SF	7	10+ years			
	Domestic Piping-Hot Water Return Risers	Entire Building	37,798	SF	7	10+ years			
	Domestic Piping-Hot Water from Risers to	Entire Building	37,798	SF	7	10+ years			

Campus Name: Senn HS Page : 72 of 95 Assessment Date: 07/18/2022





Catego	ry : Plumbing		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	37,798	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	37,798	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	37,798	SF	7	10+ years	
	Sanitary Piping	Entire Building	37,798	SF	6	10+ years	
	Storm Piping	Entire Building	37,798	SF	6	10+ years	
	Vent Piping	Entire Building	37,798	SF	6	10+ years	
Pumps							
	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years	

Category: Room **Building: Addition 2**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Qualitity	OCIVI	Nalik	Replacement	Comments
Administ	rative Suites/Offices	450 Canabla Office in Court 4		ΓΛ		0.5.40000	
	AC Unit	150 Coach's Office in Gym 1	7	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	150 Coach's Office in Gym 1	272	SF	6	10+ years	10/
	Ceiling - Plaster/Drywall	150 Coach's Office in Gym 1	20	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	150 Coach's Office in Gym 1	2	EA	6	10+ years	
	Floor - Tile/Sheet	150 Coach's Office in Gym 1	272	SF	7	10+ years	Changed to match current observations
	Floor - Tile/Sheet	150 Coach's Office in Gym 1	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	150 Coach's Office in Gym 1	4	EA	6	6-10 years	
	Power Distribution	150 Coach's Office in Gym 1	2	EA	7	10+ years	
	Walls - Plaster/Drywall	150 Coach's Office in Gym 1	520	SF	6	10+ years	
_Gymnasi	ia						
•	Ceiling - Plaster/Drywall	151 Gym	3,350	SF	7	10+ years	
	Doors - Transom Window	151 Gym	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	151 Gym	5	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	151 Gym	3,350	SF	7	6-10 years	Changed to match current observations
	Lighting - Metal Halide/Sodium Vapor	151 Gym	12	EA	7	6-10 years	
	Storage/ Closet	151 Gym	300	SF	5	10+ years	
	Walls - Masonry	151 Gym	1,680	SF	7	10+ years	
	Walls - Plaster/Drywall	151 Gym	3,670	SF	7	10+ years	
	Ceiling - Plaster/Drywall	155 Wrestling Gym former girls locker	1,380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	155 Wrestling Gym former girls locker	2	EA	7	10+ years	

Campus Name: Senn HS Page: 73 of 95 Assessment Date: 07/18/2022





Category : Room			Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	155 Wrestling Gym former girls locker	2	EA	7	2-5 years	Newly remodeled	
	Floor - Sport Flooring	155 Wrestling Gym former girls locker	1,380	SF	7	10+ years		
	Lighting - Metal Halide/ High Pressure Sodium	155 Wrestling Gym former girls locker	12	EA	7	10+ years		
	Storage/ Closet	155 Wrestling Gym former girls locker	120	SF	7	10+ years		
	Walls - Concrete Block	155 Wrestling Gym former girls locker	1,776	SF	7	10+ years		
	Bleacher Seating	Gymnasium 1	190	EA	6	10+ years		
	Ceiling - Plaster/Drywall	Gymnasium 1	9,620	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Gymnasium 1	80	SF	5	0-1 year	Water damage	
	Doors - Steel Doors incl hw	Gymnasium 1	1	EA	6	10+ years	rrator damage	
	Doors - Wood Doors inclu hw	Gymnasium 1	6	EA	7	10+ years		
	Floor - Epoxy/ Painted	Gymnasium 1	2,200	SF	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Gymnasium 1	100	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Gymnasium 1	4	SF	4	0-1 year	Missing	
	Floor - Wood	Gymnasium 1	7,400	SF	7	10+ years	WildSirig	
	Lighting - Metal Halide/Sodium Vapor	Gymnasium 1	34	EA	7	6-10 years		
	Scoreboards	Gymnasium 1	2	EA	5	6-10 years	Quantity changed to match current observations	
	Sound System	Gymnasium 1	1	EA	7	6-10 years	0.0001744.0110	
	Storage/ Closet	Gymnasium 1	340	SF	7	10+ years		
	Storage/ Closet	Gymnasium 1	120	SF	7	10+ years		
	Walls - Masonry	Gymnasium 1	8,400	SF	7	10+ years		
	,	- ,	2, 122			, , , , , , , , , , , , , , , , , , , ,		
Locker/SI	nower Room							
	Accessories	Men's Gym Locker	1,500	SF	7	6-10 years		
	Benches, ped mounted	Men's Gym Locker	46	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Men's Gym Locker	1,500	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Men's Gym Locker	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Men's Gym Locker	1,500	SF	7	10+ years		
	Floor Drain	Men's Gym Locker	3	EA	7	10+ years		
	Hand Dryer	Men's Gym Locker	6	EA	7	6-10 years		
	Lavatory	Men's Gym Locker	3	EA	7	10+ years		
	Lighting - Pendent/Surface	Men's Gym Locker	20	EA	7	10+ years		
	Partitions	Men's Gym Locker	2	EA	7	10+ years		
	Showers	Men's Gym Locker	3	EA	7	10+ years		
	Student Lockers - One Tier	Men's Gym Locker	48	EA	7	10+ years		
	Student Lockers - Two Tier	Men's Gym Locker	63	EA	7	10+ years		
	Urinals	Men's Gym Locker	2	EA	7	10+ years		
	Walls - Concrete Block	Men's Gym Locker	540	SF	7	10+ years		
	Walls - Masonry	Men's Gym Locker	270	SF	7	10+ years		

Campus Name: Senn HS Page : 74 of 95 Assessment Date: 07/18/2022





Category : Room

Ruilding : Addition 2

Catego	ry : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Plaster/Drywall	Men's Gym Locker	270	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Men's Gym Locker	540	SF	7	10+ years	
	Water Closet	Men's Gym Locker	2	EA	7	10+ years	
	Accessories	Unisex Locker in 155	97	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Locker in 155	97	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Locker in 155	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Locker in 155	97	SF	7	10+ years	
	Floor Drain	Unisex Locker in 155	1	EA	7	10+ years	
	Hand Dryer	Unisex Locker in 155	1	EA	7	6-10 years	
	Lavatory	Unisex Locker in 155	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex Locker in 155	2	EA	7	10+ years	
	Showers	Unisex Locker in 155	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Unisex Locker in 155	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex Locker in 155	300	SF	7	10+ years	
	Water Closet	Unisex Locker in 155	1	ĒΑ	7	10+ years	
	Accessories	Unisex Shower Room	110	SF	7	6-10 years	
	Benches, ped mounted	Unisex Shower Room	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex Shower Room	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Shower Room	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Shower Room	110	SF	7	10+ years	
	Floor Drain	Unisex Shower Room	1	EA	7	10+ years	
	Hand Dryer	Unisex Shower Room	1	EA	7	6-10 years	
	Lavatory	Unisex Shower Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex Shower Room	2	EA	7	10+ years	
	Showers	Unisex Shower Room	1	EA	7	10+ years	
	Student Lockers - One Tier	Unisex Shower Room	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex Shower Room	378	SF	7	10+ years	
	Water Closet	Unisex Shower Room	1	EA	7	10+ years	
	Accessories	Women's Gym Locker	1,500	SF	7	6-10 years	
	Benches, ped mounted	Women's Gym Locker	46	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Women's Gym Locker	1,500	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's Gym Locker	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Gym Locker	1,500	SF	7	10+ years	
	Floor Drain	Women's Gym Locker	3	EA	7	10+ years	
	Hand Dryer	Women's Gym Locker	6	EA	7	6-10 years	
	Lavatory	Women's Gym Locker	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's Gym Locker	20	EA	7	10+ years	
	Partitions	Women's Gym Locker	4	EA	7	10+ years	
	Showers	Women's Gym Locker	3	EA	7	10+ years	
	Student Lockers - One Tier	Women's Gym Locker	48	EA	7	10+ years	
	Student Lockers - Two Tier	Women's Gym Locker	63	EA	7	10+ years	
	Walls - Concrete Block	Women's Gym Locker	540	SF	7	10+ years	
	Walls - Masonry	Women's Gym Locker	270	SF	7	10+ years	
	Walls - Plaster/Drywall	Women's Gym Locker	270	SF	7	10+ years	
	i idotoi/Diywan	Tromond Sym Lookor	210	٥.	•	. o . youro	

Campus Name: Senn HS Page : 75 of 95 Assessment Date: 07/18/2022





Catego	ry : Room	Building : Addition 2					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	Women's Gym Locker	540	SF	7	10+ years	
	Water Closet	Women's Gym Locker	4	EA	7	10+ years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	90	SF	5	10+ years	Water damage in the wall
	Janitor's Closet	1st Floor	50	SF	5	10+ years	Transcript in the frame
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	950	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	712	SF	7	10+ years	
	Storage Room	1st Floor	18	SF	5	10+ years	
	Janitor's Closet	2nd Floor	25	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	150	SF	7	•	
	Janitor's Closet	3rd Floor	62	SF SF	, 5	10+ years	
						10+ years	
	Storage Room	3rd Floor	178	SF	5	10+ years	
	Storage Room	3rd Floor	56	SF	5	10+ years	
	Storage Room	3rd Floor	390	SF	5	10+ years	
	Air Tunnel	Basement	2,730	SF	5	10+ years	
	Air Tunnel	Basement	1,300	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	350	SF	5	10+ years	
Prep Ro	om						
•	Casework	in Science Lab 100	40	LF	7	10+ years	
	Ceiling - Plaster/Drywall	in Science Lab 100	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	in Science Lab 100	1	EΑ	7	10+ years	
	Floor - Tile	in Science Lab 100	230	SF	7	10+ years	
	Lighting - Pendent/Surface	in Science Lab 100	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	in Science Lab 100	637	SF	7	10+ years	
	Work Sink	in Science Lab 100	1	EA	7	10+ years	
	Casework	in Science Lab 100	30	LF	7	•	
				SF		10+ years	
	Ceiling - Lay-in	in Science Lab 105	326		7	10+ years	
	Doors - Transom Window	in Science Lab 105	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	in Science Lab 105	2	EA	7	10+ years	
	Floor - Tile/Sheet	in Science Lab 105	326	SF	7	10+ years	Changed to match current observations
	Lighting - Lay-in	in Science Lab 105	3	EA	7	10+ years	
	Walls - Plaster/Drywall	in Science Lab 105	693	SF	7	10+ years	
	Work Sink	in Science Lab 105	1	ĒΑ	7	10+ years	
	Casework	in Science Lab 106	49	LF	7	10+ years	
	Ceiling - Plaster/Drywall	in Science Lab 106	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	in Science Lab 106	1	EA	7	10+ years	
	Floor - Tile/Sheet	in Science Lab 106	230	SF	7	10+ years	Changed to match current
	Lighting Dondont/Surface	in Science Lab 106	2	E^	6	6 10 2222	observations
	Lighting - Pendent/Surface	in Science Lab 106	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	in Science Lab 106	566	SF	7	10+ years	

Campus Name: Senn HS Page : 76 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Addition 2							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Work Sink	in Science Lab 106	1	EA	7	10+ years				
	Casework	in Science Lab 306	40	LF	7	10+ years				
	Ceiling - Plaster/Drywall	in Science Lab 306	230	SF	7	10+ years				
	Doors - Side-lite	in Science Lab 306	20	SF	7	10+ years				
	Doors - Steel Doors incl hw	in Science Lab 306	1	EA	7	10+ years				
	Floor - Tile	in Science Lab 306	230	SF	7	10+ years				
	Lighting - Pendent/Surface	in Science Lab 306	4	EA	6	6-10 years				
	Walls - Plaster/Drywall	in Science Lab 306	637	SF	7	10+ years				
	Work Sink	in Science Lab 306	1	EA	7	10+ years				
	Casework	in Science Lab 310 (east)	48	LF	7	10+ years				
	Ceiling - Plaster/Drywall	in Science Lab 310 (east)	230	SF	7	10+ years				
	Doors - Side-lite	in Science Lab 310 (east)	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	in Science Lab 310 (east)	1	EA	7	10+ years				
	Floor - Tile	in Science Lab 310 (east)	230	SF	7	10+ years				
	Lighting - Pendent/Surface	in Science Lab 310 (east)	4	EA	7	6-10 years				
	Walls - Plaster/Drywall	in Science Lab 310 (east)	543	SF	7	10+ years				
	Work Sink	in Science Lab 310 (east)	1	EA	7	10+ years				
	Ceiling - Plaster/Drywall	in Science Lab 310 (west)	130	SF	7	10+ years				
	Doors - Steel Doors incl hw	in Science Lab 310 (west)	1	EA	7	10+ years				
	Floor - Tile	in Science Lab 310 (west)	130	SF	7	10+ years				
	Lighting - Pendent/Surface	in Science Lab 310 (west)	3	EA	6	6-10 years				
	Walls - Plaster/Drywall	in Science Lab 310 (west)	608	SF	7	10+ years				
Restroor		450411	100	05		0.40				
	Accessories	150A Unisex Locker/Toilet Room in	128	SF	7	6-10 years				
	0 ''' Di	Coach's Office of Gym 1	400	0.5	•	4.0				
	Ceiling - Plaster/Drywall	150A Unisex Locker/Toilet Room in	128	SF	6	10+ years				
	5 W 15	Coach's Office of Gym 1		- 4	_	4.0				
	Doors - Wood Doors inclu hw	150A Unisex Locker/Toilet Room in	2	EA	7	10+ years				
		Coach's Office of Gym 1	_		_					
	Doors - Wood Doors inclu hw	150A Unisex Locker/Toilet Room in	1	EA	7	6-10 years	Replaced			
		Coach's Office of Gym 1			_					
	Floor - Tile Ceramic/ Porcelain	150A Unisex Locker/Toilet Room in	28	SF	6	10+ years				
		Coach's Office of Gym 1								
	Floor - Wood	150A Unisex Locker/Toilet Room in	100	SF	6	6-10 years				
		Coach's Office of Gym 1								
	Lavatory	150A Unisex Locker/Toilet Room in	1	EA	6	10+ years				
		Coach's Office of Gym 1								
	Lighting - Pendent/Surface	150A Unisex Locker/Toilet Room in	2	EA	7	6-10 years				
		Coach's Office of Gym 1								
	Lighting - Wall Mounted	150A Unisex Locker/Toilet Room in	1	EA	5	2-5 years				
		Coach's Office of Gym 1								
	Showers	150A Unisex Locker/Toilet Room in	1	EA	5	2-5 years				
		Coach's Office of Gym 1								





Category : Room Building : Addition 2							U N Gleriwood AVENUE, Criicago, iL 60660
				anding	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sioup	Student Lockers - One Tier	150A Unisex Locker/Toilet Room in	7	EA	5	6-10 years	Commonto
	Stadont Lookers - One flor	Coach's Office of Gym 1	•		O	o ro youro	
	Walls - Concrete Block	150A Unisex Locker/Toilet Room in	70	SF	7	10+ years	
		Coach's Office of Gym 1	. •	О.	•	.o. you.o	
	Walls - Plaster/Drywall	150A Unisex Locker/Toilet Room in	350	SF	6	10+ years	
	, , , , , , , , , , , , , , , , , , ,	Coach's Office of Gym 1		-	•	, , , , , , , , , , , , , , , , , , , ,	
	Walls - Plaster/Drywall	150A Unisex Locker/Toilet Room in	100	SF	4	0-1 year	Damaged
	•	Coach's Office of Gym 1				,	3
	Water Closet	150A Unisex Locker/Toilet Room in	1	EA	6	10+ years	
		Coach's Office of Gym 1					
	Accessories	1st Floor Boys	182	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	182	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	182	SF	7	10+ years	
	Floor Drain	1st Floor Boys	1	ĒA	7	10+ years	
	Hand Dryer	1st Floor Boys	1	ĒΑ	7	6-10 years	
	Lavatory	1st Floor Boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	4	ΕA	7	6-10 years	
	Partitions	1st Floor Boys	1	EΑ	7	10+ years	
	Urinals	1st Floor Boys	4	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor Boys	150	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	256	SF	7	10+ years	
	Water Closet	1st Floor Boys	1	EA	7	10+ years	
	Accessories	1st Floor Girls	325	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	325	SF	7	10+ years	
	Doors - Side-lite	1st Floor Girls	32	SF	7	10+ years	
	Doors - Transom Window	1st Floor Girls	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	325	SF	7	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	4	EA	7	6-10 years	
	Partitions	1st Floor Girls	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls	260	SF	7	10+ years	
	Walls - Masonry	1st Floor Girls	60	SF	7		
			430	SF		10+ years	
	Walls - Plaster/Drywall	1st Floor Girls		SF EA	7	10+ years	
	Water Closet	1st Floor Girls	5	SF	7	10+ years	
	Accessories	2nd Floor Girls	244	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	244	SF SF	7	10+ years	
	Doors - Side-lite	2nd Floor Girls	32		7	10+ years	
	Doors - Transom Window	2nd Floor Girls	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls	044	EA SF	7 7	10+ years	
	Floor - Tile	2nd Floor Girls	244	3F	1	10+ years	

Campus Name: Senn HS Page : 78 of 95 Assessment Date: 07/18/2022





Category : Room				Building : Addition 2						
_			_		Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	2nd Floor Girls	1	EA	4	10+ years	Cover missing			
	Hand Dryer	2nd Floor Girls	1	EA	7	6-10 years				
	Lavatory	2nd Floor Girls	2	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor Girls	4	EA	7	6-10 years				
	Partitions	2nd Floor Girls	6	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor Girls	300	SF	7	10+ years				
	Walls - Masonry	2nd Floor Girls	60	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor Girls	280	SF	7	10+ years				
	Water Closet	2nd Floor Girls	6	EA	7	10+ years				
	Accessories	3rd floor - Multi Unisex East	244	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd floor - Multi Unisex East	244	SF	7	10+ years				
	Doors - Side-lite	3rd floor - Multi Unisex East	32	SF	7	10+ years				
	Doors - Transom Window	3rd floor - Multi Unisex East	44	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd floor - Multi Unisex East	1	ĒΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd floor - Multi Unisex East	244	SF	7	10+ years				
	Floor Drain	3rd floor - Multi Unisex East	1	ĒΑ	7	10+ years				
	Hand Dryer	3rd floor - Multi Unisex East	1	EΑ	7	6-10 years				
	Lavatory	3rd floor - Multi Unisex East	2	EΑ	7	10+ years				
	Lighting - Pendent/Surface	3rd floor - Multi Unisex East	4	EΑ	7	6-10 years				
	Partitions	3rd floor - Multi Unisex East	6	EΑ	7	10+ years				
	Walls - Concrete Block	3rd floor - Multi Unisex East	300	SF	7	10+ years				
	Walls - Masonry	3rd floor - Multi Unisex East	60	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd floor - Multi Unisex East	280	SF	7	10+ years				
	Water Closet	3rd floor - Multi Unisex East	6	EA	7	10+ years				
	Accessories	Gym 1 Balcony Mens	90	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Gym 1 Balcony Mens	90	SF	6	10+ years	Peeling paint throughout			
	Doors - Wood Doors inclu hw	Gym 1 Balcony Mens	1	EA	7	10+ years	r ceiling paint tilloughout			
	Floor - Tile Ceramic/ Porcelain	Gym 1 Balcony Mens	90	SF	6	10+ years				
	Floor Drain	Gym 1 Balcony Mens	1	EA	7	10+ years				
	Lavatory	Gym 1 Balcony Mens	1	EA	7	-				
	Lighting - Pendent/Surface	Gym 1 Balcony Mens	1	EA	6	10+ years 6-10 years				
	Partitions	Gym 1 Balcony Mens	1	EA	7	10+ years				
	Urinals	Gym 1 Balcony Mens	1	EA	6	10+ years				
	Walls - Concrete Block	Gym 1 Balcony Mens	100	SF	7	•				
	Walls - Plaster/Drywall	Gym 1 Balcony Mens	270	SF	6	10+ years 10+ years	Peeling paint throughout			
	Water Closet	Gym 1 Balcony Mens	1	EA	6		reeming paint throughout			
	Accessories	Gym 1 Balcony Womens	120	SF		10+ years				
				SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Gym 1 Balcony Womens Gym 1 Balcony Womens	110 10	SF SF	6 4	10+ years	Water damage			
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw			SF EA		0-1 year	Water damage			
		Gym 1 Balcony Womens	1	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Gym 1 Balcony Womens	120		7	10+ years				
	Lavatory	Gym 1 Balcony Womens	1	EΑ	7	10+ years				
	Lighting - Pendent/Surface	Gym 1 Balcony Womens	2	EΑ	7	6-10 years				
	Partitions	Gym 1 Balcony Womens	2	EA	7	10+ years				

Campus Name: Senn HS Page : 79 of 95 Assessment Date: 07/18/2022





Catego	ry : Room		Building : Addition 2						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	Gym 1 Balcony Womens	600	SF	7	10+ years			
	Walls - Plaster/Drywall	Gym 1 Balcony Womens	135	SF	4	0-1 year	Water damage		
	Water Closet	Gym 1 Balcony Womens	2	EA	7	10+ years			
Catama	m Classica m		Ь	به ما المالي	. A al al!4!	a 2			
Catego	ry : Classroom		В	ullaing	: Additi	on ∠ Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	om #100 (Science Lab Level 1)		•			•			
	Casework	1st Floor	83	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,314	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Eve Wash Station	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	1,314	SF	7	10+ years			
	Gas Line	1st Floor	8	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	36	EA	7	10+ years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Science Lab Elements	1st Floor	1,314	SF	7	•			
		1st Floor		EA	7	10+ years			
	Science Lab Fume Hood		1			10+ years			
	Science Lab Fume Hood	1st Floor	1	EΑ	6	10+ years			
	Science Lab Shower	1st Floor	1	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,500	SF	7	10+ years			
	Work Sink	1st Floor	8	EA	7	10+ years			
Classroo	om #101 (Regular Classroom)								
Oldooroc	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	788	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Broken		
	Chalk Board	1st Floor	24	LF	4	2-5 years	Brokon		
	Doors - Transom Window	1st Floor	11	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Wood Doors Inclu TW	1st Floor	796	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	21	Sr EA	7	10+ years 10+ years			
	Lighting - Lay-in Marker Board	1st Floor 1st Floor	24	LF	7	6-10 years			
				SF	7				
	Walls - Plaster/Drywall	1st Floor	1,065	SF	1	10+ years			
Classroo	om #103 (Regular Classroom)								
	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	750	SF	7	10+ years			
	Chalk Board	1st Floor	20	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	22	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Wood	1st Floor	750	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	21	EA	6	6-10 years			
	Ligiting Lay in	1001	21	_, 、	J	5 To yours			

Campus Name: Senn HS Page : 80 of 95 Assessment Date: 07/18/2022







Category : Classroom			В	Building : Addition 2					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Marker Board	1st Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	964	SF	6	10+ years			
Classroc	om #105 (Science Lab Level 2)								
	Casework	1st Floor	88	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,124	SF	7	10+ years			
	Doors - Transom Window	1st Floor	33	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Eye Wash Station	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	1,124	SF	7	10+ years			
	Gas Line	1st Floor	8	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Science Lab Elements	1st Floor	1,124	SF	7	10+ years			
	Science Lab Shower	1st Floor	· 1	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,174	SF	7	10+ years			
	Work Sink	1st Floor	. 8	EA	7	10+ years			
Classroc	om #106 (Science Lab Level 2)								
	Casework	1st Floor	90	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,232	SF	7	10+ years			
	Doors - Transom Window	1st Floor	22	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Fixed		
	Eye Wash Station	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	1,232	SF	7	10+ years	Changed to match current observations		
	Gas Line	1st Floor	8	EΑ	7	10+ years			
	Lighting - Lay-in	1st Floor	35	EΑ	7	6-10 years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Science Lab Shower	1st Floor	1	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,387	SF	7	10+ years			
	Work Sink	1st Floor	8	EΑ	7	10+ years			
Classes	om #110 (Science Leb Level 2)								
Classion	om #110 (Science Lab Level 2)	4-4-51			7	0.40			
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	90	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,472	SF	7	10+ years			
	Doors - Transom Window	1st Floor	22	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Eye Wash Station	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	1,472	SF	7	10+ years	Changed to match current observations		

Campus Name: Senn HS Page : 81 of 95 Assessment Date: 07/18/2022





Catego	Category : Classroom		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Line	1st Floor	8	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	7	10+ years	
	Work Sink	1st Floor	8	EA	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,237	SF	7	10+ years	
	valio i lactoriziywan	2114 1 1001	1,207	O.	,	101 youro	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	796	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	22	EA	6	6-10 years	
	Marker Board	2nd Floor	38	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,237	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	696	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	30	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
UUSSIUL	an azoo (regular Oleasiooni)						

Campus Name: Senn HS Page : 82 of 95 Assessment Date: 07/18/2022





atego	ry : Classroom		В	uilding	: Additi	on 2	-
_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	12	LF	4	2-5 years	3
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
assroc	om #204 (Regular Classroom)						
ال الناسم	Casework	2nd Floor	9	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	714	SF	7	10+ years	
		2nd Floor 2nd Floor		SF	=		Water demand
	Ceiling - Lay-in		12		4	0-1 year	Water damage
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	5	10+ years	Wood floor needs to be refinishe
	Lighting - Lay-in	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
assroc	om #205 (Other Instructional Use)						
	Casework	2nd Floor	11	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	352	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Buckled tile
	Chalk Board	2nd Floor	5	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	358	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	832	SF	7	10+ years	
ssroc	om #206 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	684	SF	7	10+ years	
		2nd Floor 2nd Floor		SF SF	4		Water demage
	Ceiling - Lay-in		42			0-1 year	Water damage
	Chalk Board	2nd Floor	22	LF CF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw Floor - Wood	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	

Campus Name: Senn HS Page: 83 of 95 Assessment Date: 07/18/2022





Catego	ry : Classroom		В	uilding	: Additi	on 2	<u> </u>
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	21	EΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	22	LF	4	2-5 years	S .
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	714	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	22	LF	4	2-5 years	Trailer damage
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	720	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	22	LF	4	2-5 years	5
	Doors - Transom Window	2nd Floor	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor		EΑ	7	10+ years	
	Floor - Wood	2nd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
			ŭ		•	,	





Catego	ry : Classroom		В	uilding	: Additi		o N Sichwood Avenoe, Gilleago, le 00000
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	726	SF	7	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	726	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	om #213 (Store Room)						
	Ceiling - Plaster/Drywall	2nd Floor	510	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	510	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Masonry	2nd Floor	190	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
_Classroo	om #217 (Office)						
	Ceiling - Lay-in	2nd Floor	140	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	152	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	4	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	557	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
_Classroo	om #300 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	813	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,114	SF	6	10+ years	
_Classroo	nm #301 (Regular Classroom)						
	Casework	3rd Floor	9	LF	6	10+ years	
		0.0.1.00.	· ·		Ü	, 54.0	

Campus Name: Senn HS Page : 85 of 95 Assessment Date: 07/18/2022






atego	ry : Classroom		В	uilding	: Addition		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	825	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	825	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,114	SF	6	10+ years	
lassroc	om #302 (Science Lab Level 3)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	786	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	-	
						10+ years	
	Floor - Tile	3rd Floor	736	SF	6	10+ years	01: 1 1 1:0
	Floor - Tile	3rd Floor	50	SF	5	0-1 year	Chipped and cracked tiles
	Gas Line	3rd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,048	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	The deficiency was fixed
assroc	om #303 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	746	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Damaged tile
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
lassroc	om #305 (Other Instructional Use)						
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	368	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
			10	SF			
	Doors - Transom Window	3rd Floor			7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	368	SF	6	10+ years	0 (4
	Lighting - Lay-in	3rd Floor	9	EA	5	6-10 years	One of the covers is buckled
	Marker Board	3rd Floor	6	LF	7	6-10 years	

Campus Name: Senn HS Page : 86 of 95 Assessment Date: 07/18/2022







Catego	ry : Classroom		В	uildina	: Addition	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	4	0-1 year	Water damage
Classroc	om #306 (Science Lab Level 2)						
	Casework	3rd Floor	92	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,216	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	22	SF	6	10+ years	Ç
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,228	SF	7	10+ years	
	Gas Line	3rd Floor	, 8	ĒΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	36	ΕA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	7	10+ years	
	Work Sink	3rd Floor	8	EA	7	10+ years	
lassroc	om #307 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	750	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
lassroc	om #309 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
lassroc	m #310 (Science Lab Level 2)						
	Casework	3rd Floor	74	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,136	SF	6	10+ years	
		U. U	1,100				

Campus Name: Senn HS Page : 87 of 95 Assessment Date: 07/18/2022







Catego	ry : Classroom	В	uilding	: Additi	on 2		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,136	SF	7	10+ years	
	Gas Line	3rd Floor	4	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor	32	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,338	SF	7	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
Classroo	om #315 (Office)						
	Ceiling - Plaster/Drywall	3rd Floor	490	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	490	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Masonry	3rd Floor	190	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	838	SF	6	10+ years	
Classroo	om #317 (Office)						
	Ceiling - Lay-in	3rd Floor	148	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	148	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	3	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	496	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Additi	on 2	
_	- -					Recommend	

					Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor						
Ceiling - Lay-in	1st Floor Corridors	2,662	SF	7	10+ years	
Ceiling - Lay-in	1st Floor Corridors	40	SF	4	1-2 years	Broken
Ceiling - Plaster/Drywall	1st Floor Corridors	949	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor Corridors	6	EA	7	10+ years	
Doors - Transom Window	1st Floor Corridors	22	SF	7	10+ years	
Doors - Wood Doors include hw	1st Floor Corridors	8	EA	6	10+ years	
Drinking Fountains - Single Water Cooler	1st Floor Corridors	2	EA	7	10+ years	
Floor - Terrazzo	1st Floor Corridors	1,257	SF	7	10+ years	
Floor - Tile/Sheet	1st Floor Corridors	2,726	SF	5	10+ years	
Floor - Tile/Sheet	1st Floor Corridors	10	SF	4	1-2 years	Chipped
Lighting - Lay-in	1st Floor Corridors	42	EA	7	6-10 years	• •
Lighting - Pendent/Surface	1st Floor Corridors	10	EA	6	6-10 years	
Student Lockers - One Tier	1st Floor Corridors	147	EA	7	10+ years	
Walls - Masonry	1st Floor Corridors	2,915	SF	7	10+ years	

Campus Name: Senn HS Page : 88 of 95 Assessment Date: 07/18/2022





tegor	y : Interior		В	uilding	: Addition	on 2	
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor Corridors	3,219	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Vestibules	415	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor Vestibules	3	EA	6	10+ years	
	Floor - Terrazzo	1st Floor Vestibules	415	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Vestibules	8	EA	7	6-10 years	
	Walls - Masonry	1st Floor Vestibules	647	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Vestibules	384	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Vestibules	326	SF	6	10+ years	
	Ceiling - Lay-in	2ndFloor Corridors	2,870	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2ndFloor Corridors	36	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	2ndFloor Corridors	2	EA	7	10+ years	
	Floor - Terrazzo	2ndFloor Corridors	334	SF	7	10+ years	
	Floor - Tile/Sheet	2ndFloor Corridors	2,382	SF	7	10+ years	
	Lighting - Lay-in	2ndFloor Corridors	41	EA	7	6-10 years	
	Student Lockers - One Tier	2ndFloor Corridors	143	EΑ	7	10+ years	
	Walls - Masonry	2ndFloor Corridors	2,056	SF	7	10+ years	
	Walls - Plaster/Drywall	2ndFloor Corridors	2,166	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor Corridors	2,846	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor Corridors	12	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	3rd Floor Corridors	48	SF	7	10+ years	ŭ
	Drinking Fountains - Single Fountain	3rd Floor Corridors	2	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor Corridors	332	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor Corridors	2,572	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor Corridors	40	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	3rd Floor Corridors	144	EΑ	7	10+ years	
	Walls - Masonry	3rd Floor Corridors	2,052	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor Corridors	1,657	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Corridor @ Locker Rooms	280	SF	7	10+ years	
	Doors - Steel Doors incl hw	Corridor @ Locker Rooms	2	EA	7	10+ years	Quantity changed to match currently observations
	Doors - Wood Doors include hw	Corridor @ Locker Rooms	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	Corridor @ Locker Rooms	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Corridor @ Locker Rooms	280	SF	7	10+ years	
	Lighting - Pendent/Surface	Corridor @ Locker Rooms	6	EΑ	7	10+ years	
	Walls - Masonry	Corridor @ Locker Rooms	300	SF	7	10+ years	
	Walls - Plaster/Drywall	Corridor @ Locker Rooms	630	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym 1 Vestibule	208	SF	6	10+ years	
	Doors - Steel Doors incl hw	Gym 1 Vestibule	2	EA	6	10+ years	
	Floor - Terrazzo	Gym 1 Vestibule	208	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym 1 Vestibule	200	EA	6	6-10 years	
	Walls - Masonry	Gym 1 Vestibule	286	SF	6	10+ years	
	Walls - Plaster/Drywall	Gym 1 Vestibule	250	SF	6	10+ years	

Campus Name: Senn HS Page : 89 of 95 Assessment Date: 07/18/2022







Building: Addition 2 Category: Interior

Calego	y . Interior		D	unumg	. Additio	JII Z	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Southeast Stairwell	136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Southeast Stairwell	162	SF	7	10+ years	
	Floor - Terrazzo	Southeast Stairwell	260	SF	7	10+ years	
	Handrails	Southeast Stairwell	123	LF	7	10+ years	
	Lighting - Lay-in	Southeast Stairwell	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Southeast Stairwell	4	EΑ	7	6-10 years	
	Stairs - Terrazzo	Southeast Stairwell	352	LF	7	10+ years	
	Walls - Masonry	Southeast Stairwell	1,004	SF	7	10+ years	
	Walls - Plaster/Drywall	Southeast Stairwell	1,507	SF	6	10+ years	
	Ceiling - Lay-in	Southwest Staircase	476	SF	6	10+ years	
	Ceiling - Lay-in	Southwest Staircase	8	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	Southwest Staircase	202	SF	6	10+ years	
	Floor - Terrazzo	Southwest Staircase	418	SF	7	10+ years	
	Handrails	Southwest Staircase	121	LF	7	10+ years	
	Lighting - Lay-in	Southwest Staircase	6	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	Southwest Staircase	6	EΑ	7	6-10 years	
	Stairs - Terrazzo	Southwest Staircase	499	LF	7	10+ years	
	Walls - Masonry	Southwest Staircase	1,085	SF	7	10+ years	
	Walls - Plaster/Drywall	Southwest Staircase	1,327	SF	7	10+ years	

Campus Name: Senn HS Page : 90 of 95 Assessment Date: 07/18/2022



Category : Site Building : Site

Catogo	y . Oile			ununig	· Oite	December	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	21	ĒΑ	6	10+ years	
	Sirin Diamage Site mainless			`	Ū	. o · you.o	
Fencing							
	Fencing - Chain Link	Entire Site	115	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	97	LF	6	10+ years	
_Landsca	De Benches	Entire Site	86	EA		6.40 years	
				SF	6	6-10 years	
	Landscape - Grass	Entire Site	132,792		6	10+ years	
	Landscape - Grass	Entire Site	20,000	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	4,000	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	30,747	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	2,000	SF	6	10+ years	
	Parkway trees	Entire Site	52	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	6,311	SF	5	6-10 years	
	Retaining Wall - Concrete	Entire Site	540	SF	5	2-5 years	
	Retaining Wall - Concrete	Entire Site	100	SF	4	1-2 years	Spalling, broken
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I	ot						
arking i	Concrete Curbs	Entire Site	715	LF	6	10+ years	
	Surface - Asphalt	Entire Site	16,174	SF	6		
		Entire Site		SF		6-10 years	Holos apollina
	Surface - Asphalt		500		4	0-1 year	Holes, spalling
	Trash Compactor	Entire Site	1	EA	5	6-10 years	
	Trash Enclosure - Chain Links	Entire Site	500	SF	6	6-10 years	N.A.
	Trash Enclosure - Chain Links	Entire Site	1,000	SF	5	1-2 years	Missing gates
	Trash Enclosure - Masonry	Entire Site	486	SF	5	10+ years	
Sidewalk	S						
	Sidewalks - Perimeter Sidewalks	Entire Site	10,924	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,000	SF	5	1-2 years	Spalling, cracks
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	5	1-2 years	Spalling, cracks
			300		-	,	1 9,
Signage							
5 5	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years	
	Flag Pole - Flag Pole	Entire Site	2	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/	Entire Site	1	EΑ	7	10+ years	
	LED		•	_, 、	•	io. youro	



Nicholas Senn High School 5900 N Glenwood AVENUE, Chicago, IL 60660

Building: Site Category: Site

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Monument - Sign	Entire Site	3	EΑ	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Senn HS Page: 92 of 95 Assessment Date: 07/18/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	monaca coage	1.00111 200011011	- Italiasi	Traine or	(0. /	700	71.00	Ciop	
Art Room	Art Room	3rd Floor	353/355	355	1,840	420	210	Υ	N
Art Room	Art Room	3rd Floor	361	361	1,584	108	54	N	N
Band Room	Music Room	4th Floor	425	425	2,447	514	214	Y	N
Computer Lab	Computer Lab	3rd Floor	326	326	1,495	650	325	Y	N
Computer Lab	Computer Lab	3rd Floor	335	335	1,130	180	90	Y	N
Computer Lab	Regular Classroom	2nd Floor	221	221	1,500	350	175	Y	N
Computer Lab	Regular Classroom	2nd Floor	276	276	730	207	103	Y	N
Dance Room	Regular Classroom	1st Floor	166	164/166	1,488	360	180	Ϋ́	N
Faculty Lounge	Regular Classroom	2nd Floor	222	222	705	210	105	Y	N
Music Room	Music Room	3rd Floor	325	325	2,395	550	150	Y	N
Regular Classroom	Art Room	3rd Floor	351	351	920	210	105	Y	N
Regular Classroom	Regular Classroom	1st Floor	158/160	158/160	1,822	640	320	N	N
Regular Classroom	Regular Classroom	1st Floor	162	162	730	207	103	Y	N
Regular Classroom	Regular Classroom	1st Floor	172	172	528	120	60	Ϋ́	N
Regular Classroom	Regular Classroom	1st Floor	174	174	528	120	60	Y	N
Regular Classroom	Regular Classroom	1st Floor	176	176	730	207	103	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	1,030	215	107	Y	N
Regular Classroom	Regular Classroom	2nd Floor	230	230	1,145	280	140	Y	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	1,130	225	125	Y	N
Regular Classroom	Regular Classroom	2nd Floor	234	234	1,030	280	140	Y	N
Regular Classroom	Regular Classroom	2nd Floor	236	236	730	450	225	Y	N
Regular Classroom	Regular Classroom	2nd Floor	260	260	730	207	103	N	N
Regular Classroom	Regular Classroom	2nd Floor	261	261	730	164	82	N	N
Regular Classroom	Regular Classroom	2nd Floor	262	262	730	207	103	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	264	264	730	207	103	N	N
Regular Classroom	Regular Classroom	2nd Floor	266	266	730	201	103	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	272	272	1,424	414	207	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	273	273	730	207	103	N	N
Regular Classroom	Regular Classroom	2nd Floor	275	275	730	207	113	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	277	277	730	207	103	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	278	278	730	207	103	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	280	280	930	390	195	N	N
Regular Classroom	Regular Classroom	2nd Floor	281	281	730	207	103	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	1,130	150	75	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	1,050	140	35	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	730	210	105	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	730	210	105	Y	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	730	210	105	Υ	N

Campus Name: Senn HS Page: 93 of 95 Assessment Date: 07/18/2022





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	332	332	730	210	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	334	334	730	300	150	Y	N
Regular Classroom	Regular Classroom	3rd Floor	363	363	816	162	81	N	N
Regular Classroom	Regular Classroom	3rd Floor	367	367	725	270	135	N	N
Regular Classroom	Regular Classroom	3rd Floor	372	372	750	126	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	374	374	750	126	63	Y	N
Regular Classroom	Regular Classroom	3rd Floor	376	376	750	126	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	378	378	750	126	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	380	380	930	390	195	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	350	350	1,300	260	130	Y	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	356	356	937	210	105	Y	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	352	352	990	280	140	Y	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	358	358	1,216	231	115	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	364	364	1,032	168	84	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	366	366	1,050	240	120	N	N

Building : Addition 1									
Art Room	Art Room	3rd Floor	336	336	1,797	370	150	N	N
Art Room	Regular Classroom	3rd Floor	344	344	1,122	282	84	N	N
Computer Lab	Regular Classroom	3rd Floor	343 East	343	982	250	65	N	N
Computer Lab	Regular Classroom	3rd Floor	343 West	343	508	94	19	N	N
Faculty Lounge	Special Program	1st Floor	149	149	1,180	384	108	N	N
Office	Special Program	1st Floor	146	146	596	214	60	N	N
Office	Special Program	2nd Floor	235	235	224	54	11	N	N
Office	Special Program	2nd Floor	239	239	512	72	22	N	N
Office	Special Program	3rd Floor	337	337	223	47	9	N	N
Regular Classroom	Computer Lab	2nd Floor	246 West	246	490	108	22	N	N
Regular Classroom	Regular Classroom	2nd Floor	240	240	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	241	241	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	242	242	671	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	243	243	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	244	244	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	247	247	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	248 East	230 (partial)	658	162	44	N	N
Regular Classroom	Regular Classroom	2nd Floor	249	249	816	216	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	340	340	1,085	250	65	N	N
Regular Classroom	Regular Classroom	3rd Floor	346 East	346 (Partial)	718	188	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	347	347	743	188	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	348	348	1,200	282	84	N	N
Regular Classroom	Regular Classroom	3rd Floor	349	349	816	188	56	N	N
Special Program	Regular Classroom	2nd Floor	246 East	248	594	180	55	N	N

Campus Name: Senn HS Page : 94 of 95 Assessment Date: 07/18/2022





Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Special Program	Special Program	2nd Floor	245	245	367	108	33	N	N
Special Program	Special Program	2nd Floor	248 West	230 (partial)	490	126	33	N	N
Special Program	Special Program	3rd Floor	345	345	367	78	19	N	N
Store Room	Store Room	1st Floor	186 ROTC	186	497	0	0	N	N
Vacant	Special Program	3rd Floor	346 West	346 (Partial)	470	94	28	N	N

Building : Addition 2 Office	Office	2nd Floor	217	217	152	72	22	N	N
Office	Other Instructional Use	3rd Floor	315	315	490	62	18	N	N
Office	Other Instructional Use	3rd Floor	317	317	148	62	18	N	N
Other Instructional Use	Other Instructional Use	2nd Floor	205	205	358	108	33	N	N
Other Instructional Use	Other Instructional Use	3rd Floor	305	305	368	94	28	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	796	256	72	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	750	256	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	796	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	796	216	44	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	726	216	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	726	216	55	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	726	216	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	825	188	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	825	188	37	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	750	188	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	750	188	56	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	750	188	56	N	N
Science Lab Level 1	Regular Classroom	1st Floor	100	100	1,314	427	120	N	N
Science Lab Level 2	Regular Classroom	1st Floor	105	105	1,124	384	108	N	N
Science Lab Level 2	Regular Classroom	1st Floor	106	106	1,232	427	120	N	N
Science Lab Level 2	Regular Classroom	1st Floor	110	110 + 108	1,472	512	132	N	N
Science Lab Level 2	Regular Classroom	3rd Floor	306	306	1,228	312	93	N	N
Science Lab Level 2	Regular Classroom	3rd Floor	310	310	1,136	312	93	N	N
Science Lab Level 3	Regular Classroom	3rd Floor	302	302	786	188	56	N	N
Store Room	Other Instructional Use	2nd Floor	213	213	510	72	22	N	N