

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1881	3	68,750
Linked Addition	2018	1	8,956
Campus Total			77,706

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	1 Main N	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	1 Main N	3	EΑ	5	6-10 years	
	Exterior Doors - Transom Lite	1 Main N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2 NE	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	2 NE	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	3 S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 S	2	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	4 E	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 E	1	EA	4	2-5 years	
	Exterior Stairs - Concrete	5 E	5	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	6 S	2	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	at Fire escapes	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	at Fire escapes	2	EA	6	10+ years	
Fire Esc	ape						
	Fire Escape	Entire Building	224	LF	6	10+ years	
Foundati	on						
	Foundation - Masonry	Entire Building	780	LF	7	10+ years	
	Foundation - Masonry	Entire Building	70	LF	5	2-5 years	Major Seepage inside
	Superstructure - Heavy Timber	Entire Building	68,750	SF	7	10+ years	, , ,



itegei	y : Exterior		В	uilding	: Main		
	_				_	Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
hting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Broken fixture
of Sys	tem						
	Access Ladder - Metal	#1	2	EA	7	10+ years	
	Access Ladder - Metal	#1	2	EA	7	10+ years	
	Coping - Clay Tile	#1	30	LF	6	10+ years	
	Coping - Stone	#1	144	LF	6	10+ years	
	Coping - Terra Cotta	#1	445	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#1	300	LF	6	10+ years	
	Parapet - 16" - 30" Height	#1	80	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#1	539	LF	6	6-10 years	
	Roof - Modified Bitumen	#1	16,400	SF	6	10+ years	
	Roof Hatch - Metal	#1	2	EA	7	10+ years	
	Roof Structure - Heavy Timber	#1	16,400	SF	7	10+ years	
	Coping - Metal	#1b @ Door #2	16,400	LF	6	10+ years	
		#1b @ Door #2 #1b @ Door #2	12	LF	6	10+ years	
	Downspouts - Exterior Downspouts Roof - Modified Bitumen		55	SF			
		#1b @ Door #2			6	10+ years	
	Roof Structure - Heavy Timber	#1b @ Door #2	55	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#2	30	LF	6	10+ years	
	Roof - Modified Bitumen	#2	40	SF	6	10+ years	
	Roof Structure - Heavy Timber	#2	40	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	#3	70	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	#3	10	LF	5	2-5 years	
	Liner						
	Coping - Stone	#3	219	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#3	30	LF	6	10+ years	
	Downspouts - Interior Downspouts	#3	40	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	149	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#3	70	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#3	2,991	SF	6	10+ years	
	Roof Structure - Heavy Timber	#3	280	SF	7	10+ years	Quantity Adjusted/Added
	Roof Structure - Steel with Clay Tile Arch	#3	2,711	SF	7	10+ years	Quantity Adjusted
	Coping - Stone	#4	50	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#4	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4	35	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4	15	LF	6	10+ years	
	Roof - Modified Bitumen	# <b>4</b>	270	SF	6	10+ years	
	Roof Structure - Heavy Timber	# <del>4</del> #4	270	SF	7	10+ years	

Campus Name: Sheridan Page : 2 of 32 Assessment Date: 06/09/2022



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cornice - Metal Projecting	Entire Building	2,016	LF	6	2-5 years	Rust/Corrosion
	Exterior Walls - Brick	Entire Building	25,461	SF	6	10+ years	Quantity Adjusted: Observed masons
							technique to solve brick condition:
							tuck pointed depicting jaggedness of
							old brick. Masonry/Bricks not flush by design/default. New Red brick is in
							good condition, dirty in places. "Rank"
							options does not adequately identify
							circumstances
	Exterior Walls - Brick	Entire Building	28	SF	4	1-2 years	Cracked/broken/ open mortar Joints
							near Door 2 and at south upper wall
	Fotorion Wells - Driels	Fating Duilding	450	0.5	4	4.0	east of roof #3
	Exterior Walls - Brick	Entire Building	150	SF	4	1-2 years	Broken and cracked Bricks. Open joints/Cracked mortar, resealing at
							foundation wall. Needs re-bricking in
							places.
	Exterior Walls - Brick	Entire Building	1,200	SF	4	1-2 years	Quantity Adjusted: broken/cracked
							bricksOpen and deteriorating mortar
							joints at parapet and perimeter upper
	Exterior Walls - Stone-Cast	Entire Duilding	2.042	SF	6	10	portion of wall
	Exterior Walls - Storie-Cast	Entire Building	3,942	SF	0	10+ years	
_Windows	S						
	Guard - Guards perforated	Entire Building	1,274	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	96	SF	6	10+ years	
	Lintels - Brick	Entire Building	32	LF	6	10+ years	
	Lintels - Steel Lintels - Stone	Entire Building	325 407	LF LF	6 6	10+ years	
	Windows - Louver	Entire Building Entire Building	96	SF	6	10+ years 10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,934	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	216	SF	4	0-1 year	North east wing under roof 1 of main
	'	3				,	at 2nd floor: Stiffened/Bad Balances -
							Windows are very hard to open
Catego	ry : Electrical		В	uilding	: Main		
				J		Recommend	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	ncy System						
· ·	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Functional and older, serves independent service
	Exit Signs - Corridors and Stairs	Entire Building	16	EΑ	7	6-10 years	Clean and functional
	Exit Signs - Gym	Entire Building	3	EΑ	4	2-5 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	4	2-5 years	Light from exit light causes glare at

Campus Name: Sheridan Page : 3 of 32 Assessment Date: 06/09/2022



Categor	ry : Electrical		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Farancia Della Della Camidana and	Fating Duillelian	40	_^	0	0.40	iPad photo. Exit light is bfunctional
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	Previously not assessed
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	Treviously flot assessed
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years	
	Room	Entire Dallaling	_		O	o io youio	
	Emergency A/C Power - Corridors and	Entire Building	3,450	SF	6	10+ years	
	Stairs	3	-,			, , , , , ,	
	Emergency A/C Power - Gym	Entire Building	2,600	SF	6	10+ years	Previously not assessed
	Emergency A/C Power - Multipurpose	Entire Building	2,150	SF	6	10+ years	•
	Room	Č				•	
	Security System - CCTV	Entire Building	68,750	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	68,750	SF	5	6-10 years	
Main Ser		4at Flaar	00.750			10	Connected to addition building
	PA System Main Electrical Service - 1200 A	1st Floor Electrical Room	68,750	SF EA	6 4	10+ years 2-5 years	Connected to addition building Serves main building, corroded, no
	120/208/3PH	Electrical Room	ı	EA	4	2-5 years	reliable
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	Served by ATS, with second meter
	emergency power	Licotrical recom	,		Ü	o ro youro	Corved by 7110, with cocond motor
Power Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	10+ years	I have the second and the second and
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	3	0-1 year	Live, no internal cover, hazardous
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
	апр						
Categor	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Fire Alarr		Location	Quantity	COIVI	Naiik	Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Also serves addition building
	Fire Alarm Strobe Lights	Entire Building	68,750	SF	6	10+ years	
	Fire Alarm_System	Entire Building	68,750	SF	5	10+ years	Connected to addition building
	Fire Pump Controller	Entire Building	1	ĒΑ	4	2-5 years	Old technology, not reliable
	•	Ŭ				•	55.
Pump Ro	oom Assembly						
Pump Ro	oom Assembly Fire Pump - 25-50 hp	1st Floor	1	EA	5	6-10 years	Serves main building, seal recently repacked



Category : Fire Protection			Building : Main						
						Recommend	•		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Sprinkle		F // B // P							
	Dry Sprinkler System	Entire Building	68,750	SF	6	10+ years	Using air compressor		
	Sprinkler Heads Sprinkler Piping	Entire Building Entire Building	68,750 68,750	SF SF	7 6	10+ years 10+ years	Sorves main building		
	Sprinkler Fibring	Entire Building	66,750	SF	O	10+ years	Serves main building		
Catego	ry : Mechanical		В	uilding	: Main				
0	Name Toma	Laatlan	0	LIOM	Dant	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Cond		D4		Ε.		0.40	O-mars have been see from a 21 (in all 224)		
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves lunchroom fan coil (in closet) unit		
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	2-5 years	Serves nurse's office fan coil unit, wall mounted, less than 2.5 tons,		
	than 5 tons						older, corroding, visible rust, not		
							reliable		
Air Hand	lling Systems								
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	5	6-10 years	In dining area closet, cooling only, served by outdoor condensing unit		
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	4	2-5 years	In nurse's office, mini split system.		
	, and the second					·	served by wall mounted condensing		
							unit, more than 20 years old, not re		
	A: 11 N: 11 % B % 1 A 10 7				_	0.40	liable		
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves east side of main building		
	Air Intake	Mechanical Room	1	EA	5	6-10 years			
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years	Recently serviced		
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	Painted		
	Zone Dampers	Mechanical Room	25	EA	4	2-5 years	Rusted, manually operated		
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	6-10 years	AHU 1, Serves west side of building		
	Steam Coils - 25001 - 35000 cfm								
	Air Intake	Mechanical Room	1	EA	5	6-10 years			
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	6-10 years	Painted		
	Zone Dampers	Mechanical Room	25	EA	4	2-5 years	Corroded, manually operated		
Boiler Sy	vstems								
	Boiler Auxiliary- Scotch Marine- Steam Low	Basement	2	EA	6	10+ years			
	Pressure Boiler - 101 - 150 HP					-			
	Chemical Feed System	Basement	1	EA	5	6-10 years			
	Combustion Dampers	Basement	2	EA	4	2-5 years	Corroded, old		

Campus Name: Sheridan Page : 5 of 32 Assessment Date: 06/09/2022



Catego	ry : Mechanical		В	uilding	: Main		533 W 27th STREET, Chicago, IL 60616
outogo.	y i moonamou		_	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Cup	Condensate Pump	Basement	1	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	6	10+ years	
	Feed Water Pumps and Tank	Basement	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Basement	2	EA	6	10+ years	Serves main building
	Steam- Low Pressure Boiler - 101 - 150 HP	Dasement	2	LA	U	10+ years	Serves main building
	Piping - Condensate Pipe- Steel	Basement	400	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Basement	400	LF	5	10+ years	
	Steam Traps	Basement	15	EA	5	6-10 years	
Heating I	Devices						
J	Fin Tube - Steam	1st Floor	12	LF	5	6-10 years	Per engineer, none.
	Radiators - Steam	1st Floor	1	EA	5	6-10 years	In office
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	Recently cleaned
Tempera	ture Control						
·	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serve 2 single zone mini split
	Draumatia Cuatam	Entire Building	68 750	C.E.	4	2 E veere	systems.
	Pneumatic System	Entire Building	68,750	SF	4	2-5 years	Leaks, mostly manually operated
	Thermostats - Pneumatic	Entire Building	35	EΑ	5	6-10 years	Net - Bleested - Ld
	Thermostats - Pneumatic	Entire Building	15	EA	4	2-5 years	Not calibrated, old
Ventilatio							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Serves kitchen, centrifugal style
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate		Location	Quantity	OOW	Ivalik	Replacement	Comments
TIOL Wate	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves main building, 2013 installation
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	4	2-5 years	Old, corroded, ceiling mounted
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	68,750	SF	6	10+ years	Minor leaks are occasionally repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	68,750	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	68,750	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	68,750	SF	6	10+ years	There are a few pipe clamps

Campus Name: Sheridan Page : 6 of 32 Assessment Date: 06/09/2022



Catego	ry : Plumbing		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	68,750	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	68,750	SF	6	10+ years	No leaks	
	Sanitary Piping	Entire Building	68,750	SF	6	10+ years		
	Storm Piping	Entire Building	68,750	SF	6	10+ years		
	Vent Piping	Entire Building	68,750	SF	6	10+ years		
Pumps								
·	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	4	2-5 years	Old, corroded, noisy, serves main building	

Category: Room **Building: Main** 

Jaiegu	I y . NOOIII		ь	unung	. Iviaiii		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st Floor-110 Assistant Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-110 Assistant Principal's Office	430	SF	7	10+ years	
	Doors - Side-lite	1st Floor-110 Assistant Principal's Office	26	SF	7	10+ years	
	Doors - Transom Window	1st Floor-110 Assistant Principal's Office	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-110 Assistant Principal's Office	2	EA	7	10+ years	
	Floor - Carpet	1st Floor-110 Assistant Principal's Office	430	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-110 Assistant Principal's Office	7	EA	7	6-10 years	
	Power Distribution	1st Floor-110 Assistant Principal's Office	8	EA	7	10+ years	
	Storage/ Closet	1st Floor-110 Assistant Principal's Office	42	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	1st Floor-110 Assistant Principal's Office	1,495	SF	6	10+ years	
	AC Unit	1st Floor-Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Main Office	536	SF	7	10+ years	
	Doors - Side-lite	1st Floor-Main Office	26	SF	7	10+ years	
	Doors - Transom Window	1st Floor-Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor-Main Office	536	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Main Office	10	EA	7	6-10 years	
	Power Distribution	1st Floor-Main Office	14	EA	7	10+ years	

Campus Name: Sheridan Page : 7 of 32 Assessment Date: 06/09/2022



Category : Room		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor-Main Office	25	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	1st Floor-Main Office	1,470	SF	7	10+ years	
	AC Unit	1st Floor-Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office	429	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	2	EA	7	10+ years	
	Floor - Carpet	1st Floor-Principal's Office	429	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office	5	EA	7	6-10 years	
	Power Distribution	1st Floor-Principal's Office	12	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office	1,148	SF	7	10+ years	
	Ceiling - Plaster/Drywall	200 Next to boys 2 flr	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	200 Next to boys 2 flr	1	EA	7	10+ years	
	Floor - Tile	200 Next to boys 2 flr	140	SF	7	10+ years	
	Lighting - Pendent/Surface	200 Next to boys 2 flr	4	EA	7	10+ years	
	Power Distribution	200 Next to boys 2 flr	2	EΑ	7	10+ years	
	Storage/ Closet	200 Next to boys 2 flr	15	SF	7	10+ years	
	Walls - Plaster/Drywall	200 Next to boys 2 flr	340	SF	7	10+ years	
	AC Unit	210	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	210	221	SF	7	10+ years	
	Doors - Transom Window	210	105	SF	7	10+ years	
	Doors - Wood Doors inclu hw	210	1	EA	7	10+ years	
	Floor - Carpet	210	221	SF	6	6-10 years	
	Lighting - Pendent/Surface	210	7	EΑ	7	6-10 years	
	Power Distribution	210	6	EA	7	10+ years	
	Walls - Metal Panel	210	366	SF	6	10+ years	
	Walls - Plaster/Drywall	210	507	SF	6	10+ years	
	Ceiling - Plaster/Drywall	310 Admin. Storage	403	SF	7	10+ years	
	Doors - Transom Window	310 Admin. Storage	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	310 Admin. Storage	1	EA	7	10+ years	
	Floor - Wood	310 Admin. Storage 310 Admin. Storage	403	SF EA	7	10+ years	
	Lighting - Pendent/Surface Power Distribution	310 Admin. Storage	7 7	EA EA	7 7	6-10 years 10+ years	
		310 Admin. Storage	24	SF	7		Pank ahangad to match current
	Storage/ Closet	•				10+ years	Rank changed to match current observation
	Walls - Metal Panel	310 Admin. Storage	247	SF	7	10+ years	
	Walls - Plaster/Drywall	310 Admin. Storage	987	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd floor Gym Office	219	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor Gym Office	2	EA	7	10+ years	
	Floor - Wood	3rd floor Gym Office	219	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd floor Gym Office	4	EA	7	6-10 years	
	Power Distribution	3rd floor Gym Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor Gym Office	708	SF	7	10+ years	
	Ceiling - Exposed	Basement Cares Room	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Cares Room	2	EA	7	10+ years	

Campus Name: Sheridan Page: 8 of 32 Assessment Date: 06/09/2022



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	Basement Cares Room	300	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Cares Room	3	EA	7	10+ years	
	Power Distribution	Basement Cares Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Cares Room	720	SF	7	10+ years	
	Work SInk	Basement Cares Room	1	EA	7	10+ years	
	Ceiling - Lay-in	Basement nurses office	540	SF	7	10+ years	
	Ceiling - Lay-in	Basement nurses office	20	SF	4	1-2 years	Water damage tiles
	Doors - Wood Doors inclu hw	Basement nurses office	1	EA	7	10+ years	
	Floor - Concrete	Basement nurses office	560	SF	7	10+ years	
	Lighting - Lay-in	Basement nurses office	8	EA	7	6-10 years	
	Power Distribution	Basement nurses office	6	EA	7	10+ years	
	Walls - Masonry	Basement nurses office	1,000	SF	6	10+ years	
	Ceiling - Exposed	Basement-Engineer's Office	350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Engineer's Office	1	EA	7	10+ years	
	Floor - Concrete	Basement-Engineer's Office	350	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Engineer's Office	4	EΑ	7	6-10 years	
	Power Distribution	Basement-Engineer's Office	8	EA	6	6-10 years	
	Walls - Masonry	Basement-Engineer's Office	780	SF	6	10+ years	
	Ceiling - Exposed	Basement-Faculty Lounge	562	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Faculty Lounge	1	EA	7	10+ years	
	Floor - Tile	Basement-Faculty Lounge	562	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Faculty Lounge	5	EA	7	6-10 years	
	Power Distribution	Basement-Faculty Lounge	12	EA	7	10+ years	
	Storage/ Closet	Basement-Faculty Lounge	285	SF SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-Faculty Lounge	1,180		7	10+ years	
	Work Sink	Basement-Faculty Lounge	1	EA SF	7 7	10+ years	
	Ceiling - Exposed	Basement-Janitor's Room	162			10+ years	
	Doors - Wood Doors inclu hw	Basement-Janitor's Room	2	EA	6	10+ years	Deterioration floor confess
	Floor - Concrete Epoxy/ Painted	Basement-Janitor's Room	162	SF	5	1-2 years	Deteriorating floor surface
	Lighting - Pendent/Surface	Basement-Janitor's Room	2	EΑ	7	6-10 years	
	Power Distribution	Basement-Janitor's Room	4	EA SF	7	10+ years	
	Storage/ Closet	Basement-Janitor's Room	=	SF SF	7	10+ years	
	Walls - Masonry	Basement-Janitor's Room	688	SF SF	7	10+ years	
	Ceiling - Exposed	Resource room basement	300	SF EA	7	10+ years	
	Doors - Wood Doors inclu hw	Resource room basement	1 300	SF	7 7	10+ years	
	Floor - Tile	Resource room basement		SF EA		10+ years	
	Lighting - Pendent/Surface	Resource room basement	4		7	6-10 years	
	Power Distribution	Resource room basement	4	EA SF	7 7	10+ years	
	Walls - Plaster/Drywall	Resource room basement	700	51	1	10+ years	
_Gymnas							
	Ceiling - Plaster/Drywall	3rd Floor	3,208	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	10+ years	
						-	



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	3,208	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Stage	3rd Floor	800	SF	6	10+ years	
	Stage Curtain	3rd Floor	5	EA	7	6-10 years	
	Stage-Stairs - Wood	3rd Floor	1	LF	6	10+ years	
	Storage/ Closet	3rd Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,237	SF	7	10+ years	
tchen							
	Ceiling - Exposed	Basement-Kitchen, with Lunchroom	485	SF	7	10+ years	
	Floor - Tile	Basement-Kitchen, with Lunchroom	485	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Kitchen, with Lunchroom	6	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Kitchen, with Lunchroom	652	SF	7	10+ years	
brary							
y	AC Unit	1st Floor-109 Library	1	EA	7	6-10 years	
	Casework	1st Floor-109 Library	90	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-109 Library	968	SF	7	10+ years	
	Doors - Side-lite	1st Floor-109 Library	30	SF	7	10+ years	
	Doors - Transom Window	1st Floor-109 Library	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-109 Library	1	EA	7	10+ years	
	Floor - Carpet	1st Floor-109 Library	968	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-109 Library	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor-109 Library	126	SF	7	10+ years	Rank changed to match current
	· ·	·			,	•	observation
	Walls - Plaster/Drywall	1st Floor-109 Library	1,807	SF	7	10+ years	
nch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement-Lunchroom 2, former Playroom	886	SF	7	10+ years	
	Floor - Tile	Basement-Lunchroom 2, former Playroom	866	SF	6	10+ years	
	Floor - Tile	Basement-Lunchroom 2, former Playroom	20	SF	4	0-1 year	Damaged, missing
	Lighting - Pendent/Surface	Basement-Lunchroom 2, former Playroom	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Lunchroom 2, former Playroom	1,240	SF	7	10+ years	
	Ceiling - Exposed	Basement-Lunchroom, with Kitchen	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Lunchroom, with Kitchen	2	EA	7	10+ years	
	Floor - Tile	Basement-Lunchroom, with Kitchen	720	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Lunchroom, with Kitchen	120	EA	7	6-10 years	
					7 7		
	Serving Line	Basement-Lunchroom, with Kitchen	20	LF	1	10+ years	



Category : Room			Building : Main					
					_	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	Basement-Lunchroom, with Kitchen	25	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement-Lunchroom, with Kitchen	820	SF	7	10+ years		
IDF_ID	F							
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Finishes	3rd Floor	220	SF	5	10+ years	Missing and loose f"or tiles	
	Window AC Unit	3rd Floor	1	EA	7	6-10 years		
echani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	10	SF	7	10+ years	No lights	
	Janitor's Closet	2nd Floor	10	SF	7	10+ years	gg	
	Janitor's Closet	3rd Floor	24	SF	7	10+ years	Rank changed to match current observation	
	Air Tunnel	Basement	532	SF	7	10+ years	observation	
	Boiler Room	Basement	1,020	SF	7	10+ years		
	Coal Room	Basement	982	SF	7	10+ years		
	Janitor's Closet	Basement	25	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	378	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	68	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	282	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	750	SF	7	10+ years		
	Mechanical/ Service Rooms		765	SF	7			
		Basement	350	SF SF	7	10+ years		
	Storage Room	Basement				10+ years		
	Storage Room	Basement	28	SF	7	10+ years		
	Storage Room	Basement	138	SF	7	10+ years	5 1 1 1 1 1 1	
	Storage Room	Basement	495	SF	7	10+ years	Rank changed to match current observation	
estrooi	m							
COHOU	Accessories	1st Floor-105 Kindergarten	70	SF	7	6-10 years		
	Cailing Diagtor/Drawall	Restroom	70	SF	7	10		
	Ceiling - Plaster/Drywall	1st Floor-105 Kindergarten Restroom	70		7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-105 Kindergarten Restroom	3	EA	7	10+ years		
	Floor - Wood	1st Floor-105 Kindergarten Restroom	70	SF	7	10+ years		
	Lavatory	1st Floor-105 Kindergarten Restroom	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor-105 Kindergarten Restroom	1	EA	6	6-10 years		
	Walls - Metal Panel	1st Floor-105 Kindergarten Restroom	110	SF	7	10+ years		





Catego	ry : Room		В	uilding	: Main		555 W 27th 5TREET, Chicago, it 60616
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor-105 Kindergarten Restroom	408	SF	6	10+ years	
	Water Closet	1st Floor-105 Kindergarten Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-107 Kindergarten Restroom	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-107 Kindergarten Restroom	30	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-107 Kindergarten Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-107 Kindergarten Restroom	30	SF	7	10+ years	
	Lavatory	1st Floor-107 Kindergarten Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-107 Kindergarten Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-107 Kindergarten Restroom	110	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-107 Kindergarten Restroom	250	SF	7	10+ years	
	Water Closet	1st Floor-107 Kindergarten Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Main Office Restroom	44	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Main Office Restroom	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Main Office Restroom	44	SF	7	10+ years	
	Lavatory	1st Floor-Main Office Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Main Office Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Main Office Restroom	254	SF	7	10+ years	
	Water Closet	1st Floor-Main Office Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Teacher's Restroom	70	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Teacher's Restroom	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Teacher's Restroom	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Teacher's Restroom	70	SF	7	10+ years	
		1st Floor-Teacher's Restroom	1	EA	7	•	
	Lavatory		2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Teacher's Restroom				6-10 years	
	Walls - Plaster/Drywall	1st Floor-Teacher's Restroom	300	SF	7	10+ years	
	Water Closet	1st Floor-Teacher's Restroom	1	EA	7	10+ years	
	Accessories	2nd Floor Boys	212	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	212	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	212	SF	7	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Lavatory	2nd Floor Boys	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys	5	EA	7	6-10 years	





Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor Boys	3	EA	7	10+ years	
	Urinals	2nd Floor Boys	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Boys	54	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys	185	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys	6	SF	4	0-1 year	Missing tiles
	Water Closet	2nd Floor Boys	3	EA	7	10+ years	
	Accessories	2nd Floor Girls	416	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	416	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	411	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	5	SF	4	0-1 year	Missing tiles
	Floor Drain	2nd Floor Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girls	1	EA	7	6-10 years	
	Lavatory	2nd Floor Girls	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls	7	EA	7	6-10 years	
	Partitions	2nd Floor Girls	7	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Girls	710	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls	665	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls	114	SF	7	10+ years	
	Water Closet	2nd Floor Girls	7	ĒΑ	7	10+ years	
	Accessories	2nd Floor Mens	93	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Mens	93	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Mens	93	SF	7	10+ years	
	Floor Drain	2nd Floor Mens	1	EΑ	7	10+ years	
	Lavatory	2nd Floor Mens	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Mens	3	EA	7	6-10 years	
	Partitions	2nd Floor Mens	1	EΑ	7	10+ years	
	Urinals	2nd Floor Mens	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Mens	84	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Mens	315	SF	7	10+ years	
	Water Closet	2nd Floor Mens	1	EA	6	10+ years	
	Accessories	2nd Floor Womens	67	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Womens	67	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Womens	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Womens	67	SF	7	10+ years	
	Lavatory	2nd Floor Womens	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Womens	1	EA	7	6-10 years	
	Partitions	2nd Floor Womens	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Womens	313	SF	6		
	Water Closet	2nd Floor Womens 2nd Floor Womens	2	SF EA	6	10+ years 10+ years	
	Accessories	Basement-Boiler Room Restroom	30	SF	7	6-10 years	
		Basement-Boiler Room Restroom	30	SF SF	7	•	
	Ceiling - Exposed		30	SF EA	6	10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	Basement Boiler Room Restroom	30	SF		10+ years	Loose and missing tiles
		Basement-Boiler Room Restroom Basement-Boiler Room Restroom	30	SF EA	4 4	0-1 year	Loose and missing tiles
	Lighting - Pendent/Surface	Dasement-Doller Room Restroom	'	EA	4	6-10 years	No fixture



Catego	ry : Room		В	uilding	: Main		<u> </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	Basement-Boiler Room Restroom	134	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Boiler Room Restroom	78	SF	7	10+ years	
	Water Closet	Basement-Boiler Room Restroom	1	EA	7	10+ years	
	Accessories	Basement-Boy's Restroom	289	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Boy's Restroom	289	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	289	SF	7	10+ years	
	Floor Drain	Basement-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Boy's Restroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement-Boy's Restroom	5	EA	7	6-10 years	
	Partitions	Basement-Boy's Restroom	3	EA	7	10+ years	
	Urinals	Basement-Boy's Restroom	4	EA	7	10+ years	
	Walls - Masonry	Basement-Boy's Restroom	212	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-Boy's Restroom	234	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement-Boy's Restroom	440	SF	7	10+ years	
	Water Closet	Basement-Boy's Restroom	3	EA	7	10+ years	
	Accessories	Basement-Resource room	80	SF	7	6-10 years	
	Ceiling - Lay-in	Basement-Resource room	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Resource room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Resource room	80	SF	7	10+ years	
	Lavatory	Basement-Resource room	1	EA	7	10+ years	
	Lighting - Lay-in	Basement-Resource room	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Resource room	244	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement-Resource room	6	SF	5	0-1 year	Water damage
	Walls - Tile Ceramic/ Porcelain	Basement-Resource room	36	SF	7	10+ years	-
	Walls - Tile Ceramic/ Porcelain	Basement-Resource room	2	SF	4	0-1 year	Missing tiles
	Water Closet	Basement-Resource room	1	EA	7	10+ years	-
Catego	ry : Classroom		В	uilding	: Main		

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #007 (Other Instructional Use)						
	Casework	Basement	6	LF	7	10+ years	
	Ceiling - Exposed	Basement	905	SF	4	0-1 year	Peeling paint falling to the floor
	Floor - Carpet	Basement	905	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Marker Board	Basement	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,140	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	m #008 (Computer Lab)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	834	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	

Campus Name: Sheridan Page : 14 of 32 Assessment Date: 06/09/2022



Catego	ry : Classroom		R	uilding	· Main		555 W 27111 STREET, CHICAGO, IL 60616
Calego	iy . Classiooni			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Floor - Tile	Basement	829	SF	7	10+ years	Comments
	Floor - Tile	Basement	5	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	Diokeii liles
	Marker Board	Basement	20	LF	7	6-10 years	
	Storage/ Closet	Basement	75	SF	7		
				SF		10+ years	
	Walls - Plaster/Drywall	Basement	1,000		7	10+ years	
	Wireless System	Basement	1	EΑ	7	6-10 years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #009 (Store Room)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Exposed	Basement	942	SF	4	0-1 year	Peeling paint falling to the floor
	Doors - Steel Doors incl hw	Basement	1	EΑ	7	10+ years	. comig paint raining to the need
	Floor - Carpet	Basement	917	SF	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	25	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	7	EA	7	6-10 years	
	Marker Board	Basement	28	LF	7	6-10 years	
	Storage/ Closet	Basement	40	SF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,225	SF	7	10+ years	
				EA	7		
	Wireless System	Basement	1	EA	,	6-10 years	
Classroo	om #102 (Science)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	55	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Floor - Wood	1st Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	Rank changed to match current
	- · · · · · · · · · · · · · · · · · · ·		-	_		, , , , , ,	observation
	Walls - Plaster/Drywall	1st Floor	1,398	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
			_		-	, , , , , , , , , , , , , , , , , , , ,	
_Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	7	10+ years	
	Doors - Transom Window	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	Rank changed to match current
			120	٥.	•	.o. youro	c.is.igss to materi ourion

Campus Name: Sheridan Page: 15 of 32 Assessment Date: 06/09/2022



- Type  - Plaster/Drywall  - (Regular Classroom) nits work og - Plaster/Drywall s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface or Board ge/ Closet  - Plaster/Drywall  - (Kindergarten) nits work	Location  1st Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity  1,398  1 7 900 9 1 900 14 33 126 1,358	EA LF SF EA LF SF SF	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	Recommend Replacement  10+ years  10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Comments observation  Rank changed to match current observation
- Plaster/Drywall  4 (Regular Classroom)  nits  work  1/2 - Plaster/Drywall  2 - Plaster/Drywall  3 - Transom Window  4 - Wood Doors inclu hw  4 - Wood  1/2 - Pendent/Surface  1/2 - Plaster/Drywall  4 - Plaster/Drywall  5 (Kindergarten)  nits	1st Floor	1,398 1 7 900 9 1 900 14 33 126 1,358	SF EA LF SF EA SF EA LF SF	7 7 7 7 7 7 7 7	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	observation  Rank changed to match current
4 (Regular Classroom) nits work Ig - Plaster/Drywall S - Transom Window S - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	1 7 900 9 1 900 14 33 126	EA LF SF SF EA SF EA LF SF	7 7 7 7 7 7 7	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	Rank changed to match current
4 (Regular Classroom) nits work Ig - Plaster/Drywall S - Transom Window S - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	1 7 900 9 1 900 14 33 126	EA LF SF SF EA SF EA LF SF	7 7 7 7 7 7 7	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
nits work g - Plaster/Drywall s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	7 900 9 1 900 14 33 126	LF SF EA SF EA LF SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
nits work g - Plaster/Drywall s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	7 900 9 1 900 14 33 126	LF SF EA SF EA LF SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
work  g - Plaster/Drywall s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	7 900 9 1 900 14 33 126	LF SF EA SF EA LF SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	900 9 1 900 14 33 126	SF SF EA SF EA LF SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
s - Transom Window s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor	9 1 900 14 33 126 1,358	SF EA SF EA LF SF	7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
s - Wood Doors inclu hw - Wood ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 900 14 33 126 1,358	EA SF EA LF SF	7 7 7 7 7	10+ years 10+ years 6-10 years 6-10 years 10+ years	
<ul> <li>- Wood</li> <li>ng - Pendent/Surface</li> <li>er Board</li> <li>ge/ Closet</li> <li>- Plaster/Drywall</li> <li>5 (Kindergarten)</li> <li>nits</li> </ul>	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	14 33 126 1,358	SF EA LF SF	7 7 7 7	10+ years 6-10 years 6-10 years 10+ years	
ng - Pendent/Surface er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor 1st Floor 1st Floor 1st Floor	14 33 126 1,358	EA LF SF	7 7 7	6-10 years 6-10 years 10+ years	
er Board ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor 1st Floor 1st Floor 1st Floor	33 126 1,358	LF SF	7 7	6-10 years 10+ years	
ge/ Closet - Plaster/Drywall 5 (Kindergarten) nits	1st Floor  1st Floor  1st Floor	126 1,358	SF	7	10+ years	
- Plaster/Drywall  5 (Kindergarten) nits	1st Floor	1,358				
5 (Kindergarten) nits	1st Floor		SF	7	10+ years	
nits		1				
nits		1				
		I	EA	7	6.10	
WOLK	4 at Flace		LF	7	6-10 years	
	1st Floor	8	SF	7	10+ years	
g - Lay-in	1st Floor	968	SF SF	7	10+ years	
s - Transom Window	1st Floor	48		7	10+ years	
s - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
- Wood	1st Floor	968	SF	7	10+ years	
ng - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
er Board	1st Floor	32	LF	7	6-10 years	5 1 1 1 1 1 1 1
ge/ Closet	1st Floor	126	SF	7	10+ years	Rank changed to match current observation
- Plaster/Drywall	1st Floor	1,489	SF	7	10+ years	
6 (Regular Classroom)						
nits	1st Floor	1	EA	7	6-10 years	
work	1st Floor	7	LF	7		
g - Plaster/Drywall	1st Floor	968	SF	7		
s - Transom Window	1st Floor	32	SF	7		
s - Wood Doors inclu hw	1st Floor	2	ĒA	7		
- Tile	1st Floor	968	SF	6	10+ years	
	1st Floor	16	EΑ	7		
ng - Pendent/Surface	1st Floor	24	LF	7		
	1st Floor	126	SF	7	10+ years	Rank changed to match current
ng - Pendent/Surface er Board ge/ Closet		1,489	SF	7	10+ years	observation
wo g s - s -	ork - Plaster/Drywall - Transom Window Wood Doors inclu hw Tile - Pendent/Surface Board	ork 1st Floor - Plaster/Drywall 1st Floor Transom Window 1st Floor Wood Doors inclu hw 1st Floor Tile 1st Floor g - Pendent/Surface 1st Floor Board 1st Floor	ork       1st Floor       7         - Plaster/Drywall       1st Floor       968         Transom Window       1st Floor       32         Wood Doors inclu hw       1st Floor       2         Tile       1st Floor       968         g - Pendent/Surface       1st Floor       16         Board       1st Floor       24         e/ Closet       1st Floor       126	ork         1st Floor         7         LF           - Plaster/Drywall         1st Floor         968         SF           Transom Window         1st Floor         32         SF           Wood Doors inclu hw         1st Floor         2         EA           Tile         1st Floor         968         SF           g - Pendent/Surface         1st Floor         16         EA           Board         1st Floor         24         LF           e/ Closet         1st Floor         126         SF	ork       1st Floor       7 LF 7         - Plaster/Drywall       1st Floor       968 SF 7         Transom Window       1st Floor       32 SF 7         Wood Doors inclu hw       1st Floor       2 EA 7         Tile       1st Floor       968 SF 6         g - Pendent/Surface       1st Floor       16 EA 7         Board       1st Floor       24 LF 7         e/ Closet       1st Floor       126 SF 7	ork       1st Floor       7       LF       7       10+ years         - Plaster/Drywall       1st Floor       968       SF       7       10+ years         Transom Window       1st Floor       32       SF       7       10+ years         Wood Doors inclu hw       1st Floor       2       EA       7       10+ years         Tile       1st Floor       968       SF       6       10+ years         g - Pendent/Surface       1st Floor       16       EA       7       6-10 years         Board       1st Floor       24       LF       7       6-10 years         br/>Closet       1st Floor       126       SF       7       10+ years

Campus Name: Sheridan Page : 16 of 32 Assessment Date: 06/09/2022



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	968	SF	7	10+ years	Rank changed to match current observation
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Wood	1st Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	Rank changed to match current
	-					-	observation
	Walls - Plaster/Drywall	1st Floor	1,468	SF	7	10+ years	
lassroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	968	SF	4	1-2 years	Cracking and broken
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	•
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	1st Floor	1,468	SF	7	10+ years	
Classroo	nm #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	892	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Boots inclu tiw	2nd Floor	892	SF	7	-	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years 6-10 years	
				LF			
	Marker Board	2nd Floor	33	SF	7	6-10 years	
	Storage/ Closet	2nd Floor	126		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,489	SF	7	10+ years	
Classroo	nm #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	35	LF SF	6	10+ years	
	Ceiling - Plaster/Drywall					10+ years	

Campus Name: Sheridan Page : 17 of 32 Assessment Date: 06/09/2022



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,398	SF	7	10+ years	
	Work Sink	2nd Floor	3	ĒΑ	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor		EA		-	
			2		7 7	10+ years	
	Floor - Tile	2nd Floor	890	SF	=	10+ years	NAIs also a 4th a
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Missing tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	66	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,398	SF	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	900	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,358	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
211200101	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	89	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	968	SF	7	10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor		SF SF	7		
			32 2	_	7 7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor		EA		10+ years	
	Floor - Tile	2nd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	

Campus Name: Sheridan Page: 18 of 32 Assessment Date: 06/09/2022



Catego	ry : Classroom		В	uilding	: Main		333 W 27th 611(EE1, 611)cag6, 1E 00010
carege	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,489	SF	7	10+ years	
_Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	89	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,468	SF	7	10+ years	
_Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	89	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	968	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	60	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,468	SF	7	10+ years	
Classroo	om #209 (Regular Classroom)						
Classiu	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	936	SF	7	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	32	SF	7		
	Doors - Transom Window  Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	SF EA	7	10+ years	
						10+ years	
	Floor - Wood	2nd Floor	936	SF E^	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	33	LF CF	7	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,403	SF	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	51110	1001	'	_, .	•	o io youio	



ategor	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	872	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	892	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	33	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	5	10+ years	Wall crack
	Walls - Plaster/Drywall	1st Floor	1,479	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Damaged plaster walls
ssron	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	900	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Bools med nw	3rd Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	33	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	Rank changed to match current
	-				-	•	observation
	Walls - Plaster/Drywall	3rd Floor	1,358	SF	7	10+ years	
ssroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	75	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	Rank changed to match current observation
	Chalk Board	3rd Floor	16	LF	4	2-5 years	observation
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	52	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	3rd Floor	1,489	SF	7	10+ years	ODSGIVATION



ıtegor	ry : Classroom		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	75	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	52	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	3rd Floor	1,489	SF	7	10+ years	observation
sroo	m #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	75	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	Rank changed to match current observation
	Chalk Board	3rd Floor	33	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	33	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,468	SF	7	10+ years	
sroo	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	75	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	968	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Water damage
	Chalk Board	3rd Floor	33	LF	4	2-5 years	-
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	968	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	33	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	Rank changed to match current observation
	Walls - Plaster/Drywall	3rd Floor	1,462	SF	7	10+ years	5.55. 14.611
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	1-2 years	Water damage



Recommend

Catego	ry : Classroom	Category : Classroom			Building : Main				
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	75	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	1,152	SF	6	10+ years	Peeling. Rank changed to match current observation		
	Chalk Board	3rd Floor	18	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Wood	3rd Floor	1,152	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years			
	Marker Board	3rd Floor	33	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,598	SF	7	10+ years			

**Building: Main** Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,849	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Wood	1st Floor	2,849	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,050	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,749	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Wood	2nd Floor	2,849	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,012	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	818	SF	7	10+ years	
	Ceiling - Splined	3rd Floor	358	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,100	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	76	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,449	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	2,879	SF	7	10+ years	
	Doors - Side-lite	Basement	44	SF	7	10+ years	
	Doors - Transom Window	Basement	226	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement	14	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	2,879	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	35	EA	7	6-10 years	
	Walls - Masonry	Basement	936	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	3,348	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	10	SF	5	0-1 year	Damaged plaster
	Walls - Structural Glazed Tile	Basement	178	SF	7	10+ years	

Campus Name: Sheridan Page : 22 of 32 Assessment Date: 06/09/2022



Catego	ry : Interior		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	5	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	#1 S Stair	685	SF	6	10+ years	
	Floor - Asphalt	#1 S Stair	465	SF	7	10+ years	
	Handrails	#1 S Stair	178	LF	7	10+ years	Rank changed to match current observation
	Lighting - Pendent/Surface	#1 S Stair	6	EA	7	6-10 years	
	Stairs - Asphalt	#1 S Stair	80	LF	7	10+ years	
	Walls - Plaster/Drywall	#1 S Stair	3,366	SF	7	10+ years	
	Walls - Plaster/Drywall	#1 S Stair	10	SF	5	0-1 year	Damaged plaster walls
	Ceiling - Plaster/Drywall	#2 N Stair	355	SF	7	10+ years	•
	Ceiling - Splined	#2 N Stair	335	SF	7	10+ years	
	Ceiling - Splined	#2 N Stair	30	SF	4	0-1 year	Water damage tiles
	Floor - Asphalt	#2 N Stair	518	SF	7	10+ years	-
	Handrails	#2 N Stair	178	LF	7	10+ years	Rank changed to match current observation
	Lighting - Pendent/Surface	#2 N Stair	7	EΑ	7	6-10 years	
	Stairs - Asphalt	#2 N Stair	80	LF	7	10+ years	
	Walls - Plaster/Drywall	#2 N Stair	3,112	SF	7	10+ years	
	Ceiling - Exposed	#3 E Stair	240	SF	7	10+ years	
	Ceiling - Plaster/Drywall	#3 E Stair	325	SF	6	10+ years	
	Floor - Asphalt	#3 E Stair	440	SF	7	10+ years	
	Handrails	#3 E Stair	198	LF	7	10+ years	Rank changed to match current observation
	Lighting - Pendent/Surface	#3 E Stair	6	EA	7	6-10 years	
	Stairs - Asphalt	#3 E Stair	88	LF	7	10+ years	
	Walls - Plaster/Drywall	#3 E Stair	3,352	SF	7	10+ years	



Category : Exterior Building : Linked Addition

ategory : Exterior			Building : Linked Addition					
					_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Entrance Control - Audio and Video	5	1	EA	7	10+ years		
	Exterior Doors - Store Front	5	3	EA	7	10+ years		
	Power Door Operator and Controls	5	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	6	2	EA	7	10+ years		
	Entrance Control - Audio and Video	7	1	EA	7	10+ years		
	Exterior Doors - Store Front	7	3	EA	7	10+ years		
	Power Door Operator and Controls	7	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	Annex Roof 6	2	EA	6	10+ years		
Foundati	on							
	Foundation - Concrete	Entire Building	424	LF	7	10+ years		
	Superstructure - Steel with Clay Tile Arch	Entire Building	9,417	SF	7	10+ years		
Lighting								
	Exterior Lighting - Wall Mounted	Entire Building	19	EA	7	10+ years		
D ( )								
Roof Sys		#5A @ A						
	Coping - Metal	#5A @ Annex, (Elevator)	20	LF	7	10+ years		
	Downspouts - Exterior Downspouts	#5A @ Annex, (Elevator)	60	LF	6	10+ years		
	Parapet - 16" - 30" Height	#5A @ Annex, (Elevator)	20	LF	7	10+ years		
	Roof - Modified Bitumen	#5A @ Annex, (Elevator)	100	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	#5A @ Annex, (Elevator)	100	SF	7	10+ years		
	Concrete Topping	_			_			
	Access Ladder - Metal	5	1	EA	7	10+ years		
	Coping - Metal	5	370	LF	7	10+ years		
	Downspouts - Exterior Downspouts	5	46	LF	7	10+ years		
	Downspouts - Interior Downspouts	5	69	LF	6	10+ years		
	Parapet - 16" - 30" Height	5	275	LF	7	10+ years		
	Parapet - Parapet > 30"	5	95	LF	7	10+ years		
	Roof - Modified Bitumen	5	3,888	SF	7	10+ years		
	Roof Hatch - Metal	5	1	EA	7	10+ years		
	Roof Structure - Steel / Metal Deck/	5	3,888	SF	7	10+ years		
	Concrete Topping					-		
	Access Ladder - Metal	6	1	EA	7	10+ years		
	Coping - Metal	6	330	LF	7	10+ years		
	Downspouts - Interior Downspouts	6	40	LF	6	10+ years		
	Parapet - 16" - 30" Height	6	330	LF	7	10+ years		
	Roof - Modified Bitumen	6	5,508	SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	6	5,508	SF	7	10+ years		



Catego	ry : Exterior		R	uilding	· I inker	d Addition	533 W 27th STREET, Chicago, IL 60616
Calego	TY . Exterior			unung	. LIIIKG	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls			<b>,</b>				
vvano	Exterior Walls - Brick	Entire Building	17,798	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	1,280	SF	7	10+ years	
	Wall	3	•			,	
Windows	3						
	Clerestory - Glass Double-Pane	Entire Building	192	SF	7	10+ years	
	Lintels - Steel	Entire Building	106	LF	7	10+ years	
	Windows - Sash Aluminum	Entire Building	360	SF	7	10+ years	
Catego	ry : Electrical		В	uildina	· I inked	d Addition	
Guiogo				unung	· Lillino	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
· ·	Exit Signs - Corridors and Stairs	1st Floor	3	EA	7	6-10 years	With internal batteries, LED exit lights
	Exit Signs - Gym	1st Floor	2	EA	7	6-10 years	With internal batteries, LED style
	Emergency Battery Packs - Corridors and	1st Floor	6	EA	6	6-10 years	2018 installation
	Stairs						
	Emergency Battery Packs - Gym	1st Floor	4	EA	6	6-10 years	2018 installation
	Emergency A/C Power - Corridors and Stairs	1st Floor	1,087	SF	7	10+ years	2018 installation
	Emergency A/C Power - Gym	1st Floor	3,671	SF	7	10+ years	2018 installation
	Security System - CCTV	Entire Building	8,956	SF	6	6-10 years	2010 Installation
	Security System - Intrusion Detection	Entire Building	8,956	SF	6	6-10 years	
	, ,	Ğ	•			,	
Main Se	rvice						
	PA System	1st Floor	8,956	SF	6	6-10 years	Connected to main building
	Main Electrical Service - 2000 A	1st Floor	1	EA	7	10+ years	2018 installation, serves addition
	120/208/3PH						
Power D	istribution						
1 OWEI D	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	2018 installation
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	2018 installation
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	800 Amps
	amp	3				, , , , , ,	, ,
Catego	ry : Fire Protection		R	uildina	·linkor	d Addition	
Jaiogo				unung	. בוווונטנ	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	1st Floor	8,956	SF	7	10+ years	
	Fire Alarm_System	1st Floor	8,956	SF	7	10+ years	Serves addition, connected to main

Campus Name: Sheridan Page : 25 of 32 Assessment Date: 06/09/2022



0-1					1 *- *	I A .I.I'4'	533 W 27th STREET, Chicago, IL 60616
Catego	ry : Fire Protection		В	uilding	: Linked	l Addition	
Crous	Itam Tura	Logotion	Quantity	LION	Donle	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments building
	Fire Pump Controller	1st Floor	1	EA	7	10+ years	building
	The Fullip Controller	1001			•	To Fyddio	
Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	1st Floor	1	EA	7	10+ years	2018 installation, serves addition
	Jockey Pump	1st Floor	1	EA	7	10+ years	
Sprinkla	System						
<u> Эрппкіе</u>	Sprinkler Heads	Entire Building	8,956	SF	7	10+ years	2018 installation
	Sprinkler Piping	Entire Building	8,956	SF	7	10+ years	2010
	Wet Sprinkler System	Entire Building	8,956	SF	7	10+ years	2018 installation
Catego	ry : Mechanical		В	uildina	: Linked	l Addition	
Guiogo	. y . moonamoa.		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10+ years	RTU 1, serves gym in addition, 2018
	Gas Heating and DX Cooling Coil - 21 - 30						installation, no longer under
	tons Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10 L VOOR9	warrantee RTU 2, serves hallway in addition, no
	Gas Heating and DX Cooling Coil - 5 - 10	Rooi	I	EA	O	10+ years	longer under warantee
	tons						longer under warantee
Heating							
	Cabinet Heaters - With Electric Coil	1st Floor	2	EA	7	10+ years	Ceiling mounted, 2018 installation
	Unit Heater - Electric	1st Floor	4	EA	7	10+ years	2018 installation
	Wall Heater - Electric	1st Floor	3	EA	7	10+ years	Ceiling mounted, in restrooms
Tempera	ature Control						
•	Electric Controls	1st Floor	8,956	SF	7	10+ years	No DDC, no pneumatics. Serve unit
		4 . =!	_		_	4.0	heaters and 2 RTUs.
	Electric Thermostat	1st Floor	5	EA	7	10+ years	Serve 3 unit heaters and 2 RTUs
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	10+ years	In elevator room, 2018 installation
	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	7	10+ years	2018 installation
	500 CFM						
Catego	ry : Plumbing		В	uilding	: Linked	Addition	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat		Location	Quantity	COIVI	Naiik	Replacement	Comments
TIOL WAL	<del>기</del>						



Catego	ry : Plumbing	В	uilding	: Linked	d Addition	-	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - Less than 150000 BTU/HR	1st Floor	2	EA	6	6-10 years	2018 installation, serves addition building
Piping							
	Domestic Piping-Hot Water Return Lines	1st Floor	8,956	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	1st Floor	8,956	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	1st Floor	8,956	SF	7	10+ years	2018 installation
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	1st Floor	8,956	SF	7	10+ years	No leaks
	Sanitary Piping	1st Floor	8,956	SF	7	10+ years	
	Storm Piping	1st Floor	8,956	SF	7	10+ years	
	Vent Piping	1st Floor	8,956	SF	7	10+ years	
Pumps							
•	Pumps - Sump-Simplex	1st Floor	1	EA	7	10+ years	Under elevator, 2018 installation, elevator shared with main building,
	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	7	10+ years	2018 installation, serves addition and main buildings

Category: Room **Building: Linked Addition** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	122D	118	SF	7	10+ years	
	Doors - Steel Doors incl hw	122D	1	ĒΑ	7	10+ years	
	Floor - Tile	122D	118	SF	7	10+ years	
	Lighting - Lay-in	122D	2	EA	7	6-10 years	
	Power Distribution	122D	10	EA	7	10+ years	
	Walls - Plaster/Drywall	122D	405	SF	7	10+ years	
Gymnasi	ia						
	Bleacher Seating	1st Floor	85	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	3,514	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	8	EA	7	10+ years	
	Floor - Sport Flooring	1st Floor	3,514	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	328	SF	7	10+ years	
	Storage/ Closet	1st Floor	157	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,381	SF	7	10+ years	



Catego	ry : Room		Building : Linked Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
1echani	cal/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	64	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	203	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	207	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	147	SF	7	10+ years			
	Storage Room	1st Floor	100	SF	7	10+ years			
Restroor	n								
	Accessories	1st Floor	72	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	72	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	72	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	1	EA	7	6-10 years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	336	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	1st Floor	175	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	175	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	175	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	2	EA	7	6-10 years			
	Lavatory	1st Floor	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years			
	Partitions	1st Floor	1	EA	7	10+ years			
	Urinals	1st Floor	2	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	640	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	1st Floor	217	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	217	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	217	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	2	EA	7	6-10 years			
	Lavatory	1st Floor	2	EΑ	7	10+ years			
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years			
	Partitions	1st Floor	4	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	714	SF	7	10+ years			
	Water Closet	1st Floor	4	EA	7	10+ years			



Catego	ry : Classroom		В	uilding	: Linked	l Addition	-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #120 (Science Lab Level 1)						
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	917	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	917	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Science Lab Elements	1st Floor	917	SF	7	10+ years	
	Storage/ Closet	1st Floor	152	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,040	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Linked	l Addition	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor	1,087	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	14	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,087	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,927	SF	7	10+ years	
_Safetv							
	Security Cameras	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	7	EA	7	6-10 years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	West	1	EA	7	10+ years	



Category : Site Building : Site

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
Fencing							
r ending	Fencing - Chain Link	Entire Site	739	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	712	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	712	LF	6	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	1,575	LF	6		
						10+ years	Manual and wave are align with
	Fencing - Old Standard Ornamental	Entire Site	25	LF	4	1-2 years	Weave and wave cracking with
	Familia Cld Ctair dayd Own are antal	Entine Cite	25	LF	4	4.0	multiple Breaks. Deteriorating Base.
	Fencing - Old Standard Ornamental	Entire Site	25	LF	4	1-2 years	Weave Cracking with multiple Breaks Deteriorating Base.
							Deteriorating base.
Landsca	•						
	Benches	Entire Site	6	EΑ	7	10+ years	
	Landscape - Grass	Entire Site	25,574	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,863	SF	6	10+ years	
	Parkway trees	Entire Site	21	EΑ	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Tree cut down 5" above grade -
	· · · · ·	<b>-</b>			_		tripping hazard
	Planting Beds/ Area	Entire Site	2,618	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	7	10+ years	
Parking I	Lot						
Ū	Concrete Curbs	Entire Site	250	LF	7	10+ years	
	Interior Plantings	Entire Site	250	LF	7	10+ years	
	Surface - Asphalt	Entire Site	17,992	SF	7	10+ years	
	Surface - Concrete	Entire Site	1,800	SF	7	10+ years	
	Surface - Concrete	Entire Site	1,800	SF	7	10+ years	
	Trash Enclosure - Chain Links	Entire Site	900	SF	7	10+ years	
						, , , , , ,	
Playgrou							
	Equipment - Pre K 3-5	South	1	EA	7	10+ years	
	Equipment - Pre K 3-5	South	1	EA	7	10+ years	
	Equipment - School Age 5-12	South	1	EA	7	10+ years	
	Surface - Poured Surface	South	3,250	SF	7	10+ years	
O. 1							
Sidewalk	(S						



#### Mark Sheridan Math & Science Academy

533 W 27th STREET, Chicago, IL 60616

Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	464	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	464	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,349	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	465	SF	4	0-1 year	Trip hazards - heaving and broken
	Sidewalks - Perimeter Sidewalks	Entire Site	465	SF	4	0-1 year	Trip hazards - heaving and broken
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Sheridan Page: 31 of 32 Assessment Date: 06/09/2022

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main					(01)	1 11 2 21		0.00	
Computer Lab	Computer Lab	Basement	008	800	834	50	22	N	N
Kindergarten	Regular Classroom	1st Floor	105	105	968	90	36	N	N
Kindergarten	Regular Classroom	1st Floor	107	107	968	100	42	N	N
Other Instructional Use	Multi Purpose Room	Basement	007	007	905	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	900	96	36	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	900	116	42	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	968	90	27	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	968	112	54	N	N
Regular Classroom	Regular Classroom	1st Floor	301	301	892	96	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	892	96	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	900	96	36	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	900	96	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	201	900	116	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	968	90	27	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	968	100	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	968	112	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	936	116	57	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	900	116	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	968	90	27	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	968	90	27	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	968	100	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	968	112	54	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	1,152	116	57	N	N
Science	Regular Classroom	1st Floor	102	102	900	96	36	N	N
Store Room	Computer Lab	Basement	009	009	942	36	15	N	N

<b>Building: Linked Addition</b>								
Science Lab Level 1	Science Lab Level 1	1st Floor	120	120	917	228	30	