

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1928 | 3 | 65,617 |
| Addition | 1952 | 2 | 4,984 |
| Campus Total | | | 70,601 |

| Catego | Category : Exterior | | | | | | |
|----------|---------------------------------------|---------------------------------|----------|-----|------|-------------|-------------------------------------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Cell Equ | ipment | | | | | | |
| | Cell Equipment - Antenna | Chimney and Roof 4 | 9 | EA | 7 | 10+ years | |
| | Cell Equipment - Cabinets | Chimney and Roof 4 | 6 | EA | 7 | 10+ years | |
| Entrance | 9 | | | | | | |
| | Exterior Doors - Exterior Steel Door | Door 1 - East - Auditorium | 2 | EA | 7 | 6-10 years | |
| | Exterior Doors - Transom Lite | Door 1 - East - Auditorium | 2 | EA | 7 | 6-10 years | |
| | Exterior Stairs - Stone | Door 1 - East - Auditorium | 64 | LF | 4 | 6-10 years | Repaired |
| | Entrance Control - Audio | Door 2 - East - Main Entrance | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | Door 2 - East - Main Entrance | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 2 - East - Main Entrance | 2 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Stone | Door 2 - East - Main Entrance | 90 | LF | 7 | 6-10 years | |
| | Power Door Operator and Controls | Door 2 - East - Main Entrance | 1 | EA | 7 | 6-10 years | |
| | Stair Handrail - Steel_Stair Handrail | Door 2 - East - Main Entrance | 24 | LF | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | Door 3 - East Center - Elevator | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 3 - East Center - Elevator | 1 | EA | 7 | 6-10 years | |
| | Exterior Stairs - Stone | Door 3 - East Center - Elevator | 3 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 4 - East | 2 | EA | 7 | 10+ years | Actual East Facade |
| | Exterior Doors - Transom Lite | Door 4 - East | 2 | EA | 7 | 6-10 years | |
| | Exterior Stairs - Stone | Door 4 - East | 96 | LF | 7 | 6-10 years | Repaired |
| | Exterior Doors - Exterior Steel Door | Door 5 - Northeast - Gym | 2 | EA | 7 | 10+ years | Actual - Southwest |
| | Exterior Doors - Transom Lite | Door 5 - Northeast - Gym | 1 | EA | 7 | 6-10 years | Actual Southwest |
| | Exterior Stairs - Stone | Door 5 - Northeast - Gym | 40 | LF | 5 | 6-10 years | Actual Southwest With no Stone Stair Issue - Previous Disrepair Note |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------|----------------------------------------------------|------------------------------------|---------------|----------|--------|------------------------|------------------------------------------------------------|
| Ū | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | | | | | | • | should apply to Entrances #2 & #4 |
| | Entrance Control - Audio | Door 6 - Northwest | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | Door 6 - Northwest | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 6 - Northwest | 2 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | Door 6 - Northwest | 76 | LF | 7 | 10+ years | |
| | Power Door Operator and Controls | Door 6 - Northwest | 1 | EA | 7 | 6-10 years | Does Not Exist at Door - Buzzer is |
| | | | • | -/ (| • | o ro youro | Office |
| | Ramp Handrail - Steel_Ramp Handrail | Door 6 - Northwest | 124 | LF | 7 | 10+ years | Needs Paint |
| | Ramps - Concrete | Door 6 - Northwest | 62 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | Door 6 - Northwest | 60 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 6.5 - Boiler North | 00 | EA | 5 | 2-5 years | Scrape/Paint |
| | Exterior Doors - Overhead Rolling/ Garage | Door 6.7 - Boiler West | 1 | EA | 6 | 10+ years | Scrape/Failt |
| | Door | Door 6.7 - Boller West | I | EA | 0 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 7 - Boiler Southwest | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Door 8 - west Kitchen | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Door 8 - west Kitchen | 1 | EA | 7 | 6-10 years | |
| | Exterior Stairs - Concrete | Door 8 - west Kitchen | 40 | LF | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Door 8 - west Kitchen | 60 | LF | 7 | 6-10 years | |
| | Ramps - Concrete | Door 8 - west Kitchen | 30 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | Door 8 - west Kitchen | 20 | LF | 7 | 6-10 years | |
| | Foundation - Concrete Superstructure - Concrete | Entire Building Entire Building | 861 65,617 | LF SF | 7 7 | 10+ years 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 12 | EA | 6 | 6-10 years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 6 | EA | 6 | 6-10 years | |
| | | 3 | - | | - | , | |
| Roof Sys | | - | | | | | |
| | Access Ladder - Wood | Roof - 1 | 2 | EA | 4 | 0-1 year | Added Item - (Ladder not Mechanically Fastened/Secured) |
| | Access Ladder - Metal | Roof 1 | 2 | EA | 5 | 2-5 years | ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, , |
| | Chimney - Brick Chimney- Concrete/ Mortar | Roof 1 | 110 | LF | 6 | 10+ years | |
| | Liner | | | | ÷ | , , | |
| | Coping - Terra Cotta | Roof 1 | 460 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 1 | 322 | LF | 6 | 6-10 years | |
| | Parapet - Parapet > 30" | Roof 1 | 460 | LF | 6 | 6-10 years | Mortar Joint Failure/Disrepair |
| | Roof - Asphalt Gravel Ballast | Roof 1 | 11,285 | SF | 6 | 2-5 years | |
| | Roof Hatch - Metal | Roof 1 | 2 | EA | 5 | 2-5 years 2-5 years | |
| | Roof Structure - Concrete | Roof 1 | ے 11,285 | SF | 5 7 | 10+ years | |
| | Access Ladder - Wood | Roof 2 | | EA | | | Unsafe |
| | Coping - Terra Cotta | Roof 2 | 2 359 | LF | 5 6 | 2-5 years 10+ years | Ulisale |
| | | BELINI Z | | | 'n | | |



| atego | ry : Exterior | | В | uilding | : Main | | |
|--------|----------------------------------|-----------------|----------|---------|--------|-------------|----------------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Downspouts - Interior Downspouts | Roof 2 | 180 | LF | 6 | 6-10 years | |
| | Parapet - 16" - 30" Height | Roof 2 | 158 | LF | 6 | 6-10 years | |
| | Parapet - Parapet > 30" | Roof 2 | 201 | LF | 6 | 6-10 years | |
| | Roof - Asphalt Gravel Ballast | Roof 2 | 7,827 | SF | 6 | 6-10 years | |
| | Roof Hatch - Metal | Roof 2 | 2 | EA | 5 | 2-5 years | |
| | Roof Structure - Concrete | Roof 2 | 7,827 | SF | 7 | 10+ years | |
| | Access Ladder - Wood | Roof 3 | 1 | EA | 5 | 2-5 years | |
| | Coping - Terra Cotta | Roof 3 | 185 | LF | 6 | 6-10 years | |
| | Downspouts - Interior Downspouts | Roof 3 | 72 | LF | 6 | 6-10 years | |
| | Parapet - 16" - 30" Height | Roof 3 | 185 | LF | 6 | 6-10 years | |
| | Roof - Asphalt Gravel Ballast | Roof 3 | 3,648 | SF | 6 | 6-10 years | |
| | Roof Hatch - Metal | Roof 3 | 1 | EA | 5 | 2-5 years | |
| | Roof Structure - Concrete | Roof 3 | 3,648 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Roof 4 | 1 | EA | 7 | 10+ years | |
| | Coping - Terra Cotta | Roof 4 | 123 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 4 | 50 | LF | 6 | 6-10 years | |
| | Parapet - 16" - 30" Height | Roof 4 | 123 | LF | 6 | 6-10 years | |
| | Roof - Asphalt Gravel Ballast | Roof 4 | 1,713 | SF | 6 | 6-10 years | |
| | Roof Structure - Concrete | Roof 4 | 1,713 | SF | 7 | 10+ years | |
| | Coping - Terra Cotta | Roof 5 | 18 | LF | 6 | 6-10 years | |
| | Downspouts - Exterior Downspouts | Roof 5 | 2 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 5 | 18 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 5 | 47 | SF | 6 | 10+ years | |
| | Roof Structure - Concrete | Roof 5 | 47 | SF | 7 | 10+ years | |
| | Coping - Terra Cotta | Roof 6 | 18 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 6 | 2 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 6 | 18 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 6 | 47 | SF | 6 | 10+ years | |
| | Roof Structure - Concrete | Roof 6 | 47 | SF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 7 | 30 | LF | 5 | 0-1 year | None Observed/ |
| | Roof - Asphalt Gravel Ballast | Roof 7 | 231 | SF | 4 | 0-1 year | Deteriorated |
| | Roof Structure - Concrete | Roof 7 | 231 | SF | 7 | 10+ years | Detenorated |
| | | | 251 | 01 | 1 | TUT years | |
| alls | | | | | | | |
| all5 | Cheek-Wall - Stone | Entire Building | 60 | SF | 6 | 10+ years | |
| | Cornice - Terra Cotta | Entire Building | 747 | LF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 31,965 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 861 | SF | 6 | 10+ years | |
| | Exterior Walls - Terra Cotta | Entire Building | 1.367 | SF | 6 | 10+ years | |
| | | | 1,507 | 0 | 0 | io+ years | |
| indows | 3 | | | | | | |
| | Curtain wall - Insulated Panel | Entire Building | 3,173 | SF | 6 | 6-10 years | |
| | | | | | | | |
| | Guard - Guards wire guard | Entire Building | 1,846 | SF | 6 | 6-10 years | |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------------|--------------------------------------------------------|----------------------------|----------|---------|--------|-------------|-------------------------------------------------------------------------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lintels - Terra Cotta | Entire Building | 194 | LF | 6 | 10+ years | |
| | Windows - Casement Steel | Entire Building | 125 | SF | 6 | 6-10 years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 4,550 | SF | 6 | 6-10 years | |
| ` otogo | | - | Р | سناطنهم | . Main | - | |
| Jatego | ry : Electrical | | В | uilding | : wain | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerger | ncy System | | | | | | |
| | Emergency A/C Power - Auditoium and Aisle Lighting | 1st Floor, Entire Building | 3,896 | SF | 6 | 6-10 years | Building has EM panel |
| | Emergency A/C Power - Corridors and Stairs | 1st Floor, Entire Building | 9,761 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Gym | 1st Floor, Entire Building | 3,016 | SF | 6 | 6-10 years | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 10+ years | Functional, tested, serves main and addition buildings |
| | Exit Signs - Auditoium | Entire Building | 11 | EA | 6 | 6-10 years | 5 |
| | Exit Signs - Corridors and Stairs | Entire Building | 33 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Auditoium and Aisle Lighting | Entire Building | 16 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 15 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | 2 in gym, damaged wire screen needs to be repaired. Functional, RUL increased |
| | Security System - CCTV | Entire Building | 65,617 | SF | 6 | 6-10 years | Also serves addition |
| | Security System - Intrusion Detection | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| /lain Sei | vice | | | | | | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | Also serves addition |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | 10+ years | Functional, tested second feed |
| | PA System | Entire Building | 65,617 | SF | 6 | 6-10 years | Connected to addition building |
| ower D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | Functional, works well |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | 10+ years | Repaired, functionI |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | Functional, inspected |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 7 | 10+ years | Functional, ranked 7 |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | Functional, tested |
| | Lighting and Power Panels - Above 100 A | Entire Building | 10 | EA | 7 | 10+ years | Functional, inspected |
| | | | - | | 7 | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 1 | 10+ years | Repaired, functional |



| Categor | y : Electrical | | R | uilding | • Main | | 5239 N Leavitt STREET, Chicago, IL 6065 |
|------------|--------------------------------------------------------------------------------------------|-----------------|----------|---------|--------|-------------|-----------------------------------------------------------------------------------|
| Calegoi | y . Electrical | | | unung | . mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| oroup | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | Functional, good condition |
| | | Entire Bananig | | L/\ | | ior youro | r unotional, good contaiton |
| Catego | y : Fire Protection | | В | uilding | : Main | | |
| eulegel | , | | | anang | - main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alarr | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | Also serves addition |
| | Fire Alarm Strobe Lights | Entire Building | 65,617 | SF | 6 | 6-10 years | Also serves addition |
| | Fire Alarm_System | Entire Building | 65,617 | SF | 6 | 6-10 years | Also serves addition |
| | | Little Building | 05,017 | 51 | 0 | 0-10 years | Also serves addition |
| Categor | y : Mechanical | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | ling Systems | | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - Less than 4000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, works well, serves gym |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | Not painted, functional |
| | Auxiliaries - Less than 4000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, adjusted |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room | 100 | LF | 6 | 10+ years | Common return, functional, not recently painted |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Works well, serviced recently, functional, serves south section of building |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, not painted recently. Needs to be painted |
| | Auxiliaries - 25001 - 35000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Repaired. Functional, work well |
| | Reheat Boxes - Reheat Boxes with Steam Coil | Mechanical Room | 6 | EA | 5 | 6-10 years | Functional, need adjustment |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room | 100 | LF | 6 | 10+ years | Functional. Needs to be painted |
| | Zone Dampers | Mechanical Room | 16 | EA | 5 | 6-10 years | Manually operated, need to be adjusted. |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, recently repaired, serve north section on building |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | Not painted, functional, adjusted |
| | Auxiliaries - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, tested |
| | Reheat Boxes - Reheat Boxes with Steam Coil | Mechanical Room | 4 | EA | 5 | 6-10 years | Recently adjusted |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room | 100 | LF | 6 | 6-10 years | Common return |
| | Zone Dampers | Mechanical Room | 11 | EA | 5 | 6-10 years | Functional, manually operated, |
| | | | | | | | adjusted |



| <u> </u> | Schools | | | | | | 6239 N Leavitt STREET, Chicago, IL 60659 |
|------------|-----------------------------------------------------|-----------------|----------|--------------|--------|-------------|--------------------------------------------|
| Catego | ry : Mechanical | | В | uilding | : Main | _ | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Steam Coils - 8001 - 15000 cfm | | _ | | _ | 0.40 | auditorium |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | Not painted |
| | Auxiliaries - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Functional, not hot |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room | 100 | LF | 6 | 10+ years | Functional, not rusted |
| Boiler Sy | vstems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Pressure Boiler - 101 - 150 HP | | - | _ / ` | Ũ | e re jeare | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 10+ years | Adjusted and cleaned recently |
| | Condensate Pump | Boiler Room | 1 | EA | 5 | 6-10 years | Functional, no leaks, tested |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 5 | 6-10 years | Motors recently replaced |
| | Non Condensing- Fire Tube- Scotch Marine- | Boiler Room | 2 | EA | 6 | 6-10 years | Serves main and addition buildings |
| | Steam- Low Pressure Boiler - 101 - 150 HP | Boller Room | 2 | LA | 0 | 0-10 years | Serves main and addition buildings |
| | Piping - Condensate Pipe- Steel | Boiler Room | 700 | LF | 6 | 10+ years | No leaks, functional |
| | Piping - Steam Pipe- Steel | Boiler Room | 700 | LF | 6 | 10+ years | No leaks, functional |
| | Steam Traps | Boiler Room | 95 | EA | 5 | 6-10 years | Frequent maintenance required |
| | Steam Traps | Boller Koolli | 90 | LA | 5 | 0-10 years | Frequent maintenance required |
| Gas Boo | oster | | | | | | |
| | Gas Booster | Boiler Room | 2 | EA | 6 | 10+ years | 2, 1 per boiler |
| Heating | Devices | | | | | | |
| liounig | Unit Heater - Gas | Boiler Room | 1 | EA | 5 | 6-10 years | Recently serviced and cleaned, |
| | | Denerreen | · | _ / (| Ũ | e re jeare | serves boiler room |
| | Wall Heater - Electric | Entire Building | 24 | EA | 6 | 6-10 years | Recently cleaned |
| | Radiators - Steam | Entire Building | 30 | EA | 5 | 6-10 years | |
| | Radiators - Steam | Entire Building | 2 | EA | 4 | 1-2 years | Does not work well, no temperature |
| | | Entire Building | 2 | L/\ | - | 1 Z yours | control. to be replaced. Corroded |
| | Fin Tube - Steam | Entire Building | 20 | LF | 6 | 10+ years | Previously not assessed |
| _ | | | | | | | |
| Tempera | ature Control | | | = ^ | | 0.40 | |
| | Electric Thermostat | Entire Building | 2 | EA | 6 | 6-10 years | 2 found, unit heater and mini split system |
| | Pneumatic System | Entire Building | 65,617 | SF | 4 | 1-2 years | Also serves addition, does not work, |
| | - | - | | | | - | manually operated controls |
| | Thermostats - Pneumatic | Entire Building | 30 | EA | 6 | 6-10 years | Functional, pneumatic control system |
| | | | | | | | needs repair |
| Ventilatio | on | | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | Previously not assessed, serve |
| | | 3 | | | - | , | mechanical rooms |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 | Entire Building | 1 | EA | 6 | 10+ years | Recently installed |
| | | - | | | | - | - |



| Catego | ry : Mechanical | | B | uilding | : Main | | |
|----------|--------------------------------------------------------------------|-----------------|----------|---------|--------|-------------|------------------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | CFM | | | | _ | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 | Entire Building | 1 | EA | 6 | 6-10 years | |
| | CFM | | | | | | |
| atego | ry : Plumbing | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| lot Wate | | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 4 | 0-1 year | Corroded, serves main building only 156000 Btu input |
| iping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 65,617 | SF | 6 | 6-10 years | There are a few pipe clamps |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 65,617 | SF | 6 | 6-10 years | Leaks occasionally repaired |
| | Sanitary Piping | Entire Building | 65,617 | SF | 6 | 6-10 years | |
| | Storm Piping | Entire Building | 65,617 | SF | 6 | 10+ years | Functional, no leaks |
| | Vent Piping | Entire Building | 65,617 | SF | 6 | 10+ years | Functional, work well |
| umps | | | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | Mechanical Room | 1 | EA | 6 | 6-10 years | Serves main building only |
| | Pumps - Sump-Duplex | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Pumps - Sump-Simplex | Mechanical Room | 1 | EA | 6 | 10+ years | Under elevator, previously not assessed |
| atego | ry : Room | | В | uilding | : Main | | |
| | | | | | | Recommend | |

| Group Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------------|---------------|----------|-------|------|--------------------------|----------|
| Administrative Suites/Offices | Looation | Quantity | 00111 | Ram | Replacement | Commente |
| AC Unit | 108 care room | 1 | EA | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 108 care room | 334 | SF | 6 | 10+ years | |
| Doors - Transom Window | 108 care room | 6 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 108 care room | 1 | EA | 6 | 10+ years | |
| Floor - Wood | 108 care room | 334 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 108 care room | 5 | EA | 7 | 6-10 years | |
| Power Distribution | 108 care room | 6 | EA | 6 | 6-10 years | |



| Catego | ry : Room | | В | uilding | : Main | | Ŧ |
|--------|-----------------------------|--------------------------------------------------------------|----------|---------|--------|-------------|---------------------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Concrete Block | 108 care room | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 108 care room | 548 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor - Custodian Office inside Boiler Room | 108 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor - Custodian Office inside Boiler Room | 1 | EA | 7 | 6-10 years | |
| | Floor - Concrete | 1st Floor - Custodian Office inside Boiler Room | 108 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor - Custodian Office inside Boiler Room | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st Floor - Custodian Office inside Boiler Room | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - Custodian Office inside Boiler Room | 100 | SF | 4 | 0-1 year | Water damage and large cracking |
| | Walls - Plaster/Drywall | 1st Floor - Custodian Office inside Boiler Room | 225 | SF | 4 | 10+ years | |
| | AC Unit | 1st floor Main Office (Principal and Assistant Principal) | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st floor Main Office (Principal and Assistant Principal) | 786 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st floor Main Office (Principal and Assistant Principal) | 9 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st floor Main Office (Principal and Assistant Principal) | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 1st floor Main Office (Principal and Assistant Principal) | 393 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st floor Main Office (Principal and Assistant Principal) | 393 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st floor Main Office (Principal and Assistant Principal) | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st floor Main Office (Principal and Assistant Principal) | 18 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st floor Main Office (Principal and Assistant Principal) | 2,564 | SF | 6 | 10+ years | |
| | AC Unit | 1st floor engineer's office inside boiler room- Basement | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st floor engineer's office inside boiler room- Basement | 108 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st floor engineer's office inside boiler room- Basement | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | 1st floor engineer's office inside boiler room- Basement | 108 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st floor engineer's office inside boiler room- Basement | 1 | EA | 7 | 6-10 years | |



| atego | ry : Room | | В | uilding | : Main | | |
|--------------|-----------------------------------------------------------|------------------------------------|-------------|----------|--------|-------------------------|-----------------|
| Ū | | | | - | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Power Distribution | 1st floor engineer's office inside | 4 | EA | 6 | 10+ years | |
| | | boiler room- Basement | | | | , | |
| | Walls - Plaster/Drywall | 1st floor engineer's office inside | 325 | SF | 6 | 10+ years | |
| | ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, | boiler room- Basement | | | | -) | |
| | AC Unit | 202 | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 202 | 334 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 202 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 202 | 334 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 202 | 5 | EA | 7 | 6-10 years | |
| | Power Distribution | 202 | 6 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 202 | 548 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 202 | 410 | SF | 7 | 10+ years | |
| | AC Unit | 309 - Store Room | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 309 - Store Room | 333 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 309 - Store Room | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 309 - Store Room | 333 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 309 - Store Room | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | 309 - Store Room | 8 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 309 - Store Room | 998 | SF | 6 | 10+ years | |
| | | | | | | - | |
| uditoriu | ım & Theater | | | | | | |
| | Balcony Seating | 1st Floor | 75 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,896 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 4 | 0-1 year | Door boarded up |
| | Floor - Concrete | 1st Floor | 930 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 2,496 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 6 | SF | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 464 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 11 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Main Floor Seating | 1st Floor | 198 | EA | 7 | 6-10 years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 464 | SF | 7 | 6-10 years | |
| | Stage Curtain | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Stage Lift | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage-Stairs - Wood | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Stairs - Terrazzo | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 5,921 | SF | 6 | 10+ years | |
| | - | | | | | - | |
| | | | | | | | |
| mnas | | | | | | | |
| <u>/mnas</u> | ia Ceiling - Plaster/Drywall Doors - Transom Window | 1st Floor 1st Floor | 3,016 12 | SF SF | 6 | 10+ years 6-10 years | |



| <u> </u> | Schools | | | | | | 6239 N Leavitt STREET, Chicago, IL 60659 |
|----------|--------------------------------------|-------------------------------|-----------------|---------|--------|-------------|------------------------------------------|
| Catego | ry : Room | | В | uilding | : Main | | |
| | | | - | | _ | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 3,016 | SF | 6 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Scoreboards | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 390 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 3,472 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,931 | SF | 7 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st floor south of auditorium | 336 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st floor south of auditorium | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st floor south of auditorium | 336 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st floor south of auditorium | 4 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st floor south of auditorium | 150 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st floor south of auditorium | 618 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st floor south of auditorium | 412 | SF | 7 | 10+ years | |
| Library | | | | | | | |
| | AC Unit | 209 | 4 | EA | 7 | 6-10 years | |
| | Casework | 209 | 83 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 209 | 1,468 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 209 | [′] 12 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 209 | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 209 | 1,458 | SF | 6 | 10+ years | |
| | Floor - Tile | 209 | 10 | SF | 4 | 0-1 year | Chipping |
| | Lighting - Pendent/Surface | 209 | 28 | ĒA | 7 | 6-10 years | - 11 3 |
| | Walls - Plaster/Drywall | 209 | 2,176 | SF | 7 | 10+ years | |
| MDF ID | F | | | | | | |
| | Doors - Wood Doors inclu hw | in 202 | 1 | EA | 6 | 10+ years | |
| | Finishes | in 202 | 94 | SF | 5 | 10+ years | |
| | Other Cooling Unit | in 202 | 1 | EA | 7 | 6-10 years | Ductless split system |
| Mechani | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 98 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 250 | SF | 5 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 98 | SF | 5 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 34 | SF | 5 | 10+ years | |
| | Air Tunnel | Basement | 4,000 | SF | 7 | 10+ years | |
| | Boiler Room | Basement | 1,600 | SF | 5 | 10+ years | |
| | Crawl Space - Unfinished | Basement | 8,436 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 875 | SF | 7 | 10+ years | |
| | Mechanical Service RUUIIS | Dasement | 075 | 0 | ' | ior years | |



| Catego | ry : Room | | Building : Main | | | | |
|---------|---------------------------------|-------------------------------------|-----------------|-----|------|-------------|-----------------------------------|
| U | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Mechanical/ Service Rooms | Basement | 980 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 128 | SF | 5 | 10+ years | |
| | Storage Room | Basement | 462 | SF | 7 | 10+ years | |
| | | | | | | | |
| Restroo | | | | | | | |
| | Accessories | 1st Floor - inside Custodian Office | 30 | SF | 5 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor - inside Custodian Office | 30 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor - inside Custodian Office | 30 | SF | 6 | 2-5 years | |
| | Lavatory | 1st Floor - inside Custodian Office | 1 | EA | 4 | 0-1 year | Not in use |
| | Lighting - Pendent/Surface | 1st Floor - inside Custodian Office | 1 | EA | 5 | 1-2 years | Missing cover |
| | Walls - Plaster/Drywall | 1st Floor - inside Custodian Office | 192 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor - inside Custodian Office | 1 | EA | 4 | 0-1 year | Not in use |
| | Accessories | 1st floor Teachers (across 109) | 126 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st floor Teachers (across 109) | 126 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st floor Teachers (across 109) | 6 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st floor Teachers (across 109) | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st floor Teachers (across 109) | 126 | SF | 6 | 10+ years | |
| | Hand Dryer | 1st floor Teachers (across 109) | 1 | ĒA | 7 | 6-10 years | |
| | Lavatory | 1st floor Teachers (across 109) | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st floor Teachers (across 109) | 2 | EA | 7 | 6-10 years | |
| | Partitions | 1st floor Teachers (across 109) | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st floor Teachers (across 109) | 582 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st floor Teachers (across 109) | 4 | SF | 4 | 10+ years | Walls have been Painted, no visib |
| | | | · | • | · | let yeare | water damage |
| | Water Closet | 1st floor Teachers (across 109) | 1 | EA | 7 | 10+ years | C C |
| | Accessories | 1st floor at Auditorium lobby | 136 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st floor at Auditorium lobby | 10 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st floor at Auditorium lobby | 136 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st floor at Auditorium lobby | 1 | ĒA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st floor at Auditorium lobby | 126 | SF | 6 | 10+ years | |
| | Lavatory | 1st floor at Auditorium lobby | 1 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st floor at Auditorium lobby | 1 | EA | 7 | 6-10 years | |
| | Partitions | 1st floor at Auditorium lobby | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st floor at Auditorium lobby | 40 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st floor at Auditorium lobby | 237 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st floor at Auditorium lobby | 197 | SF | 6 | 10+ years | |
| | Water Closet | 1st floor at Auditorium lobby | 137 | EA | 7 | 6-10 years | |
| | Accessories | 1st floor inside 101 | 219 | SF | 7 | 6-10 years | |
| | | 1st floor inside 101 | 219 | SF | 6 | • | |
| | Ceiling - Plaster/Drywall | | | SF | | 10+ years | |
| | Doors - Transom Window | 1st floor inside 101 | 24 | | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st floor inside 101 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st floor inside 101 | 217 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st floor inside 101 | 2 | SF | 4 | 0-1 year | |
| | Floor Drain | 1st floor inside 101 | 1 | EA | 7 | 6-10 years | |



| Grouptem - TypeLocationQuartWorkReplacementLavatory1st floor inside 1011EA76-10 yearsPartitions1st floor inside 1011EA76-10 yearsWalte - Paster/Dryvall1st floor inside 1011EA76-10 yearsWalte - Paster/Dryvall1st floor inside 1011EA76-10 yearsWalte - Closet1st floor inside 1011EA76-10 yearsColling - Plaster/Dryvall1st floor inside noniner's office3SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside noniner's office1EA76-10 yearsDoors - Wood Doors inclu hw1st floor inside noniner's office1EA76-10 yearsLavatory1st floor inside noniner's office1EA76-10 yearsUnpming - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWalte - Closet1st floor inside engineer's office18EA76-10 yearsWalte - Closet1st floor inside granuesd as storage71SF6610 yearsDoors - Wood Doors inclu hw1st floor inside granuesd as storage71SF610 yearsLavatory1st floor inside granuesd as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside granuesd as storage71SF610 yearsDoors - Wood Doors inclu hw1st | Catego | ory : Room | | В | uilding | : Main | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-----------------------------|------------------------------------|----------|---------|--------|------------|----------|
| Lavatory1st floor inside 1011EA76-10 yearsLighting - Pendent/Surface1st floor inside 1011EA76-10 yearsWalls - Plaster/Dywall1st floor inside 1011EA76-10 yearsWater Closet1st floor inside 1011EA76-10 yearsAccessories1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWalls - Plaster/Dywall1st floor inside engineer's office1EA76-10 yearsWater Closet1st floor inside engineer's office1EA76-10 yearsWater Closet1st floor inside engineer's office1EA76-10 yearsCeiling - Plaster/Dywall1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1EA76-10 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1EA610 yearsLighting - Pandent/Surface1st floor inside gym used as storage1EA610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1EA6 <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th>Recommend</th> <th></th> | | | | | | | Recommend | |
| LightingPendent/Surface1st floor inside 1013EA76-10 yearsWallsPlaster/Dywall1st floor inside 101762SF610 yearsWallsPlaster/Dywall1st floor inside ongineer's office30SF76-10 yearsCeilingPlaster/Dywall1st floor inside ongineer's office30SF66-10 yearsDoorsWood Doors inclu hw1st floor inside ongineer's office1EA66-10 yearsEloor - Tile1st floor inside ongineer's office1EA76-10 yearsLighting- Pendent/Surface1st floor inside ongineer's office1EA76-10 yearsLighting- Pendent/Surface1st floor inside ongineer's office1EA76-10 yearsWalts- Plaster/Dywall1st floor inside ongineer's office1EA76-10 yearsWalts- Plaster/Dywall1st floor inside ongineer's office1EA76-10 yearsAccessories1st floor inside ongineer's office1EA76-10 yearsCong- Wood Doors inclu hw1st floor inside ongineer's office1EA610 yearsCong- Plaster/Dywall1st floor inside ongineer's office1EA610 yearsCong- Wood Doors inclu hw1st floor inside ongineer's office1EA76-10 yearsPartitions- St floor inside ongineer's office1EA76-10 years <th>Group</th> <th>Item - Type</th> <th></th> <th>Quantity</th> <th></th> <th>Rank</th> <th></th> <th>Comments</th> | Group | Item - Type | | Quantity | | Rank | | Comments |
| Partitions1st floor inside 1011EA76-10 yearsWater Closet1st floor inside 101762SF610 yearsAccessories1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office1EA76-10 yearsLavatory1st floor inside engineer's office1EA76-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWatter Closet1st floor inside engineer's office1EA76-10 yearsWatter Closet1st floor inside engineer's office1EA76-10 yearsCeiling - Plaster/Dryvall1st floor inside engineer's office1EA76-10 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610 yearsLighting - Pendent/Surface1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610 yearsLighting - Pendent/Surface1st floor inside gym used as storage | | | 1st floor inside 101 | | | | | |
| Wails - Plaster/Dywall1st floor inside 1017ESF610+ yearsAccessories1st floor inside injener's office30SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWails - Plaster/Dryvall1st floor inside engineer's office1EA76-10 yearsWails - Plaster/Dryvall1st floor inside gry used as storage71SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside gry used as storage71SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside gry used as storage1EA76-10 yearsLighting - Pendent/Surface1st floor inside gry used as storage1EA76-10 yearsWails - Plaster/Dryvall1st floor inside gry used as storage1EA76-10 yearsWails - Plaster/Dryvall1st floor inside gry used as storage1EA76-10 yearsCeiling - Plaster/Dryvall1st floor inside gry used as storage1EA76-10 yearsCeiling - Plaster/Dryvall1st floor inside main office suite30SF610+ years <trr<tr></trr<tr> | | Lighting - Pendent/Surface | 1st floor inside 101 | 3 | EA | | | |
| Water Closet1st floor inside opinieer's office30SF76-10 yearsAccessories1st floor inside opineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside opineer's office30SF66-10 yearsLavatory1st floor inside opineer's office1E.A76-10 yearsLighting - Pendent/Surface1st floor inside opineer's office1E.A76-10 yearsWals - Plaster/Dyvall1st floor inside opineer's office1E.A76-10 yearsWater Closet1st floor inside opineer's office1E.A76-10 yearsAccessories1st floor inside gym used as storage71SF76-10 yearsCaling - Plaster/Dyvall1st floor inside gym used as storage1E.A610+ yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1E.A610+ yearsLighting - Pendent/Surface1st floor inside gym used as storage1E.A76-10 yearsWalts - Plaster/Dyvall1st floor inside gym used as storage1E.A76-10 yearsWalts - Plaster/Dyvall1st floor inside gym used as storage1E.A76-10 yearsWalts - Plaster/Dyvall1st floor inside gym used as storage1E.A76-10 yearsUghting - Pendent/Surface1st floor inside gym used as storage30SF76-10 yearsCaling - Plaster/Dyvall1st floor insid | | | | - | | | 6-10 years | |
| Accessories1st floor inside engineer's office30SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsDoors - Wood Doors inclu hw1st floor inside engineer's office30SF66-10 yearsLavatory1st floor inside engineer's office1EA76-10 yearsLighting - Pendem/Surface1st floor inside engineer's office1EA76-10 yearsWalls - Plaster/Drywall1st floor inside engineer's office1EA76-10 yearsWalls - Plaster/Drywall1st floor inside engineer's office1EA76-10 yearsCeiling - Plaster/Drywall1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610 yearsHighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite30SF610+ yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsCeiling - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsLighthig - Pendent/Surface | | | 1st floor inside 101 | 762 | | | | |
| Calling - Plaster/Dywall1st floor inside engineer's office30SF666-10 yearsCoor - Tile1st floor inside engineer's office1SF66-10 yearsLayatory1st floor inside engineer's office1EA76-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWalts - Plaster/Dywall1st floor inside engineer's office1EA76-10 yearsWater Closet1st floor inside engineer's office1EA76-10 yearsAccessories1st floor inside gym used as storage71SF610 yearsCeiling - Plaster/Dywall1st floor inside gym used as storage1EA610 yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Dywall1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Dywall1st floor inside gym used as storage1EA76-10 yearsCeiling - Plaster/Dywall1st floor inside gym used as storage1EA76-10 yearsUghting - Pondent/Surface1st floor inside gym used as storage1EA76-10 yearsCeiling - Plaster/Dywall1st floor inside main office suite1EA76-10 yearsDoors - Wood Doors inclu hw <t< td=""><td></td><td>Water Closet</td><td>1st floor inside 101</td><td></td><td></td><td></td><td>6-10 years</td><td></td></t<> | | Water Closet | 1st floor inside 101 | | | | 6-10 years | |
| DoorsWood Doors1st floor inside engineer's office1EA66-10 yearsHorn Tile1st floor inside engineer's office1EA76-10 yearsLavatory1st floor inside engineer's office1EA76-10 yearsWallsPlaster/Drywall1st floor inside engineer's office1EA76-10 yearsWallsPlaster/Drywall1st floor inside engineer's office1EA76-10 yearsCeilingPlaster/Drywall1st floor inside gym used as storage71SF610+ yearsDoorsWood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsDoorsWood Doors inclu hw1st floor inside gym used as storage1EA76-10 yearsFloorTile Ceramic/ Porcelain1st floor inside gym used as storage1EA76-10 yearsHartins1st floor inside gym used as storage1EA76-10 yearsAccessories1st floor inside gym used as storage30SF610+ yearsAccessories1st floor inside main office suite30SF610+ yearsDoorsWood Doors inclu hw1st floor inside main office suite30SF610+ yearsAccessories1st floor inside main office suite30SF610+ yearsDoorsWood Doors inclu hw1st floor inside main office suite30SF610+ yearsLavatory< | | | | | | | | |
| Floor - Tile1st floor inside engineer's office30SF66-10 yearsLighting - Pendent/Surface1st floor inside engineer's office1EA76-10 yearsWalte - Daster/Drywall1st floor inside engineer's office198SF66-10 yearsWatter Closet1st floor inside engineer's office198SF76-10 yearsAccessories1st floor inside gym used as storage71SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsPloors - Wood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsHorinside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsAduits - Plaster/Drywall1st floor inside gym used as storage350SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsLavatory1st floor inside main office suite1EA7 <td< td=""><td></td><td></td><td></td><td>30</td><td></td><td>-</td><td></td><td></td></td<> | | | | 30 | | - | | |
| Lavatory1st floor inside engineer's office1EA76-10 yearsWalls - Plaster/Drywall1st floor inside engineer's office18SF66-10 yearsWalls - Plaster/Drywall1st floor inside engineer's office1SA76-10 yearsAccessories1st floor inside gym used as storage71SF76-10 yearsCeiling - Plaster/Drywall1st floor inside gym used as storage71SF610 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1SF610 yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsFloor - Tile Ceramic Porcelain1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Dryvall1st floor inside gym used as storage30SF76-10 yearsAccessories1st floor inside gym used as storage30SF76-10 yearsCeiling - Plaster/Dryvall1st floor inside main office suite30SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF76-10 yearsCeiling - Plaster/Dryvall1st floor inside main office suite30SF76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surfac | | | | 1 | | | | |
| Lighting - Pendent/Surface1 st floor inside engineer's office1EA76-10 yearsWater Closet1 st floor inside engineer's office1EA76-10 yearsAccessories1 st floor inside engineer's office1EA76-10 yearsCeiling - Plaster/Drywall1 st floor inside gym used as storage71SF76-10 yearsDoors - Wood Doors inclu hw1 st floor inside gym used as storage1EA610+ yearsPloor - Tile Ceramic / Porcelain1 st floor inside gym used as storage1EA76-10 yearsPartitions1 st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1 st floor inside gym used as storage1EA76-10 yearsPartitions1 st floor inside gym used as storage350SF610+ yearsCeiling - Plaster/Drywall1 st floor inside gym used as storage30SF610+ yearsCeiling - Plaster/Drywall1 st floor inside main office suite30SF610+ yearsLighting - Pendent/Surface1 st floor inside main office suite30SF610+ yearsLighting - Pendent/Surface1 st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1 st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1 st floor inside main office suite1EA76-10 yearsLight | | | | 30 | | | | |
| Walls - Plaster/Dywall1st floor inside engineer's office198SF66-10 yearsWater Closet1st floor inside engineer's office1EA76-10 yearsAccessories1st floor inside gym used as storage71SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsLighting - Pendent/Surface1st floor inside gym used as storage71SF610+ yearsPartitions1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsAccessories1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite1EA76-10 yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsCeiling - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main | | | | 1 | | | • | |
| Water Closet1st floor inside engineer's office1EA76-10 yearsAccessories1st floor inside gym used as storage71SF610+ yearsDoors - Vaod Doors inclu hw1st floor inside gym used as storage71SF610+ yearsPoors - Tile Ceramic/ Porcelain1st floor inside gym used as storage1EA610+ yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsParitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage30SF610+ yearsCelling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsUphting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsUsatory1st floor inside main office suite1EA76-10 yearsUsatory1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite | | Lighting - Pendent/Surface | | 1 | | | | |
| Accessories1st floor inside gym used as storage71SF76-10 yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage71SF610+ yearsDoors - Tile Ceramic/ Porcelain1st floor inside gym used as storage71SF610+ yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage1EA76-10 yearsWeils - Plaster/Drywall1st floor inside gym used as storage30SF76-10 yearsAccessories1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsCeiling - Plaster/Drywall2nd Fl | | | 1st floor inside engineer's office | | - | | | |
| Ceiling - Plaster/Dywall1st floor inside gym used as storage71SF610+ yearsDoors - Wood Doors inclu hw1st floor inside gym used as storage1EA610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage30SF610+ yearsAccessories1st floor inside gym used as storage30SF610+ yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsBoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalts - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalts - Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF710+ yearsDoors - Steel Doors inclu hw2nd Floor346SF610+ yearsFloor - Tile Ceramic/ Porcelain2nd Floor2EA | | | 1st floor inside engineer's office | • | | | | |
| DoorsWood Doors inclu hw1st floor inside gym used as storage1EA610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage30SF610+ yearsAccessories1st floor inside gym used as storage30SF76-10 yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite30SF610+ yearsLighting - Pendent/Surface1st floor inside main office suite30SF610+ yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsUighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall2nd Floor346SF710- yearsCeiling - Plaster/Drywall <td< td=""><td></td><td></td><td></td><td></td><td></td><td>-</td><td>-</td><td></td></td<> | | | | | | - | - | |
| Floor - Tile Ceramic/ Porcelain1st floor inside gym used as storage71SF610- yearsLighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsParitions1st floor inside gym used as storage350SF610+ yearsWalls - Plaster/Drywall1st floor inside gym used as storage350SF610+ yearsAccessories1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Dlaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Dlaster/Drywall2nd Floor346SF710+ yearsCeiling - Plaster/Drywall2nd Floor1EA76-10 yearsCeiling - Plaster/Drywall2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsFloor Drain <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | | | | | | | | |
| Lighting - Pendent/Surface1st floor inside gym used as storage1EA76-10 yearsPartitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside gym used as storage30SF610+ yearsAccessories1st floor inside main office suite30SF610+ yearsCelling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor2EA76-10 yearsHand Dryer2nd | | | | • | | | | |
| Partitions1st floor inside gym used as storage1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite30SF610+ yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsElor - Tile Ceramic/ Porcelain1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor Trile Ceramic/ Porcelain2nd Floor2EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 years< | | | | | | | | |
| Walls - Plaster/Drywall1st floor inside gym used as storage350SF610+ yearsAccessories1st floor inside main office suite30SF76-10 yearsCeiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite1EA610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite1EA76-10 yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWater Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 years | | | | 1 | | | | |
| Accessories1st floor inside main office suite30SF76-10 yearsCelling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite30SF610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor346SF76-10 yearsFloor Trile Ceramic/ Porcelain2nd Floor346SF610+ yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsWalls - FlacerArmic/ Porcelain2nd Floor2EA76-10 | | | | 1 | | | | |
| Ceiling - Plaster/Drywall1st floor inside main office suite30SF610+ yearsDoors - Wood Doors inclu hw1st floor inside main office suite1EA610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite1EA610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite1EA76-10 yearsWater Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor2EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsWalls | | | | | | | | |
| Doors - Wood Doors inclu hw1st floor inside main office suite1EA610+ yearsFloor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite18SF610+ yearsWater Closet1st floor inside main office suite18SF76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsHand Dryer2nd Floor1EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsWalls - Structural Glazed Tile2nd Floor2EA76-10 yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | | | | | |
| Floor - Tile Ceramic/ Porcelain1st floor inside main office suite30SF610+ yearsLavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite198SF610+ yearsWater Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Train2nd Floor2EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLavatory2nd Floor3EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLavatory2nd Floor5EA710+ yearsWalls - Plaster/Drywall2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor304 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | | | | | |
| Lavatory1st floor inside main office suite1EA76-10 yearsLighting - Pendent/Surface1st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1st floor inside main office suite198SF610+ yearsWater Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor3/4SF710+ yearsWalls - Plaster/Drywall2nd Floor3/4SF710+ yearsWalls - Plaster/Drywall2nd Floor3/4SF710+ yearsWalls - Structural Glazed Tile2nd Floor3/4SF710+ years </td <td></td> <td></td> <td></td> <td>•</td> <td></td> <td>-</td> <td>•</td> <td></td> | | | | • | | - | • | |
| Lighting - Pendent/Surface1 st floor inside main office suite1EA76-10 yearsWalls - Plaster/Drywall1 st floor inside main office suite198SF610+ yearsWater Closet1 st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsDoors - Steel Doors incl hw2nd Floor346SF610+ yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLiphting - Pendent/Surface2nd Floor2EA76-10 yearsLiphting - Pendent/Surface2nd Floor2EA76-10 yearsLiphting - Pendent/Surface2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor2EA76-10 yearsWalls - Structural Glazed Tile2nd Floor2EA76-10 yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor30SF7 <t< td=""><td></td><td></td><td></td><td>30</td><td></td><td></td><td></td><td></td></t<> | | | | 30 | | | | |
| Walls - Plaster/Drywall1st floor inside main office suite198SF610+ yearsWater Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor1EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor2EA76-10 yearsWalls - Structural Glazed Tile2nd Floor2EA76-10 yearsWalls - Tile Ceramic/ Porcelain2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWalls - Structural Glazed Tile2nd Floor130SF710+ yearsWalls - Structural Glazed Tile2nd Floor9EA76-10 yearsWalls - Structural Glazed Tile2nd Floor9EA76-10 yearsWater | | | | 1 | | | | |
| Water Closet1st floor inside main office suite1EA76-10 yearsAccessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1EA76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsPartitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor9EA76-10 yearsWalls - Structural Glazed Tile2nd Floor272SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsWater Closet2nd Floor130SF710+ yearsWater Closet2nd Floor130SF710+ yearsAccessories2nd Floor185SF76-10 years< | | | | 1 | | | • | |
| Accessories2nd Floor346SF76-10 yearsCeiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor346SF76-10 yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor5EA76-10 yearsWalls - Plaster/Drywall2nd Floor9EA76-10 yearsWalls - Structural Glazed Tile2nd Floor272SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor9EA76-10 yearsAccessories2nd Floor130SF710+ yearsCeiling - Plaster/Drywall2nd Floor185SF76-10 years | | | | | | | | |
| Ceiling - Plaster/Drywall2nd Floor346SF710+ yearsDoors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor346SF610+ yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor1EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsValls - Plaster/Drywall2nd Floor2EA76-10 yearsWalls - Plaster/Drywall2nd Floor9EA76-10 yearsWalls - Structural Glazed Tile2nd Floor272SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor9EA76-10 yearsAccessories2nd Floor130SF710+ yearsAccessories2nd Floor185SF76-10 yearsAccessories2nd Floor185SF710+ yearsAccessories2nd Floor185SF710+ yearsAccessories2nd Floor </td <td></td> <td></td> <td></td> <td>•</td> <td></td> <td></td> <td></td> <td></td> | | | | • | | | | |
| Doors - Steel Doors incl hw2nd Floor1EA76-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor346SF610+ yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor2EA76-10 yearsValls - Plaster/Drywall2nd Floor5EA76-10 yearsWalls - Structural Glazed Tile2nd Floor9EA76-10 yearsWalls - Tile Ceramic/ Porcelain2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Structural Glazed Tile2nd Floor10SF710+ yearsWater Closet2nd Floor10SF710+ yearsWater Closet2nd Floor185SF76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF76-10 years | | | | | | | | |
| Floor - Tile Ceramic/ Porcelain2nd Floor346SF610+ yearsFloor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor5EA76-10 yearsPartitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor130SF710+ yearsCeiling - Plaster/Drywall2nd Floor185SF76-10 yearsAccessories2nd Floor185SF710+ yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | 346 | | | | |
| Floor Drain2nd Floor1EA76-10 yearsHand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor5EA76-10 yearsPartitions2nd Floor5EA76-10 yearsWalls - Plaster/Drywall2nd Floor9EA76-10 yearsWalls - Structural Glazed Tile2nd Floor272SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor304SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor130SF710+ yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | 1 | | | - | |
| Hand Dryer2nd Floor2EA76-10 yearsLavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor5EA76-10 yearsPartitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsAccessories2nd Floor185SF710+ yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | | |
| Lavatory2nd Floor2EA76-10 yearsLighting - Pendent/Surface2nd Floor5EA76-10 yearsPartitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | • | |
| Lighting - Pendent/Surface2nd Floor5EA76-10 yearsPartitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | - | | |
| Partitions2nd Floor9EA76-10 yearsWalls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | | |
| Walls - Plaster/Drywall2nd Floor272SF710+ yearsWalls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | • | |
| Walls - Structural Glazed Tile2nd Floor304SF710+ yearsWalls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | • | |
| Walls - Tile Ceramic/ Porcelain2nd Floor130SF710+ yearsWater Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | | |
| Water Closet2nd Floor9EA76-10 yearsAccessories2nd Floor185SF76-10 yearsCeiling - Plaster/Drywall2nd Floor185SF710+ years | | | | | | | | |
| Accessories 2nd Floor 185 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor 185 SF 7 10+ years | | | | | | | | |
| Ceiling - Plaster/Drywall 2nd Floor 185 SF 7 10+ years | | | | | | | | |
| | | | | | | | • | |
| Doors - Steel Doors Inclinw 2nd Floor 1 EA / 10+ years | | | | | | | | |
| | | Doors - Steel Doors Incl hw | 2na Fioor | 1 | EA | 1 | 10+ years | |



| | egory : Room Building : Main | | | | | | |
|--------|---------------------------------|-----------------------------------|----------|-------|--------|-------------|-------------|
| Calego | ry . Room | | D | unung | . Wall | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Group | Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 6-10 years | ooninients |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 185 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | ĒA | 7 | 6-10 years | |
| | Hand Dryer | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Urinals | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 106 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 399 | SF | 7 | 10+ years | Orange tile |
| | Walls - Structural Glazed Tile | 2nd Floor | 159 | SF | 6 | 10+ years | 5 |
| | Water Closet | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Accessories | 2nd floor Unisex Staff across 209 | 126 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd floor Unisex Staff across 209 | 126 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd floor Unisex Staff across 209 | 6 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd floor Unisex Staff across 209 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd floor Unisex Staff across 209 | 126 | SF | 6 | 10+ years | |
| | Hand Dryer | 2nd floor Unisex Staff across 209 | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd floor Unisex Staff across 209 | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd floor Unisex Staff across 209 | 2 | EA | 7 | 6-10 years | |
| | Partitions | 2nd floor Unisex Staff across 209 | 1 | EA | 7 | 6-10 years | |
| | Partitions | 2nd floor Unisex Staff across 209 | 1 | EA | 4 | 0-1 year | Missing |
| | Walls - Plaster/Drywall | 2nd floor Unisex Staff across 209 | 586 | SF | 7 | 10+ years | |
| | Water Closet | 2nd floor Unisex Staff across 209 | 2 | EA | 7 | 6-10 years | |
| | Accessories | First floor, boys near 104 | 185 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | First floor, boys near 104 | 185 | SF | 6 | 6-10 years | |
| | Doors - Transom Window | First floor, boys near 104 | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | First floor, boys near 104 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | First floor, boys near 104 | 185 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | First floor, boys near 104 | 5 | SF | 6 | 10+ years | |
| | Floor Drain | First floor, boys near 104 | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | First floor, boys near 104 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | First floor, boys near 104 | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | First floor, boys near 104 | 4 | EA | 7 | 6-10 years | |
| | Partitions | First floor, boys near 104 | 1 | EA | 7 | 6-10 years | |
| | Urinals | First floor, boys near 104 | 3 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | First floor, boys near 104 | 159 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | First floor, boys near 104 | 106 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | First floor, boys near 104 | 399 | SF | 6 | 10+ years | |
| | Water Closet | First floor, boys near 104 | 1 | EA | 7 | 6-10 years | |
| | Accessories | First floor, girls near 103 | 346 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | First floor, girls near 103 | 346 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | First floor, girls near 103 | 1 | EA | 6 | 10+ years | |



| Catego | Category : Room | | В | Building : Main | | | SECON ECONIC OTTLE 1, Officiago, in Course |
|--------|------------------------------------------------|-----------------------------|----------|-----------------|--------|-------------------------|--------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile Ceramic/ Porcelain | First floor, girls near 103 | 346 | SF | 6 | 10+ years | |
| | Floor Drain | First floor, girls near 103 | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | First floor, girls near 103 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | First floor, girls near 103 | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | First floor, girls near 103 | 5 | EA | 7 | 6-10 years | |
| | Partitions | First floor, girls near 103 | 9 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | First floor, girls near 103 | 304 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | First floor, girls near 103 | 272 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | First floor, girls near 103 | 130 | SF | 7 | 10+ years | |
| | Water Closet | First floor, girls near 103 | 9 | ĒΑ | 7 | 6-10 years | |
| | Accessories | Third floor girls | 277 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Third floor girls | 277 | SF | 6 | 10+ years | |
| | Doors - Transom Window | Third floor girls | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Third floor girls | 1 | ĒA | 6 | 10+ years | |
| | Floor - Tile | Third floor girls | 20 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Third floor girls | 277 | SF | 6 | 10+ years | |
| | Floor Drain | Third floor girls | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | Third floor girls | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Third floor girls | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Third floor girls | 4 | EA | 7 | 6-10 years | |
| | Partitions | Third floor girls | 7 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Third floor girls | 352 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Third floor girls | 338 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Third floor girls | 112 | SF | 6 | 10+ years | |
| | Walls - The Ceramic/ Forcelain Water Closet | Third floor girls | 7 | EA | 7 | 6-10 years | |
| | | Third floor, boys near 304 | 185 | SF | 7 | | |
| | Accessories Ceiling - Plaster/Drywall | Third floor, boys near 304 | 185 | SF | 6 | 6-10 years 10+ years | |
| | Doors - Transom Window | Third floor, boys near 304 | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Third floor, boys near 304 | 12 | EA | 6 | | |
| | | | | SF | - | 10+ years | |
| | Floor - Tile | Third floor, boys near 304 | 5 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Third floor, boys near 304 | 185 | | 6 | 10+ years | |
| | Floor Drain | Third floor, boys near 304 | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | Third floor, boys near 304 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Third floor, boys near 304 | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Third floor, boys near 304 | 4 | EA | 7 | 6-10 years | |
| | Partitions | Third floor, boys near 304 | 1 | EA | 7 | 6-10 years | |
| | Urinals | Third floor, boys near 304 | 4 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Third floor, boys near 304 | 159 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Third floor, boys near 304 | 106 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Third floor, boys near 304 | 399 | SF | 7 | 10+ years | |
| | Water Closet | Third floor, boys near 304 | 1 | EA | 7 | 6-10 years | |
| Catego | ry : Classroom | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments |
| | V 1.1 | | | | | | |

| Chicago Public Schools | Stone Elementary Scholastic Academy 6239 N Leavitt STREET, Chicago, IL 60659 | | | | | |
|--------------------------------------------|---------------------------------------------------------------------------------|-------|-------------|---|-------------|--|
| | | | | | Replacement | |
| Classroom #101 (Fitness Room) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 20 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 1,164 | SF | 6 | 10+ years | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| Floor - Weight/ Fitness Room Floor Matting | 1st Floor | 1,164 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 22 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 48 | LF | 7 | 6-10 years | |
| Storage/ Closet | 1st Floor | 118 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 1,507 | SF | 6 | 10+ years | |
| Classroom #103 (Regular Classroom) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 38 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 728 | SF | 6 | 10+ years | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 1st Floor | 728 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 40 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 1st Floor | 1,175 | SF | 6 | 10+ years | |
| Classroom #104 (Regular Classroom) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 38 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 728 | SF | 6 | 10+ years | |
| Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 1st Floor | 728 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 24 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 1st Floor | 1,185 | SF | 6 | 10+ years | |
| lassroom #106 (Art Room) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 9 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 728 | SF | 6 | 10+ years | |
| Chalk Board | 1st Floor | 8 | LF | 4 | 2-5 years | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| Floor - Tile | 1st Floor | 728 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | | 17 | -/ ` | | | |

| X Schools | | | | | 623 | 39 N Leavitt STREET, Chicago, IL 60659 |
|------------------------------------|-----------|-------|----|---|-------------|----------------------------------------|
| | | | | | Replacement | |
| Storage/ Closet | 1st Floor | 10 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 1,185 | SF | 6 | 10+ years | |
| Work Sink | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | | | | | - | |
| Classroom #107 (Regular Classroom) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 9 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 679 | SF | 6 | 10+ years | |
| Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| Floor - Tile | 1st Floor | 703 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 18 | LF | 7 | 6-10 years | |
| Storage/ Closet | 1st Floor | 112 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 1,497 | SF | 6 | 10+ years | |
| | | ., | • | Ũ | | |
| Classroom #109 (Regular Classroom) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 12 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 825 | SF | 6 | 10+ years | |
| Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| Floor - Tile | 1st Floor | 825 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 21 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 1st Floor | 1,277 | SF | 6 | 10+ years | |
| Classroom #110 (Art Room) | | | | | | |
| AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 1st Floor | 38 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 1st Floor | 703 | SF | 6 | 10+ years | |
| Doors - Transom Window | 1st Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 1st Floor | 703 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 46 | | 7 | , | |
| Walls - Plaster/Drywall | 1st Floor | 1,176 | SF | 6 | 6-10 years | |
| Walls - Flastel/Drywall | ISt FIOO | 1,170 | ЗГ | 0 | 10+ years | |
| Classroom #201 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Wood | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | | 0 | | - | , | |

Stone Elementary Scholastic Academy 6239 N Leavitt STREET, Chicago, IL 60659



| XUR SCHOOLS | | | | | | 6239 N Leavitt STREET, Chicago, IL 60659 |
|------------------------------------|-----------|-------|----|---|-------------|------------------------------------------|
| | | | | | Replacement | |
| Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 2nd Floor | 33 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,191 | SF | 6 | 10+ years | |
| | | | | | - | |
| Classroom #203 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | |
| Chalk Board | 2nd Floor | 6 | LF | 4 | 2-5 years | |
| Doors - Transom Window | 2nd Floor | 12 | SF | | | |
| | | | | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Wood | 2nd Floor | 725 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 2nd Floor | 23 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,211 | SF | 6 | 10+ years | |
| Classroom #204 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6 10 years | |
| | | | | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 710 | SF | 6 | 10+ years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 5 | SF | 4 | 0-1 year | Water damage |
| Doors - Transom Window | 2nd Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 2nd Floor | 715 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,191 | SF | 6 | 6-10 years | |
| Classroom #205 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 616 | SF | 6 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| Floor - Wood | 2nd Floor | 616 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | | |
| | 2nd Floor | | | | 6-10 years | |
| Marker Board | | 23 | | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,211 | SF | 6 | 10+ years | |
| Classroom #206 (Computer Lab) | | | | | | |
| AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 726 | SF | 7 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | 21011001 | Ζ. | LA | 0 | ior years | |



| SCHOOLS | | | | | | 6239 N Leavitt STREET, Chicago, IL 60 |
|----------------------------------|-----------|----------|----|---|------------------------|------------------------------------------------------|
| | | | | | Replacement | |
| Floor - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 2nd Floor | 38 | LF | 7 | 6-10 years | |
| Storage/ Closet | 2nd Floor | 114 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| | | | | 7 | • | |
| Wireless System | 2nd Floor | 1 | EA | 7 | 10+ years | |
| assroom #207 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 7 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 2nd Floor | 725 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | | EA | 7 | 6-10 years | |
| Marker Board | | 14 32 | | 7 | | |
| | 2nd Floor | | | | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,191 | SF | 7 | 10+ years | |
| assroom #208 (Regular Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 713 | SF | 7 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Wood | 2nd Floor | 713 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | | EA | 7 | | |
| | | 14 | | - | 6-10 years | |
| Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,191 | SF | 7 | 6-10 years | |
| assroom #210 (Science Classroom) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 2nd Floor | 38 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 2nd Floor | 896 | SF | 6 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 6-10 years | |
| Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Wood | 2nd Floor | 896 | SF | 7 | 10+ years | |
| Lighting - Pendent/Surface | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | | | | 7 | | |
| Marker Board | 2nd Floor | 20 | LF | - | 6-10 years | |
| Walls - Plaster/Drywall | 2nd Floor | 1,356 | SF | 6 | 10+ years | NATION 11 11 11 11 11 11 11 11 11 11 11 11 11 |
| Walls - Plaster/Drywall | 2nd Floor | 12 | SF | 4 | 0-1 year | Missing drywall/tile behind sink |
| | 2nd Elear | 2 | EA | 7 | 6-10 years | |
| Work Sink | 2nd Floor | 2 | | | - · · , · · · · | |
| Work Sink | 210 1001 | L | | • | | |
| | 3rd Floor | 1 | EA | 7 | 6-10 years | |



| XIII Schools | | | | | 62 | 39 N Leavitt STREET, Chicago, IL 60659 |
|------------------------------------|------------------------|----------|----------|--------|-------------------------|----------------------------------------|
| | | | | | Replacement | |
| Ceiling - Plaster/Drywall | 3rd Floor | 719 | SF | 6 | 10+ years | |
| Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 3rd Floor | 719 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 3rd Floor | 23 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 3rd Floor | 1,191 | SF | 6 | 10+ years | |
| | | | | | | |
| lassroom #302 (Special Education) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor | 333 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| Floor - Wood | 3rd Floor | 333 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| Walls - Masonry | 3rd Floor | 402 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 3rd Floor | 596 | SF | 6 | 10+ years | |
| | | | | | | |
| Classroom #303 (Regular Classroom) | | | | | 0.40 | |
| AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 3rd Floor | 8 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor | 715 | SF | 6 | 6-10 years | |
| Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 3rd Floor | 715 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 3rd Floor | 1,191 | SF | 6 | 10+ years | |
| Classroom #304 (Regular Classroom) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Casework | 3rd Floor | 8 | LF | 6 | 6-10 years | |
| Ceiling - Plaster/Drywall | 3rd Floor | 715 | SF | 6 | 10+ years | |
| Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 6-10 years | |
| Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| Floor - Wood | 3rd Floor | 715 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| Marker Board | 3rd Floor | 22 | | | | |
| | | | | 7 | 6-10 years | |
| Walls - Plaster/Drywall | 3rd Floor | 1,191 | SF | 6 | 10+ years | |
| | | | | | | |
| Classroom #305 (Regular Classroom) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | 3rd Floor 3rd Floor | 1 652 | EA SF | 7 6 | 6-10 years 10+ years | |
| AC Units | | | | | | |



| 6239 N | Leavitt | STREET, | Chicago, | IL | 60659 |
|--------|---------|---------|----------|----|-------|

| ALL A | | | | | | | 6239 N Leavitt STREET, Chicago, IL 60 |
|---------|-------------------------------|-----------|----------|------------|--------|-------------|---------------------------------------|
| | | | | | | Replacement | |
| | Floor - Wood | 3rd Floor | 652 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 44 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,201 | SF | 6 | 10+ years | |
| assroc | m #306 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 8 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 726 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 726 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | ĒA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 38 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 114 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,218 | SF | 6 | 10+ years | |
| | | | 1,210 | 0. | Ũ | let yeare | |
| lassroc | m #307 (Regular Classroom) | Oud Elson | | F A | | 0.40 | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 8 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 714 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 714 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,191 | SF | 6 | 10+ years | |
| lassroc | m #308 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 8 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 713 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 713 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,201 | SF | 6 | 10+ years | |
| atego | ry : Interior | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| orridor | | | 0.000 | 0 | | 10 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,390 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | 1st Floor | 6 | EA | 6 | 10+ years | |



| atego | ry : Interior | | В | uilding | : Main | | |
|-------|------------------------------------------|-------------------|----------|---------|--------|-------------|-------------------|
| _ | | | | _ | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Drinking Fountains - Double Water Cooler | 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Floor - Terrazzo | 1st Floor | 1,083 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 25 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 2,282 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 43 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 1st Floor | 7 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 1st Floor | 161 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 4,269 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,530 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 3,076 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Floor - Terrazzo | 2nd Floor | 541 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 2,601 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 34 | SF | 4 | 0-1 year | Cracking/chipping |
| | Lighting - Pendent/Surface | 2nd Floor | 43 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 2nd Floor | 165 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 2nd Floor | 7 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 3,960 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 3,162 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 2,608 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Water Cooler | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Floor - Terrazzo | 3rd Floor | 477 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 2,131 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd Floor | 108 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,980 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,558 | SF | 6 | 10+ years | |
| fety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 4 | EA | 7 | 6-10 years | |
| airs | | | | | | | |
| | Ceiling - Plaster/Drywall | Auditorium Stairs | 30 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | Auditorium Stairs | 15 | SF | 6 | 10+ years | |
| | Handrails | Auditorium Stairs | 28 | LF | 7 | 6-10 years | |
| | Stairs - Concrete | Auditorium Stairs | 18 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Auditorium Stairs | 627 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | North East | 280 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | North East | 143 | SF | 6 | 10+ years | |



| Catego | ry : Interior | | В | Building : Main | | | | | |
|---------|--------------------------------|------------|----------|-----------------|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Handrails | North East | 70 | LF | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | North East | 4 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | North East | 29 | LF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | North East | 1,204 | SF | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | North East | 803 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | South East | 286 | SF | 6 | 10+ years | | | |
| | Floor - Terrazzo | South East | 429 | SF | 6 | 10+ years | | | |
| | Handrails | South East | 171 | LF | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | South East | 9 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | South East | 71 | LF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | South East | 890 | SF | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | South East | 593 | SF | 7 | 10+ years | | | |
| ertical | Conveyance | | | | | | | | |
| | Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 7 | 6-10 years | | | |



| Category : Exterior | | | В | uilding | | | |
|---------------------|-----------------------------------------------------------------|------------------------------------|--------------|----------|----------|--------------------------|----------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| - Foundatio | | | | | | | |
| | Foundation - Concrete Superstructure - Concrete | Entire Building Entire Building | 137 4,984 | LF SF | 7 7 | 10+ years 10+ years | |
| ighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 2 | EA | 6 | 6-10 years | |
| Roof Sys | tem | | | | | | |
| , | Coping - Terra Cotta | Roof 1 | 137 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 1 | 45 | LF | 6 | 6-10 years | |
| | Parapet - 16" - 30" Height Roof - Asphalt Gravel Ballast | Roof 1 Roof 1 | 137 2,278 | LF SF | 6 6 | 6-10 years 6-10 years | |
| | Roof Structure - Concrete | Roof 1 | 2,278 | SF | 6 | 10+ years | |
| Nalls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 5,891 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 137 | SF | 6 | 10+ years | |
| | Exterior Walls - Terra Cotta | Entire Building | 137 | SF | 6 | 10+ years | |
| Vindows | | | | | | | |
| | Curtain wall - Insulated Panel | Entire Building | 418 | SF | 6 | 6-10 years | |
| | Guard - Guards wire guard | Entire Building | 442 | SF | 6 | 6-10 years | |
| | Lintels - Steel | Entire Building | 90 | LF | 6 | 10+ years | |
| | Lintels - Terra Cotta | Entire Building | 18 | LF SF | 6 6 | 10+ years | |
| | Windows - Casement Steel Windows - Sash Aluminum Double-pane | Entire Building Entire Building | 125 624 | SF | 6 | 6-10 years 6-10 years | |
| Categor | y : Electrical | | В | uilding | : Additi | on | |
| Ű, | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emergen | cy System | | | | | | |
| | Security System - CCTV | Entire Building | 4,984 | SF | 6 | 6-10 years | Served by attached main building |
| | Security System - Intrusion Detection | Entire Building | 4,984 | SF | 6 | 6-10 years | |
| Main Ser | vice | | | | | | |
| | PA System | Entire Building | 4,984 | SF | 6 | 6-10 years | Connected to main building |



Stone Elementary Scholastic Academy 6239 N Leavitt STREET, Chicago, IL 60659

| Catego | ry : Fire Protection | В | uilding | | | | |
|----------|--------------------------|-----------------|---------|----------|--------------------------|-----------|------------------------------------------|
| Group | Item - Type | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| Fire Ala | m | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 4,984 | SF | 6 | 10+ years | Functional, tested |
| | Fire Alarm_System | Entire Building | 4,984 | SF | 6 | 10+ years | Connected to main building, strobes only |
| Catego | ry : Mechanical | В | uilding | : Additi | on | | |

| Catego | ry : Mechanical | | В | uilding | : Additi | on | |
|-----------|--------------------------------------------------------|-----------------|----------|---------|----------|-------------|-----------------------------------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | Iling Systems | | | | | | |
| | Reheat Boxes - Reheat Boxes with Steam Coil | Mechanical Room | 1 | EA | 5 | 6-10 years | Serves addition, functional cleaned and adjusted, served by south AHU |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room | 100 | LF | 6 | 10+ years | Painted, common return |
| | Zone Dampers | Mechanical Room | 6 | EA | 5 | 6-10 years | Functional, need repaired controls. Manually controlled |
| Boiler Sv | /stems | | | | | | |
| | Piping - Condensate Pipe- Steel | Entire Building | 30 | LF | 6 | 6-10 years | Connected to main building. There are a few pipe clamps |
| | Piping - Steam Pipe- Steel | Entire Building | 30 | LF | 6 | 6-10 years | Connected to main building |
| | Steam Traps | Entire Building | 1 | EA | 6 | 6-10 years | Serve 1 reheat box, only 1 found |
| Tempera | ature Control | | | | | | |
| | Pneumatic System | Entire Building | 4,984 | SF | 4 | 1-2 years | Served by main building, manually operated, does not work well |
| | Thermostats - Pneumatic | Entire Building | 6 | EA | 6 | 6-10 years | Pneumatic controls do not operate well. Thermostats are functional |
| Catego | ry : Plumbing | | В | uilding | : Additi | on | |
| - | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Piping | | | | | | | |
| | Storm Piping | Entire Building | 4,984 | SF | 6 | 10+ years | Periodically cleaned, functional |
| Catego | ry : Room | | В | uildina | : Additi | on | |
| | • | | | . 3 | | | |

| Cat | tegoi | ry: | Room |
|-----|-------|-----|------|
| | | | |

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|-----------------------------|------------------------|----------|-----|------|--------------------------|----------|
| Administ | rative Suites/Offices | | | | | | |
| | AC Unit | 113 Counselor's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 113 Counselor's Office | 304 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 113 Counselor's Office | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 113 Counselor's Office | 1 | EA | 6 | 10+ years | |



| Catego | Category : Room | | | Building : Addition | | | | | |
|--------|----------------------------|------------------------|----------|---------------------|----------|-------------|----------|--|--|
| - | | • | • | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor - Tile | 113 Counselor's Office | 304 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 113 Counselor's Office | 5 | EA | 6 | 6-10 years | | | |
| | Power Distribution | 113 Counselor's Office | 8 | EA | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 113 Counselor's Office | 708 | SF | 6 | 10+ years | | | |
| • | ry : Classroom | | _ | | · Additi | | | | |

| oalcgo | ategory : Classroom | | Building : Addition | | | | | |
|----------|-----------------------------|-----------|---------------------|-----|------|-------------|----------|--|
| | | | | | _ | Recommend | - | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Classroo | m #111 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 1st Floor | 8 | LF | 6 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 725 | SF | 6 | 10+ years | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 725 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | | |
| | Marker Board | 1st Floor | 22 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,206 | SF | 6 | 10+ years | | |
| Classroo | om #112 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 1st Floor | 8 | LF | 6 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 725 | SF | 6 | 10+ years | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 725 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,206 | SF | 6 | 10+ years | | |
| Classroo | om #211 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 2nd Floor | 8 | LF | 6 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | 10+ years | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 6-10 years | | |
| | Floor - Tile | 2nd Floor | 725 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 6 | 10+ years | | |
| Classroo | om #212 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | |



| Catego | ry : Classroom | | В | uilding | : Additi | | 200 W Leavin Office 1, Officago, 12 00000 |
|----------|-----------------------------|-----------|----------|---------|----------|-------------|-------------------------------------------|
| Ŭ | • | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 2nd Floor | 8 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 725 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #213 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 8 | LF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 304 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 304 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 6 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 708 | SF | 6 | 10+ years | |

Category : Interior

| | | | | | | Recommend | |
|----------|--------------------------------|------------|----------|-----|------|-------------|-------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 122 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 31 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 82 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 10 | SF | 4 | 0-1 year | Cracking/chipping |
| | Lighting - Pendent/Surface | 1st Floor | 5 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 390 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 260 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 122 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd Floor | 31 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 72 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 20 | SF | 4 | 0-1 year | Cracking/chipping |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 390 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 260 | SF | 7 | 10+ years | |
| _Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | North West | 286 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | North West | 429 | SF | 7 | 10+ years | |
| | Handrails | North West | 171 | LF | 7 | 6-10 years | |

Building : Addition



| Catego | ry : Interior | B | Building : Addition | | | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|------------|---------------------|-----|------|-------------|----------|--|
| C = | Home Truce | Lecation | Quantitu | UOM | Denk | Recommend | Commonto | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Lighting - Pendent/Surface | North West | 6 | EA | 7 | 6-10 years | | |
| | Stairs - Terrazzo | North West | 71 | LF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | North West | 336 | SF | 7 | 10+ years | | |
| | Walls - Structural Glazed Tile | North West | 277 | SF | 7 | 10+ years | | |



| Catego | ry : Site | | В | uilding | | | |
|-----------|-------------------------------------------|--------------------|---------------|---------|--------|------------------------|-----------------------------------------------------------|
| 0 | No | | Oursetitus | | Daula | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Athletic | Surface - Natural | Baseball/Softball | 16.000 | SF | 4 | 1.0 vooro | Neede Depeir |
| | Surface - Natural Surface - Concrete | Basketball | 16,323 691 | SF | 4 7 | 1-2 years 10+ years | Needs Repair |
| | Sunace - Concrete | Baskelball | 091 | эг | 1 | 10+ years | |
| Civil/Dra | nage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 13 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Drain | Entire Site | 2 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 6 | EA | 6 | 10+ years | |
| | | | | | | | |
| Fencing | Fancian New Oten dead One are attal | | 4 000 | | 0 | 10 | |
| | Fencing - New Standard Ornamental | Entire Site | 1,968 | LF | 6 | 10+ years | |
| Landsca | De la | | | | | | |
| | Benches | Entire Site | 10 | EA | 6 | 6-10 years | |
| | Irrigation | Entire Site | 61,130 | SF | 6 | 6-10 years | |
| | Landscape - Hardscape- Pavers | Entire Site | 263 | SF | 4 | 0-1 year | Missing Pavers |
| | Landscape - Mulch | Entire Site | 6,000 | SF | 6 | 6-10 years | Quantity reduced to Allow Addition of |
| | | | 0,000 | 01 | 0 | e re jeare | New Turf Soccer Field/Asphalt Basketball Court |
| | Parkway trees | Entire Site | 34 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 5,290 | SF | 6 | 6-10 years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 37,674 | SF | 5 | 2-5 years | Quantity Increased to Account for New Basketball Court |
| | Retaining Wall - Concrete | Entire Site | 706 | SF | 6 | 10+ years | |
| | Trash Receptacles | Entire Site | 4 | EA | 6 | 10+ years | |
| | Walking Path - Hardscape- Asphalt | Entire Site | 3,665 | SF | 6 | 2-5 years | |
| Parking I | ot | | | | | | |
| | Concrete Curbs | Parking Lot- North | 1,079 | LF | 6 | 6-10 years | |
| | Interior Plantings | Parking Lot- North | 180 | LF | 6 | 6-10 years | |
| | Lighting - Pole Mounted | Parking Lot- North | 4 | EA | 6 | 6-10 years | |
| | Lighting - Pole Mounted | Parking Lot- North | 3 | EA | 6 | 6-10 years | |
| | Lighting - Pole Mounted | Parking Lot- North | 8 | EA | 6 | 6-10 years | |
| | Surface - Asphalt | Parking Lot- North | 19,479 | SF | 6 | 2-5 years | |
| | Surface - Concrete | Parking Lot- North | 1,283 | SF | 6 | 10+ years | |
| | Trash Compactor | Parking Lot- North | 1,200 | EA | 6 | 10+ years | |
| | Trash Enclosure - Chain Links | Parking Lot- North | 1 | SF | 7 | 10+ years | |
| | Vehicular Screening | Parking Lot- North | 248 | LF | 7 | 10+ years | |
| | - | - | | | | | |
| Playgrou | | | | | | 40 | |
| | Equipment - School Age 5-12 | South | 1 | EA | 6 | 10+ years | |



| | | | | | | | 0200 200 0 |
|-----------------|------------------------------------------------|-------------|----------|---------|------|-------------|------------|
| Category : Site | | | В | uilding | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Equipment - Swingset | South | 1 | EA | 7 | 10+ years | |
| | Equipment - Swingset | South | 1 | EA | 6 | 10+ years | |
| | Surface - Poured Surface | South | 7,982 | SF | 5 | 2-5 years | |
| Sidewall | KS | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 902 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 12,674 | SF | 6 | 10+ years | |
| Signage | | | | | | | |
| 0 0 | Flag Pole - Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | Marquee - Free Standing Back Lighted | Entire Site | 1 | EA | 7 | 6-10 years | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 4 | EA | 7 | 10+ years | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|---------------------|-------------------|---------------|--------|--------------------|-------|------------------|--------------------|--------|----------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | | | | | | | |
| Art Room | Regular Classroom | 1st Floor | 106 | 106 | 728 | 150 | 75 | N | Y |
| Art Room | Regular Classroom | 1st Floor | 110 | 110 | 703 | 122 | 60 | Y | Y |
| Computer Lab | Computer Lab | 2nd Floor | 206 | 206 | 840 | 102 | 50 | N | N |
| Fitness Room | Kindergarten | 1st Floor | 101 | 101 | 1,164 | 240 | 120 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 728 | 150 | 75 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 728 | 150 | 75 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 679 | 115 | 45 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 825 | 122 | 60 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 725 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 725 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 715 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 616 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 725 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 713 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 719 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 715 | 102 | 50 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 715 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 652 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 726 | 102 | 50 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 714 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 713 | 102 | 50 | N | Y |
| Science Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 896 | 122 | 60 | N | Y |
| Special Education | Special Education | 3rd Floor | 302 | 302 | 333 | 40 | 20 | N | N |
| | | | | | | | | | |
| Building : Addition | T | F | | | | | | | 1 |
| Regular Classroom | Lunch Room | 2nd Floor | 213 | Teacher lunch | 304 | 40 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 111 | 725 | 102 | 50 | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 725 | 102 | 50 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 725 | 102 | 50 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 725 | 102 | 50 | N | Y |