

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1895	3	91,945
Addition	1925	3	35,426
Campus Total			127,371

Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cell Equ			,				
	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	4	EA	7	10+ years	
	Cell Equipment - Generator	Entire Building	1	EA	7	10+ years	
_Entrance							
	Entrance Control - Audio and Video	#1 Main - South	1	EA	6	10+ years	
	Exterior Doors - Store Front	#1 Main - South	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 Main - South	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 Main - South	12	LF	5	6-10 years	Cracking, Spalling concrete
	Exterior Doors - Store Front	#10 - E	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#10 - E	3	EA	6	10+ years	
	Entrance Control - Audio and Video	#2 - S	1	EA	6	10+ years	
	Exterior Doors - Store Front	#2 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - S	3	EA	6	10+ years	
	Power Door Operator and Controls	#2 - S	1	EA	7	10+ years	
	Exterior Doors - Store Front	#3 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - S	9	LF	5	1-2 years	Spalling, cracked and broken step
	Exterior Doors - Exterior Steel Door	#8 - N	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#8 - N	1	EA	4	1-2 years	Rotted frames, rotted transom
	Exterior Doors - Exterior Steel Door	#9 Exit - E	2	EA	7	10+ years	New



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments
Foundati		Fadas Dallalia a	004		7	40	
	Foundation - Masonry	Entire Building	691	LF LF	7 6	10+ years	Look in from Classed downspart
	Foundation - Masonry	Entire Building	10	LF	ь	10+ years	Leak is from Clogged downspout, roofing issue. Also open joints in
							stone foundation
	Superstructure - Heavy Timber	Entire Building	91,945	SF	7	10+ years	Storie louridation
	Caparatracture Floaty Fillinger	Zitaro Dananig	01,010	O.	•	io. youro	
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Missing fixture
Doof Our	***						
Roof Sys	Access Ladder - Metal	Entire Building	2	EA	7	10+ years	
	Access Ladder - Metal	Entire Building	2	EA	7	10+ years	
	Access Ladder - Metal	Entire Building	1	EA	5	2-5 years	Small metal ladder
	Access Ladder - Wood	Entire Building	1	EΑ	4	0-1 year	Week, old, homemade ladder
	Chimney - Brick Chimney- Concrete/ Mortar	Entire Building	100	LF	6	10+ years	, ,
	Liner	•					
	Chimney - Metal Flue	Entire Building	6	LF	6	10+ years	
	Coping - Stone	Entire Building	335	LF	6	10+ years	
	Coping - Terra Cotta	Entire Building	1,230	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Entire Building	336	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Entire Building	24	LF	4	1-2 years	Missing downspout for vestibule roof.
	Downspouts - Interior Downspouts	Entire Building	213	LF	6	10+ years	
	Downspouts - Interior Downspouts	Entire Building	12	LF	5	1-2 years	Damaged downspout, water leakage into the boiler room
	Parapet - 16" - 30" Height	Entire Building	1,105	LF	6	10+ years	
	Parapet - 16" - 30" Height	Entire Building	15	LF	5	1-2 years	Open joints, correct Brich, open seams
	Parapet - Parapet < 16" Height	Entire Building	65	LF	6	10+ years	
	Parapet - Parapet > 30"	Entire Building	193	LF	6	10+ years	
	Parapet - Parapet > 30"	Entire Building	5	LF	5	1-2 years	Open joints
	Roof - Metal	Entire Building	160	SF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	25,997	SF	4	1-2 years	Worn surfaces, soft spots, Blistering
	Roof Hatch - Metal	Entire Building	2	EA	7	10+ years	
	Roof Structure - Heavy Timber	Entire Building	26,157	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	17,630	SF	7	10+ years	Tuckpointed
	Exterior Walls - Brick	Entire Building	19,587	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,958	SF	4	1-2 years	Reviewed, there are less open joints than before
	Exterior Walls - Stone-Cast	Entire Building	4,578	SF	5	10+ years	

Page : 2 of 40 Campus Name: Talcott Assessment Date: 07/14/2022



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Stone-Cast	Entire Building	4,578	SF	4	1-2 years	Open joints, broken, cracked, spoiled
	Exterior Walls - Terra Cotta	Entire Building	755	SF	6	10+ years	, , , , , , , , , , , , , , , , , , , ,
		G				,	
Windows							
	Guard - Guards wire guard	Entire Building	1,908	SF	6	10+ years	
	Lintels - Brick	Entire Building	315	LF	6	10+ years	
	Lintels - Steel	Entire Building	132	LF	6	10+ years	
	Lintels - Stone	Entire Building	626	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	56	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,300	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,050	SF	5	1-2 years	Balancers not working
	Windows - Sasii Aldmindin Dodbie-pane	Littile building	1,030	OI .	3	1-2 years	Balancers not working
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	UPS - Less than 30 KW	2nd Floor	2	EA	6	2-5 years	
	Automatic Transfer Switch	Basement	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	91,945	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	91,945	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	2,771	SF	6	6-10 years	
	Aisle Lighting	3	•			,	
	Emergency A/C Power - Corridors and	Entire Building	17,943	SF	6	6-10 years	
	Stairs	Zittiro Dananig	,	0.	Ū	o to youro	
	Emergency A/C Power - Lunchrooms	Entire Building	1,441	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,881	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	5	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	6-10 years	_
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	Battery power
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	2	EA	4	2-5 years	Older fixtures
	Aisle Lighting	•				•	
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	6	6-10 years	
	Stairs		· ·		-	,	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
Main Ca	n doo						
Main Se	Main Electrical Service - 2000 A	Basement	1	EA	7	10+ years	
	120/208/3PH	Dasement	1	ĽA	,	TOT years	
	Independent Electrical Service for emergency power	Basement	1	EA	7	10+ years	



ALL S			_				1840 W Ohio STREET, Chicago, IL 60622
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	91,945	SF	6	6-10 years	
	•	•				•	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	2-5 years	Fuse panel
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	i use parier
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building	2	EA	4		Progkers topod
		•				2-5 years	Breakers taped
	Lighting and Power Panels - Above 100 A	Entire Building	6	EΑ	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
Catama	m Fina Duataction		В	: a : a.			
Catego	ry : Fire Protection		В	uilding	: wain	D	
0	H T	Lagathan	0	LIOM	Danie	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Mechanical Room	91,945	SF	6	6-10 years	
	Fire Alarm_System	Mechanical Room	91,945	SF	6	6-10 years	
	Fire Pump Controller	Mechanical Room	1	EA	4	2-5 years	Old unit
Dumn Da	oom Assembly						
Fullip Ko		Machanical Deam	4	ГΛ		0.4	Duran manda ranla samant mat
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	2	0-1 year	Pump needs replacement, not
							working
Sprinkler	System						
	Dry Sprinkler System	Entire Building	35,426	SF	5	0-1 year	Pump not working
	Sprinkler Heads	Entire Building	35,426	SF	4	2-5 years	Older system
	Sprinkler Piping	Entire Building	35,426	SF	6	10+ years	Older System
	Sprinkler i iping	Little Ballaing	33,420	Si	U	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
ou.ogo.	y i meenamea.		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	10+ years	Working per building engineer
	Double Delivery- Steam Coils - Greater	Woonamou Room	'	L/\	J	TOT yours	Tronding per building engineer
	than 60000 cfm						
		Machanical Decem	4	Г^	0	10	
	Air Intake	Mechanical Room	1	EΑ	6	10+ years	
	Auxiliaries - Greater than 60000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	200	LF	5	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Ducts						
	Zone Dampers	Mechanical Room	48	EA	6	6-10 years	Actuators working per building
							engineer
oiler Sy	estems						
•	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	5	2-5 years	Rusty but dampers open and close
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	properly Condensate pump and sump pump Combine pit
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	2-5 years	Combine pit
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EΑ	5	2-5 years	Working per building engineer
	Steam- Low Pressure Boiler - 151 - 200 HP	200. 1.00	_		Ū	_ 0 ,000	rrenning per bananng enighteer
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	18	EA	6	6-10 years	
leating l	Devices						
J	Wall Heater - Electric	Entire Building	36	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	4	2-5 years	Older and cover missing
	Fin Tube - Electric	Entire Building	44	LF	4	2-5 years	Hard to maintain room temperature
	Unit Heater - Steam	Mechanical Room	1	EA	6	6-10 years	
- empera	ture Control						
•	Electric Thermostat	Entire Building	7	EA	6	6-10 years	Served electrical fin tube
	Pneumatic System	Entire Building	91,945	SF	7	6-10 years	
	Thermostats - Pneumatic	Entire Building	48	EA	7	6-10 years	
/entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor, Kitchen and Roof	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor, Kitchen and Roof	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st Floor, Kitchen and Roof	2	EA	5	2-5 years	Older and noisy
	Exhaust Fans- Roof Mounted - Less than 500 CFM	1st Floor, Kitchen and Roof	3	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	1st Floor, Kitchen and Roof	1	EA	4	0-1 year	No fire suppression system installed
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Joup	nem - Type	Location	Quantity	OOW	IVALIA	Replacement	Comments



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Served dishwasher in the kitchen
Piping							
-, 5	Domestic Piping-Hot Water Return Lines	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	35,426	SF	6	10+ years	
	Sanitary Piping	Entire Building	35,426	SF	6	6-10 years	
	Storm Piping	Entire Building	35,426	SF	6	6-10 years	
	Vent Piping	Entire Building	35,426	SF	6	6-10 years	
Pumps							
-	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	7	10+ years	Installed new in 2021
	Pumps - Sump-Duplex	Boiler Room	1	EA	6	2-5 years	Condensate pump and sump pump- Combine pit

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	Basement Break Room	400	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Break Room	1	EA	6	10+ years	
	Floor - Tile	Basement Break Room	400	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement Break Room	12	EA	6	6-10 years	
	Power Distribution	Basement Break Room	4	EA	7	10+ years	
	Walls - Masonry	Basement Break Room	135	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement Break Room	520	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	209	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	209	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	3	EA	7	6-10 years	
	Power Distribution	Engineer's Office	6	EA	6	10+ years	
	Walls - Masonry	Engineer's Office	209	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	265	SF	7	10+ years	No entry, engineer doesn't have key
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	•

Campus Name: Talcott Page : 6 of 40 Assessment Date: 07/14/2022



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	Gym Office	265	SF	6	6-10 years	
	Lighting - Pendent/Surface	Gym Office	4	EΑ	7	10+ years	
	Power Distribution	Gym Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym Office	304	SF	7	10+ years	
	Ceiling - Lay-in	Main Office	602	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Wood	Main Office	602	SF	6	10+ years	
	Lighting - Lay-in	Main Office	8	EA	7	10+ years	
	Power Distribution	Main Office	10	EA	6	10+ years	
	Walls - Plaster/Drywall	Main Office	692	SF	6	10+ years	
	Ceiling - Lay-in	Meeting Room	557	SF	7	10+ years	
	Doors - Transom Window	Meeting Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Meeting Room	2	EA	7	10+ years	
	Floor - Tile	Meeting Room	557	SF	7	10+ years	
	Lighting - Lay-in	Meeting Room	6	ĒΑ	7	6-10 years	
	Power Distribution	Meeting Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Meeting Room	640	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	132	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	ĒΑ	6	10+ years	
	Floor - Tile	Principal's Office	132	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office	3	ĒΑ	7	10+ years	
	Power Distribution	Principal's Office	8	EA	6	10+ years	
	Storage/ Closet	Principal's Office	39	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	151	SF	6	10+ years	
	Ceiling - Splined	Resource Room, Room 202	617	SF	6	10+ years	
	Doors - Transom Window	Resource Room, Room 202	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Resource Room, Room 202	1	ĒΑ	6	10+ years	
	Floor - Carpet	Resource Room, Room 202	617	SF	6	6-10 years	
	Lighting - Pendent/Surface	Resource Room, Room 202	12	EA	7	10+ years	
	Power Distribution	Resource Room, Room 202	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Resource Room, Room 202	709	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 102, Nurse's Station	302	SF	6	10+ years	
	Doors - Transom Window	Room 102, Nurse's Station	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 102, Nurse's Station	2	EA	6	10+ years	
	Floor - Tile	Room 102, Nurse's Station	302	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 102, Nurse's Station	6	EA	7	6-10 years	
	Power Distribution	Room 102, Nurse's Station	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 102, Nurse's Station	346	SF	6	10+ years	
	Work SInk	Room 102, Nurse's Station	1	EA	5	6-10 years	
	Ceiling - Lay-in	Room 203, Teacher's Lounge	1,098	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 203, Teacher's Lounge	2	ĒΑ	6	10+ years	
	Floor - Tile	Room 203, Teacher's Lounge	549	SF	6	10+ years	
	Floor - Wood	Room 203, Teacher's Lounge	549	SF	6	10+ years	
	Lighting - Lay-in	Room 203, Teacher's Lounge	15	ĒΑ	7	10+ years	
	,	,	_			,	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Room 203, Teacher's Lounge	16	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 203, Teacher's Lounge	1,262	SF	6	10+ years	
	Work SInk	Room 203, Teacher's Lounge	1	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	Room 219, Counselor's Office	615	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 219, Counselor's Office	1	EA	6	10+ years	
	Floor - Carpet	Room 219, Counselor's Office	615	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 219, Counselor's Office	10	EΑ	7	10+ years	
	Power Distribution	Room 219, Counselor's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 219, Counselor's Office	707	SF	6	10+ years	
	Ceiling - Lay-in	Work Room in Main Office	135	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Work Room in Main Office	1	EA	7	10+ years	
	Floor - Tile	Work Room in Main Office	135	SF	7	10+ years	
	Lighting - Lay-in	Work Room in Main Office	2	EA	7	6-10 years	
	Power Distribution	Work Room in Main Office	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Work Room in Main Office	155	SF	7	10+ years	
Kitchen							
	Ceiling - Exposed	Basement	350	SF	6	10+ years	
	Floor - Tile	Basement	350	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	10+ years	
	Serving Line	Basement	10	LF	6	10+ years	
	Walls - Masonry	Basement	300	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	240	SF	6	10+ years	
_Library							
	AC Unit	Room 302	2	EA	7	6-10 years	
	Casework	Room 302	86	LF	6	10+ years	
	Ceiling - Lay-in	Room 302	1,543	SF	6	10+ years	
	Doors - Transom Window	Room 302	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 302	2	ĒΑ	6	10+ years	
	Floor - Wood	Room 302	1,543	SF	6	10+ years	
	Lighting - Lay-in	Room 302	21	EA	7	10+ years	
	Storage/ Closet	Room 302	160	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 302	1,764	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 302	10	SF	6	6-10 years	Damage from previous fixture
Lunch &	Multipurpose Room						
<u>unon u</u>	Ceiling - Plaster/Drywall	Lunchroom 1, Basement	583	SF	6	10+ years	
	Floor - Tile	Lunchroom 1, Basement	583	SF	6	10+ years	
	Lighting - Pendent/Surface	Lunchroom 1, Basement	12	EA	7	6-10 years	
	Storage/ Closet	Lunchroom 1, Basement	143	SF	7	10+ years	
	Walls - Masonry	Lunchroom 1, Basement	425	SF	6	10+ years	
	Walls - Structural Glazed Tile	Lunchroom 1, Basement	425	SF	6	10+ years	
	Chactara Clazed Tile	zanomosm i, badomom	120	٥.	J	.o. youro	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Lunchroom 2, Basement	508	SF	6	2-5 years	
	Floor - Tile	Lunchroom 2, Basement	508	SF	6	10+ years	
	Lighting - Pendent/Surface	Lunchroom 2, Basement	14	EA	7	6-10 years	
	Serving Line	Lunchroom 2, Basement	10	LF	7	10+ years	
	Walls - Plaster/Drywall	Lunchroom 2, Basement	338	SF	6	10+ years	
	Walls - Structural Glazed Tile	Lunchroom 2, Basement	246	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Lunchroom 3 Former Play Room	596	SF	7	10+ years	
	Floor - Wood	Lunchroom 3 Former Play Room	596	SF	7	10+ years	
	Lighting - Pendent/Surface	Lunchroom 3 Former Play Room	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	Lunchroom 3 Former Play Room	525	SF	7	10+ years	
MDF_ID	F						
	Doors - Transom Window	Room 104	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 104	1	EΑ	6	10+ years	
	Finishes	Room 104	206	SF	7	10+ years	
	Other Cooling Unit	Room 104	1	EA	7	6-10 years	
	Window AC Unit	Room 104	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	5	10+ years	
	Janitor's Closet	1st Floor	12	SF	5	10+ years	
	Storage Room	1st Floor	667	SF	7	10+ years	
	Janitor's Closet	2nd Floor	26	SF	5	10+ years	Relamp
	Janitor's Closet	3rd Floor	26	SF	7	10+ years	•
	Air Tunnel	Basement	300	SF	7	10+ years	
	Boiler Room	Basement	1,786	SF	7	10+ years	
	Coal Room	Basement	736	SF	7	10+ years	
	Janitor's Closet	Basement	12	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,955	SF	7	10+ years	
	Storage Room	Basement	650	SF	5	10+ years	
	Storage Room	Basement	320	SF	5	10+ years	
	Storage Room	Basement	1,035	SF	5	10+ years	
	Storage Room	Basement	80	SF	5	10+ years	
Restroor	m						
	Accessories	1st Floor Boys	347	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	347	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	347	SF	6	10+ years	
	Floor Drain	1st Floor Boys	2	EA	7	10+ years	
	Hand Dryer	1st Floor Boys	2	EA	7	6-10 years	
	Lavatory	1st Floor Boys	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	6	EA	7	6-10 years	
	Partitions	•	1	EA	7	•	
	i aruuuris	1st Floor Boys	ı	ĽA	1	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	1st Floor Boys	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Boys	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	85	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	15	SF	4	1-2 years	Damaged tile
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys	199	SF	7	10+ years	-
	Water Closet	1st Floor Boys	1	EA	7	10+ years	
	Accessories	1st Floor Girls	280	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Girls	160	SF	5	1-2 years	Damaged ceiling
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	280	SF	6	10+ years	
	Floor Drain	1st Floor Girls	2	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	6	EA	7	6-10 years	
	Partitions	1st Floor Girls	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	322	SF	7	10+ years	
	Water Closet	1st Floor Girls	5	EA	7	10+ years	
	Accessories	2nd Floor	347	SF	7	6-10 years	Under construction
	Ceiling - Plaster/Drywall	2nd Floor	347	SF	6	10+ years	Under construction
	Floor - Tile Ceramic/ Porcelain	2nd Floor	347	SF	6	10+ years	Under construction
	Floor Drain	2nd Floor	2	EA	7	10+ years	Under construction
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	Under construction
	Lavatory	2nd Floor	2	EA	6	10+ years	Under construction
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	Under construction
	Partitions	2nd Floor	1	EA	7	10+ years	Under construction
	Urinals	2nd Floor	5	EA	6	10+ years	Under construction
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	10+ years	Under construction
	Walls - Structural Glazed Tile	2nd Floor	100	SF	6	10+ years	Under construction
	Walls - Tile Ceramic/ Porcelain	2nd Floor	199	SF	6	10+ years	Under construction
	Water Closet	2nd Floor	199	EA	6	10+ years	Under construction
	Accessories	2nd Floor	280	SF	7	6-10 years	Room blocked off for construction
	Ceiling - Plaster/Drywall	2nd Floor	280	SF	6	10+ years	Room blocked on for construction
	Floor - Tile Ceramic/ Porcelain	2nd Floor	280	SF	6	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	
	Partitions	2nd Floor	5	EA	7		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	322	SF	6	10+ years 10+ years	
	Water Closet	2nd Floor	5	EA	6	•	
		3rd Floor	347	SF	7	10+ years	
	Accessories	3rd Floor 3rd Floor	347 347	SF SF	7	10+ years	
	Ceiling - Plaster/Drywall Floor - Tile Ceramic/ Porcelain	3rd Floor 3rd Floor	347 347	SF SF	<i>7</i> 6	10+ years	
	Floor Drain	3rd Floor	2	Sr EA	7	10+ years	
	FIOOI DIAIII	SIU FIOOI	2	EA	′	10+ years	

Campus Name: Talcott Page : 10 of 40 Assessment Date: 07/14/2022



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Partitions	3rd Floor	1	EA	5	10+ years	Installed so lock does not line up correctly
	Urinals	3rd Floor	5	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	100	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	199	SF	6	10+ years	
	Water Closet	3rd Floor	1	EA	6	10+ years	
	Accessories	3rd Floor	280	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	280	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	280	SF	6	10+ years	
	Floor Drain	3rd Floor	2	EΑ	7	10+ years	
	Hand Dryer	3rd Floor	1	EΑ	7	6-10 years	
	Lavatory	3rd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Partitions	3rd Floor	5	EA	5	10+ years	Peeling paint
	Walls - Tile Ceramic/ Porcelain	3rd Floor	322	SF	6	10+ years	
	Water Closet	3rd Floor	5	EA	6	10+ years	
	Accessories	Basement Boys Near Lunchroom	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Boys Near Lunchroom	130	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Boys Near Lunchroom	130	SF	7	10+ years	
	Lavatory	Basement Boys Near Lunchroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys Near Lunchroom	3	EA	7	10+ years	
	Partitions	Basement Boys Near Lunchroom	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Boys Near Lunchroom	400	SF	7	10+ years	
	Water Closet	Basement Boys Near Lunchroom	2	EA	7	10+ years	
	Accessories	Basement Boys South	347	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Boys South	337	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement Boys South	10	SF	5	1-2 years	Damaged ceiling
	Floor - Tile Ceramic/ Porcelain	Basement Boys South	347	SF	7	10+ years	Damagea coming
	Floor Drain	Basement Boys South	2	EA	7	10+ years	
	Hand Dryer	Basement Boys South	1	EA	7	6-10 years	
	Lavatory	Basement Boys South	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys South	6	EA	7	10+ years	
	Partitions	Basement Boys South	2	EA	7	10+ years	
	Urinals	Basement Boys South	6	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Boys South	450	SF	7	10+ years	
	Water Closet	Basement Boys South	2	EA	7	10+ years	
	Accessories	Basement By Lunchroom	48	SF	7	6-10 years	Under construction
	Ceiling - Lay-in	Basement By Lunchroom	48	SF	7	10+ years	Officer construction
	Doors - Wood Doors inclu hw	Basement By Lunchroom	40 1	EA	7	10+ years 10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement By Lunchroom	48	SF	7	10+ years	
	1 1001 - THE CETAITHO FOICEIAIT	basement by Euroniooni	40	SI-	,	10+ years	



Catego	ry : Room		Building : Main						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lavatory	Basement By Lunchroom	1	EA	7	10+ years			
	Lighting - Lay-in	Basement By Lunchroom	1	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement By Lunchroom	55	SF	7	10+ years			
	Water Closet	Basement By Lunchroom	1	EA	7	10+ years			
	Accessories	Basement Girls Near Lunchroom	100	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement Girls Near Lunchroom	100	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement Girls Near Lunchroom	100	SF	7	10+ years			
	Lavatory	Basement Girls Near Lunchroom	2	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement Girls Near Lunchroom	3	EA	7	10+ years			
	Partitions	Basement Girls Near Lunchroom	2	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement Girls Near Lunchroom	400	SF	7	10+ years			
	Water Closet	Basement Girls Near Lunchroom	2	EA	7	10+ years			
	Accessories	Basement in Janitirs Room	55	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement in Janitirs Room	55	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement in Janitirs Room	1	EA	6	10+ years			
	Floor - Concrete	Basement in Janitirs Room	55	SF	7	10+ years			
	Lavatory	Basement in Janitirs Room	2	EA	7	6-10 years			
	Lighting - Wall Mounted	Basement in Janitirs Room	2	EA	7	6-10 years			
	Partitions	Basement in Janitirs Room	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Basement in Janitirs Room	296	SF	5	10+ years			
	Water Closet	Basement in Janitirs Room	1	EA	6	6-10 years			
	Accessories	In Engineer's Office	43	SF	7	6-10 years			
	Ceiling - Lay-in	In Engineer's Office	43	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Engineer's Office	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Engineer's Office	43	SF	6	10+ years			
	Lavatory	In Engineer's Office	1	EA	6	10+ years			
	Lighting - Lay-in	In Engineer's Office	1	EA	6	6-10 years			
	Lighting - Wall Mounted	In Engineer's Office	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	In Engineer's Office	49	SF	6	10+ years			
	Water Closet	In Engineer's Office	1	EA	6	10+ years			
	Accessories	In Main Office	35	SF	7	6-10 years			
	Ceiling - Lay-in	In Main Office	35	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Main Office	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Main Office	35	SF	6	10+ years			
	Lavatory	In Main Office	1	EA	6	10+ years			
	Lighting - Lay-in	In Main Office	1	EA	7	10+ years			
	Walls - Structural Glazed Tile	In Main Office	40	SF	6	10+ years			
	Water Closet	In Main Office	1	EA	6	10+ years			
	Accessories	Inside 108	54	SF	7	6-10 years			
	Ceiling - Splined	Inside 108	54	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Inside 108	1	EA	7	10+ years			
	Floor - Tile	Inside 108	54	SF	7	10+ years			
	Lavatory	Inside 108	1	ĒΑ	7	10+ years			
	Lighting - Pendent/Surface	Inside 108	1	EA	6	2-5 years			
	5 5		·		-	- ,			

Campus Name: Talcott Page : 12 of 40 Assessment Date: 07/14/2022



Catego	tegory : Room		В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Inside 108	162	SF	6	6-10 years	
	Water Closet	Inside 108	1	EA	7	10+ years	
	Accessories	Men's Room in Room 203	77	SF	7	6-10 years	
	Ceiling - Lay-in	Men's Room in Room 203	71	SF	6	10+ years	
	Ceiling - Lay-in	Men's Room in Room 203	6	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Men's Room in Room 203	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room in Room 203	77	SF	6	10+ years	
	Hand Dryer	Men's Room in Room 203	1	EA	7	6-10 years	
	Lavatory	Men's Room in Room 203	1	EA	5	1-2 years	Stuck running
	Lighting - Lay-in	Men's Room in Room 203	2	EA	7	10+ years	· ·
	Partitions	Men's Room in Room 203	1	EA	7	10+ years	
	Urinals	Men's Room in Room 203	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Men's Room in Room 203	45	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Men's Room in Room 203	45	SF	6	10+ years	
	Water Closet	Men's Room in Room 203	1	EΑ	6	10+ years	
	Accessories	Restroom in 101	60	SF	7	6-10 years	
	Ceiling - Lay-in	Restroom in 101	40	SF	7	10+ years	
	Ceiling - Lay-in	Restroom in 101	20	SF	4	1-2 years	Stan tile
	Doors - Wood Doors inclu hw	Restroom in 101	1	EA	7	10+ years	Ctarr tillo
	Floor - Tile Ceramic/ Porcelain	Restroom in 101	60	SF	7	10+ years	
	Lavatory	Restroom in 101	1	EA	7	10+ years	
	Lighting - Lay-in	Restroom in 101	1	EA	7	10+ years	
	Partitions	Restroom in 101	1	EA	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in 101	285	SF	7	10+ years	
	Water Closet	Restroom in 101	263	EA	7	10+ years	
	Accessories	Women's Room in Room 203	146	SF	7	6-10 years	
		Women's Room in Room 203	146	SF	6		
	Ceiling - Lay-in Doors - Wood Doors inclu hw	Women's Room in Room 203		EA		10+ years	
			1	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room in Room 203	146		6	10+ years	
	Hand Dryer	Women's Room in Room 203	1	EΑ	7	6-10 years	
	Lavatory	Women's Room in Room 203	2	EΑ	6	10+ years	
	Lighting - Lay-in	Women's Room in Room 203	2	EΑ	7	10+ years	
	Lighting - Wall Mounted	Women's Room in Room 203	1	EA	6	10+ years	
	Partitions	Women's Room in Room 203	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's Room in Room 203	84	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's Room in Room 203	83	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's Room in Room 203	1	SF	5	1-2 years	Broken tiles
	Water Closet	Women's Room in Room 203	3	EA	6	10+ years	
atego	ry : Classroom		В	uilding	: Main		
		Lagation				Recommend	Comments
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jassroc	om #101 (Pre School)	1et Floor		Г^	7	6.10	
	AC Units	1st Floor	2	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	65	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,089	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	1,089	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	[^] 21	EA	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,252	SF	6	10+ years	
Classro	om #105 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	-	
		1st Floor		SF	6	10+ years	
	Floor - Carpet		750			2-5 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	6	10+ years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	865	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classro	om #106 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	750	SF	7	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Oldiade/ Cidael		J 4			10+ years	
		1ot Eleor		C.E.		10+ years	
	Walls - Plaster/Drywall	1st Floor	850	SF	7	4.0	Cracked well
	Walls - Plaster/Drywall Walls - Plaster/Drywall	1st Floor	850 15	SF	5	1-2 years	Cracked wall
	Walls - Plaster/Drywall		850			1-2 years 6-10 years	Cracked wall
Classro	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink om #107 (Play Room)	1st Floor 1st Floor	850 15 1	SF EA	5 7	6-10 years	Cracked wall
Classro	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink om #107 (Play Room) AC Units	1st Floor 1st Floor 1st Floor	850 15 1	SF EA EA	5 7 7	6-10 years	Cracked wall
Classroo	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink om #107 (Play Room) AC Units Casework	1st Floor 1st Floor 1st Floor 1st Floor	850 15 1 1 6	SF EA EA LF	5 7	6-10 years 6-10 years 10+ years	Cracked wall
Classro	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink Om #107 (Play Room) AC Units Casework Ceiling - Splined	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	850 15 1	SF EA EA LF SF	5 7 7	6-10 years	Cracked wall
Classro	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink om #107 (Play Room) AC Units Casework	1st Floor 1st Floor 1st Floor 1st Floor	850 15 1 1 6	SF EA EA LF	5 7 7 7	6-10 years 6-10 years 10+ years	Cracked wall Stain tile
Classro	Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink Om #107 (Play Room) AC Units Casework Ceiling - Splined	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	850 15 1 1 6 829	SF EA EA LF SF	5 7 7 7 7	6-10 years 6-10 years 10+ years 10+ years	



Catego	ry : Classroom		В	uilding	: Main		1640 W Offio STREET, Chicago, IL 60622
0 0	, , , , , , , , , , , , , , , , , , , ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile	1st Floor	815	SF	7	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	948	SF	6	10+ years	
Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Splined	1st Floor	830	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	10+ years	
	Storage/ Closet	1st Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	948	SF	7	10+ years	
Classroo	om #109 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	880	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	880	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,016	SF	6	10+ years	
Classroo	om #110 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	870	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	4	1-2 years	Missing/falling tile
	Chalk Board	1st Floor	12	LF	4	2-5 years	J J
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	160	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,016	SF	6	10+ years	
			.,010	٥.	ŭ	. c . y care	

Campus Name: Talcott Page: 15 of 40 Assessment Date: 07/14/2022



Category : Classroom			В	uilding	: Main		
			•	11614		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #116 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	869	SF	6	10+ years	
	•					,	
lassroo	m #117 (Regular Classroom)	4 / 51				0.40	
	AC Units	1st Floor	2	EΑ	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Splined	1st Floor	830	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	26	LF	7	6-10 years	
	Storage/ Closet	1st Floor	140	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	959	SF	6	10+ years	
:lassroo	m #118 (Regular Classroom)						
21000100	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Splined	1st Floor	750	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Bools Incid IIW	1st Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	,	
				LF	7	6-10 years	
	Marker Board	1st Floor	16		-	6-10 years	De alian a sist
	Storage/ Closet	1st Floor	54	SF	5	10+ years	Peeling paint
	Walls - Plaster/Drywall	1st Floor	872	SF	6	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	890	SF	6	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,016	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Books including	2nd Floor	830	SF	6	10+ years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	Sear wearing
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	179	SF	7	•	
	Walls - Plaster/Drywall	2nd Floor	969	SF	6	10+ years 10+ years	
Classroo	om #205 (Special Program)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	2-5 years	Slight damage
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	862	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	7	SF	5	1-2 years	Cracking
Classroo	om #206 (Special Education)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #207 (Special Education)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	959	SF	6	10+ years	
Classroo	m #208 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	830	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	26	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	140	SF	5	10+ years	Cracking wall and boarded door
	Walls - Plaster/Drywall	2nd Floor	959	SF	6	10+ years	3
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor	21	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	880	SF	6	10+ years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	13	ĒΑ	7	10+ years	Coal moaning
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,016	SF	6	10+ years	
Classroo	m #210 (Regular Classroom)						
CIGOSIUL	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	6	LF	6	10+ years	
	Casework Ceiling - Splined	2nd Floor 2nd Floor	880	SF	6	10+ years	
	Chalk Board	2nd Floor 2nd Floor	12	LF	4	2-5 years	
	Chair Board	2110 1 1001	12	Li	7	2 o yours	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,016	SF	6	10+ years	
Classroo	om #216 (Other Instructional Use)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
						•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	46	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	846	SF	6	10+ years	
Classroo	om #217 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	830	SF	6	10+ years	Seal wearing
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	Coal Woaling
	Marker Board	2nd Floor	26	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	140	SF	5	•	Water demage on soiling
			_	SF SF		10+ years	Water damage on ceiling
	Walls - Plaster/Drywall	2nd Floor	959	SF SF	6	10+ years	0
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracking
Classroc	om #218 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	26	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	140	SF	7	10+ years	
		Z110 1 1001	140	J.	,	ioi veais	

Campus Name: Talcott Page: 19 of 40 Assessment Date: 07/14/2022



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	959	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	890	SF	6	10+ years	
	Chalk Board	3rd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	3rd Floor	26	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,039	SF	6	10+ years	
_Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	890	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	890	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	26	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,036	SF	6	10+ years	
_Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	838	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Cracking
_Classroo	om #306 (Other Instructional Use)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	750	SF	6	10+ years	
	· · · · · · · · · · · · · · · · · ·	0.0.	700		•	,	



Catego	Category : Classroom		В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	26	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	848	SF	6	10+ years	
Classroo	om #307 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	830	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	830	SF	6	10+ years	
				_	_	•	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	179	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	969	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	830	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	36	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	168	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	947	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	880	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	•	
	Storage/ Closet	3rd Floor	160	SF	7	6-10 years	
				SF SF		10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,010	or.	6	10+ years	

Campus Name: Talcott Page : 21 of 40 Assessment Date: 07/14/2022



Catego	Category : Classroom		В	uilding		1040 W Offilo Office 1, Officago, ie 0002	
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	1-2 years	water damage and broken pieces
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	880	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	160	SF	5	10+ years	Water damage
	Walls - Plaster/Drywall	3rd Floor	880	SF	6	10+ years	Traio: damage
`lassror	om #316 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	750	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	872	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classroo	om #317 (Regular Classroom)						
21400100	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	830	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	26	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	959	SF	6	10+ years	
Classroo	om #318 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	830	SF	6	10+ years	
	Coming Opinion	0.4 1 1001	000	0.	J	io. yours	



Catego	ry : Classroom		В	uilding	: Main		1040 W Offilo STREET, Chicago, IL 60622
Jaiogo	ry i Glador Com			unung	· Wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	830	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	36	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	942	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	1-2 years	Cracking
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	602	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	602	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	9	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	5	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	692	SF	6	10+ years	
Classroo	om #B6 (Regular Classroom)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	2	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	528	SF	6	0-1 year	Peeling paint
	Chalk Board	Basement	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	7	10+ years	
	Floor - Wood	Basement	528	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	12	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	Basement	740	SF	6	10+ years	
Classroo	om #B7 (Regular Classroom)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	520	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Carpet	Basement	520	SF	4	0-1 year	Ripples in carpet
	Lighting - Pendent/Surface	Basement	15	EΑ	7	6-10 years	. uppide iii dai pot
	Walls - Masonry	Basement	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	620	SF	6	10+ years	
_Classroo	om #Basement Music (Music Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	650	SF	6	10+ years	
	Chalk Board	Basement	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	

Page : 23 of 40 Campus Name: Talcott Assessment Date: 07/14/2022



Categor	ry : Classroom	В	uilding	: Main			
					_	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	Basement	650	SF	4	0-1 year	Ripples in carpet
	Lighting - Pendent/Surface	Basement	21	EA	7	6-10 years	
	Walls - Masonry	Basement	830	SF	7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
roup orridor	item - Type	Location	Quantity	OOW	Nalik	Replacement	Comments
0111001	Ceiling - Plaster/Drywall	1st Floor	3,919	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years	
	Floor - Asphalt Floor	1st Floor	3,919	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	46	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,506	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,919	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Epoxy/ Painted	2nd Floor	375	SF	7	10+ years	
	Floor - Wood	2nd Floor	3,544	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	46	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,506	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,919	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	3,919	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	46	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	52	EΑ	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,498	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Water damage
	Ceiling - Plaster/Drywall	Basement	2,826	SF	5	10+ years	water damage
	Doors - Steel Doors incl hw	Basement	2,020	EA	7	10+ years	
	Doors - Wood Doors include hw	Basement	6	EA	6		
		Basement	3	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler Floor - Epoxy/ Painted	Basement	2,826	SF	7	6-10 years	
		Basement	2,020	EA	7	10+ years	
	Lighting - Pendent/Surface			SF	6	6-10 years	
	Walls - Masonry	Basement	3,249	SF	О	10+ years	
afety							
•	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	6	EA	7	6-10 years	
tairs							
	Ceiling - Splined	East	525	SF	6	10+ years	
	Floor - Terrazzo	East	525	SF	7	10+ years	
	Handrails	East	228	LF	7	10+ years	

Campus Name: Talcott Page : 24 of 40 Assessment Date: 07/14/2022



Catego	ry : Interior	В	uilding	: Main			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	East	9	EA	7	10+ years	
	Stairs - Terrazzo	East	78	LF	6	10+ years	
	Walls - Plaster/Drywall	East	600	SF	6	10+ years	
	Walls - Plaster/Drywall	East	3	SF	6	6-10 years	Cracking
	Ceiling - Splined	South Central	1,155	SF	7	10+ years	
	Floor - Asphalt	South Central	1,155	SF	7	10+ years	
	Handrails	South Central	210	LF	7	10+ years	
	Lighting - Pendent/Surface	South Central	9	EA	7	6-10 years	
	Stairs - Asphalt	South Central	72	LF	7	10+ years	
	Walls - Plaster/Drywall	South Central	1,328	SF	7	10+ years	
	Ceiling - Splined	South East	515	SF	6	10+ years	
	Ceiling - Splined	South East	10	SF	4	1-2 years	Water damage
	Floor - Epoxy/ Painted	South East	525	SF	7	10+ years	-
	Handrails	South East	228	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	9	EA	7	10+ years	
	Stairs - Asphalt	South East	78	LF	6	10+ years	
	Walls - Plaster/Drywall	South East	591	SF	6	10+ years	
	Walls - Plaster/Drywall	South East	12	SF	5	1-2 years	Cracking
	Ceiling - Splined	South West	1,155	SF	6	10+ years	-
	Floor - Asphalt	South West	1,155	SF	7	10+ years	
	Handrails	South West	210	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	9	EA	7	6-10 years	
	Stairs - Asphalt	South West	72	LF	6	10+ years	
	Walls - Plaster/Drywall	South West	1,328	SF	6	10+ years	
Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	North	1	EA	5	2-5 years	Repairs currently taking place

Campus Name: Talcott Page : 25 of 40 Assessment Date: 07/14/2022



Category : Exterior Building : Addition

	ry : Exterior		Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Cell Equ	ipment									
	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years				
		g	·		•	.o. you.o				
Entrance	9									
	Exterior Doors - Exterior Steel Door	#4 - W	3	EA	5	2-5 years	Corroding frames			
	Exterior Doors - Transom Lite	#4 - W	3	EA	6	10+ years	•			
	Exterior Stairs - Stone	#4 - W	10	LF	5	10+ years	Small crack, somewhere in tear.			
	Ramps - Concrete	#4 - W	6	LF	6	10+ years				
	Exterior Doors - Exterior Wood Door	#5 - W	3	EA	4	1-2 years	Old, damaged wood doors. Corrodo metal frames			
	Exterior Doors - Transom Lite	#5 - W	3	EA	4	1-2 years	Single pane wood transom			
	Exterior Stairs - Stone	#5 - W	20	LF	6	2-5 years	3 1			
	Exterior Stairs - Stone	#5 - W	8	LF	4	1-2 years	Stone has settled away from level			
	Exterior Doors - Exterior Wood Door	#6 Exit - N	2	EA	6	10+ years				
	Exterior Doors - Transom Lite	#6 Exit - N	1	EA	6	10+ years				
	Exterior Stairs - Concrete	#6 Exit - N	2	LF	5	1-2 years	Broken stone			
	Exterior Stairs - Stone	#6 Exit - N	10	LF	6	10+ years				
	Exterior Doors - Exterior Steel Door	#7 - E	2	ĒΑ	6	6-10 years	Door is corroding			
oundati	ion									
Oundan	Foundation - Concrete	Entire Building	393	LF	7	10+ years				
	Superstructure - Steel with Clay Tile Arch	Entire Building	35,426	SF	7	10+ years				
ighting										
-igi iii ig	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years				
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Missing fixture			
		g	•		-	,				
Roof Sys										
Roof Sy:	Access Ladder - Metal	Entire Building	1	EA	7	10+ years				
Roof Sy:	Access Ladder - Metal Access Ladder - Metal	Entire Building	1	EA	5	2-5 years	Are small, old ladder			
loof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta	Entire Building Entire Building	1 393	EA LF		2-5 years 10+ years	Are small, old ladder			
Roof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts	Entire Building Entire Building Entire Building	1 393 366	EA LF LF	5	2-5 years 10+ years 10+ years	Are small, old ladder			
toof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta	Entire Building Entire Building	1 393 366 393	EA LF LF LF	5 6	2-5 years 10+ years	Are small, old ladder			
Roof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts	Entire Building Entire Building Entire Building	1 393 366	EA LF LF	5 6 6	2-5 years 10+ years 10+ years	Are small, old ladder Open seams, soft spots, Worn surfaces			
Roof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - Parapet > 30"	Entire Building Entire Building Entire Building Entire Building Entire Building	1 393 366 393	EA LF LF SF	5 6 6	2-5 years 10+ years 10+ years 10+ years	Open seams, soft spots, Worn			
Roof Sy:	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - Parapet > 30" Roof - Modified Bitumen	Entire Building Entire Building Entire Building Entire Building Entire Building	1 393 366 393 11,230	EA LF LF LF SF	5 6 6 4	2-5 years 10+ years 10+ years 10+ years 1-2 years	Open seams, soft spots, Worn			
·	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - Parapet > 30" Roof - Modified Bitumen Roof Hatch - Metal	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 393 366 393 11,230	EA LF LF SF	5 6 6 6 4	2-5 years 10+ years 10+ years 10+ years 1-2 years 10+ years	Open seams, soft spots, Worn			
Roof Sys	Access Ladder - Metal Access Ladder - Metal Coping - Terra Cotta Downspouts - Interior Downspouts Parapet - Parapet > 30" Roof - Modified Bitumen Roof Hatch - Metal	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 393 366 393 11,230	EA LF LF SF	5 6 6 6 4	2-5 years 10+ years 10+ years 10+ years 1-2 years 10+ years	Open seams, soft spots, Worn			

Campus Name: Talcott Page : 26 of 40 Assessment Date: 07/14/2022



							1040 W GING GTREET, GINGAGO, IE 000ZZ
Catego	ry : Exterior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	10,812	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	300	SF	5	1-2 years	Open Joints,
	Exterior Walls - Stone-Cast	Entire Building	1,230	SF	6	10+ years	open cente,
	Exterior Walls - Stone-Cast Exterior Walls - Stone-Cast	Entire Building	610	SF	5	1-2 years	Open joints
	Exterior Walls - Storie-Cast	Entire Building	010	SI	3	1-2 years	Open joints
_Windows							
	Guard - Guards wire guard	Entire Building	356	SF	6	10+ years	
	Lintels - Steel	Entire Building	267	LF	6	10+ years	
	Lintels - Stone	Entire Building	270	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,150	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	550	SF	5	1-2 years	Inoperable balancers
		9			-	,	
Catego	ry : Electrical		В	uilding	: Additi	on	
Juliogo	. y . Elooti loui			unung	· / taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	· · · · · · · · · · · · · · · · · · ·	Location	Quantity	COM	Italik	Replacement	Comments
_Emerger	ncy System		0= 100			0.40	
	Security System - CCTV	Entire Building	35,426	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	35,426	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	3,828	SF	6	6-10 years	
	Stairs						
	Emergency A/C Power - Gym	Entire Building	3,501	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	6	EA	6	6-10 years	
	Stairs	9	_			,	
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Facility Control	Entire Ballating	·		Ū	o to youro	
Main Se	rvino						
<u>IVIAIII SE</u>		Entire Building	25 426	SF	6	6.10 40000	Conved from main building
	PA System	Entire Building	35,426	5F	6	6-10 years	Served from main building
Dawar D	induite in						
_Power D	vistribution	Fatina Dadidio				40.	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Can't open the door
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	2-5 years	Breakers taped
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	·
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	· · · · · · · · · · · · · · · · · · ·	·	** *	-	- ,	

Campus Name: Talcott Page : 27 of 40 Assessment Date: 07/14/2022



Mancel Talcott Elementary School

XIII S	chools						1840 W Ohio STREET, Chicago, IL 6062
Catego	ry : Fire Protection		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Alar	m						
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	35,426 35,426	SF SF	6 6	6-10 years 6-10 years	Served from main building Served from main building
Catego	ry : Mechanical		В	uilding	: Additi	on	
Proup	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOW	Kank	Replacement	Comments
Air Hand	ling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	10+ years	Located in main building Served north side Addition Working per building engineer
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	5	6-10 years	
	Zone Dampers	Mechanical Room	25	EA	5	10+ years	Actuators working with system
Boiler Sy	stems						
	Piping - Condensate Pipe- Steel	Entire Building	150	LF	6	10+ years	Served from main building
	Piping - Steam Pipe- Steel	Entire Building	150	LF	6	10+ years	Served from main building
	Steam Traps	Entire Building	15	EA	6	6-10 years	
leating I							
	Fin Tube - Electric	Basement	60	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	7	6-10 years	
empera	ture Control						
	Electric Thermostat	Entire Building	6	EA	6	6-10 years	Served fan in electrical room
	Pneumatic System	Entire Building	35,426	SF	7	6-10 years	Served from main building
	Thermostats - Pneumatic	Entire Building	25	EA	6	2-5 years	
/entilatio							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Electrical Room and Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Electrical Room and Roof	1	EA	6	6-10 years	
catego	ry : Plumbing		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping	nem - Type	Location	Quantity	COIVI	IVALIA	Replacement	Comments
hind	Domestic Piping-Hot Water Return Lines	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	35,426	SF	6	10+ years	
	zemeene i iping met mater metam meete	g	00,0	О.	· ·	,	

Campus Name: Talcott Page : 28 of 40 Assessment Date: 07/14/2022



Catego	ry : Plumbing		В	uilding	: Additi	on	
J	·					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	35,426	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	35,426	SF	6	10+ years	
	Sanitary Piping	Entire Building	35,426	SF	6	10+ years	
	Storm Piping	Entire Building	35,426	SF	6	10+ years	
	Vent Piping	Entire Building	35,426	SF	6	10+ years	
Catego	ry : Room		В	uildina	: Additi	on	
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	AC Unit	Room 213, NPC Library	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 213, NPC Library	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 213, NPC Library	1	EA	6	10+ years	
	Floor - Wood	Room 213, NPC Library	405	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 213, NPC Library	9	EA	7	10+ years	
	Power Distribution	Room 213, NPC Library	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 213, NPC Library	465	SF	6	10+ years	
Auditorii	um & Theater						
	Balcony Seating	Basement	179	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	2,271	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2,271	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	6	EA	7	10+ years	
	Floor - Epoxy/ Painted	Basement	2,271	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	25	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement	8	EA	6	6-10 years	
	Main Floor Seating	Basement	445	EA	7	10+ years	
	Sound System	Basement	1	EA	7	6-10 years	
	Stage	Basement	839	SF	7	10+ years	
	Stage Curtain	Basement	8	EA	7	6-10 years	
			1	EA	7		
	Stage Lighting System	Basement	-	EA	7 7	6-10 years	
	Stage Lighting System	Basement	2			6-10 years	
	Stage-Stairs - Wood	Basement	8	LF	7	10+ years	
	Stairs - Asphalt	Basement	10	LF	7	10+ years	
	Storage/ Closet	Basement	30	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,306	SF	6	10+ years	



atego	ry : Room		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ymnasi	a						
	Ceiling - Plaster/Drywall	Floor 2.5	3,481	SF	6	10+ years	Updated to match current observations
	Ceiling - Plaster/Drywall	Floor 2.5	20	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Floor 2.5	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Floor 2.5	2	EA	6	10+ years	
	Floor - Tile/Sheet	Floor 2.5	3,501	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	Floor 2.5	20	EA	6	10+ years	
	Walls - Plaster/Drywall	Floor 2.5	2,013	SF	6	10+ years	Updated to match current observations
	Walls - Structural Glazed Tile	Floor 2.5	2,013	SF	6	10+ years	
echani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	64	SF	5	10+ years	
	Storage Room	1st Floor	250	SF	7	10+ years	
	Janitor's Closet	2nd Floor	67	SF	7	10+ years	
	Janitor's Closet	3rd Floor	45	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,630	SF	5	10+ years	
	Storage Room	Basement	123	SF	7	10+ years	
estroor	n						
	Accessories	Women's Auditorium Lobby	123	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Auditorium Lobby	123	SF	5	10+ years	Paint peeling.
	Doors - Wood Doors inclu hw	Women's Auditorium Lobby	1	EA	6	10+ years	· -
	Floor - Tile Ceramic/ Porcelain	Women's Auditorium Lobby	123	SF	7	10+ years	
	Lavatory	Women's Auditorium Lobby	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's Auditorium Lobby	1	EA	7	6-10 years	
	Partitions	Women's Auditorium Lobby	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's Auditorium Lobby	141	SF	7	10+ years	
	Water Closet	Women's Auditorium Lobby	2	EA	7	10+ years	
itego	ry : Classroom		В	uilding	: Additi	on	
				11614		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	m #111 (Art Room)	4.4.51				0.40	
	AC Units	1st Floor	2	EΑ	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	708	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	60	SF	5	1-2 years	Damaged ceiling
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	54	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	819	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	30	SF	5	1-2 years	Cracks in wall
Classroo	om #112 (Art Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
		1st Floor		LF		•	
	Marker Board		24	SF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	849	55	6	10+ years	
Classroc	om #114 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	6	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	768	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	849	SF	6	10+ years	
Classroc	om #115 (Music Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	_ 6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	768	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	-	
				SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor	882	ЭF	6	10+ years	

Campus Name: Talcott Page: 31 of 40 Assessment Date: 07/14/2022



Catego	Category : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #211 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	878	SF	6	10+ years	
Classroo	om #212 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	768	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	878	SF	6	10+ years	
Classroo	om #214 (Office)						
Olassio	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	768	SF	6		
	Doors - Transom Window	2nd Floor 2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
			=		_	10+ years	
	Floor - Wood	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	869	SF	6	10+ years	
Classroo	om #215 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
		2.13 . 1001	14	_, .	•	. o . youro	
	Lighting - Fertuent/Surface	ZIIU FIUUI	14	EA	,	10+ years	



Catego	ory : Classroom		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	878	SF	6	10+ years	
Classro	om #311 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	768	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	26	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	882	SF	6	10+ years	
Classro	om #312 (Science Classroom)						
_ CIGSSI U	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	880	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	80	SF	7	,	
	Walls - Plaster/Drywall	3rd Floor	1,012	SF	6	10+ years 10+ years	
	Work Sink	3rd Floor	1,012	EA	7	10+ years	
						, , , , , ,	
Classro	om #314 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	768	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	899	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	1-2 years	Cracking
Classro	om #315 (Music Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
						•	



Catego	ry : Classroom		В	uilding	: Addition	on	· 3 ·
				3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	768	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	125	SF	7	10+ years	Updated quantity
	Walls - Plaster/Drywall	3rd Floor	882	SF	6	10+ years	opamen quanty
Classroo	om #B13 (Regular Classroom)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	530	SF	6	10+ years	
	Chalk Board	Basement	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood	Basement	530	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	
	Walls - Concrete Block	Basement	153	SF	7	10+ years	
	Walls - Masonry	Basement	305	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	153	SF	7	10+ years	
Classroo	om #B14 (Regular Classroom)						
0.000.00	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	523	SF	6	1-2 years	Damaged ceiling
	Chalk Board	Basement	24	LF	4	2-5 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood Books including	Basement	523	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	
	Storage/ Closet	Basement	24	SF	7	<u>-</u>	
	Walls - Concrete Block		153	SF	7	10+ years	
	Walls - Masonry	Basement		SF SF		10+ years	
	Walls - Masority Walls - Plaster/Drywall	Basement Basement	305 153	SF	7 7	10+ years 10+ years	
Classroo	om #B15 (Regular Classroom)						
CIGSSIUC	AC Units	Basement	1	EA	7	6-10 years	
						,	
	Ceiling - Plaster/Drywall	Basement	564	SF LF	7	10+ years	
	Chalk Board	Basement	24		4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood	Basement	564	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	
	Walls - Concrete Block	Basement	153	SF	7	10+ years	
	Walls - Masonry	Basement	305	SF SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	138	0.	7	10+ years	

Page : 34 of 40 Campus Name: Talcott Assessment Date: 07/14/2022



Building: Addition Category: Classroom

Recommend Location Quantity UOM Rank Comments Group Item - Type Replacement Walls - Plaster/Drywall 1-2 years Damaged wall Basement 15 SF 6

Building : Addition Category : Interior

Catego	ry : Interior		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
<u>Corridor</u>									
	Ceiling - Plaster/Drywall	1st Floor	882	SF	7	10+ years			
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years			
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	6-10 years			
	Floor - Terrazzo	1st Floor	882	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,016	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	882	SF	6	10+ years			
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years			
	Floor - Terrazzo	2nd Floor	441	SF	6	10+ years			
	Floor - Tile/Sheet	2nd Floor	441	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,014	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	882	SF	6	10+ years			
	Doors - Wood Doors include hw	3rd Floor	4	EA	6	10+ years			
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years			
	Floor - Terrazzo	3rd Floor	441	SF	6	10+ years			
	Floor - Tile/Sheet	3rd Floor	441	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	10+ years			
	Student Lockers - Two Tiers	3rd Floor	30	EA	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,014	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement	750	SF	6	10+ years			
	Doors - Wood Doors include hw	Basement	6	EA	7	10+ years			
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years			
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Basement	750	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years			
	Stairs - Concrete Stairs	Basement	5	LF	7	10+ years			
	Walls - Masonry	Basement	900	SF	7	10+ years			
	Walls - Plaster/Drywall	Basement	1,540	SF	7	10+ years			
Ctoiro									
Stairs	Ceiling - Plaster/Drywall	North West	1,182	SF	6	10+ years			
	Floor - Terrazzo	North West	1,182	SF	7	10+ years			
	Handrails	North West	210	LF	7	10+ years			
	Lighting - Pendent/Surface	North West	9	EA	7	6-10 years			
	Stairs - Terrazzo	North West	84	LF	7	10+ years			
	Walls - Plaster/Drywall	North West	1,359	SF	6	•			
	vvalis - Flastel/Drywall	INUITIT VVEST	1,359	SF	O	10+ years			

Page: 35 of 40 Campus Name: Talcott Assessment Date: 07/14/2022



Building: Addition Category : Interior

Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments

Campus Name: Talcott Page : 36 of 40 Assessment Date: 07/14/2022



Category : Site Building : Site

Surface - Synthetic including exc & retention Surface - Synthetic including exc & retention	Location East Courtyard	Quantity	UOM	Rank	Recommend Replacement	Comments
Surface - Synthetic including exc & retention			UOM	Rank	Replacement	Comments
·	East Courtyard					
·	East Courtyard					
·	=	5,050	SF	7	10+ years	Currently torn up, under construction.
Surface - Synthetic including exc & retention						Measurements need to be verified
	East Courtyard	10,850	SF	7	10+ years	New under construction.
						Measurements need to be verified
ighting	East Courtyard	10	EA	6	10+ years	
Surface - Synthetic including exc & retention	East Courtyard	3,555	SF	7	10+ years	Under construction. Measurements
Surface Synthetic including eye & retention	East Courtward	105	QE.	7	10 Lyone	need to be verified Under construction
surface - Synthetic including exc & retention	East Courtyard	105	SF	,	10+ years	Orider construction
100						
	Entire Site	0	ΕΛ	6	10+ years	
2. m. 2. a.m.a.ge			_, ,	Ū	.o. you.o	
encing - Chain Link	Entire Site	445	LF	6	10+ vears	
encing - Chain Link	Entire Site	10	LF			Broken supports
	Entire Site	815	LF	6		
Fencing - Wood Fencing w/ Steel Frame	Entire Site	150	LF	5	1-2 years	Old, broken fence with missing slats
	Entire Site	9	FA	6	10+ years	
						Currently torn up to make room for a
		,			, , , , ,	new amenities
.andscape - Hardscape- Concrete	Entire Site	5,720	SF	6	10+ years	Currently torn up
Parkway trees	Entire Site	17	EA	6	10+ years	
Parkway trees	Entire Site	5	EΑ	4	1-2 years	Missing tree
Planting Beds/ Area	Entire Site	350		6	10+ years	
rash Receptacles	Entire Site	5	EA	6	10+ years	
	Parking Lot- Fast	321	LF	6	10+ years	
				4		Alligatored, potholes, large missing
		., 110		12	. = , 5 5	sections of surface, crumbling with
						depressions
Surface - Concrete	Parking Lot- North	1,650	SF	6	10+ years	
rash Compactor	Parking Lot- North	1	EA	6	10+ years	
rash Enclosure - Chain Links	Parking Lot- North	1,180	SF	6	10+ years	
	encing - New Standard Ornamental encing - Wood Fencing w/ Steel Frame enches andscape - Grass andscape - Hardscape- Concrete arkway trees arkway trees lanting Beds/ Area rash Receptacles concrete Curbs ighting - Pole Mounted urface - Asphalt ehicular Screening urface - Asphalt urface - Concrete rash Compactor	ge ivil/ Drainage - Catch Basin	ge ivil/ Drainage - Catch Basin Entire Site 9 ivil/ Drainage - Site Drain Entire Site 2 ivil/ Drainage - Site Manhole Entire Site 12 encing - Chain Link Entire Site 145 encing - Chain Link Entire Site 160 encing - New Standard Ornamental Entire Site 175 encing - Wood Fencing w/ Steel Frame Entire Site 1750 enches Entire Site 9 andscape - Grass Entire Site 1750 enches Entire Site 9 andscape - Hardscape- Concrete Entire Site 17,720 arkway trees Entire Site 17,720 arkway trees Entire Site 17,7 arkway trees Entire Site 15,847 elanting Beds/ Area Entire Site 15,847 elanting Beds/ Area Entire Site 15,847 elanting - Pole Mounted Parking Lot- East 130 urface - Asphalt Parking Lot- East 130 urface - Asphalt Parking Lot- East 130 urface - Asphalt Parking Lot- North 1,650 rash Compactor Parking Lot- North 1,650 rash Compactor Parking Lot- North 1,650	ge ivil/ Drainage - Catch Basin Entire Site 9 EA ivil/ Drainage - Site Drain Entire Site 2 EA ivil/ Drainage - Site Manhole Entire Site 12 EA encing - Chain Link Entire Site 10 LF encing - Chain Link Entire Site 10 LF encing - New Standard Ornamental Entire Site 815 LF encing - Wood Fencing w/ Steel Frame Entire Site 150 LF enches Entire Site 9 EA andscape - Grass Entire Site 12,050 SF andscape - Hardscape- Concrete Entire Site 17 EA arkway trees Entire Site 17 EA arkway trees Entire Site 5,720 SF arkway trees Entire Site 5 EA Foncrete Curbs 5 EA Foncrete Curbs 6 Entire Site 350 SF rash Receptacles Entire Site 350 SF each Concrete Curbs 7 EA Foncrete Curbs 8 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- East 321 LF Ighting - Pole Mounted 9 Parking Lot- North 4,440 SF Iurface - Concrete 9 Parking Lot- North 4,440 SF	ge Section	Pack

Campus Name: Talcott Page : 37 of 40 Assessment Date: 07/14/2022



Category : Site		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Playgrou	ınd						
	Equipment - Pre K 3-5	East	1	EA	7	10+ years	New, under construction
	Equipment - School Age 5-12	East	1	EA	6	10+ years	
	Equipment - Swingset	East	1	EA	7	10+ years	
	Surface - Poured Surface	East	5,688	SF	6	10+ years	
_Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	96	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	18,375	SF	6	10+ years	Number reflects new sidewalk
	Sidewalks - Perimeter Sidewalks	Entire Site	75	SF	5	1-2 years	Cracks Spalling upheaved
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	6	10+ years	
	Monument - Sign-Lighted	Entire Site	1	EA	6	10+ years	
	- ·					-	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Talcott Page: 38 of 40 Assessment Date: 07/14/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	on coage		110	110	(0.)	700	7 0	0.00	
Computer Lab	Computer Lab	3rd Floor	316	316	750	72	40	N	N
Computer Lab	Regular Classroom	1st Floor	105	105	750	102	55	N	N
Computer Lab	Regular Classroom	2nd Floor	208	208	830	72	40	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	830	154	77	N	Y
Kindergarten	Regular Classroom	1st Floor	109	109	880	88	44	N	Y
Kindergarten	Regular Classroom	1st Floor	110	110	880	182	73	N	Y
Music Room	Store Room	Basement	Basement Music	NA	650	49	20		
Other Instructional Use	Regular Classroom	1st Floor	106	106	750	88	44	N	N
Other Instructional Use	Regular Classroom	1st Floor	116	116	750	72	40	N	Υ
Other Instructional Use	Regular Classroom	2nd Floor	216	216	750	72	40	N	N
Other Instructional Use	Regular Classroom	3rd Floor	306	306	750	72	40	N	N
Play Room	Regular Classroom	1st Floor	107	107	830	88	44	N	Υ
Pre School	Kindergarten	1st Floor	101	101	1,089	102	52	N	Υ
Regular Classroom	Faculty Lounge	Basement	B6		528	49	20	N	N
Regular Classroom	Play Room	Basement	B7	NA	520	21	7	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	830	72	40	N	Υ
Regular Classroom	Regular Classroom	1st Floor	118	118	750	72	40	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	890	84	42	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	830	42	42	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	880	72	40	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	880	108	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	830	72	40	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	830	72	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	890	84	42	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	890	84	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	750	72	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	830	72	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	880	108	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	880	108	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	830	72	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	830	72	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	602	72	40	N	N
Special Education	Regular Classroom	2nd Floor	206	206	750	72	40	N	N
Special Education	Regular Classroom	2nd Floor	207	207	830	72	40	N	Υ
Special Education	Regular Classroom	3rd Floor	307	307	830	72	40	N	Υ
Special Program	Regular Classroom	2nd Floor	205	205	750	72	40	N	N





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Addition		,			\ - <i> </i>				
Art Room	Art Room	1st Floor	111	111	768	143	55	N	N
Art Room	Regular Classroom	1st Floor	112	112	768	165	55	N	N
Music Room	Regular Classroom	1st Floor	115	115	768	165	55	N	N
Music Room	Regular Classroom	3rd Floor	315	315	768	143	55	N	Υ
Office	Regular Classroom	2nd Floor	211	211	768	143	55	N	N
Office	Regular Classroom	2nd Floor	212	212	768	143	55	N	N
Office	Regular Classroom	2nd Floor	214	214	768	143	55	N	N
Office	Regular Classroom	2nd Floor	215	215	768	143	55	N	N
Regular Classroom	Play Room	Basement	B13	NA	530	88	44	N	N
Regular Classroom	Play Room	Basement	B14	NA	523	66	33	N	N
Regular Classroom	Play Room	Basement	B15	NA	564	66	33	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	768	165	55	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	768	143	55	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	768	143	55	N	N
Science Classroom	Science Classroom	3rd Floor	312	312	880	143	55	N	N