

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1969	3	38,482
Linked Addition	1976	1	7,998
Campus Total			46,480

tegor	ry : Exterior			uilding	: Main		
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
rance							
	Entrance Control - Audio and Video	1	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	11	1	EA	6	10+ years	
	Exterior Stairs - Concrete	11	6	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	11	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	2	40	LF	7	10+ years	
	Ramps - Concrete	2	25	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	2.5	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	3	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	4.5	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	5	1	EA	6	10+ years	
	Exterior Doors - Side lite	5	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7	1	EA	6	10+ years	
	Exterior Doors - Side lite	7	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Roof Access Door	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	Roof Access Door	3	LF	6	10+ years	
undatio	on						
	Foundation - Concrete	Entire Building	721	LF	7	10+ years	



Categor	y : Exterior		B	uilding			
Ŭ				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Concrete	Entire Building	38,400	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	82	SF	7	10+ years	
ighting							
	Exterior Lighting - Lighting	Entire Building	5	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Burned through Glass cover
Roof Sys	tem						
,	Access Ladder - Metal	Roof A	1	EA	7	10+ years	
	Coping - Metal	Roof A	475	LF	6	10+ years	
	Coping - Metal	Roof A	5	LF	4	0-1 year	Joint failure/Detaching.
	Downspouts - Interior Downspouts	Roof A	72	LF	6	10+ years	-
	Roof - Asphalt Gravel Ballast	Roof A	6,056	SF	5	2-5 years	Quantity Adjusted
	Roof - Asphalt Gravel Ballast	Roof A	6,040	SF	4	0-1 year	Missing Ballast/Exposed Roofing/Blistering/Bubbling with som ponding - Material deterioration.
	Roof Structure - Concrete	Roof A	12,096	SF	7	10+ years	1 3
	Access Ladder - Metal	Roof B	1	ĒA	7	10+ years	
	Chimney - Metal Flue	Roof B	30	LF	7	10+ years	
	Coping - Metal	Roof B	111	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof B	48	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof B	2,520	SF	5	2-5 years	Quantity Adjusted
	Roof - Asphalt Gravel Ballast	Roof B	2,664	SF	4	0-1 year	Missing Ballast/Exposed Roofing/Blistering/Bubbling with som ponding.
	Roof Structure - Concrete	Roof B	5,184	SF	7	10+ years	
	Coping - Metal	Roof E	255	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof E	12	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof E	2,257	SF	4	1-2 years	Missing Ballast/Exposed Roofing/Blistering/Bubbling/ Material deterioration. Ponding entire roof covered with vegetative growth.
	Roof Hatch - Metal	Roof E	1	EA	7	10+ years	
	Roof Structure - Concrete	Roof E	2,257	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	17,054	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,000	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	30	SF	4	1-2 years	Corner is depleted of mortar in joints/material deterioration.
	Exterior Walls - Brick	Entire Building	20	SF	4	1-2 years	Open/Deteriorating mortar joints
		Entire Building	20	SF	4	1-2 years	Displaced Brick/open and



	ry : Exterior		D	uilding	: wan			
_	,					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
							deteriorated mortar joints	
	Exterior Walls - Brick	Entire Building	3	SF	3	1-2 years	Open mortar joints/cracked	
		3	-	-	-	,	mortar/Spall	
Vindows								
	Guard - Guards perforated	Entire Building	627	SF	6	10+ years		
	Lintels - Steel	Entire Building	800	LF	6	10+ years		
	Lintels - Steel	Entire Building	55	LF	5	2-5 years		
	Windows - Casement Aluminum	Entire Building	1,048	SF	6	10+ years		
	Windows - Decorative	Entire Building	2,484	SF	6	10+ years	None found	
	Windows - Louver	Entire Building	429	SF	6	10+ years		
	Wildows - Louver	Entire Building	429	36	0	TOT years	Deteriorating sealant	
atego	ry : Electrical		В	uilding	: Main			
_	-			_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
merger	cy System							
	Emergency Battery Packs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years		
	Emergency Battery Packs - Gym	1st Floor	2	EA	6	6-10 years	Recently installed	
	Security System - CCTV	Entire Building	38,482	SF	4	2-5 years	Exterior cameras only, require	
			00, 102	•	•	_ 0)00.0	frequent repairs, older	
	Security System - Intrusion Detection	Entire Building	38,482	SF	6	6-10 years	Serves main building	
	Exit Signs - Corridors and Stairs	Entire Building	11	ĒA	5	6-10 years	Glare from lenses causes glare at	
					•	0.0900.0	iPad camera . Building has an AC	
							generator	
	Exit Signs - Gym	Entire Building	5	EA	5	6-10 years	Glare from fixture cover causes gla	
		Entre Dananig	Ũ	-/ (Ũ	e re jeare	at iPad camera. Recently serviced	
							functional. Building has an AC	
							generator	
	Exit Signs - Lunchroom	Entire Building	2	EA	5	6-10 years	Functional. Glare from glass cove	
		Entro Banang	2	L/(U	o ro youro	causes problems for iPad camera.	
							Building has an AC generator	
	Emergency A/C Power - Corridors and	Entire Building	10,006	SF	6	10+ years	Duliding has an AC generator	
	Stairs	Entro Banang	10,000	01	U	ior youro		
	Emergency A/C Power - Gym	Entire Building	4,665	SF	6	10+ years		
	Emergency A/C Power - Lunchrooms	Entire Building	1,665	SF	6	10+ years		
	Emergency A/C Power - Students Toilets	Entire Building	1,287	SF	6	10+ years		
	Automatic Transfer Switch	Office off of Lunch Room	1,207	EA	6	6-10 years	Serves generator	
	Emergency Generator- Outdoor- Diesel -	Site South	1	EA	5	6-10 years	Recently serviced, serves main an	
	Below 60 KW	Sile South		LA	5	0-10 years	addition buildings	
							addition buildings	
/lain Ser	vice							
			1	EA	6		Serves main building only. Origina	



-	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	A 120/208/3PH						1969 installation, functional
	PA System	Entire Building	46,480	SF	6	6-10 years	Does not work well. Requires
							frequent repairs. Connects to addition
							building and main building
-ower D				Ξ.	-	40	E (;) () Z () ()
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years	Functional rated 7 panels have a 10 vears of life
	Lighting and Dower Danala 100 A	Entire Duilding	1		4	0.1.000	Panel is more than 50 years old, trip
	Lighting and Power Panels - 100 A	Entire Building	I	EA	4	0-1 year	frequently
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Deteriorated, frequently trip
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	7	10+ years	1969 installation
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
		Entire Duliding	5	LA	'	TO+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Also serves addition building
	Fire Alarm Strobe Lights	Entire Building	38,482	SF	6	10+ years	
	Fire Alarm_System	Entire Building	38,482	SF	6	10+ years	Connected to addition building
Catego	ry : Mechanical		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond						•	
	Condensing Unit- Roof Mounted - 11-20	Lower Roof	1	EA	5	6-10 years	CU 1, Serves gym, serves AHU 1 in
	tons	2010111001	·	-/ (0	e re jeure	main building
	Condensing Unit- Roof Mounted - 11-20	Lower Roof	1	EA	5	6-10 years	CU 2, Serves cafeteria, serves AHU
	tons			-/ (U	e le jeule	in main building
							5
Air Hand	lling Systems						
Air Hand	lling Systems Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	AHU 1, serves gym
Air Hand		Mechanical Room	1	EA	6	6-10 years	AHU 1, serves gym
Air Hanc	Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	AHU 1, serves gym
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000-	Mechanical Room	1	EA	6	6-10 years 10+ years	AHU 1, serves gym
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm Air Intake	Mechanical Room		EA		10+ years	
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm Air Intake Air Handling Unit- Package Single Zone-		1		6	·	AHU 2, serves cafeteria and kitcher
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm Air Intake Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 8001-	Mechanical Room	1	EA	6	10+ years	
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm Air Intake Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 8001- 12000 cfm	Mechanical Room Mechanical Room AHU-2	1	EA EA	6 6	10+ years 6-10 years	AHU 2, serves cafeteria and kitchen
Air Hanc	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 4000- 8000 cfm Air Intake Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 8001-	Mechanical Room	1	EA	6	10+ years	AHU 2, serves cafeteria and kitche



ALLA .	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PTAC - Electric Heating and Self Contained Cooling	1st Floor	5	EA	6	6-10 years	Serve office areas
	PTAC - Electric Heating and Self Contained Cooling	1st Floor	3	EA	4	1-2 years	Serves offices, requires frequent repairs, older
	Wall Heater - Electric	Entire Building	23	EA	6	6-10 years	• *
	Wall Heater - Electric	Entire Building	5	EA	4	1-2 years	Deteriorated, not reliable, older
empera	ature Control						
	DDC System	Entire Building	38,482	SF	4	1-2 years	Partially operating. 1/2 of the controlled items are manually controlled, software not upgraded
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves fan, previously not assessed
	Thermostats - DDC	Entire Building	5	EA	6	6-10 years	Functional
	Thermostats - DDC	Entire Building	5	EA	4	1-2 years	Not calibrated, bad signal
Jnit Ver	tilation						
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	22	EA	5	6-10 years	With internal thermostats
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	5	EA	4	1-2 years	Require frequent repairs, not reliab
/entilation	วท						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof	1	EA	2	0-1 year	No fire suppression equipment
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	5	6-10 years	Served dishwasher. Dishwasher w removed

Catego	Category : Plumbing		E	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	4	1-2 years	Serve the main building, 2004 installation, old, not reliable



							409 W 80th STREET, Chicago, IL 6062	
Catego	ry : Plumbing		В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Piping	Domastic Dining Hat Water Daturn Linco	Entire Building	20,402	SF	6	10, , , , , , , , , , , , , , , , , , ,	Nalaska	
	Domestic Piping-Hot Water Return Lines	Entire Building	38,482	SF	6	10+ years	No leaks	
	Domestic Piping-Hot Water Return Risers	Entire Building	38,482			10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	38,482	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	38,482	SF	6	10+ years	1969 installation	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	38,482	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	38,482	SF	6	10+ years	Connect to addition building	
	Sanitary Piping	Entire Building	38,482	SF	6	10+ years	1969 installation	
	Storm Piping	Entire Building	38,482	SF	6	10+ years		
	Vent Piping	Entire Building	38,482	SF	6	10+ years		
oumps								
·	Pumps - Domestic Booster Pump-Simplex	1st Floor	1	EA	6	10+ years	Serves both main and addition buildings	

Administrative Suites/OfficesCeiling - Lay-in200 - Counselor Office232SF610+ yearsDoors - Wood Doors inclu hw200 - Counselor Office1EA610+ yearsFloor - Tile200 - Counselor Office232SF610+ yearsLighting - Lay-in200 - Counselor Office2EA66-10 yearsPower Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ years	
Ceiling - Lay-in200 - Counselor Office232SF610+ yearsDoors - Wood Doors inclu hw200 - Counselor Office1EA610+ yearsFloor - Tile200 - Counselor Office232SF610+ yearsLighting - Lay-in200 - Counselor Office2EA66-10 yearsPower Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	Comments
Doors - Wood Doors inclu hw200 - Counselor Office1EA610+ yearsFloor - Tile200 - Counselor Office232SF610+ yearsLighting - Lay-in200 - Counselor Office2EA66-10 yearsPower Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Doors - Wood Doors inclu hw200 - Counselor Office1EA610+ yearsFloor - Tile200 - Counselor Office232SF610+ yearsLighting - Lay-in200 - Counselor Office2EA66-10 yearsPower Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Lighting - Lay-in200 - Counselor Office2EA66-10 yearsPower Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Power Distribution200 - Counselor Office4EA610+ yearsWalls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Walls - Concrete Block200 - Counselor Office493SF610+ yearsWalls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Walls - Structural Glazed Tile200 - Counselor Office45SF710+ yearsCeiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Ceiling - Lay-in300 Office APR Coordinator232SF610+ yearsDoors - Wood Doors inclu hw300 Office APR Coordinator1EA610+ years	
Doors - Wood Doors inclu hw 300 Office APR Coordinator 1 EA 6 10+ years	
Floor - Tile 300 Office APR Coordinator 232 SF 6 10+ years	
Lighting - Lay-in 300 Office APR Coordinator 2 EA 6 6-10 years	
Power Distribution 300 Office APR Coordinator 4 EA 6 10+ years	
Walls - Concrete Block 300 Office APR Coordinator 493 SF 6 10+ years	
Walls - Structural Glazed Tile300 Office APR Coordinator45SF710+ years	
Ceiling - Lay-in Assistant Principal Office 235 SF 6 10+ years	
Doors - Wood Doors inclu hw Assistant Principal Office 1 EA 6 10+ years	
Doors - Wood Doors inclu hw Assistant Principal Office 1 EA 6 10+ years	
Floor - Carpet Assistant Principal Office 235 SF 6 6-10 years	
Lighting - Lay-in Assistant Principal Office 3 EA 6 6-10 years	
Power Distribution Assistant Principal Office 4 EA 6 10+ years	



<u> </u>	ory : Room		R	uilding	· Main		409 W 80th STREET, Chicago, IL 60620
Ualcyc				unung	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Storage/ Closet	Assistant Principal Office	12	SF	7	10+ years	
	Walls - Concrete Block	Assistant Principal Office	493	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	ĒA	6	10+ years	
	Floor - Tile	Engineer's Office	65	SF	6	10+ years	
	Lighting - Lay-in	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	4	EA	7	10+ years	
	Walls - Concrete Block	Engineer's Office	130	SF	7	10+ years	
	Ceiling - Lay-in	Faculty Room - 1st Floor	253	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Room - 1st Floor	3	EA	6	10+ years	
	Floor - Tile	Faculty Room - 1st Floor	253	SF	6	10+ years	
	Lighting - Lay-in	Faculty Room - 1st Floor	4	EA	7	6-10 years	
	Power Distribution	Faculty Room - 1st Floor	6	EA	7	10+ years	
	Storage/ Closet	Faculty Room - 1st Floor	85	SF	7	10+ years	
	Walls - Concrete Block	Faculty Room - 1st Floor	430	SF	7	10+ years	
	Walls - Structural Glazed Tile	Faculty Room - 1st Floor	50	SF	7	10+ years	
	Ceiling - Lay-in	Gym Office	97	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	97	SF	7	10+ years	
	Lighting - Lay-in	Gym Office	1	EA	7	6-10 years	
	Power Distribution	Gym Office	4	EA	7	10+ years	
	Storage/ Closet	Gym Office	32	SF	7	10+ years	
	Walls - Concrete Block	Gym Office	268	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	76	SF	6	10+ years	
	Doors - Side-lite	Kitchen Office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	7	10+ years	
	Floor - Tile	Kitchen Office	76	SF	6	10+ years	
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Office	160	SF	6	10+ years	
	Ceiling - Lay-in	Library Office 2nd Floor	164	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Library Office 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Library Office 2nd Floor	164	SF	6	10+ years	
	Lighting - Lay-in	Library Office 2nd Floor	2	EA	6	6-10 years	
	Power Distribution	Library Office 2nd Floor	4	EA	6	10+ years	
	Walls - Concrete Block	Library Office 2nd Floor	206	SF	6	10+ years	
	Ceiling - Lay-in	Main Office 1st Floor	507	SF EA	6 7	10+ years	
	Doors - Wood Doors inclu hw	Main Office 1st Floor	2	SF		10+ years	
	Floor - Carpet	Main Office 1st Floor Main Office 1st Floor	507	EA	6 7	6-10 years	
	Lighting - Lay-in Power Distribution		10	EA EA		6-10 years	
	Storage/ Closet	Main Office 1st Floor Main Office 1st Floor	10 126	SF	7 7	10+ years	
		Main Office 1st Floor	822	SF	7	10+ years	
	Walls - Concrete Block	Main Onice 1St FIOOI	022	SF	1	10+ years	



Catego	ry : Room		B	uilding	: Main		
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	Main Office 1st Floor	125	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	289	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office	289	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office	4	EA	7	6-10 years	
	Power Distribution	Principal's Office	4	EA	7	10+ years	
	Storage/ Closet	Principal's Office	12	SF	7	10+ years	
	Walls - Concrete Block	Principal's Office	276	SF	7	10+ years	
	Ceiling - Lay-in	Safe Passage Office (in Lunchroom)	193	SF	6	10+ years	
	Doors - Side-lite	Safe Passage Office (in Lunchroom)	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Safe Passage Office (in Lunchroom)	10	EA	7	10+ years	
	Floor - Tile	Safe Passage Office (in Lunchroom)	193	SF	6	10+ years	
	Lighting - Lay-in	Safe Passage Office (in Lunchroom)	2	EA	7	6-10 years	
	Power Distribution	Safe Passage Office (in Lunchroom)	2	EA	7	10+ years	
	Walls - Concrete Block	Safe Passage Office (in Lunchroom)	423	SF	7	,	
	Walls - Concrete block	Sale Fassage Office (In Euroffioon)	423	35	1	10+ years	
Symnasi							
	Ceiling - Lay-in	1st Floor	4,650	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	15	SF	4	0-1 year	Broken ceiling tiles
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Floor - Concrete	1st Floor	48	SF	7	10+ years	
	Floor - Tile	1st Floor	3,921	SF	6	10+ years	
	Floor - Wood	1st Floor	696	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	696	SF	7	10+ years	
	Stage Curtain	1st Floor	3	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	35	LF	7	10+ years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6,333	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	350	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	983	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	25	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,023	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	



atego	ry : Room		B	uilding			
alege	.,		_	anang	i ingini	Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	1,227	SF	7	10+ years	
			,	-		-)	
brary							
-	Casework	207/209 Library	127	LF	6	10+ years	
	Ceiling - Lay-in	207/209 Library	1,807	SF	6	10+ years	
	Doors - Wood Doors inclu hw	207/209 Library	3	EA	6	10+ years	
	Floor - Carpet	207/209 Library	1,807	SF	6	6-10 years	
	Lighting - Lay-in	207/209 Library	30	EA	6	6-10 years	
	Walls - Concrete Block	207/209 Library	1,306	SF	7	10+ years	
okor/C	Shower Room						
ckel/S	Accessories	1st Floor	236	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	236	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	230	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	236	SF	7		
	Floor Drain	1st Floor	230	EA	7	10+ years 10+ years	
						•	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Showers	1st Floor	5	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor	52	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	472	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	Kitchen Staff	101	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen Staff	101	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Staff	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen Staff	19	SF	7	10+ years	
	Floor - Tile/Sheet	Kitchen Staff	82	SF	7	10+ years	
	Lavatory	Kitchen Staff	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Staff	2	EA	7	6-10 years	
	Student Lockers - One Tier	Kitchen Staff	12	EA	6	6-10 years	
	Walls - Concrete Block	Kitchen Staff	202	SF	7	10+ years	
	Water Closet	Kitchen Staff	1	EA	7	10+ years	
inch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,665	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	1,665	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,126	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor	205	SF	7	•	
	wais - Structural Glazed The	151 FIUUI	205	SF	1	10+ years	



							409 W 80th STREET, Chicago, IL 60620
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd in library	1	EA	6	10+ years	
	Finishes	2nd in library	210	SF	7	10+ years	
	Other Cooling Unit	2nd in library	1	EA	7	6-10 years	PTAC
	Ũ	-					
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	35	SF	7	10+ years	
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	150	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	45	SF	7	10+ years	
	Storage Room	1st Floor	350	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	5	10+ years	Water damaged ceiling.
	Janitor's Closet	2nd Floor	35	SF	5	10+ years	Ceiling needs patch.
	Mechanical/ Service Rooms	2nd Floor	1,868	SF	7	10+ years	Coming needs paton.
	Janitor's Closet	3rd Floor	35	SF	7	10+ years	
			00	01	,	lot youro	
Restroor	n						
	Accessories	104A	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104A	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	104A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	104A	26	SF	7	10+ years	
	Lavatory	104A		EA	7	10+ years	
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years	
	Walls - Concrete Block	104A	53	SF	7	10+ years	
	Water Closet	104A	1	EA	7	10+ years	
	Accessories	106A	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	106A	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106A	_==	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	106A	26	SF	7	10+ years	
	Lavatory	106A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	106A	1	EA	7	6-10 years	
	Walls - Concrete Block	106A	53	SF	7	10+ years	
	Water Closet	106A	1	EA	7	10+ years	
	Accessories	Boys 1st Floor	247	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 1st Floor	247	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys 1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 1st Floor	247	SF	7	10+ years	
	Floor Drain	Boys 1st Floor	247	EA	7	10+ years	
	Lavatory	Boys 1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys 1st Floor	4	EA	7	6-10 years	
	Partitions	Boys 1st Floor	4	EA	7	•	
	Urinals	Boys 1st Floor	2 3	EA	7	10+ years	
	Walls - Concrete Block	Boys 1st Floor Boys 1st Floor	3 566	SF	7	10+ years	
			2	EA	6	10+ years	
	Water Closet	Boys 1st Floor	2	EA	o	10+ years	



Catarra	Category : Room Building : Main									
Catego	ry : Room		В	unaing	: wain	December				
Crown	Hom Tuno	Location	Quantitu	UOM	Donk	Recommend	Commente			
Group	Item - Type Accessories	Boys 2nd Floor	Quantity	UOM SF	Rank 7	Replacement 6-10 years	Comments			
	Ceiling - Plaster/Drywall	Boys 2nd Floor	247 247	SF	6					
			247		-	10+ years				
	Doors - Wood Doors inclu hw	Boys 2nd Floor	-	EA SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 2nd Floor	247		6 7	10+ years				
	Floor Drain	Boys 2nd Floor	1	EA		10+ years				
	Lavatory	Boys 2nd Floor	2	EA	6	10+ years				
	Lighting - Pendent/Surface	Boys 2nd Floor	4	EA	6	6-10 years				
	Partitions	Boys 2nd Floor	2	EA	7	10+ years				
	Urinals	Boys 2nd Floor	3	EA	6	10+ years				
	Walls - Concrete Block	Boys 2nd Floor	561	SF	7	10+ years				
	Walls - Concrete Block	Boys 2nd Floor	5	SF	5	0-1 year	Damaged cmu			
	Water Closet	Boys 2nd Floor	2	EA	6	10+ years				
	Accessories	Boys 3rd Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Boys 3rd Floor	247	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Boys 3rd Floor	4	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boys 3rd Floor	247	SF	6	10+ years				
	Floor Drain	Boys 3rd Floor	1	EA	7	10+ years				
	Lavatory	Boys 3rd Floor	2	EA	6	10+ years				
	Lighting - Pendent/Surface	Boys 3rd Floor	4	EA	6	6-10 years				
	Partitions	Boys 3rd Floor	2	EA	7	10+ years				
	Urinals	Boys 3rd Floor	3	EA	6	10+ years				
	Walls - Concrete Block	Boys 3rd Floor	566	SF	7	10+ years				
	Water Closet	Boys 3rd Floor	2	EA	6	10+ years				
	Accessories	Engineer's Office	25	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Engineer's Office	25	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Engineer's Office	25	SF	7	10+ years				
	Lavatory	Engineer's Office	1	EA	5	0-1 year	Leaking faucet			
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years				
	Walls - Concrete Block	Engineer's Office	47	SF	7	10+ years				
	Water Closet	Engineer's Office	1	EA	7	10+ years				
	Accessories	Girls - 1st Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Girls - 1st Floor	247	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Girls - 1st Floor	4	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Girls - 1st Floor	247	SF	7	10+ years				
	Floor Drain	Girls - 1st Floor	1	EA	7	10+ years				
	Lavatory	Girls - 1st Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	Girls - 1st Floor	4	EA	7	6-10 years				
	Partitions	Girls - 1st Floor	5	EA	7	10+ years				
	Walls - Concrete Block	Girls - 1st Floor	566	SF	7	10+ years				
	Water Closet	Girls - 1st Floor	5	EA	7	10+ years				
	Accessories	Girls - 2nd Floor	247	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Girls - 2nd Floor	247	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Girls - 2nd Floor	4	EA	6	10+ years				



Catego	ry : Room		D	uilding	·Main		409 W 80th STREET, Chicago, IL 60620
Calego	ry . Room		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Floor - Tile Ceramic/ Porcelain	Girls - 2nd Floor	244	SF	6	10+ years	Comments
	Floor - Tile Ceramic/ Porcelain	Girls - 2nd Floor	3	SF	4	1-2 years	Missing tiles
	Floor Drain	Girls - 2nd Floor	1	EA	7	10+ years	
	Lavatory	Girls - 2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls - 2nd Floor	4	EA	6	6-10 years	
	Partitions	Girls - 2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	Girls - 2nd Floor	566	SF	7	10+ years	
	Water Closet	Girls - 2nd Floor	5	EA	6	10+ years	
	Accessories	Girls - 3rd Floor	247	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls - 3rd Floor	247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls - 3rd Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls - 3rd Floor	247	SF	6	10+ years	
	Floor Drain	Girls - 3rd Floor	- 1	EA	7	10+ years	
	Lavatory	Girls - 3rd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls - 3rd Floor	4	EA	6	6-10 years	
	Partitions	Girls - 3rd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	Girls - 3rd Floor	566	SF	6	10+ years	
	Water Closet	Girls - 3rd Floor	5	EA	6	10+ years	
	Accessories	Gym Office	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Office	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym Office	25	SF	7	10+ years	
	Lavatory	Gym Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Gym Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Gym Office	47	SF	7	10+ years	
	Water Closet	Gym Office		ĒA	7	10+ years	
	Accessories	Main Office Restroom	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Restroom	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Restroom		EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office Restroom	32	SF	7	10+ years	
	Lavatory	Main Office Restroom		ĒA	7	10+ years	
	Lighting - Pendent/Surface	Main Office Restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	Main Office Restroom	72	SF	7	10+ years	
	Water Closet	Main Office Restroom	1	ĒA	7	10+ years	
	Accessories	Men's Staff 1st Floor	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Staff 1st Floor	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men's Staff 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Staff 1st Floor	28	SF	7	10+ years	
	Lavatory	Men's Staff 1st Floor	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	Men's Staff 1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	Men's Staff 1st Floor	55	SF	7	10+ years	
	Water Closet	Men's Staff 1st Floor	1	EA	7	10+ years	
	Accessories	Staff 2nd Floor	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff 2nd Floor	36	SF	6	10+ years	
	5 ·····				-	,	



Catego	ry : Room		Building : Main							
				-		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors inclu hw	Staff 2nd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Staff 2nd Floor	36	SF	6	10+ years				
	Lavatory	Staff 2nd Floor	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Staff 2nd Floor	1	EA	6	6-10 years				
	Partitions	Staff 2nd Floor	1	EA	7	10+ years				
	Walls - Concrete Block	Staff 2nd Floor	93	SF	7	10+ years				
	Water Closet	Staff 2nd Floor	1	EA	6	10+ years				
	Accessories	Staff 3rd Floor	36	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Staff 3rd Floor	36	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Staff 3rd Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Staff 3rd Floor	36	SF	6	10+ years				
	Lavatory	Staff 3rd Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Staff 3rd Floor	1	EA	6	6-10 years				
	Partitions	Staff 3rd Floor	1	EA	7	10+ years				
	Walls - Concrete Block	Staff 3rd Floor	93	SF	7	10+ years				
	Water Closet	Staff 3rd Floor	1	EA	6	10+ years				
	Accessories	Women's Staff 1st Floor	28	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Women's Staff 1st Floor	28	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Women's Staff 1st Floor	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Women's Staff 1st Floor	28	SF	7	10+ years				
	Lavatory	Women's Staff 1st Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Women's Staff 1st Floor	1	EA	7	6-10 years				
	Walls - Concrete Block	Women's Staff 1st Floor	55	SF	7	10+ years				
	Water Closet	Women's Staff 1st Floor	1	EA	7	10+ years				

Category : Classroom

Building : Main

	· · · · · · · · ·			. J			
Crown	Hom Tune	Lesstien	Quantity		Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Classroo</u>	om #101 (Faculty Lounge)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	700	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	785	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	114	SF	7	10+ years	
Classroo	om #102 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	700	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	785	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	114	SF	7	10+ years	
	Work Sink	1st Floor	1	ËA	7	10+ years	
Classroo	m #104 (Pre School)						
	Casework	1st Floor	17	LF	6	10+ years	
	Casework	1st Floor	21	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,027	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,027	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	94	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	914	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	175	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #106 (Pre School)						
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,027	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,027	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	914	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	145	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	Casework	1st Floor	27	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	725	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	725	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	662	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	198	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	114	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		409 W 8001 STREET, Chicago, ie 60020
culogo			_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	796	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	796	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	860	SF	6	10+ years	
Classroo	m #203 (Regular Classroom)						
	Casework	2nd Floor	27	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	725	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	6	10+ years	
Classroo	m #204/206 (Regular Classroom)						
	Casework	2nd Floor	59	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,513	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	. 8	SF	4	1-2 years	Damaged ceiling tile
	Chalk Board	2nd Floor	12	LF	4	2-5 years	5 5
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,521	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,324	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	396	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	140	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #205 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	725	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
					-	,	



)	Schools						409 W 80th STREET, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
		·	• • • •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	om #208/210 (Regular Classroom)						
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,193	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,118	SF	6	10+ years	
	Floor - Tile	2nd Floor	75	SF	4	0-1 year	Damaged tiles
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	5
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,066	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	140	SF	7	10+ years	
	Work Sink	2nd Floor	1	ĒA	7	10+ years	
Classroo	om #212 (Store Room)			. –			
	Casework	2nd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	701	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Damaged ceiling tiles
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	114	SF	7	10+ years	
lassroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	ĒA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
		01011001	114	0	,	ioi youio	



Oliver S Westcott Elementary School 409 W 80th STREET, Chicago, IL 60620

Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #302 (Regular Classroom)						
	Casework	3rd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Classroc	om #303 (Regular Classroom)						
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Classroc	om #304 (Regular Classroom)	- · -					
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #305 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	gig _a, iii		10	-/ \	U U		



Category : Classroom		B	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	662	SF	6	10+ years	
	Walls - Metal Panel	3rd Floor	198	SF	6		
	Walls - Metal Faller Walls - Structural Glazed Tile	3rd Floor		SF	6	10+ years	
	Wais - Structural Glazed The	310 1001	100	55	0	10+ years	
Classroo	om #307 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
Classroo	om #308 (Regular Classroom)						
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	10	ĒA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	96	SF	7	10+ years	
Classroo	om #309 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	725	SF	6	-	
	Lighting - Lay-in	3rd Floor	10	EA	6	10+ years	
					6 7	6-10 years	
	Marker Board	3rd Floor	12	LF	1	6-10 years	



	SCI IOOIS						409 W 80th STREET, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	7	10+ years	
lassroo	m #310 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	453	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	453	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	7	ĒA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	327	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	70	SF	6	10+ years	
	Work Sink	3rd Floor	78	EA	7	10+ years	
	Work Sink	510 1 1001	I	LA	,	TOF years	
lassroo	m #311 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	6	10+ years	
lassroo	m #312 (Regular Classroom)						
	Casework	3rd Floor	17	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	860	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	114	SF	6	10+ years	
		310 11001	114	эг	0	TU+ years	
atego	ry : Interior		В	uilding	: Main	Decemany	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,304	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	



	Schools						409 W 80th STREET, Chicago, IL 60620
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	112	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,172	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	0-1 year	Cracked Tiles
	Lighting - Lay-in	1st Floor	23	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,792	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,722	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	1	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,722	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	2,240	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,678	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	1	EA	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,678	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	2,182	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Metal Dedector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	East	350	SF	7	10+ years	
	Ceiling - Plaster/Drywall	East	150	SF	7	10+ years	
	Floor - Terrazzo	East	416	SF	7	10+ years	
	Floor - Tile	East	712	SF	7	10+ years	
	Handrails	East	112	LF	7	10+ years	
	Lighting - Lay-in	East	10	EA	7	6-10 years	
	Lighting - Wall Mounted	East	8	EA	7	6-10 years	
	Stairs - Terrazzo	East	314	LF	7	10+ years	
	Stairs - Tile	East	204	LF	7	10+ years	
	Walls - Concrete Block	East	3,584	SF	7	10+ years	
	Ceiling - Lay-in	West	1,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	150	SF	6	10+ years	
	Floor - Terrazzo	West	416	SF	6	10+ years	
	Floor - Tile	West	712	SF	6	10+ years	
	Handrails	West	112	LF	7	10+ years	



Catego	ry : Interior	B	uilding				
outoge			anang				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	West	10	EA	6	6-10 years	
	Lighting - Wall Mounted	West	8	EA	6	6-10 years	
	Stairs - Terrazzo	West	314	LF	6	10+ years	
	Stairs - Tile	West	204	LF	6	10+ years	
	Walls - Concrete Block	West	3,584	SF	6	10+ years	



Category : Exterior			В	uilding	: Linked	Addition Recommend		
O	How Two	Location	Quantitu	Quantity UOM Rank			Commonto	
Group	Item - Type	Location	Quantity	UUIVI	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Exterior Steel Door	10	2	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	10	1	EA	4	0-1 year	Damaged Door sweep/Rust presen	
	Exterior Doors - Exterior Steel Door	8	3	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	9	2	EA	6	6-10 years		
Foundat	ion							
	Foundation - Concrete	Entire Building	392	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	7,998	SF	7	10+ years		
Lighting								
0 0	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years		
Roof Sys	stem							
	Coping - Metal	Roof C	104	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof C	44	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof C	104	LF	6	10+ years		
	Roof - Modified Bitumen	Roof C	1,014	SF	4	0-1 year	Open Seams/Soft spots/Detachmer from substrate.	
	Roof Structure - Steel / Metal Deck/	Roof C	1,014	SF	7	10+ years	nom substrate.	
	Concrete Topping							
	Chimney - Metal Flue	Roof D	15	LF	6	10+ years		
	Coping - Metal	Roof D	312	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof D	56	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Roof D	312	LF	7	10+ years		
	Parapet - Parapet > 30"	Roof D	45	LF	7	10+ years		
	Roof - Modified Bitumen	Roof D	6,884	SF	5	2-5 years		
	Roof - Modified Bitumen	Roof D	100	SF	4	0-1 year	Open seams/soft spots/Detachmen from substrate.	
	Roof Structure - Concrete	Roof D	6,984	SF	7	10+ years		
Walls								
	Exterior Walls - Brick	Entire Building	4,838	SF	7	10+ years		
	Exterior Walls - Brick	Entire Building	200	SF	6	10+ years	Repaired.	
Windows	3							
	Guard - Guards perforated	Entire Building	480	SF	7	10+ years		
	Lintels - Steel	Entire Building	96	LF	7	10+ years		
	Lintels - Steel	Entire Building	6	LF	5	2-5 years		
	Windows - Casement Aluminum Double-	Entire Building	480	SF	6	10+ years		
	pane	g	100	•	-	,		



Oliver S Westcott Elementary School

	Schools						409 W 80th STREET, Chicago, IL 6062
Catego	ry : Exterior		В	uilding	: Linked	Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
` atoro	ry : Electrical		В	uilding	·Linkor	Addition	
Jaleyo			U	unung	. LIIIKEU	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System						
merger	Security System - CCTV	1st Floor	7.998	SF	5	6-10 years	Exterior cameras only, requiring
	Security System - OOTV	13(1100)	7,550	01	5		occasional repairs, recently service
	Security System - Intrusion Detection	1st Floor	7,998	SF	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	5	6-10 years	Glare causes iPad to take distorted
	Ũ	C C					photo. Building served by an AC
							generator
	Emergency Battery Packs - Corridors and	Entire Building	5	EA	6	6-10 years	
	Stairs						
Main Sei	Nice						
	PA System	1st Floor	7,998	SF	4	2-5 years	Connected to main building. Requi
			,			,	frequent repairs
	Main Electrical Service - 800 A and	Outside - South Facade	1	EA	6	10+ years	Serves addition only, ComEd feed
	120/240/3PH					-	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	10+ years	1976 installation
						-	
Catego	ry : Fire Protection		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity		Rank	Replacement	Comments
ire Alar		1st Floor	7,998	SF	0	10	
	Fire Alarm Strobe Lights Fire Alarm_System	1st Floor	7,998	SF	6 6	10+ years 10+ years	Connected to main building
	File Alarin_System	ISt FIOO	7,990	3F	0	TO+ years	Connected to main building
Sprinkler	- System						
phinklei	Sprinkler Heads	1st Floor	7,998	SF	7	10+ years	
	Sprinkler Piping	1st Floor	7,998	SF	6	10+ years	
	Wet Sprinkler System	1st Floor	7,998	SF	6	10+ years	Serves addition building only, using
			.,	-	-	, see geene	city water pressure, 1976 installation
Set = <i>m</i> = 1	w. Machanical		Р				
Jatego	ry : Mechanical		В	unaing	: LINKec	Addition Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
			Quantity		Nank	Replacement	Commenta
leaung	Devices Wall Heater - Electric	Entire Building	3	EA	5	6-10 years	1976 installation
		Entrie Dananig	5		U	5 10 90010	



Oliver S Westcott Elementary School 409 W 80th STREET, Chicago, IL 60620

Catego	ry : Mechanical	В					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	Electric Controls	Entire Building	7,998	SF	5	6-10 years	No DDC system, no pneumatic system. Only electrical system, 6 for univents
	Electric Thermostat	Entire Building	6	EA	5	6-10 years	Serve 6 exterior univents
Unit Ven	tilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Facade	6	EA	5	6-10 years	Occasionally repaired
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	6	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Linked	d Addition	
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		2: 2					•
	Electric Heater - Less than 20 KW	Store Room	1	EA	5	6-10 years	Serves kitchen
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	7,998	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	7,998	SF	6	10+ years	1976 installation, no leaks
	Sanitary Piping	Entire Building	7,998	SF	6	10+ years	
	Storm Piping	Entire Building	7,998	SF	6	10+ years	
	Vent Piping	Entire Building	7,998	SF	6	10+ years	
Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #111 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #112 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	



	CHOOIS						409 W 80th STREET, Chicago, IL 6062
Category : Classroom			В	uilding	: Linked	d Addition	
_				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Storage/ Closet	1st Floor	73	SF	5	10+ years	Water damaged ceiling tiles.
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	m #113 (Regular Classroom)						
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	786	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	-
	Floor - Tile	1st Floor	790	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroo	m #114 (Store Room)						
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	790	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroo	m #115 (Office)						
	Ceiling - Lay-in	1st Floor	778	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	5
	Floor - Tile	1st Floor	790	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	791	SF	7	10+ years	
lassroo	m #116 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	782	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Water damage tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	0



Category : Classroom

Building : Linked Addition

Recommend

Location Group Item - Type Quantity UOM Rank **Replacement** Comments Floor - Tile 1st Floor 790 SF 10+ vears 7 Lighting - Lay-in 1st Floor ΕA 7 6-10 vears 16 Marker Board 1st Floor 12 LF 7 6-10 years Walls - Plaster/Drywall SF 1st Floor 791 7 10+ years Category : Room **Building : Linked Addition** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group MDF IDF Doors - Wood Doors inclu hw Room 111 1 ΕA 7 10+ years SF 7 Finishes Room 111 84 6-10 years Other Cooling Unit Room 111 1 EΑ 7 6-10 years Ceiling vent Mechanical/ Service Rooms SF 7 Janitor's Closet 1st Floor 51 10+ years Restroom Accessories Men's 1st Floor 167 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 Men's 1st Floor 167 10+ years Doors - Wood Doors inclu hw Men's 1st Floor 1 ΕA 7 10+ years 167 SF 7 Floor - Tile Ceramic/ Porcelain Men's 1st Floor 10+ years Floor Drain 7 Men's 1st Floor 1 EΑ 10+ years Hand Dryer Men's 1st Floor 1 FΑ 7 6-10 years Lavatory Men's 1st Floor 2 FΑ 7 10+ years Lighting - Pendent/Surface Men's 1st Floor EΑ 7 6-10 years 1 Partitions Men's 1st Floor 2 EΑ 7 10+ vears Urinals Men's 1st Floor 2 EΑ 7 10+ years Walls - Metal Panel 420 SF 7 10+ years Men's 1st Floor Water Closet 2 ΕA 7 Men's 1st Floor 10+ years SF 7 6-10 years Accessories Women's 1st Floor 185 Ceiling - Plaster/Drywall Women's 1st Floor 185 SF 7 10+ years Doors - Wood Doors inclu hw Women's 1st Floor 1 FΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain 185 7 Women's 1st Floor 10+ years ΕA Floor Drain Women's 1st Floor 7 10+ vears 1 Hand Dryer Women's 1st Floor 1 EΑ 7 6-10 years Lavatory Women's 1st Floor 2 ΕA 7 10+ years Lighting - Pendent/Surface 2 Women's 1st Floor EΑ 7 6-10 years Partitions Women's 1st Floor ΕA 7 4 10+ years SF Walls - Metal Panel Women's 1st Floor 443 7 10+ years Water Closet Women's 1st Floor ΕA 7 4 10+ years **Category : Interior Building : Linked Addition** Item - Type Group Location Quantity UOM Rank Recommend Comments



409 W 80th STREET, Chicago, IL 60620 Replacement Corridor Ceiling - Lay-in Corridors & Vestibules 1,643 SF 7 10+ years Doors - Steel Doors incl hw 10+ years **Corridors & Vestibules** 6 ΕA 7 Doors - Wood Doors include hw 2 ΕA 7 10+ years **Corridors & Vestibules** Drinking Fountains - Single Water Cooler 10+ years **Corridors & Vestibules** 2 ΕA 7 Floor - Tile/Sheet **Corridors & Vestibules** 1,623 SF 7 10+ years SF 1-2 years Floor - Tile/Sheet **Corridors & Vestibules** 20 4 Cracks in the floor ΕA 7 6-10 years Lighting - Lay-in **Corridors & Vestibules** 19 Walls - Plaster/Drywall Corridors & Vestibules 2,396 SF 7 10+ years



Category : Site			В	uilding	: Site		
				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Natural	South Site	41,680	SF	6	6-10 years	
	Surface - Asphalt	South Site	13,720	SF	4	0-1 year	Uneven/Broken/Cracked, and
							vegetative growth.
	Surface - Asphalt	South Site	10,682	SF	4	0-1 year	Broken/Cracked w/Vegetative grow
Civil/Dra	inage						
	Civil/ Drainage - Bioswale	Entire Site	3	SF	7	10+ years	
	Civil/ Drainage - Bioswale	Entire Site	3	SF	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
encing							
	Fencing - Chain Link	Entire Site	684	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	12	LF	4	0-1 year	Missing/curling.
	Fencing - New Standard Ornamental	Entire Site	132	LF	7	10+ years	5 5
	Fencing - New Standard Ornamental	Entire Site	132	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	2,167	LF	6	10+ years	
_andsca	pe						
	Benches	Entire Site	10	EA	6	10+ years	
	Landscape - Grass	Entire Site	107,585	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	400	SF	4	0-1 year	Material deterioration.
				0.	•	e i jeu.	Broken/Cracked/Missing.
	Landscape - Hardscape- Concrete	Entire Site	3,635	SF	7	10+ years	g.
	Landscape - Hardscape- Concrete	Entire Site	5,400	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	63	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	5	2-5 years	Quantity Adjusted: Prune
		Entire One	0		0	2 0 yours	trees/Overhang on Roof.
	Parkway trees	Entire Site	3	EA	4	0-1 year	Missing tree/Heaving concrete
	Planting Beds/ Area	Entire Site	810	SF	6	10+ years	surround -Trees overgrown on Roc
	Play Area - Hardscape- Asphalt	Entire Site	2,280	SF	7	10+ years	
	Trash Receptacles	Entire Site	2,200	EA	6	10+ years	Quantity adjusted.
	Walking Path - Hardscape- Asphalt	Entire Site	200	SF	7	10+ years	Quantity aujusteu.
Parking	l ot						
акпа	Concrete Curbs	Parking Lot- West	757	LF	7	10+ years	
	Interior Plantings	Parking Lot- West	308	LF		10+ years	
			308 4	LF EA	6 6		
	Lighting - Pole Mounted	Parking Lot- West	4	EA	Ø	10+ years	



	3010013						409 W 80th STREET, Chicago, IL 60620
Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Asphalt	Parking Lot- West	21,359	SF	4	0-1 year	Holes/minor potholes Broken/Cracked/vegetative growth w/water retention crevais
	Surface - Concrete	Parking Lot- West	2,542	SF	7	10+ years	
	Trash Compactor	Parking Lot- West	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- West	481	SF	7	10+ years	
_Playgrou	Ind						
	Equipment - Pre K 3-5	North Site	1	EA	6	10+ years	
	Surface - Poured Surface	North Site	1,767	SF	4	0-1 year	Cracking/Rips/Tearing/Holes
	Equipment - School Age 5-12	South Site	1	EA	7	10+ years	
	Surface - Poured Surface	South Site	2,915	SF	6	10+ years	
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	2,002	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	25	LF	4	0-1 year	Destroyed/Broke/Cracked/sinking and heaving
	Sidewalks - Internal Walks	Entire Site	25	LF	4	0-1 year	Broken/Cracked
	Sidewalks - Perimeter Sidewalks	Entire Site	14,974	SF	6	10+ years	Quantity Adjusted
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	0-1 year	Cracked/Chipped/Broken and uneven/leaning
_Signage							
0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	4	0-1 year	Old/Deteriorated/non functioning
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	10+ years	5
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main							1.0		
Faculty Lounge	Regular Classroom	1st Floor	101	127	700	92	10	Y	N
Kindergarten	Regular Classroom	1st Floor	102	130	700	97	10	Y	N
Pre School	Kindergarten	1st Floor	104	128	1,027	114	15	Y	N
Pre School	Kindergarten	1st Floor	106	124	1,027	114	15	Y	Y
Regular Classroom	Regular Classroom	1st Floor	201	231	725	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	230	796	97	10	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	229	725	97	10	Y	N
Regular Classroom	Regular Classroom	2nd Floor	204/206	224/226	1,521	194	20	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205	227	725	97	10	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208/210	224/222	1,193	193	20	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	331	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	302	329	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	304	328	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	305	327	725	97	10	Y	N
Regular Classroom	Regular Classroom	3rd Floor	306	326	725	97	10	Y	N
Regular Classroom	Regular Classroom	3rd Floor	307	325	725	68	17	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	324	700	97	10		Y
Regular Classroom	Regular Classroom	3rd Floor	309	323	725	97	10	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	310	32s	453	53	5		N
Regular Classroom	Regular Classroom	3rd Floor	311	321	700	97	10	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312	320	700	97	10	Y	Y
Store Room	Regular Classroom	2nd Floor	212	228	725	97	10	Y	N
Building : Linked Addition									ŗ
Computer Lab	Regular Classroom	1st Floor	111	001	790	78	26	N	N
Computer Lab	Regular Classroom	1st Floor	112	003	790	78	26	N	N
Office	Regular Classroom	1st Floor	115	009	790	78	26	N	N
Regular Classroom	Regular Classroom	1st Floor	113	002	790	78	26	N	Y
Regular Classroom	Regular Classroom	1st Floor	116		790	78	26	N	Ý
Store Room	Regular Classroom	1st Floor	114	004	790	78	26	N	N