



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1944	1	24,950
Addition	2015	3	35,068
Campus Total			60,018

Category : Exterior Building : Main

	.y . =xic.i.e.					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance			•			<u> </u>	
	Entrance Control - Audio	#1 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#1 - S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - S	60	LF	6	10+ years	
	Power Door Operator and Controls	#1 - S	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#1 - S	110	LF	6	10+ years	
	Ramps - Concrete	#1 - S	55	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - S	50	LF	6	10+ years	
	Entrance Control - Audio and Video	#2 - N - Main	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#2 - N - Main	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - N - Main	1	EΑ	6	10+ years	
	Exterior Doors - Exterior AMP Door	#3 - N east end	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#3 - N east end	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#3 - N east end	30	LF	5	2-5 years	
	Ramp Handrail - Steel_Ramp Handrail	#3 - N east end	70	LF	6	10+ years	
	Ramps - Concrete	#3 - N east end	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - N east end	27	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#4 - North - Middle	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - North - Middle	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 - North - Middle	13	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#5 - N - West end	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - N - West end	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - N - West end	40	LF	5	2-5 years	



Categor	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stair Handrail - Steel_Stair Handrail	#5 - N - West end	18	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6 - W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - W	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 - W	15	LF	6	6-10 years	
	Entrance Control - Audio and Video	#8 - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#8 - SW	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#8 - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8.5 - S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8.5 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9 - S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 - S	3	LF	6	10+ years	
_Foundation	on						
	Foundation - Concrete	Entire Building	1,115	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	25,783	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	23	EA	7	6-10 years	
Roof Svs	stem						
	Coping - Metal	Low W roof	122	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low W roof	45	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low W roof	122	LF	7	10+ years	
	Roof - Modified Bitumen	Low W roof	2,654	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Low W roof	2,654	SF	7	10+ years	
	Chimney - Metal Flue	Low roof	25	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low roof	100	LF	6	10+ years	
	Roof - Modified Bitumen	Low roof	4,640	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Low roof	4,640	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	2	EA	5	2-5 years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	21	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	15	LF	6	10+ years	
	Chimney - Metal Flue	Main Roof	20	LF	6	10+ years	
	Chimney - Metal Flue	Main Roof	20	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	225	LF	6	10+ years	
	Roof - Asphalt Shingle	Main Roof	13,645	SF	6	6-10 years	with missing shingles
	Roof - Modified Bitumen	Main Roof	3,756	SF	6	6-10 years	with missing shingles
	Roof Hatch - Metal	Main Roof	3,730	EA	7	10+ years	
	Roof Structure - Heavy Timber	Main Roof	17,401	SF	7 7	•	
	NOOLSHUGULE - DEAVY HINDEL	IVIAITI NUUI	17.401	OΓ	1	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	W roof	1	EA	7	10+ years	
	Downspouts - Exterior Downspouts	W roof	36	LF	6	10+ years	
	Roof - Asphalt Shingle	W roof	5,787	SF	6	6-10 years	
	Roof Structure - Heavy Timber	W roof	5,787	SF	7	10+ years	
Valls							
	Cheek-Wall - Concrete	Entire Building	64	SF	6	6-10 years	Door #1: Dis-shelved at base/botton of cheek wall.
	Cheek-Wall - Concrete	Entire Building	54	SF	5	6-10 years	Cracked/Chipped - holes atop of cheek from previous/old stair railings Disjointed/unsealed from concrete stair.
	Cheek-Wall - Concrete	Entire Building	24	SF	4	0-1 year	Door 3: Broken/Base of Railing/Cracked/Dis-Shelved at side of Cheek wall.
	Cornice - Wood	Entire Building	1,115	LF	5	2-5 years	Exposed wood with peeling paint. Wood subject to deterioration/rot.
	Exterior Walls - Brick	Entire Building	17,890	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	35	SF	6	10+ years	
	Exterior Walls - Wood Siding	Entire Building	504	SF	5	2-5 years	Exposed wood with peeling paint. Wood subject to rot/deterioration.
Vindows							
	Clerestory - Glass Double-Pane	Entire Building	72	SF	6	10+ years	
	Clerestory - Glass Single-Pane	Entire Building	24	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	26	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	48	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	876	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	68	SF	6	10+ years	
	Lintels - Brick	Entire Building	27	LF	6	10+ years	
	Lintels - Steel	Entire Building	375	LF	6	10+ years	
	Windows - Decorative	Entire Building	60	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,044	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
merger	ncy System						
-	Automatic Transfer Switch	Entire Building	1	EA	6	6-10 years	Serves independent service in main bu8lding
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,333	SF	6	10+ years	Building has an EM panel
	Emergency A/C Power - Gym	Entire Building	2,405	SF	6	10+ years	



Catego	ry : Electrical		B	uilding	· Main		O N Filawatila AVENDE, Chicago, iL 60646
outogo.	, 1 = 100 ti 10 ti			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Students Toilets	Entire Building	1,012	SF	6	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	13	ĒΑ	6	6-10 years	
	Stairs	9			-	- · · · · · · · ·	
	Emergency Battery Packs - Multipurpose	Entire Building	4	EA	6	6-10 years	
	Room	9			-	- · · · · · · · ·	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	7	EA	6	6-10 years	
	Security System - CCTV	Entire Building	24,950	SF	5	6-10 years	Exterior cameras only, previously not
		9	_ :,555	О.	•	o .o you.o	assessed
	Security System - Intrusion Detection	Entire Building	24,950	SF	5	6-10 years	Functional, connected to addition
		g	,	-	-	- · · · · · · · · · · · · · · · · · · ·	building
							2 2
Main Ser	vice						
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	Serves main and addition building
	120/208/3PH						
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	ATS and a second electrical meter
	emergency power	· ·				•	
	PA System	Entire Building	24,950	SF	6	6-10 years	Connected to addition building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	EM panel
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	Functional panels have a 10+ years
		· ·				•	of remaining life
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Trips occasionally, deteriorated
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Access to panel provided, functional
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	Previously not assessed
	amp	3				, , , , , ,	
_							
Catego	ry : Fire Protection		В	uilding	: Main		
_			A			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
	Fire Alarm Strobe Lights	Entire Building	24,950	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	24,950	SF	6	6-10 years	Connected to addition building
Catego	ry : Mechanical		D	uilding	· Main		
Jaiego	y . moonanioai		D	unung	. Iviaiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•			Quantity	00111	Marin	Nopiasomont	COMIOINO
Air Cond	illOrling.						



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chemical Pot Feeder	Site North	1	EA	6	6-10 years	
	Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons	Site North	1	EA	6	10+ years	Serves main building, AHU and univents
	Glycol Feed	Site North	1	EA	6	10+ years	Used for univents, manually fed, previously not assessed
	Pipes - Chilled Water Pipe- Copper	Site North	100	LF	6	10+ years	,
	Pressure Fill System	Site North	1	EA	6	6-10 years	
Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Attic	1	EA	6	10+ years	Serves gym, AHU 1
	Air Intake	Attic	1	EA	6	6-10 years	
	Energy Recovery Unit	Attic	1	EA	7	10+ years	ERV, with 4 attached ducts, heat exchanger
Boiler Sy		D. 11. D.					
	Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	Previously not assessed
	Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	10+ years	Serves main building
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Previously not assessed, manually fed
	Water Fill System	Boiler Room	1	EA	5	6-10 years	Previously not assessed. With pump
Heating							
	Fin Tube - Hot Water	Engineer's Office	5	LF	5	6-10 years	Scratched cover, functional
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	5	6-10 years	Recently serviced, with internal thermostat
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	4	2-5 years	Older, deteriorated, leaks repaired
	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	, , ,
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	2	EΑ	5	6-10 years	Recently serviced
	PTAC - Electric Heating and Self Contained	Entire Building	6	EA	6	6-10 years	With internal thermostat
	Cooling	Little Building	Ü		Ü	o to years	with internal tremiostat
_Mechani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Serves air handler, ceiling mounted
	Dual Temperature Pump - Less than 10	Entire Building	2	EA	5	6-10 years	Serve boilers, with deteriorated insulation
	Hydronic Supply and Return - Copper	Entire Building	200	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	6	10+ years	Minor leaks are occasionally repaired

Campus Name: Wildwood Page : 5 of 32 Assessment Date: 06/20/2022



Fixtures

(Horizontal Lines)

(from Risers to Fixtures)

Domestic Piping-Hot/Cold Water Supply

Domestic Piping-Hot/Cold Water Supply

Wildwood IB World Magnet School 6950 N Hiawatha AVENUE, Chicago, IL 60646

1944 installation, good, has a few

pipe clamps

No active leaks

Catego	ry : Mechanical		В	uilding	: Main		
Craun	Itom Tuno	Lagation	Quantitu	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
·	DDC System	Entire Building	24,950	SF	5	6-10 years	Installed when addition was constructed. Does not work well. Requires manual operation at 1/4 of the equipment, serves main and addition buildings
	Thermostats - DDC	Entire Building	16	EA	6	6-10 years	
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	12	EA	6	6-10 years	
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	3	EA	4	2-5 years	Require frequent repairs, not reliable
Ventilation	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	EF 9
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	12	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	In toilet, ceiling mounted
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	2-5 years	Noisy, deteriorated
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	4	2-5 years	Noisy, deteriorated, not ballanced
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
		l di				Recommend	0
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
LIOL WAII	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves main building, 2015 installation
Piping							
. 0—	Domestic Piping-Hot Water Return Lines	Entire Building	24,950	SF	6	6-10 years	1944 installation, good
	Domestic Piping-Hot Water from Risers to	Entire Building	24,950	SF	6	6-10 years	Minor leaks are occasionally repaired

Campus Name: Wildwood Page: 6 of 32 Assessment Date: 06/20/2022

24,950

24,950

SF

SF

6

6

6-10 years

6-10 years

Entire Building

Entire Building



Catego	ry : Plumbing	В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sanitary Piping	Entire Building	24,950	SF	5	6-10 years	
	Storm Piping	Entire Building	24,950	SF	5	6-10 years	Gutters for sloped roof
	Vent Piping	Entire Building	24,950	SF	5	6-10 years	·
Pumps							
·	Pumps - Sump-Simplex	Crawlspace	1	EA	6	6-10 years	in crawlspace space, difficult to access

Category: Room **Building: Main**

.oun	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
oup	Item - Type	Location	Quantity	UOW	Kank	Replacement	Comments
iminist	rative Suites/Offices						
	Ceiling - Plaster/Drywall	105A	139	SF	7	10+ years	
	Doors - Transom Window	105A	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105A	1	EA	7	10+ years	
	Floor - Tile	105A	139	SF	7	10+ years	
	Lighting - Pendent/Surface	105A	2	EA	7	6-10 years	
	Power Distribution	105A	8	EA	7	10+ years	
	Walls - Plaster/Drywall	105A	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	113A Internet room	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113A Internet room	1	EA	7	10+ years	
	Floor - Tile	113A Internet room	300	SF	7	10+ years	
	Lighting - Pendent/Surface	113A Internet room	2	EA	7	6-10 years	
	Power Distribution	113A Internet room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	113A Internet room	680	SF	7	10+ years	
	AC Unit	1st floor engineer's office inside boiler rm	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor engineer's office inside boiler rm	112	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor engineer's office inside boiler rm	1	EA	7	10+ years	
	Floor - Tile	1st floor engineer's office inside boiler rm	112	SF	7	10+ years	
	Lighting - Pendent/Surface	1st floor engineer's office inside boiler rm	2	EA	7	6-10 years	
	Power Distribution	1st floor engineer's office inside boiler rm	6	EA	7	10+ years	
	Storage/ Closet	1st floor engineer's office inside boiler rm	10	SF	7	10+ years	
	Walls - Concrete Block	1st floor engineer's office inside boiler rm	550	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor north of classroom #101	322	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor north of classroom #101	2	EA	7	10+ years	
	Floor - Tile	1st floor north of classroom #101	322	SF	7	10+ years	

Campus Name: Wildwood Page : 7 of 32 Assessment Date: 06/20/2022



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st floor north of classroom #101	3	EA	7	6-10 years	
	Power Distribution	1st floor north of classroom #101	6	EA	7	10+ years	
	Storage/ Closet	1st floor north of classroom #101	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor north of classroom #101	921	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counselor's Office next to Room 107	180	SF	7	10+ years	
	Doors - Transom Window	Counselor's Office next to Room 107	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office next to Room 107	2	EA	7	10+ years	
	Floor - Tile	Counselor's Office next to Room 107	180	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselor's Office next to Room 107	2	EA	7	6-10 years	
	Power Distribution	Counselor's Office next to Room 107	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselor's Office next to Room 107	73	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 115D, Office 110 A	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 115D, Office 110 A	1	EA	7	10+ years	
	Floor - Tile	Room 115D, Office 110 A	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 115D, Office 110 A	1	EA	7	6-10 years	
	Power Distribution	Room 115D, Office 110 A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 115D, Office 110 A	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 115E, Office 110B	68	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 115E, Office 110B	1	ĒΑ	7	10+ years	
	Floor - Tile	Room 115E, Office 110B	68	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 115E, Office 110B	1	ĒΑ	7	6-10 years	
	Power Distribution	Room 115E, Office 110B	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 115E, Office 110B	68	SF	7	10+ years	
_Gymnas	ia						
•	Ceiling - Splined	1st Floor	2,385	SF	7	10+ years	
	Ceiling - Splined	1st Floor	20	SF	4	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	ŭ
	Floor - Tile	1st Floor	2,405	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	ĒΑ	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EΑ	7	6-10 years	
	Stage	1st Floor	557	SF	7	10+ years	
	Stage Curtain	1st Floor	2	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lift Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,203	SF	7	10+ years	
	vvana - Concrete block	13(1)001	1,203	J.	,	10+ years	



Categor	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Structural Glazed Tile	1st Floor	1,202	SF	7	10+ years		
MDF IDE	=							
<u> </u>	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Finishes	1st Floor	95	SF	7	10+ years		
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years		
Maabaai	cal/ Service Rooms							
iviechanic	Janitor's Closet	1st Floor	42	SF	7	10+ years		
		1st Floor		SF	7	•		
	Mechanical/ Service Rooms		100	SF SF		10+ years		
	Storage Room	1st Floor	35		7	10+ years		
	Boiler Room	1st floor south portion of building	1,018	SF	7	10+ years		
	Crawl Space - Unfinished	Basement	8,150	SF	7	10+ years		
	Mechanical/ Service Rooms	Electrical Room In the boiler room	160	SF	7	10+ years		
	Vaults	In the Gym	106	SF	7	10+ years		
Restroom	1							
	Accessories	1st Floor Girl's Room, North end of Buildiing	268	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor Girl's Room, North end of Buildiing	268	SF	7	10+ years		
	Doors - Transom Window	1st Floor Girl's Room, North end of Buildiing	36	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's Room, North end of Buildiing	268	SF	7	10+ years		
	Floor Drain	1st Floor Girl's Room, North end of Buildiing	1	EA	7	10+ years		
	Hand Dryer	1st Floor Girl's Room, North end of Buildiing	2	EA	7	6-10 years		
	Lavatory	1st Floor Girl's Room, North end of Buildiing	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor Girl's Room, North end of Buildiing	2	EA	6	6-10 years		
	Partitions	1st Floor Girl's Room, North end of Buildiing	6	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor Girl's Room, North end of Buildiing	415	SF	7	10+ years		
	Water Closet	1st Floor Girl's Room, North end of Buildiing	6	EA	7	10+ years		
	Accessories	1st flr inside engineer's office	30	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st flr inside engineer's office	30	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st flr inside engineer's office	1	EA	7	10+ years		
	Floor - Tile	1st flr inside engineer's office	30	SF	4	0-1 year	Cracked and loose tiles	



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st flr inside engineer's office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st flr inside engineer's office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st flr inside engineer's office	219	SF	7	10+ years	
	Water Closet	1st flr inside engineer's office	1	EA	7	10+ years	
	Accessories	1st flr north of boiler rm	104	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr north of boiler rm	104	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr north of boiler rm	1	EA	7	10+ years	
	Floor - Tile	1st flr north of boiler rm	104	SF	7	10+ years	
	Lavatory	1st flr north of boiler rm	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr north of boiler rm	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr north of boiler rm	330	SF	7	10+ years	
	Water Closet	1st flr north of boiler rm	1	EA	7	10+ years	
	Accessories	1st flr south end of corridor	218	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr south end of corridor	218	SF	7	10+ years	
	Doors - Transom Window	1st flr south end of corridor	32	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr south end of corridor	218	SF	7	10+ years	
	Floor Drain	1st flr south end of corridor	1	EA	7	10+ years	
	Hand Dryer	1st flr south end of corridor	2	EA	7	6-10 years	
	Lavatory	1st flr south end of corridor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr south end of corridor	4	EA	7	6-10 years	
	Partitions	1st flr south end of corridor	2	EA	7	10+ years	
	Urinals	1st flr south end of corridor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st flr south end of corridor	150	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st flr south end of corridor	600	SF	7	10+ years	
	Water Closet	1st flr south end of corridor	2	EA	7	10+ years	
	Accessories	Boy's Room In the Gym's Lobby	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boy's Room In the Gym's Lobby	190	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boy's Room In the Gym's Lobby	190	SF	7	10+ years	
	Floor Drain	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Lavatory	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boy's Room In the Gym's Lobby	3	EA	7	6-10 years	
	Partitions	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Urinals	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Boy's Room In the Gym's Lobby	74	SF	7	10+ years	
	Walls - Structural Glazed Tile	Boy's Room In the Gym's Lobby	221	SF	7	10+ years	
	Water Closet	Boy's Room In the Gym's Lobby	1	EA	7	10+ years	
	Accessories	In Room 110	33	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 110	33	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 110	1	ĒΑ	7	10+ years	
	Floor - Tile	In Room 110	33	SF	7	10+ years	
	Lavatory	In Room 110	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 110	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	In Room 110	121	SF	7	10+ years	
				٥.	•	,	



ALL A						695	0 N Hiawatha AVENUE, Chicago, IL 606
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	In Room 110	1	EA	7	10+ years	
	Accessories	Next to 114	81	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to 114	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next to 114	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to 114	81	SF	7	10+ years	
	Floor Drain	Next to 114	1	EA	7	10+ years	
	Hand Dryer	Next to 114	1	EA	7	6-10 years	
	Lavatory	Next to 114	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Next to 114	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Next to 114	108	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Next to 114	252	SF	7	10+ years	
	Water Closet	Next to 114	1	EA	7	10+ years	
	Accessories	Room 114	81	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 114	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 114	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 114	81	SF	7	10+ years	
	Floor Drain	Room 114	1	EA	7	10+ years	
	Hand Dryer	Room 114	1	EA	7	6-10 years	
	Lavatory	Room 114	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 114	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 114	108	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Room 114	252	SF	7	10+ years	
	Water Closet	Room 114	1	EA	7	10+ years	
	Accessories	Unisex In the Gym	145	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex in the Gym	145	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex in the Gym	145	EA	7		
	Floor - Tile	Unisex in the Gym	145	SF		10+ years	
				_	7	10+ years	
	Hand Dryer	Unisex In the Gym	1	EΑ	7	6-10 years	
	Lavatory	Unisex In the Gym	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex In the Gym	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex In the Gym	225	SF	7	10+ years	
	Water Closet	Unisex In the Gym	1	EA	7	10+ years	
atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassro	om #101 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Maine Dualu	1911 1001	34	ᆫ	,	o- io yeais	



Catego	ory : Classroom		В	uilding	: Main		on Thawatha Avenoe, Officago, ie 00040
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
Classro	om #102 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	•	SF	7		
		1st Floor	722	_		10+ years	
	Lighting - Pendent/Surface		12	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	62	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
Classro	om #104 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	683	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board		66	LF	7	6-10 years	
		1st Floor		SF	7 7	•	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	/	10+ years	
_Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	712	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	712	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
Classro	om #106 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Caccinon	1001	O .	_,	•	ioi youis	



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	715	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	7	10+ years	
	Doors - Side-lite	1st Floor	64	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	715	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
	Walls - Flastel/Drywall	13111001	1,100	Si	,	10+ years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	683	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,098	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Damaged plaster walls
Classroo	om #109 (Kindergarten)						
Ciassiuc	Casework	1st Floor	6	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	683	SF	7		
		1st Floor	12	SF LF		10+ years	
	Chalk Board				4	2-5 years	
	Doors - Transom Window	1st Floor	116	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	673	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		on Thawatha Avenoe, oneago, ie ooo-o
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Classroo	m #110 (Kindergarten)						
	Ceiling - Plaster/Drywall	1st Floor	718	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	718	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	41	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
Classroo	m #112 (Counseling Room)						
Classioo	Ceiling - Plaster/Drywall	1st Floor	455	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	•	
	Floor - Tile	1st Floor		SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	455 12		7	10+ years 6-10 years	
				EA LF		•	
	Marker Board	1st Floor	16		7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
Classroo	m #113 (Faculty Lounge)						
	Ceiling - Plaster/Drywall	1st Floor	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	400	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	700	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	m #114 (Pre School)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,016	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2,010	EA	7	10+ years	
	Floor - Tile	1st Floor	2,016	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2,010	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,160	SF	7	10+ years	
	Work Sink	1st Floor	2,100	EA	7	10+ years	
Classroo	m #116 (Band Room)						
<u> </u>	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	101.1/2272	
	,			SF EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĽΑ	7	10+ years	



Catego	ry : Classroom		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	5	0-1 year	Missing door knob
	Floor - Tile	1st Floor	750	SF	7	10+ years	
	Instrument Storage Casework	1st Floor	15	LF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	380	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Damaged plaster ceiling
	Walls - Structural Glazed Tile	1st Floor	700	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	4,748	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Double Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	415	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,313	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	1st Floor	68	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	38	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	242	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,570	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,658	SF	7	10+ years	
Safety							
-	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
	Conveyance						
<u>'ertical</u>	0011070100						



Category : Exterior	Building : Addition
Category : Exterior	Building : Addition

atogory . Extorr			Recommend					
Group Item - Typ	oe	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	oors - Side lite	10	2	EA	6	10+ years		
	oors - Store Front	10	2	EA	6	10+ years		
	oors - Store From	10	3	EA	6	10+ years		
	oors - Transom Lite	10.5 chiller enclosure	2	EA	6	10+ years		
	oors - Store Front				_	•		
		11	2	EΑ	6	10+ years		
	oors - Transom Lite	11	1	EΑ	6	10+ years		
	oors - Exterior FRP Door	12	1	EΑ	6	10+ years		
	Control - Audio and Video	13	1	EA	6	10+ years		
	oors - Store Front	13	2	EA	6	10+ years		
Exterior D	oors - Transom Lite	13	1	EA	6	10+ years		
oundation								
	n - Concrete	Entire Building	35,068	LF	7	10+ years		
Superstru	cture - Metal Deck/ Concrete	Entire Building	35,068	SF	7	10+ years		
Topping		•				•		
_ighting								
	ighting - Wall Mounted	Entire Building	10	EA	7	6-10 years		
Exterior E	grang Tran Meanted	Zitino Ballaling		_, 、	•	o io youro		
Roof System								
Access La	adder - Metal	1 main roof	1	EA	7	10+ years		
Coping -	Stone	1 main roof	410	LF	6	10+ years		
Downspot	uts - Interior Downspouts	1 main roof	40	LF	6	10+ years		
Parapet -	16" - 30" Height	1 main roof	410	LF	6	10+ years		
Roof - Mo	dified Bitumen	1 main roof	9,750	SF	6	6-10 years		
Roof Hato	h - Metal	1 main roof	1	EA	7	10+ years		
	cture - Steel / Metal Deck/	1 main roof	9,750	SF	7	10+ years		
Concrete			-,			, , , , ,		
Coping -		2 low roof	9	LF	6	10+ years		
Coping -		2 low roof	138	LF	6	10+ years		
	uts - Interior Downspouts	2 low roof	30	LF	6	10+ years		
	Parapet < 16" Height	2 low roof	256	LF	6	10+ years		
Paranet -	Parapet > 30"	2 low roof	40	LF	6	10+ years		
•	dified Bitumen	2 low roof	3,192	SF	6	6-10 years		
	cture - Steel / Metal Deck/	2 low roof	3,192	SF	7	10+ years		
		Z IUW IUUI	3,192	SF	,	10+ years		
Concrete	ι ορριτία							
Valls								
	Concrete/ Stucco	Entire Building	550	SF	6	10+ years		
Cheek-Wa		Entire Building	1,800	SF	6	10+ years		
Cornice -	Cast Stone	Entire Building	410	LF	6	10+ years		

Campus Name: Wildwood Page : 16 of 32 Assessment Date: 06/20/2022



Category : Exterior

Wildwood IB World Magnet School 6950 N Hiawatha AVENUE, Chicago, IL 60646

alego	y . Exterior			unung	. Additio		
		1	0			Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cornice - Metal Projecting	Entire Building	90	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20,050	SF	6	10+ years	
indows							
	Lintels - Steel	Entire Building	396	LF	6	10+ years	
	Storefront Windows	Entire Building	200	SF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	3,240	SF	6	10+ years	
	•		_		A 1 1141		
itego	ry : Electrical		В	uilding	: Addition		
	Itam Tuna	Location	Ouantitu	LIOM	Donk	Recommend	Comments
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	6	6-10 years	Batteries recently replaced
	Exit Signs - Lunchroom	Entire Building	5	EA	6	6-10 years	2015 installation.
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,280	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,320	SF	6	10+ years	Building has an EM panel
	Emergency A/C Power - Students Toilets	Entire Building	1,890	SF	6	10+ years	p
	Emergency Battery Packs - Corridors and	Entire Building	18	ĒΑ	6	6-10 years	2015 installation, batteries recently
	Stairs	ŭ				,	replaced
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	35,068	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	35,068	SF	6	6-10 years	
ain Ser	vice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	7	10+ years	Serves addition
	120/208/3PH					•	
	PA System	Entire Building	35,068	SF	6	6-10 years	Connected to main building
wer D	istribution						
	Lighting and Power Panels - 100 A	Electrical Room	7	EA	7	10+ years	2015 installation
	Lighting and Power Panels - Above 100 A	Electrical Room	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Electrical Room	1	EA	7	10+ years	
	·		_				
atego	ry : Fire Protection		В	uilding	: Additio		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	m						

Building: Addition

Campus Name: Wildwood Page : 17 of 32 Assessment Date: 06/20/2022



Category : Fire Protection

Wildwood IB World Magnet School 6950 N Hiawatha AVENUE, Chicago, IL 60646

Building: Addition

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves addition, connected to main building
	Fire Alarm Strobe Lights	Entire Building	35,068	SF	6	10+ years	· ·
	Fire Alarm_System	Entire Building	35,068	SF	6	10+ years	Connected to main building
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	Serves addition, 2015 installation
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	2015 installation
Sprinkle	r System						
	Sprinkler Heads	Entire Building	35,068	SF	7	10+ years	2015 installation
	Sprinkler Piping	Entire Building	35,068	SF	7	10+ years	2015 installation
	Wet Sprinkler System	Entire Building	35,068	SF	6	10+ years	Serves addition
Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves fan coil unit in MDF room, previously not assessed
	Chemical Pot Feeder	Site West	1	EA	5	6-10 years	
	Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons	Site West	1	EA	6	6-10 years	Recently serviced. Required occasional maintenance
	Glycol Feed	Site West	1	EA	6	10+ years	Manually fed
	Pipes - Chilled Water Pipe- Steel	Site West	100	LF	6	10+ years	
	Pressure Fill System	Site West	1	EA	6	10+ years	2015 installation, previously not assessed
Air Hand	lling Systems						
	Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Dual Temperature Coils - 6000-10000 cfm	Roof	1	EA	6	10+ years	AHU 1, serves kitchen and cafeteria
	Air Intake	Roof	1	EA	6	10+ years	Previously not assessed, attached to air handler
	VAV Box	Roof	10	EA	6	10+ years	Located above ceilings, difficult to access
	Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Dual Temperature Coils - 15001-20000 cfm	Roof	1	EA	6	10+ years	AHU 2, serves classrooms
	Air Intake	Roof	1	EA	6	10+ years	Previously not assessed, attached to air handler
	VAV Box	Roof	25	EA	6	10+ years	Located above ceilings, 2015

Campus Name: Wildwood Page : 18 of 32 Assessment Date: 06/20/2022



Catego	Category : Mechanical			uilding	: Additi		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	VAV Box	Roof	1	EA	5	6.10	installation. Difficult to access
	VAV BOX	ROOI	ı	EA	5	6-10 years	Requires occasional maintenanceo
Boiler S	ystems						
	Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	Not painted, functional, 2015 installation
	Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	10+ years	Serves addition building
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Manually fed
	Water Fill System	Boiler Room	1	EA	6	10+ years	Previously not assessed
_Heating	Devices						
	Unit Heater - Hot Water	1st Floor	3	EA	6	10+ years	2015 installation
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	6	10+ years	
	Radiator Panels - Hot Water	Entire Building	10	EA	6	10+ years	In restrooms
	Fin Tube - Hot Water	Entire Building	42	LF	6	10+ years	
Mechan	ical Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	300	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	7	10+ years	2015 installation
	Dual Temperature Pump - Less than 10	Entire Building	2	EA	6	10+ years	Serves air handler, 2015 installation,
	Eddi Tomporataro Famp 2000 than To	Entire Banding	_		O	101 youro	ceiling mounted
	Dual Temperature Pump - Less than 10	Entire Building	2	EA	6	10+ years	Serve boiler, floor mounted, 2015 installation
Temper	ature Control						
	DDC System	Entire Building	35,068	SF	6	10+ years	Serves addition, 2015 installation,
		g	22,223	-	•	, , , , , , , , , , , , , , , , , , , ,	server in main building
	Electric Thermostat	Entire Building	7	EA	7	10+ years	Serves fan coil unit, unit heaters, exhaust fan
	Thermostats - DDC	Entire Building	31	EA	6	10+ years	2015 installation
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EΑ	6	6-10 years	2015 installation
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	2015 installation
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	

Campus Name: Wildwood Page: 19 of 32 Assessment Date: 06/20/2022



	schools			·	A		60 N Hiawatha AVENUE, Chicago, IL 60646		
Catego	ry : Mechanical		В	Building : Addition					
0	N T	Laadlan	0	LIOM	Danis	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	2015 installation		
Catego	ry : Plumbing		В	uilding	· Additi	on			
Outogo	. y . i idilibilig		_	anding	. Additi	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Hot Wat	• •		444		- 10				
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	6	10+ years	Serves addition, 2015 installation		
	Cas ricator Less than 100000 B10/1110	Boiler Room	_		O	101 years	Gerves addition, 2010 installation		
Piping									
тринд	Domestic Piping-Hot Water Return Lines	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot Water Return Risers	Entire Building	35,068	SF	7	10+ years	2015 installation		
	Domestic Piping-Hot Water from Risers to	Entire Building	35,068	SF	7	10+ years	2010 motaliation		
	Fixtures	Little Dulluling	33,000	OI.	,	TOT years			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	35,068	SF	7	10+ years	2015 installation		
	(Horizontal Lines)		23,000	σ.	•	,			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	35,068	SF	7	10+ years			
	(Risers)	5	,	•		,			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	35,068	SF	7	10+ years			
	(from Risers to Fixtures)	•				_			
	Sanitary Piping	Entire Building	35,068	SF	7	10+ years	2015 installation		
	Storm Piping	Entire Building	35,068	SF	7	10+ years			
	Vent Piping	Entire Building	35,068	SF	7	10+ years			
Pumps									
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	Serves addition and main building. 2015 installation		
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Under elevator, 2015 installation		
Catego	ry : Room		В	uilding	: Additi	on			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	rative Suites/Offices								
	Ceiling - Lay-in	334	289	SF	7	10+ years			
	Ceiling - Lay-in	334	15	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	334	1	EA	7	10+ years	3		
	Floor - Tile	334	304	SF	6	10+ years			
	Lighting - Lay-in	334	5	ĒΑ	7	6-10 years			
	Power Distribution	334	12	EA	7	10+ years			
	Walls - Plaster/Drywall	334	682	SF	6	10+ years			
	Ceiling - Lay-in	Counselor's Office 142	122	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Counselor's Office 142	122	EA	7	10+ years			
		Counselor's Office 142	100	SF	=				
	Floor - Carpet Lighting - Lay-in	Counselor's Office 142	122 2	SF EA	6 7	6-10 years 6-10 years			
	Lighting - Lay-III	Couristion 5 Office 142	2	ĽA	,	0-10 years			
	Nama: Wildwood		ao : 20 of 22				Assessment Date: 06/20/20/		

Campus Name: Wildwood Page : 20 of 32 Assessment Date: 06/20/2022



Catego	Category : Room		В	uilding	: Additi		O N Filawatha AVENOE, Officago, 12 000+0
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Counselor's Office 142	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselor's Office 142	457	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Manager Office - 130	110	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager Office - 130	1	EA	7	10+ years	
	Floor - Tile	Kitchen Manager Office - 130	110	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager Office - 130	2	EA	7	6-10 years	
	Power Distribution	Kitchen Manager Office - 130	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Manager Office - 130	451	SF	7	10+ years	
	Ceiling - Lay-in	Main Office 140	143	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office 140	1	EA	7	10+ years	
	Floor - Carpet	Main Office 140	143	SF	6	6-10 years	
	Lighting - Lay-in	Main Office 140	2	EA	7	6-10 years	
	Power Distribution	Main Office 140	2	EA	7	10+ years	
	Storage/ Closet	Main Office 140	10	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office 140	481	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office 141	185	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office 141	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office 141	185	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office 141	2	EA	7	6-10 years	
	Power Distribution	Principal's Office 141	6	EA	7	10+ years	
	Storage/ Closet	Principal's Office 141	55	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office 141	546	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	1,531	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,531	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	23	ĒΑ	7	6-10 years	
	Serving Line	1st Floor	45	LF	7	10+ years	
	Storage/ Closet	1st Floor	339	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,620	SF	7	10+ years	
Library							
•	Ceiling - Lay-in	126	1,377	SF	7	10+ years	
	Doors - Wood Doors inclu hw	126	4	EΑ	7	10+ years	
	Floor - Carpet	126	1,377	SF	7	6-10 years	
	Lighting - Lay-in	126	21	EA	7	6-10 years	
	Walls - Plaster/Drywall	126	1,306	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,242	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	928	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	



om		Building : Addition							
			_		Recommend				
Гуре	Location	Quantity	UOM	Rank	Replacement	Comments			
Tile	1st Floor	3,170	SF	7	10+ years				
g - Lay-in	1st Floor	60	EA	7	6-10 years				
Line	1st Floor	45	LF	7	10+ years				
e/ Closet	1st Floor	358	SF	7	10+ years				
Plaster/Drywall	1st Floor	1,977	SF	7	10+ years				
0. 15									
Steel Doors incl hw	1st Floor 137	1	EA	7	10+ years				
S	1st Floor 137	115	SF	7	10+ years				
Cooling Unit	1st Floor 137	1	EA	7	6-10 years	Split AC system			
ice Rooms									
s Closet	1st Floor	60	SF	7	10+ years				
nical/ Service Rooms	1st Floor	915	SF	7	10+ years				
s Closet	2nd Floor	60	SF	7	10+ years				
s Closet	3rd Floor	60	SF	7	10+ years				
nical/ Service Rooms	3rd Floor	170	SF	7	10+ years				
Room	3rd Floor	82	SF	7	10+ years				
ories	1st Floor	120	SF	7	6-10 years				
- Plaster/Drywall	1st Floor	254	SF	7	10+ years				
Tile Ceramic/ Porcelain	1st Floor	254 254	SF	7					
rain	1st Floor		SF EA	7	10+ years				
		1			10+ years				
)ryer	1st Floor	2	EΑ	7	6-10 years				
y 5 1 1/0 f	1st Floor	3	EΑ	7	10+ years				
g - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years				
ns	1st Floor	4	EA	7	10+ years				
Plaster/Drywall	1st Floor	237	SF	7	10+ years				
Tile Ceramic/ Porcelain	1st Floor	450	SF	7	10+ years				
Closet	1st Floor	4	EA	7	10+ years				
ories	1st Floor	100	SF	7	6-10 years				
- Plaster/Drywall	1st Floor	254	SF	7	10+ years				
Tile Ceramic/ Porcelain	1st Floor	254	SF	7	10+ years				
rain	1st Floor	1	EA	7	10+ years				
Oryer Property of the Control of the	1st Floor	2	EA	7	6-10 years				
-y	1st Floor	3	EA	7	10+ years				
g - Pendent/Surface	1st Floor	4	EA	7	6-10 years				
ns	1st Floor	2	EA	7	10+ years				
·· ·	1st Floor	2	EA	7	10+ years				
Tile Ceramic/ Porcelain									
Plaster/Drywall	orcelain	1st Floor	1st Floor 237 orcelain 1st Floor 450	1st Floor 237 SF orcelain 1st Floor 450 SF	1st Floor 237 SF 7 orcelain 1st Floor 450 SF 7	1st Floor 237 SF 7 10+ years orcelain 1st Floor 450 SF 7 10+ years			



Catego	Category : Room			Building : Addition				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	1st Floor 133	20	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor 133	42	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor 133	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor 133	42	SF	7	10+ years		
	Hand Dryer	1st Floor 133	1	EA	7	6-10 years		
	Lavatory	1st Floor 133	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor 133	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor 133	87	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor 133	180	SF	7	10+ years		
	Water Closet	1st Floor 133	1	EA	7	10+ years		
	Accessories	1st Floor 135	40	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor 135	42	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor 135	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor 135	42	SF	7	10+ years		
	Hand Dryer	1st Floor 135	1	EA	7	6-10 years		
	Lavatory	1st Floor 135	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor 135	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor 135	87	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor 135	180	SF	6	10+ years		
	Water Closet	1st Floor 135	1	EA	7	10+ years		
	Accessories	235	60	SF	7	10+ years		
	Ceiling - Lay-in	235	42	SF	7	10+ years		
	Doors - Wood Doors inclu hw	235	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	235	42	SF	7	10+ years		
	Floor Drain	235	1	EA	7	10+ years		
	Hand Dryer	235	1	EA	7	6-10 years		
	Lavatory	235	1	EA	7	10+ years		
	Lighting - Lay-in	235	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	235	71	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	235	180	SF	7	10+ years		
	Water Closet	235	1	EA	7	10+ years		
	Accessories	2nd Floor	120	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	254	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	254	SF	7	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Hand Dryer	2nd Floor	2	EΑ	7	6-10 years		
	Lavatory	2nd Floor	3	EΑ	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	6-10 years		
	Partitions	2nd Floor	4	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	450	SF	7	10+ years		
	Water Closet	2nd Floor	4	EA	7	10+ years		
	Accessories	2nd Floor	100	SF SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	254	5F	6	10+ years		

Campus Name: Wildwood Page : 23 of 32 Assessment Date: 06/20/2022



Catego	ry : Room		Building : Addition						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	254	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor	450	SF	7	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	335	40	SF	7	10+ years			
	Ceiling - Lay-in	335	42	SF	7	10+ years			
	Doors - Wood Doors inclu hw	335	1	ĒA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	335	42	SF	7	10+ years			
	Floor Drain	335		EA	7	10+ years			
	Hand Dryer	335	1	EA	7	6-10 years			
	Lavatory	335	1	EA	7	10+ years			
	Lighting - Lay-in	335	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	335	71	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	335	180	SF	7	10+ years			
	Water Closet	335	100	EA	7	10+ years			
	Accessories	3rd Floor	120	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	254	SF	6	•			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	254	SF	7	10+ years 10+ years			
	Floor Drain	3rd Floor	1	EA	7	,			
	Hand Dryer	3rd Floor	2	EA	7	10+ years			
		3rd Floor	3	EA	7	6-10 years 10+ years			
	Lavatory	3rd Floor	4	EA	7	•			
	Lighting - Pendent/Surface					10+ years			
	Partitions	3rd Floor	4	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	237	SF SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	450		7	10+ years			
	Water Closet	3rd Floor	4	EA	7	10+ years			
	Accessories	3rd Floor	100	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	254	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	254	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EΑ	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	6-10 years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EΑ	7	6-10 years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Urinals	3rd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	237	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	450	SF	7	10+ years			
	Water Closet	3rd Floor	2	EA	7	10+ years			



Catego	ry : Room		Building : Addition							
Graun	Itom Type	Logotien	Ouantitu	LIONA	Donla	Recommend	Comments			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Catego	ry : Classroom		E	Building						
0	W T	Landin	O	HOM	D'	Recommend	0			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
_Classroo	m #226 (Regular Classroom)	0.151	750							
	Ceiling - Lay-in	2nd Floor	756	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	756	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years				
	Marker Board	2nd Floor	24	LF	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years				
Classroo	m #227 (Regular Classroom)									
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	750	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	12	EΑ	7	10+ years				
	Marker Board	2nd Floor	24	LF	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years				
_Classroo	m #228 (Regular Classroom)									
	Ceiling - Lay-in	2nd Floor	710	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	710	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years				
	Marker Board	2nd Floor	24	LF	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	947	SF	6	10+ years				
Classroo	m #229 (Regular Classroom)									
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	750	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years				
	Marker Board	2nd Floor	24	LF	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	980	SF	6	10+ years				
	wans - i laster/Drywall	ZIIU I IOOI	900	SI	U	TOT years				
_Classroo	m #230 (Computer Lab)									
	Ceiling - Lay-in	2nd Floor	1,033	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years				
	Floor - Tile	2nd Floor	1,043	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	[^] 21	EA	7	10+ years				
	Marker Board	2nd Floor	20	LF	7	6-10 years				

Campus Name: Wildwood Page : 25 of 32 Assessment Date: 06/20/2022



Catego	ry : Classroom		В	uildina	: Additi		o i i i i i i i i i i i i i i i i i i i
3	, , , , , , , , , , , , , , , , , , , ,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,125	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
_Classroo	om #231 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years	
Classro	om #232 (Art Room)						
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	900	SF	6	10+ years	
	Kiln	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,140	SF	6	10+ years	
	Work Sink	2nd Floor	1,140	EA	7	10+ years	
Classro	om #326 (Regular Classroom)						
Classiu	Ceiling - Lay-in	3rd Floor	734	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor		Sr EA	7		
	Floor - Tile		1	SF		10+ years	
		3rd Floor	734		6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	966	SF	6	10+ years	
_Classroo	om #327 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	745	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
_Classroo	om #328 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	583	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage
	<u> </u>	-	_			,	Ü

Campus Name: Wildwood Page : 26 of 32 Assessment Date: 06/20/2022



Catego	ry : Classroom	В	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years		
	Floor - Tile	3rd Floor	588	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	851	SF	6	10+ years		
Classroo	om #329 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	740	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	3.	
	Floor - Tile	3rd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years		
Classroo	om #330 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	745	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	10	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	Trailer damage	
	Floor - Tile	3rd Floor	755	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years		
Classroo	om #331 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	3rd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years		
Classroo	om #332 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	775	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years		
	Floor - Tile	3rd Floor	775	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	994	SF	6	10+ years		



Catego	ry : Interior		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	128E Kitchen Corridor	170	SF	7	10+ years		
	Doors - Steel Doors incl hw	128E Kitchen Corridor	1	EA	7	10+ years		
	Floor - Tile Quarry	128E Kitchen Corridor	170	SF	7	10+ years		
	Lighting - Lay-in	128E Kitchen Corridor	3	EA	7	10+ years		
	Student Lockers - One Tier	128E Kitchen Corridor	11	EA	7	10+ years		
	Walls - Plaster/Drywall	128E Kitchen Corridor	300	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,701	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years		
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years		
	Floor - Tile/Sheet	1st Floor	1,701	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years		
	Stairs - Concrete Stairs	1st Floor	8	LF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	3,029	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,360	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	1,360	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years		
	Student Lockers - One Tier	2nd Floor	12	EA	7	10+ years		
	Student Lockers - Two Tiers	2nd Floor	86	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	2,682	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	1,345	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	15	SF	4	0-1 year	Water damage	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	1,360	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years		
	Student Lockers - One Tier	3rd Floor	12	EA	7	10+ years		
	Student Lockers - Two Tiers	3rd Floor	86	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	2,682	SF	6	10+ years		
_Safetv								
	Security Cameras	Entire Building	2	EA	7	6-10 years		
	Security Cameras	Entire Building	4	EΑ	7	6-10 years		
	Security Cameras	Entire Building	2	EA	7	6-10 years		
04 :		-				-		
_Stairs	Coiling Lovin	Stair 1	200		7	10		
	Ceiling - Lay-in		690	SF SF	7	10+ years	Water demand	
	Ceiling - Lay-in	Stair 1	10 576	SF SF	4	0-1 year	Water damage	
	Floor - Tile Handrails	Stair 1 Stair 1	576 104	SF LF	6	10+ years		
		Stair 1 Stair 1	104 6	LF EA	7 7	10+ years		
	Lighting - Lay-in	Sidii I	б	EA	′	6-10 years		

Campus Name: Wildwood Page : 28 of 32 Assessment Date: 06/20/2022



Catego	ry : Interior		Building : Addition						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Stair 1	4	EA	7	10+ years			
	Stairs - Tile	Stair 1	288	LF	6	10+ years			
	Walls - Concrete Block	Stair 1	2,520	SF	7	10+ years			
	Ceiling - Lay-in	Stair 2	700	SF	7	10+ years			
	Floor - Tile	Stair 2	576	SF	6	10+ years			
	Handrails	Stair 2	104	LF	7	10+ years			
	Lighting - Lay-in	Stair 2	6	EA	7	6-10 years			
	Lighting - Pendent/Surface	Stair 2	4	EA	7	10+ years			
	Stairs - Tile	Stair 2	288	LF	6	10+ years			
	Walls - Concrete Block	Stair 2	2,520	SF	7	10+ years			
_Vertical (Conveyance								
	Elevator - Hydraulic Elevator	West	1	EA	6	10+ years			



Category : Site Building : Site

Catego	ry: Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra			•			<u>. </u>	
Olvini	Civil/ Drainage - Catch Basin	Entire Site	4	EA	7	10+ years	Quantity Adjusted
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	Quantity Adjusted
	Civil/ Dialilage - Site Maililole	Little Site	O	LA	,	10+ years	Quantity Adjusted
Fencing		5 11 1 2 2					
	Fencing - New Standard Ornamental	Parking Lot- South	210	LF	6	10+ years	
Landsca	•						
	Benches	Entire Site	12	EA	7	10+ years	
	Landscape - Grass	Entire Site	14,076	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	100	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	100	SF	6	10+ years	
	Planting Beds/ Area	Entire Site	4,006	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	8,369	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	430	SF	7	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking							
	Concrete Curbs	South	702	LF	6	10+ years	Added Asset
	Interior Plantings	South	300	LF	6	6-10 years	Added Asset
	Lighting - Pole Mounted	South	2	EA	6	10+ years	
	Pavers	South	6,860	SF	6	10+ years	Quantity Adjusted
	Pavers	South	560	SF	4	1-2 years	Broken/Separating/Vegetative growth
							 Sinking/Breakage/Deteriorating at
							edges where pavers meet asphalt.
	Surface - Asphalt	South	9,357	SF	6	6-10 years	
	Trash Compactor	South	1	EA	6	10+ years	
	Trash Enclosure - Masonry	South	975	SF	6	10+ years	
	Vehicular Screening	South	175	LF	6	10+ years	
Sidewalk	1 0						
Siuewali	Sidewalks - Internal Walks	Entire Site	25	LF	6	10 L voors	
	Sidewalks - Internal Walks	Entire Site	219	LF	6	10+ years 10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,771	SF	6		
	Sidewalks - Fellitietel Sidewalks	ETILITE SILE	0,771	SF	O	10+ years	
Signage							
	Flag Pole - Flag Pole	East	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter	East	1	EA	6	10+ years	
	Sign					-	



Wildwood IB World Magnet School

6950 N Hiawatha AVENUE, Chicago, IL 60646

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Wildwood Page: 31 of 32 Assessment Date: 06/20/2022





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	interfacti Osage	Room Education	Humber	Humber	(0.)	Alca	Aica	οιορ	Board
Band Room	Regular Classroom	1st Floor	116	Gym offices	750	64	32		
Counseling Room	Other Instructional Use	1st Floor	112	112	455	108	54	N	N
Faculty Lounge	Science	1st Floor	113	113	400	175	75	N	N
Kindergarten	Kindergarten	1st Floor	110	110	718	168	84	N	N
Kindergarten	Regular Classroom	1st Floor	109	109	683	108	54	N	N
Pre School	Other Instructional Use	1st Floor	114	114	2,016	120	60		
Regular Classroom	Regular Classroom	1st Floor	101	101	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	683	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	712	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	715	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	715	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	683	108	54	N	N
Building : Addition									
Art Room	Art Room	2nd Floor	232	232	900	180	27	N	N
Computer Lab	Regular Classroom	2nd Floor	230	230	1,043	180	27	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	756	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	750	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	710	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	750	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	734	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	327	327	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	588	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	329	329	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	755	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	775	120	18	N	N