2110 W Greenleaf AVENUE, Chicago, IL 60645

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1911 | 3 | 61,724 |
| Addition 2 | 1999 | 3 | 70,296 |
| Addition-Gymnasium | 1992 | 1 | 5,637 |
| Addition-Lunchroom/Kitchen | 1999 | 1 | 9,359 |
| Campus Total | | | 147,016 |

Category : Exterior Building : Main

| Outogo | IY. LAICHOI | | | unung | . Iviaiii | | |
|----------|---------------------------------------|--|----------|-------|-----------|-----------------------|-------------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Cell Equ | · - | Location | Quantity | OOM | Rank | Replacement | Comments |
| Ceir Equ | Cell Equipment - Antenna | Main Roof | 2 | EA | 7 | 10+ years | |
| Entrance | 1 | | | | | | |
| | Exterior Doors - Exterior FRP Door | Entrance 16-South | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 16-South | 4 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | Entrance 16-South | 12 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | Entrance 6-West / Assembly Hall Vestibule | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 6-West / Assembly Hall Vestibule | 4 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | Entrance 6-West / Assembly Hall Vestibule | 135 | LF | 7 | 10+ years | Divided deficient area and re-rated |
| | Exterior Stairs - Concrete | Entrance 6-West / Assembly Hall Vestibule | 5 | LF | 5 | 2-5 years | Spalls |
| | Ramp Handrail - Steel_Ramp Handrail | Entrance 6-West / Assembly Hall Vestibule | 120 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Entrance 6-West / Assembly Hall Vestibule | 60 | LF | 7 | 10+ years | Replaced |
| | Stair Handrail - Steel_Stair Handrail | Entrance 6-West / Assembly Hall Vestibule | 30 | LF | 7 | 10+ years | Replaced |
| | Entrance Control - Audio and Video | Entrance 7-NW | 1 | EA | 7 | 6-10 years | |



| Catego | Category : Exterior | | Building : Main | | | | | |
|-----------|--|------------------|-----------------|----------|------|-------------|---------------------------------------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Exterior Doors - Exterior FRP Door | Entrance 7-NW | 4 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | Entrance 7-NW | 4 | EA | 7 | 10+ years | | |
| | Exterior Stairs - Concrete | Entrance 7-NW | 37 | LF | 6 | 10+ years | | |
| | Exterior Stairs - Concrete | Entrance 7-NW | 3 | LF | 4 | 0-1 year | Chipped | |
| | Power Door Operator and Controls | Entrance 7-NW | 1 | EA | 7 | 6-10 years | | |
| | Ramp Handrail - Steel_Ramp Handrail | Entrance 7-NW | 20 | LF | 6 | 10+ years | | |
| | Ramps - Concrete | Entrance 7-NW | 20 | LF | 6 | 10+ years | | |
| | Stair Handrail - Steel_Stair Handrail | Entrance 7-NW | 20 | LF | 6 | 10+ years | | |
| | Exterior Doors - Exterior FRP Door | Entrance 8-North | 4 | EΑ | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | Entrance 8-North | 4 | EA | 6 | 10+ years | | |
| _Foundati | on | | | | | | | |
| | Foundation - Masonry | Entire Building | 500 | LF | 7 | 10+ years | | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 61,724 | SF | 7 | 10+ years | | |
| Lighting | | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 11 | EA | 7 | 10+ years | Led | |
| | Exterior Lighting - Wall Mounted | Entire Building | 8 | EA | 7 | 10+ years | | |
| Roof Sys | stem | | | | | | | |
| , | Coping - Metal | Roof 3 | 110 | LF | 7 | 10+ years | | |
| | Coping - Stone | Roof 3 | 425 | LF | 7 | 10+ years | | |
| | Downspouts - Exterior Downspouts | Roof 3 | 330 | LF | 6 | 10+ years | | |
| | Downspouts - Interior Downspouts | Roof 3 | 110 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | Roof 3 | 70 | LF | 7 | 10+ years | | |
| | Parapet - Parapet < 16" Height | Roof 3 | 465 | LF | 7 | 10+ years | | |
| | Roof - Metal | Roof 3 | 750 | SF | 7 | 10+ years | | |
| | Roof - Modified Bitumen | Roof 3 | 8,145 | SF | 5 | 2-5 years | | |
| | Roof - Modified Bitumen | Roof 3 | 5,000 | SF | 4 | 0-1 year | Bubbling, plant growth | |
| | Roof Structure - Steel / Metal Deck/ | Roof 3 | 200 | SF | 7 | 10+ years | Babbing, plant growth | |
| | Concrete Topping | | | | | • | | |
| | Roof Structure - Steel with Clay Tile Arch | Roof 3 | 13,695 | SF | 7 | 10+ years | | |
| | Access Ladder - Metal | Roof 4 - Main | 1 | EA | 7 | 10+ years | Exterior | |
| | Access Ladder - Metal | Roof 4 - Main | 2 | EA | 3 | 1-2 years | Not used, not up to current standards | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Roof 4 - Main | 52 | LF | 6 | 6-10 years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Roof 4 - Main | 28 | LF | 2 | 0-1 year | Leaning, loose brick | |
| | Coping - Stone | Roof 4 - Main | 265 | LF | 6 | 10+ years | | |
| | Downspouts - Interior Downspouts | Roof 4 - Main | 250 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | Roof 4 - Main | 265 | LF | 6 | 10+ years | | |
| | Roof - Metal | Roof 4 - Main | 300 | SF | 4 | 0-1 year | Holes, corrosion | |
| | Roof - Modified Bitumen | Roof 4 - Main | 15,370 | SF | 5 | 2-5 years | 1.0.00, 0011001011 | |
| | Samou Branion | | .5,010 | . | ŭ | 20,00.0 | | |



| | ry : Exterior | | В | uilding | : wain | B | |
|-----------------|---|------------------------------------|--------------|----------|--------|------------------------|-----------------------------------|
| 0 | Name Tama | Lagation | 0 | LIOM | Danil | Recommend | 0 |
| Group | Item - Type Roof Hatch - Metal | Location Roof 4 - Main | Quantity | UOM | Rank | Replacement | Comments |
| | | | 2 15.670 | EA SF | 3 | 1-2 years | Not used |
| | Roof Structure - Steel with Clay Tile Arch | Roof 4 - Main | 15,670 | SF | 7 | 10+ years | |
| Valls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 1,000 | SF | 6 | 10+ years | |
| | Cheek-Wall - Concrete | Entire Building | 240 | SF | 4 | 0-1 year | Displaced |
| | Cheek-Wall - Stone | Entire Building | 200 | SF | 6 | 10+ years | |
| | Cornice - Metal Projecting | Entire Building | 580 | LF | 5 | 2-5 years | Rust, holes |
| | Exterior Walls - Brick | Entire Building | 30,071 | SF | 6 | 6-10 years | |
| | Exterior Walls - Brick | Entire Building | 3,385 | SF | 5 | 1-2 years | Deteriorated mortar, missing |
| | Exterior Walls - Brick | Entire Building | 300 | SF | 3 | 0-1 year | Shifting, displaced corner, loose |
| | | - | | | | - | brick, missing lintel |
| | Exterior Walls - Prefabricated Metal Panel | Entire Building | 756 | SF | 7 | 10+ years | - |
| | Wall | - | | | | • | |
| | Exterior Walls - Stone-Cast | Entire Building | 2,994 | SF | 6 | 10+ years | |
| | | | | | | | |
| <u> Windows</u> | | Entire Duilding | 765 | SF | | 10 | |
| | Curtain wall - Insulated Panel | Entire Building Entire Building | 765 1,820 | SF SF | 6 6 | 10+ years 10+ years | |
| | Guard - Guards wire guard | • | | LF | | • | Loggo briek |
| | Lintels - Brick | Entire Building | 3 | LF | 6 | 0-1 year | Loose brick |
| | Lintels - Steel | Entire Building | 805 | SF | 6 | 10+ years | |
| | Skylite - Glass Single-Pane | Entire Building | 191 | SF SF | 6 | 10+ years | Dualian alasa samadad |
| | Skylite - Glass Single-Pane | Entire Building | 50 | | 4 | 1-2 years | Broken glass, corroded |
| | Windows - Louver | Entire Building | 25 | SF | 6 | 6-10 years | Discolanced |
| | Windows - Sash Lexan | Entire Building | 6,615 | SF | 5 | 2-5 years | Discolored |
| ategor | ry : Electrical | | В | uilding | : Main | | |
| | | Landon | 0 | | | Recommend | • |
| Froup | cy System | Location | Quantity | UOM | Rank | Replacement | Comments |
| mergen | Automatic Transfer Switch | Electrical Room | 1 | EA | 4 | 2-5 years | Deteriorated, old |
| | Security System - CCTV | Entire Building | 61,724 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 61,724 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and | Entire Building | 10,393 | SF | 6 | 6-10 years | |
| | Stairs | Z.mio Danding | | | | - | |
| | Emergency A/C Power - Multipurpose | Entire Building | 6,067 | SF | 6 | 6-10 years | |
| | Room | | | | _ | | |
| | Emergency Battery Packs - Multipurpose Room | Entire Building | 4 | EA | 4 | 2-5 years | Old, deteriorated |
| | | Entire Building | 18 | EA | 2 | 0-1 year | No battery pack, no AC unit |
| | Exit Signs - Corridors and Stairs | | 10 | EΑ | 2 | 0-1 year | No batteries, no AC generator |



| Catego | ry : Electrical | | В | uilding | : Main | | |
|----------|--|---|--|----------------------------------|---------------------------------|--|--|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 4 | 2-5 years | Using old ATS unit |
| | PA System | Entire Building | 61,724 | SF | 6 | 6-10 years | |
| ower D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 3 | 1-2 years | Deteriorated with missing circuit breakers |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | broakers |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 8 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | |
| atego | ry : Fire Protection | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ire Alar | m | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 61,724 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 61,724 | SF | 4 | 6-10 years | Updated panel in 1999 |
| atego | ry : Mechanical | | В | uilding | : Main | | |
| | | | | | | Recommend | Comments |
| Ţ. | Item - Type | Location | Quantity | UOM | Rank | Replacement | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Commente |
| roup | lling Systems Air Handling Unit- Built Up- Single Zone- | Location Mechanical Room | Quantity 1 | EA | Rank 6 | 6-10 years | |
| roup | lling Systems Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| roup | lling Systems Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake | Mechanical Room Mechanical Room | • | EA EA | 6 5 | 6-10 years 6-10 years | |
| iroup | Aling Systems Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- | Mechanical Room Mechanical Room Mechanical Room | 1 1 1 | EA EA EA | 6 5 5 | 6-10 years 6-10 years 6-10 years | Serves south side of the building |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 100 1 | EA EA EA LF | 6 5 5 5 | 6-10 years 6-10 years 6-10 years 6-10 years | |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 1 100 | EA EA EA LF EA | 6 5 5 5 6 | 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years | |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 100 1 | EA EA LF EA EA | 6 5 5 5 6 5 | 6-10 years | |
| iroup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 100 1 1 1 100 | EA EA LF EA EA LF | 6 5 5 6 5 6 | 6-10 years | |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 100 1 1 1 100 20 | EA EA LF EA EA LF | 6 5 5 6 5 6 5 | 6-10 years | Serves south side of the building |
| roup | Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room Mechanical Room | 1 1 1 100 1 1 1 100 | EA EA LF EA EA LF | 6 5 5 6 5 6 | 6-10 years | |



| Catego | Category : Mechanical | | В | uilding | : Main | | | | |
|-------------|---|--------------------|----------|---------|--------|---|--|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Auxiliaries - 15001 - 25000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | | | |
| | Return Duct Work - Indoor- Vertical Shaft | Mechanical Room | 100 | LF | 6 | 6-10 years | | | |
| | and Ducts | | | | | • | | | |
| | Zone Dampers | Mechanical Room | 24 | EA | 5 | 6-10 years | | | |
| D 11 0 | | | | | | | | | |
| Boiler Sy | | Dellas Deess | | | | 0.40 | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 5 | 6-10 years | | | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | | | |
| | Chemical Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | | | |
| | Combustion Dampers | Boiler Room | 2 | EA | 5 | 6-10 years | | | |
| | Condensate Pump | Boiler Room | 1 | EA | 5 | 6-10 years | | | |
| | Condensate Pump | Boiler Room | 1 | EA | 5 | 6-10 years | | | |
| | Condensate Pump | Boiler Room | 1 | EΑ | 5 | 6-10 years | | | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EΑ | 5 | 6-10 years | | | |
| | Non Condensing- Fire Tube- Scotch Marine- | Boiler Room | 1 | EA | 5 | 6-10 years | | | |
| | Steam- Low Pressure Boiler - 101 - 150 HP | Bollet Rootil | ' | LA | 3 | 0-10 years | | | |
| | Non Condensing- Fire Tube- Scotch Marine- | Boiler Room | 1 | EA | 5 | 6 10 years | | | |
| | Steam- Low Pressure Boiler - 101 - 150 HP | Bollet Rootti | ļ | EA | 3 | 6-10 years | | | |
| | | Dellas Desas | 500 | | _ | 0.40 | | | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 500 | LF | 5 | 6-10 years | | | |
| | Piping - Steam Pipe- Steel | Boiler Room | 500 | LF | 6 | 6-10 years | | | |
| | Steam Traps | Boiler Room | 16 | EA | 5 | 6-10 years | | | |
| Heating | Devices | | | | | | | | |
| - | Radiators - Steam | 1st Floor | 2 | EA | 4 | 2-5 years | Deteriorated, not painted | | |
| | Unit Heater - Gas | Boiler Room | 1 | EA | 4 | 2-5 years | Old unit, but still working | | |
| | Unit Heater - Steam | Boiler Room | 1 | EA | 5 | 6-10 years | 3 | | |
| | Wall Heater - Electric | Entire Building | 6 | EA | 6 | 6-10 years | | | |
| | Wall Heater - Electric | Entire Building | 2 | EΑ | 5 | 6-10 years | | | |
| _ | | Jan 1980 | | | | , | | | |
| Lempera | ature Control | Fating Desirations | | | | 0.4 | Danis and same and smith and a in | | |
| | Electric Thermostat | Entire Building | 1 | EA | 4 | 0-1 year | Damaged, serves gas unit heater in boiler room | | |
| | Pneumatic System | Entire Building | 61,724 | SF | 4 | 2-5 years | Many actuators are manually | | |
| | Thermostats - Pneumatic | Entire Building | 45 | EA | 5 | 2-5 years | controlled | | |
| | memostats - medinatic | Entire Building | 70 | LA | 3 | 2-5 years | | | |
| Ventilation | | | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 3 | EA | 5 | 6-10 years | | | |
| Catego | ry : Plumbing | | В | uilding | : Main | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments | | |



| | | | Replacement | | | | | |
|-----------|---|-----------------|-------------|----|---|------------|-------------------|--|
| _Hot Wate | er | | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Mechanical Room | 1 | EΑ | 7 | 10+ years | Installed in 2021 | |
| | Gas Heater - Less than 150000 BTU/HR | Mechanical Room | 1 | EA | 6 | 6-10 years | | |
| _Piping_ | | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Sanitary Piping | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Storm Piping | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| | Vent Piping | Entire Building | 61,724 | SF | 6 | 6-10 years | | |
| Pumps | | | | | | | | |
| • | Pumps - Domestic Booster Pump-Simplex | Mechanical Room | 1 | EA | 5 | 6-10 years | | |
| | Pumps - Sump-Simplex | Mechanical Room | 1 | EA | 5 | 6-10 years | | |

Category: Room **Building: Main**

| | | | | | | Recommend | |
|---------|---------------------------------|--------------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Adminis | trative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 102 A Office | 98 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 102 A Office | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 102 A Office | 98 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 102 A Office | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | 102 A Office | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 102 A Office | 186 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 106 Office | 470 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 106 Office | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 106 Office | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 106 Office | 470 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 106 Office | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 106 Office | 12 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 106 Office | 700 | SF | 7 | 10+ years | |
| | AC Unit | 211 ADJ Room | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 211 ADJ Room | 415 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 211 ADJ Room | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 211 ADJ Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 211 ADJ Room | 415 | SF | 7 | 10+ years | |
| | | | | | | | |



| Category : Room | | | Building : Main | | | | | | | |
|-----------------|-----------------------------|-----------------------------|-----------------|-----|------|-------------|----------|--|--|--|
| _ | | | | _ | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Lighting - Lay-in | 211 ADJ Room | 6 | EA | 6 | 6-10 years | | | | |
| | Power Distribution | 211 ADJ Room | 8 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 211 ADJ Room | 930 | SF | 7 | 10+ years | | | | |
| | AC Unit | 99 Office | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Lay-in | 99 Office | 490 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 99 Office | 80 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 99 Office | 1 | EΑ | 6 | 10+ years | | | | |
| | Floor - Tile | 99 Office | 490 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 99 Office | 9 | EΑ | 6 | 6-10 years | | | | |
| | Power Distribution | 99 Office | 12 | EΑ | 7 | 10+ years | | | | |
| | Storage/ Closet | 99 Office | 20 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 99 Office | 730 | SF | 7 | 10+ years | | | | |
| | AC Unit | 99-1 Conference | 1 | EΑ | 7 | 6-10 years | | | | |
| | Ceiling - Lay-in | 99-1 Conference | 187 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 99-1 Conference | 70 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 99-1 Conference | 1 | EΑ | 6 | 10+ years | | | | |
| | Floor - Tile | 99-1 Conference | 187 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 99-1 Conference | 3 | EA | 6 | 6-10 years | | | | |
| | Power Distribution | 99-1 Conference | 8 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 99-1 Conference | 355 | SF | 7 | 10+ years | | | | |
| | AC Unit | Assistant Engineer's Office | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Plaster/Drywall | Assistant Engineer's Office | 167 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | Assistant Engineer's Office | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | Assistant Engineer's Office | 167 | SF | 6 | 10+ years | | | | |
| | Lighting - Pendent/Surface | Assistant Engineer's Office | 3 | EA | 7 | 6-10 years | | | | |
| | Power Distribution | Assistant Engineer's Office | 6 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | Assistant Engineer's Office | 317 | SF | 7 | 10+ years | | | | |
| | Ceiling - Exposed | Custodian Office | 190 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | Custodian Office | 1 | EA | 7 | 10+ years | | | | |
| | Floor - Concrete | Custodian Office | 190 | SF | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | Custodian Office | 2 | EΑ | 6 | 6-10 years | | | | |
| | Power Distribution | Custodian Office | 6 | EΑ | 7 | 10+ years | | | | |
| | Walls - Masonry | Custodian Office | 361 | SF | 7 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | Engineer's Office | 179 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | Engineer's Office | 179 | SF | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | Engineer's Office | 1 | EA | 6 | 6-10 years | | | | |
| | Power Distribution | Engineer's Office | 4 | EA | 7 | 10+ years | | | | |
| | Storage/ Closet | Engineer's Office | 30 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | Engineer's Office | 650 | SF | 7 | 10+ years | | | | |
| | Work Sink | Engineer's Office | 1 | ĒΑ | 7 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | P.E Office | 127 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | P.E Office | 1 | EΑ | 6 | 10+ years | | | | |
| | Floor - Tile | P.E Office | 127 | SF | 6 | 10+ years | | | | |
| | · · · · | | | | - | , | | | | |



| Catego | ory : Room | | В | uilding | : Main | | |
|---------|-------------------------------------|------------------------|--------------|---------|--------|------------------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | P.E Office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | P.E Office | 6 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | P.E Office | 241 | SF | 7 | 10+ years | |
| Gymnas | sia | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,890 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,177 | SF | 7 | 10+ years | Quantity changed to update/correct to match current observation |
| | Doors - Wood Doors inclu hw | 1st Floor | 7 | EΑ | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 100 | SF | 5 | 1-2 years | Worn and torn carpet |
| | Floor - Wood | 1st Floor | 5,967 | SF | 7 | 10+ years | · |
| | Lighting - Pendent/Surface | 1st Floor | 17 | EA | 7 | 6-10 years | |
| | Main Floor Seating | 1st Floor | 425 | EA | 7 | 10+ years | |
| | Scoreboards | 1st Floor | 1 | ΕA | 7 | 6-10 years | |
| | Sound System | 1st Floor | 1 | ΕA | 7 | 6-10 years | |
| | Stage | 1st Floor | 420 | SF | 6 | 10+ years | |
| | Stage Curtain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage Curtain Stage Lighting System | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Stage-Stairs - Wood | 1st Floor | 14 | LF | 6 | 10+ years | |
| | Storage/ Closet | | | SF | | | |
| | Walls - Masonry | 1st Floor 1st Floor | 160 3,164 | SF | 7 6 | 10+ years 10+ years | |
| Machan | ical/ Service Rooms | | | | | • | |
| MECHAII | Air Intake Plenums | 1st Floor | 1.050 | C.E. | 7 | 10 | |
| | | | 1,250 | SF | 7 | 10+ years | |
| | Air Tunnel | 1st Floor | 3,680 | SF | 7 | 10+ years | |
| | Boiler Room | 1st Floor | 1,511 | SF | 7 | 10+ years | |
| | Coal Room | 1st Floor | 276 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 2,150 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 70 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 205 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 50 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 50 | SF | 7 | 10+ years | |
| Restroo | m | | | | | | |
| | Accessories | 1st Floor Boy's Room | 467 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Boy's Room | 467 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Boy's Room | 1 | EA | 7 | 10+ years | Quantity changed to update/correct to match current observation |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boy's Room | 467 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Boy's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Boy's Room | 2 | EA | 7 | 6-10 years | |
| | riana Diyor | Tot I loor boy o Room | 2 | _/\ | , | o io yours | |



| Catego | ry : Room | - | В | uilding | : Main | | <u>- </u> |
|--------|---------------------------------|-----------------------|----------|---------|--------|-------------|--|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lavatory | 1st Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Boy's Room | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor Boy's Room | 5 | EA | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor Boy's Room | 532 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Walls - Plaster/Drywall | 1st Floor Boy's Room | 532 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Water Closet | 1st Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Girl's Room | 468 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Girl's Room | 468 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Doors - Wood Doors inclu hw | 1st Floor Girl's Room | 2 | EA | 7 | 10+ years | gg g |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Girl's Room | 468 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor Girl's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Girl's Room | 2 | EA | 7 | 10+ years | |
| | | 1st Floor Girl's Room | 2 | EA | 6 | - | |
| | Lavatory | | | EA | | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Girl's Room | 4 | | 7 | 6-10 years | |
| | Partitions | 1st Floor Girl's Room | 7 | EA | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor Girl's Room | 532 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor Girl's Room | 532 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Water Closet | 1st Floor Girl's Room | 7 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 50 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 50 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 50 | SF | 7 | 10+ years | |
| | Lavatory | 2nd Floor | 1 | EΑ | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Partitions | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 285 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor Boy's Room | 467 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boy's Room | 467 | SF | 5 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boy's Room | 464 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boy's Room | | SF | 5 | - | Damagad |
| | | | 3 | EA | | 1-2 years | Damaged |
| | Floor Drain | 2nd Floor Boy's Room | 1 | | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Boy's Room | 2 | EΑ | 7 | 10+ years | |
| | Lavatory | 2nd Floor Boy's Room | 2 | EΑ | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Boy's Room | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor Boy's Room | 5 | EA | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor Boy's Room | 532 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Boy's Room | 532 | SF | 7 | 10+ years | |
| | | - | | | | - | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|--|-----------------------|----------|----------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | 2nd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor Girl's Room | 468 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 468 | SF | 5 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Girl's Room | 468 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor Girl's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Girl's Room | 2 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor Girl's Room | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Girl's Room | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Girl's Room | 7 | EA | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor Girl's Room | 532 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Girl's Room | 532 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor Girl's Room | 7 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor | 50 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 50 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 50 | SF | 7 | 10+ years | |
| | Lavatory | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 285 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Accessories | 3rd Floor Boy's Room | 467 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Boy's Room | 467 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor Boy's Room | 467 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor Boy's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor Boy's Room | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor Boy's Room | 4 | EA | 6 | 6-10 years | |
| | Partitions | 3rd Floor Boy's Room | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor Boy's Room | 5 | EA | 7 | 10+ years | |
| | Walls - Masonry | 3rd Floor Boy's Room | 532 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor Boy's Room | 532 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor Boy's Room | 2 | EΑ | 7 | 10+ years | |
| | Accessories | 3rd Floor Girl's Room | 468 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Girl's Room | 468 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor Girl's Room | 468 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor Girl's Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor Girl's Room | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor Girl's Room | 2 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 3rd Floor Girl's Room | 4 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor Girl's Room | 7 | EA | 7 | 6-10 years | |
| | | 3rd Floor Girl's Room | 532 | SF | 7 | | |
| | Walls - Masonry Walls - Plaster/Drywall | 3rd Floor Girl's Room | 532 | SF SF | 7 7 | 10+ years | |
| | | | 532 | SF EA | 7 7 | 10+ years | |
| | Water Closet | 3rd Floor Girl's Room | 1 | ĽΑ | 1 | 10+ years | |

Campus Name: Armstrong G Page : 10 of 60 Assessment Date: 11/07/2023



| Catego | ry : Room | | R | uilding | : Main | 2110 | W Greenlear AVENUE, Chicago, IL 60645 |
|--------|---------------------------------|---|----------|---------|--------|-------------|--|
| Jaiogo | . J. 1.00iii | | | ananig | . man | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Accessories | 99 Staff Unisex Toilet | 37 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 99 Staff Unisex Toilet | 37 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 99 Staff Unisex Toilet | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 99 Staff Unisex Toilet | 37 | SF | 6 | 10+ years | |
| | Lavatory | 99 Staff Unisex Toilet | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 99 Staff Unisex Toilet | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 99 Staff Unisex Toilet | 230 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 99 Staff Unisex Toilet | 40 | SF | 5 | 1-2 years | Plaster wall as damage |
| | Water Closet | 99 Staff Unisex Toilet | 1 | EA | 6 | 10+ years | |
| | Accessories | First Floor Men's Staff in Boys Restroom | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | First Floor Men's Staff in Boys Restroom | 45 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | First Floor Men's Staff in Boys Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | First Floor Men's Staff in Boys Restroom | 45 | SF | 7 | 10+ years | |
| | Lavatory | First Floor Men's Staff in Boys Restroom | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | First Floor Men's Staff in Boys Restroom | 1 | EA | 7 | 10+ years | |
| | Partitions | First Floor Men's Staff in Boys Restroom | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | First Floor Men's Staff in Boys Restroom | 187 | SF | 7 | 10+ years | |
| | Water Closet | First Floor Men's Staff in Boys Restroom | 1 | EA | 7 | 10+ years | |
| | Accessories | In Boiler Room Area | 16 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In Boiler Room Area | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Boiler Room Area | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Concrete | In Boiler Room Area | 16 | SF | 5 | 10+ years | |
| | Lighting - Wall Mounted | In Boiler Room Area | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | In Boiler Room Area | 145 | SF | 5 | 10+ years | |
| | Water Closet | In Boiler Room Area | 1 | EA | 6 | 10+ years | |
| | Accessories | Unisex Toilet in room 105 | 46 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Unisex Toilet in room 105 | 46 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Toilet in room 105 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Toilet in room 105 | 46 | SF | 7 | 10+ years | |
| | Lavatory | Unisex Toilet in room 105 | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | Unisex Toilet in room 105 | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Unisex Toilet in room 105 | 280 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Water Closet | Unisex Toilet in room 105 | 2 | EA | 7 | 10+ years | |



| | | | | uilding | · Wan | | |
|-----------|-----------------------------|-----------|----------|---------|-------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #100 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 50 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 915 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 915 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |
| _Classroo | m #101 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | m #102 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 815 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 815 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,220 | SF | 7 | • | |
| | walls - Plastel/Drywall | 1St Floor | 1,220 | SF | , | 10+ years | |
| _Classroo | m #103 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 815 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 6 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | 2110 | 7 VV Greenlear AVENUE, Chicago, iL 60045 |
|-----------|-----------------------------|-------------|----------|---------|--------|-------------|--|
| 5 2.090 | - y = -1.000.00 | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Doors - Transom Window | 1st Floor | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| Classro | om #104 (Regular Classroom) | | | | | | |
| Classion | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 10 | EA | 7 | 6-10 years | |
| | Floor - Wood Books inclu hw | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,240 | SF | 6 | 10+ years | |
| | walis - i lasten/brywali | 2110 1 1001 | 1,240 | OI. | O | 10+ years | |
| Classroo | om #105 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 50 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 915 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 915 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| _Classroo | om #200 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 20 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 415 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 50 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 415 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 930 | SF | 7 | 10+ years | |
| | | | | | - | , | |



| Catego | ry : Classroom | | В | uilding | : Main | | 5 W Greenical AVENUE, Gilleago, IE 00045 |
|-----------|-----------------------------|-------------|----------|------------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 805 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 10 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | ŭ |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 10 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,321 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 10+ years | |
| | Cacomonic | 2110 1 1001 | 30 | <u>-</u> 1 | , | io. yours | |



| Catego | ry : Classroom | | В | uilding | : Main | | · · |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|---------------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 2nd Floor | 807 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 8 | SF | 5 | 1-2 years | Damaged tiles |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | - |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 805 | SF | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 10 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Lay-in | 2nd Floor | 12 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| _Classroo | om #205 (Science Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Casework | 2nd Floor | 30 | LF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,145 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | 6-10 years | |
| | | | | | | • | |
| Classroo | om #206 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #207 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | - | | | | | • | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|---------|-----------------------------|------------------------|----------|---------|--------|-------------|------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| lassroo | om #208 (Regular Classroom) | | | | | | |
| павогос | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor 2nd Floor | 30 | LF | 6 | 10+ years | |
| | | | | SF | | | |
| | Ceiling - Lay-in | 2nd Floor | 815 | | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,220 | SF | 7 | 10+ years | |
| | | | | | | | |
| lassroc | om #209 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | | | | | | • | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,210 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 10 | SF | 4 | 1-2 years | Water damage, deteriorating plaste |
| lassroc | om #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 20 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 533 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood Books inclu hw | 2nd Floor | 533 | SF | 7 | 10+ years | |
| | | | | | | • | |
| | Lighting - Lay-in | 2nd Floor | 6 | EΑ | 7 | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | W Orcemeal Avenue, omeago, ie 00043 |
|-----------|-----------------------------------|------------------------|----------|----------|--------|-------------|-------------------------------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 920 | SF | 7 | 10+ years | |
| Classroo | om #300 (Other Instructional Use) | | | | | | |
| Ciassion | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 24 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 3rd Floor | 417 | SF | 7 | | |
| | | | | | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 40 | SF | | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 417 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 996 | SF | 7 | 10+ years | |
| _Classroo | om #301 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 815 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classro | om #302 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6 10 years | |
| | Casework | 3rd Floor 3rd Floor | 30 | LF | 7 | 6-10 years | |
| | | | | SF | | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 50 | LF CF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #303 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | | 2.2 | | | - | , | |



| Catego | ry : Classroom | | В | uilding | : Main | | 7 W Greenlear AVENUE, Chicago, iL 60045 |
|----------|-----------------------------|------------|----------|---------|--------|-------------|---|
| <u> </u> | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 3rd Floor | 807 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 5 | 1-2 years | Water damage |
| | Chalk Board | 3rd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #304 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #305 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 20 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | Damagea |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classro | om #306 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 6 | 10+ years | |
| | Casework Ceiling - Lay-in | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Hallsolli Williadw | 310 1 1001 | 8 | Ji | , | 10+ years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #307 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | SF | 6 | 6-10 years | |
| | Chalk Board | 3rd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | • | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | | | 815 | SF | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | | | | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Classroo | om #308 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EΑ | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 815 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 50 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 809 | SF | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 6 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Lay-in | 3rd Floor | 12 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 6 | 10+ years | |
| Classroo | om #309 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 3rd Floor | 815 | SF | 6 | 6-10 years | |
| | | | 50 | LF | | , | |
| | Chalk Board | 3rd Floor | | | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 805 | SF | 6 | 10+ years | 5 |
| | Floor - Wood | 3rd Floor | 10 | SF | 4 | 1-2 years | Damaged |



| Name | Catego | ry : Classroom | | В | uilding | : Main | | |
|---|----------|-----------------------------|-----------|----------|---------|--------|-------------|--------------|
| Lighting - Lay-in 3rd Floor 12 EA 6 6-10 years | | | | | | | | |
| Marker Board 3rd Floor 16 | Group | | | | | | | Comments |
| Storage/Closet 3rd Floor 40 SF 7 10+ years | | | | 12 | | - | | |
| Walls - Plaster/Drywall 3rd Floor 1,220 SF 7 10+ years | | | 3rd Floor | 16 | | - | | |
| Classroom #310 (Regular Classroom) | | | 3rd Floor | | SF | 7 | 10+ years | |
| Casework 3rd Floor 533 SF 7 10+ years | | Walls - Plaster/Drywall | 3rd Floor | 1,220 | SF | 7 | 10+ years | |
| Casework Sid Floor 20 LF 7 10 + years | Classroo | m #310 (Regular Classroom) | | | | | | |
| Celling - Lay-in 3rd Floor 533 SF 7 10 + years | | , • | 3rd Floor | 20 | LF | 7 | 10+ vears | |
| Doors - Transom Window 3rd Floor 8 SF 7 10+ years Floor - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Wood Doors inclu hw 3rd Floor 533 SF 7 10+ years Lighting - Lay-in 3rd Floor 6 EA 7 6-10 years Storage/ Closet 3rd Floor 40 SF 7 10+ years Storage/ Closet 3rd Floor 40 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 1 EA 7 6-10 years Walls - Plaster/Drywall 3rd Floor 399 SF 7 10+ years Water damage Water da | | Ceiling - Lav-in | | | | | • | |
| Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10- years Floor Wood 3rd Floor 533 SF 7 10- years Lighting - Lay-in 3rd Floor 6 EA 7 6-10 years Storage/ Closet 3rd Floor 8 EF 7 6-10 years Storage/ Closet 3rd Floor 920 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 1 EA 7 6-10 years Walls - Plaster/Drywall 3rd Floor 399 SF 7 10- years Water damage Walls - Plaster/Drywall 3rd Floor 399 SF 7 10- years Water damage Walls - Plaster/Drywall 3rd Floor 16 SF 5 1-2 years Water damage Walls - Plaster/Drywall 3rd Floor 16 SF 5 1-2 years Water damage Walls - Plaster/Drywall 3rd Floor 16 EA 7 10- years Water damage Walls - Plaster/Drywall 3rd Floor 15 SF 6 10- years Walls - Plaster/Drywall 3rd Floor 415 SF 6 10- years Walls - Plaster/Drywall 3rd Floor 8 EF 7 6-10 years Walls - Plaster/Drywall 3rd Floor 8 EF 7 6-10 years Walls - Plaster/Drywall 3rd Floor 930 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 7 10- years Walls - Plaster/Drywall 3rd Floor 3,071 SF 6 10- years 3,071 SF 6 10- years 3,071 SF 7 | | | | | | | • | |
| Floor - Wood | | | | | | | | |
| Lighting - Lay-in 3rd Floor 6 EA 7 6-10 years Marker Board 3rd Floor 8 LF 7 6-10 years Storage/ Closet 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 920 SF 7 10+ years Walls - Plaster/Drywall ST Plaster/Drywall | | | | · · | | | | |
| Marker Board 3rd Floor 40 SF 7 6-10 years | | | | | | | | |
| Storage/ Closet 3rd Floor 40 SF 7 10+ years | | | | | | | | |
| Calistro | | | | | | | | |
| AC Units | | | | | | | • | |
| AC Units | | Walls - Plaster/Drywall | 3rd Floor | 920 | SF | 7 | 10+ years | |
| Ceiling - Lay-in 3rd Floor 399 SF 7 10+ years | Classroo | | | | | | | |
| Ceiling - Lay-in 3rd Floor 16 SF 5 1-2 years Water damage | | | 3rd Floor | | | | 6-10 years | |
| Doors - Transom Window 3rd Floor 8 SF 7 10+ years | | Ceiling - Lay-in | 3rd Floor | 399 | | 7 | 10+ years | |
| Doors - Transom Window 3rd Floor 8 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Tile 3rd Floor 415 SF 6 10+ years Lighting - Lay-in 3rd Floor 6 EA 7 6-10 years Walls - Plaster/Drywall 3rd Floor 930 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 930 SF 7 10+ years Walls - Plaster/Drywall Walls - Plaster/Dry | | Ceiling - Lay-in | 3rd Floor | 16 | SF | 5 | 1-2 years | Water damage |
| Doors - Wood Doors inclu hw 3rd Floor 1 | | | 3rd Floor | 8 | SF | 7 | - | • |
| Floor - Tile | | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | | - | |
| Lighting - Lay-in 3rd Floor 6 EA 7 6-10 years Marker Board 3rd Floor 930 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 930 SF 7 10+ years Category : Interior Building : Main Group Item - Type Location Quantity UOM Rank Replacement Comments | | | | | | | | |
| Marker Board Street Stre | | | | | | | | |
| Walls - Plaster/Drywall 3rd Floor 930 SF 7 10+ years Category : Interior Building : Main Group Item - Type Location Quantity UOM Rank Recommend Replacement Corridor Corridor Ceiling - Lay-in 1st Floor 3,071 SF 7 10+ years Doors - Steel Doors incl hw 1st Floor 3 EA 6 10+ years Doors - Wood Doors include hw 1st Floor 12 EA 6 10+ years Drinking Fountains - Single Fountain 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Walls - Plaster/Drywall 1st Floor <td></td> <td>• • •</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | | • • • | | | | | | |
| Ceiling - Lay-in | | | | | | | • | |
| Item - Type Location Quantity UOM Rank Replacement Comments | Catego | rv : Interior | | R | uildina | · Main | | |
| Ceiling - Lay-in 1st Floor 3,071 SF 7 10+ years Doors - Steel Doors incl hw 1st Floor 3 EA 6 10+ years Doors - Wood Doors include hw 1st Floor 12 EA 6 10+ years Drinking Fountains - Single Fountain 1st Floor 3 EA 7 10+ years Drinking Fountains - Single Water Cooler 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | outogo. | | | | | | | |
| Ceiling - Lay-in 1st Floor 3,071 SF 7 10+ years Doors - Steel Doors incl hw 1st Floor 3 EA 6 10+ years Doors - Wood Doors include hw 1st Floor 12 EA 6 10+ years Drinking Fountains - Single Fountain 1st Floor 3 EA 7 10+ years Drinking Fountains - Single Water Cooler 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Doors - Steel Doors incl hw 1st Floor 3 EA 6 10+ years Doors - Wood Doors include hw 1st Floor 12 EA 6 10+ years Drinking Fountains - Single Fountain 1st Floor 3 EA 7 10+ years Drinking Fountains - Single Water Cooler 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | Jorridor | Cailing Lavin | 1ot Floor | 2.071 | | 7 | 10 | |
| Doors - Wood Doors include hw 1st Floor 12 EA 6 10+ years Drinking Fountains - Single Fountain 1st Floor 3 EA 7 10+ years Drinking Fountains - Single Water Cooler 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Walls - Plaster/Drywall 1st Floor 3,071 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | | | | | | • | |
| Drinking Fountains - Single Fountain Drinking Fountains - Single Water Cooler Drinking Fountains - Single Water Cooler Sloor - Concrete Epoxy/ Painted Sloor - Concrete Epoxy/ Painted Sloor - Single Water Cooler Sloor - Concrete Epoxy/ Painted Sloor - Single Water Cooler Sloor - Single Water Cooler Sloor - Single Water Cooler Sloor - Single Fountain Sloor - Single | | | | | | | • | |
| Drinking Fountains - Single Water Cooler 1st Floor 1 EA 7 10+ years Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | | | | | | • | |
| Floor - Concrete Epoxy/ Painted 1st Floor 3,071 SF 7 10+ years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | | | | | | | |
| Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 2 EA 7 10+ years Lighting - Pendent/Surface 1st Floor 35 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 4,481 SF 7 10+ years Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | | | · · | | | - | |
| Lighting - Pendent/Surface1st Floor2EA710+ yearsLighting - Pendent/Surface1st Floor35EA76-10 yearsWalls - Plaster/Drywall1st Floor4,481SF710+ yearsCeiling - Lay-in2nd Floor3,071SF610+ years | | | | 3,071 | | | | |
| Lighting - Pendent/Surface1st Floor35EA76-10 yearsWalls - Plaster/Drywall1st Floor4,481SF710+ yearsCeiling - Lay-in2nd Floor3,071SF610+ years | | | 1st Floor | | EA | 7 | | |
| Lighting - Pendent/Surface1st Floor35EA76-10 yearsWalls - Plaster/Drywall1st Floor4,481SF710+ yearsCeiling - Lay-in2nd Floor3,071SF610+ years | | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 7 | 10+ years | |
| Walls - Plaster/Drywall1st Floor4,481SF710+ yearsCeiling - Lay-in2nd Floor3,071SF610+ years | | | 1st Floor | | EA | 7 | | |
| Ceiling - Lay-in 2nd Floor 3,071 SF 6 10+ years | | | | | | | | |
| | | | | | | | | |
| Dining Contains Double Contain Englised | | | | | | | | |



| Catego | ry : Interior | | В | uilding | : Main | | |
|--------|--|-----------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Drinking Fountains - Single Fountain | 2nd Floor | 1 | EA | 5 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 2nd Floor | 3,071 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 29 | EA | 6 | 6-10 years | |
| | Student Lockers - One Tier | 2nd Floor | 8 | EA | 7 | 10+ years | New |
| | Student Lockers - Two Tiers | 2nd Floor | 140 | EA | 7 | 10+ years | New |
| | Walls - Plaster/Drywall | 2nd Floor | 4,481 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 3,071 | SF | 5 | 6-10 years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 3 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 3rd Floor | 3,071 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 29 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 4,481 | SF | 7 | 10+ years | |
| | | | | | | | |
| Safety | Security Comorce | Entire Building | 10 | EA | 7 | 10 | |
| | Security Cameras | Entire Building | 10 | EA | , | 10+ years | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | Stairwell # 1 (south) | 321 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Stairwell # 1 (south) | 590 | SF | 7 | 10+ years | |
| | Handrails | Stairwell # 1 (south) | 180 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Stairwell # 1 (south) | 6 | EA | 6 | 10+ years | |
| | Lighting - Wall Mounted | Stairwell # 1 (south) | 2 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | Stairwell # 1 (south) | 60 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Stairwell # 1 (south) | 2,052 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Stairwell # 2 (north) | 321 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Stairwell # 2 (north) | 590 | SF | 7 | 10+ years | |
| | Handrails | Stairwell # 2 (north) | 180 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Stairwell # 2 (north) | 6 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | Stairwell # 2 (north) | 2 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | Stairwell # 2 (north) | 60 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Stairwell # 2 (north) | 2,052 | SF | 7 | 10+ years | |
| | vvalio i lacioi/Diywali | Clairwoii # 2 (Horar) | 2,002 | O. | , | ioi youis | |





Building: Addition 2 Category : Exterior

| ugu | ry : Exterior | | | ullaing | . / (GGICI | J.: _ | |
|-------|--------------------------------------|-------------------------|----------|----------|------------|------------------------|----------|
| | | | | | | Recommend | |
| up | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Eau | pment | | | | | | |
| - 1- | Cell Equipment - Antenna | Roof | 3 | EA | 7 | 10+ years | |
| | Cell Equipment - Cabinets | Roof | 3 | EΑ | 7 | 10+ years | |
| | Och Equipment Odbinets | 11001 | 3 | L/\ | • | 101 years | |
| | | | | | | | |
| ance | | 0.0 \M+ Fl+ | 0 | | 7 | 40 | |
| | Exterior Doors - Exterior Steel Door | 3A-West Electrical Room | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 3A-West Electrical Room | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 3B-West Pump Room | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 3B-West Pump Room | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Side lite | Entrance 3-West | 4 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 3-West | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 3-West | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 4-NW | 2 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | Entrance 5-North | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | Entrance 5-North | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 5-North | 2 | EΑ | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Exit 2-South | 2 | EΑ | 6 | 10+ years | |
| | Entrance Control - Audio and Video | Main Entrance 1-South | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Store Front | Main Entrance 1-South | 6 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Main Entrance 1-South | 6 | EΑ | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Roof Access | 4 | EA | 7 | 10+ years | |
| | Exterior Stairs - Steel or Aluminum | Roof Access | 12 | LF | 7 | 10+ years | |
| | Exterior stairs - steer or Admiriant | Nooi Access | 12 | LI | , | 10+ years | |
| ndati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 628 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Caperolitation Clock | Litting Ballating | 70,200 | O1 | , | 101 youro | |
| ing | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 27 | EA | 7 | 10+ years | |
| ٠ | to me | | | | | | |
| _Sys | tem Access Ladder - Metal | Roof 1 | 1 | EA | 7 | 10+ years | |
| | Chimney - Metal Flue | Roof 1 | 25 | LF | 7 | 10+ years | |
| | Coping - Metal | Roof 1 | 50 | LF | 7 | 10+ years | |
| | Coping - Metal | Roof 1 | 410 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 1 | 195 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 1 | 300 | LF | 7 | 10+ years 10+ years | |
| | Parapet - 16 - 30 Height | Roof 1 | 50 | LF LF | 7 | 10+ years 10+ years | |
| | Roof - Modified Bitumen | | | SF | | | |
| | | Roof 1 | 5,830 | | 7 | 10+ years | |
| | Roof Hatch - Metal | Roof 1 | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | Roof 1 | 5,830 | SF | 7 | 10+ years | |
| | Concrete Topping | | • | | | • | |



| Catego | ry : Exterior | | В | Building : Addition 2 | | | | | |
|-----------|--|-----------------|-----------------------|-----------------------|------|-------------|---|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Access Ladder - Metal | Roof 2 | 1 | EA | 7 | 10+ years | | | |
| | Coping - Stone | Roof 2 | 675 | LF | 7 | 10+ years | | | |
| | Downspouts - Interior Downspouts | Roof 2 | 545 | LF | 6 | 10+ years | | | |
| | Parapet - Parapet < 16" Height | Roof 2 | 45 | LF | 7 | 10+ years | | | |
| | Parapet - Parapet > 30" | Roof 2 | 630 | LF | 7 | 10+ years | | | |
| | Roof - Modified Bitumen | Roof 2 | 15,035 | SF | 7 | 10+ years | | | |
| | Roof Hatch - Metal | Roof 2 | . 1 | EA | 7 | 10+ years | | | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof 2 | 15,035 | SF | 7 | 10+ years | | | |
| Valls | | | | | | | | | |
| | Cornice - Cast Stone | Entire Building | 700 | LF | 7 | 10+ years | | | |
| | Exterior Walls - Brick | Entire Building | 33,896 | SF | 7 | 10+ years | | | |
| | Exterior Walls - Concrete Block | Entire Building | 1,168 | SF | 7 | 10+ years | | | |
| | Exterior Walls - Stone-Cast | Entire Building | 6,834 | SF | 7 | 10+ years | | | |
| Vindows | | | | | | | | | |
| | Guard - Guards perforated | Entire Building | 2,294 | SF | 7 | 10+ years | | | |
| | Lintels - Steel | Entire Building | 906 | LF | 7 | 10+ years | | | |
| | Windows - Louver | Entire Building | 750 | SF | 7 | 10+ years | | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 6,590 | SF | 6 | 10+ years | | | |
| Catego | ry : Electrical | | Building : Addition 2 | | | | | | |
| | | | | | | Recommend | | | |
| ≩roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| merger | cy System | | | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 10+ years | | | |
| | Security System - CCTV | Entire Building | 70,296 | SF | 6 | 6-10 years | | | |
| | Security System - Intrusion Detection | Entire Building | 70,296 | SF | 6 | 6-10 years | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 19,592 | SF | 6 | 10+ years | | | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 29 | EA | 2 | 0-10 years | No batteries, no AC generator | | |
| /lain Sei | vice | | | | | | | | |
| | Main Electrical Service - 2000 A 277/480/3PH | Electrical Room | 1 | EA | 7 | 10+ years | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 7 | 10+ years | | | |
| | PA System | Entire Building | 70,296 | SF | 4 | 2-5 years | Serves addition 2 and other building Speakers in main building don't wor properly. Haven't upgraded since 1912, per principal concerns | | |



| Catego | ry : Electrical | | В | uilding | : Additi | | W Greenical Avenue, Officago, 12 00040 |
|------------|--|-------------------|----------|---------|----------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Dower D | istribution | | | | | | |
| _ Power D | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 16 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 2 | EA | 7 | 10+ years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 4 | EA | 7 | 10+ years | |
| Catego | ry : Fire Protection | | В | uilding | : Additi | on 2 | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Fire Alar | m | | | | | | |
| | Fire Alarm Panel | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm Panel | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm Strobe Lights | Mechanical Room | 70,296 | SF | 6 | 10+ years | |
| | Fire Alarm_System | Mechanical Room | 70,296 | SF | 5 | 6-10 years | |
| | Fire Pump Controller | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| _Pump R | oom Assembly | | | | | | |
| | Fire Pump - 25-50 hp | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Jockey Pump | Mechanical Room | 1 | EA | 6 | 10+ years | |
| Sprinkle | r Svetam | | | | | | |
| _ортпис | Sprinkler Heads | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Sprinkler Piping | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Wet Sprinkler System | Entire Building | 70,296 | SF | 6 | 10+ years | |
| Catego | ry : Mechanical | | В | uildina | : Additi | on 2 | |
| Galogo | . y i moonamou. | | _ | ununng | . , (| Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Air Conc | litioning | | | | | | |
| | Chemical Pot Feeder | Roof | 1 | EA | 6 | 6-10 years | |
| | Chiller-Air Cooled- Recipricating-Roof | Roof | 1 | EA | 7 | 10+ years | |
| | Mounted - 201 - 300 tons | | | | | - | |
| | Glycol Feed | Roof | 1 | EA | 7 | 10+ years | 2023 installed |
| | Pipes - Chilled Water Pipe- Copper | Roof | 100 | LF | 6 | 6-10 years | |
| | Pipes - Chilled Water Pipe- Steel | Roof | 400 | LF | 6 | 6-10 years | |
| | Pressure Fill System | Roof | 1 | EA | 6 | 6-10 years | |
| _Air Hand | lling Systems | | | | | | |
| | Fan Power Box - Fan Power Box with Hot | Entire Building | 25 | EA | 5 | 6-10 years | |
| | Water Coil | Fating Desiration | 4.0 | _ ^ | _ | 0.40 | |
| | Fan Power Box - Fan Power Box with Hot | Entire Building | 16 | EA | 5 | 6-10 years | |
| | | | | | | | |

Campus Name: Armstrong G Page : 24 of 60 Assessment Date: 11/07/2023



| Catego | Category : Mechanical | | В | uilding | : Additi | on 2 | , |
|-----------|--|-----------------|----------|---------|----------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Coil Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 17 | EA | 5 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Air Intake | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| | VAV Box | Mechanical Room | 2 | EA | 5 | 6-10 years | |
| | VAV Box | Mechanical Room | 6 | EA | 5 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | VAV Box | Mechanical Room | 7 | EA | 5 | 6-10 years | Difficult to access, 1999 installation |
| Boiler S | vstems | | | | | | |
| · | Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH | Boiler Room | 4 | EA | 6 | 6-10 years | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 4 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Water Fill System | Boiler Room | 1 | EA | 7 | 10+ years | 2023 installed |
| Gas Boo | ster | | | | | | |
| _ 303 500 | Gas Booster | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| Heating | Dovices | | | | | | |
| neaung_ | Unit Heater - Electric | Entire Building | 2 | EA | 6 | 6-10 years | |
| | 5 | Bananiy | _ | _, . | ŭ | 3 10 jouro | |



| Catego | ry : Mechanical | В | | | | | |
|-----------|--|-----------------|----------|---------|----------|-------------|------------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Unit Heater - Hot Water | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 8 | EA | 7 | 10+ years | |
| Mechan | ical Plumbing | | | | | | |
| | Hot Water Pump - 10 - 20 HP | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump - 10 - 20 HP | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | 6-10 years | Replaced in 2023 |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 6 | 6-10 years | Replaced in 2023 |
| | Hydronic Supply and Return - Copper | Entire Building | 1,300 | LF | 6 | 10+ years | • |
| | Hydronic Supply and Return - Steel | Entire Building | 600 | LF | 6 | 10+ years | |
| | Chilled Water Pump - 10 - 20 HP | Mechanical Room | 1 | EA | 7 | 10+ years | 2023 replaced |
| | Chilled Water Pump - 10 - 20 HP | Mechanical Room | 1 | EA | 7 | 10+ years | 2023 replaced |
| Tempera | ature Control | | | | | | |
| • | DDC System | Entire Building | 70,296 | SF | 5 | 6-10 years | |
| | Electric Thermostat | Entire Building | 8 | EA | 6 | 6-10 years | |
| | Thermostats - DDC | Entire Building | 73 | EA | 6 | 6-10 years | |
| Ventilati | on | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| Catego | ary · Plumhina | | R | uildina | · Additi | on 2 | |

Category : Plumbing **Building : Addition 2**

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|---|-----------------|----------|-----|------|--------------------------|----------|
| Hot Wat | er | | | | | <u>.</u> | |
| | Gas Heater - 150000 - 300000 BTU/HR | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| _Piping_ | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 70,296 | SF | 7 | 10+ years | |
| | Sanitary Piping | Entire Building | 70,296 | SF | 7 | 10+ years | |

Campus Name: Armstrong G Page : 26 of 60 Assessment Date: 11/07/2023



| Catego | Category : Plumbing | | | Building : Addition 2 | | | | | |
|--------|--------------------------------------|-----------------|----------|-----------------------|------|-------------|----------|--|--|
| | | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Storm Piping | Entire Building | 70,296 | SF | 7 | 10+ years | | | |
| | Vent Piping | Entire Building | 70,296 | SF | 7 | 10+ years | | | |
| _Pumps | | | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Mechanical Room | 1 | EA | 6 | 6-10 years | | | |
| | Pumps - Sump-Simplex | Mechanical Room | 1 | EA | 6 | 10+ years | | | |

Category: Room **Building: Addition 2**

| Calego | ry . Room | | D | unung | . Additi | OH Z | |
|----------|-----------------------------|------------------------------------|----------|-------|----------|---|------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Administ | trative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 1st Floor - Faculty Room | 476 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor - Faculty Room | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 1st Floor - Faculty Room | 476 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor - Faculty Room | 6 | ĒΑ | 7 | 6-10 years | |
| | Power Distribution | 1st Floor - Faculty Room | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor - Faculty Room | 739 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - Faculty Room | 336 | SF | 7 | 10+ years | |
| | Work SInk | 1st Floor - Faculty Room | 1 | ĒΑ | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor - Music Room Next to | 175 | SF | 7 | 10+ years | Quantity changed as total has been |
| | 5g | Staff Restroom | | - | - | , | aggregated/divided. |
| | Doors - Wood Doors inclu hw | 2nd Floor - Music Room Next to | 1 | EA | 7 | 10+ years | |
| | | Staff Restroom | | | | , , , , , , | |
| | Floor - Tile | 2nd Floor - Music Room Next to | 175 | SF | 7 | 10+ years | |
| | | Staff Restroom | | | | , , , , , , | |
| | Lighting - Lay-in | 2nd Floor - Music Room Next to | 3 | EA | 7 | 6-10 years | |
| | 3 * 3 * */ | Staff Restroom | | | | , | |
| | Power Distribution | 2nd Floor - Music Room Next to | 4 | EA | 7 | 10+ years | |
| | | Staff Restroom | | | | , , , , , , | |
| | Walls - Concrete Block | 2nd Floor - Music Room Next to | 653 | SF | 7 | 10+ years | |
| | | Staff Restroom | | | | , | |
| | Ceiling - Lay-in | 3rd floor - Next to Staff Restroom | 167 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd floor - Next to Staff Restroom | 8 | SF | 4 | 0-1 year | Damaged |
| | Doors - Wood Doors inclu hw | 3rd floor - Next to Staff Restroom | 1 | EA | 7 | 10+ years | G |
| | Floor - Tile | 3rd floor - Next to Staff Restroom | 175 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd floor - Next to Staff Restroom | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd floor - Next to Staff Restroom | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd floor - Next to Staff Restroom | 653 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | In room 221 | 175 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | In room 221 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | In room 221 | 175 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | In room 221 | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | In room 221 | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | In room 221 | 368 | SF | 7 | 10+ years | |
| | | | | | | • | |

Campus Name: Armstrong G Page : 27 of 60 Assessment Date: 11/07/2023



| Category : Room | | В | uilding | : Additi | on 2 | | |
|-----------------|-----------------------------|-------------------|----------|----------|--------|-------------|--|
| | | | | | | Recommend | |
| oup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | In room 221 | 176 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | In room 321 | 167 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | In room 321 | 8 | SF | 4 | 0-1 year | Damaged |
| | Doors - Wood Doors inclu hw | In room 321 | 1 | EA | 7 | 10+ years | - |
| | Floor - Tile | In room 321 | 175 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | In room 321 | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | In room 321 | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | In room 321 | 368 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | In room 321 | 176 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Library office | 141 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Library office | 8 | SF | 5 | 0-1 year | Damaged |
| | Doors - Transom Window | Library office | 15 | SF | 7 | 10+ years | Barragoa |
| | Doors - Wood Doors inclu hw | Library office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Library office | 149 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Library office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | Library office | 8 | EA | 7 | 10+ years | |
| | Storage/ Closet | | 68 | SF | 7 | • | |
| | | Library office | | SF SF | | 10+ years | |
| | Walls - Concrete Block | Library office | 170 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Library office | 309 | SF | 7 | 10+ years | |
| | Work SInk | Library office | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Main Office | 855 | SF | 7 | 10+ years | Quantity changed as total has be aggregated/divided. |
| | Doors - Side-lite | Main Office | 64 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Main Office | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | Main Office | 615 | SF | 7 | 6-10 years | |
| | Floor - Terrazzo | Main Office | 240 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Main Office | 13 | EA | 7 | 6-10 years | |
| | Power Distribution | Main Office | 16 | EA | 7 | 10+ years | |
| | Storage/ Closet | Main Office | 23 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Main Office | 1,809 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Main Office | 514 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Next to room 222A | 64 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Next to room 222A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Next to room 222A | 64 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Next to room 222A | 1 | EA | 5 | 10+ years | |
| | Power Distribution | Next to room 222A | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Next to room 222A | 160 | SF | 7 | 10+ years | |
| | | | 160 | SF | | - | |
| | Walls - Plaster/Drywall | Next to room 222A | 311 | SF SF | 5 7 | 10+ years | Quantity abanged as total bas ba |
| | Ceiling - Lay-in | Principals office | | | | 10+ years | Quantity changed as total has be aggregated/divided. |
| | Doors - Wood Doors inclu hw | Principals office | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | Principals office | 311 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | Principals office | 5 | EA | 7 | 6-10 years | |
| | Power Distribution | Principals office | 16 | EA | 7 | 10+ years | |



| Category : Room | | | Building : Addition 2 | | | | | | |
|-----------------|-----------------------------|----------------------|-----------------------|----------|--------|------------------------|---|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Walls - Concrete Block | Principals office | 501 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Principals office | 645 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Vault in main office | 221 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Vault in main office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | Vault in main office | 221 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Vault in main office | 4 | ĒΑ | 7 | 10+ years | | | |
| | Power Distribution | Vault in main office | 4 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Vault in main office | 560 | SF | 7 | 10+ years | | | |
| Library | | | | | | | | | |
| <u></u> | Casework | Room 222 | 191 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Room 222 | 1,562 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Room 222 | . 8 | SF | 4 | 0-1 year | Damaged | | |
| | Doors - Side-lite | Room 222 | 8 | SF | 7 | 10+ years | 3.1 | | |
| | Doors - Wood Doors inclu hw | Room 222 | 1 | ĒΑ | 7 | 10+ years | | | |
| | Floor - Carpet | Room 222 | 1,570 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | Room 222 | 18 | EA | 7 | 6-10 years | | | |
| | Walls - Concrete Block | Room 222 | 1,277 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Room 222 | 562 | SF | 7 | 10+ years | | | |
| MDF ID | F | | | | | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Finishes | 2nd Floor | 148 | SF | 7 | 10+ years | | | |
| | Other Cooling Unit | 2nd Floor | 1 | EA | 7 | 6-10 years | Ductless Split | | |
| Mechani | cal/ Service Rooms | | | | | | | | |
| | Janitor's Closet | 1st Floor | 28 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 1st Floor | 64 | SF | 7 | 10+ years | Quantity changed to update/correct to match current observation | | |
| | Mechanical/ Service Rooms | 1st Floor | 22 | SF | 7 | 10+ years | materi current observation | | |
| | Mechanical/ Service Rooms | 1st Floor | 170 | SF | 7 | 10+ years 10+ years | | | |
| | Mechanical/ Service Rooms | 1st Floor | 65 | SF SF | 7 7 | • | | | |
| | | | 305 | SF SF | 7 | 10+ years | Quantity abanged to undete/servent to | | |
| | Mechanical/ Service Rooms | 1st Floor | | | | 10+ years | Quantity changed to update/correct to match current observation | | |
| | Janitor's Closet | 2nd Floor | 28 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 2nd Floor | 64 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 2nd Floor | 22 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Janitor's Closet | 3rd Floor | 28 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 3rd Floor | 64 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 3rd Floor | 22 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 3rd Floor | 12 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 4th Floor | 4,630 | SF | 7 | 10+ years | | | |



| atego | gory : Room | | Building : Addition 2 | | | | | |
|--------|--------------------------------|------------------------|-----------------------|-----|------|-------------|----------|--|
| | | | | | | Recommend | | |
| oup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | | | | | | | | |
| stroor | | | | | | | | |
| | Accessories | 1st Floor | 241 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 241 | SF | 7 | 10+ years | | |
| | Floor - Terrazzo | 1st Floor | 241 | SF | 7 | 10+ years | | |
| | Floor Drain | 1st Floor | 2 | EA | 7 | 10+ years | | |
| | Hand Dryer | 1st Floor | 2 | EA | 7 | 6-10 years | | |
| | Lavatory | 1st Floor | 3 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 7 | EA | 7 | 6-10 years | | |
| | Partitions | 1st Floor | 3 | EA | 7 | 10+ years | | |
| | Urinals | 1st Floor | 3 | EA | 7 | 10+ years | | |
| | Walls - Structural Glazed Tile | 1st Floor | 995 | SF | 7 | 10+ years | | |
| | Water Closet | 1st Floor | 3 | ĒΑ | 7 | 10+ years | | |
| | Accessories | 1st Floor | 293 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 293 | SF | 7 | 10+ years | | |
| | Floor - Terrazzo | 1st Floor | 293 | SF | 7 | 10+ years | | |
| | Floor Drain | 1st Floor | 2 | EΑ | 7 | 10+ years | | |
| | Hand Dryer | 1st Floor | 2 | EΑ | 7 | 6-10 years | | |
| | Lavatory | 1st Floor | 3 | EΑ | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 7 | EΑ | 7 | 6-10 years | | |
| | Partitions | 1st Floor | 6 | EA | 7 | 10+ years | | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,155 | SF | 7 | 10+ years | | |
| | Water Closet | 1st Floor | 6 | EA | 7 | 10+ years | | |
| | Accessories | 2nd Floor | 241 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 241 | SF | 7 | 10+ years | | |
| | Floor - Terrazzo | 2nd Floor 2nd Floor | 241 | SF | 7 | | | |
| | | | | | | 10+ years | | |
| | Floor Drain | 2nd Floor | 2 | EΑ | 7 | 10+ years | | |
| | Hand Dryer | 2nd Floor | 2 | EΑ | 7 | 6-10 years | | |
| | Lavatory | 2nd Floor | 3 | EΑ | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 7 | EΑ | 7 | 6-10 years | | |
| | Partitions | 2nd Floor | 3 | EA | 7 | 10+ years | | |
| | Urinals | 2nd Floor | 3 | EA | 7 | 10+ years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 995 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd Floor | 3 | EA | 7 | 10+ years | | |
| | Accessories | 2nd Floor | 42 | SF | 7 | 6-10 years | | |
| | Ceiling - Lay-in | 2nd Floor | 42 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Terrazzo | 2nd Floor | 42 | SF | 7 | 10+ years | | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 213 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Accessories | 2nd Floor | 293 | SF | 7 | 6-10 years | | |



| Category : Room | | | Building : Addition 2 | | | | | | |
|-----------------|--------------------------------|-------------|-----------------------|-----|------|-------------|----------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 293 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 2nd Floor | 293 | SF | 7 | 10+ years | | | |
| | Floor Drain | 2nd Floor | 2 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Lavatory | 2nd Floor | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 7 | EA | 7 | 6-10 years | | | |
| | Partitions | 2nd Floor | 6 | EΑ | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 1,155 | SF | 7 | 10+ years | | | |
| | Water Closet | 2nd Floor | 6 | EΑ | 7 | 10+ years | | | |
| | Accessories | 3rd Floor | 241 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 241 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 3rd Floor | 241 | SF | 7 | 10+ years | | | |
| | Floor Drain | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 3rd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Lavatory | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 7 | EA | 7 | 6-10 years | | | |
| | Partitions | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Urinals | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 3rd Floor | 995 | SF | 7 | 10+ years | | | |
| | Water Closet | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Accessories | 3rd Floor | 42 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 38 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 5 | 1-2 years | Damaged ceiling tile | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | 3rd Floor | 42 | SF | 7 | 10+ years | | | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | 3rd Floor | 213 | SF | 7 | 10+ years | | | |
| | Water Closet | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 3rd Floor | 293 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 293 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 3rd Floor | 293 | SF | 7 | 10+ years | | | |
| | Floor Drain | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Lavatory | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 7 | EA | 7 | 6-10 years | | | |
| | Partitions | 3rd Floor | 6 | EΑ | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 3rd Floor | 1,155 | SF | 7 | 10+ years | | | |
| | Water Closet | 3rd Floor | 6 | ĒΑ | 7 | 10+ years | | | |
| | Accessories | In Room 110 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 110 | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 110 | 1 | EΑ | 7 | 10+ years | | | |
| | Floor - Terrazzo | In Room 110 | 36 | SF | 7 | 10+ years | | | |
| | | | | | - | , | | | |



| Catego | ry : Room | | Building : Addition 2 | | | | | | |
|--------|--------------------------------|-------------|-----------------------|-----|------|-------------|--|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor Drain | In Room 110 | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | In Room 110 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | In Room 110 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | In Room 110 | 200 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 110 | 1 | EA | 7 | 10+ years | | | |
| | Accessories | In Room 111 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 111 | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 111 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | In Room 111 | 36 | SF | 7 | 10+ years | | | |
| | Floor Drain | In Room 111 | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | In Room 111 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | In Room 111 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | In Room 111 | 200 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 111 | 1 | EA | 7 | 10+ years | | | |
| | Accessories | In Room 112 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 112 | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 112 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | In Room 112 | 36 | SF | 7 | 10+ years | | | |
| | Floor Drain | In Room 112 | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | In Room 112 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | In Room 112 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | In Room 112 | 200 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 112 | 1 | EA | 7 | 10+ years | | | |
| | Accessories | In Room 113 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 113 | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 113 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | In Room 113 | 36 | SF | 7 | 10+ years | | | |
| | Floor Drain | In Room 113 | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | In Room 113 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | In Room 113 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | In Room 113 | 200 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 113 | 1 | EA | 7 | 10+ years | | | |
| | Accessories | In Room 114 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 114 | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 114 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | In Room 114 | 36 | SF | 7 | 10+ years | | | |
| | Floor Drain | In Room 114 | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | In Room 114 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | In Room 114 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Structural Glazed Tile | In Room 114 | 200 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 114 | 1 | EA | 4 | 0-1 year | Toilet leaks from the seal in the floor when flushed | | |
| | Accessories | In Room 115 | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | In Room 115 | 36 | SF | 7 | 10+ years | | | |
| | , | | | | | , | | | |



| Category : Room | | Building : Addition 2 | | | | | | |
|-----------------|--------------------------------|-----------------------|----------|-----|------|-------------|----------|--|
| | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Doors - Wood Doors inclu hw | In Room 115 | 1 | EΑ | 7 | 10+ years | | |
| | Floor - Terrazzo | In Room 115 | 36 | SF | 7 | 10+ years | | |
| | Floor Drain | In Room 115 | 1 | EA | 7 | 10+ years | | |
| | Lavatory | In Room 115 | 1 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | In Room 115 | 1 | EA | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | In Room 115 | 200 | SF | 7 | 10+ years | | |
| | Water Closet | In Room 115 | 1 | EA | 7 | 10+ years | | |
| | Accessories | In Room 116 | 36 | SF | 7 | 6-10 years | | |
| | Ceiling - Lay-in | In Room 116 | 36 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | In Room 116 | 1 | EA | 7 | 10+ years | | |
| | Floor - Terrazzo | In Room 116 | 36 | SF | 7 | 10+ years | | |
| | Floor Drain | In Room 116 | 1 | EA | 7 | 10+ years | | |
| | Lavatory | In Room 116 | 1 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | In Room 116 | 1 | EA | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | In Room 116 | 200 | SF | 7 | 10+ years | | |
| | Water Closet | In Room 116 | 1 | EA | 7 | 10+ years | | |
| | Accessories | Main Office | 42 | SF | 7 | 6-10 years | | |
| | Ceiling - Lay-in | Main Office | 42 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Main Office | 1 | EΑ | 7 | 10+ years | | |
| | Floor - Terrazzo | Main Office | 42 | SF | 7 | 10+ years | | |
| | Floor Drain | Main Office | 1 | EA | 7 | 10+ years | | |
| | Lavatory | Main Office | 1 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | Main Office | 1 | EA | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | Main Office | 233 | SF | 7 | 10+ years | | |
| | Water Closet | Main Office | 1 | EA | 7 | 10+ years | | |

Category : Classroom **Building: Addition 2**

| | | | | | | Recommend | |
|----------|-----------------------------|-----------|----------|-----|------|-------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Classro | om #110 (Pre School) | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 46 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,060 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 326 | SF | 6 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |

Campus Name: Armstrong G Page : 33 of 60 Assessment Date: 11/07/2023



| Category : Classroom | | В | Building : Addition 2 | | | | |
|----------------------|-----------------------------|-----------|-----------------------|-------|------|-------------|----------|
| | | | | Recon | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #111 (Pre School) | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,172 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,172 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 692 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 692 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| | | | | | | | |
| _Classroo | m #112 (Pre School) | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,220 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 17 | EΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 754 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 612 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| | | | | | | | |
| _Classroo | m #113 (Pre School) | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,172 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,172 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 692 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 692 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| Classroo | m #114 (Kindergarten) | | | | | | |



| Category : Classroom | | | Building : Addition 2 | | | | | | |
|----------------------|-----------------------------|-----------|-----------------------|-----|------|-------------|------------------------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | | | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 17 | EΑ | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 754 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 612 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| Classroo | om #115 (Kindergarten) | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 1,172 | SF | 7 | 10+ years | Quantity changed as total has been | | |
| | | | • | | | - | aggregated/divided. | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | | | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 1,172 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 692 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 692 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| _Classroo | om #116 (Kindergarten) | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 1,196 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 24 | SF | 4 | 0-1 year | Water damage | | |
| | Chalk Board | 1st Floor | 50 | LF | 4 | 2-5 years | Trator damage | | |
| | Doors - Side-lite | 1st Floor | 8 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 1,220 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 50 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 1,060 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 306 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| | WOLK SILIK | 191 LIOOI | 2 | EA | , | 10+ years | | | |



| Category : Classroom | | Building : Addition 2 | | | | | |
|----------------------|-----------------------------|-----------------------|----------|-------|------|-------------|--|
| 0 | H | Landi | 0 4" | 11014 | D | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #117/119 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 54 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 900 | SF | 7 | 10+ years | Quantity changed as total has been aggregated/divided. |
| | Doors - Side-lite | 1st Floor | 16 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 10 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 728 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 728 | SF | 7 | 10+ years | |
| Classroo | m #213 (Special Program) | | | | | | |
| | Casework | 2nd Floor | 23 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 450 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 450 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 6 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 364 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 238 | SF | 7 | 10+ years | |
| Classroo | m #214 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 924 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 237 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #215 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 28 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 2nd Floor | 925 | SF | 7 | 10+ years | |
| | Centring - Lay-III | 2110 1 1001 | 923 | OI. | ı | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Additi | | ov Greenical Avenue, Gricago, le 60045 |
|----------|-----------------------------------|------------------------|----------|---------|----------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 925 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 414 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 60 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #216 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | | 2nd Floor | 12 | EA | 7 | • | |
| | Lighting - Lay-in Marker Board | 2nd Floor 2nd Floor | | LF | 7 | 6-10 years | |
| | | | 10 | | | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 474 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #217 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 474 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #218 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Coming Lay III | 2110 1 1001 | 300 | Oi. | , | ioi yeais | |



| Catego | ry : Classroom | | В | uilding | : Additi | | |
|---------|-----------------------------|------------------------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 470 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 4 | SF | 5 | 1-2 years | Cracked |
| | Walls - Plaster/Drywall | 2nd Floor | 699 | SF | 7 | 10+ years | Cracked |
| | | | | | 7 | | |
| | Work Sink | 2nd Floor | 1 | EA | / | 10+ years | |
| lassroc | om #219 (Language Lab) | | | | | | |
| | Casework | 2nd Floor | 22 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 450 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 450 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 6-10 years | |
| | | | 10 | LF | 7 | , | |
| | Marker Board | 2nd Floor | - | | | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 364 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 364 | SF | 7 | 10+ years | |
| lassroc | om #220 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | | LF | 7 | | |
| | | | 8 | | | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 640 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| lassroc | om #221 (Art Room) | | | | | | |
| | Casework | 2nd Floor | 58 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,024 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 8 | SF | 4 | 0-1 year | Damaged |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | Damagea |
| | Doors - Side-lite | | 8 | SF | 7 | • | |
| | Doors - Side-life | 2nd Floor | 8 | 2L | 1 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | |
|----------|------------------------------|------------------------|-----------------|---------|----------|------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,034 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 637 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 577 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 60 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | 10+ years | |
| Classroo | om #222A (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 49 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 653 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 653 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 374 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,004 | SF | 7 | • | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,004 | SF | 6 | 10+ years 10+ years | |
| | Walls - Flastel/Drywall | 2110 1 1001 | 20 | Si | O | 10+ years | |
| Classroc | om #223 (Computer Lab) | | | | | | |
| | Casework | 2nd Floor | 130 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,221 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,221 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | ['] 16 | ĒΑ | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 132 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 703 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 703 | SF | 7 | 10+ years | |
| Classroo | om #225 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 20 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 425 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 425 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 6-10 years | |
| | | 2nd Floor 2nd Floor | 10 | LF | 7 7 | • | |
| | Marker Board | | | | | 6-10 years | |



| Category : Classroom | | | Building : Addition 2 | | | | | |
|----------------------|---------------------------------|-----------|-----------------------|----------|--------|-------------|--------------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Storage/ Closet | 2nd Floor | 5 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 2nd Floor | 602 | SF | 7 | 10+ years | | |
| _Classroo | om #313 (Special Program) | | | | | | | |
| | Casework | 3rd Floor | 20 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 394 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 24 | SF | 4 | 0-1 year | Water damage | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | g- | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | | |
| | Floor - Tile | 3rd Floor | 398 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 3rd Floor | 331 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 223 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | | SF | 6 | | | |
| | walls - Plaster/Drywall | 31d F1001 | 20 | SF | 0 | 10+ years | | |
| Classroo | om #314/316 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 902 | SF | 7 | 10+ years | | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | 3rd Floor | 918 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | | |
| | Walls - Concrete Block | 3rd Floor | 730 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 320 | SF | 7 | 10+ years | | |
| Classro | om #315 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 895 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 30 | SF | 4 | 0-1 year | Water damage | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | water damage | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 0 | Sr EA | 7 | | | |
| | Floor - Tile | 3rd Floor | 925 | SF | 7 7 | 10+ years | | |
| | | | | | | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 3rd Floor | 699 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 494 | SF | 7 | 10+ years | | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | |
|-----------|-----------------------------|-----------|----------|---------|----------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | om #317 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 26 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 876 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 5 | 1-2 years | Water damage |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 880 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 477 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| _Classroo | om #318 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 899 | SF | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Lay-in | 3rd Floor | 12 | EΑ | 7 | 6-10 years | • |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 699 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #319 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 377 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 377 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 330 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 320 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | |
|-----------|-----------------------------|-----------|----------|---------|----------|-------------|--------------|
| | | | <u> </u> | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Classroo | m #320 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 699 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #321 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 45 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,034 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,034 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 637 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 637 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 7 | 10+ years | |
| Classroo | m #322 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 890 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 10 | SF | 5 | 1-2 years | Water damage |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | Ü |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 640 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | - | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | · · |
|----------|-----------------------------|------------|----------|----------|----------|-------------|----------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | om #323 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 453 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 12 | SF | 5 | 1-2 years | Water damage |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 465 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | 6-10 years | |
| | | 3rd Floor | 5 | SF | 7 | | |
| | Storage/ Closet | 3rd Floor | 366 | SF SF | | 10+ years | |
| | Walls - Concrete Block | | | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 264 | SF | 7 | 10+ years | |
| Classroo | om #324 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 888 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 12 | SF | 5 | 1-2 years | Water damage |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | Traiter damage |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 410 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 640 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | WORK SILIK | 314 (100) | ' | LA | , | 10+ years | |
| Classroo | om #325 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 28 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 905 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | - |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 925 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 454 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 40 | SF | 6 | 10+ years | |
| | vvalis - i lastel/DiyWall | 310 1 1001 | 40 | JF | U | 10+ years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | |
|-----------|-----------------------------|------------------------|----------|----------|----------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #326 (Regular Classroom) | | | | | | |
| Classion | , , | 3rd Floor | 40 | LF | 7 | 10 | |
| | Casework | 3rd Floor 3rd Floor | 40 | SF | 7 7 | 10+ years | |
| | Ceiling - Lay-in | | 898 | SF LF | - | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | SF | 4 7 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | | - | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 474 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 679 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 20 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| _Classroo | om #327 (Special Program) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 446 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 450 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 364 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 243 | SF | 7 | 10+ years | |
| | Traile Tracton 21, Trail | 0.4 1.60. | 210 | O. | • | io. youro | |
| _Classroo | om #328 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 30 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 5 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 699 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 474 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |



| Categor | y : Interior | | В | uilding | : Additi | on 2 | |
|----------|--|-----------------|----------|---------|----------|-------------|--------------|
| | _ | | | | | Recommend | _ |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 7,073 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 24 | SF | 4 | 0-1 year | Damaged |
| | Ceiling - Plaster/Drywall | 1st Floor | 60 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 11 | EΑ | 7 | 10+ years | |
| | Doors - Store Front | 1st Floor | 10 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 7,097 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 143 | EΑ | 7 | 6-10 years | |
| | Stairs - Terrazzo | 1st Floor | 36 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 11,684 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 5,633 | SF | 7 | 10+ years | 5 |
| | Ceiling - Lay-in | 2nd Floor | 4 | SF | 4 | 0-1 year | Damaged |
| | Doors - Steel Doors incl hw | 2nd Floor | 10 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | _ 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 2nd Floor | 5,647 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 120 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 7,636 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 5,627 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Doors - Steel Doors incl hw | 3rd Floor | 10 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor | 5,647 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 120 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 7,636 | SF | 7 | 10+ years | |
| Safety | | | | | | | |
| , | Camera Viewing Station | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 4 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 2 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 2 | EA | 7 | 6-10 years | |
| _Stairs | | | | | | | |
| | Ceiling - Exposed | Stairwell #1 | 72 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Stairwell #1 | 478 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Stairwell #1 | 373 | SF | 7 | 10+ years | |
| | Handrails | Stairwell #1 | 130 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Stairwell #1 | 10 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Stairwell #1 | 2 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Stairwell #1 | 54 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Stairwell #1 | 1,874 | SF | 7 | 10+ years | |
| | Ceiling - Exposed | Stairwell #2 | 356 | SF | 7 | 10+ years | |
| | Coming Exposor | Can won #2 | 550 | J1 | , | ioi youis | |



| Catego | ry : Interior | | В | uilding | : Addition | on 2 | |
|----------|-------------------------------|--------------|----------|---------|------------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | Stairwell #2 | 329 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Stairwell #2 | 12 | SF | 4 | 0-1 year | Damaged |
| | Floor - Terrazzo | Stairwell #2 | 455 | SF | 7 | 10+ years | |
| | Handrails | Stairwell #2 | 162 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Stairwell #2 | 6 | EΑ | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Stairwell #2 | 1 | EΑ | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Stairwell #2 | 4 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Stairwell #2 | 77 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Stairwell #2 | 4,070 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Stairwell #2 | 45 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Stairwell #3 | 480 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Stairwell #3 | 373 | SF | 7 | 10+ years | |
| | Handrails | Stairwell #3 | 130 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Stairwell #3 | 8 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Stairwell #3 | 2 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Stairwell #3 | 54 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Stairwell #3 | 1,874 | SF | 7 | 10+ years | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 6 | 10+ years | |





Category : Exterior **Building: Addition-Gymnasium**

| Culogo. | y . Exterior | | _ | an an ig | . , (| Recommend | · |
|-----------|---------------------------------------|----------------------------------|----------|------------|-------|-------------|-----------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | , | | | J J | | | 2 3 |
| Lilliance | Exterior Doors - Exterior Steel Door | Entrance 13-East / Kitchen | 2 | EA | 6 | 2-5 years | |
| | Exterior Doors - Exterior Steel Door | Entrance 14-SE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | Entrance 14-SE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 14-SE | 2 | EΑ | 6 | 10+ years | |
| | Exterior Stairs - Concrete | Entrance 14-SE | 30 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | Entrance 14-SE | 25 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Entrance 15-South | 2 | ĒΑ | 5 | 2-5 years | |
| | Exterior Doors - Side lite | Entrance 15-South | 2 | EA | 4 | 1-2 years | Corroded |
| | Exterior Doors - Transom Lite | Entrance 15-South | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Entrance 15A-South / Inner court | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | Entrance 15A-South / Inner court | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | Entrance 15A-South / Inner court | 2 | EA | 7 | 10+ years | |
| | | | | | | • | |
| Foundati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 244 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 5,637 | SF | 7 | 10+ years | |
| | | - | | | | • | |
| Lighting | | | | | | | |
| 0 0 | Exterior Lighting - Wall Mounted | Entire Building | 6 | EA | 7 | 10+ years | |
| | 3 3 | 3 | | | | , | |
| Roof Sys | tem | | | | | | |
| , | Access Ladder - Metal | Roof 6 | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | Roof 6 | 260 | LF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | Roof 6 | 135 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 6 | 88 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof 6 | 260 | LF | 7 | 10+ years | |
| | Roof - Metal | Roof 6 | 1,920 | SF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Roof 6 | 3,717 | SF | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | Roof 6 | 5,637 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| | | | | | | | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 6,336 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 244 | SF | 7 | 10+ years | |
| | | | | | | | |
| _Windows | | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 413 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 98 | LF | 7 | 10+ years | |
| | Windows - Decorative | Entire Building | 745 | SF | 6 | 10+ years | Recombined quantities |
| | | | | | | | |



| Catego | ry : Electrical | | В | uilding | : Additio | on-Gymnasiun | <u> </u> |
|-----------|--|-----------------|----------|---------|-----------|--------------|-------------------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerger | ncy System | | | | | | |
| | Security System - CCTV | Entire Building | 5,637 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 5,637 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 758 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 1,646 | SF | 6 | 10+ years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 2 | EA | 2 | 0-1 year | No batteries, no AC generator |
| | Exit Signs - Gym | Entire Building | 2 | EA | 2 | 0-1 year | No batteries, no AC generator |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 2 | EA | 6 | 6-10 years | |
| Main Se | | | | | | | |
| | PA System | Entire Building | 5,637 | SF | 6 | 6-10 years | |
| Catego | ry : Fire Protection | | В | uilding | : Additio | on-Gymnasiun | 1 |
| O | Hom. Time | Location | Quantity | UOM | Dank | Recommend | Comments |
| Group | Item - Type | Location | Quantity | UOW | Rank | Replacement | Comments |
| Fire Alar | | E 6 B 3 B | 5.007 | 05 | | 0.40 | |
| | Fire Alarm Strobe Lights | Entire Building | 5,637 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 5,637 | SF | 5 | 6-10 years | |
| Sprinkle | System | | | | | | |
| · | Sprinkler Heads | Entire Building | 5,637 | SF | 7 | 10+ years | |
| | Sprinkler Piping | Entire Building | 5,637 | SF | 7 | 10+ years | |
| | Wet Sprinkler System | Entire Building | 5,637 | SF | 7 | 10+ years | |
| Catego | ry : Mechanical | | В | uilding | : Additio | on-Gymnasiun | 1 |
| | _ | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | lling Systems | | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted- | Roof | 1 | EA | 7 | 10+ years | |
| | DX Cooling Only with Self Contained Compressor - 21 - 30 tons | | | | | | |
| Tempera | | | | | | | |
| Tempera | Compressor - 21 - 30 tons | Entire Building | 5,637 | SF | 7 | 10+ years | Not connected to DDC yet |



| Catego | Category : Plumbing | | | Building : Addition-Gymnasium | | | | | |
|----------|---------------------|-----------------|----------|-------------------------------|------|-------------|----------|--|--|
| | | Recommend | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| _Piping_ | | | | | | | | | |
| | Storm Piping | Entire Building | 5,637 | SF | 6 | 10+ years | | | |
| | Vent Piping | Entire Building | 5,637 | SF | 6 | 10+ years | | | |

Category : Room **Building** · Addition-Gymnasium

| Catego | ry : Room | | Building : Addition-Gymnasium | | | | | | |
|----------|-----------------------------|---|-------------------------------|-----|------|-------------|----------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Administ | rative Suites/Offices | | | | | | | | |
| | Ceiling - Lay-in | 103A, Gym Teacher's Office | 185 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 103A, Gym Teacher's Office | 4 | SF | 5 | 1-2 years | Missing ceiling tile | | |
| | Doors - Steel Doors incl hw | 103A, Gym Teacher's Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 103A, Gym Teacher's Office | 189 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 103A, Gym Teacher's Office | 2 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 103A, Gym Teacher's Office | 6 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 103A, Gym Teacher's Office | 451 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Faculty Lounge | 273 | SF | 7 | 10+ years | | | |
| | Floor - Tile | Faculty Lounge | 273 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | Faculty Lounge | 2 | EA | 7 | 6-10 years | | | |
| | Power Distribution | Faculty Lounge | 6 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Faculty Lounge | 614 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Parent's Room | 248 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Parent's Room | 4 | SF | 5 | 1-2 years | Missing ceiling tile | | |
| | Doors - Wood Doors inclu hw | Parent's Room | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | Parent's Room | 252 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Parent's Room | 2 | EA | 7 | 6-10 years | | | |
| | Power Distribution | Parent's Room | 8 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Parent's Room | 655 | SF | 7 | 10+ years | | | |
| Gymnasi | a | | | | | | | | |
| - | Ceiling - Exposed | 1st Floor | 1,646 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Sport Flooring | 1st Floor | 1,646 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | 6-10 years | | | |
| | Sound System | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 5,244 | SF | 7 | 10+ years | | | |
| Restroon | n | | | | | | | | |
| | Accessories | Gender Neutral Across from Parent's Room | 47 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | Gender Neutral Across from Parent's Room | 47 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Gender Neutral Across from Parent's Room | 1 | EA | 7 | 10+ years | | | |



| Catego | ry : Room | | Building : Addition-Gymnasium | | | | | | |
|--------|---|--|-------------------------------|----------|--------|------------------------|--------------|--|--|
| | | | | _ | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor - Concrete Epoxy/ Painted | Gender Neutral Across from | 47 | SF | 7 | 10+ years | | | |
| | | Parent's Room | | | | | | | |
| | Floor Drain | Gender Neutral Across from | 1 | EA | 7 | 10+ years | | | |
| | | Parent's Room | | | | | | | |
| | Lavatory | Gender Neutral Across from | 1 | EA | 7 | 10+ years | | | |
| | | Parent's Room | | | | | | | |
| | Lighting - Lay-in | Gender Neutral Across from | 1 | EA | 7 | 6-10 years | | | |
| | | Parent's Room | | | _ | | | | |
| | Walls - Concrete Block Gender Neutral Across from Parent's Room | | 122 | SF | 7 | 10+ years | | | |
| | | | | | _ | | | | |
| | Water Closet | Gender Neutral Across from | 1 | EA | 7 | 10+ years | | | |
| | Parent's Room Ceiling - Plaster/Drywall Gender Neutral across Parents Rom | | 07 | 0.5 | - | 40 | | | |
| | | | 37 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Gender Neutral across Parents Rom | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile Floor Drain | Gender Neutral across Parents Rom | 37 | SF EA | 7 7 | 10+ years | | | |
| | | Gender Neutral across Parents Rom | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | Gender Neutral across Parents Rom Gender Neutral across Parents Rom | 1 | EA EA | 7 | 10+ years | | | |
| | Lighting - Lay-in Walls - Concrete Block | Gender Neutral across Parents Rom | 112 | SF | 7 | 6-10 years | | | |
| | Water Closet | Gender Neutral across Parents Rom | 112 | EA | 7 | 10+ years | | | |
| | Accessories | Toilet locker room | 1 | SF | 7 | 10+ years 10+ years | | | |
| | Ceiling - Lay-in | Toilet locker room | 34 | SF | 6 | 6-10 years | | | |
| | Ceiling - Lay-in | Toilet locker room Toilet locker room | 8 | SF | 5 | 0-10 years 0-1 year | Damaged tile | | |
| | Doors - Wood Doors inclu hw | Toilet locker room | 2 | EA | 7 | 10+ years | Damaged tile | | |
| | Floor - Epoxy/ Painted | Toilet locker room | 42 | SF | 7 | 10+ years | | | |
| | Floor Drain | Toilet locker room | 1 | EA | 7 | 10+ years | | | |
| | Hand Dryer | Toilet locker room | i i | EA | 7 | 10+ years | | | |
| | Lavatory | Toilet locker room | 1 | EΑ | 7 | 10+ years | | | |
| | Lighting - Lay-in | Toilet locker room | 2 | EΑ | 7 | 10+ years | | | |
| | Student Lockers - One Tier | Toilet locker room | 1 | EΑ | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Toilet locker room | 260 | SF | 7 | 10+ years | | | |
| | Water Closet | Toilet locker room | 1 | EΑ | 7 | 10+ years | | | |
| | | | | | | - , | | | |

Category: Interior Building: Addition-Gymnasium

| <u> </u> | | | | J | | Recommend | |
|----------|-----------------------------|-----------|----------|-----|------|-------------|--------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 742 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 16 | SF | 5 | 1-2 years | Water damage |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EΑ | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 758 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,365 | SF | 7 | 10+ years | |



| Catego | ry : Interior | | В | 1 | | | |
|--------|------------------|-----------------|----------|-----|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| Safety | | | | | | | |
| , | Security Cameras | Entire Building | 1 | EA | 7 | 6-10 years | |

Campus Name: Armstrong G Page : 51 of 60 Assessment Date: 11/07/2023



| Category : Exterior | Building : Addition-Lunchroom/Kitchen |
|---------------------|---------------------------------------|
| outogoly i =xtolioi | |

| Jacogo | y . Exterior | | | ug | . , (4476) | Recommend | , |
|-------------------|--|------------------------------------|----------------|----------|---------------|------------------------|-----------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | , | | 444 | | | Tio piacomonic | |
| LIMANOC | Exterior Doors - Exterior Steel Door | Entrance 8A-NE / Outside Yard | 2 | EA | 6 | 10+ years | |
| | Exterior Boors Exterior Gleer Boor | Storage | _ | L/ \ | O | 101 years | |
| | Exterior Doors - Exterior Steel Door | Exit 10-NE / Lunchroom | 1 | EA | 5 | 2-5 years | Rusted frame |
| | Ramp Handrail - Steel_Ramp Handrail | Exit 10-NE / Lunchroom | 115 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Exit 10-NE / Lunchroom | 55 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Exit 11-East / Lunchroom | 1 | EA | 6 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Exit 11-East / Lunchroom | 140 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Exit 11-East / Lunchroom | 55 | LF | 5 | 2-5 years | |
| | Exterior Doors - Exterior Steel Door | Exit 12-East | 1 | EA | 5 | 2-5 years | Rusted door and frame |
| | Exterior Stairs - Concrete | Exit 12-East | 25 | LF | 7 | 6-10 years | |
| | Stair Handrail - Steel_Stair Handrail | Exit 12-East | 12 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Exit 9-SW / Lunchroom | 2 | EA | 7 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | Exit 9-SW / Lunchroom | 40 | LF | 7 | 10+ years | |
| | Ramps - Concrete | Exit 9-SW / Lunchroom | 10 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Roof Access Door | 1 | EA | 6 | 2-5 years | |
| | Exterior Stairs - Steel or Aluminum | Roof Access Door | 3 | LF | 7 | 6-10 years | |
| oundati | on | | | | | | |
| <u>ouridan</u> | Foundation - Concrete | Entire Building | 338 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 9,359 | SF | 7 | 10+ years | |
| i au la 4 i ao au | | | | | | | |
| ghting_ | Exterior Lighting - Wall Mounted | Entire Building | 10 | EA | 7 | 10+ years | |
| oof Sys | tom | | | | | | |
| OOI Oys | Access Ladder - Metal | Roof 5 | 1 | EA | 7 | 10+ years | |
| | Chimney - Metal Flue | Roof 5 | 5 | LF | 7 | 10+ years | Corrected quantity |
| | Coping - Stone | Roof 5 | 380 | LF | 7 | 10+ years | Corrected quartity |
| | Downspouts - Interior Downspouts | Roof 5 | 150 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Roof 5 | 380 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | Roof 5 | 9,359 | SF | 5 | 2-5 years | |
| | Roof Hatch - Metal | Roof 5 | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | Roof 5 | 9,359 | SF | 7 | 10+ years | |
| | Concrete Topping | | 0,000 | • | • | .o. you.o | |
| | | | | | | | |
| /alls | Cheek-Wall - Concrete | Entire Building | 570 | SF | 6 | 10 L VOORS | |
| | Exterior Walls - Brick | Entire Building Entire Building | 9,180 | SF SF | 7 | 10+ years 10+ years | Recombined quantities |
| | Exterior Walls - Brick Exterior Walls - Stone-Cast | Entire Building Entire Building | 9,180 2,704 | SF SF | <i>7</i> 6 | • | Recombined quantities |
| | EXIGNOL MAILS - STOLLE-CASE | Little building | 2,704 | ЭF | O | 10+ years | |
| | | | | | | | |



| Catego | ry : Exterior | | В | Building : Addition-Lunchroom/Kitchen | | | | | |
|-----------|--|-----------------|----------|---------------------------------------|-----------|--------------|-------------------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Vindows | | | | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 336 | SF | 7 | 10+ years | | | |
| | Lintels - Steel | Entire Building | 64 | LF | 7 | 10+ years | | | |
| | Windows - Louver | Entire Building | 80 | SF | 7 | 10+ years | | | |
| Catego | ry : Electrical | | В | uilding | : Additio | on-Lunchroom | /Kitchen | | |
| | | 1 | 0 | | D | Recommend | • | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Emerger | ncy System | | | | | | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 1,341 | SF | 6 | 6-10 years | | | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 5,733 | SF | 6 | 6-10 years | | | |
| | Security System - CCTV | Entire Building | 9,359 | SF | 6 | 6-10 years | | | |
| | Security System - Intrusion Detection | Entire Building | 9,359 | SF | 6 | 6-10 years | | | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 2 | EA | 6 | 6-10 years | | | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 5 | EA | 6 | 6-10 years | | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 2 | EA | 2 | 0-1 year | No batteries, no AC generator | | |
| | Exit Signs - Lunchroom | Entire Building | 6 | EA | 2 | 0-1 year | No batteries, no AC generator | | |
| Main Se | vice | | | | | | | | |
| | PA System | Entire Building | 9,359 | SF | 6 | 6-10 years | | | |
| Power D | istribution | | | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 7 | 10+ years | | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 6-10 years | | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 4 | 1-2 years | Rust on panel | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | · | | |
| Catego | ry : Fire Protection | | В | uilding | : Additio | on-Lunchroom | /Kitchen | | |
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Fire Alar | m | | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 9,359 | SF | 6 | 6-10 years | | | |
| | Fire Alarm_System | Entire Building | 9,359 | SF | 5 | 6-10 years | | | |
| Sprinklei | System | | | | | | | | |
| | | | | | | | | | |



| Catego | ry : Mechanical | | В | Building : Addition-Lunchroom/Kitchen | | | | | |
|-------------|--|----------------------|----------|---------------------------------------|------|-------------|--|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Air Hand | lling Systems | | | | | | | | |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Kitchen / Lunch room | 4 | EA | 5 | 6-10 years | | | |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Kitchen / Lunch room | 5 | EA | 5 | 6-10 years | | | |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | | | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | | | |
| | Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm | Roof | 1 | EA | 3 | 2-5 years | MAU -1 requires frequent maintenance, old, serves kitchen, 1999 insulation | | |
| _Heating | | | | | | | | | |
| | Unit Heater - Electric | Entire Building | 1 | EA | 6 | 6-10 years | | | |
| | Unit Heater - Hot Water | Entire Building | 3 | EA | 6 | 6-10 years | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 2 | EA | 6 | 6-10 years | | | |
| | Cabinet Heaters - With Electric Coil | Entire Building | 1 | EA | 6 | 6-10 years | | | |
| Mechani | cal Plumbing | | | | | | | | |
| | Hydronic Supply and Return - Copper | Entire Building | 150 | LF | 6 | 6-10 years | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 100 | LF | 6 | 6-10 years | | | |
| | Hot Water Pump - Less than 10 | Mechanical Room | 1 | ĒΑ | 6 | 6-10 years | | | |
| Tempera | ature Control | | | | | | | | |
| _тетрен | DDC System | Entire Building | 9,359 | SF | 4 | 2-5 years | Software not upgraded recently, 1999 installation | | |
| | Electric Thermostat | Entire Building | 4 | EA | 5 | 6-10 years | | | |
| | Thermostats - DDC | Entire Building | 9 | EA | 6 | 6-10 years | | | |
| Ventilation | on | | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | | | |
| | Roof Mounted Duct Work | Entire Building | 10 | LF | 5 | 6-10 years | | | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 10+ years | | | |
| | ·· · | Ç | | | | ŕ | | | |

Campus Name: Armstrong G Page : 54 of 60 Assessment Date: 11/07/2023



| Categor | y : Plumbing | | Building : Addition-Lunchroom/Kitchen Recommend | | | | | |
|-----------|--|------------------|---|----------|-----------|------------------------|----------------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Hot Wate | · · | 200411011 | Quantity | 00 | rtariit | replacement | | |
| IUL Wate | Gas Heater - 150000 - 300000 BTU/HR | Mechanical Room | 1 | EA | 6 | 6 10 vooro | 2021 installed | |
| | Gas Heater - 150000 - 300000 BTU/HR | Mechanical Room | 1 | EA | 6 5 | 6-10 years | 2021 installed 2021 installed | |
| | Gas Healer - 150000 - 500000 BT0/HR | Mechanical Room | 1 | EA | 3 | 6-10 years | 2021 Installed | |
| Dining | | | | | | | | |
| Piping | Demostic Dinion Het Weten Detum Lines | Eutina Duildin a | 0.050 | 0.5 | 7 | 40 | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 9,359 | SF SF | 7 | 10+ years | | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 9,359 | 5F | 7 | 10+ years | | |
| | Domestic Piping-Hot/Cold Water Supply | Entire Building | 0.250 | SF | 7 | 10 L Vooro | | |
| | | Entire Building | 9,359 | SF | , | 10+ years | | |
| | (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply | Entire Building | 9,359 | SF | 7 | 10± vears | | |
| | (from Risers to Fixtures) | Entire Building | 9,339 | SF | , | 10+ years | | |
| | Sanitary Piping | Entire Building | 9,359 | SF | 7 | 10± vears | | |
| | Storm Piping | Entire Building | 9,359 | SF | 7 | 10+ years 10+ years | | |
| | Vent Piping | Entire Building | 9,359 | SF | 6 | 10+ years | | |
| | vent i iping | Little Ballaing | 9,339 | Si | U | 10+ years | | |
| Categor | y : Room | | В | uildina | : Additio | on-Lunchroom | /Kitchen | |
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Administr | ative Suites/Offices | | | | | | | |
| | Ceiling - Lay-in | Kitchen Manager | 66 | SF | 7 | 10+ years | | |
| | Doors - Side-lite | Kitchen Manager | 12 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Kitchen Manager | 1 | EA | 7 | 10+ years | | |
| | Floor - Concrete | Kitchen Manager | 66 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Kitchen Manager | 1 | EA | 7 | 6-10 years | | |
| | Power Distribution | Kitchen Manager | 6 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | Kitchen Manager | 243 | SF | 7 | 10+ years | | |
| | | | | | | | | |
| Kitchen | | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 407 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 407 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 5 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 1st Floor | 649 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Dishwash | 166 | SF | 7 | 10+ years | NATIONAL AND ADDRESS AND | |
| | Ceiling - Lay-in | Dishwash | 12 | SF | 5 | 0-1 year | Missing ceiling tiles | |
| | Doors - Steel Doors incl hw | Dishwash | 1 | EA | 7 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | Dishwash | 178 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Dishwash | 2 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | Dishwash | 338 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Servery Line | 893 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Servery Line | 2 | EA | 7 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | Servery Line | 893 | SF | 7 | 10+ years | | |



| Category : Room | | В | Building : Addition-Lunchroom/Kitchen | | | | | |
|-------------------------------------|-----------------|---------------------------------------|---------------------------------------|------|-------------|----------|--|--|
| | | | | | Recommend | | | |
| Group Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Lighting - Lay-in | Servery Line | 13 | EA | 7 | 6-10 years | | | |
| Serving Line | Servery Line | 60 | LF | 7 | 10+ years | | | |
| Walls - Concrete Block | Servery Line | 1,696 | SF | 7 | 10+ years | | | |
| ocker/Shower Room | | | | | | | | |
| Accessories | In Kitchen Area | 75 | SF | 7 | 6-10 years | | | |
| Ceiling - Lay-in | In Kitchen Area | 75 | SF | 7 | 10+ years | | | |
| Doors - Steel Doors incl hw | In Kitchen Area | 1 | EA | 7 | 10+ years | | | |
| Floor - Concrete | In Kitchen Area | 75 | SF | 7 | 10+ years | | | |
| Lavatory | In Kitchen Area | 1 | EA | 7 | 10+ years | | | |
| Lighting - Lay-in | In Kitchen Area | 1 | EA | 7 | 6-10 years | | | |
| Student Lockers - One Tier | In Kitchen Area | 9 | EA | 7 | 10+ years | | | |
| Walls - Concrete Block | In Kitchen Area | 345 | SF | 7 | 10+ years | | | |
| Water Closet | In Kitchen Area | 1 | EA | 7 | 10+ years | | | |
| unch & Multipurpose Room | | | | | | | | |
| Ceiling - Exposed | 1st Floor | 5,733 | SF | 7 | 10+ years | | | |
| Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| Floor - Concrete Epoxy/ Painted | 1st Floor | 5,733 | SF | 7 | 10+ years | | | |
| Lighting - Chandelier, Incandescent | 1st Floor | 3 | EA | 7 | 6-10 years | | | |
| Walls - Concrete Block | 1st Floor | 8,902 | SF | 7 | 10+ years | | | |
| Mechanical/ Service Rooms | | | | | | | | |
| Janitor's Closet | 1st Floor | 30 | SF | 7 | 10+ years | | | |
| Mechanical/ Service Rooms | 1st Floor | 56 | SF | 7 | 10+ years | | | |
| Category : Interior | | Building : Addition-Lunchroom/Kitchen | | | | | | |
| | | | | | Recommend | | | |

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|---------------------------------|-----------|----------|-----|------|--------------------------|--------------|
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,329 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 12 | SF | 5 | 1-2 years | Water damage |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 1,341 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,829 | SF | 7 | 10+ years | |
| Safety | | | | | | | |
| , | Security Cameras | 1st Floor | 1 | EA | 7 | 6-10 years | |



Equipment - Pre K 3-5

| Catego | ry : Site | | В | | | | |
|------------|-----------------------------------|-------------------------|----------|------|------|-------------|------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Athletic_ | | | | | | | |
| | Surface - Synthetic | North | 5,450 | SF | 7 | 10+ years | Separated out from Football/Soccer |
| | Surface - Synthetic | West | 8,000 | SF | 7 | 10+ years | |
| | Surface - Synthetic | West | 4,550 | SF | 7 | 6-10 years | Separated out from Football/Soccer |
| _Civil/Dra | nage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 4 | EA | 7 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 8 | EA | 7 | 10+ years | |
| Fencina | | | | | | | |
| crionig | Fencing - Guard Rail | Entire Site | 110 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 1,441 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 20 | LF | 5 | 2-5 years | |
| | • | | | | | • | |
| _Landsca | | F. (1. O) | 4.5 | Ε.Δ. | | 40 | |
| | Benches | Entire Site | 15 | EA | 7 | 10+ years | |
| | Landscape - Grass | Entire Site | 10,827 | SF | 6 | 6-10 years | |
| | Landscape - Hardscape- Asphalt | Entire Site | 14,890 | SF | 7 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 13,441 | SF | 7 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 500 | SF | 6 | 10+ years | |
| | Parkway trees | Entire Site | 36 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 5,363 | SF | 6 | 6-10 years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 8,113 | SF | 7 | 10+ years | |
| | Retaining Wall - Concrete | Entire Site | 600 | SF | 5 | 2-5 years | |
| | Retaining Wall - Masonry | Entire Site | 60 | SF | 7 | 10+ years | |
| | Trash Receptacles | Entire Site | 1 | EΑ | 6 | 10+ years | |
| | Walking Path - Hardscape- Pavers | Entire Site | 200 | SF | 7 | 10+ years | |
| Parking | ot | | | | | | |
| | Concrete Curbs | NW | 635 | LF | 7 | 10+ years | |
| | Interior Plantings | NW | 60 | LF | 7 | 6-10 years | |
| | Lighting - Pole Mounted | NW | 4 | EA | 7 | 10+ years | |
| | Surface - Asphalt | NW | 17,951 | SF | 6 | 2-5 years | |
| | Surface - Concrete | NW | 7,516 | SF | 7 | 10+ years | |
| | Trash Compactor | NW | 1,010 | EA | 6 | 10+ years | |
| | Trash Enclosure - Masonry | NW | 2,860 | SF | 7 | 10+ years | |
| | Vehicular Screening | NW | 375 | LF | 6 | 10+ years | |
| | Surface - Asphalt | South - Main Entrance 1 | 2,050 | SF | 6 | 6-10 years | |
| DI- | | | | | | - | |
| Playgrou | nd | E di Oit | | | | 10 | |

1

EΑ

6

10+ years

Entire Site



| Category : Site | | | В | uilding | - | | |
|-----------------|--|-------------|----------|---------|------|-----------------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Surface - Poured Surface | Entire Site | 2,150 | SF | 7 | 10+ years | |
| Sidewalk | KS. | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 1,122 | LF | 7 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 13,729 | SF | 7 | 10+ years | |
| Signage | | | | | | | |
| 0 0 | Flag Pole - Building Mounted Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | Flag Pole - Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | Marquee - Building Mounted Back Lighted w/ LED | Entire Site | 1 | EA | 6 | 10+ years | |
| | Marquee - Free Standing Back Lighted | Entire Site | 1 | EA | 6 | 6-10 years | |
| | Monument - Sign | Entire Site | 1 | EA | 7 | 10+ years | |

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

| Classroom Summary | | | | Fl Dl | | 01 | 0 | | |
|-------------------------|---------------------------------|---------------|---------|--------------------|--------------|------------------|--------------------|--------|--------|
| | | | Room | Floor Plan Room | A *** | Glazed Window | Operable Window | Window | Smart- |
| Current Usage | Intended Hoose | Room Location | Number | Number | Area (SF) | | Area | | Board |
| Building : Main | Intended Usage | Room Location | Number | Number | (37) | Area | Area | Stop | Doard |
| Other Instructional Use | Regular Classroom | 3rd Floor | 300 | NA | 417 | 66 | 33 | N | Υ |
| Regular Classroom | Kindergarten | 1st Floor | 105 | 105 | 915 | 132 | 66 | N | N |
| Regular Classroom | | 1st Floor | 100 | 100 | 915 | 132 | 66 | N | N |
| Regular Classroom | Library Other Instructional Use | 3rd Floor | 311 | Adj. Room | 415 | 66 | 33 | N | N |
| | | 1st Floor | 101 | 101 | 815 | 132 | 66 | N N | N |
| Regular Classroom | Regular Classroom | | | | | | 66 | | |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 815 | 132 | | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 815 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 104 | 104 | 815 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 200 | NA | 415 | 66 | 33 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 815 | 132 | 66 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 815 | 120 | 60 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 533 | 88 | 44 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 815 | 132 | 66 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 815 | 132 | 66 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 815 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 309 | 815 | 132 | 66 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | 310 | 533 | 88 | 44 | N | Y |
| Science Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 815 | 132 | 66 | N | Υ |
| | | • | • | | • | | | | |
| Building : Addition 2 | | | | | | | | | |
| Art Room | Art Room | 2nd Floor | 221 | 2-14 | 1,034 | 154 | 77 | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 223 | 2-06 | 1,221 | 176 | 88 | N | Υ |
| Kindergarten | Kindergarten | 1st Floor | 114 | 1-31 | 1,220 | 232 | 116 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 116 | 1-34 | 1,220 | 232 | 116 | N | N |
| Kindergarten | Pre School | 1st Floor | 115 | 1-12 | 1,172 | 176 | 88 | N | N |
| Kindergarten | Regular Classroom | 1st Floor | 117/119 | 1-05/1-06 | 900 | 66 | 33 | N | N |
| Language Lab | Regular Classroom | 2nd Floor | 219 | 2-15 | 450 | 66 | 33 | N | N |





Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|-------------------|-------------------|---------------|---------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Pre School | Kindergarten | 1st Floor | 112 | 1-28 | 1,220 | 232 | 116 | N | N |
| Pre School | Pre School | 1st Floor | 110 | 1-25 | 1,220 | 232 | 116 | N | N |
| Pre School | Pre School | 1st Floor | 111 | 1-18 | 1,172 | 176 | 88 | N | N |
| Pre School | Pre School | 1st Floor | 113 | 1-15 | 1,172 | 176 | 88 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 214 | 2-19 | 900 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 215 | 2-17 | 925 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 2-20 | 900 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 2-16 | 900 | 66 | 33 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 2-21 | 900 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 2-22/2-23 | 900 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 222A | - | 653 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 225 | 2-05 | 425 | 66 | 33 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 314/316 | 3-18/3-19 | 918 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 315 | 3-16 | 925 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 317 | 3-15 | 880 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 318 | 3-20 | 900 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | 3-14 | 377 | 66 | 33 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 3-21 | 900 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 3-13 | 1,034 | 154 | 77 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 3-22/3-23 | 900 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 3-07 | 465 | 44 | 22 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | 3-24 | 900 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 325 | 3-06 | 925 | 132 | 66 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 326 | 3-25 | 900 | 132 | 66 | N | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 328 | 3-26 | 900 | 132 | 66 | N | N |
| Special Program | Regular Classroom | 2nd Floor | 213 | 2-18 | 450 | 66 | 33 | N | N |
| Special Program | Regular Classroom | 3rd Floor | 313 | 3-17 | 398 | 66 | 33 | N | N |
| Special Program | Regular Classroom | 3rd Floor | 327 | 3-05 | 450 | 66 | 33 | N | N |