

8300 S St Louis AVENUE, Chicago, IL 60652

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Leased-Main	1953	2	58,580
Campus Total			58,580

Category : Exterior Building : Leased-Main

	<b>,</b>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	· ·		•			•	
	Entrance Control - Audio and Video	1	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	1	4	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	2	EA	7	10+ years	
	Exterior Stairs - Concrete	2	6	LF	7	10+ years	
	Entrance Control - Audio	3	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	3	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	3	7	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	4	2	EA	6	10+ years	
	Exterior Stairs - Concrete	4	6	LF	7	10+ years	
	Exterior Stairs - Stone	4	6	LF	7	10+ years	
	Entrance Control - Audio and Video	5 - Main	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	5 - Main	4	EA	6	10+ years	
	Exterior Doors - Side lite	5 - Main	1	EA	7	10+ years	
	Exterior Stairs - Stone	5 - Main	15	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6	2	EΑ	4	1-2 years	Corroded door and frames
	Ramps - Concrete	6	2	LF	7	10+ years	
	Exterior Doors - Side lite	6 northeast side	1	EA	6	6-10 years	
	Exterior Doors - Store Front	6 northeast side	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	6 northeast side	3	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	6 northeast side	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	8 - Boiler Room	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	8 - Boiler Room	1	EA	7	10+ years	
	Exterior Stairs - Concrete	8 - Boiler Room	45	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	8 - Boiler Room	14	LF	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Lease	d-Main	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oundati	on Foundation - Concrete	Entire Building	988	LF	7	10	
	Superstructure - Concrete	Entire Building	20	SF	7 7	10+ years	
	Superstructure - Concrete			SF	7	10+ years	
	Superstructure - Concrete	Entire Building	58,560	5F	7	10+ years	
ahtina							
9	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	6-10 years	Recombined quantities
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	Recombined quantities
Roof Sys	otom						
our oys	Coping - Metal	1 - South Roof	355	LF	6	10+ years	
	Downspouts - Exterior Downspouts	1 - South Roof	151	LF	7	10+ years	
	Downspouts - Exterior Downspouts	1 - South Roof	6	LF	4	0-1 year	Cracked cast iron downspout
	Roof - Asphalt Gravel Ballast	1 - South Roof	6,540	SF	4	0-1 year	Old roof, blistering throughout
	Roof Hatch - Metal	1 - South Roof	1	EA	3	1-2 years	Closed permanently
	Roof Structure - Concrete	1 - South Roof	6,540	SF	7	10+ years	Closed permanently
	Chimney - Brick Chimney- Concrete/ Mortar	2- Central Upper Roof	6,540	LF	5	•	Cracked open joints
	Liner	2- Central Opper Roof	4	LF	5	1-2 years	Cracked, open joints
	Chimney - Brick Chimney- Concrete/ Mortar Liner	2- Central Upper Roof	36	LF	5	6-10 years	
	Coping - Metal	2- Central Upper Roof	452	LF	7	10+ years	
	Coping - Stone	2- Central Upper Roof	15	LF	7	10+ years	
	Downspouts - Interior Downspouts	2- Central Upper Roof	213	LF	7	10+ years	
	Roof - Modified Bitumen	2- Central Upper Roof	10,462	SF	6	6-10 years	
	Roof - Modified Bitumen	2- Central Upper Roof	3	SF	3	1-2 years	Open seam
	Roof Hatch - Metal	2- Central Upper Roof	1	EA	3	0-1 year	No access to this roof. Used a lade
	Roof Structure - Concrete	2- Central Upper Roof	10,465	SF	7	10+ years	No access to this root. Osed a ladd
	Coping - Metal	3 - Northwest Roof	305	LF	7	10+ years	
	Downspouts - Interior Downspouts	3 - Northwest Roof	59	LF	7	10+ years	
	Roof - Modified Bitumen	3 - Northwest Roof	5,560	SF	6	6-10 years	
			200	SF	3		Active leaks pooling
	Roof - Modified Bitumen	3 - Northwest Roof 3 - Northwest Roof		SF EA	3	0-1 year	Active leaks, pooling Not used, obstructed
	Roof Hatch - Metal		1			2-5 years	Not used, obstructed
	Roof Structure - Concrete	3 - Northwest Roof	5,760	SF	7	10+ years	
	Coping - Metal	4 - North Roof	81	LF	6	10+ years	
	Downspouts - Interior Downspouts	4 - North Roof	43	LF	6	2-5 years	Distanced the second sections of
	Roof - Asphalt Gravel Ballast	4 - North Roof	1,620	SF	4	0-1 year	Blistered throughout, growing vegetation
	Roof Hatch - Metal	4 - North Roof	1	EA	3	1-2 years	Not used, old hatch
	Roof Structure - Concrete	4 - North Roof	1,620	SF	7	10+ years	
	Coping - Metal	5 - North Roof	68	LF	7	10+ years	
	Downspouts - Interior Downspouts	5 - North Roof	9	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	5 - North Roof	1,035	SF	4	0-1 year	Blistered throughout, growing



	ry : Exterior		В	uilding	: Lease		
0	Itama Tuna	Location	0	11014	Dawl	Recommend	C
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Concrete	5 - North Roof	1,035	SF	7	10+ years	vegetation
	Roof Structure - Concrete	5 - NOITH ROOF	1,033	SF	,	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	245	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	19,996	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	800	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Brick	Entire Building	50	SF	4	1-2 years	Cracked, broken, open joints
	Exterior Walls - Stone-Cast	Entire Building	1,695	SF	7	10+ years	•
	Exterior Walls - Stone-Cast	Entire Building	500	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	5	SF	4	1-2 years	Broken
lindow							
Vindows	Clerestory - Glass Double-Pane	Entire Building	90	SF	7	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	528	SF	7	10+ years	
	Lintels - Steel	Entire Building	1,469	LF	7	10+ years	
		· ·		SF			Decembined questities
	Skylite - Lexan	Entire Building	60		7	10+ years	Recombined quantities
	Windows - Insulated Panel	Entire Building	327	SF	7	10+ years	
	Windows - Louver	Entire Building	60	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	9,341	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Lease	d-Main	
_				_		Recommend	
roup	Item - Type	Location	B Quantity	uilding UOM	: Lease		Comments
roup	Item - Type acy System		Quantity	UOM	Rank	Recommend Replacement	Comments
roup	Item - Type  acy System  Security System - CCTV	Entire Building	Quantity 58,580	<b>UOM</b>	Rank 6	Recommend Replacement 6-10 years	Comments
roup	Item - Type  ncy System  Security System - CCTV  Security System - Intrusion Detection	Entire Building Entire Building	Quantity 58,580 58,580	UOM SF SF	<b>Rank</b> 6 6	Recommend Replacement 6-10 years 6-10 years	Comments
roup	Item - Type  Incy System  Security System - CCTV  Security System - Intrusion Detection  Exit Signs - Corridors and Stairs	Entire Building	Quantity 58,580	<b>UOM</b>	Rank 6	Recommend Replacement 6-10 years	Comments
roup	Item - Type  ncy System  Security System - CCTV  Security System - Intrusion Detection	Entire Building Entire Building	Quantity 58,580 58,580	UOM SF SF	<b>Rank</b> 6 6	Recommend Replacement 6-10 years 6-10 years	Recently replaced exit Signs are in
roup	Item - Type  Incy System  Security System - CCTV  Security System - Intrusion Detection  Exit Signs - Corridors and Stairs  Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and	Entire Building Entire Building Entire Building	Quantity  58,580 58,580 27	SF SF EA	6 6 6	Recommend Replacement 6-10 years 6-10 years 6-10 years	
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity  58,580 58,580 27 5	SF SF EA EA	6 6 6 7 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	98,580 58,580 27 5	SF SF EA EA	6 6 6 7	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose	Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity  58,580 58,580 27 5	SF SF EA EA	6 6 6 7 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity  58,580 58,580 27 5 25	SF SF EA EA	6 6 6 7 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs	Entire Building	Quantity  58,580 58,580 27 5 25 3 15 4,450	SF SF EA EA EA EA	6 6 6 6 6 6 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years	Recently replaced exit Signs are in
Froup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room	Entire Building	900	SF SF EA EA EA EA SF	6 6 6 6 6 6 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose	Entire Building	Quantity  58,580 58,580 27 5 25 3 15 4,450	SF SF EA EA EA EA	6 6 6 6 6 6 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years	Recently replaced exit Signs are in
roup	Item - Type  Icy System  Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room Emergency A/C Power - Multipurpose Room Emergency A/C Power - Students Toilets	Entire Building	900	SF SF EA EA EA EA SF	6 6 6 6 6 6 6	Recommend Replacement  6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Recently replaced exit Signs are in

Campus Name: Ashburn Page : 3 of 31 Assessment Date: 02/07/2024



XXX	SCHOOIS						300 S St Louis AVENUE, Chicago, IL 60652		
Catego	ry : Electrical		В	Building : Leased-Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Main Electrical Service - 1200 A 120/240/3PH	West Facade	1	EA	6	10+ years	not get PA announcements Electrical service is 1200A single phase, not three phase as previously documented		
Power D	Distribution								
	Lighting and Power Panels - 100 A	Basement	1	EA	6	6-10 years	Unlabeled panels in or near basement office/storage room		
	Main Distribution Panels - 400 - 600 amp	Basement	1	EΑ	7	10+ years	DP-1		
	Main Distribution Panels - Greater than 600 amp	Basement	1	EA	7	10+ years	SES-1		
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	Vintage unlabeled panel		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Unlabeled EM panel in Main Entranc		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	100 amp unlabeled panel in janitor closet, first floor primary as live front		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	AC-2A AC-2A-2		
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Panel A Panel C		
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	Vintage and newer, unlabeled panels		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Panel B is live front		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	MDF panel is live front		
Catego	ry : Fire Protection		В	uilding					
			<b>0</b>	11014		Recommend	•		
Group Fire Ala	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
FIIE AIAI		Fatire Duilding	F0 F00	ΕΛ	7	10			
	Fire Alarm Anunciator	Entire Building	58,580	EΑ	7	10+ years			
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years			
	Fire Alarm Strobe Lights	Entire Building	58,580	SF	6	10+ years			
	Fire Alarm_System	Entire Building	58,580	SF	6	6-10 years			
Catego	ry : Mechanical		В	uilding	: Lease	d-Main			
					Rank	Recommend Replacement	Comments		
Craun	Ham Tune	Lagation	Oughtitu.			Replacement	Comments		
•	Item - Type	Location	Quantity	UOM	Italiit	•			
•	ditioning  Condensing Unit- Ground Mounted - 5-10	Site West	Quantity 2	EA	5	1-2 years	Serve multipurpose rooms Older, bu		
•	ditioning		,						
Air Cond	Condensing Unit- Ground Mounted - 5-10 tons Condensing Unit- Ground Mounted - 5-10 tons	Site West	2	EA	5	1-2 years	Serve multipurpose rooms Older, but		
	ditioning  Condensing Unit- Ground Mounted - 5-10 tons  Condensing Unit- Ground Mounted - 5-10	Site West	2	EA	5	1-2 years	Serve multipurpose rooms Older, bu		

Campus Name: Ashburn Page : 4 of 31 Assessment Date: 02/07/2024



	Item - Type					D	
						Recommend	
		Location	Quantity	UOM	Rank	Replacement	Comments
	Coils and Chilled Water Coils - Less than 6000 cfm						kitchen located in storage room
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	5	1-2 years	Deteriorating, old, cooling, only forced air in multipurpose room, exposed ceiling mounted Functional
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	5	1-2 years	Deteriorating, old, cooling, only forced air in multipurpose room, exposed ceiling mounted Functional
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	5	1-2 years	Deteriorating, old, cooling, only forced air in multipurpose room, exposed ceiling mounted Functional
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	2	0-1 year	Older smokeeter unit, not used
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EΑ	2	0-1 year	Older smokeeter unit, not used
Boiler Sys	· ·					·	
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	4	1-2 years	Deteriorating, frequent maintenance
	Pressure Boiler - 76 - 100 HP					•	Deteriorating, frequent maintenance
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	Functional
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	In floor near multipurpose room
	Condensate Pump	Boiler Room	1	EA	4	1-2 years	Functional, but end of life
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	Unit is leaking at float switch
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	6-10 years	One pump is newly replaced
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	4	1-2 years	B-1 Cast iron, 1953 original Frequent tube maintenance, valves
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	4	1-2 years	B-2 Cast-iron original 1953 installation
	Piping - Condensate Pipe- Steel	Boiler Room	200	LF	5	1-2 years	There are pipe clamps, uninsulated, condensate lines common
	Piping - Steam Pipe- Steel	Boiler Room	200	LF	3	1-2 years	Active leak, all steam piping is insulated with asbestos
	Steam Traps	Boiler Room	6	EA	5	6-10 years	Steam trap survey, complete, many traps replaced in last year
	Vacuum Pump	Boiler Room	2	EA	5	2-5 years	One pump remains original to system
_Heat Exch							
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	6	6-10 years	Serves unit vents, uninsulated in boiler room
Heating De	evices						
	Fin Tube - Hot Water	Entire Building	36	LF	5	6-10 years	
	Unit Heater - Hot Water	Entire Building	6	EA	5	6-10 years	
	Unit Heater - Steam	Entire Building	2	EA	5	6-10 years	



Catego	ry : Mechanical		В	uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Steam	Entire Building	3	EA	2	10+ years	Fan motor nonfunctional. Quantity segregated to reflect observed conditions. One in storage room.
	Cabinet Heaters - With Steam Coil	Entire Building	11	EA	5	6-10 years	
	Radiators - Steam	Entire Building	6	EA	6	10+ years	Moved from fin tube
Mechani	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	7	10+ years	Serves the heat exchanger, replaced new within the last 12 months since assessment
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	Serves heat exchanger, unit vents, unit heaters, fintube.
Tempera	ature Control						
	Electric Thermostat	Entire Building	10	EA	6	6-10 years	
	Pneumatic System	Entire Building	58,580	SF	5	1-2 years	Air dryer nonfunctional, actuators, failing regularly
	Thermostats - Pneumatic	Entire Building	43	EA	5	1-2 years	Not calibrated, thermostats leaking
Unit Ven	itilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	11	EA	5	6-10 years	Original with new controls inside unit
Ventilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years	New indoor exhaust fans in student toilet rooms added since previous assessment.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	North Roof, serves principal's office
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	NW Roof
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	High roof Duplicated, made obsolete by interior, mounted exhaust fans, installed in 2020 Intentionally not operational at time of assessment
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Southwest roof, not included in previous assessment.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	NW Roof
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	Abandoned, not in use
Catego	ry : Plumbing		В	uilding	: Lease	d-Main	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement	
_Hot Wate	er						
	Electric Heater - Less than 20 KW	Basement	1	EA	7	10+ years	Serves handwashing sink for kitchen. New.\nNot included in previous assessment.
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	1	EΑ	7	6-10 years	
	Gas Heater - Less than 150000 BTU/HR	Entire Building	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,580	SF	6	6-10 years	1953 installation functional
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,580	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,580	SF	6	6-10 years	
	Sanitary Piping	Entire Building	58,580	SF	6	6-10 years	
	Storm Piping	Entire Building	58,580	SF	6	6-10 years	Storm plumbing leak recently repaired.
	Vent Piping	Entire Building	58,580	SF	6	6-10 years	
Pumps							
•	Pumps - Sump-Duplex	Boiler Room	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	10+ years	Not included in previous assessment

Building : Leased-Main Category : Room

	. –					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	001 - Principal's Office	1	EA	7	6-10 years	
	Ceiling - Splined	001 - Principal's Office	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	001 - Principal's Office	3	EA	7	10+ years	
	Floor - Carpet	001 - Principal's Office	166	SF	7	6-10 years	
	Floor - Carpet	001 - Principal's Office	10	SF	4	0-1 year	Torn and bubbling carpet
	Lighting - Lay-in	001 - Principal's Office	1	EA	7	10+ years	
	Power Distribution	001 - Principal's Office	2	EA	7	10+ years	
	Storage/ Closet	001 - Principal's Office	4	SF	7	10+ years	
	Walls - Plaster/Drywall	001 - Principal's Office	530	SF	7	10+ years	
	Walls - Plaster/Drywall	001 - Principal's Office	10	SF	6	10+ years	Cracking and bubbling paint
	AC Unit	002 - Conference Room	1	EA	7	6-10 years	
	Ceiling - Splined	002 - Conference Room	252	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002 - Conference Room	2	EA	7	10+ years	
	Floor - Carpet	002 - Conference Room	252	SF	4	1-2 years	Worn, wrinkled, frayed seams, dirty



Catego	ry : Room		В	uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Linkston Lauria	000 0		_^	7	40	throughout
	Lighting - Lay-in	002 - Conference Room	4	EA	7	10+ years	
	Power Distribution	002 - Conference Room	8	EA	7	10+ years	
	Storage/ Closet	002 - Conference Room	6	SF	7	10+ years	
	Walls - Metal Panel	002 - Conference Room	192	SF	7	10+ years	
	Walls - Plaster/Drywall	002 - Conference Room	448	SF	7	10+ years	
	Ceiling - Splined	003 - Clerk's Office	152	SF	7	10+ years	
	Doors - Wood Doors inclu hw	003 - Clerk's Office	1	EA	7	10+ years	
	Floor - Carpet	003 - Clerk's Office	154	SF	6	2-5 years	
	Lighting - Lay-in	003 - Clerk's Office	2	EA	7	10+ years	
	Power Distribution	003 - Clerk's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	003 - Clerk's Office	500	SF	7	10+ years	
	Ceiling - Splined	004	126	SF	7	10+ years	
	Doors - Wood Doors inclu hw	004	1	EA	7	10+ years	
	Floor - Carpet	004	126	SF	6	6-10 years	
	Lighting - Lay-in	004	2	EΑ	7	10+ years	
	Power Distribution	004	2	EA	7	10+ years	
	Walls - Plaster/Drywall	004	460	SF	7	10+ years	
	Ceiling - Splined	005 - Copy Room	116	SF	7	10+ years	
	Ceiling - Splined	005 - Copy Room	10	SF	4	0-1 year	Broken and sagging ceiling, tiles nearby light fixtures
	Doors - Wood Doors inclu hw	005 - Copy Room	2	EA	7	10+ years	, ,
	Floor - Carpet	005 - Copy Room	126	SF	6	6-10 years	
	Lighting - Lay-in	005 - Copy Room	4	EA	7	10+ years	
	Power Distribution	005 - Copy Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	005 - Copy Room	460	SF	7	10+ years	
	AC Unit	108 - Reading Lab	1	EA	7	6-10 years	
	Ceiling - Splined	108 - Reading Lab	720	SF	7	10+ years	
	Doors - Transom Window	108 - Reading Lab	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108 - Reading Lab	1	EA	7	10+ years	
	Floor - Carpet	108 - Reading Lab	720	SF	7	6-10 years	
	Lighting - Pendent/Surface	108 - Reading Lab	12	EA	7	10+ years	
	Power Distribution	108 - Reading Lab	4	EA	7	10+ years	
	Storage/ Closet	108 - Reading Lab	10	SF	7	10+ years	
	Walls - Plaster/Drywall	108 - Reading Lab	720	SF	7	10+ years	
	Walls - Structural Glazed Tile	108 - Reading Lab	110	SF	7	10+ years	
	AC Unit	111 - Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Splined	111 - Teacher's Lounge	522	SF	7	10+ years	
	Ceiling - Splined	111 - Teacher's Lounge	6	SF	4	0-1 year	Loose and missing ceiling tiles
	Doors - Transom Window	111 - Teacher's Lounge	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	111 - Teacher's Lounge	1	EA	7	10+ years	
	Floor - Carpet	111 - Teacher's Lounge	528	SF	6	6-10 years	
	Lighting - Pendent/Surface	111 - Teacher's Lounge	10	EA	7	10+ years	
	Power Distribution	111 - Teacher's Lounge	10	EA	7	10+ years	
	. 55. 2154115411511		10		•	10. 300.0	



Catego	ry : Room		В	uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	111 - Teacher's Lounge	150	SF	7	10+ years	
	Walls - Metal Panel	111 - Teacher's Lounge	522	SF	7	10+ years	
	Walls - Plaster/Drywall	111 - Teacher's Lounge	178	SF	7	10+ years	
	Ceiling - Splined	111A - North Faculty	99	SF	7	10+ years	
	Ceiling - Splined	111A - North Faculty	5	SF	5	1-2 years	Loose and falling tiles
	Doors - Wood Doors inclu hw	111A - North Faculty	1	EA	4	6-10 years	Hardware loose
	Floor - Tile	111A - North Faculty	104	SF	7	10+ years	
	Lighting - Pendent/Surface	111A - North Faculty	1	EA	7	10+ years	
	Power Distribution	111A - North Faculty	2	EA	7	10+ years	
	Walls - Plaster/Drywall	111A - North Faculty	380	SF	7	10+ years	
	AC Unit	113 - Engineer Office	1	EA	7	6-10 years	
	Ceiling - Exposed	113 - Engineer Office	396	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113 - Engineer Office	1	EA	7	10+ years	
	Floor - Tile	113 - Engineer Office	396	SF	6	10+ years	
	Lighting - Pendent/Surface	113 - Engineer Office	4	EA	6	6-10 years	
	Power Distribution	113 - Engineer Office	10	EA	7	10+ years	
	Walls - Concrete Block	113 - Engineer Office	900	SF	7	10+ years	
	Work Sink	113 - Engineer Office	1	EA	7	10+ years	
	AC Unit	218 - Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Splined	218 - Assistant Principal	265	SF	7	10+ years	
	Doors - Wood Doors inclu hw	218 - Assistant Principal	1	EA	7	10+ years	
	Floor - Carpet	218 - Assistant Principal	265	SF	7	6-10 years	
	Lighting - Pendent/Surface	218 - Assistant Principal	10	ĒΑ	7	10+ years	
	Power Distribution	218 - Assistant Principal	12	EA	7	10+ years	
	Walls - Concrete Block	218 - Assistant Principal	677	SF	7	10+ years	
	AC Unit	219 - Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Splined	219 - Faculty Lounge	276	SF	7	10+ years	
	Doors - Wood Doors inclu hw	219 - Faculty Lounge	2	ĒΑ	7	10+ years	
	Floor - Tile	219 - Faculty Lounge	276	SF	7	6-10 years	
	Lighting - Lay-in	219 - Faculty Lounge	6	ĒA	7	10+ years	
	Power Distribution	219 - Faculty Lounge	6	EA	7	10+ years	
	Walls - Concrete Block	219 - Faculty Lounge	700	SF	7	10+ years	
	Work Sink	219 - Faculty Lounge	1	ĒΑ	7	10+ years	
	Ceiling - Splined	B006	440	SF	6	10+ years	Moved from Classrooms
	Doors - Steel Doors incl hw	B006	1	ĒΑ	7	10+ years	Moved from Classrooms
	Floor - Tile	B006	440	SF	7	10+ years	Moved from Classrooms
	Lighting - Lay-in	B006	5	ĒΑ	7	6-10 years	Moved from Classrooms
	Lighting - Lay-in	B006	1	EΑ	5	10+ years	Moved from Classrooms. Missing
						·	cover, relamp
	Power Distribution	B006	6	EA	7	10+ years	
	Walls - Plaster/Drywall	B006	755	SF	7	10+ years	Moved from Classrooms
	Ceiling - Lay-in	Kitchen Office	299	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	7	10+ years	
	Floor - Tile	Kitchen Office	299	SF	6	10+ years	

Campus Name: Ashburn Page : 9 of 31 Assessment Date: 02/07/2024



Catego	ry : Room		R	uildina	: Lease		300 S St Louis AVENUE, Chicago, IL 60652
Catego	i y . Room			unung	. LCasc	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Gup	Lighting - Lay-in	Kitchen Office	2	EA	7	10+ years	
	Power Distribution	Kitchen Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	710	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	10	SF	6	10+ years	
	vvalio i laotoi/Diywali	Tationeri Cinico	10	O.	· ·	To Tyouro	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	410	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	4	SF	4	0-1 year	Chipped
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	414	SF	7	10+ years	
	Floor - Tile	Basement	12	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	Basement	4	EA	7	10+ years	
	Serving Line	Basement	6	LF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	820	SF	7	10+ years	
Library							
шиату	AC Unit	110/112	2	EA	7	6-10 years	
	Casework	110/112	150	LF	6	10+ years	
	Ceiling - Splined	110/112	1,560	SF	7	10+ years	
	Doors - Transom Window	110/112	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110/112	2	EA	7	10+ years	
	Floor - Carpet	110/112	1,560	SF	7	6-10 years	
	Lighting - Pendent/Surface	110/112	24	EA	7	10+ years	
	Storage/ Closet	110/112	10	SF	7	10+ years	
	Walls - Plaster/Drywall	110/112	1,107	SF	7	10+ years	
	Walls - Structural Glazed Tile	110/112	180	SF	7	10+ years	
			100	O.	•	.o. youro	
Lunch &	Multipurpose Room						
	Ceiling - Splined	Basement	5,638	SF	6	10+ years	
	Ceiling - Splined	Basement	5	SF	4	0-1 year	Damaged tiles
	Floor - Tile	Basement	5,621	SF	7	10+ years	
	Floor - Tile	Basement	22	SF	5	1-2 years	Broken, damaged tiles
	Lighting - Lay-in	Basement	60	EA	7	10+ years	
	Serving Line	Basement	12	LF	7	10+ years	
	Walls - Masonry	Basement	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,350	SF	7	10+ years	
MDF_ID	F						
_	Doors - Steel Doors incl hw	111B	1	EA	7	10+ years	
	Finishes	111B	380	SF	7	6-10 years	
	Window AC Unit	111B	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
.viconulli	CONTROL NOTION						



Catego	ry : Room	Building : Leased-Main					
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	1st Floor	14	SF	7	10+ years	
	Janitor's Closet	1st Floor	51	SF	5	10+ years	Missing floor and ceiling tiles
	Storage Room	1st Floor	100	SF	7	10+ years	-
	Storage Room	1st Floor	320	SF	7	10+ years	
	Janitor's Closet	2nd Floor	66	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Boiler Room	Basement	552	SF	7	10+ years	
	Janitor's Closet	Basement	12	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	103	SF	7	10+ years	
	Storage Room	Basement	747	SF	7	10+ years	
Restroor	m						
	Accessories	001A - Principal's Office	15	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	001A - Principal's Office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	001A - Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	001A - Principal's Office	15	SF	4	0-1 year	Worn, frayed, stained
	Hand Dryer	001A - Principal's Office	1	EA	7	6-10 years	
	Lavatory	001A - Principal's Office	1	EA	6	2-5 years	
	Lighting - Pendent/Surface	001A - Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	001A - Principal's Office	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	001A - Principal's Office	80	SF	7	10+ years	
	Water Closet	001A - Principal's Office	1	EA	7	10+ years	
	Accessories	006 - 1st Floor	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	006 - 1st Floor	240	SF	7	10+ years	
	Doors - Wood Doors inclu hw	006 - 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	006 - 1st Floor	240	SF	7	10+ years	
	Hand Dryer	006 - 1st Floor	1	EA	7	6-10 years	
	Lavatory	006 - 1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	006 - 1st Floor	2	EA	7	10+ years	
	Partitions	006 - 1st Floor	2	EA	7	10+ years	
		006 - 1st Floor	6	EA	7		
	Urinals			SF		2-5 years	
	Walls - Plaster/Drywall	006 - 1st Floor	260		7	10+ years	
	Walls - Structural Glazed Tile	006 - 1st Floor	450	SF	7	10+ years	
	Water Closet	006 - 1st Floor	2	EA	7	2-5 years	
	Accessories	007 - 1st Floor	240	SF	7	6-10 years	
	Ceiling - Lay-in	007 - 1st Floor	232	SF	7	10+ years	
	Ceiling - Lay-in	007 - 1st Floor	8	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	007 - 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	007 - 1st Floor	240	SF	7	10+ years	
	Floor Drain	007 - 1st Floor	1	EA	7	10+ years	
	Hand Dryer	007 - 1st Floor	1	EA	7	6-10 years	
	Lavatory	007 - 1st Floor	1	EA	7	2-5 years	
	Lighting - Lay-in	007 - 1st Floor	2	EA	7	10+ years	
	Partitions	007 - 1st Floor	8	EA	7	10+ years	

Campus Name: Ashburn Page : 11 of 31 Assessment Date: 02/07/2024



Catego	Category : Room			Building : Leased-Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	007 - 1st Floor	272	SF	7	10+ years			
	Walls - Structural Glazed Tile	007 - 1st Floor	408	SF	7	10+ years			
	Water Closet	007 - 1st Floor	8	EA	7	2-5 years			
	Accessories	008 - 2nd Floor	210	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	008 - 2nd Floor	210	SF	6	10+ years			
	Doors - Wood Doors inclu hw	008 - 2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	008 - 2nd Floor	210	SF	7	10+ years	Renovated		
	Hand Dryer	008 - 2nd Floor	1	EA	7	6-10 years			
	Lavatory	008 - 2nd Floor	2	EA	7	10+ years			
	Lighting - Lay-in	008 - 2nd Floor	3	EA	7	10+ years			
	Partitions	008 - 2nd Floor	2	EA	7	10+ years			
	Urinals	008 - 2nd Floor	2	EA	7	10+ years	Renovated		
	Walls - Plaster/Drywall	008 - 2nd Floor	170	SF	7	10+ years	Renovated		
	Walls - Tile Ceramic/ Porcelain	008 - 2nd Floor	510	SF	7	10+ years	Renovated		
	Water Closet	008 - 2nd Floor	2	EA	7	10+ years			
	Accessories	009 - 2nd Floor	210	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	009 - 2nd Floor	210	SF	7	10+ years			
	Doors - Wood Doors inclu hw	009 - 2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	009 - 2nd Floor	210	SF	7	10+ years			
	Floor Drain	009 - 2nd Floor	1	EA	7	10+ years			
	Hand Dryer	009 - 2nd Floor	1	EA	7	6-10 years			
	Lavatory	009 - 2nd Floor	5	EA	7	10+ years			
	Lighting - Pendent/Surface	009 - 2nd Floor	2	EA	7	10+ years	Renovated		
	Partitions	009 - 2nd Floor	5	EA	7	10+ years	Renovated		
	Walls - Plaster/Drywall	009 - 2nd Floor	170	SF	7	10+ years	Renovated		
	Walls - Tile Ceramic/ Porcelain	009 - 2nd Floor	510	SF	7	10+ years	Renovated		
	Water Closet	009 - 2nd Floor	4	EA	7	10+ years	Renovated		
	Accessories	009A - 2nd Floor Unisex	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	009A - 2nd Floor Unisex	30	SF	6	10+ years			
	Doors - Wood Doors inclu hw	009A - 2nd Floor Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	009A - 2nd Floor Unisex	30	SF	7	10+ years			
	Hand Dryer	009A - 2nd Floor Unisex	1	EA	7	10+ years			
	Lavatory	009A - 2nd Floor Unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	009A - 2nd Floor Unisex	1	EA	7	10+ years			
	Walls - Plaster/Drywall	009A - 2nd Floor Unisex	55	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	009A - 2nd Floor Unisex	165	SF	7	10+ years			
	Water Closet	009A - 2nd Floor Unisex	1	EA	7	10+ years			
	Accessories	010 - 1.5 North	130	SF	7	6-10 years			
	Ceiling - Splined	010 - 1.5 North	130	SF	4	0-1 year	Water damage, falling tiles		
	Doors - Wood Doors inclu hw	010 - 1.5 North	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	010 - 1.5 North	130	SF	6	10+ years			
	Hand Dryer	010 - 1.5 North	1	ĒΑ	7	6-10 years			
	Lavatory	010 - 1.5 North	2	EA	7	10+ years			
	Lighting - Lay-in	010 - 1.5 North	2	EA	7	10+ years			
	3 3 - 7		_			- <b>,</b>			

Campus Name: Ashburn Page : 12 of 31 Assessment Date: 02/07/2024



Catego	Category : Room			uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	010 - 1.5 North	2	EA	7	10+ years	
	Urinals	010 - 1.5 North	3	EΑ	7	10+ years	
	Walls - Concrete Block	010 - 1.5 North	184	SF	7	10+ years	
	Walls - Structural Glazed Tile	010 - 1.5 North	276	SF	7	10+ years	
	Water Closet	010 - 1.5 North	2	EA	7	10+ years	
	Accessories	011 - 1.5 North	114	SF	7	6-10 years	
	Ceiling - Splined	011 - 1.5 North	114	SF	7	10+ years	
	Doors - Wood Doors inclu hw	011 - 1.5 North	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	011 - 1.5 North	114	SF	7	10+ years	
	Hand Dryer	011 - 1.5 North	1	EA	7	6-10 years	
	Lavatory	011 - 1.5 North	2	EA	7	10+ years	
	Lighting - Lay-in	011 - 1.5 North	2	EA	7	10+ years	
	Partitions	011 - 1.5 North	3	EA	5	6-10 years	
	Walls - Concrete Block	011 - 1.5 North	184	SF	7	10+ years	
	Walls - Structural Glazed Tile	011 - 1.5 North	336	SF	7	10+ years	
	Water Closet	011 - 1.5 North	3	EA	7	10+ years	
	Accessories	0125 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0125 South	154	SF	7	10+ years	
	Ceiling - Plaster/Drywall	0125 South	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	0125 South	13	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0125 South	169	SF	7	10+ years	
	Floor Drain	0125 South	103	EA	7	10+ years	
	Hand Dryer	0125 South	1	EA	7	6-10 years	
	Lavatory	0125 South	1	EA	7	2-5 years	
	Lighting - Lay-in	0125 South	3	EA	7	,	
	Partitions	0125 South	3 1	EA		10+ years	
	Urinals	0125 South	3	EA	7 7	10+ years 2-5 years	
	Walls - Concrete Block	0125 South	310	SF	7	•	
				SF SF		10+ years	
	Walls - Structural Glazed Tile	0125 South	310		7	10+ years	
	Water Closet	0125 South	1	EA	7	6-10 years	
	Accessories	0135 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0135 South	169	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0135 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0135 South	169	SF	7	10+ years	
	Floor Drain	0135 South	1	EΑ	7	10+ years	
	Hand Dryer	0135 South	1	EΑ	7	6-10 years	
	Lavatory	0135 South	1	EA	7	2-5 years	
	Lighting - Pendent/Surface	0135 South	1	EA	7	10+ years	
	Partitions	0135 South	4	EA	7	10+ years	
	Walls - Concrete Block	0135 South	310	SF	7	10+ years	
	Walls - Structural Glazed Tile	0135 South	310	SF	7	10+ years	
	Water Closet	0135 South	4	EA	7	2-5 years	
	Accessories	014 - 1.5 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	014 - 1.5 South	169	SF	6	10+ years	

Campus Name: Ashburn Page: 13 of 31 Assessment Date: 02/07/2024



Catego	ry : Room		В	uilding	: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	014 - 1.5 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	014 - 1.5 South	169	SF	6	10+ years	
	Floor Drain	014 - 1.5 South	1	EA	7	10+ years	
	Lavatory	014 - 1.5 South	1	EA	7	2-5 years	
	Lighting - Lay-in	014 - 1.5 South	1	EA	7	10+ years	
	Partitions	014 - 1.5 South	1	EA	7	10+ years	
	Urinals	014 - 1.5 South	3	EA	7	2-5 years	
	Walls - Concrete Block	014 - 1.5 South	292	SF	7	10+ years	
	Walls - Concrete Block	014 - 1.5 South	8	SF	6	10+ years	
	Walls - Structural Glazed Tile	014 - 1.5 South	300	SF	7	10+ years	
	Water Closet	014 - 1.5 South	1	EA	7	10+ years	
	Accessories	015 - 1.5 South	169	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	015 - 1.5 South	169	SF	7	10+ years	
	Doors - Wood Doors inclu hw	015 - 1.5 South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	015 - 1.5 South	169	SF	7	10+ years	
	Floor Drain	015 - 1.5 South	1	EA	7	10+ years	
	Lavatory	015 - 1.5 South	1	EA	7	10+ years	
	Lighting - Pendent/Surface	015 - 1.5 South	1	EA	7	10+ years	
	Partitions	015 - 1.5 South	4	EA	7	10+ years	
	Walls - Concrete Block	015 - 1.5 South	310	SF	7	10+ years	
	Walls - Structural Glazed Tile	015 - 1.5 South	310	SF	7	10+ years	
	Water Closet	015 - 1.5 South	4	EA	7	10+ years	
	Accessories	016 - 1.5 Floor South	102	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	016 - 1.5 Floor South	102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	016 - 1.5 Floor South	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	016 - 1.5 Floor South	102	SF	7	10+ years	
	Hand Dryer	016 - 1.5 Floor South	1	EA	7	6-10 years	
	Lavatory	016 - 1.5 Floor South	1	EA	7	10+ years	
	Lighting - Lay-in	016 - 1.5 Floor South	1	EA	7	10+ years	
	Partitions	016 - 1.5 Floor South	3	EA	7	10+ years	
	Walls - Concrete Block	016 - 1.5 Floor South	210	SF	7	10+ years	
	Walls - Structural Glazed Tile	016 - 1.5 Floor South	210	SF	7	10+ years	
	Water Closet	016 - 1.5 Floor South	3	EA	7	10+ years	
	Accessories	0175 North	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0175 North	120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	0175 North	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0175 North	120	SF	7	10+ years	
	Hand Dryer	0175 North	1	EA	7	6-10 years	
	Lavatory	0175 North	2	EA	7	10+ years	
	Lighting - Lay-in	0175 North	3	EA	7	10+ years	
	Partitions	0175 North	1	EA	7	10+ years	
	Urinals	0175 North	2	EA	7	10+ years	
	Walls - Concrete Block	0175 North	216	SF	7	10+ years	
	Walls - Structural Glazed Tile	0175 North	324	SF	7	10+ years	
		•				<b>,</b>	

Campus Name: Ashburn Page : 14 of 31 Assessment Date: 02/07/2024



Catego	Category : Room				: Lease	d-Main	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	0175 North	1	EA	7	10+ years	
	Accessories	0185 North	120	SF	7	6-10 years	
	Ceiling - Splined	0185 North	110	SF	7	10+ years	
	Ceiling - Splined	0185 North	10	SF	4	0-1 year	Cracking and water damaged tiles
	Doors - Wood Doors inclu hw	0185 North	2	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0185 North	120	SF	7	10+ years	
	Hand Dryer	0185 North	1	EA	7	10+ years	
	Lavatory	0185 North	2	EA	7	10+ years	
	Lighting - Pendent/Surface	0185 North	1	EΑ	7	10+ years	
	Partitions	0185 North	3	EΑ	7	10+ years	
	Walls - Concrete Block	0185 North	211	SF	7	10+ years	
	Walls - Concrete Block	0185 North	5	SF	6	6-10 years	Cracking mortar
	Walls - Structural Glazed Tile	0185 North	324	SF	7	10+ years	
	Water Closet	0185 North	3	EA	7	10+ years	
	Accessories	219A - North restroom - Staff	20	SF	7	6-10 years	
	Ceiling - Splined	219A - North restroom - Staff	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	219A - North restroom - Staff	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	219A - North restroom - Staff	20	SF	7	10+ years	
	Lavatory	219A - North restroom - Staff	1	EA	7	10+ years	
	Lighting - Pendent/Surface	219A - North restroom - Staff	1	EA	7	10+ years	
	Walls - Concrete Block	219A - North restroom - Staff	108	SF	7	-	
			72	SF SF	7	10+ years	
	Walls - Structural Glazed Tile	219A - North restroom - Staff				10+ years	
	Water Closet	219A - North restroom - Staff	1	EA	7	10+ years	
	Accessories	B-008 - Basement	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	B-008 - Basement	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	B-008 - Basement	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	B-008 - Basement	120	SF	7	10+ years	
	Hand Dryer	B-008 - Basement	1	EA	7	6-10 years	
	Lavatory	B-008 - Basement	1	EA	7	2-5 years	
	Lighting - Pendent/Surface	B-008 - Basement	1	EA	7	10+ years	
	Partitions	B-008 - Basement	1	EA	7	10+ years	
	Urinals	B-008 - Basement	3	EA	7	2-5 years	
	Walls - Plaster/Drywall	B-008 - Basement	225	SF	7	10+ years	
	Walls - Structural Glazed Tile	B-008 - Basement	278	SF	7	10+ years	
	Water Closet	B-008 - Basement	1	EA	7	10+ years	
	Accessories	B-009 - Basement	144	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	B-009 - Basement	134	SF	7	10+ years	
	Ceiling - Plaster/Drywall	B-009 - Basement	10	SF	5	10+ years	Water damage, peeling paint
	Doors - Wood Doors inclu hw	B-009 - Basement	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	B-009 - Basement	144	SF	7	10+ years	
	Floor Drain	B-009 - Basement	1	EΑ	7	10+ years	
	Hand Dryer	B-009 - Basement	1	EA	7	6-10 years	
	Lavatory	B-009 - Basement	1	EA	7	10+ years	
	Lighting - Lay-in	B-009 - Basement	1	EA	7	10+ years	
						,	

Campus Name: Ashburn Page : 15 of 31 Assessment Date: 02/07/2024



Catego	ry : Room		Building : Leased-Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	B-009 - Basement	1	EA	7	10+ years			
	Partitions	B-009 - Basement	2	EA	7	10+ years			
	Walls - Plaster/Drywall	B-009 - Basement	240	SF	7	10+ years			
	Walls - Structural Glazed Tile	B-009 - Basement	348	SF	7	10+ years			
	Water Closet	B-009 - Basement	2	EA	7	10+ years			
Catego	ry : Classroom		В	uilding	: Lease	d-Main			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classroo	om #101 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	54	LF	7	10+ years			
	Ceiling - Splined	1st Floor	732	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	732	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Storage/ Closet	1st Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	Not previously assessed		
	Walls - Concrete Block	1st Floor	892	SF	7	10+ years	Not previously assessed		
	Walls - Coliciete block	1St Floor	092	SF	,	10+ years			
Classro	om #102 (Kindergarten)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	54	LF	6	10+ years			
	Ceiling - Splined	1st Floor	732	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	732	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Storage/ Closet	1st Floor	10	SF	7	6-10 years			
	Student Lockers - One Tier	1st Floor	24	EA	7	,			
	Walls - Concrete Block	1st Floor	892	SF	7	10+ years			
	Walls - Concrete Block	IST FIOOI	092	SF	,	10+ years			
Classro	om #103 (Kindergarten)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	54	LF	6	6-10 years			
	Ceiling - Splined	1st Floor	732	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	732	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	20	LF	7	6-10 years			
	Storage/ Closet	1st Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	1st Floor	24	EA	7				
			892	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	692	SF	1	10+ years			

Campus Name: Ashburn Page : 16 of 31 Assessment Date: 02/07/2024



Category : Classroom			В	uilding	: Lease	d-Main	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #104 (Other Instructional Lies)						
Classion	om #104 (Other Instructional Use) Casework	1st Floor	54	LF	7	10	
						10+ years	
	Ceiling - Splined	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	Relamp
	Lighting - Pendent/Surface	1st Floor	1	EA	5	6-10 years	Missing cover
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	772	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	om #105 (Store Room)						
	Casework	1st Floor	54	LF	7	10+ years	
	Ceiling - Splined	1st Floor	732	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	732	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	772	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
	Traile Structural Stazes Tile	1001	120	0.	•	io: youro	
_Classroo	om #106 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	920	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Damaged and loose tiles
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	925	SF	7	6-10 years	
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Missing and broken tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	-
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classro	om #107 (Music Room)						
CidaaiUl	AC Units	1st Floor	1	EA	7	6-10 years	
	AO Olika	13111001	1	LA	,	0-10 years	



Catego	ry : Classroom	В	uilding	: Lease		oo o ot Louis Avenoe, omeago, ie ooose	
<u> </u>					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	930	SF	6	6-10 years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	930	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	om #109 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	7	10+ years	
	Ceiling - Splined	1st Floor	920	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Broken tiles
	Doors - Transom Window	1st Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Carpet	1st Floor	930	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	ĒA	6	6-10 years	Relamp
	Lighting - Pendent/Surface	1st Floor	11	EA	6	6-10 years	1
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	810	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	om #113 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	54	LF	6	10+ years	
	Ceiling - Splined	1st Floor	930	SF	6	10+ years	
	Doors - Transom Window	1st Floor	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Carpet	1st Floor	930	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	690	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	120	SF	7	10+ years	
Classroo	om #114 (Regular Classroom)						
_ UIGSSI UI	AC Units	1st Floor	1	EA	7	6-10 years	
	AC UIIIS	191 11001	ı	EA	,	0-10 years	



atego	ry : Classroom		В	Building : Leased-Main					
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Casework	1st Floor	23	LF	6	10+ years			
	Ceiling - Splined	1st Floor	805	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	805	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	12	SF	7	10+ years			
	Student Lockers - One Tier	1st Floor	26	ĒΑ	7	10+ years			
	Walls - Concrete Block	1st Floor	540	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years			
lassroc	om #115 (Science Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	78	LF	7	10+ years			
	Ceiling - Splined	1st Floor	805	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	805	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	6	6-10 years			
	Storage/ Closet	1st Floor	12	SF	7	-			
	Student Lockers - One Tier	1st Floor	26	EA	7	10+ years			
				SF		10+ years			
	Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor 1st Floor	540 150	SF	7 7	10+ years 10+ years			
laceroe	om #116 (Regular Classroom)								
iassiuc	,	1st Floor	1	ГΛ	7	6.10 vooro			
	AC Units		1	EA	7	6-10 years			
	Casework	1st Floor	23	LF 0F	7	10+ years			
	Ceiling - Splined	1st Floor	790	SF	6	6-10 years	NA		
	Ceiling - Splined	1st Floor	15	SF	4	0-1 year	Water damage		
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	765	SF	7	6-10 years			
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Missing tiles		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	6	6-10 years			
	Student Lockers - One Tier	1st Floor	26	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	873	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	165	SF	7	10+ years			
assroc	om #117 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	23	LF	7	10+ years			



Catego	ry : Classroom	В	Building : Leased-Main					
				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	775	SF	7	6-10 years		
	Floor - Tile	1st Floor	30	SF	4	0-1 year	Missing tiles	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	6-10 years	3	
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Student Lockers - One Tier	1st Floor	26	EA	6	10+ years		
	Walls - Concrete Block	1st Floor	873	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	165	SF	7	10+ years		
Classroo	om #201 (Regular Classroom)							
21000101	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	54	LF	7	10+ years		
	Casework Ceiling - Splined			SF		•		
	Chalk Board	2nd Floor 2nd Floor	744 12	SF LF	6 4	6-10 years		
						2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	734	SF	7	6-10 years	61.1	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Chipped tiles	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years		
Classroo	om #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	54	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	744	SF	7	6-10 years		
	Chalk Board	2nd Floor	24	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	744	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years		
Classroo	om #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	54	LF	7	10+ years		
	Casework Ceiling - Splined	2nd Floor	744	SF	6	6-10 years		
	Chalk Board	2nd Floor	24	LF	4	2-5 years		
				EA	4 7	•		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĽΑ	1	10+ years		

Campus Name: Ashburn Page : 20 of 31 Assessment Date: 02/07/2024



Category : Classroom				Building : Leased-Main					
_				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Floor - Tile	2nd Floor	734	SF	7	6-10 years			
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Missing tiles		
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	3		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years			
lassroc	om #204 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	54	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	6	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor 2nd Floor	24	Sr EA	7		Not proviously assessed		
		2nd Floor 2nd Floor		SF		10+ years	Not previously assessed		
	Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor 2nd Floor	640 135	SF SF	7 7	10+ years			
	Walls - Structural Glazed Tile	2110 1 1001	133	OI.	,	10+ years			
lassroc	om #205 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	54	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	744	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	10	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years	Not previously assessed		
	Walls - Concrete Block	2nd Floor	640	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	135	SF	7	10+ years			
lassroc	om #206 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years			
	Chalk Board	2nd Floor	18	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	724	SF	7	6-10 years			
	Floor - Tile	2nd Floor	20	SF	4	0-10 years	Damaged tiles		
	i iooi i iio	2110 1 1001	20	51	7	o i yeai	Damagea tiles		

Campus Name: Ashburn Page : 21 of 31 Assessment Date: 02/07/2024



Category : Classroom			В	Building : Leased-Main				
					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years		
Classroo	om #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	30	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	724	SF	7	10+ years		
	Ceiling - Splined	2nd Floor	20	SF	4	0-1 year	Missing tiles	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	Wildeling tilled	
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	744	SF	7	6-10 years		
				EA	7	•		
	Lighting - Pendent/Surface	2nd Floor	12	SF		6-10 years		
	Storage/ Closet	2nd Floor	10		7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years		
Classroo	om #208 (Science Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	36	LF	7	10+ years		
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years		
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	729	SF	7	6-10 years		
	Floor - Tile	2nd Floor	15	SF	4	0-1 year	Chipped tiles	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	• • • • • • • • • • • • • • • • • • • •	
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years		
lassroo	om #209 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	30	LF	7	10+ years		
	Casework Ceiling - Splined	2nd Floor 2nd Floor	744	SF	7	10+ years		
	Chalk Board	2nd Floor 2nd Floor		LF				
			24	LF SF	4	2-5 years		
	Doors - Transom Window	2nd Floor	3		7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	744	SF	7	6-10 years		

Campus Name: Ashburn Page : 22 of 31 Assessment Date: 02/07/2024



Catego	ry : Classroom		В	Building : Leased-Main						
			Recommend							
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years				
	Marker Board	2nd Floor	12	LF	7	6-10 years				
	Storage/ Closet	2nd Floor	10	SF	7	10+ years				
	Student Lockers - One Tier	2nd Floor	24	ĒΑ	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years				
lassroc	om #210 (Office)									
1400101	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	30	LF	7	10+ years				
	Casework Ceiling - Splined	2nd Floor	739	SF	7	10+ years				
	Ceiling - Splined Ceiling - Splined	2nd Floor	5	SF	4	0-1 year	Cracked tile			
			12	LF		•	Cracked life			
	Chalk Board	2nd Floor			4	2-5 years				
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	744	SF	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years				
	Marker Board	2nd Floor	8	LF	7	6-10 years				
	Storage/ Closet	2nd Floor	10	SF	7	10+ years				
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years				
lassroc	om #211 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	30	LF	7	10+ years				
	Ceiling - Splined	2nd Floor	744	SF	6	6-10 years				
	Chalk Board	2nd Floor	16	LF	4	2-5 years				
	Doors - Transom Window	2nd Floor	3	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	744	SF	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years				
	Marker Board	2nd Floor	8	LF	7	6-10 years				
	Storage/ Closet	2nd Floor	10	SF	7	10+ years				
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years				
lassroo	om #212 (Office)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	30	LF	7	10+ years				
	Casework Ceiling - Splined	2nd Floor 2nd Floor	744	SF	6	6-10 years				
	Chalk Board	2nd Floor 2nd Floor	24	LF	4					
	Doors - Transom Window		3	SF		2-5 years				
		2nd Floor	3		7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	•	EA	7	10+ years				
	Floor - Carpet	2nd Floor	744	SF	7	6-10 years				

Campus Name: Ashburn Page : 23 of 31 Assessment Date: 02/07/2024



atego	ry : Classroom		B	Building : Leased-Main						
				_						
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years				
	Marker Board	2nd Floor	12	LF	7	6-10 years				
	Storage/ Closet	2nd Floor	10	SF	7	10+ years				
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	Corrected quantity			
lassroc	om #213 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	30	LF	7	10+ years				
	Ceiling - Splined	2nd Floor	744	SF	7	10+ years				
	Chalk Board	2nd Floor	24	LF	4	2-5 years				
	Doors - Transom Window	2nd Floor	3	SF	7	•				
			3			10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	· · · · · · · · · · · · · · · · · · ·	EA	7	10+ years				
	Floor - Tile	2nd Floor	744	SF	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years				
	Marker Board	2nd Floor	12	LF	7	6-10 years				
	Storage/ Closet	2nd Floor	10	SF	7	10+ years				
	Student Lockers - One Tier	2nd Floor	24	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years				
assroc	om #214 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	21	LF	7	10+ years				
	Ceiling - Splined	2nd Floor	756	SF	6	6-10 years				
	Chalk Board	2nd Floor	18	ĹF	4	2-5 years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	756	SF	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years				
	Marker Board	2nd Floor	8	LF	7	6-10 years				
				SF		•				
	Storage/ Closet	2nd Floor	12		7	10+ years	Not any development			
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years	Not previously assessed			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years				
assroc	om #215 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	21	LF	7	10+ years				
	Ceiling - Splined	2nd Floor	751	SF	6	6-10 years				
	Ceiling - Splined	2nd Floor	5	SF	4	0-1 year	Water damaged			
	Chalk Board	2nd Floor	16	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	2nd Floor	19	EA	7	10+ years				
	Floor - Tile	2nd Floor	756	SF	7	6-10 years				
		2nd Floor 2nd Floor	22	EA	7	•				
	Lighting - Pendent/Surface	2110 11001	22	EA	,	6-10 years				

Campus Name: Ashburn Page : 24 of 31 Assessment Date: 02/07/2024



Category : Classroom			В	Building : Leased-Main					
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years			
lassroo	om #216 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	21	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	756	SF	7	10+ years			
	Chalk Board	2nd Floor	14	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	756	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years			
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	12	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years			
lassroo	om #217 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	57	LF	6	10+ years			
	Ceiling - Splined	2nd Floor	756	SF	7	10+ years			
	Chalk Board	2nd Floor	24	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	756	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	12	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor	26	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	558	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	147	SF	7	10+ years			
atego	ry : Interior		В	uilding	: Lease	d-Main			
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor	0.11.	B							
	Ceiling - Splined	Basement B-010	800	SF	7	10+ years			
	Floor - Tile/Sheet	Basement B-010	800	SF	7	6-10 years			
	Lighting - Lay-in	Basement B-010	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	Basement B-010	1,485	SF	7	10+ years			
	Ceiling - Splined	Basement B-011	323	SF	7	10+ years			
	Drinking Fountains - Single Water Cooler	Basement B-011	1	EA	7	10+ years	New		
	Britishing redistante enigle water ecolor			_, ,	•	6-10 years	11011		



Catego	ry : Interior		Building : Leased-Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile/Sheet	Basement B-011	5	SF	4	0-1 year	Broken		
	Lighting - Lay-in	Basement B-011	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Basement B-011	715	SF	7	10+ years			
	Ceiling - Splined	Corridor 1	1,070	SF	7	10+ years			
	Ceiling - Splined	Corridor 1	10	SF	4	0-1 year	Missing tiles		
	Drinking Fountains - Single Fountain	Corridor 1	2	EA	7	10+ years			
	Floor - Terrazzo	Corridor 1	1,060	SF	7	10+ years			
	Floor - Terrazzo	Corridor 1	20	SF	5	1-2 years	Cracking		
	Lighting - Pendent/Surface	Corridor 1	9	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 1	1,200	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 1	1,190	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 1	10	SF	4	1-2 years	Missing tiles underneath water fountains		
	Ceiling - Splined	Corridor 2	1,782	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 2	2	EA	7	10+ years			
	Floor - Terrazzo	Corridor 2	1,782	SF	7	10+ years			
	Lighting - Pendent/Surface	Corridor 2	9	EA	7	6-10 years			
	Walls - Plaster/Drywall	Corridor 2	1,175	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 2	1,175	SF	7	10+ years			
	Ceiling - Splined	Corridor 3	666	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 3	1	EA	7	10+ years			
	Floor - Terrazzo	Corridor 3	650	SF	7	10+ years			
	Floor - Terrazzo	Corridor 3	16	SF	5	1-2 years	Cracking		
	Lighting - Pendent/Surface	Corridor 3	11	ĒΑ	7	6-10 years	3		
	Walls - Concrete Block	Corridor 3	830	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 3	824	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 3	6	SF	4	1-2 years	Missing tiles under water fountain		
	Ceiling - Splined	Corridor 4	1,772	SF	6	6-10 years	3		
	Ceiling - Splined	Corridor 4	10	SF	4	0-1 year	Chipped		
	Drinking Fountains - Single Fountain	Corridor 4	1	ĒΑ	7	10+ years	- 11		
	Floor - Terrazzo	Corridor 4	1,782	SF	7	10+ years			
	Lighting - Pendent/Surface	Corridor 4	9	EA	7	6-10 years			
	Walls - Plaster/Drywall	Corridor 4	1,175	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 4	1,175	SF	7	10+ years			
	Ceiling - Splined	Corridor 5	1,080	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 5	2	ĒΑ	7	10+ years			
	Floor - Terrazzo	Corridor 5	1,080	SF	7	10+ years			
	Lighting - Lay-in	Corridor 5	4	ĒΑ	6	6-10 years			
	Lighting - Pendent/Surface	Corridor 5	5	EA	7	6-10 years			
	Walls - Concrete Block	Corridor 5	1,200	SF	7	10+ years			
	Walls - Structural Glazed Tile	Corridor 5	1,200	SF	7	10+ years			
	Ceiling - Splined	Corridor 6	666	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Corridor 6	2	EA	7	10+ years			
	Floor - Terrazzo	Corridor 6	666	SF	7	6-10 years			
			300	٥.	•	- 12 ,00.0			

Campus Name: Ashburn Page : 26 of 31 Assessment Date: 02/07/2024



Catego	ry : Interior		Building : Leased-Main  Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	Corridor 6	10	EA	7	6-10 years				
	Walls - Concrete Block	Corridor 6	830	SF	7	10+ years				
	Walls - Structural Glazed Tile	Corridor 6	830	SF	7	10+ years				
	Ceiling - Splined	Vestibule 1	221	SF	7	10+ years				
	Doors - Side-lite	Vestibule 1	42	SF	7	10+ years				
	Doors - Steel Doors incl hw	Vestibule 1	2	EA	7	10+ years				
	Doors - Store Front	Vestibule 1	2	EA	7	10+ years				
	Floor - Terrazzo	Vestibule 1	221	SF	7	10+ years				
	Lighting - Lay-in	Vestibule 1	6	EA	7	10+ years				
	Walls - Concrete Block	Vestibule 1	108	SF	7	10+ years				
	Walls - Structural Glazed Tile	Vestibule 1	180	SF	7	10+ years				
	Ceiling - Splined	Vestibule 4	63	SF	6	10+ years				
	Doors - Side-lite	Vestibule 4	42	SF	7	10+ years				
	Doors - Steel Doors incl hw	Vestibule 4	2	ĒΑ	7	10+ years				
	Doors - Wood Doors include hw	Vestibule 4	1	EA	7	10+ years				
	Floor - Terrazzo	Vestibule 4	63	SF	7	10+ years				
	Lighting - Lay-in	Vestibule 4	1	EΑ	6	10+ years				
	Walls - Masonry	Vestibule 4	112	SF	7	10+ years				
	Ceiling - Plaster/Drywall	Vestibule 6	352	SF	7	10+ years				
	Doors - Side-lite	Vestibule 6	42	SF	7	10+ years				
	Doors - Steel Doors incl hw	Vestibule 6	4	EA	7	10+ years				
	Floor - Terrazzo	Vestibule 6	352	SF	7	10+ years				
	Lighting - Pendent/Surface	Vestibule 6	4	EA	7	10+ years				
	Walls - Masonry	Vestibule 6	480	SF	7	10+ years				
	Walls - Masolly	vestibule o	400	OI.	′	10+ years				
Safety										
Galety	Camera Viewing Station	1st Floor	1	EA	7	6-10 years				
	Security Cameras	1st Floor	3	EA	7	10+ years	Not previously assessed			
	Security Cameras	1st Floor	5	EA	7	6-10 years	Not previously assessed			
	Security Cameras	13111001	3	LA	,	0-10 years				
Stairs										
	Ceiling - Plaster/Drywall	Stair 1	35	SF	7	10+ years				
	Ceiling - Splined	Stair 1	243	SF	7	10+ years				
	Floor - Terrazzo	Stair 1	99	SF	7	10+ years				
	Handrails	Stair 1	45	LF	7	10+ years				
	Lighting - Lay-in	Stair 1	2	EA	6	6-10 years				
	Stairs - Terrazzo	Stair 1	92	LF	7	10+ years				
	Walls - Concrete Block	Stair 1	745	SF	7	10+ years				
	Walls - Structural Glazed Tile	Stair 1	335	SF	7	10+ years				
	Ceiling - Plaster/Drywall	Stair 2	162	SF	7	10+ years				
	Ceiling - Flaster/Drywali Ceiling - Splined	Stair 2	420	SF	7	,				
	Floor - Terrazzo	Stair 2 Stair 2	540	SF	7	10+ years				
	Handrails	Stair 2		LF	7 7	10+ years 10+ years				
			113			-				
	Lighting - Lay-in	Stair 2	4	EA	7	10+ years				



Category : Interior			Building : Leased-Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	Stair 2	4	EA	7	10+ years		
	Stairs - Terrazzo	Stair 2	312	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair 2	2,469	SF	7	10+ years		
	Walls - Structural Glazed Tile	Stair 2	915	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 3	65	SF	7	10+ years		
	Ceiling - Splined	Stair 3	420	SF	6	10+ years		
	Floor - Terrazzo	Stair 3	240	SF	7	10+ years		
	Handrails	Stair 3	54	LF	7	10+ years		
	Lighting - Lay-in	Stair 3	4	EA	6	6-10 years		
	Stairs - Terrazzo	Stair 3	115	LF	7	10+ years		
	Walls - Masonry	Stair 3	566	SF	7	10+ years		
	Walls - Structural Glazed Tile	Stair 3	250	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 4	162	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Stair 4	540	SF	6	10+ years		
	Ceiling - Splined	Stair 4	420	SF	6	10+ years		
	Floor - Terrazzo	Stair 4	540	SF	7	10+ years		
	Handrails	Stair 4	113	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 4	6	EA	7	10+ years		
	Stairs - Terrazzo	Stair 4	312	LF	6	10+ years		
	Walls - Masonry	Stair 4	1,584	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 5	50	SF	7	10+ years		
	Ceiling - Splined	Stair 5	384	SF	7	10+ years		
	Floor - Terrazzo	Stair 5	403	SF	7	10+ years		
	Handrails	Stair 5	54	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 5	3	EA	7	10+ years		
	Stairs - Terrazzo	Stair 5	96	LF	7	10+ years		
	Walls - Concrete Block	Stair 5	940	SF	7	10+ years		
	Walls - Structural Glazed Tile	Stair 5	625	SF	7	10+ years		
	Ceiling - Splined	Stair 6A	119	SF	6	10+ years		
	Floor - Terrazzo	Stair 6A	21	SF	7	10+ years		
	Handrails	Stair 6A	26	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 6A	1	EA	7	10+ years		
	Stairs - Terrazzo	Stair 6A	105	LF	7	10+ years		
	Walls - Structural Glazed Tile	Stair 6A	451	SF	7	10+ years		
	Ceiling - Splined	Stairs 6B	250	SF	6	10+ years		
	Floor - Terrazzo	Stairs 6B	176	SF	7	10+ years		
	Handrails	Stairs 6B	40	LF	7	10+ years		
	Lighting - Pendent/Surface	Stairs 6B	3	EA	7	10+ years		
	Stairs - Terrazzo	Stairs 6B	100	LF	7	10+ years		
	Walls - Masonry	Stairs 6B	600	SF	7	10+ years		
	•					•		





Category : Site **Building: Site** 

	y . Site			unung		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
il/Drai						no più como in	
ı/Diai	Civil/ Drainage - Catch Basin	Entire Site	1	EA	7	10+ years	Repaired
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	7	10+ years	Repaired
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain	Entire Site	1	EA	7	10+ years	
			9	EA	7		
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	/	10+ years	
ing							
	Fencing - Chain Link	Entire Site	303	LF	7	10+ years	New
	Fencing - Chain Link	Entire Site	432	LF	4	0-1 year	Damaged, deteriorated fence with
							missing sections. Detached and be
							posts and rails. Some fencing was
							demolished after previous
							assessment
	Fencing - New Standard Ornamental	Entire Site	300	LF	7	10+ years	New
	Fencing - Old Standard Ornamental	Entire Site	87	LF	5	6-10 years	
	<b>G</b>					,	
dscap			5.010				
	Irrigation	Entire Site	5,010	SF	7	10+ years	
	Landscape - Grass	Entire Site	5,010	SF	7	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	2,415	SF	4	0-1 year	Large cracks, alligatored surface
	Landscape - Hardscape- Concrete	Entire Site	4,750	SF	6	10+ years	
	Parkway trees	Entire Site	8	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,105	SF	7	10+ years	New 2023
	Planting Beds/ Area	Entire Site	300	SF	7	10+ years	New landscape area at trash enclosure
	Planting Beds/ Area	Entire Site	1,250	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	6,235	SF	7	10+ years	New, as well as reduced due to ne
	, ,		•			,	concrete, outdoor classroom, new
							playgrounds, and new planting are
	Play Area - Hardscape- Concrete	Entire Site	360	SF	7	10+ years	New concrete, outdoor seating are
	Retaining Wall - Concrete	Entire Site	320	SF	7	10+ years	rtow concrete, catagor coating are
	Retaining Wall - Masonry	Entire Site	65	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	20	SF	5	1-2 years	Loose stone, open joints
	Trash Receptacles	Entire Site	3	EA	7	10+ years	Loose storie, open joints
	Trasif Receptacies	Entire Site	3	EA	1	10+ years	
king L							
	Concrete Curbs	East	150	LF	7	10+ years	
	Interior Plantings	East	240	LF	7	10+ years	
	Surface - Asphalt	East	7,610	SF	4	1-2 years	Divided existing parking lot into two
							areas because of a new gate. This
							parking lot is used as a play area a
							well.

Page : 29 of 31 Campus Name: Ashburn Assessment Date: 02/07/2024



Catego	Category : Site		В	uilding	: Site		<u> </u>
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Asphalt	West	29,700	SF	4	0-1 year	Alligator and disintegrated surface throughout with large cracks and several potholes. Some patching has been made. Deducted 1000 ft.Ų for new concrete pad at trash enclosure, and 300 ft.Ų for new planting area behind this trash enclosure.
	Surface - Concrete	West	1,000	SF	7	10+ years	New at trash enclosure
	Trash Enclosure - Chain Links	West	1,296	SF	7	10+ years	
Playgrou	und						
	Equipment - School Age 5-12	Central Courtyard	1	EA	7	10+ years	
	Surface - Poured Surface	Central Courtyard	2,500	SF	7	10+ years	
	Equipment - Pre K 3-5	Central Courtyard	1	EA	7	10+ years	
	Surface - Poured Surface	Central Courtyard	700	SF	7	10+ years	
_Sidewall	KS						
	Sidewalks - Perimeter Sidewalks	Entire Site	13,266	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	600	SF	4	0-1 year	Upheaved, settlement, large cracks, spalling
Signage							
	Flag Pole - Flag Pole	East	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	East	1	EA	7	6-10 years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Ashburn Page: 30 of 31 Assessment Date: 02/07/2024

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Leased-Main	onaca coago		1101111001	110	(0.)	7	7.1.00		
Art Room	Regular Classroom	1st Floor	106	107-3	930	185	58	Υ	Υ
Computer Lab	Computer Lab	1st Floor	109	108	930	167	167	Y	Y
Computer Lab	Regular Classroom	1st Floor	113	112	930	167	49	Y	Υ
Kindergarten	Regular Classroom	1st Floor	102	102-1	732	176	54	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	103	103-K	732	176	54	Υ	Υ
Music Room	Regular Classroom	1st Floor	107	106-4	930	185	58	Υ	Υ
Office	Office	1st Floor	B006 - NA	B006	440	42	14	Υ	N
Office	Regular Classroom	2nd Floor	210	NA	744	176	54	Υ	Υ
Office	Regular Classroom	2nd Floor	212	NA	744	176	54	Υ	Υ
Other Instructional Use	Regular Classroom	1st Floor	104		732	176	54		
Regular Classroom	Art Room	2nd Floor	201	201-Art	744	176	54	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101-2	732	160	46	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	114	NA	805	161	53	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	116	NA	805	161	53	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	117	NA	805	161	53	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202-8	744	176	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203-7	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204-6	744	162	46	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205-5	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	NA	744	176	54	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	744	162	46	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	744	176	54	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	213	744	176	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	NA	756	163	53	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	NA	756	168	51	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	NA	756	168	51	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	NA	756	168	51	Y	Υ
Science Classroom	Regular Classroom	1st Floor	115	NA	805	161	53	Υ	Υ
Science Classroom	Regular Classroom	2nd Floor	208	NA	744	176	57	Υ	Υ
Store Room	Regular Classroom	1st Floor	105		732	176	54		