



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1959	1	31,760
Addition-Building B	1956	1	4,290
Branch	1956	2	34,329
Campus Total			70,379

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	<u> </u>		•			<u>.</u>	
	Entrance Control - Audio and Video	#1-Main-W	1	EA	6	10+ years	
	Exterior Doors - Store Front	#1-Main-W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1-Main-W	4	EA	6	10+ years	
	Exterior Doors - Side lite	#2-NW	2	EA	6	10+ years	
	Exterior Doors - Store Front	#2-NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2-NW	6	EA	6	10+ years	
	Exterior Stairs - Concrete	#2-NW	6	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#3-NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3-NE	3	LF	5	0-1 year	Cracked.
	Exterior Doors - Exterior Steel Door	#4-E	2	EA	5	1-2 years	Corroded door and frame
	Exterior Doors - Transom Lite	#4-E	1	EA	6	10+ years	
	Exterior Stairs - Stone	#4-E	6	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#4.5 - SE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4.5 - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4.5 - SE	4	LF	6	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	850	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	31,760	SF	7	10+ years	
Lighting							



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	10+ years	
Roof Sys	stem						
-	Access Ladder - Metal	Low Center Roof	1	EA	7	10+ years	
	Coping - Metal	Low Center Roof	508	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low Center Roof	30	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Low Center Roof	10,422	SF	5	0-1 year	Blistering throughout
	Roof Structure - Steel / Metal Deck/	Low Center Roof	10,422	SF	7	10+ years	3 3
	Concrete Topping		-,	_		, , , , ,	
	Coping - Metal	Low NW Roof	50	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW Roof	10	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Low NW Roof	150	SF	5	0-1 year	Blistering throughout, very old roof
	Roof Structure - Steel / Metal Deck/	Low NW Roof	150	SF	7	10+ years	bilatering throughout, very old roof
	Concrete Topping	LOW IVV IVOOI	100	Oi.	,	101 years	
	Access Ladder - Metal	Upper North Roof	1	EA	7	10+ years	
	Access Ladder - Metal	Upper North Roof	1	EA	7	•	
	Chimney - Brick Chimney- Concrete/ Mortar	Upper North Roof	46	LF	4	10+ years 0-1 year	Leaning chimney, open joints,
	Liner		40		4	0-1 year	cracked brick
	Coping - Metal	Upper North Roof	170	LF	6	10+ years	
	Coping - Stone	Upper North Roof	140	LF	6	10+ years	
	Coping - Stone	Upper North Roof	120	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper North Roof	78	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Upper North Roof	430	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Upper North Roof	10,990	SF	5	2-5 years	
	Roof Hatch - Metal	Upper North Roof	1	ĒΑ	4	0-1 year	Poorly placed hatch. Climber comes up to the hinge area of the hatch instead of the open area.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper North Roof	10,990	SF	7	10+ years	instead of the open area.
Walls							
	Canopy - Concrete/ Stucco	Entire Building	70	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	1,347	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	12,110	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,125	SF	4	1-2 years	Open joints, mostly at roof walls
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	25	SF	5	10+ years	opan jame, maanj ar too mano
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	280	SF	6	10+ years	
	Curtain wall - Glazed Single Pane	Entire Building	244	SF	6	10+ years	
	Curtain wall - Glazed Single Falle Curtain wall - Insulated Panel	Entire Building	126	SF	6	10+ years	
	Ourtain Wall - Insulated Fallel	Little building	120	SI-	O	TOT years	

Campus Name: Black Page : 2 of 39 Assessment Date: 01/08/2024



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Curtain wall - Louver	Entire Building	20	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,020	SF	6	10+ years	
	Lintels - Steel	Entire Building	304	LF	6	10+ years	
	Lintels - Steel	Entire Building	35	LF	4	1-2 years	Corroded, warped, steel
	Windows - Casement Aluminum Double- pane	Entire Building	266	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,112	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System					Tropiacomonia	
<u>-morgor</u>	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	7	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	6-10 years	
	Exit Signs - Auditoium	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	31,760	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	31,760	SF	6	6-10 years	
Main Sei	rvice						
	PA System	Entire Building	31,760	SF	5	2-5 years	Dated speakers, ongoing issues
	Main Electrical Service - 1200 A 120/208/3PH	Multipurpose Room Stage	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Corroding
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	-
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	2-5 years	
Catego	ry : Fire Protection		В	uilding	: Main		
J -	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement	9101 3 Euclid AVENDE, Chicago, IL 606
ire Aları	n					Replacement	
ire Alair	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building Entire Building	1	EA	6	6-10 years	Also serves addition.
	Fire Alarm Strobe Lights	Entire Building Entire Building	31,760	SF	6	6-10 years	Also serves addition.
	Fire Alarm_System	Entire Building Entire Building	31,760	SF	5	2-5 years	
	File Alaini_System	Entire Building	31,760	SF	5	2-5 years	
ategoi	y : Mechanical		В	uilding	: Main		
arogo.	y 1		_	uug		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	tioning		•			•	
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	5	2-5 years	
r Hand	ing Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - Less than 4000 cfm	Copy Room - Above Ceiling	1	EA	5	2-5 years	Dated unit
	Air Intake	Copy Room - Above Ceiling	1	EA	4	2-5 years	Rusted.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 12001-20000 cfm	Mechanical Room - North	1	EA	5	2-5 years	Dated unit
	Air Intake	Mechanical Room - North	1	EA	4	2-5 years	Dampers are rusted and need to manually adjusted.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 12001-20000 cfm	Mechanical Room - South	1	EA	5	2-5 years	Dated unit
	Air Intake	Mechanical Room - South	1	EA	4	2-5 years	Rusted and need to be manually adjusted.
oiler Sy	stems						
	Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH	Entire Building	8	EA	5	2-5 years	
	Chemical Pot Feeder	Entire Building	1	EA	6	2-5 years	Feed system
	Combustion Dampers	Entire Building	1	EA	4	0-1 year	Broken link connecting all dampe together
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - Less than 500 MBH	Entire Building	8	EA	5	2-5 years	togo.i.e.
	Water Fill System	Entire Building	1	EA	5	2-5 years	
eating [Devices						
Ŭ	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	5	2-5 years	
	Fin Tube - Hot Water	Entire Building	350	LF	5	2-5 years	



Catego	y : Mechanical		E	Building	: Main	_	
Craun	Hom Tune	Lagation	Quantity	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vlechani	cal Plumbing	- · · · -					
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	2-5 years	
	Hydronic Supply and Return - Steel	Entire Building	325	LF	5	2-5 years	
empera	ture Control						
	Pneumatic System	Entire Building	31,760	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	10	EA	4	0-1 year	Not operational
entilatio	n						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	5	LF	5	2-5 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No suppression system
atego	y : Plumbing		E	Building	: Main		
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OCIVI	IVAIIN	Replacement	Comments
lot Wate	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
						·	
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	31,760	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	31,760	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	31,760	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	31,760	SF	6	2-5 years	
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	31,760	SF	6	2-5 years	

Campus Name: Black Page : 5 of 39 Assessment Date: 01/08/2024



Catego	ry : Plumbing		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	(from Risers to Fixtures)							
	Sanitary Piping	Entire Building	31,760	SF	5	2-5 years		
	Storm Piping	Entire Building	31,760	SF	5	2-5 years		
	Vent Piping	Entire Building	31,760	SF	5	2-5 years		
Pumps								
•	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years		
	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years		

Building: Main Category: Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	0.5- Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	0.5- Faculty Lounge	249	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5- Faculty Lounge	1	EΑ	7	10+ years	
	Floor - Tile	0.5- Faculty Lounge	249	SF	6	10+ years	
	Lighting - Pendent/Surface	0.5- Faculty Lounge	4	EΑ	7	6-10 years	
	Power Distribution	0.5- Faculty Lounge	4	EΑ	7	10+ years	
	Storage/ Closet	0.5- Faculty Lounge	57	SF	7	10+ years	
	Walls - Concrete Block	0.5- Faculty Lounge	363	SF	7	10+ years	
	Walls - Plaster/Drywall	0.5- Faculty Lounge	182	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	98	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	98	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	245	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Assistant Principals Office	153	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Assistant Principals Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor - Assistant Principals Office	153	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Assistant Principals Office	4	EA	7	6-10 years	
	Power Distribution	1st Floor - Assistant Principals Office	4	EA	7	10+ years	
	Storage/ Closet	1st Floor - Assistant Principals Office	10	SF	5	10+ years	
	Walls - Concrete Block	1st Floor - Assistant Principals Office	500	SF	6	10+ years	
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	298	SF	7	10+ years	
		***************************************			-	. ,	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor - Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office	298	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Main Office	8	EA	7	6-10 years	
	Power Distribution	1st Floor - Main Office	6	EA	7	10+ years	
	Storage/ Closet	1st Floor - Main Office	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor - Main Office	640	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Office//Copy Room	252	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Office//Copy Room	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor - Office//Copy Room	252	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Office//Copy Room	6	ĒΑ	7	6-10 years	
	Power Distribution	1st Floor - Office//Copy Room	6	ΕA	7	10+ years	
	Walls - Concrete Block	1st Floor - Office//Copy Room	576	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Principals Office	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principals Office	2	EA	7	10+ years	
	Floor - Tile	1st Floor - Principals Office	200	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principals Office	7	EA	7	6-10 years	
	Power Distribution	1st Floor - Principals Office	4	EA	7	10+ years	
	Storage/ Closet	1st Floor - Principals Office	67	SF	7	10+ years	
	Walls - Concrete Block	1st Floor - Principals Office	492	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principals Office	108	SF	7	10+ years	
	Walls - Flaster/Drywall	13t 1 looi - 1 fincipais Office	100	OI.	,	10+ years	
Auditoriu	ım & Theater						
	Ceiling - Plaster/Drywall	0.5 Floor	4,000	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	6	EA	6	10+ years	
	Floor - Terrazzo	0.5 Floor	3,500	SF	7	10+ years	
	Floor - Wood	0.5 Floor	500	SF	6	10+ years	
	Lighting - Lay-in	0.5 Floor	20	EA	7	6-10 years	
	Main Floor Seating	0.5 Floor	450	EA	5	6-10 years	
	Sound System	0.5 Floor	430	EA	5	6-10 years	
	Stage	0.5 Floor	500	SF	6	10+ years	
	Stage Curtain	0.5 Floor	1	EA	7	6-10 years	
	Stage Curtain Stage Lighting System	0.5 Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	0.5 Floor	12	LF	6		
	Walls - Concrete Block		1,000	SF	6	10+ years	
		0.5 Floor				10+ years	
	Walls - Masonry	0.5 Floor	3,000	SF	7	10+ years	
	Walls - Metal Panel	0.5 Floor	1,000	SF	7	10+ years	
_Gvmnasi	ia						
	Ceiling - Lay-in	0.5 Floor	5,413	SF	7	10+ years	
	Ceiling - Plaster/Drywall	0.5 Floor	5,413	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	4	EA	7	10+ years	
	Floor - Tile	0.5 Floor	10,786	SF	7	10+ years	
	Floor - Tile	0.5 Floor	40	SF	4	1-2 years	Cracked and chipped flooring
	1100. 1110	0.0 1 1001	70	Oi.	т	1 2 yours	throughout



Catego	ry : Room		В	uilding	: Main		STOT & Eddid AVENOE, Officago, IE 00017
2 22 2 2 2			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	0.5 Floor	27	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	0.5 Floor	49	EΑ	7	6-10 years	
	Scoreboards	0.5 Floor	1	EA	7	6-10 years	
	Stage	0.5 Floor	1,200	SF	4	0-1 year	Major crack in flooring and missing
	S .		,			,	tiles
	Stage Curtain	0.5 Floor	2	EA	7	6-10 years	
	Stage-Stairs - Tile	0.5 Floor	60	LF	6	6-10 years	
	Walls - Concrete Block	0.5 Floor	3,626	SF	7	10+ years	
	Walls - Masonry	0.5 Floor	1,813	SF	7	10+ years	
	Walls - Metal Panel	0.5 Floor	1,813	SF	6	10+ years	
	Wallo Wolai Fallor	0.011001	1,010	O.	J	101 youro	
_Kitchen							
	Ceiling - Plaster/Drywall	0.5 Floor	888	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	4	EA	7	10+ years	
	Floor - Tile	0.5 Floor	888	SF	6	10+ years	
	Lighting - Pendent/Surface	0.5 Floor	10	EA	7	6-10 years	
	Walls - Concrete Block	0.5 Floor	1,292	SF	7	10+ years	
			, -			, , , , , ,	
Library							
	AC Unit	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	47	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	864	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	98	SF	6	10+ years	
	Floor - Tile	1st Floor	766	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	249	SF	7	10+ years	
	,					,	
_MDF_ID							
	Doors - Wood Doors inclu hw	Room 102	1	EA	7	10+ years	
	Finishes	Room 102	225	SF	7	6-10 years	
	Window AC Unit	Room 102	1	EA	7	6-10 years	
Mechani	ical/ Service Rooms						
viconan	Mechanical/ Service Rooms	1.5 - Above Stage	342	SF	5	10+ years	
	Mechanical/ Service Rooms	1.5 - Above Stage	342	SF	5	10+ years	
	Storage Room	1.5 - Above Stage	108	SF	7	10+ years	
	Boiler Room	Basement	225	SF	7	10+ years	
			20,134	SF SF	7		
	Crawl Space - Unfinished	Basement		SF SF		10+ years	
	Janitor's Closet	Basement	22		5	10+ years	
	Mechanical/ Service Rooms	Basement	10	SF	7	10+ years	
	Storage Room	Basement	3,371	SF	5	10+ years	



Category : Room			Building : Main				
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	Basement	40	SF	5	10+ years	
estroon		4 . 5				0.40	
	Accessories	1st Floor	69	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	69	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	69	SF	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	274	SF	7	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
	Accessories	1st Floor	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	45	SF	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Urinals	1st Floor	2	ΕA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	91	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	15	SF	5	1-2 years	Crack in corner
	Water Closet	1st Floor	5	EA	7	10+ years	Ordok in comor
	Accessories	1st Floor Staff Restroom/Inside	22	SF	7	6-10 years	
	Accessories	Principal's office	22	Oi	,	0-10 years	
	Ceiling - Plaster/Drywall	1st Floor Staff Restroom/Inside	5	SF	7	10 L Vooro	
	Celling - Plaster/Drywaii		3	SF	,	10+ years	
	Cailing Diagton/Drawell	Principal's office	47	C.E.	7	40	
	Ceiling - Plaster/Drywall	1st Floor Staff Restroom/Inside	17	SF	7	10+ years	
	B W IB : 1 I	Principal's office		_ ^	-	40	
	Doors - Wood Doors inclu hw	1st Floor Staff Restroom/Inside	1	EA	7	10+ years	
		Principal's office			_		
	Floor - Tile Ceramic/ Porcelain	1st Floor Staff Restroom/Inside	22	SF	7	10+ years	
		Principal's office					
	Lavatory	1st Floor Staff Restroom/Inside	1	EA	7	10+ years	
		Principal's office					
	Lighting - Pendent/Surface	1st Floor Staff Restroom/Inside	1	EA	7	6-10 years	
		Principal's office					
	Walls - Concrete Block	1st Floor Staff Restroom/Inside	25	SF	7	10+ years	
		Principal's office				•	
	Walls - Concrete Block	1st Floor Staff Restroom/Inside	5	SF	5	0-1 year	Quantity updated. Cracked wall
		Principal's office				,	, ,
	Walls - Structural Glazed Tile	1st Floor Staff Restroom/Inside	25	SF	7	10+ years	
	Oli dollarar Olazoa i lio	Principal's office	20	٥.	•	io. youro	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor Staff Restroom/Inside	1	EA	7	10+ years	
		Principal's office					
	Accessories	Basement	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	180	SF	6	10+ years	
	Lavatory	Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	1	EΑ	7	6-10 years	
	Partitions	Basement	1	EA	5	10+ years	
	Urinals	Basement	2	EΑ	6	10+ years	
	Walls - Structural Glazed Tile	Basement	450	SF	6	10+ years	
	Water Closet	Basement	1	EA	6	10+ years	
	Accessories	Basement	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	217	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	217	SF	7	10+ years	
	Lavatory	Basement	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	Quantity updated to match current
	Lighting - Wall Mounted	Basement	3	EA	7	6-10 years	observations. Re-lamp fixture
	Partitions	Basement	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	Basement	545	SF	7	10+ years	
	Water Closet	Basement	2	ĒΑ	7	10+ years	
						,	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	40	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	878	SF	7	10+ years	
	Walls - Tile	1st Floor	50	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classro	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	

Campus Name: Black Page : 10 of 39 Assessment Date: 01/08/2024



Catego	ry : Classroom		В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
_Classroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
Classroo	m #105 (Regular Classroom)						
Classioo	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
Classres	m #106 (Office)						
_Classioo	AC Units	1st Floor	1	EA	7	6-10 years	_
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7 7	10+ years	
	Chalk Board	1st Floor	450 8	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	o 21	SF	7	2-5 years 10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years 10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years 10+ years	
	Lighting - Pendent/Surface	1st Floor	450 10	SF EA	7 7		
	Storage/ Closet	1st Floor	5	SF	7 7	6-10 years 10+ years	
	Walls - Concrete Block	1st Floor	ა 777	SF SF	7 7		
	vvans - Concrete Block	IST LIOOL	111	or.	1	10+ years	
_Classroo	m #107 (Office)						

Campus Name: Black Page : 11 of 39 Assessment Date: 01/08/2024



Catego	Category : Classroom		В	uilding	: Main		. ,		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	1st Floor	1	EΑ	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years			
	Doors - Side-lite	1st Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	450	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	5	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years			
_Classroo	om #108 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years			
	Doors - Side-lite	1st Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	450	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	5	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years			
Classroo	om #109 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years			
	Doors - Side-lite	1st Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	450	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	5	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years			
_Classroo	om #110 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years			
	Doors - Side-lite	1st Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	450	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Marker Board	1st Floor	14	LF	7	6-10 years			
	Storage/ Closet	1st Floor	5	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	5 777	SF	7	10+ years			
	vvalis - Colloidie Diock	1311 1001	111	OI.	,	10+ years			



Catego	Category : Classroom		В	uilding	: Main		STOT & Eddid AVENUE, Officago, IE 00017
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
Classroo	m #112 (Regular Classroom)						
UIGSSIUL	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	225	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	225	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	577	SF	7	10+ years	
	Walls Condicte Block	13111001	011	Oi.	,	101 years	
Classroo	m #113 (Regular Classroom)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
Classroo	m #114 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Floor - Tile	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	5	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	777	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	m #Basement (Art Room)						
	,						

Campus Name: Black Page: 13 of 39 Assessment Date: 01/08/2024



Catego	ry : Classroom	Category : Classroom			Building : Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Casework	Basement	49	LF	7	10+ years			
	Ceiling - Lay-in	Basement	55	SF	7	10+ years			
	Ceiling - Lay-in	Basement	1,373	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Basement	2	EΑ	7	10+ years			
	Floor - Tile	Basement	1,428	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement	25	EA	7	6-10 years			
	Storage/ Closet	Basement	50	SF	7	10+ years			
	Walls - Concrete Block	Basement	1,164	SF	7	10+ years			
	Walls - Structural Glazed Tile	Basement	206	SF	7	10+ years			

Category : Interior Building: Main

ategoi	ry: interior		D	ullaing	. IVIAIII		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor-Corridor towards Building B	1,212	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor-Corridor towards Building B	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor-Corridor towards Building B	1,212	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Corridor towards Building B	10	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor-Corridor towards Building B	4	LF	6	10+ years	
	Walls - Concrete Block	1st Floor-Corridor towards Building B	2,536	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor-Corridor towards Building B	42	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Entry corridor	788	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Entry corridor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor-Entry corridor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor-Entry corridor	788	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Entry corridor	8	ĒΑ	7	10+ years	
	Stairs - Concrete Stairs	1st Floor-Entry corridor	4	LF	7	10+ years	
	Walls - Masonry	1st Floor-Entry corridor	1,320	SF	7	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	5	2-5 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	North East	140	SF	7	10+ years	
	Floor - Tile/Sheet	North East	140	SF	7	10+ years	

Campus Name: Black Page : 14 of 39 Assessment Date: 01/08/2024



Catego	Category : Interior			Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Handrails	North East	54	LF	7	10+ years			
	Lighting - Pendent/Surface	North East	2	EA	7	6-10 years			
	Stairs - Tile	North East	40	LF	7	10+ years			
	Walls - Concrete Block	North East	465	SF	7	10+ years			
	Walls - Concrete Block	North East	40	SF	7	10+ years			

Campus Name: Black Page: 15 of 39 Assessment Date: 01/08/2024



Category : Exterior			Building : Addition-Building B					
			Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Exterior Doors - Exterior Steel Door	#5 - SE	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#5 - SE	1	EA	6	10+ years		
	Exterior Stairs - Stone	#5 - SE	6	LF	5	6-10 years		
	Exterior Doors - Exterior Steel Door	#6-SE	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#6-SE	3	LF	5	0-1 year	Cracking.	
	Exterior Doors - Store Front	#7-SW	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#7-SW	2	EA	6	10+ years		
undati	on							
	Foundation - Concrete	Entire Building	260	LF	7	10+ years		
	Foundation - Concrete	Entire Building	10	LF	5	10+ years		
	Superstructure - Concrete	Entire Building	4,290	SF	7	10+ years		
	Superstructure - Concrete	Entire Building	10	SF	5	10+ years		
hting								
Ū	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	Repaired	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	10+ years		
of Sys	stem							
,	Coping - Stone	Low SE/SW Roof	285	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Low SE/SW Roof	6	LF	6	10+ years		
	Downspouts - Interior Downspouts	Low SE/SW Roof	20	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Low SE/SW Roof	285	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	Low SE/SW Roof	1,420	SF	5	0-1 year	Blistering throughout	
	Roof Structure - Heavy Timber	Low SE/SW Roof	1,420	SF	7	10+ years		
	Coping - Metal	Main Roof	200	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	20	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Main Roof	200	LF	6	10+ years		
	Roof - Modified Bitumen	Main Roof	2,545	SF	5	2-5 years		
	Roof - Modified Bitumen	Main Roof	50	SF	4	1-2 years	Blistered surface	
	Roof Structure - Heavy Timber	Main Roof	2,595	SF	7	10+ years		
alls								
	Cheek-Wall - Stone	Entire Building	130	SF	5	10+ years		
	Exterior Walls - Brick	Entire Building	1,559	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	25	SF	5	10+ years		
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Open joints	
	Exterior Walls - Stone-Cast	Entire Building	216	SF	5	10+ years		

Campus Name: Black Page : 16 of 39 Assessment Date: 01/08/2024



Catego	ry : Exterior		В	uilding	: Additi	on-Building B	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Curtain wall - Glazed Double Pane	Entire Building	22	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	124	SF	6	10+ years	
	Lintels - Steel	Entire Building	59	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	124	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Additi	on-Building B	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System	Location	Quantity	OOW	Naiik	Replacement	Comments
Lineigei	Emergency Battery Packs - Corridors and	Corridors and Stairs	6	EA	7	6-10 years	
	Stairs				-	-	
	Exit Signs - Corridors and Stairs	Corridors and Stairs	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	4,290	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	4,290	SF	6	6-10 years	
Main Se	rvice						
	PA System	Entire Building	4,290	SF	5	2-5 years	Dated speakers, ongoing issues
	·	•				·	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uildina	: Additi	on-Building B	
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	4,290	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	4,290	SF	6	6-10 years	
Catego	ry : Mechanical		R	uildina	· Additio	on-Building B	
Outogo	i y : inconumoui			unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems		•			•	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20	Roof	1	EA	5	2-5 years	Deteriorating. 7.5 tons
	tons						
Heating							
Heating		1st Floor	6	LF	5	2-5 years	
Heating	Devices	1st Floor Entire Building	6 7	LF EA	5 5	2-5 years 2-5 years	Dated units

Campus Name: Black Page: 17 of 39 Assessment Date: 01/08/2024



Category : Mechanical

Robert A Black Magnet Elementary School 9101 S Euclid AVENUE, Chicago, IL 60617

9101 S Euclid AVENUE, Chicago, IL 60617 **Building : Addition-Building B**

Croun	Hom Type	Location	Ougatitu	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	75	LF	6	6-10 years	
Tempera	ature Control						
·	Electric Thermostat	1st Floor	2	EA	6	6-10 years	
Ventilation	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	5	2-5 years	
Catego	ry : Plumbing		В	uilding	: Additi	on-Building B	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	4,290	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	4,290	SF	6	2-5 years	
	Sanitary Piping	Entire Building	4,290	SF	6	6-10 years	
	Storm Piping	Entire Building	4,290	SF	6	6-10 years	
	Vent Piping	Entire Building	4,290	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Additi	on-Building B	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	480	SF	7	10+ years	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	480	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	480	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Maintenance Office	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Maintenance Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor Maintenance Office	150	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Maintenance Office	2	EA	7	6-10 years	
	Storage/ Closet	1st Floor Maintenance Office	236	SF	7	10+ years	
	Walls - Concrete Block	1st Floor Maintenance Office	480	SF	7	10+ years	
	Work SInk	1st Floor Maintenance Office	1	EA	7	10+ years	
_Locker/S	Shower Room						
	Ceiling - Exposed	1st Floor	1,426	SF	7	10+ years	

Campus Name: Black Page: 18 of 39 Assessment Date: 01/08/2024



Catego	ry : Room		В	uildina	: Additi	on-Building B	9101 3 Euclid AVENDE, Chicago, IL 6061
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile/Sheet	1st Floor	1,426	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	30	EA	7	6-10 years	
	Student Lockers - Two Tier	1st Floor	344	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,306	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	435	SF	7	10+ years	
	,					,	
Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	300	SF	5	6-10 years	
Restrooi	n						
	Accessories	1st Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	206	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	206	SF	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	800	SF	7	10+ years	
	Water Closet	1st Floor	3	ĒΑ	7	10+ years	
	Accessories	1st Floor	164	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	164	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	164	SF	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	•	
						6-10 years	
	Partitions	1st Floor	5	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	480	SF	7	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Additi	on-Building B	
	Ham Time	Location	Overtitue	HOM	Dank	Recommend	Comments
Sroup	Item - Type om #100E (Science Classroom)	Location	Quantity	UOM	Rank	Replacement	Comments
iassiuc	Casework	1st Floor	2	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	155	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	379	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Steel Doors incl fiw Doors - Store Front	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	534	SF	7	10+ years	
						6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	7	•	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	97	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	437	SF	7	10+ years	

Campus Name: Black Page : 19 of 39 Assessment Date: 01/08/2024



Category : Classroom			В	uilding	: Addition	on-Building B	oror o Luciia Avenoe, Oriidago, ie ooc
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #100W (Science Lab Level 1)						
	Casework	1st Floor	44	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	650	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years	
	Doors - Store Front	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	650	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	773	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
			_				
atego	ry : Interior		В	uilding	: Addition	on-Building B	
	Na Tana	Laadian	0		Danie	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Exposed	East	48	SF	7	10+ years	
	Doors - Steel Doors incl hw	East	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	East	1	EA	7	6-10 years	
	Floor - Tile/Sheet	East	48	SF	5	10+ years	
	Lighting - Chandelier, Incandescent	East	1	EA	7	6-10 years	
	Walls - Concrete Block	East	110	SF	7	10+ years	
	Walls - Plaster/Drywall	East	70	SF	7	10+ years	
	Ceiling - Lay-in	North	480	SF	7	10+ years	
	Doors - Store Front	North	2	EA	7	10+ years	
	Floor - Tile/Sheet	North	480	SF	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years	
	Walls - Concrete Block	North	1,360	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	42	SF	7	10+ years	
	Ceiling - Lay-in	West	310	SF	7	10+ years	
	Doors - Store Front	West	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	West	1	EA	7	6-10 years	
	Floor - Tile/Sheet	West	310	SF	7	10+ years	
	Lighting - Pendent/Surface	West	5	EA	7	6-10 years	
						4.0	
	Walls - Concrete Block	West	680	SF	7	10+ years	
Safety		West	680	SF	7	10+ years	





Category : Exterior **Building: Branch**

						Recommend	
лр	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ance							
	Entrance Control - Audio and Video	#1-Main-SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#1-Main-SW	2	EA	6	10+ years	
	Exterior Doors - Side lite	#1-Main-SW	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#1-Main-SW	48	LF	6	10+ years	
	Exterior Stairs - Concrete	#1-Main-SW	8	LF	6	6-10 years	Repaired
	Stair Handrail - Steel_Stair Handrail	#1-Main-SW	50	LF	6	10+ years	•
	Exterior Doors - Exterior FRP Door	#2-W	4	EA	6	10+ years	
	Exterior Doors - Side lite	#2-W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2-W	2	EA	6	10+ years	
	Exterior Stairs - Stone	#2-W	115	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2-W	15	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3-NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3-NW	3	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4-N	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#4-N	6	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5-N	4	ΕA	5	1-2 years	Missing hardware
	Exterior Doors - Transom Lite	#5-N	3	ΕA	6	10+ years	
	Exterior Stairs - Concrete	#5-N	12	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#6-N	4	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	#6-N	3	ΕA	6	10+ years	
	Exterior Stairs - Concrete	#6-N	12	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#7-N	2	ĒΑ	6	6-10 years	
	Exterior Stairs - Concrete	#7-N	8	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#8-Boiler Room-NE, also currently named/numbered seven	4	EA	4	1-2 years	Delaminated wood door
	Exterior Stairs - Concrete	#8-Boiler Room-NE, also currently named/numbered seven	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#9- Electrical Room-NE. also currently named/numbered seven	2	EA	4	1-2 years	Delaminated wood door
	Exterior Stairs - Concrete	#9- Electrical Room-NE. also currently named/numbered seven	6	LF	6	10+ years	
	Entrance Control - Audio and Video	1.5	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	1.5	2	EA	5	10+ years	New
	Power Door Operator and Controls	1.5	1	ΕA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1.5	110	LF	7	10+ years	
	Ramps - Concrete	1.5	53	LF	7	10+ years	
ndation	n						
	Foundation - Concrete	Entire Building	780	LF	7	10+ years	
	Foundation - Concrete	Entire Building	1	LF	5	1-2 years	Spalled, cracked concrete
	Superstructure - Concrete	Entire Building	34,319	SF	7	10+ years	,
	Superstructure - Concrete	Entire Building	10	SF	5	1-2 years	Cracked brick

Campus Name: Black Page : 21 of 39 Assessment Date: 01/08/2024



Catego	ry : Exterior	В	uilding	: Branc	h		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
1: 1::							
_Lighting	Exterior Lighting - Lighting	Entire Building	1	EA	5	1-2 years	Broken lamp and fixture
	Exterior Lighting - Lighting Exterior Lighting - Parapet or Roof Mounted	Entire Building	1 6	EA EA	5 6	10+ years	Broken lamp and lixture
	Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	O	10+ years	
Roof Svs	stem						
	Access Ladder - Metal	Auditorium	1	EA	7	10+ years	
	Coping - Metal	Auditorium	18	LF	6	10+ years	
	Coping - Stone	Auditorium	286	LF	6	10+ years	
	Downspouts - Interior Downspouts	Auditorium	72	LF	6	10+ years	
	Parapet - 16" - 30" Height	Auditorium	286	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Auditorium	18	LF	6	10+ years	
	Roof - Modified Bitumen	Auditorium	4,930	SF	7	10+ years	
	Roof Hatch - Metal	Auditorium	2	ĒΑ	3	1-2 years	Blocked access
	Roof Structure - Concrete	Auditorium	4,930	SF	7	10+ years	
	Access Ladder - Metal	Gym	1	ĒΑ	7	10+ years	
	Coping - Stone	Gym	310	LF	6	10+ years	
	Downspouts - Interior Downspouts	Gym	40	LF	6	10+ years	
	Parapet - 16" - 30" Height	Gym	310	LF	6	10+ years	
	Roof - Modified Bitumen	Gym	5,550	SF	7	10+ years	
	Roof Structure - Concrete	Gym	5,550	SF	7	10+ years	
	Access Ladder - Metal	Low South	1	ĒΑ	7	10+ years	
	Coping - Stone	Low South	280	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low South	16	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low South	280	LF	6	10+ years	
	Roof - Modified Bitumen	Low South	3,458	SF	7	10+ years	
	Roof Hatch - Metal	Low South	, 1	EA	7	10+ years	
	Roof Structure - Concrete	Low South	3,458	SF	7	10+ years	
	Access Ladder - Metal	Main		EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Main	34	LF	6	10+ years	
	Liner					·	
	Coping - Metal	Main	825	LF	6	10+ years	
	Coping - Stone	Main	825	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main	52	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main	825	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main	825	LF	6	10+ years	
	Roof - Modified Bitumen	Main	7,050	SF	7	10+ years	
	Roof Hatch - Metal	Main	1	ĒΑ	7	10+ years	
	Roof Structure - Concrete	Main	7,050	SF	7	10+ years	
_Walls	2						
	Canopy - Concrete/ Stucco	Entire Building	432	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Brancl	h	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cheek-Wall - Stone	Entire Building	720	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	12,690	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	145	SF	4	0-1 year	Deteriorated mortar with open joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,566	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	125	SF	6	10+ years	
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	1,080	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	108	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	52	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,608	SF	6	10+ years	
	Lintels - Steel	Entire Building	492	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	180	SF	6	10+ years	
	pane	· ·				•	
	Windows - Sash Aluminum Double-pane	Entire Building	2,562	SF	6	10+ years	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
Ū	Automatic Transfer Switch	Boiler Room	3	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,600	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,069	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	4,175	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	19	EA	4	2-5 years	Over 20 years old with incandescent bulbs
	Exit Signs - Multipurpose Room	Entire Building	7	EA	4	2-5 years	Over 20 years old with incandescent bulbs
	Security System - Intrusion Detection	Entire Building	34,329	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3,656	EA	7	10+ years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4,175	EA	6	6-10 years	
	Emergency Generator- Outdoor- Natural Gas - 60 - 100 KW	Site South	1	EA	6	6-10 years	
_Main Se	rvice						
	Main Electrical Service - 1200 A	Boiler Room	1	EA	6	10+ years	

Campus Name: Black Page : 23 of 39 Assessment Date: 01/08/2024



12001-20000 cfm Air Intake

Robert A Black Magnet Elementary School 9101 S Euclid AVENUE, Chicago, IL 60617

	ory : Electrical		D	uildina	: Branci		9101 S Euclid AVENUE, Chicago, IL 60617
Jaiego	ny . Electrical		В	unung	. Dianci	n Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH Independent Electrical Service for emergency power	Boiler Room	1	EA	4	0-1 year	Meter missing
	PA System	Entire Building	34,329	SF	6	6-10 years	
ower D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EΑ	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp	Little Ballaling	ı	LA	U	10+ years	
Catego	ry : Fire Protection		В	uilding	: Brancl	h	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alaı							
	Fire ALarm Anunciator	Entire Building	1	EA	3	0-1 year	Needs replacement to work with nevelevator
	Fire Alarm Panel	Entire Building	1	EΑ	3	1-2 years	Obsolete parts
	Fire Alarm Strobe Lights	Entire Building	34,329	SF	6	2-5 years	•
	Fire Alarm_System	Entire Building	34,329	SF	6	2-5 years	
Catego	ry : Mechanical		В	uilding	: Brancl	h	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Cond	ditioning						
	Chiller-Air Cooled- Recipricating-Ground Mounted - 101 - 200 tons	Basement	1	EA	2	0-1 year	Abandoned
	Pipes - Chilled Water Pipe- Galvanized	Basement	100	LF	4	0-1 year	Not in use, old galvanized and insulation
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	6-10 years	Serves two classrooms in basemen
	Condensing Unit- Ground Mounted - Less than 5 tons	Site West	1	EA	6	6-10 years	Serves elevator room.
Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils	Basement	1	EA	5	2-5 years	Serves auditorium, kitchen, multipurpose room, and corridors.

Campus Name: Black Page : 24 of 39 Assessment Date: 01/08/2024

Basement

1 EA

1-2 years

Rusting



Catego	ry : Mechanical		В	uildina	: Branc		5101 6 Eddid AVENGE, Gilleage, 12 00017
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fan Coil Unit- Celing Mounted - Dual Temperature Coil	Entire Building	1	EA	7	10+ years	Serves elevator room.
	Fan Coil Unit- Celing Mounted - Dual Temperature Coil	Entire Building	1	EA	5	2-5 years	Dated unit, issues. Serves kitchen.
	Fan Coil Unit- Celing Mounted - Dual Temperature Coil	Entire Building	1	EA	5	2-5 years	Dated unit, issues. Serves kitchen.
	Fan Coil Unit- Celing Mounted - Hot Water- Heating	Entire Building	1	EA	4	1-2 years	Dated unit, issues. Serves kitchen.
_Boiler Sv	vstems						
,	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	3	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	3	EA	5	6-10 years	
	Non Condensing. Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	2-5 years	Boiler 1 is rusting heavily near burner
	Water Fill System	Boiler Room	1	EA	5	6-10 years	
Heating	Devices						
	Wall Heater - Electric	Auditorium	1	EA	6	10+ years	
	Wall Heater - Electric	Auditorium	1	EA	4	0-1 year	Dated and nonfunctional.
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	5	2-5 years	
	Fin Tube - Hot Water	Entire Building	550	LF	5	2-5 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	Insulation deteriorated
_Tempera	ature Control						
	Electric Thermostat	Basement	3	EA	6	10+ years	
_Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Installed recently
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	10+ years	Installed recently

Campus Name: Black Page : 25 of 39 Assessment Date: 01/08/2024



ategor	y : Mechanical		В	uilding	: Brancl	h	
		I a setta a	0		.	Recommend	•
Froup	Item - Type CFM	Location	Quantity	UOM	Rank	Replacement	Comments
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No suppression system
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EΑ	4	0-1 year	Not in use, blocked off
		g				·	
Categor	y : Plumbing		В	uilding	: Brancl		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lot Wate			•				
	Electric Heater - Less than 20 KW	Auditorium	1	EA	5	2-5 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
, ,	Domestic Piping-Hot Water Return Lines	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old, inne
							rusting causing hot water to have lower flow
	Domestic Piping-Hot Water Return Risers	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old, inne
		-				·	rusting causing hot water to have lower flow
	Domestic Piping-Hot Water from Risers to	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old, inne
	Fixtures						rusting causing hot water to have
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,329	SF	4	2-5 years	lower flow Galvanized and 40+ years old, inne
	(Horizontal Lines)	Ziilii o Dallallig	01,020	O.	•	2 0 700.0	rusting causing hot water to have lower flow
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old, inne
	(Risers)	G	,			•	rusting causing hot water to have
							lower flow
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old, inne
	(from Risers to Fixtures)						rusting causing hot water to have lower flow
	Sanitary Piping	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old
	Storm Piping	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old
	Vent Piping	Entire Building	34,329	SF	4	2-5 years	Galvanized and 40+ years old
umps							
	Pumps - Sump-Duplex	Boiler Room	1	EA	4	2-5 years	Dated pumps and motors, exposed electrical wiring
ategor	y : Room		В	uilding	: Brancl		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ative Suites/Offices				- COIII	. topiasomont	23
. WILLIEU	Ceiling - Plaster/Drywall	0.5 Floor	388	SF	7	10+ years	
						-	
	ame: Black		Page : 26 of 39				Assessment Date: 01/08/2



Catego	ry : Room		Building : Branch						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	0.5 Floor	1	EA	7	10+ years			
	Floor - Tile	0.5 Floor	388	SF	7	6-10 years			
	Lighting - Pendent/Surface	0.5 Floor	6	EA	7	6-10 years			
	Power Distribution	0.5 Floor	6	EA	7	10+ years			
	Storage/ Closet	0.5 Floor	20	SF	7	10+ years			
	Walls - Plaster/Drywall	0.5 Floor	480	SF	7	10+ years			
	Ceiling - Plaster/Drywall	0.5 Floor - Engineer Office	145	SF	7	10+ years			
	Ceiling - Plaster/Drywall	0.5 Floor - Engineer Office	15	SF	3	0-1 year	Broken gypsum		
	Doors - Wood Doors inclu hw	0.5 Floor - Engineer Office	1	EA	7	10+ years			
	Floor - Tile	0.5 Floor - Engineer Office	160	SF	7	6-10 years			
	Lighting - Pendent/Surface	0.5 Floor - Engineer Office	2	EA	7	6-10 years			
	Power Distribution	0.5 Floor - Engineer Office	4	EA	7	10+ years			
	Storage/ Closet	0.5 Floor - Engineer Office	200	SF	7	10+ years			
	Walls - Concrete Block	0.5 Floor - Engineer Office	540	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st floor - Guidance office	200	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor - Guidance office	1	EA	7	10+ years			
	Floor - Tile	1st floor - Guidance office	200	SF	7	10+ years			
	Lighting - Pendent/Surface	1st floor - Guidance office	12	EA	7	6-10 years			
	Power Distribution	1st floor - Guidance office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	1st floor - Guidance office	360	SF	7	10+ years			
	AC Unit	1st floor -Main Office	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st floor -Main Office	270	SF	7	10+ years			
	Doors - Store Front	1st floor -Main Office	2	EA	7	10+ years			
	Floor - Tile	1st floor -Main Office	270	SF	7	10+ years			
	Lighting - Pendent/Surface	1st floor -Main Office	4	EA	7	6-10 years			
	Power Distribution	1st floor -Main Office	10	EA	7	10+ years			
	Storage/ Closet	1st floor -Main Office	70	SF	7	10+ years			
	Walls - Plaster/Drywall	1st floor -Main Office	650	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd floor Teacher's	350	SF	7	10+ years			
		Lounge/Unlabled							
	Ceiling - Plaster/Drywall	2nd floor Teacher's	10	SF	5	1-2 years	Damage around vent		
		Lounge/Unlabled							
	Doors - Wood Doors inclu hw	2nd floor Teacher's	1	EA	7	10+ years			
		Lounge/Unlabled							
	Floor - Tile	2nd floor Teacher's	300	SF	7	10+ years			
		Lounge/Unlabled							
	Floor - Tile	2nd floor Teacher's	60	SF	4	1-2 years	Damaged from previous construction		
		Lounge/Unlabled							
	Lighting - Pendent/Surface	2nd floor Teacher's	3	EA	7	6-10 years			
		Lounge/Unlabled							
	Power Distribution	2nd floor Teacher's	14	EA	7	10+ years			
		Lounge/Unlabled							
	Storage/ Closet	2nd floor Teacher's	6	SF	7	10+ years			
		Lounge/Unlabled							

Campus Name: Black Page : 27 of 39 Assessment Date: 01/08/2024



Catego	ry : Room		В	uilding	: Branc	h	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd floor Teacher's Lounge/Unlabled	490	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd floor Teacher's Lounge/Unlabled	10	SF	5	1-2 years	Water damage
	Walls - Plaster/Drywall	2nd floor Teacher's Lounge/Unlabled	67	SF	5	1-2 years	Damage from previous construction
	Ceiling - Plaster/Drywall	Kitchen	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen	5	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Kitchen	2	EA	7	10+ years	Trator damage
	Floor - Tile/Sheet	Kitchen	85	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen	1	EA	7	6-10 years	
	Power Distribution	Kitchen	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen	250	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen	10	SF	5	1-2 years	Domogod
			_	SF SF		,	Damaged.
	Ceiling - Plaster/Drywall	Principal's Office (Connected to Main Office)	126		7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office (Connected to Main Office)	1	EA	7	10+ years	
	Floor - Tile	Principal's Office (Connected to Main Office)	126	SF	7	6-10 years	
	Lighting - Pendent/Surface	Principal's Office (Connected to Main Office)	2	EA	7	6-10 years	
	Power Distribution	Principal's Office (Connected to Main Office)	4	EA	7	6-10 years	
	Storage/ Closet	Principal's Office (Connected to Main Office)	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office (Connected to Main Office)	460	SF	7	10+ years	
_Auditoriu	ım & Theater						
	Ceiling - Plaster/Drywall	0.5 Floor	3,600	SF	7	10+ years	
	Doors - Steel Doors incl hw	0.5 Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	4	EA	7	10+ years	
	Floor - Carpet	0.5 Floor	1,790	SF	6	2-5 years	
	Floor - Carpet	0.5 Floor	10	SF	4	0-1 year	Torn carpet
	Floor - Tile/Sheet	0.5 Floor	1,800	SF	7	10+ years	
	Lighting - Lay-in	0.5 Floor	55	ĒΑ	7	6-10 years	
	Main Floor Seating	0.5 Floor	380	EΑ	7	10+ years	
	Sound System	0.5 Floor	1	EΑ	7	6-10 years	
	Stage	0.5 Floor	600	SF	6	10+ years	
	Stage-Stairs - Tile	0.5 Floor	26	LF	4	0-1 year	Carpet torn.
	Stairs - Tile	0.5 Floor	64	LF	6	10+ years	carpet.
	Storage/ Closet	0.5 Floor	315	SF	7	10+ years	carpet.
	Storage/ Closet	0.5 Floor	315	SF	7	10+ years 10+ years	

Campus Name: Black Page : 28 of 39 Assessment Date: 01/08/2024



	Category : Room		В	uilding	: Branc	h		
Walls - Masonry 0.5 Floor 4.300 SF 7 10+ years 10.5 Floor 18.30 SF 7 10+ years 10.5 Floor 18.30 SF 7 10+ years 10+ y								
Walls - Masonry 0.5 Floor 1.830 SF 7 10+ years	Group			•				Comments
Symmats Symmats								
Ceiling - Splined			0.5 Floor					
Celling - Splined		Walls - Plaster/Drywall	0.5 Floor	580	SF	7	10+ years	
Celling - Splined	Gvmnas	ia						
Doors - Steel Doors inch hw 0.5 Floor 9 EA 7 10+ years	,		0.5 Floor	4,175	SF	7	10+ years	
Floor - Tile							•	
Lighting - Pendent/Surface 0.5 Floor 930 EA 7 6-10 years			0.5 Floor					
Stage								
Stage Curtain								
Stage Lighting System					_			
Stage-Stairs - Wood 0.5 Floor 3.4				1				
Walfs - Masonry 0.5 Floor 4,883 SF 7 10+ years							•	
Walls - Plaster/Drywall 0.5 Floor 580 SF 7 10+ years							,	
Ceiling - Plaster/Drywall 0.5 Floor 565 SF 7 10+ years Ceiling - Plaster/Drywall 0.5 Floor 10 SF 5 1-2 years Water damage Doors - Steel Doors inclu hw 0.5 Floor 1 EA 7 10+ years Floor - Tile/Sheet 0.5 Floor 565 SF 7 10+ years Floor - Tile/Sheet 0.5 Floor 565 SF 7 10+ years Floor - Tile/Sheet 0.5 Floor 565 SF 7 10+ years Floor - Tile/Sheet 0.5 Floor 565 SF 7 10+ years Water damage from standing water around floor drain, chipping tile Lighting - Pendent/Surface 0.5 Floor 8 EA 7 6-10 years Storage/ Closet 0.5 Floor 130 SF 5 6-10 years Storage/ Closet 0.5 Floor 715 SF 7 10+ years Walls - Plaster/Drywall 0.5 Floor 715 SF 7 10+ years Walls - Plaster/Drywall 0.5 Floor 715 SF 5 1-2 years Strong odor coming from wall Walls - Plaster/Drywall 0.5 Floor 20 SF 5 1-2 years Water damage Walls - Plaster/Drywall 0.5 Floor 20 SF 7 10+ years Strong odor coming from wall Walls - Plaster/Drywall 0.5 Floor 20 SF 7 10+ years Strong odor coming from wall Walls - Plaster/Drywall 0.5 Floor 20 SF 7 10+ years Strong odor coming from wall Service Rooms Sasement 666 SF 5 10+ years Strong odor coming from wall Service Rooms Sasement 666 SF 5 10+ years Strong odor coming from wall Service Rooms Sasement 666 SF 5 10+ years Strong odor coming from wall Service Rooms Sasement 265 SF 7 10+ years Storage Room Sasement 265 SF 7 10+ years Storage Room							,	
Ceiling - Plaster/Drywall		walls - Plaster/Drywall	0.5 F100r	580	5F	/	10+ years	
Ceiling - Plaster/Drywall	Kitchen							
Doors - Steel Doors incl hw Dos Floor 1		Ceiling - Plaster/Drywall			SF	7		
Doors - Wood Doors inclu hw D.5 Floor 2 EA 7 10+ years Floor - Tile/Sheet D.5 Floor S65 SF 7 10+ years Floor - Tile/Sheet D.5 Floor S65 SF 7 10+ years Floor - Tile/Sheet D.5 Floor S7 4 10+ years Water damage from standing water around floor drain, chipping tile			0.5 Floor	10	SF	5	1-2 years	Water damage
Floor - Tile/Sheet 0.5 Floor 565 SF 7 10+ years Floor - Tile/Sheet 0.5 Floor 10 SF 4 1-2 years Water damage from standing water around floor drain, chipping tile		Doors - Steel Doors incl hw	0.5 Floor	1	EA	7	10+ years	
Floor - Tile/Sheet		Doors - Wood Doors inclu hw	0.5 Floor	2	EA	7	10+ years	
Floor - Tile/Sheet		Floor - Tile/Sheet	0.5 Floor	565	SF	7	10+ years	
Lighting - Pendent/Surface 0.5 Floor 8 EA 7 6-10 years Storage/ Closet 0.5 Floor 130 SF 5 6-10 years Cracked tile		Floor - Tile/Sheet	0.5 Floor		SF	4		
Storage Closet 0.5 Floor 130 SF 5 6-10 years Cracked tile		Lighting - Pendent/Surface	0.5 Floor	8	FA	7	6-10 years	areana neer aram, empping me
Walls - Plaster/Drywall 0.5 Floor 715 SF 7 10+ years Strong odor coming from wall Walls - Plaster/Drywall 0.5 Floor 15 SF 5 1-2 years Strong odor coming from wall Walls - Plaster/Drywall 0.5 Floor 20 SF 5 1-2 years Water damage MDF_IDF Doors - Wood Doors inclu hw Finishes 2nd Floor 1 EA 7 10+ years Finishes 2nd Floor 100 SF 7 10+ years Mechanical/ Service Rooms Janitor's Closet 20 SF 7 10+ years Janitor's Closet 2nd Floor 12 SF 7 10+ years Boiler Room Basement 666 SF 5 10+ years Mechanical/ Service Rooms Basement 143 SF 7 10+ years Mechanical/ Service Rooms Basement 265 SF 7 10+ years Storage Room Basement 206 SF 7 10+ years							•	Cracked tile
Walls - Plaster/Drýwall 0.5 Floor 15 SF 5 1-2 ýears Strong odor coming from wall Walls - Plaster/Drywall MDF_IDF 20 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Finishes 2nd Floor 1 EA 7 10+ years 10+								ordonod tilo
Walls - Plaster/Drywall 0.5 Floor 20 SF 5 1-2 years Water damage MDF_IDF								Strong odor coming from wall
Doors - Wood Doors inclu hw Finishes 2nd Floor 2nd Floor 100 SF 7 10+ years							•	
Doors - Wood Doors inclu hw Finishes 2nd Floor 2nd Floor 100 SF 7 10+ years	MDE ID	E						
Finishes 2nd Floor 100 SF 7 10+ years Mechanical/ Service Rooms Janitor's Closet 1st Floor 20 SF 7 10+ years Janitor's Closet 2nd Floor 12 SF 7 10+ years Boiler Room Basement 666 SF 5 10+ years Mechanical/ Service Rooms Basement 143 SF 7 10+ years Mechanical/ Service Rooms Basement 265 SF 7 10+ years Storage Room Basement 206 SF 7 10+ years	<u> </u>		2nd Floor	1	FA	7	10+ years	
Janitor's Closet1st Floor20SF710+ yearsJanitor's Closet2nd Floor12SF710+ yearsBoiler RoomBasement666SF510+ yearsMechanical/ Service RoomsBasement143SF710+ yearsMechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years								
Janitor's Closet1st Floor20SF710+ yearsJanitor's Closet2nd Floor12SF710+ yearsBoiler RoomBasement666SF510+ yearsMechanical/ Service RoomsBasement143SF710+ yearsMechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years	Mechani	cal/ Service Rooms						
Janitor's Closet2nd Floor12SF710+ yearsBoiler RoomBasement666SF510+ yearsMechanical/ Service RoomsBasement143SF710+ yearsMechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years	weeman		1st Floor	20	SF	7	10± vears	
Boiler RoomBasement666SF510+ yearsMechanical/ Service RoomsBasement143SF710+ yearsMechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years								
Mechanical/ Service RoomsBasement143SF710+ yearsMechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years								
Mechanical/ Service RoomsBasement265SF710+ yearsStorage RoomBasement206SF710+ years								
Storage Room Basement 206 SF 7 10+ years								
Restroom		Storage Room	Basement	206	SF	1	10+ years	
	Restroor	n						

Campus Name: Black Page : 29 of 39 Assessment Date: 01/08/2024



Group	Item - Type Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile	Location 0.5 Floor (inside Office) 0.5 Floor (inside Office)	Quantity 21	UOM	Rank	Recommend Replacement	Comments
Group	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	0.5 Floor (inside Office)			Rank	Replacement	Comments
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw		21				Comments
	Doors - Wood Doors inclu hw	0.5 Floor (inside Office)		SF	7	6-10 years	
		(/	21	SF	7	10+ years	
	Floor - Tile	0.5 Floor (inside Office)	1	EA	7	10+ years	
		0.5 Floor (inside Office)	21	SF	7	10+ years	
	Lavatory	0.5 Floor (inside Office)	1	EA	7	10+ years	
	Lighting - Pendent/Surface	0.5 Floor (inside Office)	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	0.5 Floor (inside Office)	50	SF	7	10+ years	
	Water Closet	0.5 Floor (inside Office)	1	EA	7	10+ years	
	Accessories	0.5 Floor	195	SF	7	10+ years	
	Ceiling - Plaster/Drywall	0.5 Floor	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0.5 Floor	195	SF	7	10+ years	
	Floor Drain	0.5 Floor	1	ĒΑ	7	10+ years	
	Lavatory	0.5 Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	0.5 Floor	4	EΑ	7	6-10 years	
	Partitions	0.5 Floor	2	EΑ	7	10+ years	
	Urinals	0.5 Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	0.5 Floor	315	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	0.5 Floor	315	SF	7	10+ years	
	Water Closet	0.5 Floor	2	EA	7	10+ years	
	Accessories	0.5 Floor	240	SF	7	-	
				SF	7	6-10 years	
	Ceiling - Plaster/Drywall	0.5 Floor	240			10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0.5 Floor	120	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	0.5 Floor	120	SF	7	10+ years	
	Floor Drain	0.5 Floor	1	EA	7	10+ years	
	Lavatory	0.5 Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	0.5 Floor	4	EA	7	6-10 years	
	Partitions	0.5 Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	0.5 Floor	395	SF	7	10+ years	
	Walls - Structural Glazed Tile	0.5 Floor	395	SF	7	10+ years	
	Water Closet	0.5 Floor	4	EA	7	10+ years	
	Accessories	0.5 Floor Behind stage in storage area	21	SF	7	10+ years	
	Ceiling - Plaster/Drywall	0.5 Floor Behind stage in storage area	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	0.5 Floor Behind stage in storage	1	EA	7	10+ years	
	Floor - Tile	area 0.5 Floor Behind stage in storage	21	SF	7	6-10 years	
	Lavatory	area 0.5 Floor Behind stage in storage	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	area 0.5 Floor Behind stage in storage area	1	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Branc	<u></u> h	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	0.5 Floor Behind stage in storage	60	SF	7	10+ years	
	N/ / Ol /	area		^	•	0.40	
	Water Closet	 Floor Behind stage in storage area 	1	EA	6	6-10 years	
	Accessories	2nd Floor	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	152	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	152	SF	7	10+ years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	162	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	270	SF	7	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	2nd Floor	270	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	260	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	270	SF	7	10+ years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	5	6-10 years	
	Urinals	2nd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	320	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	320	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	75	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Damage around missing vent cover
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	80	SF	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Showers	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	238	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	In Class 104	60	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	In Class 104	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Class 104	1	EA	7	6-10 years	
	Floor - Tile	In Class 104	60	SF	7	10+ years	
	Lighting - Pendent/Surface	In Class 104	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In Class 104	170	SF	7	6-10 years	
	Water Closet	In Class 104	1	EA	7	6-10 years	



Category : Classroom			Building : Branch					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #001/001.2 (Computer Lab)							
	Casework	Basement	31	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Basement	1,775	SF	7	10+ years		
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	6-10 years		
	Floor - Tile	Basement	1,775	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	44	EA	7	6-10 years		
	Marker Board	Basement	4	LF	7	6-10 years		
	Storage/ Closet	Basement	300	SF	7	10+ years		
	Walls - Concrete Block	Basement	2,110	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement	1,500	SF	7	10+ years		
	Wireless System	Basement	1	EA	7	6-10 years		
Classroo	m #100 (Regular Classroom)							
	AC Units	1st Floor	1	EA	5	6-10 years		
	Casework	1st Floor	19	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	690	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	690	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	7	EA	5	1-2 years	Missing covers	
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	57	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,060	SF	7	10+ years		
Classroo	m #101 (Regular Classroom)							
2.000.00	AC Units	1st Floor	2	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	950	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor	950	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	36	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	1,220	SF	7	10+ years		
01	#400 (Or:- Dr.							
Classroo	m #103 (Special Program)	4 . 🗔				0.40		
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	470	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	470	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	860	SF	7	10+ years		



	ry : Classroom		Building : Branch					
Outogo	i y i Giacorcom		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	om #104 (Regular Classroom)		•			•		
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	30	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	950	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor	950	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	1,120	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	om #200 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	930	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,200	SF	7	10+ years		
Classroo	om #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	930	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,260	SF	7	10+ years		
Classroo	om #204 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	930	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	1,128	SF	7	10+ years		
Classroo	om #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	902	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	902	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		

Campus Name: Black Page : 33 of 39 Assessment Date: 01/08/2024



Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	2,520	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	460	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	460	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	610	SF	7	10+ years	
						•	

Category: Interior Building: Branch

Jai c yu	ry . Iliterioi		D	ununng	. Dianc	11	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ridor							
	Ceiling - Plaster/Drywall	0.5 Floor	475	SF	7	10+ years	
	Doors - Steel Doors incl hw	0.5 Floor	4	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	0.5 Floor	4	EA	7	10+ years	
	Drinking Fountains - Double Fountain	0.5 Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	0.5 Floor	475	SF	7	10+ years	
	Lighting - Lay-in	0.5 Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	0.5 Floor	13	EΑ	7	6-10 years	
	Stairs - Concrete Stairs	0.5 Floor	14	LF	7	10+ years	
	Walls - Masonry	0.5 Floor	280	SF	7	10+ years	
	Walls - Plaster/Drywall	0.5 Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	0.5 Floor	360	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,190	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,190	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	52	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	3,186	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,190	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,190	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	52	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	3,186	SF	7	10+ years	
	Ceiling - Exposed	Basement	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	12	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years	
	Floor - Tile/Sheet	Basement	389	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	3	SF	7	10+ years	

Campus Name: Black Page : 34 of 39 Assessment Date: 01/08/2024



Catego	ry : Interior		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	Basement	12	EA	7	6-10 years	
	Walls - Concrete Block	Basement	855	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	East	312	SF	7	10+ years	
	Floor - Tile/Sheet	East	20	SF	7	10+ years	
	Floor - Tile/Sheet	East	195	SF	7	10+ years	
	Handrails	East	63	LF	7	10+ years	
	Lighting - Pendent/Surface	East	3	EA	7	6-10 years	
	Stairs - Rubber	East	26	LF	7	10+ years	
	Walls - Concrete Block	East	560	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	312	SF	7	10+ years	
	Floor - Concrete	West	194	SF	7	10+ years	
	Handrails	West	63	LF	7	10+ years	
	Lighting - Pendent/Surface	West	1	EA	7	6-10 years	
	Stairs - Concrete	West	26	LF	7	10+ years	
	Walls - Masonry	West	872	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	5	1-2 years	Not in use, installation not complete
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	5	1-2 years	Disassembled control board, installation not complete





Category : Site **Building: Site**

	ry . Site			unanig		Recommend	
	Itam Tuna	Location	Quantity	UOM	Donk	Replacement	Comments
oup	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
letic	1.1.						
	Lighting	Main Campus South	1	EA	7	10+ years	
	Surface - Asphalt	Main Campus South	3,520	SF	7	10+ years	
il/Drai	inage						
	Civil/ Drainage - Catch Basin	Branch - Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Branch - Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Branch - Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Main - Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Main - Entire Site	2	EA	6	10+ years	
ncina							
<u>-</u>	Fencing - Chain Link	Branch - Entire Site	410	LF	6	2-5 years	
	Fencing - New Standard Ornamental	Branch - Entire Site	300	LF	6	10+ years	
	Fencing - Chain Link	Main - Entire Site	132	LF	7	10+ years	
	Fencing - New Standard Ornamental	Main - Entire Site	469	LF	6	10+ years	
ıdscaı	ne						
	Landscape - Grass	Branch - Entire Site	15,605	SF	6	6-10 years	
	Landscape - Grass	Branch - Entire Site	1,000	SF	5	1-2 years	Bare soil
	Parkway trees	Branch - Entire Site	14	ĒΑ	6	10+ years	
	Planting Beds/ Area	Branch - Entire Site	900	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Branch - Entire Site	2,290	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Branch - Entire Site	90	SF	4	0-1 year	Cracked, broken
	Retaining Wall - Concrete	Branch - Entire Site	125	SF	6	10+ years	Oracica, proterr
	Trash Receptacles	Branch - Entire Site	5	EA	6	10+ years	
			2	EA	7		
	Benches	Main - Entire Site				10+ years	New
	Landscape - Grass	Main - Entire Site	1,676	SF	7	10+ years	New
	Landscape - Grass	Main - Entire Site	15,900	SF	6	10+ years	4500 sf area demolished at sout parking
	Landscape - Hardscape- Pavers	Main - Entire Site	176	SF	7	10+ years	New
	Landscape - Mulch	Main - Entire Site	3,662	SF	7	10+ years	New
	Parkway trees	Main - Entire Site	17	ĒΑ	6	10+ years	-
	Parkway trees	Main - Entire Site	3	EΑ	4	0-1 year	Missing trees
	Planting Beds/ Area	Main - Entire Site	2,000	SF	6	10+ years	5
	Play Area - Hardscape- Asphalt	Main - Entire Site	1,750	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Main - Entire Site	12,115	SF	6	10+ years	Original, not demolished
	Play Area - Haruscape- Aspirali Play Area - Synthetic Turf	Main - Entire Site	4,158	SF	7		Original, flot defilolished
					-	10+ years	
	Retaining Wall - Concrete	Main - Entire Site	147	SF	6	10+ years	Dusting displaced actain:
	Retaining Wall - Concrete	Main - Entire Site	75	SF	4	1-2 years	Broken, displaced retaining wall
	Retaining Wall - Masonry	Main - Entire Site	100	SF	6	10+ years	0 1 1 1
	Retaining Wall - Masonry	Main - Entire Site	6	SF	5	1-2 years	Cracked , broken masonry

Campus Name: Black Page : 36 of 39 Assessment Date: 01/08/2024



Catego	ry : Site		В	uilding	: Site		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Trash Receptacles	Main - Entire Site	2	EA	6	10+ years	
arking							
	Concrete Curbs	Branch - S Site	518	LF	6	10+ years	
	Surface - Asphalt	Branch - S Site	24,980	SF	6	10+ years	
	Trash Enclosure - Chain Links	Branch - S Site	50	SF	6	10+ years	
	Concrete Curbs	Main - NE Lot	525	LF	6	10+ years	
	Interior Plantings	Main - NE Lot	225	LF	6	10+ years	
	Pavers	Main - NE Lot	150	SF	6	10+ years	
	Surface - Asphalt	Main - NE Lot	3,000	SF	7	10+ years	
	Surface - Asphalt	Main - NE Lot	29,800	SF	6	10+ years	Some area given to new trash
			-,			, , , , ,	enclosure
	Surface - Asphalt	Main - NE Lot	4,900	SF	4	1-2 years	Potholes, large cracks, alligatored
	Curiado Moprian	Maii NE Lot	1,000	O.	•	. L youro	surface
	Trash Enclosure - Chain Links	Main - NE Lot	552	SF	6	10+ years	diraco
	Trash Enclosure - Chain Links	Main - NE Lot	48	SF	5	1-2 years	Damaged hardware
	Vehicular Screening	Main - NE Lot	510	LF	6	10+ years	Damagea naraware
	verticular octeering	Walli - NE LOT	310	Li	O	10+ years	
aygrou							
	Equipment - Combo 3-12	Branch - S Site	1	EA	7	10+ years	
	Surface - Square Rubber Mats	Branch - S Site	2,090	SF	7	10+ years	
	Equipment - School Age 5-12	Northeast- Main Campus	1	EA	7	10+ years	
	Equipment - Swingset	Northeast- Main Campus	1	EA	7	10+ years	
	Surface - Poured Surface	Northeast- Main Campus	750	SF	7	10+ years	
	Surface - Poured Surface	Northeast- Main Campus	1,850	SF	7	10+ years	
idewall	KS.						
	Sidewalks - Internal Walks	Branch - Entire Site	96	LF	7	10+ years	New or repaired
	Sidewalks - Internal Walks	Branch - Entire Site	24	LF	4	1-2 years	Broken sidewalk
	Sidewalks - Perimeter Sidewalks	Branch - Entire Site	9,150	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Branch - Entire Site	125	SF	6	6-10 years	Minor sidewalk crack
	Sidewalks - Internal Walks	Main - Entire Site	207	LF	7	10+ years	New
	Sidewalks - Internal Walks	Main - Entire Site	120	LF	6	10+ years	
	Sidewalks - Internal Walks	Main - Entire Site	35	LF	4	0-1 year	Cracked.
	Sidewalks - Perimeter Sidewalks	Main - Entire Site	13,440	SF	7	10+ years	New or repaired.
	Sidewalks - Perimeter Sidewalks	Main - Entire Site	2,800	SF	6	10+ years	New or Repaired.
	Sidewaiks - Felifficiel Sidewaiks	Main - Entire Site	2,800	SI	O	10+ years	New of Repaired.
gnage							
	Flag Pole - Flag Pole	Branch - Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Branch - Entire Site	1	EA	6	10+ years	
	Monument - Sign	Branch - Entire Site	1	EA	6	10+ years	
	Flag Pole - Flag Pole	Main - Entire Site	1	EA	6	10+ years	
	riay rule - riay rule	ivialii - Etitlie Site	1	EA	О	10+ years	

Campus Name: Black Page : 37 of 39 Assessment Date: 01/08/2024



Catego	Category : Site			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marquee - Free Standing Back lighted w/	Main - Entire Site	1	EΑ	6	10+ years	
	LED						
	Monument - Sign	Main - Entire Site	2	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Black Page: 38 of 39 Assessment Date: 01/08/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary		T						1	1
			5	Floor Plan		Glazed	Operable	140	
Current Hears	Intended Heere	Doom Location	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Lo: D	In .	15.	NIA.	4 400	440			T
Art Room	Store Room	Basement	Basement	NA	1,428	116	58	N	Y
Computer Lab	Regular Classroom	1st Floor	114	114	450	63	27	N	Y
Office	Regular Classroom	1st Floor	106	106	450	63	27	N	N
Office	Regular Classroom	1st Floor	107	107	450	63	27	N	Υ
Regular Classroom	Kindergarten	1st Floor	101	101	840	63	27	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	450	63	27	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	450	63	27	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	450	63	27	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	450	63	27	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	450	63	27	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	450	63	27	N	Y
Regular Classroom	Regular Classroom	1st Floor	111	111	450	63	27	N	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	225	63	27	N	Y
Regular Classroom	Regular Classroom	1st Floor	113	113	450	63	27	N	Y
Building : Branch									
Computer Lab	Computer Lab	Basement	001/001.2	NA	1,775	171	171	N	Υ
Regular Classroom	Music Room	2nd Floor	208	208	460	66	10	Y	Y
Regular Classroom	Regular Classroom	1st Floor	100	100	690	96	14	Y	Y
Regular Classroom	Regular Classroom	1st Floor	101	101	950	132	20	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	103	950	132	20	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	201/200	930	132	20	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	203/ 202	930	132	20	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204/205	930	132	20	Ÿ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206/207	902	264	40	Ÿ	Υ
Special Program	Regular Classroom	1st Floor	103	102	470	66	10	N	Y
	1 0 0 0 0 0 0 0	1					-	1	
Building : Addition-Building									
Science Classroom	Science Classroom	1st Floor	100E	NA	534	56	145	N	Υ
Science Lab Level 1	Science Lab Level 1	1st Floor	100W	NA	650	112	182	N	Y