

### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1959	2	184,611
Driver Ed Modular	2000	1	800
Campus Total			185,411

Catego	ry : Exterior		В	uilding	: Main		
			•			Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Entire Building	2	EA	7	10+ years	Corrected quantity
	Cell Equipment - Cabinets	Entire Building	1	EA	7	10+ years	
Entrance	1						
	Entrance Control - Audio and Video	#1 E	1	EA	6	2-5 years	
	Exterior Doors - Exterior FRP Door	#1 E	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 E	3	EA	5	6-10 years	Broken seal
	Exterior Stairs - Concrete	#1 E	36	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#1 E	48	LF	6	6-10 years	
	Ramps - Concrete	#1 E	24	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 E	90	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#10 S	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 S	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 S	45	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#10 S	20	LF	6	2-5 years	
	Exterior Doors - Overhead Rolling/ Garage	#10.5 OHD E	1	EA	6	6-10 years	
	Door Exterior Doors - Exterior FRP Door	#11 E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11 E #12 E	2	EA	6		
	Exterior Doors - Exterior FRP Door	#12 E #13 E	Z A	EA	6	10+ years 6-10 years	
	Exterior Doors - Transom Lite	#13 E	4	EA	6	•	Broken seals
	Exterior Stairs - Concrete	#13 E #13 E	20	LF	6	6-10 years	DIORCH SEAIS
	Exterior Stairs - Concrete	#13 E #13 E	20	LF	6	10+ years	
		#13 E	14	LF	0	10+ years	



Catarra				به منام از	Main		3939 W 79th STREET, Chicago, IL 60652
Catego	ry : Exterior		E	Building	: Main		
-			•		<b>_</b> .	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stair Handrail - Steel_Stair Handrail	#13 E	12		6	10+ years	
	Exterior Doors - Exterior FRP Door	#14 E	2		6	6-10 years	
	Exterior Doors - Transom Lite	#14 E	2	EA	6	6-10 years	Broken seals
	Exterior Doors - Exterior Steel Door	#15 E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#15 E	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#15 E	12	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#16 Courtyard	2		6	6-10 years	
	Exterior Doors - Transom Lite	#16 Courtyard	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#17 Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#17 Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#18 Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#18 Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#2 N	4	EA	6	6-10 years	
	Exterior Doors - Store Front	#2 N	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 N	6	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 N	81	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 W	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 W	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3 W	36	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 W	16	LF	6	2-5 years	
	Exterior Doors - Store Front	#4 W	8	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4 W	4	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#5 W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5 W	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5 W	20	LF	6	2-5 years	
	Exterior Doors - Exterior FRP Door	#6 W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 W	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6 W	20	LF	6	2-5 years	
	Exterior Doors - Exterior FRP Door	#7 S	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#7 S	36	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#7 S	54	LF	6	2-5 years	
	Ramps - Concrete	#7 S	23	LF	6	10+ years	
	Ramps - Concrete	#7 S	4	LF	5	0-1 year	Cracked, spalling concrete at rails
	Exterior Doors - Exterior FRP Door	#8 S	4	ĒA	6	6-10 years	
	Exterior Doors - Transom Lite	#8 S	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 S	_ 24	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#8 S	12	LF	6	6-10 years	Repaired
	Exterior Doors - Exterior FRP Door	#9 S	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9 S	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9 S	24	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 S	12	LF	6	6-10 years	
			12	L1	0	5 TO yours	

Foundation



							3939 W 79th STREET, Chicago, IL 60652
Catego	ory : Exterior		В	uilding	: Main		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Foundation - Concrete	Entire Building	2,031	LF	7	10+ years	
	Superstructure - Steel	Entire Building	184,611	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	7	10+ years	Newer LEDs
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	Newer LEDs
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	5	2-5 years	
Roof Sy					0	0.40	
	Coping - Metal	Courtyard Roof North	90	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Courtyard Roof North	40	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Courtyard Roof North	90	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Courtyard Roof North	1,180	SF	5	0-1 year	Bubbling, deteriorating, soft spots.
	Roof Structure - Concrete	Courtyard Roof North	1,180	SF	7	10+ years	
	Coping - Metal	Courtyard Roof South	135	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Courtyard Roof South	40	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Courtyard Roof South	135	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Courtyard Roof South	3,075	SF	5	0-1 year	Bubbling, worn surface, poor drainage
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Courtyard Roof South	3,075	SF	7	10+ years	
	Access Ladder - Metal	High Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	High Roof	50	LF	7	6-10 years	
	Liner	C C				•	
	Coping - Metal	High Roof	898	LF	6	6-10 years	
	Downspouts - Interior Downspouts	High Roof	210	LF	6	6-10 years	
	Parapet - 16" - 30" Height	High Roof	898	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	High Roof	32,277	SF	4	0-1 year	Areas of bubbling, poor drainage
	Roof Structure - Steel / Metal Deck/ Concrete Topping	High Roof	32,277	SF	7	10+ years	
	Access Ladder - Metal	Low Roof - SE	2	EA	7	10+ years	Corrected quantity
	Chimney - Metal Flue	Low Roof - SE	60	LF	6	6-10 years	
	Coping - Metal	Low Roof - SE	500	LF	6	6-10 years	Recalculated all quantities.
	Downspouts - Interior Downspouts	Low Roof - SE	105	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Low Roof - SE	500	LF	6	10+ years	Recalculated all quantities.
	Roof - Asphalt Gravel Ballast	Low Roof - SE	23,910	SF	5	0-1 year	Recalculated all quantities. Bubbling,
	Rooi - Asphalt Graver Ballast	LOW ROOF - SE	23,910	55	5	0-1 year	open joints, poor drainage, deteriorated surface
	Roof Hatch - Metal	Low Roof - SE	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low Roof - SE	23,910	SF	7	10+ years	Recalculated all quantities.
	Coping - Metal	Low Roof North	190	LF	7	6-10 years	
	Downspouts - Interior Downspouts	Low Roof North	190 60	LF	6	6-10 years	
			00	LF	0	U-TU years	



**Category : Exterior Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Parapet - Parapet < 16" Height Low Roof North 190 LF 10+ vears 7 Roof - Asphalt Gravel Ballast 2.300 SF 5 0-1 vear Low Roof North Vegetation growth. Roof Structure - Steel / Metal Deck/ Low Roof North 2.300 SF 7 10+ years Concrete Topping Access Ladder - Metal Low Roof South EA 5 2-5 years No handrail extensions 1 LF 7 Chimney - Metal Flue Low Roof South 15 6-10 years Coping - Stone Low Roof South 225 LF 7 10+ years LF **Downspouts - Interior Downspouts** Low Roof South 60 6 6-10 years LF Parapet - 16" - 30" Height Low Roof South 225 7 10+ years SF Roof - Asphalt Gravel Ballast Low Roof South 6.078 5 0-1 year Bubbling, deteriorating, soft spots. SF Roof Structure - Concrete Low Roof South 6.078 7 10+ vears Access Ladder - Metal Low Southwest EA 5 2-5 years Does not go above roof 1 425 LF 7 6-10 years Coping - Metal Low Southwest LF 6-10 years **Downspouts - Interior Downspouts** Low Southwest 120 6 Parapet - Parapet < 16" Height 425 LF 7 10+ years Low Southwest Roof - Asphalt Gravel Ballast SF 5 Low Southwest 12.800 0-1 year Bubbling, deteriorating, soft spots. SF 7 Roof Structure - Concrete Low Southwest 12.800 10+ vears LF Chimney - Brick Chimney- Concrete/ Mortar Main Roof 20 5 6-10 years Cracking and shifting of masonry Liner Chimney - Metal Flue Main Roof 20 LF 6 6-10 years Coping - Metal Main Roof 2.170 LF 6 6-10 years Recalculated all quantities. Downspouts - Interior Downspouts LF 6 Main Roof 280 6-10 years Recalculated all quantities. LF 6 Parapet - 16" - 30" Height Main Roof 100 10+ years Recalculated all quantities. Parapet - Parapet < 16" Height LF 7 Main Roof 1.630 10+ years Recalculated all quantities. Roof - Asphalt Gravel Ballast 48.730 SF Recalculated all quantities. Open Main Roof 4 0-1 year ioints, soft spots, poor drainage, bubbling surface Main Roof SF 7 6-10 years Roof - Modified Bitumen 145 SF Roof Structure - Steel / Metal Deck/ Main Roof 48.875 7 10+ years Corrected material Concrete Topping Walls Canopy - Concrete/ Stucco Entire Building 461 SF 6 10+ years Cheek-Wall - Concrete Entire Building 320 SF 6 10+ years Exterior Walls - Brick Entire Building SF 6 27,460 10+ years SF Exterior Walls - Brick Entire Building 1,880 4 0-1 year Areas of spalled and deteriorated brick Exterior Walls - Precast Panel Wall SF 7 Entire Building 5.130 10+ years SF Exterior Walls - Prefabricated Metal Panel Entire Building 7.034 7 10+ vears Wall Windows Curtain wall - Insulated Panel SF Entire Building 10.515 6 6-10 years Lintels - Concrete Entire Building 2,338 LF 6 10+ years **Recombined** quantities



Catego	ry : Exterior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lintels - Steel	Entire Building	358	LF	6	10+ years		
	Skylite - Lexan	Entire Building	168	SF	6	6-10 years		
	Windows - Casement Aluminum Double-	Entire Building	5,376	SF	6	6-10 years		
	pane							
	Windows - Louver	Entire Building	200	SF	6	6-10 years		
	Windows - Sash Aluminum Double-pane	Entire Building	12,543	SF	6	6-10 years		
Catego	rv : Electrical		В	uildina	· Main			

Catego	ry : Electrical		B	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
-	Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting	Electrical Room Entire Building	1 11,159	EA SF	6 6	6-10 years 10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	37,414	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	7,562	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	8,316	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	7,498	SF	6	10+ years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	Four are located in each of the two gyms (two in the girls gym are damaged as noted in this report). Quantity changed as total has been divided/aggregated.
	Emergency Battery Packs - Gym	Entire Building	2	EA	2	0-1 year	Two emergency battery packs in girls gym are damaged.
	Emergency Battery Packs - Pool	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	1	EA	2	0-1 year	No backup battery, and school does not have a generator. One exit sign face is damaged and deteriorated.
	Exit Signs - Auditoium	Entire Building	8	EA	2	0-1 year	No backup battery, and school does not have a generator. Quantity changed as total has been divided/aggregated.
	Exit Signs - Corridors and Stairs	Entire Building	40	EA	2	0-1 year	No backup battery, and school does not have a generator. Quantity changed based on current observations.
	Exit Signs - Gym	Entire Building	9	EA	2	0-1 year	No backup battery, and school does



Catego	ory : Electrical		В	uilding	: Main		SSS W FSH OTREET, Officago, iE 00032
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	not have a generator. Six in boys gym, three in girls gym. No backup battery, and school does not have a generator.
	Exit Signs - Multipurpose Room	Entire Building	1	EA	2	0-1 year	No backup battery, and school does not have a generator. Quantity changed to match current observations.
	Exit Signs - Pool	Entire Building	2	EA	2	0-1 year	No backup battery, and school does not have a generator.
	Security System - CCTV	Entire Building	184,611	SF	7	6-10 years	Upgraded since last assessment. Rank, Reason and Priority Rep adjusted to match current observations.
	Security System - Intrusion Detection	Entire Building	184,611	SF	7	6-10 years	Upgraded since last assessment. Rank adjusted to match current observations.
Main Se							
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	184,611	SF	5	6-10 years	Older system. PA is not functional in Rooms 112, 117, 119, 120, 217 and 236.
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Quantity changed to match current observations and as the total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	PP110A. Open breaker slot exposes live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	2	0-1 year	Item Type changed as quantity has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	2	0-1 year	Quantity changed to match current observations and as the total has been divided/aggregated. Greater than 40 years old and substantially deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Quantity changed to match current observations and as the total has



Catego	ry : Electrical		B	uilding	: Main		3939 W F9th STREET, Chicago, IE 00032
outogo				anang	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	1NW and 1NW-A. Located in a Main
					_		Office Suite closet.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Quantity changed to match current
							observations and as the total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	Located in the mechanical room
		2mile Danang	-	<b>_</b> / (	•	ior youro	upstairs from the auditorium stage.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Panel 2SEA. Located in the
							mechanical room upstairs from the
	Lighting and Dawar Danala Above 400 A	Entire Duilding	4	Γ.	c	0.10	pool equipment room.
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	1	EA EA	6 4	6-10 years 0-1 year	Missing cover plate exposes live
	Lighting and Power Parlets - Above 100 A	Entitle Building	1	EA	4	0-1 year	conductors presenting a live front
							condition.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	2	0-1 year	Located in north basement
							mechanical room. Greater than 40
							years old and substantially
			0	Ξ.	-	40	deteriorated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Panels AC-1 and AC-2. Quantity changed as total has been
							divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	Panel BSE
	·······				-	<b>,</b>	
Catego	ry : Fire Protection		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	184,611	SF	7	10+ years	
	Fire Alarm_System	Entire Building	184,611	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
5	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Conc	litioning						
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	6-10 years	Item Type changed to match current
	than 5 tons						observations. Component of a
							ductless split system serving the MDF
							Room fan coil unit.
A · 11							

Air Handling Systems



Category : Mechanical **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Air Handling Unit- Package Single Zone-Boiler Room FΑ 5 6-10 vears 1 Indoor- Steam Coils - 12001-20000 cfm Air Intake Boiler Room 1 FΑ 5 6-10 years ΕA 5 Indoor Return Fans- Centrifugal Squirrel Entire Building 1 6-10 years 020923 Cage - 10001 - 20000 CFM Indoor Return Fans- Centrifugal Squirrel Entire Building EΑ 5 6-10 years 020942 1 Cage - 5000 - 10000 CFM Indoor Return Fans- Centrifugal Squirrel Entire Building 2 ΕA 5 6-10 years 020930, 020933 Cage - Greater than 20000 CFM Indoor Return Fans- Centrifugal Squirrel FΑ 021011 Entire Building 1 5 6-10 years Cage - Greater than 20000 CFM Indoor Return Fans- Centrifugal Squirrel Entire Building 3 ΕA 5 2-5 years 020926, 020924, 020922, Located in Cage - Less than 5000 CFM the mechanical space behind Room 239. Quantity changed as total has been divided/aggregated. Rank adjusted based on current observations as the condition of these units does not detract from their integrity, the units are well-maintained and repaired as necessary, and they are fully operational. New unit being installed as part of the Dehumidification Unit- Indoor- Steam Mechanical Room 1 ΕA 7 10+ years pool equipment modernization project Heating- DX Cooling with Self Contained Compressor - Greater than 8000 cfm underway at the time of assessment. No CPS Asset Tag present. Rank, Reason and Priority Rep adjusted to account for the new equipment. Mechanical Room ΕA Located in the mechanical room Air Handling Unit- Package Single Zone-1 5 6-10 years Indoor- Steam Coils - 20001-30000 cfm upstairs from the auditorium stage. Serves auditorium. Air Handling Unit- Package Single Zone-Mechanical Room FΑ 5 6-10 years Located in the mechanical room 1 Indoor- Steam Coils - 20001-30000 cfm behind Room 239. Older unit that is deteriorated but not to the extent that functionality is affected. Rank. Reason and Priority Rep adjusted based on current observations. Air Handling Unit- Package Single Zone-Mechanical Room 1 ΕA 5 6-10 years Located in the mechanical room Indoor- Steam Coils - 20001-30000 cfm behind Room 239. No CPS Asset tag present. Older unit that is deteriorated but not to the extent that functionality is affected. Rank, Reason and Priority Rep adjusted based on current observations. Air Handling Unit- Package Single Zone-Mechanical Room 1 EΑ 5 6-10 years Located in the mechanical room



Catego	ry : Mechanical		B	uilding	· Main		3939 W 79th STREET, Chicago, IL 60652	
oalego	ry meenamear			unung	. mani	Recommend		
Group	<b>Item - Type</b> Indoor- Steam Coils - 20001-30000 cfm	Location	Quantity	UOM	Rank	Replacement	<b>Comments</b> upstairs from the auditorium stage.	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves auditorium. Located in north basement mechanical room.	
	Air Intake	Mechanical Room	2	EA	6	10+ years		
	Air Intake	Mechanical Room	2	EA	6	10+ years	Location changed to match current observations.	
	Air Intake	Mechanical Room	2	EA	6	10+ years	Location changed to match current observations.	
Boiler Sy	vstems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Entire Building	3	EA	6	6-10 years	Boilers auxiliaries have been subject to proper annual maintenance; over the years they have been subject to all necessary repairs and all are in appropriate working condition. Rank Reason and Priority Rep adjusted based on review with the Chief Engineer and current observations.	
	Chemical Feeder	Entire Building	3	EA	6	10+ years	Each chemical feed pump has a CPS Asset Tag.	
	Combustion Dampers	Entire Building	3	EA	6	10+ years		
	Condensate Pump	Entire Building	1	EA	7	10+ years	New condensate pump is in the mid- of being installed as part of the construction project for the mechanical room.	
	Condensate Pump	Entire Building	1	EA	5	6-10 years		
	Condensate Pump	Entire Building	1	EA	5	10+ years	Located in north basement mechanical room.	
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	Tank has a CPS Asset Tag and its three pumps also have CPS Asset Tags. Older assembly that has bee well maintained and repaired as necessary. Free of leaks at the time of assessment. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building	1	EA	6	6-10 years	B-2. Boilers are original to the building and have been subject to proper annual maintenance; over th years they have been subject to all necessary repairs and all are in appropriate working condition,	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	<b>Comments</b> generally operating at approximately 3 psi. Rank, Reason and Priority Rep adjusted based on review with the Chief Engineer and current observations. Superficial corrosion noted on exterior shell. Boilers were in the midst of seasonal maintenance
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building	1	EA	6	6-10 years	protocol at the time of assessment. B-3. Boilers are original to the building and have been subject to proper annual maintenance; over the years they have been subject to all necessary repairs and all are in appropriate working condition, generally operating at approximately 3 psi. Rank, Reason and Priority Rep adjusted based on review with the Chief Engineer and current observations. Superficial corrosion noted on exterior shell. Boilers were in the midst of seasonal maintenance protocol at the time of assessment.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building	1	EA	6	6-10 years	B-1. Boilers are original to the building and have been subject to proper annual maintenance; over the years they have been subject to all necessary repairs and all are in appropriate working condition, generally operating at approximately 3 psi. Rank, Reason and Priority Rep adjusted based on review with the Chief Engineer and current observations. Superficial corrosion noted on exterior shell. Boilers were in the midst of seasonal maintenance
	Steam Traps	Entire Building	250	EA	6	6-10 years	protocol at the time of assessment. Steam traps that had internal leaks at the time of the previous assessment have been repaired or replaced since that time. Rank adjusted based on current observations and per review with Building Engineer.

Gas Booster



Catego	ry : Mechanical		В	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Booster	Boiler Room	3	EA	6	10+ years	Quantity changed as total has been divided/aggregated, hence N/A here. The three units date from 1977.
Heating							
	Unit Heater - Steam	Entire Building	2	EA	7	10+ years	Located in the mechanical room upstairs from the pool equipment room. New units installed as part of the construction project for the mechanical room.
	Unit Heater - Steam	Entire Building	5	EA	6	6-10 years	Located in Boys Gym
	Unit Heater - Steam	Entire Building	1	EA	6	6-10 years	Located in the mechanical room behind Room 239.
	Unit Heater - Steam	Entire Building	2	EA	6	6-10 years	Located in the mechanical room upstairs from the auditorium stage.
	Unit Heater - Steam	Entire Building	5	EA	6	6-10 years	Located in Girls Gym
	Fin Tube - Steam	Entire Building	1,074	LF	6	6-10 years	Fin tube has been cleaned since last assessment. Rank adjusted based on current observations.
	Wall Heater - Electric	Entire Building	1	EA	6	10+ years	Located in the storage room inside Room 110.
	Cabinet Heaters - With Steam Coil	Entire Building	16	EA	5	10+ years	
Tempera	ature Control						
	Pneumatic System	Entire Building	184,611	SF	3	0-1 year	System is nonfunctional throughout the school due to a general breakdown and overall failure. Pneumatic lines do not hold pressure control devices do not respond to settings, and dampers which are not seized are artificially held in a fixed position. Temperatures in all spaces of the building are manually controlled by the Building Engineer and are readjusted on a continual basis depending on day-to-day weather conditions. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Thermostats - Pneumatic	Entire Building	87	EA	4	0-1 year	Pneumatic thermostats throughout the school are inoperative pursuant t failure of the pneumatic control system. Thermostats are



Categor	y : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quartity	UOM	Rank	Recommend	Comments
Group	item - Type	Location	Quantity	UOM	капк	Replacement	contaminated with oil and dust and cannot be refurbished. Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
Unit Vent							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	80	EA	5	6-10 years	Quantity changed as total has been divided/aggregated. Dataplate inaccessible at the time of assessment. All units are original to the building but generally operational and well-maintained with frequent repairs being necessary. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
Ventilatio							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	Location and quantity changed to match current observations.
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Ceiling-mounted in a custodial closet between Rooms 106 and 108. No dataplate found.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	10	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen	Entire Building Entire Building	1	EA EA	2 6	0-1 year 6-10 years	Not equipped with fire suppression. Located in the serving line.



-							3939 W 79th STREET, Chicago, IL 60652
Catego	ry : Mechanical		E	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	2-5 years	
Catego	ry : Plumbing		E	Building	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - Less than 150000 BTU/HR Gas Heater - Less than 150000 BTU/HR	Entire Building Entire Building	1 1	EA EA	6 4	6-10 years 1-2 years	Serves Kitchen only. Dataplate inaccessible at the time of assessment. Older unit that is basically functional and leak free but shows signs of corrosion and deterioration and has reached the end of its anticipated service life.
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Entire Building	1	EA	6	10+ years	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Entire Building	1	EA	6	6-10 years	Serves Kitchen only.
Piping							
<u> </u>	Domestic Piping-Hot Water Return Lines	Entire Building	184,611	SF	4	2-5 years	Approx. ten to twenty pipe clamps throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life.
	Domestic Piping-Hot Water Return Risers	Entire Building	184,611	SF	4	2-5 years	Approx. ten to twenty pipe clamps throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	184,611	SF	4	2-5 years	Approx. ten to twenty pipe clamps throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	184,611	SF	4	2-5 years	Approx. ten to twenty pipe clamps throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	184,611	SF	4	2-5 years	Approx. ten to twenty pipe clamps throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life.



3939 W 79th STREET, Chicago, IL 60652 **Category : Plumbing** Building : Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Domestic Piping-Hot/Cold Water Supply Entire Building 184.611 SF 4 2-5 years Approx. ten to twenty pipe clamps (from Risers to Fixtures) throughout the piping system as temporary repairs to prevent leaks. Galvanized material beyond its anticipated service life. Sanitary Piping Entire Building 184,611 SF 6 6-10 years Storm Piping Entire Building 184,611 SF 6 6-10 years SF Vent Piping Entire Building 184.611 6 6-10 years Pool Systems Pool Drain Piping 100 LF 7 Entire Building 10+ years In the process of being replaced with new equipment at the time of assessment. Rank, Reason and Priority Rep adjusted to account for the new equipment. Pool Filtration System including Pump Entire Building 1 ΕA 7 In the process of being replaced with 10+ years new equipment at the time of assessment. Rank, Reason and Priority Rep adjusted to account for the new equipment. Pool Hot Water Heater - Gas Fired Entire Building 1 ΕA 7 10+ years Located in the mechanical room upstairs from the pool equipment room. In the process of being replaced with new equipment at the time of assessment. Rank, Reason and Priority Rep adjusted to account for the new equipment. LF In the process of being replaced with Pool Supply and Return Piping Entire Building 230 7 10+ years new equipment at the time of assessment. Rank. Reason and Priority Rep adjusted to account for the new equipment. Pumps Pumps - Eiector-Duplex Entire Building 1 ΕA 7 10+ vears In the process of being replaced with new equipment at the time of assessment. Rank. Reason and Priority Rep adjusted to account for the new equipment. Pumps - Ejector-Duplex Entire Building ΕA 6 6-10 years 1 ΕA Pumps - Sump-Duplex Entire Building 1 7 10+ years No CPS Asset Tag(s) present. In the process of being replaced with new equipment at the time of assessment. Rank, Reason and Priority Rep



## William J Bogan High School

3939 W 79th STREET, Chicago, IL 60652

Catego	В	uilding	: Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							adjusted to account for the new equipment.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located at the bottom of the elevator pit. Inaccessible at the time of assessment.
	Pumps - Sump-Simplex	Entire Building	1	EA	5	6-10 years	Located in north basement mechanical room.

**Building : Main** 

#### Category : Room

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Administrative Suites/Offices Ceiling - Lav-in 102 Security Office 323 SF 6 6-10 years SF Ceiling - Lay-in 102 Security Office 5 4 0-1 year Water damage Doors - Wood Doors inclu hw 102 Security Office 1 ΕA 6 10+ years SF Floor - Tile 102 Security Office 328 6 6-10 years 102 Security Office 6 6-10 years Lighting - Lay-in 6 EΑ Walls - Concrete Block 102 Security Office 148 SF 6 10+ years SF Walls - Metal Panel 102 Security Office 327 6 10+ years AC Unit 105 Assistant Principle Office 1 EΑ 7 6-10 years 105 Assistant Principle Office SF Ceiling - Splined 127 6 10+ years Doors - Wood Doors inclu hw 105 Assistant Principle Office EΑ 6 10+ vears 1 Floor - Tile/Sheet 105 Assistant Principle Office SF 5 127 10+ years Lighting - Pendent/Surface 105 Assistant Principle Office 2 ΕA 6 6-10 years ΕA 6 Power Distribution 105 Assistant Principle Office 4 6-10 years Walls - Concrete Block 105 Assistant Principle Office SF 6 357 10+ years 7 AC Unit 107 Nurse Office 1 FΑ 6-10 years Ceiling - Splined 107 Nurse Office 816 SF 6 10+ years Doors - Wood Doors inclu hw 107 Nurse Office EΑ 6 10+ years 1 Floor - Tile/Sheet SF 107 Nurse Office 816 5 6-10 vears Lighting - Pendent/Surface 107 Nurse Office 7 EΑ 6 6-10 years **Power Distribution** 107 Nurse Office 12 ΕA 6 6-10 years Walls - Concrete Block SF 107 Nurse Office 986 6 10+ years 114A Teachers Office-part of room 7 AC Unit EΑ 6-10 years 1 114 Ceiling - Splined 114A Teachers Office-part of room 556 SF 7 10+ years 114 114A Teachers Office-part of room Doors - Wood Doors inclu hw EΑ 7 6-10 years 1 114 Floor - Tile/Sheet 114A Teachers Office-part of room 546 SF 7 10+ years 114 SF Floor - Tile/Sheet 114A Teachers Office-part of room Cracked- chipped 10 4 0-1 year 114



Category : Room			B	uilding	· Main		
oulego				anang	· Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	114A Teachers Office-part of room	11	EA	5	2-5 years	
	5 5	114				,	
	Power Distribution	114A Teachers Office-part of room	10	EA	7	10+ years	
		114				-	
	Storage/ Closet	114A Teachers Office-part of room	56	SF	5	2-5 years	
		114					
	Walls - Concrete Block	114A Teachers Office-part of room	612	SF	6	10+ years	
		114					
	Walls - Plaster/Drywall	114A Teachers Office-part of room	331	SF	7	10+ years	
		114		~-	_		
	Ceiling - Splined	115 Office	200	SF	7	10+ years	<b>N N N N</b>
	Ceiling - Splined	115 Office	60	SF	4	0-1 year	Missing tiles
	Doors - Wood Doors inclu hw	115 Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	115 Office	260	SF	7	10+ years	
	Lighting - Pendent/Surface	115 Office	8	EA	7	6-10 years	
	Power Distribution	115 Office	4	EA	7	6-10 years	
	Walls - Concrete Block	115 Office	380	SF	7	10+ years	
	Walls - Metal Panel	115 Office	150	SF	7	10+ years	
	AC Unit	118 Copy room	1	EA	7	6-10 years	
	Ceiling - Splined	118 Copy room	342	SF	6	10+ years	
	Ceiling - Splined	118 Copy room	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	118 Copy room	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	118 Copy room	352	SF	7	10+ years	
	Lighting - Pendent/Surface	118 Copy room	8	ĒA	7	10+ years	
	Power Distribution	118 Copy room	8	EA	7	10+ years	
	Walls - Concrete Block	118 Copy room	763	SF	6	10+ years	
	AC Unit	120A Security Office	1	EA	7	6-10 years	
	Ceiling - Splined	120A Security Office	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	120A Security Office	1	EA	6	10+ years	
	Floor - Tile	120A Security Office	55	SF	6	6-10 years	
		120A Security Office	55	EA	6	•	
	Lighting - Lay-in		55	SF	7	6-10 years	
	Walls - Concrete Block	120A Security Office		SF		10+ years	
	Walls - Metal Panel	120A Security Office	25	-	6	10+ years	
	AC Unit	1st Floor 128 Office	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor 128 Office	318	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor 128 Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor 128 Office	288	SF	5	2-5 years	
	Floor - Tile/Sheet	1st Floor 128 Office	30	SF	4	0-1 year	Missing floor
	Lighting - Pendent/Surface	1st Floor 128 Office	9	EA	6	6-10 years	
	Power Distribution	1st Floor 128 Office	8	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor 128 Office	483	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor 128 Office	235	SF	6	10+ years	
	AC Unit	1st Floor Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor Engineer's Office	161	SF	6	10+ years	
		-					



Catego	ry : Room		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor Engineer's Office	161	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Engineer's Office	3	EA	6	6-10 years	
	Walls - Metal Panel	1st Floor Engineer's Office	250	SF	6	10+ years	
	AC Unit	1st floor 102F Women staff lounge	1	EA	7	6-10 years	
	Ceiling - Splined	1st floor 102F Women staff lounge	227	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor 102F Women staff lounge	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st floor 102F Women staff lounge	227	SF	5	10+ years	
	Lighting - Pendent/Surface	1st floor 102F Women staff lounge	3	EA	6	6-10 years	
	Power Distribution	1st floor 102F Women staff lounge	4	EA	6	6-10 years	
	Walls - Concrete Block	1st floor 102F Women staff lounge	498	SF	6	10+ years	
	AC Unit	1st floor 108 Men staff lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st floor 108 Men staff lounge	20	SF	4	1-2 years	Missing/ damaged tile
	Ceiling - Splined	1st floor 108 Men staff lounge	207	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor 108 Men staff lounge	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st floor 108 Men staff lounge	227	SF	5	10+ years	
	Lighting - Pendent/Surface	1st floor 108 Men staff lounge	3	EA	6	6-10 years	
	Power Distribution	1st floor 108 Men staff lounge	4	EA	6	6-10 years	
	Walls - Concrete Block	1st floor 108 Men staff lounge	598	SF	6	10+ years	
	Walls - Concrete Block	1st floor 108 Men staff lounge	100	SF	5	1-2 years	Cracked wall
	Ceiling - Plaster/Drywall	212C Women staff lounge	205	SF	6	10+ years	
	Doors - Wood Doors inclu hw	212C Women staff lounge	1	EA	6	10+ years	
	Floor - Tile/Sheet	212C Women staff lounge	205	SF	5	10+ years	
	Lighting - Pendent/Surface	212C Women staff lounge	4	EA	6	10+ years	
	Power Distribution	212C Women staff lounge	2	EA	6	10+ years	
	Walls - Metal Panel	212C Women staff lounge	737	SF	6	10+ years	
	Ceiling - Splined	212F Men staff lounge	205	SF	6	10+ years	
	Doors - Wood Doors inclu hw	212F Men staff lounge	1	EA	6	10+ years	
	Floor - Tile/Sheet	212F Men staff lounge	205	SF	5	10+ years	
	Lighting - Pendent/Surface	212F Men staff lounge	4	EA	6	10+ years	
	Power Distribution	212F Men staff lounge	2	EA	6	10+ years	
	Walls - Metal Panel	212F Men staff lounge	237	SF	6	10+ years	
	Walls - Structural Glazed Tile	212F Men staff lounge	200	SF	6	10+ years	
	AC Unit	238C Office 2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	238C Office 2nd Floor	282	SF	6	10+ years	
	Doors - Wood Doors inclu hw	238C Office 2nd Floor	1	EA	6	10+ years	
	Floor - Terrazzo	238C Office 2nd Floor	282	SF	6	10+ years	
	Lighting - Pendent/Surface	238C Office 2nd Floor	4	EA	7	10+ years	
	Power Distribution	238C Office 2nd Floor	14	EA	6	10+ years	
	Walls - Plaster/Drywall	238C Office 2nd Floor	490	SF	6	10+ years	
	Walls - Structural Glazed Tile	238C Office 2nd Floor	336	SF	5	2-5 years	
	Ceiling - Lay-in	238D Radio/TV Studio	914	SF	6	10+ years	
	Doors - Wood Doors inclu hw	238D Radio/TV Studio	1	EA	6	6-10 years	
	Floor - Tile/Sheet	238D Radio/TV Studio	914	SF	4	1-2 years	Water damage



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 238D Radio/TV Studio 8 ΕA 10+ vears 7 Power Distribution 8 ΕA 7 238D Radio/TV Studio 10+ years Storage/ Closet 238D Radio/TV Studio 250 SF 5 6-10 years Walls - Concrete Block SF 6 238D Radio/TV Studio 462 10+ years Walls - Metal Panel SF 238D Radio/TV Studio 440 6 10+ years AC Unit Admin. Assistant Office - Main EΑ 7 6-10 years 1 Office Ceiling - Splined Admin. Assistant Office - Main 158 SF 6 10+ years Office Doors - Wood Doors inclu hw Admin. Assistant Office - Main FΑ 1 6 10+ years Office Floor - Tile Admin. Assistant Office - Main 158 SF 5 10+ years Office Lighting - Pendent/Surface Admin. Assistant Office - Main 6 EΑ 6 6-10 years Office Admin. Assistant Office - Main FΑ Power Distribution 6 6 6-10 years Office Walls - Concrete Block Admin. Assistant Office - Main 497 SF 6 10+ years Office AC Unit Assistant Principal -Main Office 1 EΑ 7 6-10 years Ceiling - Splined Assistant Principal -Main Office 175 SF 6 10+ years Doors - Wood Doors inclu hw Assistant Principal -Main Office 10+ years 1 EΑ 6 Floor - Tile SF 6 Assistant Principal -Main Office 175 10+ years Lighting - Pendent/Surface Assistant Principal -Main Office FΑ 6 6-10 years 4 Power Distribution Assistant Principal -Main Office 6 ΕA 6 6-10 years SF Storage/ Closet Assistant Principal -Main Office 13 7 10+ vears Walls - Concrete Block SF Assistant Principal -Main Office 524 6 10+ years AC Unit Attendance office 1st Floor ΕA 7 6-10 years 1 SF Ceiling - Splined Attendance office 1st Floor 339 6 10+ years Doors - Wood Doors inclu hw Attendance office 1st Floor ΕA 6 10+ years 1 Floor - Tile/Sheet Attendance office 1st Floor 339 SF 5 6-10 years Lighting - Pendent/Surface Attendance office 1st Floor 6 EΑ 6 6-10 vears Power Distribution Attendance office 1st Floor 18 FΑ 6 6-10 years Walls - Concrete Block Attendance office 1st Floor 619 SF 6 10+ vears 7 AC Unit Community Room 2 EA 6-10 years SF Ceiling - Splined Community Room 1,700 6 10+ years SF Ceiling - Splined Community Room 81 4 0-1 year Missing and water damage Doors - Store Front Community Room EA 6 6-10 years 1 Floor - Tile **Community Room** 1.781 SF 6 10+ years Lighting - Pendent/Surface Community Room 15 ΕA 6 6-10 vears Power Distribution Community Room 22 ΕA 6 6-10 years SF 7 Storage/ Closet Community Room 206 10+ vears Walls - Concrete Block Community Room 1,283 SF 6 10+ years SF Walls - Plaster/Drywall Community Room 339 6 10+ years



Catego	ry : Room		Building : Main							
_	-					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Work SInk	Community Room	1	EA	7	6-10 years				
	AC Unit	Counselor's Office in Room 106	1	EA	7	6-10 years				
	Ceiling - Splined	Counselor's Office in Room 106	81	SF	6	10+ years				
	Ceiling - Splined	Counselor's Office in Room 106	5	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	Counselor's Office in Room 106	1	EA	6	6-10 years				
	Floor - Tile/Sheet	Counselor's Office in Room 106	86	SF	5	10+ years				
	Lighting - Pendent/Surface	Counselor's Office in Room 106	2	EA	6	6-10 years				
	Power Distribution	Counselor's Office in Room 106	4	EA	6	6-10 years				
	Walls - Concrete Block	Counselor's Office in Room 106	134	SF	6	10+ years				
	Walls - Plaster/Drywall	Counselor's Office in Room 106	160	SF	6	10+ years				
	AC Unit	Counselor's Suite 108	1	EA	7	6-10 years				
	Ceiling - Splined	Counselor's Suite 108	266	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Counselor's Suite 108	1	EA	6	6-10 years				
	Floor - Tile/Sheet	Counselor's Suite 108	266	SF	5	2-5 years				
	Lighting - Pendent/Surface	Counselor's Suite 108	6	EA	6	6-10 years				
	Power Distribution	Counselor's Suite 108	6	EA	6	6-10 years				
	Walls - Concrete Block	Counselor's Suite 108	656	SF	6	10+ years				
	AC Unit	Dean of Students Office D in Room	1	EA	7	6-10 years				
		102								
	Ceiling - Lay-in	Dean of Students Office D in Room	166	SF	6	10+ years				
		102								
	Doors - Wood Doors inclu hw	Dean of Students Office D in Room	1	EA	6	6-10 years				
		102								
	Floor - Tile	Dean of Students Office D in Room	166	SF	6	6-10 years				
		102								
	Lighting - Lay-in	Dean of Students Office D in Room	4	EA	6	6-10 years				
		102								
	Power Distribution	Dean of Students Office D in Room	18	EA	6	6-10 years				
		102								
	Walls - Concrete Block	Dean of Students Office D in Room	367	SF	6	10+ years				
		102								
	Walls - Metal Panel	Dean of Students Office D in Room	201	SF	6	10+ years				
		102								
	Ceiling - Lay-in	Discipline Office E in Room 102	156	SF	6	10+ years				
	Ceiling - Lay-in	Discipline Office E in Room 102	10	SF	4	1-2 years	Buckled			
	Doors - Wood Doors inclu hw	Discipline Office E in Room 102	1	EA	6	10+ years				
	Floor - Tile	Discipline Office E in Room 102	166	SF	6	10+ years				
	Lighting - Lay-in	Discipline Office E in Room 102	4	EA	6	6-10 years				
	Power Distribution	Discipline Office E in Room 102	18	EA	6	6-10 years				
	Walls - Concrete Block	Discipline Office E in Room 102	222	SF	6	10+ years				
	Walls - Metal Panel	Discipline Office E in Room 102	201	SF	6	10+ years				
	Ceiling - Splined	Library Conference Room 126B	362	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Library Conference Room 126B	1	EA	6	6-10 years				
	Floor - Tile/Sheet	Library Conference Room 126B	362	SF	5	2-5 years				



Category : Room			В	uilding	: Main		
Ū						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Library Conference Room 126B	6	EA	6	6-10 years	
	Walls - Concrete Block	Library Conference Room 126B	650	SF	6	10+ years	
	Ceiling - Splined	Library Office 126A	357	SF	5	6-10 years	
	Ceiling - Splined	Library Office 126A	5	SF	4	0-1 year	Holes and damage
	Doors - Wood Doors inclu hw	Library Office 126A	1	EA	6	6-10 years	
	Floor - Tile/Sheet	Library Office 126A	362	SF	5	6-10 years	
	Lighting - Pendent/Surface	Library Office 126A	6	EA	6	6-10 years	
	Walls - Concrete Block	Library Office 126A	690	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Splined	Main Office	1,014	SF	6	10+ years	
	Doors - Store Front	Main Office	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Tile	Main Office	1,014	SF	6	6-10 years	
	Lighting - Pendent/Surface	Main Office	19	EA	6	6-10 years	
	Power Distribution	Main Office	18	EA	6	6-10 years	
	Storage/ Closet	Main Office	66	SF	5	10+ years	
	Walls - Concrete Block	Main Office	1,502	SF	6	10+ years	
	Walls - Metal Panel	Main Office	246	SF	6	10+ years	
	Ceiling - Splined	Music Office	168	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Music Office	1	EA	6	10+ years	
	Floor - Tile	Music Office	168	SF	6	10+ years	
	Lighting - Pendent/Surface	Music Office	4	EA	6	6-10 years	
	Power Distribution	Music Office	6	EA	6	6-10 years	
	Walls - Concrete Block	Music Office	310	SF	6	10+ years	
	Ceiling - Splined	Office 170B kitchen manager	112	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Office 170B kitchen manager	1	EA	6	6-10 years	
	Floor - Tile	Office 170B kitchen manager	112	SF	6	6-10 years	
	Lighting - Pendent/Surface	Office 170B kitchen manager	1	EA	6	6-10 years	
	Walls - Concrete Block	Office 170B kitchen manager	223	SF	6	10+ years	
	AC Unit	Office 209	1	EA	7	6-10 years	
	Ceiling - Splined	Office 209	327	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office 209	1	EA	6	10+ years	
	Floor - Tile/Sheet	Office 209	327	SF	5	10+ years	
	Lighting - Pendent/Surface	Office 209	10	EA	7	10+ years	
	Power Distribution	Office 209	12	EA	6	10+ years	
	Walls - Concrete Block	Office 209	698	SF	6	10+ years	
	AC Unit	Office 211	1	EA	7	6-10 years	
	Ceiling - Splined	Office 211	340	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office 211	1	EA	6	10+ years	
	Floor - Tile/Sheet	Office 211	340	SF	5	6-10 years	
	Lighting - Pendent/Surface	Office 211	8	EA	7	10+ years	
	Power Distribution	Office 211	42	EA	7	10+ years	
	Walls - Concrete Block	Office 211	740	SF	6	10+ years	
	Ceiling - Lay-in	Office A in Room 102	126	SF	6	6-10 years	
	- <u> </u>				-	,	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Office A in Room 102 Doors - Wood Doors inclu hw EΑ 6-10 years 6 1 Office A in Room 102 126 SF 6 Floor - Tile 6-10 years Lighting - Lay-in Office A in Room 102 3 FΑ 6 6-10 years Power Distribution 18 6 Office A in Room 102 EΑ 6-10 years SF Walls - Concrete Block Office A in Room 102 130 6 10+ years SF Walls - Metal Panel Office A in Room 102 186 6 10+ years AC Unit Office A in Room 108 ΕA 7 6-10 years 1 SF Ceiling - Splined Office A in Room 108 84 6 6-10 years Doors - Wood Doors inclu hw Office A in Room 108 2 ΕA 6 6-10 years SF Floor - Tile/Sheet Office A in Room 108 74 7 10+ vears Floor - Tile/Sheet Office A in Room 108 10 SF 4 0-1 vear Damaged Lighting - Pendent/Surface Office A in Room 108 2 EA 6 6-10 years **Power Distribution** 4 ΕA 6 6-10 years Office A in Room 108 SF 6 Walls - Concrete Block Office A in Room 108 164 10+ years SF 5 Walls - Concrete Block Office A in Room 108 10 0-1 year Cracked SF 6 Ceiling - Lay-in Office B in Room 102 112 10+ years Doors - Wood Doors inclu hw ΕA Office B in Room 102 1 6 6-10 vears Floor - Tile Office B in Room 102 112 SF 6 6-10 years Lighting - Lay-in Office B in Room 102 3 ΕA 6 6-10 years Walls - Concrete Block Office B in Room 102 72 SF 6 10+ years Walls - Metal Panel Office B in Room 102 175 SF 6 10+ years 7 AC Unit Office B in Room 108 1 EA 6-10 years SF Ceiling - Splined Office B in Room 108 84 6 10+ years Doors - Wood Doors inclu hw Office B in Room 108 FΑ 6 10+ years 1 Floor - Tile/Sheet 84 SF 5 Office B in Room 108 6-10 years Lighting - Pendent/Surface Office B in Room 108 2 FΑ 6 6-10 years Power Distribution Office B in Room 108 4 EΑ 6 6-10 years Walls - Concrete Block Office B in Room 108 174 SF 6 10+ years 7 AC Unit Office C in Room 102 1 EA 6-10 years Ceiling - Lay-in Office C in Room 102 123 SF 6 6-10 years SF Ceiling - Lav-in Office C in Room 102 3 4 0-1 vear Water damage Doors - Wood Doors inclu hw Office C in Room 102 1 EΑ 6 6-10 vears SF Floor - Tile Office C in Room 102 126 6 6-10 vears Office C in Room 102 FΑ 6 6-10 years Lighting - Lay-in 3 Power Distribution Office C in Room 102 18 EΑ 6 6-10 years SF 6 Walls - Concrete Block Office C in Room 102 130 10+ years SF Walls - Metal Panel Office C in Room 102 186 6 10+ years 5 AC Unit Office C in Room 108 EA 2-5 years 1 Ceiling - Splined Office C in Room 108 84 SF 6 10+ years Water damage has been fixed Doors - Wood Doors inclu hw Office C in Room 108 1 EΑ 6 10+ vears Floor - Tile/Sheet Office C in Room 108 84 SF 5 10+ years

Lighting - Pendent/Surface

Power Distribution

Walls - Concrete Block

Office C in Room 108

Office C in Room 108

Office C in Room 108

2

4

174

FΑ

EΑ

SF

6

6

6

6-10 vears

6-10 years

10+ years



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	Office D in Room 108	1	EA	7	6-10 years	
	Ceiling - Splined	Office D in Room 108	84	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office D in Room 108	1	EA	6	10+ years	
	Floor - Tile/Sheet	Office D in Room 108	84	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	Office D in Room 108	2	EA	6	6-10 years	
	Power Distribution	Office D in Room 108	4	EA	6	6-10 years	
	Walls - Concrete Block	Office D in Room 108	164	SF	6	10+ years	
	AC Unit	Office E in Room 108	1	EA	5	6-10 years	
	Ceiling - Splined	Office E in Room 108	84	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office E in Room 108	1	EA	6	10+ years	
	Floor - Tile/Sheet	Office E in Room 108	84	SF	5	6-10 years	
	Lighting - Pendent/Surface	Office E in Room 108	2	EA	6	6-10 years	
	Power Distribution	Office E in Room 108	4	EA	6	6-10 years	
	Walls - Concrete Block	Office E in Room 108	174	SF	6	10+ years	
	Ceiling - Splined	Office in 141	5	SF	7	10+ years	Repaired.
	Ceiling - Splined	Office in 141	137	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office in 141	1	EA	6	10+ years	
	Floor - Tile	Office in 141	142	SF	6	10+ years	
	Lighting - Pendent/Surface	Office in 141	3	EA	6	6-10 years	
	Power Distribution	Office in 141	2	EA	6	6-10 years	
	Walls - Concrete Block	Office in 141	328	SF	6	10+ years	
	Walls - Concrete Block	Office in 141	25	SF	5	0-1 year	Large crack, painted over
	Ceiling - Splined	Office in Main Office	88	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Office in Main Office	1	EA	6	6-10 years	
	Floor - Tile/Sheet	Office in Main Office	88	SF	5	2-5 years	
	Lighting - Pendent/Surface	Office in Main Office	2	EA	6	6-10 years	
	Power Distribution	Office in Main Office	2	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Office in Main Office	153	SF	6	10+ years	
	AC Unit	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Splined	Principal's Office	242	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office	242	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	6	EA	6	6-10 years	
	Power Distribution	Principal's Office	6	EA	6	6-10 years	
	Storage/ Closet	Principal's Office	13	SF	7	10+ years	
	Walls - Metal Panel	Principal's Office	540	SF	6	10+ years	
	AC Unit	Room 105 Office	1	EA	7	6-10 years	
	Ceiling - Splined	Room 105 Office	221	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 105 Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Room 105 Office	221	SF	5	10+ years	
	Lighting - Pendent/Surface	Room 105 Office	5	EA	6	6-10 years	
	Power Distribution	Room 105 Office	6	EA	6	6-10 years	
	Storage/ Closet	Room 105 Office	25	SF	7	10+ years	
	Walls - Concrete Block	Room 105 Office	530	SF	6	10+ years	



Category : Room		В	uilding	: Main			
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	Room 106 Teacher's Lounge	2	EA	7	6-10 years	
	Ceiling - Splined	Room 106 Teacher's Lounge	702	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 106 Teacher's Lounge	2	EA	6	10+ years	
	Floor - Tile/Sheet	Room 106 Teacher's Lounge	702	SF	5	10+ years	
	Lighting - Pendent/Surface	Room 106 Teacher's Lounge	15	EA	6	6-10 years	
	Walls - Concrete Block	Room 106 Teacher's Lounge	629	SF	6	10+ years	
	Walls - Metal Panel	Room 106 Teacher's Lounge	240	SF	6	10+ years	
	AC Unit	Room 212W-Program Office	1	ĒA	5	0-1 year	Older unit.
	Ceiling - Splined	Room 212W-Program Office	336	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 212W-Program Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	Room 212W-Program Office	336	SF	5	10+ years	
	Lighting - Pendent/Surface	Room 212W-Program Office	9	EA	7	10+ years	
	Power Distribution	Room 212W-Program Office	10	EA	6	10+ years	
	Walls - Concrete Block	Room 212W-Program Office	353	SF	6	10+ years	
	Walls - Metal Panel	Room 212W-Program Office	320	SF	6	10+ years	
		Room 212W Program Onice	020	01	0	Tor years	
Auditoriu	um & Theater						
	Ceiling - Exposed	1st Floor	2,132	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	9,027	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	10+ years	
	Floor - Tile	1st Floor	11,142	SF	6	10+ years	
	Floor - Tile	1st Floor	17	SF	4	0-1 year	Cracking and separating
	Lighting - Pendent/Surface	1st Floor	114	EA	6	6-10 years	5 1 5
	Main Floor Seating	1st Floor	10	EA	5	6-10 years	
	Main Floor Seating	1st Floor	1,070	EA	5	6-10 years	
	Sound System	1st Floor	, 1	EA	5	6-10 years	
	Stage	1st Floor	2,291	SF	5	0-1 year	Needs refinishin
	Stage Curtain	1st Floor	15	ËA	5	6-10 years	
	Stage Lighting System	1st Floor	1	EA	5	10+ years	
	Stage-Stairs - Wood	1st Floor	16	LF	6	10+ years	
	Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	10,838	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,178	SF	5	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	50	SF	4	0-1 year	Cracked, chipped, holes
						,	
Gymnas							
	Bleacher Seating	1st Floor Boys Gym	680	EA	5	6-10 years	
	Ceiling - Exposed	1st Floor Boys Gym	8,316	SF	5	10+ years	
	Doors - Steel Doors incl hw	1st Floor Boys Gym	8	EA	6	10+ years	
	Floor - Wood	1st Floor Boys Gym	8,316	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys Gym	30	EA	5	6-10 years	
	Scoreboards	1st Floor Boys Gym	1	EA	5	6-10 years	
	Sound System	1st Floor Boys Gym	1	EA	5	6-10 years	
	Storage/ Closet	1st Floor Boys Gym	50	SF	5	6-10 years	



Group

Kitchen

Category : Room

Recommend Item - Type Location Quantity UOM Rank Replacement Comments Walls - Concrete Block 1st Floor Boys Gym 7.442 SF 6 10+ vears 1st Floor Boys Gym 25 SF 5 Walls - Concrete Block 0-1 vear Cracks. Walls - Structural Glazed Tile 1st Floor Boys Gym 2.514 SF 6 10+ years 1st Floor Girls Gym 5 **Bleacher Seating** 340 EΑ 6-10 years SF 5 Ceiling - Exposed 1st Floor Girls Gym 7,562 10+ years 7 Doors - Hardware 1st Floor Girls Gym EΑ 10+ years 13 Floor - Wood 1st Floor Girls Gym SF 7 10+ years 7,562 Lighting - Pendent/Surface 1st Floor Girls Gym 30 ΕA 5 6-10 years Scoreboards 1st Floor Girls Gym 1 ΕA 5 6-10 years Sound System 1st Floor Girls Gvm FΑ 5 6-10 years 1 1st Floor Girls Gvm Storage/ Closet 50 SF 5 10+ vears Walls - Concrete Block 1st Floor Girls Gym 7,182 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor Girls Gym SF 6 2,401 10+ years Ceiling - Lay-in 1st Floor Servery 1.680 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor Serverv 1 FΑ 6 10+ years Floor - Tile Quarry 1st Floor Servery 1,680 SF 6 10+ years Lighting - Pendent/Surface 1st Floor Servery 18 EA 6 6-10 years Serving Line LF 6 6-10 years 1st Floor Servery 114 SF Storage/ Closet 1st Floor Servery 25 7 10+ years Walls - Structural Glazed Tile 1st Floor Serverv 1.356 SF 6 6-10 years SF Ceiling - Lav-in Cafeteria Kitchen 2.400 6 6-10 years Doors - Wood Doors inclu hw Cafeteria Kitchen ΕA 6 10+ vears 1 Floor - Tile Quarry Cafeteria Kitchen 2.400 SF 6 10+ years Lighting - Pendent/Surface 6 6-10 years Cafeteria Kitchen 18 EA SF 7 Storage/ Closet Cafeteria Kitchen 400 6-10 years Walls - Structural Glazed Tile SF Cafeteria Kitchen 3,600 6 10+ years **Dishwashing Room** SF Ceiling - Lay-in 489 6 10+ years Doors - Wood Doors inclu hw ΕA **Dishwashing Room** 6 6 10+ years SF Floor - Tile Quarry **Dishwashing Room** 489 6 10+ years Lighting - Pendent/Surface **Dishwashing Room** 9 ΕA 6 6-10 years Walls - Structural Glazed Tile **Dishwashing Room** 777 SF 6 10+ years Ceiling - Splined Located in Community Room 117 SF 5 10+ years Ceiling - Splined Located in Community Room SF 4 1 0-1 year Missing tile Doors - Wood Doors inclu hw 7 Located in Community Room 1 EA 10+ years SF Floor - Tile Located in Community Room 116 7 6-10 years Floor - Tile Located in Community Room SF 2 4 0-1 year Missing tiles Lighting - Pendent/Surface Located in Community Room 45 FΑ 7 6-10 vears Storage/ Closet Located in Community Room 63 SF 7 10+ years Walls - Concrete Block Located in Community Room 370 SF 7 10+ years AC Unit Room 126 3 ΕA 7 6-10 years

**Building : Main** 

Library



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Casework Room 126 165 LF 6-10 vears 6 Room 126 SF Ceiling - Splined 2.945 6 10+ years Doors - Side-lite Room 126 SF 6 10+ years 12 Doors - Store Front Room 126 6 1 EΑ 6-10 years 5 Floor - Tile/Sheet Room 126 2,945 SF 10+ years Lighting - Pendent/Surface Room 126 EA 6 6-10 years 66 Walls - Concrete Block Room 126 SF 1,142 6 10+ years SF Walls - Plaster/Drywall Room 126 660 6 10+ years Locker/Shower Room 1st Floor Boys Locker Room (Not in SF 7 1,363 6-10 years Accessories use) LF Benches, ped mounted 1st Floor Boys Locker Room (Not in 36 6 6-10 years use) SF Ceiling - Plaster/Drywall 1st Floor Boys Locker Room (Not in 1.363 6 10+ years use) Doors - Wood Doors inclu hw 1st Floor Boys Locker Room (Not in 2 FΑ 6 10+ years use) SF Floor - Tile Ceramic/ Porcelain 1st Floor Boys Locker Room (Not in 400 6 10+ years use) Floor - Tile Ceramic/ Porcelain 1st Floor Boys Locker Room (Not in 40 SF 4 0-1 year Cracked/missing. use) Floor - Tile/Sheet 923 SF 1st Floor Boys Locker Room (Not in 5 10+ years use) Lighting - Pendent/Surface 1st Floor Boys Locker Room (Not in 13 EA 6 6-10 years use) Partitions 1st Floor Boys Locker Room (Not in 2 EΑ 7 10+ years use) SF Storage/ Closet 1st Floor Boys Locker Room (Not in 25 7 10+ years use) Student Lockers - Two Tier 1st Floor Boys Locker Room (Not in 116 EΑ 6 6-10 years use) Urinals 1st Floor Boys Locker Room (Not in 3 EΑ 7 10+ years use) Walls - Concrete Block SF 1st Floor Boys Locker Room (Not in 1,251 6 10+ years use) Walls - Metal Panel 1st Floor Boys Locker Room (Not in 450 SF 6 10+ years use) Walls - Structural Glazed Tile 1st Floor Boys Locker Room (Not in 1.014 SF 6 10+ years use) Water Closet 1st Floor Boys Locker Room (Not in 2 EΑ 6 10+ years use) Ceiling - Plaster/Drywall Boys Shower in Locker Room B101 492 SF 5 10+ years Floor - Concrete Epoxy/ Painted Boys Shower in Locker Room B101 492 SF 4 0-1 year Giant hole.



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Boys Shower in Locker Room B101	7	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys Shower in Locker Room B101	7	EA	5	6-10 years	
	Showers	Boys Shower in Locker Room B101	16	EA	5	6-10 years	
	Walls - Concrete Block	Boys Shower in Locker Room B101	1,298	SF	4	0-1 year	Missing/replacing throughout.
	Accessories	Girls Locker Room G101	603	SF	5	6-10 years	
	Benches, ped mounted	Girls Locker Room G101	34	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Girls Locker Room G101	603	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Locker Room G101	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Girls Locker Room G101	403	SF	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Locker Room G101	200	SF	6	10+ years	
	Hand Dryer	Girls Locker Room G101	8	EA	5	6-10 years	
	Lavatory	Girls Locker Room G101	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls Locker Room G101	11	EA	6	6-10 years	
	Partitions	Girls Locker Room G101	3	EA	7	6-10 years	
	Showers	Girls Locker Room G101	10	EA	7	10+ years	
	Student Lockers - Two Tier	Girls Locker Room G101	80	EA	6	6-10 years	
	Walls - Concrete Block	Girls Locker Room G101	744	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Locker Room G101	200	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Girls Locker Room G101	200	SF	6	10+ years	
	Water Closet	Girls Locker Room G101	3	EA	7	10+ years	
	Accessories	Girls Shower in Locker Room	325	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Shower in Locker Room	325	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Shower in Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Shower in Locker Room	225	SF	6	10+ years	
	Floor - Tile/Sheet	Girls Shower in Locker Room	100	SF	7	6-10 years	
	Floor Drain	Girls Shower in Locker Room	2	EA	7	6-10 years	
	Hand Dryer	Girls Shower in Locker Room	8	EA	7	6-10 years	
	Lighting - Lay-in	Girls Shower in Locker Room	4	EA	6	6-10 years	
	Showers	Girls Shower in Locker Room	11	EA	7	6-10 years	
	Student Lockers - Two Tier	Girls Shower in Locker Room	60	EA	6	•	
	Walls - Concrete Block	Girls Shower in Locker Room	100	SF	7	10+ years 10+ years	
	Walls - Metal Panel	Girls Shower in Locker Room	46	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Shower in Locker Room	378	SF	6		
				SF	5	10+ years	
	Accessories	Staff Kitchen Laundry Room	171	SF	5 5	6-10 years	
	Ceiling - Splined (Moister Resistance)	Staff Kitchen Laundry Room	171	EA		6-10 years	
	Doors - Wood Doors inclu hw	Staff Kitchen Laundry Room	2		6	6-10 years	
	Floor - Tile/Sheet	Staff Kitchen Laundry Room	171	SF	7	6-10 years	
	Lavatory	Staff Kitchen Laundry Room	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Staff Kitchen Laundry Room	2	EA	6	6-10 years	
	Student Lockers - One Tier	Staff Kitchen Laundry Room	18	EA	6	6-10 years	
	Walls - Concrete Block	Staff Kitchen Laundry Room	431	SF	6	10+ years	
	Water Closet	Staff Kitchen Laundry Room	1	EA	6	6-10 years	
	Accessories	Team Locker Room	353	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Team Locker Room	353	SF	5	0-1 year	Holes/missing pieces.



Category : Room			ب الماني -	Mair	3939 W 79th STREET, Chicago, IL 6065		
Jatego	ry: Koom		В	uilding	: wain	Decement	
	Hom Tune	Location	Quantity	UOM	Rank	Recommend	Commente
Group	Item - Type Doors - Wood Doors inclu hw	Team Locker Room	Quantity	EA	6	Replacement	Comments
		Team Locker Room	=	SF	6 7	10+ years	
	Floor - Tile Ceramic/ Porcelain		353			10+ years	
	Floor Drain	Team Locker Room	1	EA	7	6-10 years	
	Lavatory	Team Locker Room	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Team Locker Room	4	EA	6	6-10 years	
	Showers	Team Locker Room	1	EA	7	6-10 years	
	Student Lockers - One Tier	Team Locker Room	6	EA	7	6-10 years	
	Walls - Concrete Block	Team Locker Room	126	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Team Locker Room	619	SF	6	10+ years	
	Water Closet	Team Locker Room	1	EA	7	6-10 years	
unch &	Multipurpose Room						
	AC Unit	170C Teachers cafeteria	1	EA	7	6-10 years	
	Ceiling - Splined	170C Teachers cafeteria	1,250	SF	6	6-10 years	
	Doors - Steel Doors incl hw	170C Teachers cafeteria	1	EA	6	6-10 years	
	Floor - Tile/Sheet	170C Teachers cafeteria	1,250	SF	5	6-10 years	
	Lighting - Pendent/Surface	170C Teachers cafeteria	<sup>′</sup> 13	EA	7	6-10 years	
	Walls - Concrete Block	170C Teachers cafeteria	1,500	SF	7	10+ years	
	Ceiling - Splined	1st Floor	7,498	SF	7	10+ years	It has been fixed
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	7,473	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	1st Floor	118	EA	6	6-10 years	Damagoa
	Serving Line	1st Floor	6	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	2,016	SF	6	10+ years	
1DF ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Finishes	2nd Floor	50	SF	5	0-1 year	Water damage
	Finishes	2nd Floor	570	SF	5	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split system.
	Window AC Unit	2nd Floor	3	EA	5	6-10 years	
echan	ical/ Service Rooms						
	Boiler Room	1st Floor	820	SF	5	6-10 years	
	Janitor's Closet	1st Floor	37	SF	5	6-10 years	
	Janitor's Closet	1st Floor	25	SF	5	6-10 years	
	Janitor's Closet	1st Floor	25	SF	5	6-10 years	
	Janitor's Closet	1st Floor	87	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	64	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	4	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	30	SF	5	6-10 years	
			30 4	SF	5		
	Mechanical/ Service Rooms	1st Floor	4	35	Э	6-10 years	



Category : Room		В	uilding	: Main			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	29	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	45	SF	5	6-10 years	
	Storage Room	1st Floor	341	SF	5	6-10 years	
	Storage Room	1st Floor	77	SF	5	6-10 years	
	Storage Room	1st Floor	352	SF	5	6-10 years	
	Storage Room	1st Floor	153	SF	5	6-10 years	
	Storage Room	1st Floor	366	SF	5	6-10 years	
	Vaults	1st Floor	106	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	26	SF	5	10+ years	
	Janitor's Closet	2nd Floor	40	SF	5	10+ years	
	Janitor's Closet	2nd Floor	4	SF	5	10+ years	
	Janitor's Closet	2nd Floor	54	SF	5	10+ years	
	Janitor's Closet	2nd Floor	4	SF	5	10+ years	
	Janitor's Closet	2nd Floor	25	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,080	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	4	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	4	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	4	SF	5	10+ years	
	Storage Room	2nd Floor	307	SF	5	10+ years	
	Storage Room	2nd Floor	208	SF	5	10+ years	
	Storage Room	2nd Floor	65	SF	5	10+ years	
	latatorium						
	Accessories	1st Floor	3,996	SF	5	6-10 years	
	Bleachers Seating/Plank Seating	1st Floor	42	EA	6	6-10 years	
	Ceiling - Splined (Moister Resistance)	1st Floor	3,996	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,996	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒA	6	6-10 years	
	Pool Basin	1st Floor	1,917	SF	6	6-10 years	
	Pool Deck Drains	1st Floor	6	EA	5	6-10 years	
	Storage/ Closet	1st Floor	40	SF	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	8,216	SF	6	10+ years	
Prep Ro	om						
	Casework	110A Prep Room	15	LF	6	6-10 years	
	Ceiling - Lay-in	110A Prep Room	175	SF	7	10+ years	
	Ceiling - Lay-in	110A Prep Room	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110A Prep Room	1	EA	7	10+ years	
	Floor - Tile/Sheet	110A Prep Room	205	SF	7	10+ years	
	Lighting - Lay-in	110A Prep Room	203	EA	5	0-1 year	None functioning
	Walls - Concrete Block	110A Prep Room	288	SF	7	10+ years	
	Walls - Plaster/Drywall	110A Prep Room	250	SF	7	10+ years	
	Work Sink	110A Prep Room	200	EA	7	10+ years	
				_/ `	,	io. youro	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	112B Prep Room	15	LF	7	10+ years	
	Ceiling - Splined	112B Prep Room	53	SF	7	10+ years	
	Ceiling - Splined	112B Prep Room	1	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	112B Prep Room	1	EA	7	10+ years	-
	Floor - Tile/Sheet	112B Prep Room	54	SF	7	10+ years	
	Lighting - Pendent/Surface	112B Prep Room	2	EA	7	10+ years	
	Walls - Concrete Block	112B Prep Room	115	SF	7	10+ years	
	Casework	114C Prep Room	15	LF	7	10+ years	
	Ceiling - Splined	114C Prep Room	54	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114C Prep Room	1	EA	7	10+ years	
	Floor - Tile/Sheet	114C Prep Room	54	SF	7	10+ years	
	Lighting - Pendent/Surface	114C Prep Room	2	EA	7	10+ years	
	Walls - Concrete Block	114C Prep Room	115	SF	7	10+ years	
	Work Sink	114C Prep Room	1	EA	7	10+ years	
	Casework	116A Prep Room	15	LF	6	6-10 years	
	Ceiling - Splined	116A Prep Room	54	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	116A Prep Room	1	EA	7	6-10 years	
	Floor - Tile/Sheet	116A Prep Room	54	SF	7	6-10 years	
	Lighting - Pendent/Surface	116A Prep Room	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	116A Prep Room	1	EA	5	0-1 year	Lens damaged
	Walls - Concrete Block	116A Prep Room	115	SF	7	10+ years	C C
	Work Sink	116A Prep Room	1	EA	7	10+ years	
	Casework	117B Prep Room	15	LF	7	10+ years	
	Ceiling - Splined	117B Prep Room	53	SF	7	10+ years	
	Ceiling - Splined	117B Prep Room	1	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	117B Prep Room	1	EA	7	10+ years	
	Floor - Tile	117B Prep Room	54	SF	7	10+ years	
	Lighting - Pendent/Surface	117B Prep Room	1	EA	7	10+ years	
	Walls - Concrete Block	117B Prep Room	115	SF	7	10+ years	
	Casework	119B Prep Room	20	LF	7	10+ years	
	Ceiling - Splined	119B Prep Room	54	SF	7	10+ years	
	Doors - Wood Doors inclu hw	119B Prep Room	1	EA	7	10+ years	
	Floor - Tile	119B Prep Room	54	SF	7	10+ years	
	Lighting - Pendent/Surface	119B Prep Room	1	EA	7	10+ years	
	Walls - Concrete Block	119B Prep Room	115	SF	7	10+ years	
	Casework	121B Prep Room	20	LF	7	10+ years	
	Ceiling - Splined	121B Prep Room	54	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121B Prep Room	1	EA	7	10+ years	
	Floor - Tile/Sheet	121B Prep Room	54	SF	7	10+ years	
	Lighting - Pendent/Surface	121B Prep Room	1	EA	7	10+ years	
	Walls - Concrete Block	121B Prep Room	115	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor Engineer's Restroom	52	SF	5	6-10 years	



Catego	ry : Room		В					
			Building : Main Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor Engineer's Restroom	52	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Engineer's Restroom	1	EA	6	10+ years		
	Floor - Terrazzo	1st Floor Engineer's Restroom	52	SF	6	10+ years		
	Lavatory	1st Floor Engineer's Restroom	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor Engineer's Restroom	1	EA	6	6-10 years		
	Showers	1st Floor Engineer's Restroom	1	EA	5	6-10 years		
	Walls - Plaster/Drywall	1st Floor Engineer's Restroom	50	SF	6	6-10 years		
	Walls - Structural Glazed Tile	1st Floor Engineer's Restroom	50	SF	6	10+ years		
	Water Closet	1st Floor Engineer's Restroom	1	EA	6	6-10 years		
	Accessories	1st Floor Locate in 102G Women	99	SF	7	6-10 years		
		lounge						
	Ceiling - Splined	1st Floor Locate in 102G Women	99	SF	6	10+ years		
		lounge						
	Doors - Wood Doors inclu hw	1st Floor Locate in 102G Women	1	EA	6	10+ years		
		lounge						
	Floor - Terrazzo	1st Floor Locate in 102G Women	99	SF	6	10+ years		
		lounge						
	Lavatory	1st Floor Locate in 102G Women	1	EA	6	6-10 years		
		lounge						
	Lighting - Pendent/Surface	1st Floor Locate in 102G Women	2	EA	6	6-10 years		
		lounge						
	Partitions	1st Floor Locate in 102G Women	1	EA	7	6-10 years		
		lounge						
	Walls - Concrete Block	1st Floor Locate in 102G Women	240	SF	6	10+ years		
		lounge						
	Water Closet	1st Floor Locate in 102G Women	1	EA	6	6-10 years		
		lounge						
	Accessories	2nd Floor Locate in 212C Women	75	SF	7	6-10 years		
		lounge						
	Ceiling - Plaster/Drywall	2nd Floor Locate in 212C Women	75	SF	7	10+ years		
		lounge						
	Doors - Wood Doors inclu hw	2nd Floor Locate in 212C Women	1	EA	6	10+ years		
		lounge						
	Floor - Terrazzo	2nd Floor Locate in 212C Women	75	SF	6	10+ years		
		lounge						
	Lavatory	2nd Floor Locate in 212C Women	2	EA	6	10+ years		
		lounge						
	Lighting - Pendent/Surface	2nd Floor Locate in 212C Women	1	EA	7	10+ years		
		lounge						
	Partitions	2nd Floor Locate in 212C Women	2	EA	5	6-10 years		
		lounge						
	Urinals	2nd Floor Locate in 212C Women	1	EA	6	10+ years		
		lounge				-		
	Walls - Plaster/Drywall	2nd Floor Locate in 212C Women	78	SF	6	10+ years		
						-		



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		lounge					
	Walls - Structural Glazed Tile	2nd Floor Locate in 212C Women	75	SF	6	10+ years	
	Water Classi	lounge 2nd Elear Leaste in 212C Wemen	2		6	10, 10000	
	Water Closet	2nd Floor Locate in 212C Women lounge	2	EA	6	10+ years	
	Accessories	2nd Floor Locate in 212F Men	65	SF	7	6-10 years	
	10000001100	lounge	00	01		o ro youro	
	Ceiling - Plaster/Drywall	2nd Floor Locate in 212F Men	65	SF	7	10+ years	
	0	lounge				,	
	Doors - Wood Doors inclu hw	2nd Floor Locate in 212F Men	1	EA	6	10+ years	
		lounge					
	Floor - Terrazzo	2nd Floor Locate in 212F Men	65	SF	6	10+ years	
	Leveten	lounge	4		0	10	
	Lavatory	2nd Floor Locate in 212F Men	1	EA	6	10+ years	
	Lighting - Pendent/Surface	lounge 2nd Floor Locate in 212F Men	1	EA	7	10+ years	
	Lighting - rendent/Sunace	lounge	I		1	IUT years	
	Partitions	2nd Floor Locate in 212F Men	2	EA	5	6-10 years	
		lounge	_		Ū	e le jeale	
	Urinals	2nd Floor Locate in 212F Men	1	EA	6	10+ years	
		lounge				-	
	Walls - Plaster/Drywall	2nd Floor Locate in 212F Men	63	SF	6	10+ years	
		lounge		~-			
	Walls - Structural Glazed Tile	2nd Floor Locate in 212F Men	63	SF	6	10+ years	
	Water Closet	lounge 2nd Floor Locate in 212F Men	2	EA	6	10	
	Water Closet	lounge	2	EA	0	10+ years	
	Accessories	Boys 118C	296	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Boys 118C	296	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	Boys 118C	1	EA	7	10+ years	
	Floor - Terrazzo	Boys 118C	296	SF	7	10+ years	
	Hand Dryer	Boys 118C	2	EA	7	6-10 years	
	Lavatory	Boys 118C	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys 118C	4	EA	7	10+ years	
	Partitions	Boys 118C	2	EA	7	10+ years	
	Student Lockers - Two Tiers	Boys 118C	3	EA	6	6-10 years	
	Urinals	Boys 118C	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	Boys 118C	685	SF	7	10+ years	
	Water Closet	Boys 118C	2	EA	7	10+ years	
	Accessories	Boys 131A-next to room 131	296	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Boys 131A-next to room 131	296	SF	6	10+ years	
	Floor - Terrazzo	Boys 131A-next to room 131	296	SF	6	10+ years	
	Hand Dryer	Boys 131A-next to room 131	2	ĒA	7	6-10 years	



Category : Room			В				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Boys 131A-next to room 131	4	EA	6	6-10 years	
	Partitions	Boys 131A-next to room 131	1	EA	5	6-10 years	
	Urinals	Boys 131A-next to room 131	4	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Boys 131A-next to room 131	685	SF	6	10+ years	
	Water Closet	Boys 131A-next to room 131	1	EA	6	6-10 years	
	Accessories	Boys 218C	296	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Boys 218C	296	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys 218C	1	EA	6	10+ years	
	Floor - Terrazzo	Boys 218C	296	SF	6	10+ years	
	Hand Dryer	Boys 218C	2	EA	5	6-10 years	
	Lavatory	Boys 218C	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys 218C	4	EA	7	10+ years	
	Partitions	Boys 218C	2	EA	5	6-10 years	
	Urinals	Boys 218C	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	Boys 218C	685	SF	6	10+ years	
	Water Closet	Boys 218C	2	EA	6	10+ years	
	Accessories	Boys 239E	278	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Boys 239E	278	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys 239E	1	EA	6	10+ years	
	Floor - Terrazzo	Boys 239E	278	SF	6	10+ years	
	Lavatory	Boys 239E	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Boys 239E	3	EA	7	10+ years	
	Partitions	Boys 239E	2	EA	5	6-10 years	
	Urinals	Boys 239E	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	Boys 239E	639	SF	6	10+ years	
	Water Closet	Boys 239E	2	EA	6	10+ years	
	Accessories	Girls 118A	296	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 118A	296	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls 118A	1	EA	7	10+ years	
	Floor - Terrazzo	Girls 118A	296	SF	7	10+ years	
	Hand Dryer	Girls 118A	2	EA	7	6-10 years	
	Lavatory	Girls 118A	4	EA	7	10+ years	
	Lighting - Pendent/Surface	Girls 118A	4	EA	7	10+ years	
	Partitions	Girls 118A	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	Girls 118A	685	SF	7	10+ years	
	Water Closet	Girls 118A	5	EA	7	10+ years	
	Accessories	Girls 131B-next to room 131	296	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Girls 131B-next to room 131	296	SF	6	10+ years	
	Floor - Terrazzo	Girls 131B-next to room 131	296	SF	6	10+ years	
	Hand Dryer	Girls 131B-next to room 131	2	ĒA	5	6-10 years	
	Lavatory	Girls 131B-next to room 131	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Girls 131B-next to room 131	4	EA	6	6-10 years	
	Partitions	Girls 131B-next to room 131	4	EA	5	6-10 years	
	Walls - Structural Glazed Tile	Girls 131B-next to room 131	685	SF	6	10+ years	



Catego	ry : Room		Building : Main						
-						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	Girls 131B-next to room 131	4	EA	6	10+ years			
	Accessories	Girls 218A	296	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Girls 218A	296	SF	5	10+ years			
	Doors - Wood Doors inclu hw	Girls 218A	1	EA	6	10+ years			
	Floor - Terrazzo	Girls 218A	296	SF	6	10+ years			
	Hand Dryer	Girls 218A	2	EA	5	6-10 years			
	Lavatory	Girls 218A	4	EA	6	10+ years			
	Lighting - Pendent/Surface	Girls 218A	4	EA	7	10+ years			
	Partitions	Girls 218A	5	EA	5	6-10 years			
	Walls - Structural Glazed Tile	Girls 218A	685	SF	6	10+ years			
	Water Closet	Girls 218A	5	EA	6	10+ years			
	Accessories	Girls 239G	266	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Girls 239G	266	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Girls 239G	200	EA	6	10+ years			
	Floor - Terrazzo	Girls 239G	266	SF		•			
			200 4		6	10+ years			
	Lavatory	Girls 239G	=	EA	6	10+ years			
	Lighting - Pendent/Surface	Girls 239G	4	EA	6	10+ years			
	Partitions	Girls 239G	5	EA	5	6-10 years			
	Walls - Structural Glazed Tile	Girls 239G	685	SF	6	10+ years			
	Water Closet	Girls 239G	5	EA	6	10+ years			
	Accessories	Locate in 105 Asst. Principal Off.	38	SF	7	6-10 years			
	Ceiling - Splined	Locate in 105 Asst. Principal Off.	38	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Locate in 105 Asst. Principal Off.	1	EA	6	10+ years			
	Floor - Terrazzo	Locate in 105 Asst. Principal Off.	38	SF	6	10+ years			
	Lavatory	Locate in 105 Asst. Principal Off.	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Locate in 105 Asst. Principal Off.	2	EA	6	6-10 years			
	Walls - Concrete Block	Locate in 105 Asst. Principal Off.	77	SF	6	10+ years			
	Water Closet	Locate in 105 Asst. Principal Off.	1	EA	6	6-10 years			
	Accessories	Main Office	30	SF	7	6-10 years			
	Ceiling - Splined	Main Office	30	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Main Office	1	ĒA	6	10+ years			
	Floor - Terrazzo	Main Office	30	SF	6	10+ years			
	Lavatory	Main Office	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Main Office	1	EA	6	6-10 years			
	Lighting - Wall Mounted	Main Office	1	EA	6	6-10 years			
	Walls - Concrete Block	Main Office	67	SF	6	10+ years			
	Water Closet	Main Office	1	EA	6				
						6-10 years			
	Accessories	Men's 1134 Staff In Locker Room B101	56	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Men's 1134 Staff In Locker Room B101	56	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Men's 1134 Staff In Locker Room B101	1	EA	6	6-10 years			
	Floor - Terrazzo	Men's 1134 Staff In Locker Room	56	SF	6	10+ years			



Catego	ry : Room		Building : Main							
j-	· · · · · · · · · · · · · · · · · · ·					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		B101	-							
	Floor Drain	Men's 1134 Staff In Locker Room	1	EA	7	6-10 years				
		B101								
	Lavatory	Men's 1134 Staff In Locker Room	1	EA	6	6-10 years				
		B101								
	Lighting - Pendent/Surface	Men's 1134 Staff In Locker Room	1	EA	6	6-10 years				
		B101								
	Partitions	Men's 1134 Staff In Locker Room	1	EA	7	6-10 years				
		B101								
	Walls - Structural Glazed Tile	Men's 1134 Staff In Locker Room	195	SF	6	6-10 years				
		B101			_					
	Water Closet	Men's 1134 Staff In Locker Room	1	EA	6	6-10 years				
	• ·	B101		0-	_					
	Accessories	Men's Staff 108G	98	SF	7	2-5 years				
	Ceiling - Splined	Men's Staff 108G	98	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Men's Staff 108G	1	EA	6	10+ years				
	Floor - Terrazzo	Men's Staff 108G	98	SF	6	10+ years				
	Lavatory	Men's Staff 108G	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	Men's Staff 108G	2	EA EA	6 7	6-10 years				
	Partitions Urinals	Men's Staff 108G Men's Staff 108G	1	EA EA		6-10 years				
	Walls - Concrete Block		145	SF	6 6	6-10 years				
	Water Closet	Men's Staff 108G Men's Staff 108G	145 1	EA	6	10+ years				
	Accessories	Principal's Office	45	SF	7	6-10 years 6-10 years				
	Ceiling - Splined	Principal's Office	45	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Principal's Office	40	EA	6	10+ years				
	Floor - Terrazzo	Principal's Office	45	SF	6	10+ years				
	Lavatory	Principal's Office		EA	6	6-10 years				
	Lighting - Pendent/Surface	Principal's Office	1	EA	6	6-10 years				
	Lighting - Wall Mounted	Principal's Office	1	EA	6	6-10 years				
	Walls - Concrete Block	Principal's Office	97	SF	6	10+ years				
	Water Closet	Principal's Office	1	EA	6	6-10 years				
				<u> </u>	Ŭ	5 10 ,0010				

### Category : Classroom

Building	. Main	
Бинана	: wain	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Science)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	59	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	784	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	241	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,020	SF	7	10+ years	



**Building : Main** Category : Classroom Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Floor - Tile/Sheet SF Cracked around drain 1st Floor 5 4 0-1 year Gas Line 1st Floor 21 ΕA 7 10+ vears Lighting - Lay-in 1st Floor 15 FΑ 7 6-10 years Marker Board 12 LF 1st Floor 6 6-10 years SF Science Lab Elements 1st Floor 1,025 7 6-10 years 7 Science Lab Fume Hood 1st Floor EΑ 6-10 years 1 Science Lab Shower 1st Floor ΕA 7 10+ years 1 SF Storage/ Closet 1st Floor 250 7 6-10 years SF Walls - Concrete Block 1st Floor 291 6 10+ years SF Walls - Plaster/Drvwall 1st Floor 648 6 10+ years Work Sink 1st Floor 9 ΕA 7 10+ years Classroom #112 (Science) AC Units 1st Floor 2 ΕA 7 6-10 years Casework 1st Floor 65 LF 6 10+ years Ceiling - Lay-in 1st Floor 934 SF 6 10+ years Doors - Wood Doors inclu hw 3 ΕA 7 1st Floor 10+ years SF Floor - Tile/Sheet 1st Floor 934 7 10+ years Lighting - Pendent/Surface 7 1st Floor 24 EA 10+ years Marker Board 1st Floor 12 LF 6-10 years 6 SF Science Lab Elements 1st Floor 934 7 10+ years Storage/ Closet 1st Floor 100 SF 7 10+ vears SF Walls - Concrete Block 1st Floor 1.036 6 10+ years Work Sink 1st Floor ΕA 7 4 10+ years Classroom #113 (Computer Lab) AC Units 1st Floor 4 ΕA 7 6-10 years 1st Floor 808 SF 7 Ceiling - Splined 10+ vears Ceiling - Splined 1st Floor 5 SF 4 0-1 vear Hole 20 SF Ceiling - Splined 1st Floor 4 0-1 year Tiles out of place Doors - Wood Doors inclu hw 3 ΕA 7 1st Floor 10+ years SF 7 Floor - Tile/Sheet 1st Floor 833 10+ years Lighting - Pendent/Surface 1st Floor 20 ΕA 7 10+ years Marker Board 1st Floor 22 LF 7 6-10 years Storage/ Closet 1st Floor 63 SF 7 10+ vears SF Walls - Concrete Block 1st Floor 20 7 10+ years Walls - Concrete Block 1st Floor SF 711 6 10+ vears Walls - Metal Panel 1st Floor 360 SF 7 10+ years ΕA 7 Wireless System 1st Floor 1 10+ years Classroom #113E (Special Education) Ceiling - Splined 1st Floor 304 SF 7 10+ years SF Ceiling - Splined 1st Floor 15 4 0-1 year Holes



NOR S	3939 W 79th STREET, Chicago, IL 60652						
Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	300	SF	5	2-5 years	Areas missing
	Floor - Tile/Sheet	1st Floor	19	SF	4	0-1 year	Cracked flooring
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	433	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	240	SF	7	10+ years	
Classroo	om #114 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	461	SF	7	10+ years	
	Ceiling - Splined	1st Floor	4	SF	4	0-1 year	Missing damaged
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years	5 5
	Floor - Tile/Sheet	1st Floor	465	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	ĒA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	568	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒA	4	0-1 year	Poor water pressure
	AC Units Casework Ceiling - Splined Ceiling - Splined Doors - Wood Doors inclu hw Floor - Tile/Sheet Lighting - Pendent/Surface Marker Board Storage/ Closet Student Lockers - Two Tiers	1st Floor 1st Floor	2 18 564 100 3 664 14 14 110 6	EA LF SF EA SF EA LF SF EA	7 6 7 7 7 7 7 7 7	6-10 years 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	Water damage
	Walls - Concrete Block	1st Floor	761	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	120	SF	7	10+ years	
Classroo	om #116 (Science)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Casework	1st Floor	65	LF	4	0-1 year	Counter damaged
	Ceiling - Splined	1st Floor	834	SF	7	10+ years	
	Ceiling - Splined	1st Floor	100	SF	4	0-1 year	Water damage
	Chalk Board	1st Floor	60	LF	4	2-5 years	-
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	884	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	0-1 year	Worn and damaged



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Science Lab Elements	1st Floor	934	SF	7	10+ years	
	Storage/ Closet	1st Floor	100	SF	5	0-1 year	Hole in ceiling
	Walls - Concrete Block	1st Floor	1,036	SF	6	10+ years	C C
	Work Sink	1st Floor	1	EA	5	0-1 year	Excessive water damage from use
lassroc	om #117 (Science)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	65	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	934	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	934	SF	7	10+ years	
	Gas Line	1st Floor	1	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	24	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	934	SF	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,026	SF	6	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	
lassroo	om #119 (Science)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	934	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	934	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	934	SF	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	100	SF	5	2-5 years	One ceiling tile missing.
	Walls - Concrete Block	1st Floor	1,036	SF	7	10+ years	5 5
	Work Sink	1st Floor	5	EA	7	10+ years	
lassroo	om #120 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Splined	1st Floor	634	SF	7	10+ years	
	Ceiling - Splined	1st Floor	30	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	664	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	



**Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 1st Floor 6 ΕA 4 0-1 vear Non operational Marker Board 1st Floor 38 LF 7 6-10 vears Walls - Concrete Block 1st Floor 861 SF 7 10+ years 20 SF Walls - Concrete Block 1st Floor 5 0-1 year Cracking. Classroom #121 (Store Room) AC Units 1st Floor 2 FΑ 7 6-10 years LF 34 Casework 1st Floor 6 10+ years SF Ceiling - Splined 1st Floor 934 6 10+ years LF Chalk Board 1st Floor 12 4 2-5 years Doors - Wood Doors inclu hw ΕA 7 1st Floor 1 10+ years Floor - Tile/Sheet 1st Floor 934 SF 7 10+ years Lighting - Pendent/Surface 1st Floor ΕA 7 10+ years 24 SF Storage/ Closet 1st Floor 100 7 10+ years Walls - Concrete Block 996 SF 7 1st Floor 10+ years Walls - Plaster/Drywall 1st Floor 30 SF 4 0-1 year Water damage, peeling paint, and large crack. Classroom #130 (Regular Classroom) AC Units 1st Floor 2 ΕA 7 6-10 years 20 LF Casework 1st Floor 6 6-10 years Ceiling - Splined SF 1st Floor 659 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years Floor - Tile/Sheet 659 SF 5 6-10 years 1st Floor Lighting - Pendent/Surface 1st Floor 14 ΕA 6 6-10 years Marker Board 1st Floor 18 LF 6 6-10 years SF Walls - Concrete Block 1st Floor 939 6 10+ years 220 SF 6 Walls - Plaster/Drywall 1st Floor 10+ years Classroom #131 (Regular Classroom) AC Units 1st Floor 2 7 EA 6-10 years 8 LF Casework 1st Floor 6 6-10 years Ceiling - Splined 1st Floor 662 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years SF Floor - Tile/Sheet 1st Floor 662 5 2-5 years Lighting - Pendent/Surface 1st Floor 9 ΕA 6 6-10 years Lighting - Pendent/Surface 5 1st Floor EΑ 4 0-1 year Not in operation. Marker Board 1st Floor 36 LF 6 6-10 years Walls - Concrete Block SF 1st Floor 839 6 10+ years Classroom #132 (Computer Lab) AC Units 1st Floor 4 ΕA 7 6-10 years SF Ceiling - Splined 1st Floor 1,243 6 10+ years



3939 W 79th STREET, Chicago, IL 60652 **Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments SF Ceiling - Splined 1st Floor 10 5 0-1 vear Isolated areas with water damage and broken tile. Doors - Wood Doors inclu hw 1st Floor 3 FΑ 6 10+ years Floor - Tile/Sheet SF 5 2-5 years 1st Floor 1.238 SF Floor - Tile/Sheet 1st Floor 15 4 1-2 years Damaged and cracking ΕA 6 6-10 years Lighting - Pendent/Surface 1st Floor 22 Marker Board 1st Floor 30 LF 6 6-10 years LF Marker Board 1st Floor 20 4 1-2 years Markers have stained board SF Storage/ Closet 1st Floor 68 7 6-10 years SF Walls - Concrete Block 1st Floor 1.122 6 10+ years SF Walls - Plaster/Drvwall 1st Floor 149 6 10+ years Classroom #133 (Regular Classroom) AC Units 2 1st Floor ΕA 7 6-10 years Casework 1st Floor 8 LF 6 6-10 vears Ceiling - Splined 1st Floor 662 SF 6 10+ years Doors - Wood Doors inclu hw ΕA 1st Floor 1 6 10+ vears 5 Floor - Tile/Sheet 1st Floor 662 SF 6-10 years Lighting - Pendent/Surface ΕA 1st Floor 14 6 6-10 years Marker Board 1st Floor 36 LF 6 6-10 years SF Walls - Concrete Block 1st Floor 839 6 10+ years Classroom #134 (Regular Classroom) AC Units 1st Floor ΕA 7 1 6-10 years Ceiling - Splined 1st Floor 642 SF 6 10+ years SF Ceiling - Splined 1st Floor 9 0-1 year 4 Missing water damage Doors - Wood Doors inclu hw 1st Floor 1 ΕA 6 10+ years SF 6 Floor - Tile 1st Floor 651 10+ years Lighting - Pendent/Surface 1st Floor 10 FΑ 6 6-10 vears Lighting - Pendent/Surface 1st Floor 10 FΑ 5 0-1 year Did not turn on Marker Board 1 F 6 1st Floor 6 6-10 years SF Walls - Concrete Block 1,119 1st Floor 6 10+ years Work Sink ΕA 7 1st Floor 1 6-10 years Classroom #134A (Regular Classroom) AC Units 1st Floor 1 EΑ 7 6-10 vears 1st Floor 3 LF 6-10 years Casework 6 Ceiling - Splined 1st Floor 646 SF 6 10+ years SF Ceiling - Splined Water damage, missing 1st Floor 5 4 0-1 year Doors - Wood Doors inclu hw ΕA 6 10+ years 1st Floor 1 SF Floor - Tile 1st Floor 651 6 10+ years Lighting - Pendent/Surface 1st Floor 19 EΑ 6 6-10 years LF Marker Board 1st Floor 6 6 6-10 years



William J Bogan High School 3939 W 79th STREET, Chicago, IL 60652

Oatama					Mala		
Catego	ry : Classroom		В	uilding	: Main	December	
<b>O</b>	Ham Tuna	Location	Quentitu	UOM	Dank	Recommend	Commonto
Group	Item - Type Walls - Concrete Block	1st Floor	Quantity	SF	Rank	Replacement	Comments
	Walls - Concrete Block	IST FIOOI	1,119	SF	6	10+ years	
~							
Classroc	om #135 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	662	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	662	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	839	SF	6	10+ years	
Classroo	om #136 (Art Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	83	LF	4	0-1 year	Cabinets worn from use
	Ceiling - Splined	1st Floor	745	SF	6	10+ years	
	Ceiling - Splined	1st Floor	25	SF	4	0-1 year	Water damage and missing
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	3
	Floor - Tile/Sheet	1st Floor	770	SF	5	2-5 years	
	Lighting - Pendent/Surface	1st Floor	36	ĒA	6	6-10 years	
	Storage/ Closet	1st Floor	170	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	809	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	246	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
						,	
Classroo	om #138 (Art Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	1,367	SF	6	10+ years	
	Ceiling - Splined	1st Floor	2	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	1,369	SF	4	0-1 year	Missing and cracked throughout.
	Lighting - Pendent/Surface	1st Floor	39	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Storage/ Closet	1st Floor	31	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,336	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classro	om #139 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	21	LF	6	6-10 years	
	Casework Ceiling - Splined	1st Floor		SF			
	Doors - Wood Doors inclu hw		1,030	-	6	10+ years	
		1st Floor	1 000	EA SF	6 5	10+ years	
	Floor - Tile/Sheet	1st Floor	1,030	эг	Э	2-5 years	



Category : Classroom **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 1st Floor 25 FΑ 6 6-10 vears Marker Board 1st Floor 12 LF 6 6-10 years Walls - Concrete Block 1st Floor 1,108 SF 6 10+ years Classroom #141 (Regular Classroom) AC Units 1st Floor 2 FΑ 7 6-10 vears Casework 1st Floor 8 LF 6 6-10 years SF Ceiling - Splined 1st Floor 1.152 6 10+ years Doors - Wood Doors inclu hw 1st Floor EΑ 6 10+ years 3 SF Floor - Tile 1st Floor 1,152 6 10+ years Lighting - Pendent/Surface ΕA 6 6-10 years 1st Floor 25 Marker Board 1st Floor 20 LF 6 6-10 years Storage/ Closet 1st Floor 40 SF 7 10+ years SF Walls - Concrete Block 1st Floor 1.135 6 10+ years Classroom #142 (Store Room) AC Units 1st Floor ΕA 7 1 6-10 years Ceiling - Lav-in 619 SF 6 10+ years 1st Floor Doors - Wood Doors inclu hw FΑ 1st Floor 6 10+ years 1 Floor - Tile 1st Floor 619 SF 6 10+ years Lighting - Lay-in 1st Floor 10 EΑ 6 6-10 years Marker Board LF 1st Floor 12 6 6-10 years SF Walls - Concrete Block 1st Floor 8 7 10+ years Walls - Concrete Block SF 1st Floor 1,086 6 10+ years Walls - Metal Panel 1st Floor 448 SF 6 10+ years Classroom #143 (Music Room) AC Units 1st Floor 4 ΕA 7 6-10 years Casework 1st Floor 40 LF 5 2-5 years 2,271 SF 1-2 years Ceiling - Splined 1st Floor 4 Missing and loose Doors - Wood Doors inclu hw ΕA 5 10+ years 1st Floor 2 SF 7 Floor - Tile 1st Floor 2,271 6-10 years Lighting - Pendent/Surface FΑ 6 6-10 years 1st Floor 53 Lighting - Pendent/Surface 1st Floor 3 EΑ 5 1-2 years Cracks in cover LF Marker Board 1st Floor 18 6 6-10 years SF Storage/ Closet 1st Floor 200 5 2-5 vears Walls - Concrete Block SF 1st Floor 2,840 6 10+ years Walls - Plaster/Drywall 1st Floor 40 SF 5 0-1 year Water damage present on walls 15 SF 5 Walls - Plaster/Drywall 1st Floor 0-1 year Water damage Classroom #144 (Office) AC Units 1st Floor 1 ΕA 7 6-10 years SF Ceiling - Lay-in 1st Floor 607 6 10+ years



Category : Classroom **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Ceiling - Lay-in 1st Floor 12 SF 4 0-1 vear Missing tiles and water damage Doors - Wood Doors inclu hw 1st Floor ΕA 6 6-10 vears 1 Floor - Tile/Sheet 1st Floor 619 SF 5 6-10 years ΕA 6 Lighting - Lay-in 1st Floor 10 6-10 years Marker Board 1 F 1st Floor 12 6 6-10 years SF Walls - Concrete Block 1st Floor 1,086 6 10+ years Walls - Plaster/Drywall SF 1st Floor 448 6 10+ years Classroom #201 (Regular Classroom) AC Units 2nd Floor 2 ΕA 7 6-10 years Casework 2nd Floor 9 LF 6 10+ years Ceiling - Splined 2nd Floor 664 SF 6 10+ years LF Chalk Board 2nd Floor 8 2-5 years 4 Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile/Sheet 2nd Floor SF 5 664 6-10 years Lighting - Pendent/Surface 2nd Floor 14 FΑ 7 10+ years LF Marker Board 2nd Floor 24 6 6-10 years SF Walls - Concrete Block 2nd Floor 866 6 10+ years Classroom #202 (Regular Classroom) AC Units 2nd Floor 2 ΕA 7 6-10 years LF Casework 2nd Floor 9 6-10 years 6 SF Ceiling - Splined 2nd Floor 664 6 10+ years Doors - Wood Doors inclu hw 6 6-10 years 2nd Floor 1 EA Floor - Tile/Sheet 2nd Floor 664 SF 5 6-10 years Lighting - Pendent/Surface 2nd Floor ΕA 6 6-10 years 14 LF Marker Board 2nd Floor 32 6 6-10 years 2nd Floor SF 6 Walls - Concrete Block 631 10+ years Walls - Concrete Block 2nd Floor 250 SF 5 0-1 vear Damaged Classroom #203 (Regular Classroom) 2nd Floor 2 7 AC Units ΕA 6-10 years Ceiling - Splined 2nd Floor SF 6 10+ years 664 Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years SF 7 Floor - Tile/Sheet 2nd Floor 664 10+ years Lighting - Pendent/Surface 2nd Floor 14 EΑ 7 10+ vears Marker Board LF 2nd Floor 40 6 10+ years Walls - Concrete Block 2nd Floor 866 SF 6 10+ years Classroom #204 (Regular Classroom) 2nd Floor AC Units 2 ΕA 7 6-10 vears Casework 2nd Floor 9 LF 6 6-10 years SF Ceiling - Splined 2nd Floor 664 6 6-10 years



							3939 W 79th STREET, Chicago, IL 60652
Catego	ry : Classroom		В	uilding	: Main	_	
•			0			Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	895	SF	6	10+ years	
Classroo	om #205 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	994	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	994	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	10+ years	
	Marker Board	2nd Floor	23	LA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,049	SF	6		
	Work Sink	2nd Floor	1,049	EA	5	10+ years	
	WORK SINK		I	EA	Э	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	652	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	5
	Floor - Tile/Sheet	2nd Floor	664	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	<u> </u>	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
	Wireless System	2nd Floor	- 10	EA	5	10+ years	
	Work Sink	2nd Floor	1	EA	5	10+ years	
						, , , , , , , , , , , , , , , , , , ,	
Classroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	866	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
		2110 1 1001	004	0	0	IUT years	



ateno	ry : Classroom		P	uilding	• Main		3939 W 79th STREET, Chicago, IL 60
Jaleyo	19.01055100111		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
noup	Doors - Transom Window	2nd Floor	Quantity 1	SF	6	6-10 years	Comments
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	14	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	641	SF	6	•	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	240	SF	6	10+ years 10+ years	
locaroo	m #210 (Computer Lab)					·	
assi00	AC Units	2nd Floor	4	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	4 994	SF	5		
	Doors - Wood Doors inclu hw	2nd Floor		EA		6-10 years	
			2		6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	994	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,049	SF	6	10+ years	
assroo	m #212E (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	654	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	5
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	641	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
lassroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	4	0-1 year	Damaged
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	5
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	652	SF	5	10+ years	
	Floor - Tile/Sheet	2nd Floor	12	SF	4	0-1 year	Chipped and buckled floor tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	44	LA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
			001	36	0	10+ years	
assroo	m #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	7	10+ years	



**Building : Main** Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 2nd Floor 14 ΕA 10+ vears 7 Marker Board 2nd Floor 38 LF 6 6-10 years Walls - Concrete Block 2nd Floor 881 SF 6 10+ years Classroom #216 (Regular Classroom) AC Units 2nd Floor 2 FΑ 7 6-10 years Casework 2nd Floor 9 LF 4 1-2 years Damaged SF 2nd Floor Ceiling - Splined 641 6 10+ years Ceiling - Splined SF 2nd Floor 23 4 0-1 vear Water damage Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile/Sheet 2nd Floor 664 SF 5 6-10 years Lighting - Pendent/Surface 2nd Floor 14 EΑ 7 10+ years Marker Board 2nd Floor 38 LF 6-10 years 6 SF Walls - Concrete Block 2nd Floor 881 6 10+ years Classroom #217 (Store Room) AC Units 2nd Floor 2 ΕA 7 6-10 years Casework 2nd Floor 74 LF 6 10+ years 2nd Floor SF Ceiling - Splined 994 6 10+ years Chalk Board 2nd Floor 36 LF 4 2-5 years 6 Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 10+ years SF 5 Floor - Tile/Sheet 2nd Floor 994 6-10 years Lighting - Pendent/Surface 2nd Floor 19 EΑ 7 10+ years Science Lab Elements 2nd Floor 994 SF 5 2-5 years Storage/ Closet 2nd Floor 80 SF 5 10+ years Walls - Concrete Block 2nd Floor SF 6 1,034 10+ years Work Sink 2nd Floor FΑ 5 6-10 years 1 Classroom #218 (Regular Classroom) AC Units 2nd Floor 2 7 ΕA 6-10 years Casework 2nd Floor 9 LF 6 10+ years SF Ceiling - Splined 2nd Floor 664 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor EΑ 6 6-10 years 1 SF Floor - Tile/Sheet 2nd Floor 664 5 6-10 years ΕA Lighting - Pendent/Surface 2nd Floor 14 6 6-10 years LF Marker Board 2nd Floor 32 6 6-10 years Walls - Concrete Block SF 2nd Floor 881 6 10+ years Classroom #219 (Regular Classroom) AC Units 2nd Floor 2 ΕA 7 6-10 vears LF Casework 2nd Floor 9 6 10+ years Ceiling - Splined 2nd Floor 624 SF 6 10+ years SF Ceiling - Splined 2nd Floor 40 4 0-1 year Chipped



Category : Classroom **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Chalk Board LF 2nd Floor 36 4 2-5 years Doors - Wood Doors inclu hw 2nd Floor ΕA 6 1 10+ years Floor - Tile/Sheet 2nd Floor 654 SF 5 10+ years Floor - Tile/Sheet SF 2nd Floor 10 4 0-1 year Damaged 7 Lighting - Pendent/Surface 2nd Floor 14 EA 10+ years LF Marker Board 32 2nd Floor 6 10+ years Science Lab Elements 2nd Floor 664 SF 5 6-10 years SF Storage/ Closet 2nd Floor 85 5 10+ years 866 SF Walls - Concrete Block 2nd Floor 7 10+ vears Classroom #220 (Regular Classroom) AC Units 2nd Floor 2 EΑ 7 6-10 years Casework 2nd Floor 9 LF 10+ years 6 SF Ceiling - Splined 2nd Floor 664 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor ΕA 6 1 10+ years Floor - Tile/Sheet 2nd Floor 664 SF 5 10+ years FΑ Lighting - Pendent/Surface 2nd Floor 14 6 6-10 years Marker Board 2nd Floor 38 1 F 6 6-10 years SF Walls - Concrete Block 2nd Floor 881 6 10+ years Classroom #221 (Science) AC Units 2nd Floor 2 ΕA 7 6-10 years LF Casework 2nd Floor 169 6 10+ years 2nd Floor 979 SF 10+ years Ceiling - Splined 6 Ceiling - Splined 2nd Floor 15 SF 4 0-1 year Water damage LF Chalk Board 2nd Floor 4 2-5 years 24 Doors - Wood Doors inclu hw 2nd Floor 2 FΑ 6 10+ years 2nd Floor ΕA 6 6-10 vears **Eve Wash Station** 1 Floor - Tile/Sheet 2nd Floor 994 SF 5 6-10 years FΑ Gas Line 2nd Floor 26 6 10+ years Lighting - Pendent/Surface 25 ΕA 7 2nd Floor 10+ years SF 5 Science Lab Elements 2nd Floor 994 6-10 years Science Lab Fume Hood 2nd Floor ΕA 5 6-10 years 4 Science Lab Shower 2nd Floor 1 EΑ 5 6-10 years Storage/ Closet 2nd Floor 170 SF 5 10+ vears SF Walls - Concrete Block 2nd Floor 1.034 6 10+ years Work Sink 2nd Floor ΕA 5 5 10+ years Classroom #222 (Regular Classroom) AC Units 2nd Floor ΕA 7 6-10 years 1 2nd Floor 9 LF Casework 6 10+ years Ceiling - Splined 2nd Floor 664 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 FΑ 6 6-10 years



Category : Classroom **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile/Sheet 2nd Floor 664 SF 4 0-1 vear Damaged Lighting - Pendent/Surface 2nd Floor ΕA 6 6-10 vears 14 Marker Board 2nd Floor 34 LF 6 10+ years Walls - Concrete Block 866 SF 6 2nd Floor 10+ years Classroom #223 (Regular Classroom) AC Units 2nd Floor 1 FΑ 7 6-10 years LF 2nd Floor 9 Casework 6 10+ years SF Ceiling - Splined 2nd Floor 659 6 10+ years SF Ceiling - Splined 2nd Floor 5 4 0-1 year Damaged Doors - Wood Doors inclu hw 2nd Floor 6 1 EΑ 10+ years Floor - Tile/Sheet 2nd Floor 664 SF 5 6-10 years Lighting - Pendent/Surface 2nd Floor ΕA 6 14 10+ years LF Marker Board 2nd Floor 16 6 10+ years Walls - Concrete Block 2nd Floor 874 SF 6 10+ years Classroom #224 (Regular Classroom) AC Units 2nd Floor 7 1 EA 6-10 years 2nd Floor 9 LF Casework 6 10+ years Ceiling - Splined 2nd Floor 664 SF 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years SF Floor - Tile/Sheet 2nd Floor 649 5 10+ years SF Floor - Tile/Sheet 2nd Floor 15 4 0-1 year Damaged Lighting - Pendent/Surface 2nd Floor ΕA 6 14 10+ years Marker Board 2nd Floor 34 LF 6 10+ years SF Walls - Concrete Block 2nd Floor 866 6 10+ years Classroom #225 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 9 LF 6 10+ years Ceiling - Splined SF 6 2nd Floor 664 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 6 10+ years Floor - Tile/Sheet 2nd Floor 664 SF 7 6-10 years Lighting - Pendent/Surface 2nd Floor 14 FΑ 6 10+ years LF Marker Board 2nd Floor 16 4 0-1 year Chipped SF Walls - Concrete Block 2nd Floor 866 6 10+ vears Classroom #226 (Regular Classroom) AC Units 2nd Floor ΕA 7 6-10 years 1 2nd Floor 9 LF Casework 6 6-10 vears SF Ceiling - Splined 2nd Floor 664 6 6-10 vears Doors - Wood Doors inclu hw 2nd Floor ΕA 6 6-10 years 1 Floor - Tile/Sheet SF 5 2nd Floor 664 6-10 years



Catego	ry : Classroom		B	uilding	: Main		
- 30						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	866	SF	6	10+ years	
						,	
Classroo	om #227 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	16	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	866	SF	6	10+ years	
	Walls - Concrete Block		000	36	0	10+ years	
Classroo	om #228 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	34	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	866	SF	6	10+ years	
				-	-	,	
Classroo	om #229 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	614	SF	5	6-10 years	
	Floor - Tile/Sheet	2nd Floor	50	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	10+ years	
	Marker Board	2nd Floor	32	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	866	SF	6	10+ years	
						2	
Classroo	om #230 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	649	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	15	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
		Out of Electric	004	0	~	40.	
	Floor - Tile/Sheet	2nd Floor 2nd Floor	664	SF	5	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	641	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	240	SF	6	6-10 years	
			210	0.	Ū	e le yeare	
lassroc	om #231 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	32	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
				•	Ū	let jeare	
lassroc	om #232 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
lassroc	om #233 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	Water damage has been fixed
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	5
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
lassror	om #234 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	664	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	004 14	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	32		6	•	
		2nd Floor 2nd Floor	32 881	SF	6	6-10 years	
	Walls - Concrete Block		881	ЪГ	O	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<b>.</b> .							
Classroo	m #235 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
Classroo	m #236 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	32	LF	6	2-5 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
Classroo	m #237 (Regular Classroom)						
51255100	AC Units	2nd Floor	2	E۸	7	6 10 vooro	
		2nd Floor 2nd Floor	2 9	EA LF	7 6	6-10 years	
	Casework			SF		10+ years	
	Ceiling - Splined	2nd Floor	664		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	881	SF	6	10+ years	
Classroo	m #238 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	664	SF	6	6-10 years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	664	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
					~		
	Marker Board	2nd Floor	32	LF	6	6-10 years	



**Building : Main Category : Classroom** Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Classroom #239 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Ceiling - Lay-in 2nd Floor 1,002 SF 6 10+ years Ceiling - Lay-in 2nd Floor SF 4 0-1 year Cracking ceiling tiles 16 Doors - Wood Doors inclu hw 2nd Floor 3 ΕA 6 10+ years Floor - Tile/Sheet 2nd Floor SF 5 1.018 6-10 years Lighting - Lay-in 2nd Floor 21 EΑ 7 10+ years LF Marker Board 2nd Floor 6 6 6-10 years SF Storage/ Closet 2nd Floor 16 5 10+ years Walls - Concrete Block SF 2nd Floor 1,250 6 10+ years Classroom #244 (Special Education) AC Units 2nd Floor 1 ΕA 7 6-10 years LF Casework 2nd Floor 9 6 10+ years Ceiling - Splined 2nd Floor 200 SF 6 10+ years Ceiling - Splined 2nd Floor 119 SF 4 0-1 year Water damage Doors - Wood Doors inclu hw 2nd Floor ΕA 6 1 10+ years Floor - Tile 2nd Floor 319 SF 6 10+ years 2nd Floor ΕA 7 10+ years Lighting - Pendent/Surface 9 Marker Board 2nd Floor 9 LF 6 6-10 years SF Walls - Concrete Block 2nd Floor 430 6 10+ years SF 5 Walls - Concrete Block 2nd Floor 10 0-1 year Cracked wall SF Walls - Plaster/Drywall 2nd Floor 240 6 10+ years

#### **Category : Interior**

J	•			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Kem - Type	Location	Quantity		ιτατικ	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	15	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	23,616	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	311	SF	6	10+ years	
	Ceiling - Splined	1st Floor	471	SF	6	10+ years	
	Doors - Side-lite	1st Floor	84	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	6	10+ years	
	Doors - Transom Window	1st Floor	104	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	10	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	5	EA	5	2-5 years	
	Floor - Tile/Sheet	1st Floor	24,022	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	391	SF	4	0-1 year	Scratches/ cracking breaking loose at
						,	entrance
	Lighting - Pendent/Surface	1st Floor	222	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	945	EA	6	6-10 years	

**Building : Main** 



Category : Interior **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Walls - Concrete Block 1st Floor 21.407 SF 6 10+ years 1st Floor 632 SF 6 Walls - Masonry 10+ years Walls - Masonry 1st Floor 60 SF 5 0-1 year Masonry wall has significant cracking Walls - Metal Panel SF 6 1st Floor 2,108 10+ years SF Ceiling - Lay-in 2nd Floor 13,011 6 10+ years ΕA 5 Drinking Fountains - Single Fountain 2nd Floor 2 6-10 years Drinking Fountains - Single Water Cooler 2nd Floor ΕA 5 6-10 years 2 SF Floor - Tile/Sheet 2nd Floor 13.011 5 6-10 years Lighting - Lay-in 2nd Floor 212 ΕA 7 10+ years Student Lockers - One Tier 2nd Floor 1.590 FΑ 6 10+ years Walls - Concrete Block 2nd Floor 16.273 SF 6 10+ years Safety Camera Viewing Station Entire Building 3 ΕA 5 6-10 years 3 ΕA 5 Metal Detector Entire Building 6-10 vears Security Cameras Entire Building 38 FΑ 5 6-10 years ΕA Security Cameras Entire Building 11 5 6-10 years Stairs Ceiling - Splined 404 SF 6 10+ years Stair 1 Floor - Concrete SF Stair 1 100 5 10+ years SF Floor - Tile Stair 1 172 6 6-10 years LF Handrails Stair 1 36 5 10+ years Lighting - Pendent/Surface 2 ΕA 7 6-10 years Stair 1 Stairs - Concrete Stair 1 18 LF 6 10+ years Walls - Concrete Block SF 6 Stair 1 1,239 10+ years SF Ceiling - Splined Stair 2 574 6 6-10 years Floor - Asphalt SF 6 Stair 2 100 10+ years Floor - Tile Stair 2 342 SF 6 6-10 years LF Handrails Stair 2 36 5 10+ years Lighting - Pendent/Surface 2 ΕA 7 Stair 2 6-10 years LF Stairs - Asphalt Stair 2 18 6 10+ years Walls - Concrete Block SF 6 Stair 2 110 10+ years Walls - Concrete Block Stair 2 1,449 SF 6 10+ years Ceiling - Splined Stair 3 430 SF 6 6-10 years SF Floor - Concrete 100 5 Stair treads have minor deterioration Stair 3 0-1 year and finish cracking Floor - Tile Stair 3 198 SF 6 6-10 years 36 LF 7 10+ years Handrails Stair 3 7 Lighting - Pendent/Surface Stair 3 2 EΑ 10+ years LF Stairs - Asphalt Stair 3 18 6 10+ years Walls - Concrete Block 1,202 SF 6 10+ years Stair 3 SF Ceiling - Splined Stair 4 430 6 10+ years Floor - Concrete Stair 4 100 SF 7 10+ years



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Stair 4	198	SF	6	6-10 years	
	Handrails	Stair 4	36	LF	5	10+ years	
	Lighting - Pendent/Surface	Stair 4	2	EA	7	6-10 years	
	Stairs - Asphalt	Stair 4	18	LF	6	10+ years	
	Walls - Concrete Block	Stair 4	1,321	SF	6	10+ years	
	Ceiling - Splined	Stair 5	686	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Stair 5	601	SF	5	0-1 year	Stair treads are cracking and
						-	deteriorating
	Handrails	Stair 5	56	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 5	2	EA	6	10+ years	
	Stairs - Concrete	Stair 5	18	LF	6	10+ years	
	Walls - Concrete Block	Stair 5	1,428	SF	6	10+ years	
	Ceiling - Splined	Stair 6	430	SF	6	10+ years	
	Floor - Concrete	Stair 6	996	SF	5	10+ years	
	Floor - Tile	Stair 6	200	SF	7	6-10 years	
	Handrails	Stair 6	40	LF	5	10+ years	
	Lighting - Pendent/Surface	Stair 6	2	EA	7	6-10 years	
	Stairs - Asphalt	Stair 6	18	LF	5	10+ years	
	Walls - Concrete Block	Stair 6	1,321	SF	5	0-1 year	Water damage
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Driver	Ed Modular	
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	Classroom	1	EA	6	6-10 years	
	Exterior Stairs - Steel or Aluminum	Classroom	12	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Classroom	6	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Office	1	EA	6	6-10 years	
	Exterior Stairs - Steel or Aluminum	Office	12	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Office	6	LF	6	6-10 years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	0-1 year	Missing lenses
Roof Sys	stem						
	Roof - Metal	Main Roof	800	SF	5	2-5 years	No roof access. Condition assumed based on building age
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	800	SF	6	6-10 years	Not exposed
Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,230	SF	4	1-2 years	Rusted, damaged
Windows	3						
	Guard - Guards perforated	North Façade	12	SF	6	6-10 years	
	Windows - Casement Aluminum	North Façade	12	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Driver	Ed Modular	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
-	Security System - CCTV	Entire Building	800	SF	3	0-1 year	Due to deferred replacement of an obsolete system, it is comprised of least 22-year-old equipment and is nonfunctional with no source for repair parts. Rank, Reason and Priority Rep changed based on current observations and per detail
	Security System - Intrusion Detection	Entire Building	800	SF	3	0-1 year	review with Building Engineer. Due to deferred replacement of an obsolete system, it is comprised of least 22-year-old equipment and is nonfunctional with no source for



## William J Bogan High School 3939 W 79th STREET, Chicago, IL 60652

Cotogo	ry : Electrical			Juilding		Ed Modulor	3939 W 7911 STREET, Chicago, 12 00052
Calego	ry . Electrical			sunang	. Driver	Ed Modular Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cloup	Exit Signs - Multipurpose Room	Multipurpose Room	2		6	6-10 years	repair parts. Rank, Reason and Priority Rep changed based on current observations and per detailed review with Building Engineer. Successful physical testing by the Building Engineer at the time of assessment indicates that the Exit Signs are not in poor condition; they are older equipment but are fully operational and properly illuminated. Rank, Reason and Priority Rep
	Emergency Battery Packs - Multipurpose Room	Multipurpose Room	2	EA	6	6-10 years	changed accordingly.
Main Se	rvice						
	Main Electrical Service - 800 A and Less than 120/240/3PH	Site - East	1	EA	4	2-5 years	The panel is post-mounted exterior to the building and is continually subject to adverse weather conditions. There are signs of corrosion and deterioration of the enclosure, however the functionality and safety of the equipment inside the enclosure is such that it is not in question. Due to the age of the panel and the condition of the enclosure, it can be determined to be at the end of its anticipated service life. Rank, Reason and Priority Rep changed to more accurately reflect its condition at the time of assessment. Location changed to match current observations.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Multipurpose Room	1	EA	7	10+ years	
Catego	ry : Mechanical		E	Building	: Driver	Ed Modular	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>    l'empera</u>	ature Control Electric Thermostat	Multinumono Doom		۲^	6	6 10 20070	
		Multipurpose Room	1	EA	6	6-10 years	



# William J Bogan High School 3939 W 79th STREET, Chicago, IL 60652

	on due to weather ent that its integrity Unit is well- ully operational for cooling.
Unit Ventilation    Image: Contained Cooling    East Building Exterior    1    EA    6    6-10 years    Exterior of the un minor deterioration but not to the extrine compromised.      Ventilation    Image: Contained Cooling    Extract Fans- Indoor - Less than 500 CFM Extract Stars Building    1    EA    6    6-10 years    Extract of the un minor deterioration but not to the extrine score compromised.      Ventilation    Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - Less than 500 CFM    Entire Building    1    EA    6    6-10 years    Unit is severely contained and fn both heating and both heating and foot the cur unit and, by defining 500 CFM      Category : Room    Entire Building    1    EA    6    6-10 years    Unit is severely contact.      Category : Room    Eucation    Quantity    UOM    Rank    Replacement    Comments      Administrative Suites/Offices    Item - Type    Location    1    EA    7    6-10 years    Comments      Additing - Plaster/Drywall    1st Floor    1    EA    7    6-10 years    Carpet worn and Lighting - Plendent/Surface    1st Floor    185    SF    6    2-5 years    Carpet worn and Lighting - Pendent/Surface    1st Floor	on due to weather ent that its integrity Unit is well- ully operational for cooling. orroded and prity Rep adjusted
Unit Ventilators - Vertical Package Electric Heat & Self Contained CoolingEast Building Exterior1EA66-10 yearsExterior of the un minor deterioratio but not to the ext is compromised. maintained and fi both heating andVentilation	on due to weather ent that its integrity Unit is well- ully operational for cooling. orroded and prity Rep adjusted
Heat & Self Contained Coolingminor deterioratic but not to the extu is compromised. maintained and fr both heating andVentilationExhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - Less than 500 CFMEntire Building1EA66-10 years 0.1 yearUnit is severely c deteriorated. Pric based on the curi unit and, by deteriorated. Pric based on the curi nonfunctional.Category : RoomBuilding : Driver Ed ModularRecommend ReplacementCommentsGroupItem - TypeLocationQuantityUOM RankReplacement ReplacementCommentsAdministrative Suites/OfficesIter Floor1EA76-10 yearsCommentsAdding : Plaster/Drywall1st Floor1EA76-10 yearsCorportsGood Doors inclu hw1st Floor1EA66-10 yearsCarpet worn andLighting - Pendent/Surface1st Floor185SF62-5 yearsCarpet worn andDoors - Wood Doors inclu hw1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor185SF41-2 yearsCarpet worn andDighting - Power Distribution1st Floor18SF76-10 yearsCarpet worn andStorage/Closet1st Floor18SF76-10 yearsCarpet worn and	on due to weather ent that its integrity Unit is well- ully operational for cooling. orroded and prity Rep adjusted
Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - Less than 500 CFMEntire Building1EA66-10 years 0-1 yearUnit is severely of deteriorated. Price based on the curn unit and, by defin nonfunctional.Category : RoomBuilding : Driver Ed ModularGroupItem - TypeLocationQuantityVOMRankRecommend ReplacementCommentsAdministrative Suites/OfficesAC Unit1 st Floor1EA76-10 yearsCommentsAdministrative Suites/OfficesSF62-5 yearsCarpet worn and Lighting - Pendent/Surface1 st Floor185SF62-5 yearsCarpet worn and Lighting - Pendent/SurfaceCarpet worn and Ist Floor185SF41-2 yearsCarpet worn and Lighting - Pendent/SurfaceUighting - Pendent/Surface1 st Floor4EA66-10 yearsCarpet worn and Lighting - Pendent/Surface1 st Floor18SF76-10 yearsPower Distribution1 st Floor18SF76-10 yearsCarpet worn and Lighting - Pendent/Surface1 st Floor18SF76-10 yearsPower Distribution1 st Floor18SF76-10 yearsCarpet worn and Lighting - Pendent/Surface1 st Floor18SF76-10 yearsStorage/Closet1 st Floor18SF76-10 yearsCarpet worn and Lighting - Pendent/Surface1 st Floor18SF76-10 years<	ority Rep adjusted
Exhaust Fans- Roof Mounted - Less than 500 CFMEntire Building1EA30-1 year vearUnit is severely c deteriorated. Price based on the current unit and, by defin nonfunctional.Category : RoomBuilding : DriverEd ModularGroupItem - TypeLocationQuantityUOM RankRank ReplacementRecommend ReplacementAdministrative Suites/OfficesAC Unit1 st Floor1EA76-10 yearsAdministrative Suites/Offices1EA76-10 yearsCommentsAdministrative Suites/Offices1EA76-10 yearsCarpet worn and Lighting - Plaster/Drywall1st Floor1EA76-10 yearsCarpet worn and Lighting - Pendent/Surface1st Floor185SF41-2 yearsCarpet worn and Lighting - Pendent/SurfaceCarpet1st Floor12EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsCarpet worn and Lighting - Pendent/Surface1st Floor12EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsCarpet worn and Lighting - For - Carpet1st Floor18SF76-10 years	ority Rep adjusted
GroupItem - TypeLocationQuantityUOMRankRecommend ReplacementCommentsAdministrative Suites/OfficesAC Unit1st Floor1EA76-10 yearsAC Unit1st Floor185SF62-5 yearsDoors - Wood Doors inclu hw1st Floor3EA62-5 yearsFloor - Carpet1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	ition, because it is
GroupItem - TypeLocationQuantityUOMRankRecommend ReplacementComments_Administrative Suites/Offices	
Administrative Suites/OfficesAC Unit1st FloorCeiling - Plaster/Drywall1st FloorDoors - Wood Doors inclu hw1st Floor1st Floor185SF62-5 yearsFloor - Carpet1st FloorLighting - Pendent/Surface1st FloorPower Distribution1st FloorStorage/Closet1st Floor1st Floor18SF76-10 years66-10 years76-10 years85576-10 years	
AC Unit1st Floor1EA76-10 yearsCeiling - Plaster/Drywall1st Floor185SF62-5 yearsDoors - Wood Doors inclu hw1st Floor3EA62-5 yearsFloor - Carpet1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/Closet1st Floor18SF76-10 years	
Ceiling - Plaster/Drywall1st Floor185SF62-5 yearsDoors - Wood Doors inclu hw1st Floor3EA62-5 yearsFloor - Carpet1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	
Doors - Wood Doors inclu hw1st Floor3EA62-5 yearsFloor - Carpet1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	
Floor - Carpet1st Floor185SF41-2 yearsCarpet worn andLighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	
Lighting - Pendent/Surface1st Floor4EA66-10 yearsPower Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	
Power Distribution1st Floor12EA66-10 yearsStorage/ Closet1st Floor18SF76-10 years	torn
Storage/ Closet 1st Floor 18 SF 7 6-10 years	
Walls - Vinyl Coated Gypsum Panel1st Floor390SF66-10 years	
Category : Classroom Building : Driver Ed Modular	
Recommend	
Group Item - Type Location Quantity UOM Rank Replacement Comments	
Classroom #1 (Other Instructional Use)	
Ceiling - Plaster/Drywall 1st Floor 615 SF 7 6-10 years	
Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years	
Doors - Wood Doors inclu hw 1st Floor 1 EA 6 6-10 years	
Floor - Carpet 1st Floor 615 SF 4 0-1 year Worn	
Lighting - Pendent/Surface 1st Floor 11 EA 6 6-10 years	
Walls - Vinyl Coated Gypsum Panel 1st Floor 1,230 SF 6 6-10 years	
Category : Interior Building : Driver Ed Modular	
Group Item - Type Location Quantity UOM Rank Recommend Comments	



						3939 W 79th STREET, Chicago, IL 00052
					Replacement	
Safety						
Camera Viewing Station	1st Floor	1	EA	5	1-2 years	Informed that security system is not working as needed
Security Cameras	1st Floor	2	EA	5	1-2 years	Informed cameras are not working as needed



Category : Site		В	uilding	: Site	D		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Civil/Dra			,				
	Civil/ Drainage - Catch Basin	Drivers Education	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Drivers Education	1	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	17	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	5	6-10 years	Sunken
	Civil/ Drainage - Site Manhole	Entire Site	25	EA	6	10+ years	
Fencina							
	Fencing - Chain Link	Drivers Education	105	LF	6	6-10 years	
	Fencing - Guard Rail	Drivers Education	375	LF	6	10+ years	
	Fencing - New Standard Ornamental	Drivers Education	910	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Drivers Education	405	LF	6	6-10 years	Combined quantities
	Fencing - Guard Rail	Entire Site	590	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	2,262	LF	6	10+ years	Recombined quantities
	Fencing - New Standard Ornamental	Entire Site	10	LF	4	0-1 year	Heavy rust, rusted through top caps
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	595	LF	6	6-10 years	
Landsca	pe						
	Benches	Entire Site	13	EA	6	6-10 years	
	Landscape - Grass	Entire Site	55,438	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	16,573	SF	6	6-10 years	
	Landscape - Mulch	Entire Site	3,500	SF	6	6-10 years	
	Lighting - Pole Mounted	Entire Site	5	EA	7	6-10 years	
	Parkway trees	Entire Site	35	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	506	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	347	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	85	SF	6	10+ years	Recombined quantities
	Trash Receptacles	Entire Site	4	EA	6	6-10 years	
Parking	Lot						
0	Concrete Curbs	Drivers Education and East Lot	450	LF	7	10+ years	Not previously assessed
	EV Charge Station	Drivers Education and East Lot	1	EA	7	6-10 years	. ,
	Surface - Asphalt	Drivers Education and East Lot	57,300	SF	4	0-1 year	Recalculated quantity. Cracking throughout.
	EV Charge Station	Northeast	1	EA	7	10+ years	
	Lighting - Lighting	Northeast	6	EA	6	2-5 years	
	Surface - Asphalt	Northeast	27,400	SF	4	0-1 year	Recalculated quantity. Potholes and raveling throughout
	Surface - Concrete	Northeast	1,800	SF	7	10+ years	<u> </u>
	Trash Compactor	Northeast	1	EA	6	10+ years	
	Surface - Asphalt	Southeast	8,600	SF	4	0-1 year	Cracking throughout and uneven.



Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	480	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	24,655	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	20	SF	4	0-1 year	Heaved, sunken and cracked sections
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated ٠
- ٠ Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



### Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	1st Floor	136	136	770	126	36	N	N
Art Room	Art Room	1st Floor	138	138	1,369	23	18	N	N
Computer Lab	Computer Lab	1st Floor	132	132	1,253	84	82	N	N
Computer Lab	Computer Lab	2nd Floor	205	205	994	110	50	N	N
Computer Lab	Computer Lab	2nd Floor	210	210	994	110	50	N	N
Computer Lab	Regular Classroom	1st Floor	113	113	833	30	10	N	N
Music Room	Music Room	1st Floor	143	143	2,271	320	40	N	N
Office	Regular Classroom	1st Floor	144	144	619	17	6	N	Y
Other Instructional Use	Other Instructional Use	1st Floor	114	114	465	40	20	N	Y
Regular Classroom	Art Room	1st Floor	134	134	651	36	13	N	N
Regular Classroom	Art Room	1st Floor	134A	134A	651	42	18	N	N
Regular Classroom	Choral Room	1st Floor	141	141	1,152	84	36	N	N
Regular Classroom	Computer Lab	2nd Floor	208	208	664	70	40	N	N
Regular Classroom	Other Instructional Use	2nd Floor	238	238	664	80	40	N	N
Regular Classroom	Other Instructional Use	2nd Floor	239	239	1,018	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	115	115	664	80	40	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	664	80	40	N	N
Regular Classroom	Regular Classroom	1st Floor	130	130	659	84	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	131	131	662	84	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	133	133	662	84	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	135	135	662	84	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	139	139	1,030	84	35	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	664	70	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	664	70	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	664	70	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	212E	212E	664	70	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	664	80	40	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	219	219	664	80	40	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	220	220	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	222	664	80	40	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	223	223	664	70	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	664	70	30	N	N



### **Classroom Summary**

Ourseast Hanna		Describer	Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	225	225	664	70	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	664	70	30	N	I
Regular Classroom	Regular Classroom	2nd Floor	227	227	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	664	75	35	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	230	230	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	231	231	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	232	232	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	234	234	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	235	235	664	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	236	236	664	80	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	237	237	664	80	40	N	N
Science	Science	1st Floor	110	110	1,025	70	30	N	N
Science	Science	1st Floor	112	112	934	70	30	N	N
Science	Science	1st Floor	116	116	934	70	30	N	N
Science	Science	1st Floor	117	117	934	70	30	N	N
Science	Science	1st Floor	119	119	934	70	30	N	N
Science	Science	2nd Floor	221	221	994	105	45	N	N
Special Education	Special Education	1st Floor	113E	113E	319	40	20	N	N
Special Education	Special Education	2nd Floor	244	244	319	40	20	N	Ν
Store Room	Regular Classroom	1st Floor	142	142	619	17	6	N	N
Store Room	Science	1st Floor	121	121	934	70	30	N	N
Store Room	Science	2nd Floor	217	217	994	120	60	N	Ν
Building : Driver Ed Modula	ar								
Other Instructional Use	Other Instructional Use	1st Floor	1	1	615	0	0	N	Ν