

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1919	2	24,650
Addition 1	1995	1	3,080
Addition 2	2000	3	53,000
Campus Total			80,730

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior FRP Door	2 W	2	EA	6	10+ years	
	Exterior Doors - Side lite	2 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	2 W	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 W	2	EA	6	10+ years	
	Exterior Doors - Side lite	6 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6 W	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	7 W	2	EA	6	10+ years	
	Exterior Doors - Side lite	7 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	7 W	3	EA	6	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	460	LF	7	10+ years	
	Foundation - Concrete	Entire Building	80	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	24,650	SF	7	10+ years	
_Liahtina							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	
_Roof Sys	stem						



Catego	ry : Exterior		B	Building : Main			
	<b>,</b>		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Chimney - Brick Chimney- Concrete/ Mortar	2	38	LF	6	10+ years	
	Liner					•	
	Coping - Clay Tile	2	103	LF	6	10+ years	
	Coping - Metal	2	200	LF	7	10+ years	
	Coping - Metal	2	520	LF	6	10+ years	
	Downspouts - Exterior Downspouts	2	340	LF	6	10+ years	
	Parapet - 16" - 30" Height	2	623	LF	6	10+ years	
	Roof - Modified Bitumen	2	9,950	SF	5	0-1 year	Ponding throughout, poor drainage No safe access, no fixed ladder
	Roof Hatch - Metal	2	1	EA	5	10+ years	
	Roof Structure - Heavy Timber	2	9,950	SF	7	10+ years	
	Coping - Stone	3	34	LF	6	10+ years	
	Downspouts - Exterior Downspouts	3	50	LF	6	10+ years	
	Parapet - Parapet < 16" Height	3	34	LF	6	10+ years	
	Roof - Modified Bitumen	3	630	SF	5	0-1 year	Ponding
	Roof Structure - Heavy Timber	3	630	SF	7	10+ years	
	Coping - Stone	5	34	LF	6	10+ years	
	Downspouts - Exterior Downspouts	5	50	LF	6	10+ years	
	Parapet - Parapet < 16" Height	5	34	LF	6	10+ years	
	Roof - Modified Bitumen	5	615	SF	5	0-1 year	Ponding
	Roof Structure - Heavy Timber	5	615	SF	7	10+ years	
/alls							
	Exterior Walls - Brick	Entire Building	12,525	SF	6	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	275	SF	6	6-10 years	
indows							
	Guard - Guards perforated	Entire Building	485	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	96	SF	6	10+ years	
	Lintels - Steel	Entire Building	514	LF	6	10+ years	
	Windows - Decorative	Entire Building	96	SF	4	0-1 year	Cracks
	Windows - Sash Aluminum Double-pane	Entire Building	4,670	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
meraer	cv Svstem						
-	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EΑ	6	6-10 years	Rank, Reason and Priority Rep
			·		-	3 . <b> ,</b>	adjusted as signs have been
							upgraded since previous assessme
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
		Entire Building					Oughtity shanged as total has been
	Emergency Battery Packs - Corridors and	Entire building	12	EA	6	6-10 years	Quantity changed as total has beer



	SCNOOIS		_			3825	S Washtenaw AVENUE, Chicago, IL 60632
Catego	ry : Electrical		В	uilding	: Main		
Croun	Item - Type	Location	Ouantitu	ПОМ	Donk	Recommend Replacement	Comments
Group	Stairs	Location	Quantity	UOM	Rank	Replacement	Comments divided/aggregated.
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,352	SF	6	6-10 years	uivided/aggregated.
	Security System - CCTV	Entire Building	24,650	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	24,650	SF	6	6-10 years	
_Main Se							
	Main Electrical Service - 2000 A 120/208/3PH	Basement	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	24,650	SF	6	6-10 years	Served from Addition 2. Rank, Reason and Priority Rep changed as the system has been restored since previous assessment.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	Unable to open the panel at the time of assessment. Condition verified by
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	the Building Engineer. Missing door which does not present a risk of shock or fire; missing directory.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	Quantity changed based on current observations and per review with Building Engineer.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	Quantity changed based on current observations and per review with Building Engineer.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	Dulluling Engineer.
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	24,650	SF	4	2-5 years	Served by Addition 2. System is functional and passes inspection. Rank, Reason and Priority Rep adjusted as the system is 23 years old and has reached the end of its EUL.
	Fire Alarm_System	Entire Building	24,650	SF	4	2-5 years	Served by Addition 2. System is functional and passes inspection.



**Building: Main Category : Fire Protection** Recommend Quantity UOM Rank Comments Item - Type Location Replacement Group Rank, Reason and Priority Rep

adjusted as the system is 23 years old and has reached the end of its EUL.

Category : Mechanical **Building: Main** 

	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler S							
- <b></b>	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP	Basement	2	EA	5	6-10 years	
	Chemical Feed System	Basement	1	EA	6	10+ years	
	Combustion Dampers	Basement	2	EA	6	6-10 years	
	Feed Water Pumps and Tank	Basement	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Basement	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Basement	1	EA	5	6-10 years	No dataplate present.
	Piping - Condensate Pipe- Steel	Basement	400	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Basement	400	LF	5	6-10 years	
	Steam Traps	Basement	54	EA	5	6-10 years	Radiators have steam traps; no radiator leaks observed at the time of assessment.
Heating	Devices						
J	Radiators - Steam	Entire Building	54	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.
	Unit Heater - Steam	Entire Building	2	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	Quantity changed based on current observations.
Tempera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Located in the north student restroom. Rank, Reason and Priority Rep changed as the thermostat was replaced since previous assessment.
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Control boiler valves for radiators throughout Main; located in Rooms 227 and 101
Ventilation	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	5	2-5 years	Location changed for clarification. Not directly accessible in a safe



#### Brighton Park Elementary School 3825 S Washtenaw AVENUE, Chicago, IL 60632

Catoria	ry · Machanical		D	uildina	· Main	3023	O Washichaw AVENOE, Officago, ie 00002
Catego	ry : Mechanical		В	uilding	. Widili	Docommond	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	пеш - туре	Location	Quantity	OOM	Kank	Replacement	manner at the time of assessment due to unreliable climbing means. Condition verified by Building Engineer. Documented in previous assessment as being beyond service life with no new observations.
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	24,650	SF	6	6-10 years	
	(Horizontal Lines)				_		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	24,650	SF	6	6-10 years	
	(Risers)	Entire Duilding	24 560	C.E.	6	6.10 40000	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	24,560	SF	6	6-10 years	
	Sanitary Piping	Entire Building	24,650	SF	5	6-10 years	
	Storm Piping	Entire Building	24,650	SF	5	10+ years	
	Vent Piping	Entire Building	24,650	SF	5	10+ years	
		g	,	-	•	, , , , , , , , , , , , , , , , , , , ,	
Pumps							
	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years	
						•	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	102 - Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	102 - Teacher's Lounge	350	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102 - Teacher's Lounge	2	EA	6	10+ years	
	Floor - Tile	102 - Teacher's Lounge	345	SF	7	10+ years	
	Floor - Tile	102 - Teacher's Lounge	5	SF	4	0-1 year	Damaged tile
	Lighting - Lay-in	102 - Teacher's Lounge	6	EA	6	6-10 years	
	Power Distribution	102 - Teacher's Lounge	8	EA	6	10+ years	
	Walls - Plaster/Drywall	102 - Teacher's Lounge	630	SF	6	10+ years	
	Ceiling - Lay-in	137 Copy/Book storage Room	530	SF	7	10+ years	
	Doors - Wood Doors inclu hw	137 Copy/Book storage Room	1	EA	7	10+ years	
	Floor - Tile	137 Copy/Book storage Room	530	SF	7	10+ years	



Catego	Category : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	137 Copy/Book storage Room	6	EA	7	6-10 years	
	Power Distribution	137 Copy/Book storage Room	12	EA	6	10+ years	
	Walls - Concrete Block	137 Copy/Book storage Room	230	SF	7	10+ years	
	Walls - Plaster/Drywall	137 Copy/Book storage Room	635	SF	7	10+ years	
	Ceiling - Splined	206 Counseling Office	138	SF	7	10+ years	
	Ceiling - Splined	206 Counseling Office	2	SF	4	0-1 year	Broken tile
	Doors - Wood Doors inclu hw	206 Counseling Office	1	EΑ	7	10+ years	
	Floor - Tile	206 Counseling Office	140	SF	7	10+ years	
	Lighting - Pendent/Surface	206 Counseling Office	1	EA	7	6-10 years	
	Power Distribution	206 Counseling Office	8	EΑ	7	10+ years	
	Walls - Plaster/Drywall	206 Counseling Office	350	SF	7	10+ years	
	Ceiling - Lay-in	224 Store Room	505	SF	7	10+ years	
	Ceiling - Lay-in	224 Store Room	25	SF	4	0-1 year	Missing tiles and water damage
	Doors - Steel Doors incl hw	224 Store Room	1	EA	7	10+ years	
	Floor - Tile	224 Store Room	515	SF	7	10+ years	
	Floor - Tile	224 Store Room	15	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	224 Store Room	6	EΑ	7	6-10 years	
	Power Distribution	224 Store Room	12	EΑ	7	10+ years	
	Walls - Concrete Block	224 Store Room	230	SF	7	10+ years	
	Walls - Plaster/Drywall	224 Store Room	30	SF	7	10+ years	
	Walls - Plaster/Drywall	224 Store Room	605	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	270	SF	7	10+ years	
	Doors - Steel Doors incl hw	Engineer's Office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Engineer's Office	270	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office	4	EΑ	7	10+ years	
	Walls - Masonry	Engineer's Office	340	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	340	SF	7	10+ years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	4	SF	5	10+ years	
	Boiler Room	Basement	1,347	SF	4	0-1 year	Damaged drywall
	Crawl Space - Unfinished	Basement	750	SF	7	10+ years	g ,
	Storage Room	Basement	170	SF	7	10+ years	
	Storage Room	Basement	83	SF	7	10+ years	
	Storage Room	Basement	370	SF	7	10+ years	
	Storage Room	Basement	325	SF	7	10+ years	
	Vaults	Basement	215	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor Boys	470	SF	7	6-10 years	
	Ceiling - Exposed	1st Floor Boys	470	SF	4	0-1 year	Cracking
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	7	10+ years	Ciacining
	Floor - Terrazzo	1st Floor Boys	464	SF	7	10+ years	
					-	<b>,</b>	



Catego	ategory : Room		В	Building : Main			3023 3 Washlehaw AVENUE, Chicago, in 00032		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Terrazzo	1st Floor Boys	6	SF	4	0-1 year	Cracked floor		
	Floor Drain	1st Floor Boys	1	EA	7	10+ years			
	Lavatory	1st Floor Boys	4	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor Boys	7	EA	7	6-10 years			
	Partitions	1st Floor Boys	3	EA	7	10+ years			
	Partitions	1st Floor Boys	1	EA	4	0-1 year	Missing door		
	Urinals	1st Floor Boys	10	EA	7	10+ years	3		
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys	988	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys	2	SF	4	0-1 year	Broken tile		
	Water Closet	1st Floor Boys	4	ĒΑ	7	10+ years			
	Accessories	1st Floor Girls	470	SF	7	6-10 years			
	Ceiling - Exposed	1st Floor Girls	470	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	6	10+ years			
	Floor - Terrazzo	1st Floor Girls	10	SF	7	10+ years			
	Floor - Terrazzo	1st Floor Girls	460	SF	7	10+ years			
	Floor Drain	1st Floor Girls	1	EA	4	0-1 year	Repaired		
	Lavatory	1st Floor Girls	1	EA	6	6-10 years	Repaired		
		1st Floor Girls	6	EA		6-10 years			
	Lavatory		7	EA	6	-			
	Lighting - Pendent/Surface	1st Floor Girls		EA	7 7	6-10 years			
	Partitions	1st Floor Girls	10			10+ years	Mississedos		
	Partitions	1st Floor Girls	1	EA	4	0-1 year	Missing door		
	Walls - Tile Ceramic/ Porcelain	1st Floor Girls	990	SF	7	10+ years			
	Water Closet	1st Floor Girls	10	EA	7	10+ years			
	Water Closet	1st Floor Girls	1	EA	4	1-2 years	Inoperable		
	Accessories	In Room 206	20	SF	7	6-10 years			
	Ceiling - Lay-in	In Room 206	20	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In Room 206	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Room 206	18	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Room 206	2	SF	6	2-5 years	Repaired		
	Lavatory	In Room 206	1	EA	7	10+ years			
	Lighting - Wall Mounted	In Room 206	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	In Room 206	34	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	In Room 206	20	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	In Room 206	20	SF	7	10+ years			
	Water Closet	In Room 206	1	EA	6	10+ years			
atego	ry : Classroom		В	uilding	: Main				
2roup	Itom - Typo	Location	Quantity	UOM	Rank	Recommend Replacement	Commonts		
<b>Froup</b> Classroo	Item - Type om #101 (Kindergarten)	Location	Quantity	COIVI	Naiik	Replacement	Confinents		
นสออเป็น	AC Units	1st Floor	4	EA	7	101.1/0070			
			1		7	10+ years			
	Casework	1st Floor	47	LF CF	6	10+ years			
	Ceiling - Lay-in	1st Floor	715	SF	6	10+ years			
	Doors - Transom Window	1st Floor	6	SF	6	10+ years			



Catego	Category : Classroom Building : Main						
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	695	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Damaged
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #138 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	715	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	715	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	310	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	685	SF	7	10+ years	
				<b>.</b>	•	.o. yea.e	
Classroo	m #143 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	765	SF	6	10+ years	
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	754	SF	6	10+ years	
	Floor - Tile	1st Floor	11	SF	4	0-1 year	Damaged
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	ŭ
	Marker Board	1st Floor	33	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	850	SF	6	10+ years	
Classroo	om #144/145 (Regular Classroom)						
5,000,00	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	346	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	1-2 years	Damaged
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	Damayea
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	350	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	330	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	630	SF	6	10+ years	
	vvalis - Flastel/Diywali	121 LIOOI	630	SF	Ü	10+ years	
Classroo	om #146 (Regular Classroom)						
	, ,						



Category : Classroom			В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	698	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	2	SF	4	0-1 year	Damaged
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	660	SF	7	6-10 years	
	Floor - Tile	1st Floor	40	SF	4	0-1 year	Damaged
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	Ğ
	Marker Board	1st Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	805	SF	7	10+ years	
Classroo	nm #148 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	765	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	725	SF	6	10+ years	
	Floor - Tile	1st Floor	40	SF	4	0-1 year	Damaged
		1st Floor	14	EA	7		Damageu
	Lighting - Lay-in		33	LF	7	6-10 years	
	Marker Board	1st Floor		SF		6-10 years	
	Storage/ Closet	1st Floor	75		5	2-5 years	
	Walls - Plaster/Drywall	1st Floor	850	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #225 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	710	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	5	SF	4	0-1 year	Damaged
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	_
	Floor - Tile	2nd Floor	715	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	310	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	685	SF	7	10+ years	
Classroo	nm #227 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	765	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	725	SF	7	10+ years	
	1100. 1110	2110 1 1001	125	01	,	ioi youis	



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	40	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	
Classroc	om #228 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	126	SF	7	10+ years	
	Floor - Tile	2nd Floor	24	SF	4	0-1 year	Damaged
	Marker Board	2nd Floor 2nd Floor	24	LF	7	6-10 years	Damageu
				SF			
	Walls - Plaster/Drywall	2nd Floor	315	51	7	10+ years	
Classroc	om #229 (Regular Classroom)						
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Tile	2nd Floor	334	SF	7	10+ years	
	Floor - Tile	2nd Floor	16	SF	4	0-1 year	Damaged
	Storage/ Closet	2nd Floor	150	SF	7	10+ years	g
	Walls - Plaster/Drywall	2nd Floor	555	SF	7	10+ years	
Classroc	om #232/ 231 (Regular Classroom)						
CHOOLOG	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	700	SF	7	10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	EA	7	•	
						10+ years	
	Floor - Tile	2nd Floor	668	SF	7	10+ years	5
	Floor - Tile	2nd Floor	32	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	
Classroc	om #233 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	757	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Damaged
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Damagoa
	Floor - Tile	2nd Floor	740	SF	7	10+ years	
	1 1001 - 1 11C	ZHU FIUUI	740	SI.	,	IUT years	



140						3023	5 Washlehaw Avenue, Chicago, iL 6065
Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	25	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	Zamagoa
	Marker Board	2nd Floor	33	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	
	Walls - Flaster/Drywall	211d F1001	650	SF	,	10+ years	
lassroc	nm #234 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	699	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Damaged
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	700	SF	6	10+ years	
	Floor - Tile	2nd Floor	15	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	Damagea
	Marker Board	2nd Floor	45	LF	7	6-10 years	
				SF		•	
	Storage/ Closet	2nd Floor	75		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
lassroc	om #235 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	715	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	5	10+ years	
	Floor - Tile	2nd Floor	695	SF	7	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Damaged
	Marker Board		45	LF	7		
		2nd Floor		SF		6-10 years	
	Storage/ Closet	2nd Floor	75	SF SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	880	٥F	7	10+ years	
atego	ry : Interior		В	uilding	: Main		
			<b>a</b>			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Splined	1st Floor	1,800	SF	6	10+ years	
	Ceiling - Splined	1st Floor	192	SF	4	0-1 year	Damaged
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	-
	Floor - Tile/Sheet	1st Floor	1,972	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,808	SF	6	10+ years	
	Trans Tiaston Dry Wall	13(1)001	7,000	Ji	U	TOT years	



Catego	ry : Interior	В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Ceiling - Splined	2nd Floor	1,800	SF	6	6-10 years		
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	1,780	SF	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	20	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	2nd Floor	7	EA	7	6-10 years	•	
	Walls - Plaster/Drywall	2nd Floor	4,163	SF	7	10+ years		
Safety								
	Security Cameras	Entire Building	4	EA	7	6-10 years		
Stairs								
	Ceiling - Lay-in	Main Center Stairs	412	SF	7	10+ years		
	Floor - Tile	Main Center Stairs	384	SF	6	6-10 years		
	Handrails	Main Center Stairs	92	LF	7	10+ years		
	Lighting - Pendent/Surface	Main Center Stairs	2	EA	7	6-10 years		
	Stairs - Terrazzo	Main Center Stairs	24	LF	7	10+ years		
	Stairs - Terrazzo	Main Center Stairs	8	LF	6	10+ years		
	Stairs - Terrazzo	Main Center Stairs	15	LF	4	0-1 year	Damaged	
	Walls - Plaster/Drywall	Main Center Stairs	890	SF	7	10+ years	-	
	Ceiling - Lay-in	North East	700	SF	7	10+ years		
	Floor - Concrete	North East	46	SF	7	10+ years		
	Floor - Tile	North East	84	SF	6	10+ years		
	Handrails	North East	56	LF	7	10+ years		
	Lighting - Pendent/Surface	North East	2	EA	7	6-10 years		
	Stairs - Concrete	North East	350	LF	7	10+ years		
	Walls - Masonry	North East	1,007	SF	6	10+ years		
	Ceiling - Splined	South East	700	SF	7	10+ years		
	Floor - Concrete	South East	23	SF	7	10+ years		
	Floor - Tile	South East	23	SF	4	0-1 year	Damaged	
	Handrails	South East	56	LF	7	10+ years	<b>0</b>	
	Lighting - Pendent/Surface	South East	2	ĒΑ	7	6-10 years		
	Stairs - Concrete	South East	35	LF	6	10+ years		
	Walls - Masonry	South East	927	SF	7	10+ years		
	Walls - Plaster/Drywall	South East	80	SF	6	10+ years		



Category : Exterior Building : Addition 1

	y . Exterior		Recommend						
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ntrance					. WIII	. topiasomont			
	Exterior Doors - Store Front	3 W	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	3 W	1	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	4 E	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	4 E	1	EΑ	5	0-1 year	Rusted through		
	Ramp Handrail - Steel_Ramp Handrail	4 E	42	LF	6	10+ years	radioa imoagii		
	Ramps - Concrete	4 E	19	LF	7	10+ years	Divided out damaged areas		
	Ramps - Concrete	4 E	2	LF	5	1-2 years	Spalled		
	Exterior Doors - Exterior Steel Door	5 E	_ 1	EA	6	10+ years	<b>Opanioa</b>		
	Exterior Doors - Transom Lite	5 E	1	EΑ	5	0-1 year	Deteriorating plywood		
	Exterior Stairs - Concrete	5 E	16	LF	6	10+ years	g p-y		
	Stair Handrail - Steel_Stair Handrail	5 E	20	LF	6	10+ years			
		<b>~</b> -			Ū	.o. yeare			
oundati									
	Foundation - Concrete	Entire Building	540	LF	7	10+ years			
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	3,080	SF	7	10+ years			
ahtina									
ghting	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	10+ years	New		
		g	_		-	, , , , , , , , , , , , , , , , , , , ,			
oof Sys									
	Access Ladder - Metal	6	1	EA	7	10+ years			
	Chimney - Metal Flue	6	20	LF	6	10+ years			
	Coping - Metal	6	190	LF	6	2-5 years	Not previously assessed		
	Downspouts - Interior Downspouts	6	26	LF	6	10+ years			
	Roof - Modified Bitumen	6	3,100	SF	4	1-2 years	Worn surface, multiple patches,		
	Doef Hotol Motol	6	4	ГΛ	E	10	ponding		
	Roof Hatch - Metal	6 6	1 3,100	EA SF	5 7	10+ years	Broken hardware		
	Roof Structure - Steel / Metal Deck/ Concrete Topping	0	3,100	SF	1	10+ years			
alls									
unu	Exterior Walls - Brick	Entire Building	12,585	SF	6	10+ years			
/:l.a									
indows	Lintels - Steel	Entire Building	36	LF	6	10+ years			
	Windows - Sash Aluminum Double-pane	Entire Building	240	SF	6	10+ years			
atego	ry : Electrical		В	uildina	: Additio	on 1			
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments		



	3CHOOIS					0020	S Washtenaw AVENUE, Chicago, IL 6063
						Replacement	
Emerge	ncy System						
	Emergency Battery Packs - Corridors and Stairs	1st Floor	1	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Multipurpose Room	1st Floor	1	EA	6	6-10 years	Quantity changed to match current observations.
	Exit Signs - Corridors and Stairs	Electrical Room	1	EA	6	6-10 years	Quantity changed to match current observations.
	Exit Signs - Multipurpose Room	Electrical Room	3	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency A/C Power - Corridors and Stairs	Entire Building	300	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,730	SF	6	6-10 years	
	Security System - CCTV	Entire Building	3,080	SF	6	6-10 years	
	Automatic Transfer Switch	Pump Room	1	EA	6	6-10 years	
1ain Se	ervice						
	PA System	Entire Building	3,080	SF	5	6-10 years	Served by Addition 2.
	Main Electrical Service - 800 A and Less than 277/480/3PH	Site - East	1	EA	6	10+ years	Item Type changed to match curre observations.
ower Γ	Distribution						
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open breaker slots expose live conductors presenting live front condition.
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	7	10+ years	
atego	ory : Fire Protection		В	uilding	: Additi	on 1	
_						Recommend	
<b>iroup</b> ire Ala	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ile Ala	Fire Alarm Strobe Lights	Entire Building	3,080	SF	4	2-5 years	System is functional and passes inspection. Rank, Reason and Priority Rep adjusted as the system 23 years old and has reached the
	Fire Alarm_System	Entire Building	3,080	SF	4	2-5 years	of its EUL. System is functional and passes
	The Alami_System						inspection. Rank, Reason and Priority Rep adjusted as the syste 23 years old and has reached the of its EUL.



Catego	ry : Fire Protection		В	uilding	: Additi		
	<del></del>		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp	Fire Pump Room	1	EA	6	10+ years	
	Jockey Pump	Fire Pump Room	1	EA	6	10+ years	
Sprinkler	System						
	Sprinkler Heads	Entire Building	3,080	SF	7	10+ years	
	Sprinkler Piping	Entire Building	3,080	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	3,080	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Roof Top Unit-Single Zone-Roof Mounted-	Lower Roof	1	EA	7	10+ years	Serves Addition 1. Rank and Priorit
	Gas Heating and DX Cooling Coil - 11 - 20						Rep adjusted as the unit was
	tons						replaced since previous assessmen
Tempera	ature Control						
•	Electric Thermostat	Entire Building	1	EA	7	10+ years	Rank and Priority Rep adjusted as
							the thermostat was replaced since the previous assessment.
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Lower Roof	1	EA	6	6-10 years	
	CFM					•	
	Exhaust Fans- Roof Mounted - 500 - 1500	Lower Roof	1	EA	5	6-10 years	
	CFM						
Catego	ry : Plumbing		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Storage	1	EA	5	2-5 years	Unit is leak-free with no signs of
							undue corrosion, however Reason
							and Priority Rep changed as it is 30
							years old and has reached its EUL.
Piping							
пршу	Domestic Piping-Hot Water Return Lines	Entire Building	3,080	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	3,080	SF	6	6-10 years	
	Fixtures	o Dananig	3,000	0.	Ŭ	5 10 Joans	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	3,080	SF	6	6-10 years	
		<b>-</b>	•			•	

Campus Name: Brighton Park Page: 15 of 39 Assessment Date: 12/19/2023



Category : Plumbing

# Brighton Park Elementary School 3825 S Washtenaw AVENUE, Chicago, IL 60632

**Building: Addition 1** 

Calego	ory : Plumbing	Building : Addition 1						
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	(Horizontal Lines)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	3,080	SF	6	6-10 years		
	(from Risers to Fixtures)	Entire Ballating	9,000	O.	O	o to years		
		E 4	0.000	0=	_	4.0		
	Sanitary Piping	Entire Building	3,080	SF	6	10+ years		
	Storm Piping	Entire Building	3,080	SF	6	10+ years		
	Vent Piping	Entire Building	3,080	SF	6	10+ years		
	1 5	9	,			•		
`atono	ory : Room		B	uilding	· Additi	on 1		
alego	ny . Room			ununig	. Additi			
_	_					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminis	trative Suites/Offices							
	Ceiling - Exposed	Nurse Office	103	SF	6	10+ years		
				EA	6			
	Doors - Wood Doors inclu hw	Nurse Office	1			10+ years		
	Floor - Tile	Nurse Office	103	SF	6	6-10 years		
	Lighting - Pendent/Surface	Nurse Office	2	EA	6	6-10 years		
	Power Distribution	Nurse Office	6	EA	7	10+ years		
	Walls - Concrete Block	Nurse Office	269	SF	6	10+ years		
	Work Sink	Nurse Office	1	EA	7	10+ years		
			•		-			
	Ceiling - Lay-in	Work room	505	SF	6	10+ years		
	Doors - Steel Doors incl hw	Work room	2	EA	6	10+ years		
	Floor - Concrete Epoxy/ Painted	Work room	505	SF	7	10+ years		
	Lighting - Lay-in	Work room	8	EA	6	6-10 years		
	Power Distribution	Work room	8	EA	6	10+ years		
	Walls - Concrete Block	Work room	1,085	SF	6	10+ years		
	Work Sink	Work room	1,000	EA	7	10+ years		
	WOIK SIIIK	WOIK TOOTT	ļ	LA	,	10+ years		
unch &	Multipurpose Room							
<u> </u>	AC Unit	1st Floor	1	EA	7	6-10 years		
			· · · · · · · · · · · · · · · · · · ·	SF				
	Ceiling - Exposed	1st Floor	1,730		7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,730	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	33	EΑ	7	6-10 years		
	Serving Line	1st Floor	15	LF	7	10+ years		
	Storage/ Closet	1st Floor	40	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	2,905	SF	7	10+ years		
	Walls - Concrete block	1St F1001	2,905	SF	1	10+ years		
lechani	ical/ Service Rooms							
	Janitor's Closet	1st Floor	21	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	50	SF	7			
						10+ years		
	Storage Room	1st Floor	250	SF	7	10+ years		
estrooi	m							
	Accessories	Unisex Restroom	45	SF	7	6-10 years		
	ACCESSUIRS	OHISEX RESUUDIN	45	SF	,	o- to years		
	Nama, Brighton Dark		2000 1 16 of 20				Assessment Date: 12/10/	



Catego	ry : Room		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Unisex Restroom	45	SF	6	10+ years	
	Doors - Steel Doors incl hw	Unisex Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Restroom	45	SF	7	10+ years	
	Floor Drain	Unisex Restroom	1	EA	7	10+ years	
	Lavatory	Unisex Restroom	1	EA	6	10+ years	
	Lighting - Wall Mounted	Unisex Restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	Unisex Restroom	90	SF	6	10+ years	
	Water Closet	Unisex Restroom	1	EA	6	10+ years	
	Accessories	Unisex restroom	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex restroom	45	SF	6	10+ years	
	Doors - Steel Doors incl hw	Unisex restroom	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Unisex restroom	45	SF	7	10+ years	
	Floor Drain	Unisex restroom	1	EA	7	10+ years	
	Lavatory	Unisex restroom	1	EA	6	10+ years	
	Lighting - Wall Mounted	Unisex restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	Unisex restroom	90	SF	6	10+ years	
	Water Closet	Unisex restroom	1	EA	6	10+ years	

Category : Interior **Building: Addition 1** 

y . Interior		Ballating : Addition 1					
					Recommend		
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Ceiling - Exposed	1st Floor	90	SF	7	10+ years		
Ceiling - Plaster/Drywall	1st Floor	350	SF	7	10+ years		
Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years		
Floor - Tile/Sheet	1st Floor	440	SF	4	0-1 year	Damaged tile	
Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years		
Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years		
Stairs - Concrete Stairs	1st Floor	25	LF	6	6-10 years	Repaired	
Walls - Concrete Block	1st Floor	490	SF	7	10+ years		
Walls - Plaster/Drywall	1st Floor	650	SF	7	10+ years		
	Ceiling - Exposed Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Concrete Block	Item - TypeLocationCeiling - Exposed Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Concrete Block1st Floor 1st Floor 1st Floor 1st Floor	Item - Type         Location         Quantity           Ceiling - Exposed         1st Floor         90           Ceiling - Plaster/Drywall         1st Floor         350           Doors - Steel Doors incl hw         1st Floor         2           Floor - Tile/Sheet         1st Floor         440           Lighting - Lay-in         1st Floor         1           Lighting - Pendent/Surface         1st Floor         3           Lighting - Pendent/Surface         1st Floor         1           Stairs - Concrete Stairs         1st Floor         25           Walls - Concrete Block         1st Floor         490	Item - Type         Location         Quantity         UOM           Ceiling - Exposed Ceiling - Plaster/Drywall         1st Floor 1st Floor         90         SF 2stel Doors - Steel Doors incl hw           Doors - Steel Doors incl hw Floor - Tile/Sheet         1st Floor 1st Floor         2 EA 440         EA 440           Lighting - Lay-in Lighting - Pendent/Surface         1st Floor 1st Floor         3 EA 1st Floor 1 EA Stairs - Concrete Stairs 1st Floor         1 EA 25 LF 490           Stairs - Concrete Stairs Walls - Concrete Block         1st Floor 1st Floor         490         SF	Item - Type         Location         Quantity         UOM         Rank           Ceiling - Exposed Ceiling - Plaster/Drywall         1st Floor 1st Floor         90 350 350 350 357 7         SF 7         7           Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Lighting - Lay-in Lighting - Pendent/Surface 1st Floor Lighting - Pendent/Surface Stairs - Concrete Stairs 1st Floor Stairs - Concrete Stairs 1st Floor 1st Flo	Item - TypeLocationQuantityUOMRankRecommend ReplacementCeiling - Exposed Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Lighting - Pendent/Surface Stairs - Concrete Stairs Walls - Concrete Block1st Floor 1st Floor 2st F	



Category : Exterior Building : Addition 2

Calego	y . Exterior		В	unung	. Additi		
0	Ham Time	Lagation	Oues the	LIONA	Don's	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 Main SW	1	EA	6	10+ years	
	Exterior Doors - Side lite	1 Main SW	2	EA	6	10+ years	
	Exterior Doors - Store Front	1 Main SW	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 Main SW	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	10 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	10 N	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	11 N	2	EA	5	0-1 year	Rusted frame and door
	Exterior Doors - Exterior Steel Door	12 N	2	EA	6	10+ years	
	Exterior Doors - Side lite	13 W	2	EΑ	6	10+ years	
	Exterior Doors - Store Front	13 W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	13 W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	7.1 SE	2	EA	7	10+ years	Repaired
	Exterior Doors - Exterior Steel Door	8 E	2	EA	6	10+ years	
	Exterior Doors - Exterior Stainless Steel	9 NE	1	EΑ	6	10+ years	
	Door					-	
Foundati	on						
	Foundation - Concrete	Entire Building	575	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	53,000	SF	7	10+ years	
	Topping	3	,			, , , , ,	
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	10+ years	
		C				j	
Roof Sys	tem						
-	Access Ladder - Metal	1	1	EA	7	10+ years	
	Chimney - Metal Flue	1	20	LF	6	10+ years	
	Coping - Stone	1	639	LF	6	10+ years	
	Downspouts - Interior Downspouts	1	160	LF	6	10+ years	
	Parapet - Parapet > 30"	1	639	LF	6	10+ years	
	Roof - Modified Bitumen	1	17,670	SF	5	2-5 years	Assessed based on current condition
			,			•	Worn surface
	Roof Hatch - Metal	1	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	1	17,670	SF	7	10+ years	
	Concrete Topping		,			,	
	0						
Walls							
	Exterior Walls - Brick	Entire Building	24,275	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25	SF	4	0-1 year	No safe access to area
	Exterior Walls - Stone-Cut	Entire Building	2,300	SF	6	10+ years	
			_,500		-	- <i>,</i>	



Category : Exterior

#### Brighton Park Elementary School 3825 S Washtenaw AVENUE, Chicago, IL 60632

**Building: Addition 2** 

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Commonts
Group		Location	Quantity	UOIVI	Kalik	Replacement	Comments
_Windows							
	Guard - Guards perforated	Entire Building	1,660	SF	6	6-10 years	
	Lintels - Steel	Entire Building	550	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,200	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on 2	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System	Location	Quantity	OOM	Italik	Replacement	Comments
_Emerger	Security System - CCTV	1st Floor	53,000	SF		6.10 vooro	
			53,000	SF SF	6	6-10 years	
	Security System - Intrusion Detection	1st Floor		SF EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1		6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	17	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EΑ	6	6-10 years	Overtity about and to market assument
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	19	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,619	SF	6	6-10 years	observations.
	Emergency A/C Power - Gym	Entire Building	4,234	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	5,104	SF	6	6-10 years	
_Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	1st Floor	1	EA	6	10+ years	
	PA System	1st Floor	53,000	SF	5	6-10 years	Serves Addition 1, Main, and Addition 2.
	Independent Electrical Service for emergency power	Fire Pump Room, Electrical Room	1	EA	6	10+ years	For fire pump.
	Independent Electrical Service for emergency power	Fire Pump Room, Electrical Room	1	EA	6	10+ years	
_Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	5	EΑ	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	Quantity changed to match current observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles and missing

Campus Name: Brighton Park Page: 19 of 39 Assessment Date: 12/19/2023



Catego	ry : Electrical		В	uilding	: Addition		
	W		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	<b>Comments</b> interior cover expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire ALarm Anunciator	Entire Building	1	EA	6	10+ years	No CPS Asset Tag present. Serves Addition 1, Main, and Addition 2.
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves Addition 1, Main, and Additio 2.
	Fire Alarm Strobe Lights	Entire Building	53,000	SF	6	10+ years	
	Fire Alarm_System	Entire Building	53,000	SF	4	2-5 years	Serves Addition 1, Main, and Addition 2. System is functional and passes inspection. Rank, Reason and Priority Rep adjusted as the system 23 years old and has reached the er of its EUL.
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	6-10 years	
	Jockey Pump	Mechanical Room	1	EA	6	6-10 years	
Sprinkle	r System						
,	Sprinkler Heads	Entire Building	53,000	SF	7	10+ years	
	Sprinkler Piping	Entire Building	53,000	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	53,000	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Additio	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	litioning						
	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons	Entire Building Entire Building	1	EA EA	6 5	6-10 years 2-5 years	Limited functionality and considerab deterioration noted. Documented in previous assessment as being
Campus	Name: Brighton Park		Page: 20 of 39				Assessment Date: 12/19/20

Page : 20 of 39 Campus Name: Brighton Park Assessment Date: 12/19/2023



Catego	ry : Mechanical		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							beyond service life with no new observations.
	Glycol Feed	Entire Building	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Copper	Entire Building	150	LF	6	10+ years	
	Pressure Fill System	Entire Building	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	2-5 years	Component of a ductless split syster serving the MDF Room. Older unit with considerable deterioration.
Air Hand	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	3	EA	6	6-10 years	Served by AHU-2. Fan power boxes are located above the suspended ceiling grid and not accessible at the time of assessment.
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	29	EA	6	6-10 years	Served by AHU-1. Fan power boxes are located above the suspended ceiling grid and not accessible at the time of assessment.
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	10+ years	RF-3
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-1
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room - AHU-1	1	EA	6	6-10 years	AHU-1. Rank, Reason and Priority Rep changed as the equipment has been restored to full normal operating functionality since previous assessment.
	Air Intake	Mechanical Room - AHU-1	1	EΑ	6	6-10 years	
	Induction Fan	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	VAV Box	Mechanical Room - AHU-1	3	EA	5	6-10 years	VAV boxes are located above the suspended ceiling grid and not accessible at the time of assessmen
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	Induction Fan	Mechanical Room - AHU-2	1	EA	5	6-10 years	
	VAV Box	Mechanical Room - AHU-2	2	EA	5	6-10 years	VAV boxes are located above the suspended ceiling grid and not accessible at the time of assessmen
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU-3	1	EA	6	6-10 years	AHU-3. Rank, Reason and Priority Rep changed as the equipment has been restored to full normal operatin functionality since previous



Catego	ry : Mechanical		В	uilding	: Addition	on 2	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	•		•			•	assessment.
	Air Intake	Mechanical Room - AHU-3	1	EA	6	10+ years	Location changed to match current
						,	observations.
	Make Up Air Unit- Roof Mounted- Electric	Roof	1	EA	5	6-10 years	No CPS Asset Tag present.
	Coils - Less than 6000 cfm						
Boiler Sy	vstems						
<del>,</del>	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	6	10+ years	
	- 1001 - 2000 MBH	Wednamear Room	_		O	101 years	
	Chemical Pot Feeder	Mechanical Room	2	EA	6	6-10 years	
	Glycol Feed System	Mechanical Room	1	EA	6	6-10 years	
	Non Condensing- Flexible Tube-	Mechanical Room	2	EA	6	•	B-1 B-2
	Atmospheric- Hot Water Boiler - 1001 - 2000	Wechanical Room	2	LA	O	10+ years	D-1 D-2
	MBH						
	Water Fill System	Mechanical Room	1	EA	5	6 10 voore	
	water Fill System	Mechanical Room	ı	EA	5	6-10 years	
Gas Boo	ster						
	Gas Booster	Mechanical Room	1	EA	6	6-10 years	
Heating I	Devices						
J	Unit Heater - Electric	Entire Building	2	EA	6	10+ years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	10+ years	Quantity changed to match current
	One reader that water	Zittiro Dananig	_	_, 、	Ū	ioi youlo	observations and per review with
							Building Engineer.
	Cabinet Heaters - With Hot Water Coil	Entire Building	9	EA	6	6-10 years	Danaing Engineer.
	Radiator Panels - Hot Water	Entire Building	6	EA	5	6-10 years	Ceiling-mounted in student
	radiator rancis - riot water	Entire Ballating	O	L/\	9	o to years	restrooms. Quantity changed to
							match current observations.
	Wall Heater - Electric	Meter Room	1	EA	6	10+ years	Location changed for clarification.
	Wall Fleater - Liectric	Meter Room	'	LA	U	10+ years	Location changed for clarification.
Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	700	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	ΕA	6	6-10 years	
	Chilled Water Pump - Less than 10	Mechanical Room	1	EΑ	5	6-10 years	
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years	
Temporo	uture Control						
rempera	IUIE CONIO						
	DDC System	Entire Building	53,000	SF	4	2-5 years	Software upgraded since previous



Catego	ry : Mechanical		В	uilding	: Additi	on 2	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	assessment but system is not reliable. Reason and Priority Rep changed to reflect that the system has reached its EUL. Location changed for clarification. Quantity changed based on current observations and per review with Building Engineer that the interest of the system.
	Thermostats - DDC	Entire Building	38	EA	6	10+ years	heaters are equipped with integral thermostats.  Quantity changed as total has been divided/aggregated.
_Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	10+ years	Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	Quantity changed to match current observations.
	Roof Mounted Duct Work	Entire Building	10	LF	5	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	6	10+ years	Quantity changed to match current observations.

**Category: Plumbing Building: Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	53,000	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	53,000	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	53,000	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	53,000	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	53,000	SF	6	10+ years	
	(Risers)				_		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	53,000	SF	6	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	53,000	SF	6	10+ years	



Catego	ry : Plumbing		В	uilding	: Addition	on 2	- ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storm Piping	Entire Building	53,000	SF	6	10+ years	
	Vent Piping	Entire Building	53,000	SF	6	10+ years	
_Pumps							
	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	1st Floor	1	EA	6	6-10 years	Located in the bottom of the elevator pit. Inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by the Building Engineer.

Category: Room **Building: Addition 2** 

	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Recommend							
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	rative Suites/Offices					•			
	Ceiling - Lay-in	102 Main Office	717	SF	6	10+ years			
	Ceiling - Lay-in	102 Main Office	8	SF	4	1-2 years	Water stained tile		
	Doors - Side-lite	102 Main Office	144	SF	6	10+ years			
	Doors - Wood Doors inclu hw	102 Main Office	2	ĒΑ	6	10+ years			
	Floor - Carpet	102 Main Office	615	SF	6	6-10 years			
	Floor - Terrazzo	102 Main Office	110	SF	6	10+ years			
	Lighting - Lay-in	102 Main Office	10	ĒΑ	7	6-10 years			
	Power Distribution	102 Main Office	18	EA	6	10+ years			
	Walls - Concrete Block	102 Main Office	1,318	SF	6	10+ years			
	Walls - Plaster/Drywall	102 Main Office	713	SF	6	10+ years			
	Ceiling - Lay-in	105 Office in Main Office	153	SF	7	10+ years			
	Doors - Wood Doors inclu hw	105 Office in Main Office	1	EA	7	10+ years			
	Floor - Carpet	105 Office in Main Office	153	SF	6	6-10 years			
	Lighting - Lay-in	105 Office in Main Office	2	EA	7	6-10 years			
	Power Distribution	105 Office in Main Office	6	EA	7	10+ years			
	Walls - Concrete Block	105 Office in Main Office	30	SF	7	10+ years			
	Walls - Plaster/Drywall	105 Office in Main Office	335	SF	7	10+ years			
	Ceiling - Lay-in	106 Work Room	222	SF	6	10+ years			
	Ceiling - Lay-in	106 Work Room	8	SF	4	1-2 years	Water damage tile		
	Doors - Wood Doors inclu hw	106 Work Room	1	EA	6	10+ years			
	Floor - Tile	106 Work Room	230	SF	6	10+ years			
	Lighting - Lay-in	106 Work Room	4	EA	6	6-10 years			
	Power Distribution	106 Work Room	6	EA	6	10+ years			
	Walls - Concrete Block	106 Work Room	486	SF	6	10+ years			
	Work SInk	106 Work Room	1	EA	7	10+ years			
	Ceiling - Lay-in	107 Asst. Principal in Main Office	153	SF	6	10+ years			
	Doors - Wood Doors inclu hw	107 Asst. Principal in Main Office	1	EA	6	10+ years			
	Floor - Carpet	107 Asst. Principal in Main Office	153	SF	6	6-10 years			
	Lighting - Lay-in	107 Asst. Principal in Main Office	2	EA	6	6-10 years			

Campus Name: Brighton Park Page : 24 of 39 Assessment Date: 12/19/2023



Calego	ry : Room		Building : Addition 2					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	107 Asst. Principal in Main Office	6	EA	6	10+ years		
	Walls - Concrete Block	107 Asst. Principal in Main Office	30	SF	6	10+ years		
	Walls - Plaster/Drywall	107 Asst. Principal in Main Office	435	SF	6	10+ years		
	Ceiling - Lay-in	111 Principal in Main Office	230	SF	6	10+ years		
	Doors - Wood Doors inclu hw	111 Principal in Main Office	1	EA	6	10+ years		
	Floor - Carpet	111 Principal in Main Office	230	SF	6	6-10 years		
	Lighting - Lay-in	111 Principal in Main Office	4	EA	6	6-10 years		
	Power Distribution	111 Principal in Main Office	6	EA	6	10+ years		
	Walls - Concrete Block	111 Principal in Main Office	30	SF	6	10+ years		
	Walls - Plaster/Drywall	111 Principal in Main Office	486	SF	6	10+ years		
	Ceiling - Lay-in	112- Student Services	125	SF	6	10+ years		
	Doors - Wood Doors inclu hw	112- Student Services	1	EA	6	10+ years		
	Floor - Tile	112- Student Services	125	SF	6	10+ years		
	Lighting - Lay-in	112- Student Services	2	EA	6	6-10 years		
	Power Distribution	112- Student Services	6	EA	6	10+ years		
	Walls - Concrete Block	112- Student Services	110	SF	6	10+ years		
	Walls - Plaster/Drywall	112- Student Services	185	SF	6	10+ years		
	Work SInk	112- Student Services	1	EA	7	10+ years		
	Ceiling - Lay-in	130 - Counseling Office	420	SF	6	10+ years		
	Doors - Side-lite	130 - Counseling Office	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	130 - Counseling Office	1	EA	6	10+ years		
	Floor - Tile	130 - Counseling Office	420	SF	6	10+ years		
	Lighting - Lay-in	130 - Counseling Office	6	EA	6	6-10 years		
	Power Distribution	130 - Counseling Office	8	EA	6	10+ years		
	Walls - Concrete Block	130 - Counseling Office	700	SF	6	10+ years		
	Walls - Plaster/Drywall	130 - Counseling Office	200	SF	6	10+ years		
	Ceiling - Lay-in	302 - Seminar	470	SF	6	10+ years		
	Doors - Side-lite	302 - Seminar	24	SF	7	10+ years		
	Doors - Wood Doors inclu hw	302 - Seminar	1	EA	7	10+ years		
	Floor - Tile	302 - Seminar	470	SF	7	10+ years		
	Lighting - Lay-in	302 - Seminar	6	EΑ	7	6-10 years		
	Power Distribution	302 - Seminar	6	EA	7	10+ years		
	Walls - Concrete Block	302 - Seminar	1,056	SF	7	10+ years		
	Ceiling - Lay-in	Gym- Office	270	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Gym- Office	1	EA	7	10+ years		
	Floor - Tile	Gym- Office	270	SF	7	10+ years		
	Lighting - Lay-in	Gym- Office	2	EA	7	6-10 years		
	Power Distribution	Gym- Office	8	EA	7	10+ years		
	Walls - Concrete Block	Gym- Office	606	SF	7	10+ years		
	Ceiling - Lay-in	Kitchen Office 124	70	SF	6	10+ years		
	Doors - Steel Doors incl hw	Kitchen Office 124	1	EA	6	10+ years		
	Floor - Tile	Kitchen Office 124	70	SF	6	10+ years		
	Lighting - Lay-in	Kitchen Office 124	1	EΑ	6	6-10 years		
	Power Distribution	Kitchen Office 124	4	EA	6	10+ years		

Campus Name: Brighton Park Page : 25 of 39 Assessment Date: 12/19/2023



Category : Room			Building : Addition 2					
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	Kitchen Office 124	215	SF	6	10+ years		
0								
_Gymnas		0.15	4.074			40		
	Ceiling - Exposed	2nd Floor	4,074	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	160	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	5	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	4,234	SF	7	10+ years		
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	16	EA	7	6-10 years		
	Scoreboards	2nd Floor	1	EA	7	6-10 years		
	Sound System	2nd Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	8,384	SF	7	10+ years		
IV:taban								
_Kitchen_	Ceiling - Lay-in	1st Floor	1,218	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1,210	EA	6	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor	= = = = = = = = = = = = = = = = = = = =	SF	7			
		1st Floor	1,218	EA		10+ years		
	Lighting - Lay-in	1st Floor	8 278	SF	7	6-10 years		
	Storage/ Closet			SF SF	7 7	10+ years		
	Walls - Concrete Block	1st Floor	1,562	51	7	10+ years		
Locker/S	Shower Room							
	Accessories	Kitchen	73	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Kitchen	73	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Kitchen	1	ĒΑ	6	10+ years		
	Floor - Concrete Epoxy/ Painted	Kitchen	73	SF	7	10+ years		
	Floor Drain	Kitchen	1	ĒΑ	7	10+ years		
	Lavatory	Kitchen	1	EΑ	7	10+ years		
	Lighting - Lay-in	Kitchen	1	EΑ	7	6-10 years		
	Student Lockers - Two Tier	Kitchen	10	EΑ	7	6-10 years		
	Student Lockers - Two Tiers	Kitchen	5	EΑ	6	6-10 years		
	Walls - Concrete Block	Kitchen	150	SF	7	10+ years		
	Water Closet	Kitchen	1	EA	6	10+ years		
					-	<b>,</b>		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	5,095	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	9	SF	4	0-1 year	Damaged	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Tile	1st Floor	5,104	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	64	EA	6	6-10 years		
	Serving Line	1st Floor	36	LF	6	10+ years		
	Storage/ Closet	1st Floor	260	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	8,384	SF	6	10+ years		
						-		



Category : Room			Building : Addition 2					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
MDF_IDI								
	Doors - Steel Doors incl hw	215 2nd Floor	1	EA	7	10+ years		
	Finishes	215 2nd Floor	135	SF	7	10+ years		
	Other Cooling Unit	215 2nd Floor	1	EA	7	6-10 years	Fan Coil Unit.	
Mechanio	cal/ Service Rooms							
	Janitor's Closet	1st Floor	48	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	298	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	300	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	120	SF	5	10+ years		
	Storage Room	208 & 222 Storage	298	SF	7	10+ years		
	Storage Room	209 Storage	198	SF	7	10+ years		
	Janitor's Closet	213 Janitors Closet	18	SF	7	10+ years		
	Storage Room	216 science storage	84	SF	7	10+ years		
	Mechanical/ Service Rooms	221 Electrical closet	72	SF	7	10+ years		
	Storage Room	301 Storage room	185	SF	7	10+ years		
	Mechanical/ Service Rooms	306 mechanical room	1,014	SF	7	10+ years		
	Janitor's Closet	309 Janitors Closet	18	SF	7	10+ years		
Prep Roc	om.							
r rep rece	Ceiling - Lay-in	217 Science Prep Room	190	SF	6	10+ years		
	Doors - Wood Doors inclu hw	217 Science Prep Room	1	EA	7	10+ years		
	Floor - Tile	217 Science Prep Room	190	SF	7	10+ years		
	Lighting - Lay-in	217 Science Prep Room	2	EA	7	6-10 years		
	Walls - Concrete Block	217 Science Prep Room	330	SF	7	10+ years		
	Walls - Plaster/Drywall	217 Science Prep Room	100	SF	7	10+ years		
	Work Sink	217 Science Prep Room	1	EA	7	10+ years		
_						•		
Restroon								
	Accessories	1st Floor Boys	242	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Boys	242	SF	6	10+ years		
	Floor - Terrazzo	1st Floor Boys	242	SF	6	10+ years		
	Floor Drain	1st Floor Boys	2	EA	7	10+ years		
	Hand Dryer	1st Floor Boys	1	EA	7	10+ years		
	Lavatory	1st Floor Boys	3	EA	6	10+ years		
	Lighting - Lay-in	1st Floor Boys	5	EA	6	6-10 years		
	Partitions	1st Floor Boys	2	EA	7	10+ years		
	Urinals	1st Floor Boys	3	EA	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor Boys	500	SF	6	10+ years		
	Water Closet	1st Floor Boys	2	EA	6	10+ years		
	Accessories	1st Floor Girls	242	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Girls	242	SF	7	10+ years		
	Floor - Terrazzo	1st Floor Girls	242	SF	6	10+ years		



Category : Room			Building : Addition 2					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor Drain	1st Floor Girls	2	EA	7	10+ years		
	Hand Dryer	1st Floor Girls	1	EA	7	6-10 years		
	Lavatory	1st Floor Girls	3	EA	7	10+ years		
	Lighting - Lay-in	1st Floor Girls	5	EA	7	6-10 years		
	Partitions	1st Floor Girls	5	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor Girls	500	SF	7	10+ years		
	Water Closet	1st Floor Girls	5	EA	7	10+ years		
	Accessories	1st Floor-Unisex Staff Restroom	56	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-Unisex Staff Restroom	56	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-Unisex Staff Restroom	1	EA	6	10+ years		
	Floor - Terrazzo	1st Floor-Unisex Staff Restroom	56	SF	6	10+ years		
	Floor Drain	1st Floor-Unisex Staff Restroom	1	EA	7	10+ years		
	Lavatory	1st Floor-Unisex Staff Restroom	1	EA	6	10+ years		
	Lighting - Lay-in	1st Floor-Unisex Staff Restroom	1	EA	7	6-10 years		
	Walls - Structural Glazed Tile	1st Floor-Unisex Staff Restroom	130	SF	6	10+ years		
	Water Closet	1st Floor-Unisex Staff Restroom	1	EA	6	10+ years		
	Accessories	2nd Floor - Unisex Staff Restroom	56	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Unisex Staff Restroom	56	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - Unisex Staff Restroom	1	EA	7	10+ years		
	Floor - Terrazzo	2nd Floor - Unisex Staff Restroom	56	SF	7	10+ years		
	Floor Drain	2nd Floor - Unisex Staff Restroom	1	EA	7	10+ years		
	Lavatory	2nd Floor - Unisex Staff Restroom	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor - Unisex Staff Restroom	1	EA	7	6-10 years		
	Walls - Structural Glazed Tile	2nd Floor - Unisex Staff Restroom	130	SF	7	10+ years		
	Water Closet	2nd Floor - Unisex Staff Restroom	1	EA	7	10+ years		
	Accessories	2nd Floor Boys	242	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Boys	242	SF	7	10+ years		
	Floor - Terrazzo	2nd Floor Boys	242	SF	7	10+ years		
	Floor Drain	2nd Floor Boys	2	EA	7	10+ years		
	Hand Dryer	2nd Floor Boys	1	EA	7	10+ years		
	Lavatory	2nd Floor Boys	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor Boys	5	EA	7	6-10 years		
	Partitions	2nd Floor Boys	2	EA	7	10+ years		
	Urinals	2nd Floor Boys	3	EA	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor Boys	500	SF	7	10+ years		
	Water Closet	2nd Floor Boys	2	EA	7	10+ years		
	Accessories	2nd Floor Girls	242	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Girls	242	SF	7	10+ years		
	Floor - Terrazzo	2nd Floor Girls	242	SF	7	10+ years		
	Floor Drain	2nd Floor Girls	2	EA	7	10+ years		
	Hand Dryer	2nd Floor Girls	1	EA	7	6-10 years		
	Lavatory	2nd Floor Girls	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor Girls	5	EA	7	6-10 years		
	Partitions	2nd Floor Girls	5	EA	7	10+ years		
						·		



Category : Room			Building : Addition 2				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	2nd Floor Girls	500	SF	7	10+ years	
	Water Closet	2nd Floor Girls	5	EA	7	10+ years	
	Accessories	3rd Floor - Unisex Staff Restroom	56	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - Unisex Staff Restroom	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - Unisex Staff Restroom	1	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor - Unisex Staff Restroom	56	SF	7	10+ years	
	Floor Drain	3rd Floor - Unisex Staff Restroom	1	EA	7	6-10 years	
	Lavatory	3rd Floor - Unisex Staff Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor - Unisex Staff Restroom	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor - Unisex Staff Restroom	130	SF	7	10+ years	
	Water Closet	3rd Floor - Unisex Staff Restroom	1	ĒΑ	7	10+ years	
	Accessories	3rd Floor Boys	242	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boys	242	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor Boys	242	SF	7	10+ years	
	Floor Drain	3rd Floor Boys	2	EA	7	10+ years	
	Hand Dryer	3rd Floor Boys	1	EA	7	6-10 years	
	Lavatory	3rd Floor Boys	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor Boys	5	EΑ	7	10+ years	
	Partitions	3rd Floor Boys	2	EΑ	7	10+ years	
	Urinals	3rd Floor Boys	3	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys	500	SF	7	10+ years	
	Water Closet	3rd Floor Boys	2	EA	7	10+ years	
	Accessories	3rd Floor Girls	242	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Girls	242	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor Girls	242	SF	7	10+ years	
	Floor Drain	3rd Floor Girls	2	EA	7	10+ years	
	Hand Dryer	3rd Floor Girls	1	EA	7	6-10 years	
	Lavatory	3rd Floor Girls	3	EΑ	7	6-10 years	
	Lighting - Lay-in	3rd Floor Girls	5	EΑ	7	6-10 years	
	Partitions	3rd Floor Girls	5	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Girls	500	SF	7	10+ years	
	Water Closet	3rd Floor Girls	5	EA	7	10+ years	
	Accessories	Main Office Unisex	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Unisex	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office Unisex	1	EA	6	10+ years	
	Floor - Terrazzo	Main Office Unisex	44	SF	6	10+ years	
	Floor Drain	Main Office Unisex	1	EA	7	10+ years	
	Lavatory	Main Office Unisex	1	EA	6	10+ years	
	Lighting - Lay-in	Main Office Unisex	1	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Main Office Unisex	90	SF	6	10+ years	
	Water Closet	Main Office Unisex	1	EA	6	10+ years	
	Trator Oloot	Maiii Oilioo Oilioox	'		J	TOT years	
Catono	ry : Classroom		ь	uildina	: Additi	on 2	
	Item - Type	Location	Quantity	UOM		Recommend	Comments
Group	item - Type	LUCATION	Quantity	OOW	Kalik	Recommend	Comments



					Replacement	, ,
Classroom #113 (Regular Classroom)						
Casework	1st Floor	35	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	916	SF	6	10+ years	
Ceiling - Lay-in	1st Floor	4	SF	4	1-2 years	Damaged
Doors - Side-lite	1st Floor	12	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	. <u>-</u> 1	EΑ	7	10+ years	
Floor - Tile	1st Floor	920	SF	6	10+ years	
Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	10+ years	
Walls - Concrete Block	1st Floor	1,131	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	200	SF	6	10+ years	
_Classroom #130 (Other Instructional Use)						
Casework	1st Floor	20	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	420	SF	6	10+ years	
Chalk Board	1st Floor	12	LF	4	2-5 years	
Doors - Side-lite	1st Floor	12	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	420	SF	6	10+ years	
Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	10+ years	
Walls - Concrete Block	1st Floor	768	SF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	200	SF	7	10+ years	
Wallo T lactor/Bry Wall	10111001	200	O.	•	101 youro	
Classroom #131 (Regular Classroom)						
Casework	1st Floor	35	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	912	SF	6	10+ years	
Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Damaged
Doors - Side-lite	1st Floor	12	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	920	SF	6	10+ years	
Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Walls - Concrete Block	1st Floor	1,131	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	200	SF	6	10+ years	
Classroom #132 (Faculty Lounge)						
Casework	1st Floor	20	LF	7	10+ years	
Ceiling - Lay-in	1st Floor	420	SF	6	10+ years	
Chalk Board	1st Floor	12	LF	4	2-5 years	
Doors - Side-lite	1st Floor	12	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	420	SF	6	10+ years	
Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	



Schools Schools						S Washtenaw AVENUE, Chicago, IL 6
					Replacement	
Walls - Concrete Block	1st Floor	768	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	200	SF	7	10+ years	
·					•	
ssroom #202 (Faculty Lounge)						
Casework	2nd Floor	10	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	470	SF	6	10+ years	
Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
Floor - Tile	2nd Floor	470	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	5	EA	6	6-10 years	
Marker Board	2nd Floor	12	LF	6	6-10 years	
Walls - Concrete Block	2nd Floor	1,056	SF	6	10+ years	
					•	
ssroom #203 (Office)						
Casework	2nd Floor	7	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	420	SF	6	10+ years	
Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	420	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
Marker Board	2nd Floor	24	LF	7	6-10 years	
Storage/ Closet	2nd Floor	12	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	768	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
ssroom #204 (Computer Lab)						
Casework	2nd Floor	45	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	1,304	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Missing
Doors - Side-lite	2nd Floor	24	SF	7	10+ years	Wilsoning
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	1,312	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
Marker Board	2nd Floor	32	LF	6	6-10 years	
Walls - Concrete Block	2nd Floor	1,082	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
Walls Tlaster/Brywall	2110 1 1001	200	Oi.	,	101 years	
sroom #205 (Store Room)						
Casework	2nd Floor	35	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	885	SF	7	10+ years	
Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	2nd Floor	885	SF	7	6-10 years	
Floor - Carpet		000	٠.			
	2nd Floor	12	EA	7	6-10 years	



XII X SCHOOLS					3023	S Washtenaw AVENUE, Chicago, IL 6
					Replacement	
Storage/ Closet	2nd Floor	12	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	1,000	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
,					, , , , , ,	
assroom #210 (Regular Classroom)						
	0 151	050	05		40	
Ceiling - Lay-in	2nd Floor	952	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Damaged
Chalk Board	2nd Floor	8	LF	4	2-5 years	
Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
Floor - Tile	2nd Floor	960	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	13	EΑ	7	6-10 years	
Marker Board	2nd Floor	8	LF	7	6-10 years	
Walls - Concrete Block	2nd Floor	1,364	SF	7	10+ years	
		,			, , , , , ,	
assroom #218 (Art Room)						
Casework	2nd Floor	12	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	900	SF	6	10+ years	
Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	900	SF	6	,	
	2nd Floor 2nd Floor		EA	7	10+ years 6-10 years	
Lighting - Lay-in		14		7		
Marker Board	2nd Floor	24	LF	=	6-10 years	
Storage/ Closet	2nd Floor	330	SF	7	10+ years	
Student Lockers - One Tier	2nd Floor	2	EA	7	10+ years	
Walls - Concrete Block	2nd Floor	900	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
Work Sink	2nd Floor	4	EA	7	10+ years	
assroom #219 (Office)						
Casework	2nd Floor	35	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor 2nd Floor	4	SF	4	1-2 years	Damaged
Doors - Side-lite			SF	7	,	Damageu
	2nd Floor	24			10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	726	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
Marker Board	2nd Floor	24	LF	7	6-10 years	
Storage/ Closet	2nd Floor	12	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	1,010	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
assroom #220 (Other Instructional Use)						
Casework	2nd Floor	32	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	726	SF	6	•	
Coming - Lay-in	Z110 1 1001	120	OF-	U	10+ years	



						Ashlehaw Avenue, Chicago, in 6063.
					Replacement	
Doors - Transom Window	2nd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	726	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
Marker Board	2nd Floor	24	LF	7	6-10 years	
Storage/ Closet	2nd Floor	12	SF	7	10+ years	
Walls - Concrete Block	2nd Floor	1,210	SF	6	10+ years	
Walls - Collete block	2110 1 1001	1,210	OI	U	10+ years	
Classroom #303 (Regular Classroom)						
	3rd Floor	25	LF		10:	
Casework		35		6	10+ years	
Ceiling - Lay-in	3rd Floor	920	SF	6	10+ years	
Doors - Side-lite	3rd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Tile	3rd Floor	920	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	1,331	SF	7	10+ years	
		,,,,,			, , , , , , , , , , , , , , , , , , , ,	
lassroom #304 (Regular Classroom)						
Casework	3rd Floor	40	LF	6	10+ years	
Ceiling - Lay-in	3rd Floor	920	SF	6	10+ years	
Doors - Side-lite	3rd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Floor - Tile	3rd Floor	920	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	3rd Floor	24	LF	7	6-10 years	
Marker Board				-	-	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	1,331	SF	7	10+ years	
Classroom #305 (Regular Classroom)						
Casework	3rd Floor	40	LF	6	10+ years	
Ceiling - Lay-in	3rd Floor	920	SF	6	10+ years	
Doors - Transom Window	3rd Floor	24	SF	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	<u>•</u>	
		="	SF		10+ years	
Floor - Tile	3rd Floor	920		7	10+ years	
Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
Marker Board	3rd Floor	12	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	1,031	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	300	SF	7	10+ years	
Classroom #311 (Other Instructional Use)						
nassiooni #3 i i (Oniei instructional Ose)	3rd Floor	40	LF	6	10+ years	
Casaviant						
Casework Ceiling - Lay-in	3rd Floor 3rd Floor	12 420	SF	6	10+ years	



3CHOOIS						vashtenaw AVENUE, Chicago, IL 60632
					Replacement	
Doors - Transom Windo		24	SF	7	10+ years	
Doors - Wood Doors inc		1	EΑ	7	10+ years	
Floor - Tile	3rd Floor	420	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	768	SF	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	200	SF	7	10+ years	
Classroom #312 (Regular Classro	oom)					
Casework	3rd Floor	40	LF	6	10+ years	
Ceiling - Lay-in	3rd Floor	920	SF	6	10+ years	
Doors - Transom Windo		24	SF	7	10+ years	
Doors - Wood Doors in		1	EA	7	10+ years	
Floor - Tile	3rd Floor	920	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	1,331	SF	7	10+ years	
valio controlo biock	014 1 1001	1,001	O.	•	101 youro	
_Classroom #313 (Regular Classro						
Casework	3rd Floor	40	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	420	SF	6	10+ years	
Doors - Side-lite	3rd Floor	24	SF	7	10+ years	
Doors - Wood Doors inc	clu hw 3rd Floor	1	EA	7	10+ years	
Floor - Tile	3rd Floor	420	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	968	SF	7	10+ years	
Classroom #314 (Regular Classro	nom)					
Casework	3rd Floor	7	LF	7	10+ years	
Ceiling - Lay-in	3rd Floor	726	SF	6	10+ years	
Doors - Transom Windo		24	SF	7	10+ years	
Doors - Wood Doors in		1	EA	7	10+ years	
Floor - Tile	3rd Floor	726	SF	7	10+ years	
Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	12	SF	7	10+ years	
Walls - Concrete Block	3rd Floor	1,210	SF	7	10+ years	
Trails Control Blook	314 1 1001	1,210	٥.	•	10. 30010	



Catego	ry : Interior		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor	3,870	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Damaged	
	Doors - Side-lite	1st Floor	36	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years		
	Doors - Store Front	1st Floor	3	EA	7	10+ years		
	Doors - Transom Window	1st Floor	36	SF	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years		
	Floor - Terrazzo	1st Floor	3,886	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	23	EA	7	6-10 years		
	Stairs - Terrazzo	1st Floor	5	LF	7	10+ years		
	Walls - Concrete Block	1st Floor	5,386	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	2,175	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	8	EA	7	10+ years		
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years		
	Floor - Terrazzo	2nd Floor	2,175	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	3,200	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	2,150	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Damaged	
	Doors - Steel Doors incl hw	3rd Floor	8	EA	7	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years		
	Floor - Terrazzo	3rd Floor	2,166	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	17	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	2,660	SF	7	10+ years		
_Safety								
	Camera Viewing Station	Entire Building	2	EA	7	6-10 years		
	Security Cameras	Entire Building	7	EA	7	6-10 years		
	Security Cameras	Entire Building	1	EA	7	6-10 years		
Stairs								
	Ceiling - Lay-in	Stair 1	898	SF	7	10+ years		
	Floor - Terrazzo	Stair 1	1,196	SF	7	10+ years		
	Handrails	Stair 1	64	LF	7	10+ years		
	Lighting - Lay-in	Stair 1	10	EA	7	6-10 years		
	Stairs - Terrazzo	Stair 1	60	LF	7	10+ years		
	Walls - Concrete Block	Stair 1	2,715	SF	7	10+ years		
	Ceiling - Lay-in	Stair 2	898	SF	7	10+ years		
	Floor - Terrazzo	Stair 2	1,196	SF	7	10+ years		
	Handrails	Stair 2	64	LF	7	10+ years		
	Lighting - Lay-in	Stair 2	10	EA	7	6-10 years		
	Stairs - Terrazzo	Stair 2	60	LF	7	10+ years		



Catego	ry : Interior		Building : Addition 2						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	Stair 2	2,715	SF	7	10+ years			
	Ceiling - Lay-in	Stair 3	270	SF	7	10+ years			
	Floor - Concrete	Stair 3	414	SF	7	10+ years			
	Handrails	Stair 3	141	LF	7	10+ years			
	Lighting - Lay-in	Stair 3	6	EA	7	6-10 years			
	Stairs - Concrete	Stair 3	106	LF	7	10+ years			
	Walls - Concrete Block	Stair 3	838	SF	7	10+ years			
Vertical C	Conveyance								
	Elevator - Hydraulic Elevator	1st to 3rd floor	1	EA	7	10+ years			

Campus Name: Brighton Park Page : 36 of 39 Assessment Date: 12/19/2023



Category : Site Building : Site

Hom Tune	Logotion	Ouantitu	ПОМ	Donk	Recommend	Comments
	Location	Quantity	UOW	Rank	Replacement	Comments
Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	One has been repaired, not level wit
						surface
Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	10+ years	
Foncing Chain Link	Entiro Sito	145	16	1	0.1 year	Rusted, detached fencing and pole
						Rusteu, detached fericing and pole
rending - New Standard Ornamental	Little Site	002	LF	O	10+ years	
De .						
Benches	Entire Site	11	EA	6	10+ years	
Landscape - Hardscape- Asphalt	Entire Site	3,000	SF	5	2-5 years	Some repair. Floods from alley
Landscape - Hardscape- Concrete	Entire Site	3,770	SF	6	2-5 years	
Landscape - Hardscape- Pavers	Entire Site	1,950	SF	7	10+ years	
Landscape - Mulch	Entire Site	2,760	SF	7	6-10 years	
	Entire Site	19	EA	7	10+ years	Corrected quantity
Parkway trees	Entire Site	1	EA	4	0-1 year	Missing
Play Area - Hardscape- Asphalt	Entire Site	660	SF	6	2-5 years	Minor cracks
	Entire Site	250	SF	6		
Trash Receptacles	Entire Site	4	EA	6	10+ years	
ot						
	Parking Lot - Northwest	375	l F	6	6-10 years	Divided quantity between parking lot
						Corrected quantity
						Power supply cut
						Drain area repaired
					•	Brain area repaired
						Divided between parking lots
						Alligator cracking
Canada Alophian	9 _00	_,, 0.	٥.	•	o . you.	· ····gator oraci.····g
		1				
Equipment - School Age 5-12		1				
Surface - Poured Surface	West	2,325	SF	7	10+ years	
Sarage						
Service Garage - Free-Standing	Entire Site	396	SF	5	2-5 years	
0						
Sidewalks - Internal Walks	Entire Site	290	LF	6	10+ years	
	Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Pavers Landscape - Mulch Parkway trees Parkway trees Play Area - Hardscape- Asphalt Retaining Wall - Masonry Trash Receptacles  Lot Concrete Curbs Interior Plantings Lighting - Pole Mounted Surface - Asphalt Vehicular Screening Concrete Curbs Surface - Asphalt  Vehicular Screening Concrete Curbs Surface - Asphalt  Ind Equipment - Pre K 3-5 Equipment - School Age 5-12 Surface - Poured Surface  Garage Service Garage - Free-Standing	Civil/ Drainage - Catch Basin Entire Site Civil/ Drainage - Catch Basin Entire Site  Civil/ Drainage - Site Manhole Entire Site  Fencing - Chain Link Entire Site Fencing - New Standard Ornamental Entire Site  Benches Entire Site  Entire Site  Benches Entire Site Landscape - Hardscape- Asphalt Entire Site Landscape - Hardscape- Pavers Entire Site Landscape - Hardscape- Pavers Entire Site Parkway trees Entire Site Parkway trees Entire Site Play Area - Hardscape- Asphalt Entire Site Retaining Wall - Masonry Entire Site Retaining Wall - Masonry Entire Site  Lot  Concrete Curbs Parking Lot - Northwest Interior Plantings Parking Lot - Northwest Surface - Asphalt Parking Lot - South Surface - Asphalt Parking Lot - South Parking Lot - Sou	inage Civil/ Drainage - Catch Basin Civil/ Drainage - Catch Basin Entire Site Entire Site 1 Civil/ Drainage - Site Manhole Entire Site Entire Site 10  Fencing - Chain Link Fencing - New Standard Ornamental Entire Site Intire Site Inti	inage Civil/ Drainage - Catch Basin Civil/ Drainage - Catch Basin Entire Site Entire Site 1 EA  Civil/ Drainage - Site Manhole Entire Site Entire Site 10 EA  Fencing - Chain Link Fencing - New Standard Ornamental Entire Site Entire Si	Civil/ Drainage - Catch Basin Entire Site 2 EA 6 Civil Drainage - Catch Basin Entire Site 1 EA 4 Civil/ Drainage - Catch Basin Entire Site 1 EA 4 Civil/ Drainage - Site Manhole Entire Site 10 EA 6 Entire Site 11 EA 6 EA	Civil/ Drainage - Catch Basin



Categor	Category : Site			Building : Site				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Sidewalks - Internal Walks	Entire Site	20	LF	4	0-1 year	Cracks	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,300	SF	6	10+ years		
Signage								
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years		
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	6	6-10 years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	6	10+ years	Divided quantities	
	Monument - Sign	Entire Site	1	EA	6	10+ years		

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Brighton Park Page : 38 of 39 Assessment Date: 12/19/2023

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom

Store Room

Regular Classroom

Regular Classroom
Regular Classroom

Regular Classroom

Library

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	,	-	<u>'</u>	•					
Kindergarten	Regular Classroom	1st Floor	101	101	715	72	22	N	N
Kindergarten	Regular Classroom	1st Floor	148	148	765	132	58	N	N
Regular Classroom	Office	2nd Floor	228	228	150	104	52	Υ	Υ
Regular Classroom	Office	2nd Floor	229	229	350	104	52	N	N
Regular Classroom	Regular Classroom	1st Floor	138	138	715	33	17	N	N
Regular Classroom	Regular Classroom	1st Floor	143	143	765	132	58	N	N
Regular Classroom	Regular Classroom	1st Floor	144/145	144	350	52	26	N	N
Regular Classroom	Regular Classroom	1st Floor	146	146/147	700	104	52	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	225	715	33	17	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	765	132	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	232/ 231	232/ 231	700	104	52	N	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	765	132	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	234	234	715	105	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	235	235	715	105	50	N	N
Building : Addition 2									
Art Room	Science	2nd Floor	218	218	900	144	18	Y	N
Computer Lab	Computer Lab	2nd Floor	204	204	1,312	216	27	Υ	Υ
Faculty Lounge	Regular Classroom	1st Floor	132	132	420	72	9	Υ	N
Faculty Lounge	Regular Classroom	2nd Floor	202	202	470	96	12	Υ	N
Office	Computer Lab	2nd Floor	203	203	420	72	9	Υ	N
Office	Regular Classroom	2nd Floor	219	219	726	144	18	Υ	N
Other Instructional Use	Regular Classroom	1st Floor	130	130	420	72	9	Υ	N
Other Instructional Use	Regular Classroom	2nd Floor	220	220	726	144	18	Υ	N
Other Instructional Use	Regular Classroom	3rd Floor	311	311	420	72	9	Υ	N
Regular Classroom	Regular Classroom	1st Floor	113	113	920	144	18	Υ	N
Regular Classroom	Regular Classroom	1st Floor	131	131	920	144	18	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	960	144	18	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	920	144	18	Y	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	920	144	18	Υ	N

305

312

313

314

205

305

312

313

314

205

920

920

420

726

885

144

144

72

144

144

18

18

9

18

18

Ν

Ν

Ν

Ν

Ν

Υ

Υ

3rd Floor

3rd Floor

3rd Floor

3rd Floor

2nd Floor