

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	2	55,812
Field House	1924	1	2,715
Campus Total			58,527

Catego	ry : Exterior		В	uilding	: Main		
		1	0			Recommend	<b>2</b>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Entire Building	6	EΑ	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	3	EA	7	10+ years	
Entrance	3						
	Entrance Control - Audio and Video	#1 SE	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#1 SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 SE	1	EA	6	10+ years	
	Power Door Operator and Controls	#1 SE	2	EA	7	10+ years	
	Ramps - Concrete	#1 SE	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10 Fire Escape	1	EA	7	6-10 years	
	Exterior Doors - Transom Lite	#10 Fire Escape	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 Fire Escape	1	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2 S	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#2 S	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#2 S	3	LF	7	10+ years	
	Power Door Operator and Controls	#2 S	1	EA	7	6-10 years	Not previously assessed
	Exterior Doors - Exterior FRP Door	#3 SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 SW	7	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#4 NW	2	EA	5	1-2 years	Corroded door frame at center
	Exterior Doors - Transom Lite	#4 NW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#4 NW	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#5 W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.5 N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#5.5 N	10	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	#6 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 N	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 E	5	LF	7	10+ years	
	Entrance Control - Audio and Video	#8 NE	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#8 NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 NE	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9 Fire escape	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9 Fire escape	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9 Fire escape	3	LF	6	10+ years	
						, , , , , ,	
Fire Esca	•	N d E				0.40	
	Exterior Doors - Exterior Steel Door	North Façade	2	EA	6	6-10 years	
	Fire Escape	North Façade	90	LF	6	10+ years	
	Paints	North Façade	90	LF	5	2-5 years	
Foundati	ion						
	Foundation - Masonry	Entire Building	660	LF	7	10+ years	Recombined quantities. corrected designation
	Superstructure - Heavy Timber	Entire Building	51,472	SF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	4,340	SF	7	10+ years	
Lighting							
-0 0	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
Roof Sys	stem						
	Coping - Stone	#1	61	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#1	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#1	61	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#1	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#1	386	SF	7	10+ years	
	Access Ladder - Metal	#2	1	EΑ	5	2-5 years	
	Access Ladder - Wood	#2	1	EA	4	0-1 year	This ladder is the old ladder that goes
							from the third-floor up to the ceiling. Very difficult to climb. Limited to hold,
	Carina Clay Tile	<b>#</b> 0	407		0	40	dangerous.
	Coping - Clay Tile	#2 #2	167	LF LF	6	10+ years	
	Downspouts - Exterior Downspouts		78		6	10+ years	

Campus Name: Burley Page : 2 of 31 Assessment Date: 12/18/2023



Catego	ry : Exterior		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	#2	167	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#2	100	SF	6	1-2 years	Open joints, deteriorated mortar
	Roof - Asphalt Gravel Ballast	#2	3,100	SF	6	10+ years	
	Roof Hatch - Metal	#2	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#2	3,200	SF	7	10+ years	
	Access Ladder - Metal	#3	1	EA	5	2-5 years	Galvanized steel pipe with rebar ladder
	Access Ladder - Wood	#3	1	EA	4	0-1 year	This ladder is similar to ladder to the roof 4. Dangerous
	Chimney - Brick Chimney- Concrete/ Mortar Liner	#3	40	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	#3	10	LF	5	1-2 years	Cracked brick
	Coping - Clay Tile	#3	366	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#3	84	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	83	LF	5	1-2 years	Open joints, deteriorated mortar
	Parapet - Parapet > 30"	#3	143	LF	6	10+ years	open jemie, actemerates menta.
	Parapet - Parapet > 30"	#3	40	LF	5	1-2 years	Open joints, deteriorated mortar
	Roof - Asphalt Gravel Ballast	#3	6,478	SF	6	6-10 years	opon jointo, actoriorated mortar
	Roof - Asphalt Gravel Ballast	#3	200	SF	5	1-2 years	Sealant at counter flashing is worn out throughout this roof
	Roof Hatch - Metal	#3	1	EA	7	10+ years	out an oughout and roof
	Roof Structure - Heavy Timber	#3	6,678	SF	7	10+ years	
	Access Ladder - Metal	#4	1	ĒΑ	5	2-5 years	Galvanized steel with rebar ladder
	Access Ladder - Wood	#4	1	EA	4	0-1 year	Old wooden ladders. Did not visit this roof because the access looked dangerous. Images are from above, from roof number three. In general, it all up Ruth's, the sealant is worn out at the counter flashing.
	Coping - Clay Tile	#4	130	LF	6	10+ years	
	Coping - Clay Tile	#4	5	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#4	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4	135	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#4	3,518	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	#4	100	SF	4	0-1 year	Did not visit this roof because the access looked dangerous. Images are from above, from roof number three. In general, it all up Ruth's, the sealant is worn out at the counter flashing.
	Roof Hatch - Metal	#4	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#4	3,618	SF	7	10+ years	

Campus Name: Burley Page : 3 of 31 Assessment Date: 12/18/2023



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	#5	63	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#5	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#5	63	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#5	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#5	386	SF	7	10+ years	
	Coping - Clay Tile	#6	339	LF	6	10+ years	
	Coping - Clay Tile	#6	3	LF	6	6-10 years	Not observed
	Downspouts - Exterior Downspouts	#6	52	LF	6	10+ years	
	Parapet - 16" - 30" Height	#6	20	LF	5	1-2 years	Joints
	Parapet - Parapet < 16" Height	#6	322	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#6	3,277	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#6	500	SF	4	1-2 years	Large area of moss, growing vegetation, missing ballast
	Roof - Modified Bitumen	#6	200	SF	6	10+ years	3
	Roof Structure - Steel with Clay Tile Arch	#6	3,977	SF	7	10+ years	
alls							
	Cornice - Masonry Projecting Limestone	Entire Building	252	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,166	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	50	LF	4	0-1 year	Missing sections, peeling, deteriorating sealant
	Exterior Walls - Brick	Entire Building	16,365	SF	6	10+ years	•
	Exterior Walls - Brick	Entire Building	2,888	SF	4	0-1 year	Open joints
	Exterior Walls - Precast Panel Wall	Entire Building	480	SF	6	10+ years	. ,
	Exterior Walls - Stone-Cut	Entire Building	3,332	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	100	SF	5	10+ years	
indows							
	Guard - Guards perforated	Entire Building	2,185	SF	6	10+ years	
	Lintels - Brick	Entire Building	145	LF	6	10+ years	
	Lintels - Brick	Entire Building	12	LF	5	1-2 years	Art brick lintels are cracked
	Lintels - Brick	Entire Building	4	LF	4	1-2 years	Loose bricks at lintel
	Lintels - Steel	Entire Building	9	LF	6	10+ years	
	Lintels - Stone	Entire Building	715	LF	6	10+ years	
	Windows - Decorative	Entire Building	528	SF	6	10+ years	
	Windows - Louver	Entire Building	60	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,321	SF	6	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	2-5 years	



ategory	y : Electrical		R	uilding	· Main		1630 W Barry AVENUE, Chicago, it 6063
alegory	y . Licoti icai		D	unung	. Iviaiii	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	55,812	SF	5	2-5 years	Exterior cameras only
	Security System - Intrusion Detection	Entire Building	55,812	SF	5	6-10 years	Exterior carrierae erriy
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	7	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building  Entire Building	14	EA	6	•	
	Stairs	· ·	14			6-10 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	7	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,330	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	6,207	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	870	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,546	SF	6	6-10 years	
lain Serv		<b>3</b>	,			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Independent Electrical Service for	Boiler Room	1	EA	6	6-10 years	
	emergency power						
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH						
	PA System	Entire Building	55,812	SF	4	1-2 years	Obsolete
	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	
ategory	y : Fire Protection		В	uilding	: Main		
				J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alarm							
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building  Entire Building	18,000	SF	6	6-10 years	
	Fire Alarm_System	Entire Building Entire Building	55,812	SF		6-10 years	
			55,612		6 4		Obsolata
	Fire Pump Controller	Entire Building	1	EA	4	1-2 years	Obsolete
_	om Assembly						



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Pump - 25-50 hp	Basement	1	EA	5	2-5 years	
Sprinkler	System						
	Dry Sprinkler System	Electrical Room	55,812	SF	5	6-10 years	
	Sprinkler Heads	Electrical Room	55,812	SF	4	2-5 years	Sprinkler heads are old
	Sprinkler Piping	Electrical Room	55,812	SF	5	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10+ years	
	than 5 tons						
	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10+ years	
	than 5 tons	M : D (	<u>.</u>	_ ^	•	40	
	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10+ years	
	than 5 tons Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10	
	than 5 tons	Maili Rooi	Į	EA	O	10+ years	
	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10+ years	
	than 5 tons	Wall Roof	ı	LA	U	10+ years	
	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	6	10+ years	
	than 5 tons					, , , , , ,	
۸: ا ام ما	line Customs						
Air Hand	ling Systems  Air Handling Unit- Built Up-Multi Zone-	Dagament	1	EA	5	6-10 years	
	Double Delivery- Steam Coils - 30001 -	Basement	I	EA	5	6-10 years	
	45000 cfm						
	Air Intake	Basement	1	EA	5	6-10 years	
	Auxiliaries - 30001 - 45000 cfm	Basement	1	EA	5	2-5 years	
	Return Duct Work - Masonry and Ducts-	Basement	100	LF	5	6-10 years	
	Missing or Existing Shaft						
	Zone Dampers	Basement	27	EA	5	2-5 years	
	Fan Coil Unit- Celing Mounted - Electric	Gym	1	EA	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric	Gym	1	EΑ	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric	Gym	1	EΑ	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric	Gym	1	EΑ	6	10+ years	
	Fan Coil Unit- Celing Mounted - Electric Fan Coil Unit- Celing Mounted - Electric	Gym	1	EA EA	6 6	10+ years	
	ran con onit- cening Mounted - Electric	Gym	1	EA	0	10+ years	
Boiler Sy	estems						
,	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP						



\_Piping\_

Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers

#### Augustus H Burley Elementary School 1630 W Barry AVENUE, Chicago, IL 60657

Catego	ry : Mechanical		В	uilding	: Main		1030 W Barry AVENUE, Chicago, in 00037
- Cuitge	.,		_	······		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	5	2-5 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	<u> </u>				•	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	<u> </u>				•	
	Piping - Condensate Pipe- Steel	Entire Building	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	400	LF	6	6-10 years	
	Steam Traps	Entire Building	45	EA	5	6-10 years	
_Heating_	Davicas						
пеашу	Unit Heater - Electric	Entire Building	1	EA	5	6-10 years	Currently not operational/needs repair
	Unit Heater - Gas	Entire Building	1	ΕA	5	6-10 years	
	Unit Heater - Steam	Entire Building	1	EA	5	2-5 years	Dated
	Radiators - Steam	Entire Building	4	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	17	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	1	EA	4	1-2 years	Missing cover exposing live wires
Tempera	ature Control						
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Unit heaters and exhaust fan
	Pneumatic System	Entire Building	55,912	SF	5	6-10 years	orne ricatoro ana oxiliadot lari
	Thermostats - Pneumatic	Entire Building	12	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	15	EA	5	2-5 years	
Ventilatio	on.						
_verman	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	
	CFM	<u> </u>				,	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	4	1-2 years	Excessive vibration
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	3	0-1 year	Damaged and buzzing noise
•			_				
Catego	ry : Plumbing		В	uilding	: Main	December 1	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate			- Judinity	<b>J J</b>		. top.a.somonic	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	10+ years	

Campus Name: Burley Page : 7 of 31 Assessment Date: 12/18/2023

SF SF

6

6

55,812

55,812

10+ years

10+ years

Entire Building Entire Building



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	55,812	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	55,812	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	55,812	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	55,812	SF	6	10+ years	Newer piping and insulation installed
	Sanitary Piping	Entire Building	55,812	SF	5	6-10 years	
	Storm Piping	Entire Building	55,812	SF	5	6-10 years	
	Vent Piping	Entire Building	55,812	SF	5	6-10 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	6	6-10 years	

Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st Floor - Main Office 103	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Main Office 103	389	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Main Office 103	70	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Main Office 103	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office 103	1	EA	6	10+ years	
	Floor - Wood	1st Floor - Main Office 103	389	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - Main Office 103	7	EA	6	10+ years	
	Power Distribution	1st Floor - Main Office 103	8	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office 103	400	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor - Main Office 103	450	SF	6	10+ years	
	AC Unit	1st Floor - Meeting Room	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Meeting Room	264	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Meeting Room	1	EA	6	10+ years	
	Floor - Wood	1st Floor - Meeting Room	264	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - Meeting Room	4	EA	7	10+ years	
	Power Distribution	1st Floor - Meeting Room	8	EA	7	10+ years	
	Storage/ Closet	1st Floor - Meeting Room	95	SF	7	10+ years	
	Storage/ Closet	1st Floor - Meeting Room	78	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Meeting Room	646	SF	6	10+ years	
	AC Unit	1st floor - Principal office	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st floor - Principal office	350	SF	7	10+ years	
	Doors - Transom Window	1st floor - Principal office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor - Principal office	2	EA	6	10+ years	
	Floor - Wood	1st floor - Principal office	350	SF	7	10+ years	
	Lighting - Lay-in	1st floor - Principal office	8	EA	7	6-10 years	

Campus Name: Burley Page : 8 of 31 Assessment Date: 12/18/2023



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	1st floor - Principal office	6	EA	7	10+ years	
	Storage/ Closet	1st floor - Principal office	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor - Principal office	820	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor- Office 209	170	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor- Office 209	1	EA	7	10+ years	
	Floor - Tile	2nd Floor- Office 209	170	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor- Office 209	2	EA	7	6-10 years	
	Power Distribution	2nd Floor- Office 209	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor- Office 209	743	SF	7	10+ years	
	AC Unit	Basement - 002A counselor office	1	EA	7	6-10 years	
	Ceiling - Exposed	Basement - 002A counselor office	350	SF	7	10+ years	
	Doors - Side-lite	Basement - 002A counselor office	24	SF	7	10+ years	Not previously assessed
	Doors - Transom Window	Basement - 002A counselor office	3	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	Basement - 002A counselor office	1	EA	6	10+ years	•
	Floor - Tile	Basement - 002A counselor office	350	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - 002A counselor office	6	EA	7	6-10 years	
	Power Distribution	Basement - 002A counselor office	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - 002A counselor office	710	SF	7	10+ years	
	Work SInk	Basement - 002A counselor office	1	EA	7	6-10 years	
	AC Unit	Basement - 004 Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - 004 Teacher's Lounge	285	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - 004 Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement - 004 Teacher's Lounge	285	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - 004 Teacher's Lounge	6	EA	6	10+ years	
	Power Distribution	Basement - 004 Teacher's Lounge	18	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement - 004 Teacher's Lounge	720	SF	6	10+ years	
	Work SInk	Basement - 004 Teacher's Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement - Engineer's Office	175	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Basement - Engineer's Office	175	SF	6	10+ years	
	Lighting - Lay-in	Basement - Engineer's Office	2	EA	6	10+ years	
	Power Distribution	Basement - Engineer's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	425	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	10	SF	5	1-2 years	Cracking plaster
	Ceiling - Exposed	Basement - Lunchroom Office	125	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Lunchroom Office	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	Basement - Lunchroom Office	125	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Lunchroom Office	2	EA	6	10+ years	
	Power Distribution	Basement - Lunchroom Office	6	EA	6	10+ years	
	Walls - Masonry	Basement - Lunchroom Office	240	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Lunchroom Office	240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Speech Therapist Office	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Speech Therapist Office	1	ĒΑ	6	10+ years	
	Floor - Concrete	Basement - Speech Therapist Office	44	SF	7	10+ years	
		•				·	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete	Basement - Speech Therapist Office	8	SF	5	1-2 years	Cracks, spalling
	Lighting - Pendent/Surface	Basement - Speech Therapist Office	1	EA	6	10+ years	
	Power Distribution	Basement - Speech Therapist Office	2	EA	6	10+ years	
	Walls - Metal Panel	Basement - Speech Therapist Office	170	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Speech Therapist Office	145	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Speech Therapist Office	25	SF	5	1-2 years	Cracking plaster
Gymnas	ia						
-	Ceiling - Plaster/Drywall	3rd Floor	3,255	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	7	10+ years	
	Floor - Wood	3rd Floor	3,255	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	6-10 years	
	Scoreboards	3rd Floor	1	EΑ	7	6-10 years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Stage	3rd Floor	550	SF	7	10+ years	
	Stage Curtain	3rd Floor	3	EA	7	10+ years	
	Stage Cultain Stage Lighting System	3rd Floor	1	EA	7	6-10 years	
				LF			
	Stage-Stairs - Asphalt Walls - Plaster/Drywall	3rd Floor	10	SF	7 7	10+ years	
	Walls - Flastel/Drywall	3rd Floor	4,965	SF	,	10+ years	
Lunch &	Multipurpose Room						
	AC Unit	Basement - N Lunchroom	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - N Lunchroom	870	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - N Lunchroom	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement - N Lunchroom	870	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - N Lunchroom	19	ĒΑ	6	10+ years	
	Storage/ Closet	Basement - N Lunchroom	65	SF	7	10+ years	
	Walls - Masonry	Basement - N Lunchroom	1,212	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - N Lunchroom	200	SF	7	10+ years	
	AC Unit	Basement - S Lunchroom/warming	2	EA	7	6-10 years	
	Ceiling - Lay-in	kitchen Basement - S Lunchroom/warming	1,210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	kitchen Basement - S Lunchroom/warming	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	kitchen Basement - S Lunchroom/warming kitchen	1,210	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - S Lunchroom/warming kitchen	27	EA	6	10+ years	
	Serving Line	Basement - S Lunchroom/warming kitchen	13	LF	6	6-10 years	
	Walls - Masonry	Basement - S Lunchroom/warming	750	SF	6	10+ years	

Campus Name: Burley Page : 10 of 31 Assessment Date: 12/18/2023



Category : Room		В	uilding	: Main	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	пеш - туре	kitchen	Quantity	COM	IVALIK	Replacement	Comments
	Walls - Plaster/Drywall	Basement - S Lunchroom/warming kitchen	1,083	SF	6	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	143	SF	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	14	SF	7	10+ years	
	Storage Room	1st Floor	100	SF	7	6-10 years	Main Office Store Room
	Janitor's Closet	2nd Floor	14	SF	5	10+ years	Wall and ceiling paint is cracking
	Janitor's Closet	3rd Floor	15	SF	7	10+ years	
	Storage Room	3rd Floor	75	SF	7	10+ years	
	Storage Room	3rd Floor	75	SF	5	10+ years	Door and frame are severely worn
	Air Intake Plenums	Basement	320	SF	7	10+ years	
	Air Tunnel	Basement	340	SF	7	10+ years	
	Boiler Room	Basement	1,798	SF	7	6-10 years	Updated to match current observations
	Janitor's Closet	Basement	20	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	75	SF	5	10+ years	Spalling masonry Corrected ratings
	Mechanical/ Service Rooms	Basement	250	SF	5	10+ years	Spalling masonry. Corrected ratings
	Mechanical/ Service Rooms	Basement	145	SF	5	10+ years	Spalling masonry Corrected ratings
	Storage Room	Basement	100	SF	7	6-10 years	
	Storage Room	Basement	180	SF	7	6-10 years	
	Storage Room	Basement	455	SF	7	10+ years	
	Storage Room	Basement	172	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor - Men's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men's Staff Restroom	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men's Staff Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Men's Staff Restroom	162	SF	6	6-10 years	
	Hand Dryer	1st Floor - Men's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor - Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Men's Staff Restroom	2	EA	6	10+ years	
	Partitions	1st Floor - Men's Staff Restroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor - Men's Staff Restroom	2	EA	6	6-10 years	
	Accessories	1st Floor - Women's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Women's Staff Restroom	162	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Women's Staff Restroom	8	SF	6	10+ years	



Catego	Category : Room			uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor - Women's Staff Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Women's Staff Restroom	162	SF	6	10+ years	
	Hand Dryer	1st Floor - Women's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor - Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Women's Staff Restroom	2	EA	6	10+ years	
	Partitions	1st Floor - Women's Staff Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Women's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor - Women's Staff Restroom	2	EA	6	6-10 years	
	Accessories	2nd Floor-Boys Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Boys Restroom	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Boys Restroom	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor-Boys Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Boys Restroom	2	EA	7	10+ years	
	Hand Dryer	2nd Floor-Boys Restroom	2	EA	7	6-10 years	
	Lavatory	2nd Floor-Boys Restroom	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Boys Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Boys Restroom	3	EA	7	10+ years	
	Urinals	2nd Floor-Boys Restroom	7	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Boys Restroom	267	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Boys Restroom	534	SF	6	10+ years	
	Water Closet	2nd Floor-Boys Restroom	3	EA	6	6-10 years	
	Accessories	2nd Floor-Girls Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Girls Restroom	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Girls Restroom	2	EA	7	10+ years	
	Hand Dryer	2nd Floor-Girls Restroom	2	EA	7	6-10 years	
	Lavatory	2nd Floor-Girls Restroom	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Girls Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Girls Restroom	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	534	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	2	SF	5	1-2 years	Wall tiles are cracked
	Water Closet	2nd Floor-Girls Restroom	9	EA	6	6-10 years	
	Accessories	2nd Floor-Unisex Restroom	123	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Unisex Restroom	123	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Unisex Restroom	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor-Unisex Restroom	123	SF	7	10+ years	
	Hand Dryer	2nd Floor-Unisex Restroom	1	EΑ	7	6-10 years	
	Lavatory	2nd Floor-Unisex Restroom	2	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor-Unisex Restroom	2	EA	7	10+ years	
	Partitions	2nd Floor-Unisex Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Unisex Restroom	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Unisex Restroom	173	SF	7	10+ years	
	Water Closet	2nd Floor-Unisex Restroom	2	ĒΑ	6	6-10 years	
			_		-	<b>,</b>	

Campus Name: Burley Page : 12 of 31 Assessment Date: 12/18/2023



Catego	ry : Room		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Basement - Boy's Restroom	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Boy's Restroom	152	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Boy's Restroom	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Boy's Restroom	152	SF	7	10+ years	
	Floor Drain	Basement - Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement - Boy's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement - Boy's Restroom	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Boy's Restroom	3	EΑ	6	10+ years	
	Partitions	Basement - Boy's Restroom	4	EΑ	7	10+ years	
	Urinals	Basement - Boy's Restroom	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Boy's Restroom	165	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - Boy's Restroom	430	SF	6	10+ years	
	Water Closet	Basement - Boy's Restroom	4	EΑ	6	6-10 years	
	Accessories	Basement - Engineer's Restroom	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Restroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Engineer's Restroom	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Engineer's Restroom	50	SF	6	10+ years	
	Floor Drain	Basement - Engineer's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement - Engineer's Restroom	1	EA	7	6-10 years	
	Lavatory	Basement - Engineer's Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement - Engineer's Restroom	1	EA	6	10+ years	
	Showers	Basement - Engineer's Restroom	1	EA	5	1-2 years	Missing hardware
	Walls - Plaster/Drywall	Basement - Engineer's Restroom	285	SF	6	10+ years	wissing nardware
	Walls - Plaster/Drywall	Basement - Engineer's Restroom	30	SF	5	10+ years	Cracking plaster around pipework,
	·	· ·	30	-		10+ years	Corrected rating
	Walls - Tile Ceramic/ Porcelain	Basement - Engineer's Restroom	65	SF	6	10+ years	
	Water Closet	Basement - Engineer's Restroom	1	EA	6	6-10 years	
	Accessories	Basement - Girl's Restroom	510	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Girl's Restroom	460	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Girl's Restroom	50	SF	4	1-2 years	Water damage cracking
	Doors - Wood Doors inclu hw	Basement - Girl's Restroom	2	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Girl's Restroom	510	SF	6	10+ years	
	Floor Drain	Basement - Girl's Restroom	2	EA	7	10+ years	
	Hand Dryer	Basement - Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement - Girl's Restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement - Girl's Restroom	7	EA	6	10+ years	
	Partitions	Basement - Girl's Restroom	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Girl's Restroom	365	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - Girl's Restroom	800	SF	6	10+ years	
	Water Closet	Basement - Girl's Restroom	10	EA	6	6-10 years	
	Accessories	Basement - Men's Staff Restroom	155	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Men's Staff Restroom	155	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Men's Staff Restroom	2	ĒΑ	6	10+ years	
	Floor - Tile	Basement - Men's Staff Restroom	70	SF	6	10+ years	
	<del></del>				-	,	

Campus Name: Burley Page : 13 of 31 Assessment Date: 12/18/2023



Catego	ategory : Room		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Basement - Men's Staff Restroom	85	SF	6	10+ years	
	Floor Drain	Basement - Men's Staff Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement - Men's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	Basement - Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Men's Staff Restroom	2	EA	6	10+ years	
	Lighting - Wall Mounted	Basement - Men's Staff Restroom	1	EΑ	6	10+ years	
	Partitions	Basement - Men's Staff Restroom	2	EA	7	10+ years	
	Urinals	Basement - Men's Staff Restroom	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement - Men's Staff Restroom	365	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - Men's Staff Restroom	225	SF	6	10+ years	
	Water Closet	Basement - Men's Staff Restroom	2	EA	6	6-10 years	
	Accessories	Basement - Women's Staff	145	SF	7	6-10 years	
		Restroom				, , , , , , ,	
	Ceiling - Plaster/Drywall	Basement - Women's Staff	145	SF	6	10+ years	
	Coming Tractor, 21, wan	Restroom	0	٥.	Ŭ	ioi youro	
	Doors - Wood Doors inclu hw	Basement - Women's Staff	2	EA	6	10+ years	
	Doors Wood Doors mold riw	Restroom	_	L/\	O	101 years	
	Floor - Tile	Basement - Women's Staff	60	SF	6	10+ years	
	1 loor - Tile	Restroom	00	01	U	TOT years	
	Floor - Tile Ceramic/ Porcelain	Basement - Women's Staff	85	SF	6	10 L Vooro	
	Floor - The Ceramic/ Porcelain		65	SF	O	10+ years	
	Hand Dave	Restroom	4	<b>-</b> ^	7	C 40	
	Hand Dryer	Basement - Women's Staff	1	EA	7	6-10 years	
		Restroom	4	_ ^	•	0.40	
	Lavatory	Basement - Women's Staff	1	EA	6	6-10 years	
		Restroom	_		_		
	Lighting - Pendent/Surface	Basement - Women's Staff	2	EA	7	10+ years	
		Restroom			_		
	Lighting - Wall Mounted	Basement - Women's Staff	1	EA	7	10+ years	
		Restroom					
	Partitions	Basement - Women's Staff	2	EA	7	10+ years	
		Restroom					
	Walls - Plaster/Drywall	Basement - Women's Staff	345	SF	6	10+ years	
		Restroom					
	Walls - Tile Ceramic/ Porcelain	Basement - Women's Staff	255	SF	6	10+ years	
		Restroom					
	Water Closet	Basement - Women's Staff	2	EΑ	6	6-10 years	
		Restroom				•	
	Accessories	Main Office	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	51	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	51	SF	7	10+ years	
	Lavatory	Main Office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office		SF	6		
	vvalis - Flastel/DryWall	Main Onice	310	SF	О	10+ years	

Campus Name: Burley Page : 14 of 31 Assessment Date: 12/18/2023



Catego	ry : Room		В	uilding			
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Main Office	1	EA	6	6-10 years	
	Accessories	Restroom 001	24	SF	7	6-10 years	
	Ceiling - Exposed	Restroom 001	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom 001	1	EA	6	10+ years	
	Floor - Tile	Restroom 001	24	SF	6	10+ years	
	Lavatory	Restroom 001	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Restroom 001	1	EA	6	10+ years	
	Walls - Masonry	Restroom 001	60	SF	6	10+ years	
	Walls - Plaster/Drywall	Restroom 001	100	SF	7	10+ years	
	Water Closet	Restroom 001	1	EA	6	6-10 years	
	Accessories	Restroom 002A Inside Counselor's Office	30	SF	7	6-10 years	
	Ceiling - Lay-in	Restroom 002A Inside Counselor's Office	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom 002A Inside Counselor's Office	1	EA	6	10+ years	
	Floor - Tile	Restroom 002A Inside Counselor's Office	30	SF	6	10+ years	
	Lavatory	Restroom 002A Inside Counselor's Office	1	EA	6	6-10 years	
	Lighting - Lay-in	Restroom 002A Inside Counselor's Office	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Restroom 002A Inside Counselor's Office	175	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Restroom 002A Inside Counselor's Office	43	SF	6	10+ years	
	Water Closet	Restroom 002A Inside Counselor's Office	1	EA	6	6-10 years	

**Building: Main** Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #001 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	765	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Wood	Basement	765	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	6	10+ years	
	Walls - Masonry	Basement	1,054	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
_Classroo	om #002 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	5	LF	6	6-10 years	

Page : 15 of 31 Campus Name: Burley Assessment Date: 12/18/2023



Catego	ry : Classroom		В	uilding	: Main		
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	1,039	SF	6	10+ years	
	Doors - Transom Window	Basement	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Wood	Basement	1,039	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	10+ years	
	Marker Board	Basement	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,260	SF	6	10+ years	
Classroo	om #003 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	ĒΑ	6	10+ years	
	Floor - Tile	Basement	822	SF	6	10+ years	
	Lighting - Lay-in	Basement	14	ĒΑ	6	10+ years	
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	960	SF	7	10+ years	
Classroo	om #005 (Special Program)						
01000101	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	339	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	335	SF	6	10+ years	
	Floor - Tile	Basement	4	SF	4	1-2 years	Chipping tiles
	Lighting - Lay-in	Basement	6	EA	6	10+ years	Chipping tiles
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	663	SF	6	10+ years	
Classroo	om #101 (Computer Lab)						
Oldborok	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	195	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	7	10+ years	
	Walls - Plaster/Drywall Walls - Vinyl Coated Gypsum Panel	1st Floor	262	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #102 (Regular Classroom)						
CIUSSIUC	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	743	SF	7	10+ years	
	Genning - Fraster/Drywall	13(1100)	143	JI.	,	10+ years	

Campus Name: Burley Page : 16 of 31 Assessment Date: 12/18/2023



Catego	Category : Classroom			uilding	: Main			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	5	SF	6	10+ years		
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Wood	1st Floor	748	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Storage/ Closet	1st Floor	195	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	om #104 (Regular Classroom)							
_Uassi00	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st Floor	830	SF	7	10+ years		
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	Corrected quantity	
	Floor - Wood Doors Inclu riw	1st Floor		SF	7			
			830		=	10+ years		
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	195	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years		
Classroo	om #105 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	10+ years		
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Wood	1st Floor	830	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	125	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,085	SF	7	10+ years		
Classroo	om #106 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	10+ years		
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Compoted quantity	
	Floor - Wood Bools inclu hw	1st Floor	830	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Storage/ Closet	1st Floor	195	SF	7 7	10+ years		
				SF SF	7	-		
	Walls - Plaster/Drywall	1st Floor	1,085	2L	1	10+ years		



Catego	ry : Classroom		R	uilding	: Main		1630 W Barry AVENUE, Chicago, IL 60657
Jalogo	. ,			9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #107 (Regular Classroom)		_			•	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	748	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
_Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	5	10+ years	Lights don't turn on with switch
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	G
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	92	SF	7	10+ years	
						-	

Campus Name: Burley Page : 18 of 31 Assessment Date: 12/18/2023



Cateno	ry : Classroom		R	uilding	· Main		
Calego	Ty . Classicolli		<u> </u>	ununig	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	Comments
	Work Sink	2nd Floor	1,040	EA	7	10+ years	
	Work on k	2110 1 1001	'	LA	,	10+ years	
lassroc	om #202A (Special Education)						
	Ceiling - Plaster/Drywall	2nd Floor	253	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	253	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	560	SF	7	10+ years	
lassroc	om #203 (Science Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,310	SF	7	10+ years	
	Work Sink	2nd Floor	1,310	EA	7	10+ years	
`lassroc	om #204 (Regular Classroom)						
<i>nassio</i> c	AC Units	2nd Floor	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	375	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	70	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	•	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	12	EA	7	10+ years	
		2nd Floor	375	SF	7	10+ years	
	Floor - Wood					10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	655	SF	7	10+ years	
lassroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	·
	Floor - Wood	2nd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	

Campus Name: Burley Page: 19 of 31 Assessment Date: 12/18/2023



Category : Classroom			В	uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Storage/ Closet	2nd Floor	125	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years		
Classroo	m #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	5	LF	7	10+ years	Not previously assessed	
	Ceiling - Plaster/Drywall	2nd Floor	830	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	830	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	125	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years		
Classroo	m #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	5	LF	7	10+ years	Not previously assessed	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	'	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	, ,	
	Floor - Wood	2nd Floor	748	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	20	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	125	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years		
Classroo	m #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	Corrected quantity	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	1	
	Floor - Wood	2nd Floor	748	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	20	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	125	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years		
Classroo	m #301 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	4	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years		
				SF	7	· ,		

Campus Name: Burley Page : 20 of 31 Assessment Date: 12/18/2023



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	Wall painted, all good
	Walls - Plaster/Drywall	3rd Floor	1,385	SF	7	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	There are 2 AC units
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	795	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	, ,
	Floor - Wood	3rd Floor	795	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	130	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,485	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	There are 2 AC units
	Casework	3rd Floor	5	LF	7	10+ years	more are 27to arms
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	170	SF	5	10+ years	Wall paint is peeling
	Walls - Plaster/Drywall	3rd Floor	1,568	SF	7	10+ years	wan paint is peening
	walls - Flastel/Drywall	310 1 1001	1,500	OI .	,	10+ years	
Classroo	om #304 (Regular Classroom)	Ord Flace		Ε.Δ	7	0.40	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	875	SF	7	10+ years	0
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	95	SF	5	10+ years	Wall paint chipping
	Walls - Plaster/Drywall	3rd Floor	1,325	SF	7	10+ years	

Campus Name: Burley Page : 21 of 31 Assessment Date: 12/18/2023



Catego	ory : Classroom		В	uilding	: Main		
	<del></del>		0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #307 (Laboratory/Shop)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	26	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,565	SF	7	10+ years	
Classro	om #308 (Special Education)						
	AC Units	3rd Floor	2	EA	7	6-10 years	There are 2 AC units
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	corrected quartity
	Floor - Wood	3rd Floor	775	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	4	1-2 years	Floor boards are missing and there
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	7	10+ years	drywall missing with possible mold
Catego	ory : Interior			uilding	· Main	•	
Calego	i y . iiiterioi			ununig	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	•						
	Ceiling - Plaster/Drywall	1st Floor	2,065	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2,000	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	2,065	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,118	SF	6	10+ years	
			2,065	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor					
	Ceiling - Plaster/Drywall	2nd Floor			6	10∓ vears	
	Doors - Transom Window	2nd Floor	85	SF	6 6	10+ years	
	Doors - Transom Window Doors - Wood Doors include hw	2nd Floor 2nd Floor	85 8	SF EA	6	10+ years	
	Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Fountain	2nd Floor 2nd Floor 2nd Floor	85 8 2	SF EA EA	6 7	10+ years 10+ years	
	Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Wood	2nd Floor 2nd Floor 2nd Floor 2nd Floor	85 8 2 2,065	SF EA EA SF	6 7 6	10+ years 10+ years 10+ years	
	Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Wood Lighting - Pendent/Surface	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	85 8 2 2,065 21	SF EA EA SF EA	6 7 6 6	10+ years 10+ years 10+ years 10+ years	
	Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Wood	2nd Floor 2nd Floor 2nd Floor 2nd Floor	85 8 2 2,065	SF EA EA SF	6 7 6	10+ years 10+ years 10+ years	



Catego	Category : Interior			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	40	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	196	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,465	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	<sup>′</sup> 18	EA	7	6-10 years	
	Stairs - Wood	3rd Floor	12	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,085	SF	7	10+ years	
	Ceiling - Exposed	Basement	1,956	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	858	SF	6	10+ years	
	Doors - Transom Window	Basement	80	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	12	ĒΑ	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Basement	2,120	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	32	EA	6	10+ years	
	Lighting - Wall Mounted	Basement	8	EA	6	10+ years	
	Stairs - Concrete Stairs	Basement	48	LF	6	10+ years	
	Student Lockers - Two Tiers	Basement	5	EA	7	10+ years	
	Walls - Masonry	Basement	2,100	SF	6	10+ years	
	Walls - Naster/Drywall	Basement	5,495	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	20	SF	5	1-2 years	Spalling plaster
	Walls - Flastel/Drywall	Dasement	20	SF	5	1-2 years	Spalling plaster
Safety							
Carcty	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	3	EΑ	7	6-10 years	
	Coounty Camerao		· ·		-	0 .0 ,00.0	
Stairs							
	Ceiling - Plaster/Drywall	E Stairs	432	SF	7	10+ years	
	Floor - Asphalt	E Stairs	612	SF	5	1-2 years	There are cracks in all the stair floor
							landings
	Handrails	E Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	E Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	E Stairs	518	LF	5	1-2 years	There are cracks throughout all the
							stairs
	Walls - Plaster/Drywall	E Stairs	3,696	SF	7	10+ years	
	Ceiling - Plaster/Drywall	W Stairs	432	SF	7	10+ years	
	Floor - Asphalt	W Stairs	612	SF	7	1-2 years	There are cracks at each stair floor landing
	Handrails	W Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	W Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	W Stairs	518	LF	5	1-2 years	There are cracks throughout all the
	Stallo Applian	vv Otalio	310	LI	3	1 2 years	stairs
	Walls - Plaster/Drywall	W Stairs	3,681	SF	7	10+ years	otan o
	vvano i lastoi/Diyvvall	VV Otalio	3,001	01	,	ioi years	

Campus Name: Burley Page : 23 of 31 Assessment Date: 12/18/2023



flaking anymore

**Building: Main Category: Interior** Recommend Location UOM Group Item - Type Quantity Rank Comments Replacement Walls - Plaster/Drywall SF 6-10 years The walls are repainted and not W Stairs 15 7

Campus Name: Burley Page : 24 of 31 Assessment Date: 12/18/2023



Catego	ry : Exterior		Building : Field House Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance			•			-		
	Entrance Control - Audio and Video	#10 S	1	EA	7	10+ years		
	Exterior Doors - Exterior Wood Door	#10 S	1	EA	4	2-5 years	Delaminated door	
	Exterior Stairs - Concrete	#10 S	3	LF	5	6-10 years	Shattered concrete	
	Exterior Doors - Exterior Wood Door	#11 S	1	EA	4	2-5 years	Damaged old door	
	Exterior Doors - Exterior Wood Door	#12 Exit N	1	EA	4	1-2 years	The laminated, damaged door on exterior.	
	Exterior Doors - Exterior Wood Door	#13 Exit N	1	EA	6	6-10 years		
	Exterior Stairs - Concrete	#13 Exit N	5	LF	6	6-10 years		
	Exterior Doors - Exterior Wood Door	#9 Exit S	1	EA	4	1-2 years	Delaminated door	
	Exterior Stairs - Concrete	#9 Exit S	5	LF	5	1-2 years	Broken concrete	
Foundati								
	Foundation - Concrete	Entire Building	250	LF	7	10+ years		
	Foundation - Concrete	Entire Building	3	LF	6	10+ years		
	Superstructure - Heavy Timber	Entire Building	2,715	SF	7	10+ years		
Lighting								
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years		
Roof Sys								
	Downspouts - Exterior Downspouts	Entire Building	30	LF	6	6-10 years		
	Downspouts - Exterior Downspouts	Entire Building	22	LF	5	1-2 years	Crushed downspouts	
	Roof - Asphalt Shingle	Entire Building	3,394	SF	5	6-10 years		
	Roof Structure - Heavy Timber	Entire Building	3,394	SF	7	10+ years		
Walls								
	Exterior Walls - Brick	Entire Building	286	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	2	SF	4	1-2 years	Missing bricks	
	Exterior Walls - Wood Siding	Entire Building	1,217	SF	7	10+ years		
	Exterior Walls - Wood Siding	Entire Building	1,518	SF	6	10+ years		
	Exterior Walls - Wood Siding	Entire Building	300	SF	4	1-2 years	Cracked, broken, siding, large gaps	
_Windows								
	Guard - Guards wire guard	Entire Building	56	SF	5	6-10 years		
	Lintels - Steel	Entire Building	30	LF	6	10+ years		
	Windows - Wood- Single-pane	Entire Building	56	SF	4	2-5 years	old, single pane, wood windows	



Catego	ry : Electrical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Sei	vice						
	Main Electrical Service - 800 A and Less than 120/240/3PH	Electrical Room	1	EA	4	2-5 years	Over 50 years old
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	6	2-5 years	
Catego	ry : Fire Protection		В	uilding	: Field H	louse	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	2,715	SF	7	10+ years	
	Fire Alarm_System	Entire Building	2,715	SF	6	10+ years	
	i iio Alaim_Oystem	Entire building	2,710	OI.	J	TOT years	
Catego	ry : Mechanical	В	uilding	House			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Gas/ Natural Draft Furnace - 101 - 200 MBH	Mechanical Room	1	EA	5	6-10 years	
Tempera	ture Control						
	Electric Thermostat	1st Floor	1	EA	6	6-10 years	
			·	`	ŭ	0 .0 ,00.0	
Catego	ry : Plumbing		В	uilding	: Field F	louse	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er					_	
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	2-5 years	
	233.754.67 2555 47411 155555 21 5/1111	soriariisar (toom		_, .	3	_ 0 youro	
Piping							
-	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	2,715	SF	6	6-10 years	
	Sanitary Piping	Entire Building	2,715	SF	6	6-10 years	
	Vent Piping	Entire Building	2,715	SF	6	6-10 years	
	. •	S	, -			•	
Catego	ry : Classroom		В	uilding	: Field F		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	m #109E (Kindergarten)		Quality	· · · ·			

Campus Name: Burley Page : 26 of 31 Assessment Date: 12/18/2023



Catego	Category : Classroom		В	uilding	: Field H	louse	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Walls - Masonry	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	7	10+ years	
Classroo	m #109W (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
				LF		•	
	Marker Board	1st Floor	8	SF	7	6-10 years	
	Storage/ Closet	1st Floor	41		7	10+ years	
	Walls - Masonry	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	7	10+ years	
Catego	ry : Room		В	uilding	: Field H		
_			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Mechani</u>	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	70	SF	5	10+ years	The work sink requires repair or replacement
	Storage Room	1st Floor	8	SF	7	10+ years	The only storage room in the corridor is an 8 sf storage closet
Restroor	n						
_Restroor	n Accessories	1st Floor-109E Restroom	38	SF	7	6-10 years	
Restroor	Accessories		38 38	SF SF			
_Restroor	Accessories Ceiling - Plaster/Drywall	1st Floor-109E Restroom	38	SF	6	10+ years	
Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	1st Floor-109E Restroom 1st Floor-109E Restroom	38 1	SF EA	6 6	10+ years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted	1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom	38 1 38	SF EA SF	6 6 7	10+ years 10+ years 6-10 years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain	1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom	38 1 38 1	SF EA SF EA	6 6 7 7	10+ years 10+ years 6-10 years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory	1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom	38 1 38 1 1	SF EA SF EA EA	6 6 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface	1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom	38 1 38 1 1	SF EA SF EA EA	6 6 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface Walls - Vinyl Coated Gypsum Panel	1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom 1st Floor-109E Restroom	38 1 38 1 1 1 242	SF EA EA EA SF	6 6 7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface Walls - Vinyl Coated Gypsum Panel Water Closet	1st Floor-109E Restroom	38 1 38 1 1 242 1	SF EA SF EA EA SF EA	6 6 7 7 7 7 7 6	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface Walls - Vinyl Coated Gypsum Panel Water Closet Accessories	1st Floor-109E Restroom 1st Floor-109W Restroom	38 1 38 1 1 242 1 38	SF EA SF EA EA SF EA SF	6 6 7 7 7 7 7 6 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 6-10 years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface Walls - Vinyl Coated Gypsum Panel Water Closet Accessories Ceiling - Plaster/Drywall	1st Floor-109E Restroom 1st Floor-109W Restroom 1st Floor-109W Restroom	38 1 38 1 1 1 242 1 38 38	SF EA EA EA SF EA SF SF	6 6 7 7 7 7 6 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years	
_Restroor	Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted Floor Drain Lavatory Lighting - Pendent/Surface Walls - Vinyl Coated Gypsum Panel Water Closet Accessories	1st Floor-109E Restroom 1st Floor-109W Restroom	38 1 38 1 1 242 1 38	SF EA SF EA EA SF EA SF	6 6 7 7 7 7 7 6 7	10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 10+ years 6-10 years	

Campus Name: Burley Page : 27 of 31 Assessment Date: 12/18/2023



Catego	ry : Room		Building : Field House					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Epoxy/ Painted	1st Floor-109W Restroom	33	SF	7	10+ years		
	Floor - Epoxy/ Painted	1st Floor-109W Restroom	5	SF	5	2-5 years	Floor has cracks and deterioration	
	Floor Drain	1st Floor-109W Restroom	1	EA	7	10+ years		
	Lavatory	1st Floor-109W Restroom	1	EA	7	10+ years		
	Lighting - Wall Mounted	1st Floor-109W Restroom	1	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor-109W Restroom	242	SF	6	10+ years		
	Water Closet	1st Floor-109W Restroom	1	EA	7	10+ years		

Category : Interior **Building: Field House** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	175	SF	5	10+ years	Cracking paint throughout the ceiling
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	173	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	460	SF	7	10+ years	

Campus Name: Burley Page : 28 of 31 Assessment Date: 12/18/2023





Category : Site **Building: Site** 

	y : Site			ullaing	. Oile		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
hletic							
	Lighting	North Courtyard	2	EA	6	10+ years	
	Surface - Asphalt	North Courtyard	4,000	SF	6	10+ years	
	Surface - Synthetic	North Courtyard	4,894	SF	6	10+ years	
	Surface - Synthetic	North Courtyard	10	SF	5	1-2 years	Small crack
	Surface - Synthetic	North Courtyard	10	Oi	3	1-2 years	Omail crack
ivil/Drai	nage						
VII/ DIGI	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole	Entire Site	•	EA			
	Civil/ Drainage - Site Mannole	Entire Site	11	EA	6	10+ years	
encing							
J	Fencing - Chain Link	Entire Site	384	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	10	LF	5	1-2 years	Damaged, bent, corroded
	Fencing - Chain Link	Entire Site	470	LF	4	1-2 years	Bent, damaged, corroded
	Fencing - New Standard Ornamental	Entire Site	287	LF	6	10+ years	, , , , , , , , , , , , , , , , , , ,
	. c.i.s.i.g	5 5			· ·	.o. you.o	
andscap	oe						
	Benches	Entire Site	10	EA	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	20,286	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	2,050	SF	4	1-2 years	Large cracks, alligatored surface, potholes
	Landscape - Hardscape- Concrete	Entire Site	2,010	SF	6	10+ years	poundid
	Landscape - Hardscape- Concrete	Entire Site	750	SF	4	1-2 years	Shattered, br
	Landscape - Hardscape- Pavers	Entire Site	85	SF	6	10+ years	Chattered, bi
	Lighting - Pole Mounted	Entire Site	3	EA	6	10+ years	
	Parkway trees	Entire Site	5	EA	6		
			_			10+ years	
	Planting Beds/ Area	Entire Site	1,200	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	7,620	SF	6	10+ years	
	Play Area - Synthetic Turf	Entire Site	40	SF	5	1-2 years	Upheaved surface
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
arking L	ot						
	Surface - Asphalt	E Parking Lot	3,620	SF	6	10+ years	
	Trash Compactor	E Parking Lot	1	ĒΑ	6	10+ years	
	Trash Enclosure - Chain Links	E Parking Lot	400	SF	7	10+ years	
	Trast. Englocato Strain Entro	L I diming Lot	700	0.	,	io. yours	
aygrou							
	Equipment - Pre K 3-5	NE Playground	1	EA	7	10+ years	New
	Surface - Poured Surface	NE Playground	2,358	SF	7	10+ years	New
	Equipment - School Age 5-12	NW Playground	1	EA	7	10+ years	New

Campus Name: Burley Page : 29 of 31 Assessment Date: 12/18/2023



#### **Augustus H Burley Elementary School**

1630 W Barry AVENUE, Chicago, IL 60657

Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Surface - Poured Surface	NW Playground	1,600	SF	7	10+ years	New
Sidewall	KS						
	Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site Entire Site	50 50 5,035	LF SF SF	5 6 6	1-2 years 6-10 years 10+ years	Cracked concrete Repaired
_Signage							
	Flag Pole - Building Mounted Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Sign	Entire Site Entire Site Entire Site	1 1 1	EA EA EA	6 6 6	10+ years 10+ years 10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Burley Page: 30 of 31 Assessment Date: 12/18/2023

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

Classiconi Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					\-\-				
Computer Lab	Library	1st Floor	101	101	748	140	58	N	N
Kindergarten	Kindergarten	Basement	003	003	822	62	28	N	N
Kindergarten	Pre School	Basement	002	002	1,039	34	12	N	N
Kindergarten	Regular Classroom	Basement	001	001	765	62	28	N	N
Laboratory/Shop	Regular Classroom	3rd Floor	307	307	775	140	58	Υ	N
Regular Classroom	Office	2nd Floor	204	204	375	15	15		
Regular Classroom	Regular Classroom	1st Floor	102	102	748	140	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	748	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	748	140	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	748	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	830	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	748	140	58	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	748	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	760	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	795	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	865	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	880	140	58	Υ	N
Regular Classroom	Special Education	2nd Floor	202	202	748	140	58	Υ	N
Regular Classroom	Special Education	2nd Floor	206	206	830	140	58	Υ	N
Science Classroom	Regular Classroom	2nd Floor	203	203	748	140	58	Υ	N
Special Education	Regular Classroom	3rd Floor	308	308	775	140	58	Υ	N
Special Education	Store Room	2nd Floor	202A	202A	253	15	15		
Special Program	Kindergarten	Basement	005	005	339	124	40	N	N
Building : Field House									
Art Room	Regular Classroom	1st Floor	109W	109W	686	72	30	N	N
		1st Floor	109W	109W	686	84	40	N N	N N
Kindergarten	Kindergarten	151 51001	109E	1090	000	04	40	IN	IN