

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	3	60,929
Campus Total			60,929

Category : Exterior Building : Main

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	1	3	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	1	1	EA	6	10+ years	
	Power Door Operator and Controls	1	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	2	3	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	2	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	3	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	4	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	4.5	1	EA	4	0-1 year	Rotted.
	Exterior Doors - Transom Lite	4.5	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	4.5	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4.5 - Coal Room	1	EΑ	5	2-5 years	
	Exterior Doors - Exterior FRP Door	5	1	EΑ	6	6-10 years	
	Exterior Doors - Side lite	5	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	5	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	6	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	6	10	LF	5	0-1 year	Damaged.
	Ramp Handrail - Steel_Ramp Handrail	6	12	LF	6	10+ years	•
	Ramps - Concrete	6	27	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	6	5	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	7	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	7	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	8	1	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		TW Wabansia AVENOE, Officago, IE 00022
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exterior Doors - Side lite	8	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	8	6	LF	5	0-1 year	Cracking
	Exterior Doors - Exterior FRP Door	Courtyard Door	1	EA	6	10+ years	3
	Exterior Doors - Transom Lite	Courtyard Door	1	ĒΑ	6	10+ years	
	Exterior Stairs - Concrete	Courtyard Door	3	LF	5	2-5 years	
		•				•	
_Foundat							
	Foundation - Masonry	Entire Building	840	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	46,148	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	14,781	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	7	6-10 years	
	3 3	J				,	
Roof Sy							
	Coping - Stone	Roof 1	70	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	15	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	70	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	525	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	525	SF	6	10+ years	
	Coping - Clay Tile	Roof 10	56	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 10	12	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 10	56	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 10	360	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 10	360	SF	7	10+ years	
	Coping - Stone	Roof 11	25	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 11	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 11	25	LF	5	2-5 years	
	Roof - Modified Bitumen	Roof 11	75	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 11	75 75	SF	7	10+ years	
	Coping - Clay Tile	Roof 12	53	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 12 Roof 12	5	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 12 Roof 12	53	LF	6		
			696	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 12				6-10 years	
	Roof Structure - Heavy Timber	Roof 12	696	SF	7	6-10 years	
	Access Ladder - Metal	Roof 13	2	EΑ	7	10+ years	
	Access Ladder - Metal	Roof 13	2	EA	5	2-5 years	
	Coping - Terra Cotta	Roof 13	233	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 13	117	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 13	233	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 13	3,355	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 13	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 13	3,355	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Roof 14	1	EA	5	0-1 year	Rust/corrosion
	Coping - Terra Cotta	Roof 14	296	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 14	59	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 14	218	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 14	15	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 14	4,316	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Roof 14	4,316	SF	7	10+ years	
	Access Ladder - Metal	Roof 15	1	EA	7	10+ years	
	Access Ladder - Metal	Roof 15	1	EA	7	6-10 years	
	Access Ladder - Wood	Roof 15	1	EA	5	1-2 years	Old wooden ladder
	Coping - Terra Cotta	Roof 15	241	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 15	117	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 15	211	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Roof 15	30	LF	5	6-10 years	
	Roof - Modified Bitumen	Roof 15	3,692	SF	6	10+ years	
	Roof Hatch - Metal	Roof 15	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 15	3,692	SF	7	10+ years	
	Coping - Terra Cotta	Roof 16	12	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 16	15	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 16	51	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 16	1,014	SF	5	2-5 years	
	Roof Structure - Heavy Timber	Roof 16	1,014	SF	7	10+ years	
	Coping - Stone	Roof 2	76	LF	6	10+ years	
	Coping - Terra Cotta	Roof 2	15	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	15	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	76	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	868	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	868	SF	7	10+ years	
	Coping - Clay Tile	Roof 3	22	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	15	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	22	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	112	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	112	SF	7	10+ years	
	Coping - Stone	Roof 4	267	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	38	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	267	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	3,755	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4	3,755	SF	7	10+ years	
	Coping - Stone	Roof 5	44	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 5	44	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 5	459	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 5	459	SF	7	10+ years	
	Coping - Stone	Roof 6	36	LF	6	6-10 years	

Campus Name: Burr Page : 3 of 27 Assessment Date: 02/21/2024



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Roof 6	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 6	36	LF	5	6-10 years	
	Roof - Modified Bitumen	Roof 6	160	SF	5	0-1 year	Bubbling
	Roof Structure - Steel with Clay Tile Arch	Roof 6	160	SF	7	10+ years	
	Coping - Clay Tile	Roof 7	48	LF	6	10+ years	
	Coping - Stone	Roof 7	48	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	15	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 7	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 7	50	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 7	96	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 7	1,248	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 7	1,248	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 8	55	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 8	30	LF	5	6-10 years	
	Coping - Terra Cotta	Roof 8	66	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 8	15	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 8	66	LF	6	6-10 years	
	Roof - Metal	Roof 8	1,650	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 8	1,650	SF	7	10+ years	
	Coping - Stone	Roof 9	25	LF	5	6-10 years	
	Downspouts - Exterior Downspouts	Roof 9	28	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 9	25	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 9	800	SF	6	10+ years	Unable to view
	Roof Structure - Steel with Clay Tile Arch	Roof 9	800	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	2,710	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	36,255	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,230	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,231	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	240	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Roof	25	LF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Roof	36	LF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Roof	50	LF	6	10+ years	
	Cornice - Metal Projecting	Roof	155	LF	6	10+ years	
	Cornice - Metal Projecting	Roof	80	LF	6	10+ years	
	Cornice - Metal Projecting	Roof	102	LF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	1,900	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	310	SF	6	10+ years	
	Lintels - Brick	Entire Building	50	LF	6	10+ years	



Category : Exterior

# Jonathan Burr Elementary School 1621 W Wabansia AVENUE, Chicago, IL 60622

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lintels - Steel	Entire Building	50	LF	6	10+ years	
	Lintels - Stone	Entire Building	555	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	30	LF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	5,156	SF	6	10+ years	
	Windows - Decorative	Entire Building	100	SF	6	10+ years	
	Windows - Insulated Panel	Entire Building	490	SF	6	10+ years	
	Windows - Louver	Entire Building	121	SF	6	10+ years	
Categor	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	cy System	2004.1011	quantity	<b>CO</b>	rtaint	Ropidoomont	
	Automatic Transfer Switch	Basement	1	EA	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose	Entire Building	3	EA	6	6-10 years	Quantity changed to match current
	Room	•				·	observations. Location changed for clarification as the multipurpose roo occupies space on multiple floors.
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	8	EA	6	6-10 years	Location changed for clarification as the multipurpose room occupies space on multiple floors. Quantity changed as total has been divided/aggregated.
	Exit Signs - Multipurpose Room	Entire Building	1	EA	4	0-1 year	Missing electrical compartment coverage exposes live conductors presenting live front condition.
	Security System - CCTV	Entire Building	60,929	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	60,929	SF	6	6-10 years	Rank, Reason and Priority Rep adjusted based on system upgrade having been completed since previous assessment.
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,246	SF	6	6-10 years	•
	Emergency A/C Power - Gym	Entire Building	911	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	4,082	SF	6	6-10 years	

**Building: Main** 

Campus Name: Burr Page : 5 of 27 Assessment Date: 02/21/2024



Catego	ry : Electrical		В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	60,929	SF	4	0-1 year	Older system employing outdated technology that does not have communication to all receiving stations.
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Switchgear Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Switchgear Room	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting a live front condition. Quantity changed to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	DP-1 is missing a dataplate.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	

**Category: Fire Protection Building: Main** 

C=====	Mann Trunc	Landin	Overetite	ПОМ	Dank	Recommend	Commonts
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alaı	m						
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	60,929	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	60,929	SF	6	6-10 years	Rank changed based on current observations that pull stations and strobe lights are adequately positioned throughout the building.
	Fire Pump Controller	Entire Building	1	EA	4	2-5 years	Reason and Priority Rep adjusted to account for the controller being functional and passing inspection but having exceeded its anticipated service life.

Campus Name: Burr Page : 6 of 27 Assessment Date: 02/21/2024



Group							
						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Pump Ro</u>	om Assembly						
	Fire Pump - 25-50 hp	Storeroom next to Classroom 102-B	1	EA	5	6-10 years	Older equipment, leak-free at the time of assessment. Location changed for clarification.
Sprinkler	System						
•	Dry Sprinkler System	Entire Building	60,929	SF	5	6-10 years	Location changed for clarification. Older system that is well-maintained.
	Sprinkler Heads	Entire Building	60,929	SF	7	6-10 years	•
	Sprinkler Piping	Entire Building	60,929	SF	5	6-10 years	
Categor	y : Mechanical		В	uilding	: Main		
	B	L	0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Handl	ing Systems					0.40	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	Serves auditorium.
	Air Intake	Basement	1	EΑ	5	6-10 years	Location changed for clarification.
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Basement	1	EA	5	6-10 years	Serves north, central and south sections of the building.
	Air Intake	Basement	1	EA	5	10+ years	Location changed for clarification.
	Auxiliaries - 30001 - 45000 cfm	Basement	1	EΑ	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	5	10+ years	
	Zone Dampers	Basement	22	EA	5	6-10 years	Location changed for clarification.
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Basement	1	EA	5	6-10 years	Serves auditorium.
Boiler Sy:	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	7	10+ years	Rank and Priority Rep changed as combustion dampers have been replaced since previous assessment.
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-1

Campus Name: Burr Page : 7 of 27 Assessment Date: 02/21/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	5	6-10 years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	Location changed for clarification.
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	Location changed for clarification.
	Steam Traps	Boiler Room	20	EA	5	6-10 years	Quantity changed based on current observations and per review with Building Engineer. Location changed for clarification.
Heating	Devices						
	Wall Heater - Electric	Entire Building	11	EA	6	10+ years	Quantity changed as total has been divided/aggregated and to match current observations.
	Wall Heater - Electric	Entire Building	1	EA	5	6-10 years	Priority Rep adjusted based on current observations and to conform with Rank and Reason. Location changed for clarification.
	Wall Heater - Electric	Entire Building	3	EA	4	0-1 year	Rank, Reason and Priority Rep changed based on current observations that missing front covers expose live conductors presenting a live front condition and/or expose hot and moving parts presenting a risk of personal injury. Quantity changed as total has been divided/aggregated.
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	One each located in Room 002 and Switchgear Room.
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	5 5
Tempera	ature Control						
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	
	Pneumatic System	Entire Building	60,929	SF	4	1-2 years	Approx. 15% of the system is operational with most temperature control performed by manual adjustments.
	Thermostats - Pneumatic	Entire Building	23	EA	4	1-2 years	Quantity changed as total has been divided/aggregated. Most of the thermostats are nonfunctional and contaminated with oil.
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	7	10+ years	Installed in late 2023. Not directly

Campus Name: Burr Page: 8 of 27 Assessment Date: 02/21/2024



Catego	Category : Mechanical			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM						accessible in a safe manner at the time of assessment due to unreliable climbing arrangement.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	Installed in late 2023.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations. Older, well-maintained units with no dataplates, both operating as intended with no undue noise or vibration.

Category: Plumbing **Building: Main** 

Calego	ry . Fluilibilig		<u> </u>	unung	. IVIAIII		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
1 3	Domestic Piping-Hot Water Return Lines	Entire Building	60,929	SF	6	6-10 years	Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over time; system found to be leak-free at the time of assessment.
	Domestic Piping-Hot Water Return Risers	Entire Building	60,929	SF	6	6-10 years	Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over time and water pressure throughout the building being adequate at the time of assessment.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	60,929	SF	6	6-10 years	Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over time; system found to be leak-free at the time of assessment.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	60,929	SF	6	6-10 years	Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over time and water pressure throughout the building is adequate.
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	60,929	SF	6	6-10 years	Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over

Campus Name: Burr Page : 9 of 27 Assessment Date: 02/21/2024



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	60,929	SF	6	6-10 years	time; water pressure throughout the building is adequate and there are no pipe clamps in the system. Rank, Reason and Priority Rep changed based on portions of the piping having been replaced over time; water pressure throughout the building is adequate and there are no pipe clamps in the system.
	Sanitary Piping Storm Piping	Entire Building Entire Building	60,929 60,929	SF SF	5 5	6-10 years 6-10 years	
	Vent Piping	Entire Building	60,929	SF	5	6-10 years	
Catego	ry : Room		В	uilding	: Main		

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	204A	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	204A	1	EA	7	10+ years	
	Floor - Tile	204A	210	SF	7	10+ years	
	Lighting - Pendent/Surface	204A	1	EΑ	7	10+ years	
	Power Distribution	204A	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	204A	420	SF	7	10+ years	
	Ceiling - Plaster/Drywall	206A	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206A	1	EA	7	10+ years	
	Floor - Wood	206A	210	SF	6	10+ years	
	Lighting - Pendent/Surface	206A	1	EA	7	10+ years	
	Power Distribution	206A	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	206A	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	208A	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	208A	1	EA	7	10+ years	
	Floor - Wood	208A	210	SF	6	10+ years	
	Lighting - Pendent/Surface	208A	1	EΑ	7	10+ years	
	Power Distribution	208A	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	208A	480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	228	SF	6	6-10 years	
	Floor - Tile	2nd Floor	2	SF	4	1-2 years	Broken
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	6-10 years	
	Power Distribution	2nd Floor	5	EA	7	10+ years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	131	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	196	SF	7	10+ years	

Campus Name: Burr Page : 10 of 27 Assessment Date: 02/21/2024



Catego	ry : Room	Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Work Sink	2nd Floor	1	EA	7	10+ years		
	AC Unit	300	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	300	288	SF	6	10+ years		
	Doors - Transom Window	300	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	300	2	EA	6	10+ years		
	Floor - Tile	300	288	SF	6	10+ years		
	Lighting - Pendent/Surface	300	5	EA	7	6-10 years		
	Power Distribution	300	5	EA	7	10+ years		
	Storage/ Closet	300	12	SF	7	10+ years		
	Walls - Plaster/Drywall	300	936	SF	6	10+ years		
	Work Sink	300	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	309	150	SF	5	1-2 years	Peeling paint and cracked plaster	
	Doors - Wood Doors inclu hw	309	1	EA	7	10+ years		
	Floor - Wood	309	150	SF	6	10+ years		
	Lighting - Pendent/Surface	309	3	ĒΑ	7	6-10 years		
	Power Distribution	309	4	ĒΑ	7	10+ years		
	Walls - Plaster/Drywall	309	346	SF	6	10+ years		
	Ceiling - Exposed	Engineer room in basement	180	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Engineer room in basement	1	EA	7	10+ years		
	Floor - Epoxy/ Painted	Engineer room in basement	180	SF	4	0-1 year	Worn.	
	Lighting - Pendent/Surface	Engineer room in basement	1	EA	7	10+ years	***************************************	
	Power Distribution	Engineer room in basement	2	EA	7	10+ years		
	Walls - Masonry	Engineer room in basement	260	SF	7	10+ years		
	AC Unit	Main Office	1	EA	7	6-10 years		
	Ceiling - Splined	Main Office	420	SF	7	10+ years		
	Doors - Transom Window	Main Office	9	SF	7	-		
	Doors - Wood Doors inclu hw	Main Office	3	EA	6	10+ years 10+ years		
	Floor - Tile	Main Office	420	SF	6	-		
						6-10 years		
	Lighting - Pendent/Surface	Main Office	5	EΑ	7	6-10 years		
	Power Distribution	Main Office	8	EA	7	10+ years		
	Walls - Plaster/Drywall	Main Office	1,118	SF	6	10+ years		
	AC Unit	Principal Office	2	EA	7	6-10 years		
	Ceiling - Splined	Principal Office	240	SF	6	10+ years		
	Floor - Carpet	Principal Office	240	SF	6	6-10 years		
	Lighting - Pendent/Surface	Principal Office	4	EA	7	6-10 years		
	Power Distribution	Principal Office	10	EA	7	10+ years		
	Walls - Plaster/Drywall	Principal Office	484	SF	6	10+ years		
_Auditoriu	um & Theater							
	Balcony Seating	Basement (Used as a lunchroom as	80	EA	7	10+ years		
		well)						
	Ceiling - Exposed	Basement (Used as a lunchroom as	738	SF	7	10+ years		
	Ceiling - Plaster/Drywall	well) Basement (Used as a lunchroom as	3,344	SF	6	10+ years		

Campus Name: Burr Page : 11 of 27 Assessment Date: 02/21/2024



Catego	Category : Room		Building : Main					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	well) Basement (Used as a lunchroom as	3,344	SF	6	10+ years		
	Floor - Tile	well)	3,344	Si	O	10+ years		
	Floor - Wood Basement (Used as a lunchroom a		738	SF	6	10+ years		
		well)			_			
	Lighting - Pendent/Surface	Basement (Used as a lunchroom as	34	EA	7	6-10 years		
	Sound System	well) Basement (Used as a lunchroom as	1	EA	7	6-10 years		
	Country Cyclom	well)	•		•	o .o you.o		
	Stage	Basement (Used as a lunchroom as	704	SF	7	10+ years		
	Stage Curtain	well)	1	EA	7	6.10 , , , , , , ,		
	Stage Curtain	Basement (Used as a lunchroom as well)	ı	EA	7	6-10 years		
	Stage Lighting System	Basement (Used as a lunchroom as	1	EA	7	6-10 years		
		well)				-		
	Stage-Stairs - Wood	Basement (Used as a lunchroom as	36	LF	7	10+ years		
	Stairs - Wood	well) Basement (Used as a lunchroom as	183	LF	7	10+ years		
	Stand Wood	well)	100		•	101 youro		
	Walls - Masonry	Basement (Used as a lunchroom as	5,102	SF	6	10+ years		
	Malla Blactar/Drawall	well)	F 402	SF	0	10		
	Walls - Plaster/Drywall	Basement (Used as a lunchroom as well)	5,103	SF	6	10+ years		
_Gymnas	ia							
	Ceiling - Plaster/Drywall	3rd Floor	911	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	24	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	8	SF	5	1-2 years	Damaged glazing	
	Doors - Wood Doors inclu hw	3rd Floor	6	EA	7	10+ years		
	Floor - Wood	3rd Floor	911	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years		
	Storage/ Closet	3rd Floor	40	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	3,016	SF	6	10+ years		
<u>Kitchen</u>								
	Ceiling - Plaster/Drywall	Basement	513	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Floor - Tile	Basement	503	SF	6	10+ years		
	Floor - Tile	Basement	10	SF	4	1-2 years	Broken	
	Lighting - Pendent/Surface	Basement	5	ĒΑ	7	6-10 years		
	Serving Line	Basement	7	LF	7	6-10 years		
	Walls - Masonry	Basement	460	SF	7	10+ years		
	Walls - Masorify Walls - Plaster/Drywall	Basement	460	SF	6	10+ years		
	vvalio - i lastei/Diywali	Dasement	400	OI.	U	10+ years		



Catego	ry : Room		В	uilding	: Main				
0	Hom. Time	Lagation	0	LION	Dani	Recommend	Commonto		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Library	AO.11.11	000				0.10			
	AC Unit	302	1	EA	7	6-10 years			
	Casework	302	78	LF	7	10+ years			
	Ceiling - Plaster/Drywall	302	992	SF	6	10+ years	_		
	Ceiling - Plaster/Drywall	302	10	SF	5	1-2 years	Damaged.		
	Doors - Transom Window	302	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	302	3	EA	6	10+ years			
	Floor - Tile	302	1,002	SF	6	10+ years			
	Lighting - Pendent/Surface	302	13	EΑ	7	6-10 years			
	Storage/ Closet	302	144	SF	5	10+ years	Peeling paint		
	Walls - Plaster/Drywall	302	1,534	SF	7	10+ years			
MDF IDI	=								
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years			
	Finishes	1st Floor	144	SF	5	10+ years	Water stains on ceiling		
	Window AC Unit	1st Floor	1	EΑ	7	6-10 years	3		
NA l :	aal/ Oamica Baansa								
_wechani	cal/ Service Rooms	1st Floor	20	- CE		10			
	Janitor's Closet		30	SF	5	10+ years			
	Janitor's Closet	2nd Floor	42	SF	5	10+ years			
	Janitor's Closet	3rd Floor	42	SF	5	10+ years			
	Auditorium Plenums	Basement	2,700	SF	7	10+ years			
	Boiler Room	Basement	2,400	SF	7	10+ years			
	Coal Room	Basement	600	SF	7	10+ years			
	Janitor's Closet	Basement	30	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	1,620	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	1,075	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	104	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	528	SF	7	10+ years			
	Storage Room	Basement	808	SF	7	10+ years			
Restroor	n.								
	Accessories	102 closet	42	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	102 closet	42	SF	6	10+ years	Peeling paint		
	Floor - Tile	102 closet	42	SF	6	6-10 years			
	Lavatory	102 closet	1	EA	7	10+ years			
	Lighting - Pendent/Surface	102 closet	1	EA	5	1-2 years	Not operating well		
	Walls - Plaster/Drywall	102 closet	90	SF	6	10+ years			
	Water Closet	102 closet	1	EA	7	10+ years			
	Accessories	1st Floor	165	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	165	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	1st Floor	42	SF	6	6-10 years			
						•			

Campus Name: Burr Page : 13 of 27 Assessment Date: 02/21/2024



Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	1st Floor	123	SF	6	10+ years				
	Hand Dryer	1st Floor	1	EA	7	6-10 years				
	Lavatory	1st Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years				
	Partitions	1st Floor	2	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	179	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor	197	SF	6	10+ years				
	Water Closet	1st Floor	2	EA	7	10+ years				
	Accessories	2nd Floor	120	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	120	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	120	SF	7	6-10 years				
	Lavatory	2nd Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years				
	Partitions	2nd Floor	2	EΑ	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	120	SF	6	10+ years				
	Walls - Plaster/Drywall	2nd Floor	3	SF	4	1-2 years	Cracked			
	Walls - Tile Ceramic/ Porcelain	2nd Floor	128	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	2nd Floor	6	SF	4	1-2 years	Missing broken			
	Water Closet	2nd Floor	2	EA	7	10+ years				
	Accessories	2nd Floor	190	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	190	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	185	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	5	SF	4	0-1 year	Damaged.			
	Floor Drain	2nd Floor	1	EA	7	10+ years				
	Lavatory	2nd Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	10+ years				
	Partitions	2nd Floor	2	EA	7	10+ years				
	Urinals	2nd Floor	2	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	185	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	2nd Floor	130	SF	7	10+ years	Dualian			
	Walls - Tile Ceramic/ Porcelain	2nd Floor	30	SF	4	1-2 years	Broken			
	Water Closet	2nd Floor	2	EA	7	10+ years				
	Accessories	Basement	526 526	SF SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Basement	526 526	SF SF	6 7	10+ years				
	Floor - Tile Ceramic/ Porcelain Floor Drain	Basement		SF EA	7	10+ years				
	Hoor Drain Hand Dryer	Basement Basement	2 2	EA EA	7	10+ years				
		Basement	3	EA EA	7	10+ years				
	Lavatory		15	EA EA	7	10+ years				
	Lighting - Pendent/Surface	Basement				6-10 years				
	Partitions Walls - Concrete Block	Basement	11 664	EA SF	7	10+ years				
	Walls - Concrete Block Walls - Plaster/Drywall	Basement Basement	168	SF SF	7 7	10+ years				
	vvalis - i lastei/Diywall	Dascilletti	100	SI⁻	,	10+ years				

Campus Name: Burr Page : 14 of 27 Assessment Date: 02/21/2024



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Tile Ceramic/ Porcelain	Basement	368	SF	7	10+ years			
	Water Closet	Basement	11	EA	7	10+ years			
	Accessories	Basement	525	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement	525	SF	7	10+ years			
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement	525	SF	7	10+ years			
	Floor Drain	Basement	1	EA	7	10+ years			
	Hand Dryer	Basement	2	EA	7	10+ years			
	Lavatory	Basement	4	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement	13	EA	7	6-10 years			
	Partitions	Basement	4	EA	7	10+ years			
	Urinals	Basement	9	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement	368	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement	664	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement	168	SF	7	10+ years			
	Water Closet	Basement	4	EA	7	10+ years			
	Accessories	Basement at boys RR	70	SF	7	10+ years			
	Ceiling - Exposed	Basement at boys RR	70	SF	7	10+ years			
	Doors - Steel Doors incl hw	Basement at boys RR	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement at boys RR	70	SF	7	10+ years			
	Floor Drain	Basement at boys RR	1	EA	7	10+ years			
	Hand Dryer	Basement at boys RR	1	EA	7	10+ years			
	Lavatory	Basement at boys RR	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement at boys RR	1	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement at boys RR	80	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement at boys RR	140	SF	7	10+ years			
	Water Closet	Basement at boys RR	1	EA	7	10+ years			
	Accessories	Basement at girls RR	90	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Basement at girls RR	90	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Basement at girls RR	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement at girls RR	90	SF	7	10+ years			
	Floor Drain	Basement at girls RR	1	EA	7	10+ years			
	Hand Dryer	Basement at girls RR	1	EA	7	10+ years			
	Lavatory	Basement at girls RR	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement at girls RR	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Basement at girls RR	80	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	Basement at girls RR	180	SF	7	10+ years			
	Water Closet	Basement at girls RR	1	EA	7	10+ years			
	Accessories	In Boiler room	40	SF	7	10+ years			
	Ceiling - Lay-in	In Boiler room	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In Boiler room	1	EA	7	10+ years			
	Floor - Epoxy/ Painted	In Boiler room	40	SF	7	2-5 years			
	Lighting - Pendent/Surface	In Boiler room	1	EA	7	10+ years			
	Walls - Concrete Block	In Boiler room	60	SF	6	10+ years			

Campus Name: Burr Page : 15 of 27 Assessment Date: 02/21/2024



Catego	Category : Room				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	In Boiler room	40	SF	5	10+ years	
	Water Closet	In Boiler room	1	EA	7	10+ years	
	Accessories	Inside 002	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 002	36	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Inside 002	4	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Inside 002	1	EA	7	10+ years	
	Floor - Tile	Inside 002	40	SF	6	10+ years	
	Lavatory	Inside 002	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Inside 002	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside 002	80	SF	6	10+ years	
	Water Closet	Inside 002	1	EA	7	10+ years	
	Accessories	Staff Restroom - 2nd Floor, womens	114	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Restroom - 2nd Floor, womens	114	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff Restroom - 2nd Floor, womens	1	EA	6	10+ years	
	Floor - Tile	Staff Restroom - 2nd Floor, womens	34	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom - 2nd Floor, womens	80	SF	6	6-10 years	
	Floor Drain	Staff Restroom - 2nd Floor, womens	1	EA	7	10+ years	
	Hand Dryer	Staff Restroom - 2nd Floor, womens	1	EA	7	6-10 years	
	Lavatory	Staff Restroom - 2nd Floor, womens	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff Restroom - 2nd Floor, womens	3	EA	7	6-10 years	
	Partitions	Staff Restroom - 2nd Floor, womens	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Restroom - 2nd Floor, womens	124	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Staff Restroom - 2nd Floor, womens	126	SF	7	10+ years	
	Water Closet	Staff Restroom - 2nd Floor, womens	3	EA	7	10+ years	
	Accessories	Staff restroom - 2nd Floor, mens	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff restroom - 2nd Floor, mens	126	SF	6	10+ years	
	Doors - Transom Window	Staff restroom - 2nd Floor, mens	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff restroom - 2nd Floor, mens	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff restroom - 2nd Floor, mens	126	SF	6	10+ years	
	Lavatory	Staff restroom - 2nd Floor, mens	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff restroom - 2nd Floor, mens	2	EA	7	10+ years	
	Partitions	Staff restroom - 2nd Floor, mens	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	Staff restroom - 2nd Floor, mens	212	SF	6	10+ years	
	Walls - Plaster/Drywall	Staff restroom - 2nd Floor, mens	4	SF	4	1-2 years	Cracked
	Water Closet	Staff restroom - 2nd Floor, mens	3	EA	7	10+ years	
Catego	Category : Classroom				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #002 (Art Room)						

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #002 (Art Room)						
AC Units	Basement	2	EA	7	6-10 years	
Casework	Basement	25	LF	7	10+ years	
Ceiling - Plaster/Drywall	Basement	1,000	SF	7	10+ years	
Doors - Wood Doors inclu hw	Basement	3	EA	7	10+ years	

Campus Name: Burr Page : 16 of 27 Assessment Date: 02/21/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement	1,000	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	7	6-10 years	
	Storage/ Closet	Basement	55	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,300	SF	7	10+ years	
	Work Sink	Basement	1	ĒΑ	7	6-10 years	
Classroo	om #006 (Office)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	475	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	475	SF	6	10+ years	
				EA	7		
	Lighting - Pendent/Surface	Basement	10			10+ years	
	Marker Board	Basement	7	LF	7	6-10 years	
	Storage/ Closet	Basement	27	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	880	SF	7	10+ years	
Classroo	om #007 (Regular Classroom)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	1,000	SF	7	10+ years	
	Chalk Board	Basement	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	1,000	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	14	ĒΑ	7	10+ years	
	Marker Board	Basement	12	LF	7	6-10 years	
	Storage/ Closet	Basement	50	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,300	SF	6	10+ years	
Classroo	om #008 (Regular Classroom)						
Oldoorox	AC Units	Basement	4	EA	7	6-10 years	
	Ceiling - Exposed	Basement	1,000	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1,000	EA	7	•	
	Floor - Tile		·	SF		10+ years	
		Basement	1,000	_	6	10+ years	
	Lighting - Pendent/Surface	Basement	16	EA	7	10+ years	
	Marker Board	Basement	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,300	SF	6	10+ years	
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
					-	<b>,</b>	



Catego	ry : Classroom		В	uilding	: Main		W Wabansia AVENUE, Officago, IE 00022
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,002	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	144	SF	5	2-5 years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
Classroo	om #102 (Pre School)						
Classion	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	1,002	SF	6		
	Doors - Transom Window	1st Floor	1,002	SF	7	10+ years	
				SF EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2		6	10+ years	
	Floor - Tile	1st Floor	992	SF	6	6-10 years	Cracked tile recorded
	Floor - Tile/Sheet	1st Floor	10	SF	4	1-2 years	Cracked tile near door
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
_Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,002	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	1st Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,002	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
	vvalis - Flastel/DiyWall	191 11001	1,334	ЗF	O	TUT YEATS	

Campus Name: Burr Page : 18 of 27 Assessment Date: 02/21/2024



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	m #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,002	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	0-1 year	Light is missing, interrupter loose
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	858	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	858	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,534	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	807	SF	6	6-10 years	
	Floor - Tile	2nd Floor	25	SF	4	1-2 years	Cracked and chipped
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	Graciica ana emppea
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,508	SF	6	10+ years	
Classres	om #202 (Regular Classroom)						
_CIA5510C	AC Units	2nd Floor	4	EA	7	6 10 2000	
		2nd Floor 2nd Floor	1	LF		6-10 years	
	Casework	∠nd Floor 2nd Floor	4 822	SF	6 6	10+ years 10+ years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	022	SF EA	6	10+ years 10+ years	
	Floor - Tile	2nd Floor 2nd Floor	812	SF	6	6-10 years	
	Floor - Tile Floor - Tile	2nd Floor 2nd Floor	10	SF SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	10	SF EA	4 7	6-10 years	Cracked
	Marker Board	2nd Floor 2nd Floor	12	LF	7 7	•	
	IVIAINEI DUAIU	ZIIU FIUUI	12	LF	,	6-10 years	

Campus Name: Burr Page : 19 of 27 Assessment Date: 02/21/2024



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	72	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,846	SF	7	10+ years	
Classroo	m #203 (Special Education)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	408	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	404	SF	6	6-10 years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,066	SF	6	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,002	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,534	SF	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
	Floor - Tile	2nd Floor	972	SF	6	6-10 years	
	Floor - Tile	2nd Floor	30	SF	4	1-2 years	Cracked chipped
	Lighting - Pendent/Surface	2nd Floor	13	ĒΑ	7	6-10 years	11 -
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,528	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	1-2 years	Cracked
Classroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Category : Classroom			В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	921	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	921	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,534	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,002	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,002	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,534	SF	6	10+ years	
01	, , , , , , , , , , , , , , , , , , ,					•	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	858	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	858	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,534	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	600	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	600	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,248	SF	6	10+ years	
Classro	om #307 (Regular Classroom)						
		0-451		Ε,	7	0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,002	SF	7	10+ years	



Catego	Category : Classroom			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	
	Floor - Tile	3rd Floor	982	SF	7	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Minor cracked and damaged tiles
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	144	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,524	SF	7	10+ years	
_Classroo	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	933	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	933	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,534	SF	6	10+ years	
	Traile Tractor, 21, trail	0.0.1.00.	.,00.	•	•	.o. you.o	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor			•			·	
	Ceiling - Plaster/Drywall	1st Floor	2,298	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2	SF	5	1-2 years	Hole in ceiling
	Doors - Transom Window	1st Floor	282	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	2,300	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	3,900	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,898	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	120	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,890	SF	6	10+ years	
	Floor - Wood	2nd Floor	1,090	SF	5	1-2 years	Bulging
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years	Daiging
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	3,120	SF	6	•	
	Ceiling - Plaster/Drywall	3rd Floor	1,041	SF SF	6	10+ years	
			,			10+ years	Mater democratical
	Coiling Plactor/Dravell	2rd Floor		C.			
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water damaged ceiling
	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	3rd Floor 3rd Floor	5 1	SF EA	5 7	1-2 years 10+ years	water damaged ceiling

Campus Name: Burr Page : 22 of 27 Assessment Date: 02/21/2024



Category : Interior			В	uilding	: Main		
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	6-10 years	
	Floor - Wood	3rd Floor	1,046	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Needs new lighrs
	Student Lockers - Two Tiers	3rd Floor	248	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,390	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Assembly Hall Passage/Corridor	840	SF	6	10+ years	
	Floor - Asphalt Floor	Assembly Hall Passage/Corridor	840	SF	6	10+ years	
	Lighting - Pendent/Surface	Assembly Hall Passage/Corridor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	Assembly Hall Passage/Corridor	1,601	SF	6	10+ years	
	Walls - Plaster/Drywall	Assembly Hall Passage/Corridor	10	SF	5	0-1 year	Damaged.
	Ceiling - Plaster/Drywall Auditorium Atrium Entry		572 572	SF	6	10+ years	
	Floor - Asphalt Floor	- Pendent/Surface Auditorium Atrium Entry Concrete Stairs Auditorium Atrium Entry lasonry Auditorium Atrium Entry		SF	5	10+ years	
	Lighting - Pendent/Surface			EA	7	6-10 years	
	Stairs - Concrete Stairs			LF	7	10+ years	
	Walls - Masonry			SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement between rooms 6 &8	1,620	SF	7	10+ years	
	Floor - Asphalt Floor	Basement between rooms 6 &8	1,620	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement between rooms 6 &8	10	EΑ	7	10+ years	
	Stairs - Concrete Stairs	Basement between rooms 6 &8	40	LF	7	10+ years	
	Student Lockers - One Tier	Basement between rooms 6 &8	60	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement between rooms 6 &8	2,200	SF	7	10+ years	
	Ceiling - Exposed	Corridor at Rooms 002 & 007	1,730	SF	7	10+ years	
	Doors - Steel Doors incl hw	Corridor at Rooms 002 & 007	3	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Corridor at Rooms 002 & 007	1	EA	7	6-10 years	
	Floor - Asphalt Floor	Corridor at Rooms 002 & 007	806	SF	7	10+ years	
	Floor - Tile/Sheet	Corridor at Rooms 002 & 007	924	SF	5	10+ years	
	Lighting - Pendent/Surface	Corridor at Rooms 002 & 007	23	EA	7	6-10 years	
	Stairs - Concrete Stairs	Corridor at Rooms 002 & 007	42	LF	7	10+ years	
	Walls - Masonry	Corridor at Rooms 002 & 007	510	SF	7	10+ years	
	Walls - Plaster/Drywall	Corridor at Rooms 002 & 007	2,770	SF	6	10+ years	
	Ceiling - Exposed	Passage Behind Stage	528	SF	7	10+ years	
	Doors - Wood Doors include hw	Passage Behind Stage	2	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	Passage Behind Stage	1	EA	7	10+ years	
	Floor - Asphalt Floor	Passage Behind Stage	528	SF	6	10+ years	
	Stairs - Concrete Stairs	Passage Behind Stage	30	LF	7	10+ years	
	Walls - Masonry	Passage Behind Stage	600	SF	7	10+ years	
	Walls - Plaster/Drywall	Passage Behind Stage	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Vestibule 1	72	SF	6	10+ years	
	Doors - Steel Doors incl hw	Vestibule 1	6	EA	7	10+ years	
	Doors - Transom Window	Vestibule 1	36	SF	7	10+ years	
	Floor - Asphalt Floor	Vestibule 1	72	SF	7	10+ years	
	Lighting - Pendent/Surface	Vestibule 1	1	EA SF	7	6-10 years	
	Walls - Masonry	Vestibule 1	120	31	6	10+ years	

Campus Name: Burr Page : 23 of 27 Assessment Date: 02/21/2024



Catego	Category : Interior		В	uilding			
				_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	Vestibule 2	72	SF	6	10+ years	
	Doors - Steel Doors incl hw	Vestibule 2	3	EA	7	10+ years	
	Doors - Transom Window	Vestibule 2	36	SF	7	10+ years	
	Floor - Asphalt Floor	Vestibule 2	52	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Vestibule 2	20	SF	6	10+ years	
	Lighting - Pendent/Surface	Vestibule 2	1	EA	7	6-10 years	
	Walls - Masonry	Vestibule 2	120	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
Stairs							
	Handrails	Balcony Stairs	104	LF	7	10+ years	
	Stairs - Asphalt	Balcony Stairs	144	LF	7	10+ years	
	Walls - Masonry	Balcony Stairs	400	SF	7	10+ years	
	Ceiling - Exposed	Stair 1 - South	1,044	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair 1 - South	312	SF	6	10+ years	
	Floor - Asphalt	Stair 1 - South	396	SF	6	10+ years	
	Floor - Tile/Sheet	Stair 1 - South	132	SF	5	10+ years	
	Handrails	Stair 1 - South	158	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 1 - South	6	EA	7	6-10 years	
	Stairs - Concrete	Stair 1 - South	474	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair 1 - South	2,172	SF	6	10+ years	
	Ceiling - Exposed	Stair 2 - North	1,044	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stair 2 - North	312	SF	6	10+ years	
	Floor - Tile	Stair 2 - North	396	SF	6	10+ years	
	Handrails	Stair 2 - North	158	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 2 - North	6	EA	7	6-10 years	
	Stairs - Concrete	Stair 2 - North	474	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair 2 - North	2,172	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 3 - North East	210	SF	6	10+ years	
	Floor - Asphalt	Stair 3 - North East	120	SF	7	10+ years	
	Handrails .	Stair 3 - North East	34	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair 3 - North East	2	EA	7	6-10 years	
	Stairs - Concrete	Stair 3 - North East	102	LF	7	10+ years	
	Walls - Plaster/Drywall	Stair 3 - North East	680	SF	6	10+ years	



Category : Site Building : Site

maged fence
· ·
ng apart
g span
ce
_



Category : Site	В	Building : Site						
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Signage								
Flag Pole - Flag Pole	East	1	EA	6	6-10 years			
Marquee - Free Standing Back Lighted	East	1	EΑ	6	6-10 years			
Monument - Building Mounted Cut Letter	East	3	EΑ	7	10+ years			
Sign								

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Burr Page: 26 of 27 Assessment Date: 02/21/2024

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		•	•	•	, ,			•	
Art Room	Kindergarten	Basement	002	102-B	1,000	70	20	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	108	108	858	137	54	Y	Υ
Office	Store Room	Basement	006	Shower/bath	475	5	10	N	N
Pre School	Kindergarten	1st Floor	102	102	1,002	137	54	Υ	Υ
Regular Classroom	Play Room	Basement	007		1,000	40	12	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	1,002	137	54	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	1,002	137	54	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	1,002	137	54	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	1,002	137	54	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	832	137	54	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	202	202	822	137	54	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	204	204	1,002	137	54	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,002	137	54	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	921	137	54	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	208	208	1,002	137	54	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	858	137	54	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	600	97	36	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	1,002	177	72	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	933	137	57	Υ	Υ
Regular Classroom	Regular Classroom	Basement	008	108-B	1,000	28	4	Υ	Υ
Special Education	Regular Classroom	2nd Floor	203	203	408	137	54	Υ	N