



#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1894	3	41,959
Linked Addition	1991	3	42,756
Campus Total			84,715

Category : Exterior Building : Main

July	I y . Exterior		Building . Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	•	Location	Quantity	CON	Ivalik	Replacement	Comments		
Entrance		40. On d Floor Fire Foreign	4	Ε.	7	40			
	Exterior Doors - Exterior FRP Door	18- 2nd Floor Fire Escape	1	EA	/	10+ years			
	Exterior Doors - Transom Lite	18- 2nd Floor Fire Escape	1	EΑ	<u>/</u>	10+ years			
	Exterior Stairs - Stone	18- 2nd Floor Fire Escape	3	LF	/	10+ years	Not previously assessed		
	Exterior Doors - Exterior FRP Door	19- 3rd Floor Fire Escape	1	EA	6	2-5 years	Difficult to open, needs several intents		
	Exterior Doors - Transom Lite	19- 3rd Floor Fire Escape	1	EA	7	10+ years			
	Exterior Stairs - Concrete	19- 3rd Floor Fire Escape	3	LF	7	10+ years			
	Exterior Doors - Exterior Wood Door	3	1	EA	6	6-10 years			
	Exterior Doors - Transom Lite	3	1	EA	6	6-10 years			
	Exterior Stairs - Concrete	3	3	LF	7	10+ years			
	Exterior Stairs - Concrete	3	1	LF	5	1-2 years	Cracked		
	Exterior Doors - Exterior Steel Door	4	2	EA	6	10+ years			
	Exterior Doors - Side lite	4	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	4	1	EA	6	10+ years			
	Exterior Stairs - Concrete	4	18	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	5	1	EA	4	0-1 year	Corroded door		
	Exterior Doors - Transom Lite	5	1	EA	6	10+ years			
	Exterior Stairs - Concrete	5	3	LF	5	0-1 year	Broken concrete		
	Exterior Doors - Exterior Steel Door	6	1	EA	6	2-5 years			
	Exterior Doors - Exterior Steel Door	7	1	EA	5	0-1 year	Corroded door frame		
	Exterior Doors - Exterior Steel Door	8	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	8	1	EA	7	10+ years			
	Exterior Doors - Exterior Steel Door	9	1	EA	6	10+ years			



Cuarum II							
O					: Main	Recommend	
	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
E	Exterior Doors - Transom Lite	9	1	EA	6	10+ years	
Fire Escape	e e						
	Exterior Doors - Exterior FRP Door	North East	2	EA	6	10+ years	Third floor: Difficult to open, needs several tries, second floor: blocked by storage
F	Fire Escape	North East	50	LF	7	10+ years	3.
	Paints .	North East	50	LF	5	2-5 years	
Foundation	n						
	Foundation - Masonry	Entire Building	562	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	37,729	SF	7	10+ years	Corrected item type
	Superstructure - Steel with Clay Tile Arch	Entire Building	4,230	SF	7	10+ years	<b>3.</b>
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	7	10+ years	
Roof Syste	em						
	Access Ladder - Metal	A	2	EA	7	10+ years	
	Coping - Stone	A	150	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	30	LF	6	6-10 years	
	Parapet - 16" - 30" Height	A	150	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	A	4,350	SF	5	2-5 years	
	Roof Hatch - Metal	A	1	ĒΑ	7	10+ years	
	Roof Structure - Heavy Timber	A	4,350	SF	7	10+ years	
	Access Ladder - Metal	В	2	EΑ	7	10+ years	
	Coping - Stone	В	10	LF	7	10+ years	
	Coping - Stone	В	334	LF	6	10+ years	
	Downspouts - Exterior Downspouts	В	239	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	В	3	LF	4	1-2 years	Distorted, broken seam
	Parapet - 16" - 30" Height	В	324	LF	6	10+ years	Diotorioa, broken ocam
	Parapet - 16" - 30" Height	В	20	LF	6	2-5 years	
	Roof - Asphalt Gravel Ballast	В	6,616	SF	5	2-5 years	Deteriorated sealant at counter flashing, open seams
F	Roof - Metal	В	200	SF	6	6-10 years	nasining, open seams
F	Roof Hatch - Metal	В	2	ĒΑ	4	2-5 years	Corroding hatch
	Roof Structure - Heavy Timber	В	6,816	SF	7	10+ years	<b>J</b>
	Coping - Stone	C	32	LF	6	10+ years	
	Downspouts - Exterior Downspouts	C	16	LF	6	10+ years	
	Parapet - Parapet < 16" Height	C	32	LF	6	2-5 years	
	Roof - Modified Bitumen	C	120	SF	4	0-1 year	Distressed surface, inaccessible
	Roof Structure - Steel with Clay Tile Arch	C	120	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	D	50	LF	6	6-10 years	



Category : Exterior			В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Liner	5	22		-	0.4	•
	Chimney - Brick Chimney- Concrete/ Mortar	D	30	LF	5	0-1 year	Open joints
	Liner Coping - Stone	D	240	LF	7	10 L VOOR9	
	Coping - Stone	D	15	LF	, 5	10+ years 10+ years	
	Downspouts - Exterior Downspouts	D	39	LF	6	10+ years	
	Parapet - Parapet < 16" Height	D	255	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	D	3,571	SF	6	2-5 years	Older roof in fair condition
	Roof - Modified Bitumen	D	300	SF	6	0-1 year	Vegetation growth, no ballast
	Roof Structure - Steel with Clay Tile Arch	D	3,871	SF	7	10+ years	vogotation growth, no ballact
	Coping - Metal	Ē	24	LF	5	1-2 years	Corroded
	Parapet - Parapet < 16" Height	Ē	12	LF	7	10+ years	Concaca
	Roof - Modified Bitumen	Ē	240	SF	4	1-2 years	Blistering, worn surface
	Roof Structure - Steel with Clay Tile Arch	Ē	240	SF	7	10+ years	Bilotoring, Worri Gariago
	,	_		Ο.	-	.o. yea.e	
Valls	0	E.C. D.T.C.	0.40			4.0	
	Cornice - Metal Projecting	Entire Building	348	LF	5	1-2 years	Corroding, corroded
	Exterior Walls - Brick	Entire Building	18,085	SF	6	10+ years	Recombined quantities
	Exterior Walls - Brick	Entire Building	140	SF SF	4	0-1 year	Open joints, cracked brick
	Exterior Walls - Stone-Cut	Entire Building	300 300	SF SF	5 5	10+ years	Recombined quantities
	Exterior Walls - Stone-Cut Exterior Walls - Stone-Cut	Entire Building Entire Building	300	SF SF	5 4	10+ years	Broken windowsill near door five
	Exterior Walls - Storie-Cut  Exterior Walls - Terra Cotta	Entire Building	110	SF	6	1-2 years 10+ years	Broken windowsiii near door nve
	Exterior Walls - Terra Cotta	Entire building	110	SI	U	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	2,250	SF	6	2-5 years	
	Guard - Guards wire guard	Entire Building	60	SF	6	10+ years	Not previously assessed
	Lintels - Brick	Entire Building	255	LF	6	6-10 years	
	Lintels - Brick	Entire Building	20	LF	4	0-1 year	Crack, brick, open joints, displaced
	Lintels - Steel	Entire Building	50	LF	6	10+ years	arch
	Lintels - Steel	Entire Building	50	LF	4	0-1 year	Corroded lintels are displacing brick
	Lintels - Stone	Entire Building	263	LF	6	10+ years	corrected initials and displacing shall
	Skylite - Glass Single-Pane	Entire Building	30	SF	6	10+ years	
	Windows - Insulated Panel	Entire Building	218	SF	6	10+ years	
	Windows - Louver	Entire Building	44	SF	6	10+ years	
	Windows - Louver	Entire Building	14	SF	4	0-1 year	Corroded
	Windows - Sash Aluminum Double-pane	Entire Building	5,223	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						



Catego	ry : Electrical		В	uilding	: Main		-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Automatic Transfer Switch	Basement	1	EA	4	10+ years	Serves main building, does not show emergency power source available
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,807	SF	6	10+ years	3, ,
	Emergency A/C Power - Multipurpose Room	Entire Building	3,684	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	6	10+ years	
	Exit Signs - Multipurpose Room	Entire Building	5	EA	6	10+ years	
	Security System - CCTV	Entire Building	41,959	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	41,959	SF	5	2-5 years	
_Main Se	vice						
	Independent Electrical Service for emergency power	Basement	1	EA	6	6-10 years	Serves fire pump, controller, see fire protection category
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	41,959	SF	6	6-10 years	Served by PA system in addition
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	6-10 years	Vintage unlabeled panels
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	LP-3 door latch missing
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	4	0-1 year	Locked EM fuse panel F1 is live front
	Lighting and Power Panels - Above 100 A	Entire Building	10	ĒĀ	7	10+ years	MS-2 AC-1 AC-1A AC-3 CP-1 CP-2 CP-4 IDF LP-1A in electrical vault Vintage panel, AC-1 in boiler room Quantity updated to reflect observed conditions
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Unlabeled panel and second-floor electrical closet within classroom
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	CDP-1
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	PP-A
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Entire Building	1 41,959	EA SF	6 6	6-10 years 10+ years	

Campus Name: Chase Page : 4 of 41 Assessment Date: 02/29/2024



Ent Ent Ent	cation tire Building tire Building sement tire Building	<b>Quantity</b> 84,715 1	UOM SF EA	<b>Rank</b> 6 6	Recommend Replacement 6-10 years 6-10 years	Comments Some components connected to dry sprinkler. System has been updated recently.
Ent Ent Ent	tire Building tire Building sement	84,715 1 1	SF EA	6	Replacement 6-10 years 6-10 years	Some components connected to dry sprinkler. System has been updated
Ent Ent Ent	tire Building tire Building sement	84,715 1 1	SF EA	6	6-10 years 6-10 years	Some components connected to dry sprinkler. System has been updated
Bas Ent	sement	1			,	recently.
Ent Ent			EA	5		
Ent Ent			EA	5		
Ent	ire Building	44.050		•	1-2 years	Corroded, showing signs of age
Ent	tire Building	41.050				
		41,959	SF	7	10+ years	Recently, refurbished, valved and
	tire Building	41,959	SF	4	1-2 years	tagged Older, outdated, sprinkler heads, not reliable
Ent	tire Building	41,959	SF	5	6-10 years	
		В	uilding	: Main		
					Recommend	
Lo	cation	Quantity	UOM	Rank	Replacement	Comments
- Less Ro	of	6	EA	7	10+ years	Six split units, serve multipurpose room Not included in previous assessment
Electric Gv	mnasium	6	EA	6	6-10 years	Not previously assessed
		1	EA	6	6-10 years	., ,
		1	EA	6	6-10 years	
		1		-	6-10 years	
Ducts- Me	chanical Room	100	LF	6	6-10 years	
Me	chanical Room	24	EA	3	6-10 years	All controll is manual
		2	EA	6	10+ years	
		1	EA	6	10+ years	
Boi		1			10+ years	
		1			•	
Boi		1		_	10+ years	
Boi Boi		1	EA			B-1
7	Zone- Me  Me  Me  Me  Ducts- Me  Steam Low Boi  Boi  Boi  Boi  Boi  Boi  Boi	Mechanical Room  Mechanical Room  Mechanical Room  Mechanical Room  Ducts-  Mechanical Room  Mechanical Room	Mechanical Room         1           Mechanical Room         1           Mechanical Room         1           Ducts-         Mechanical Room         100           Mechanical Room         24           Steam Low         Boiler Room         1           Boiler Room         1           Boiler Room         3           Boiler Room         1           Boiler Room         1	Mechanical Room         1         EA           Mechanical Room         1         EA           Mechanical Room         1         EA           Ducts-         Mechanical Room         100         LF           Mechanical Room         24         EA           Steam Low         Boiler Room         1         EA           Boiler Room         3         EA           Boiler Room         1         EA	Mechanical Room         1         EA         6           Mechanical Room         1         EA         6           Mechanical Room         1         EA         6           Ducts-         Mechanical Room         100         LF         6           Mechanical Room         24         EA         3           Steam Low         Boiler Room         1         EA         6           Boiler Room         3         EA         6           Boiler Room         1         EA         6	Cone-         Mechanical Room         1         EA         6         6-10 years           Mechanical Room         1         EA         6         6-10 years           Mechanical Room         1         EA         6         6-10 years           Ducts-         Mechanical Room         100         LF         6         6-10 years           Mechanical Room         24         EA         3         6-10 years           Steam Low         Boiler Room         1         EA         6         10+ years           Boiler Room         3         EA         6         10+ years           Boiler Room         1         EA         6         10+ years

Campus Name: Chase Page : 5 of 41 Assessment Date: 02/29/2024



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	10+ years	B-2
	Steam- Low Pressure Boiler - 50 - 75 HP					, , , , ,	
	Piping - Condensate Pipe- Steel	Boiler Room	160	LF	6	10+ years	Welded steel, uninsulated
	Piping - Steam Pipe- Steel	Boiler Room	160	LF	6	10+ years	Wolded Steel, armiodiated
	Steam Traps	Boiler Room	12	EA	6	6-10 years	
	Steam Traps	Boiler Room	12	LA	U	0-10 years	
leating	Davicas						
leating	Unit Heater - Steam	Boiler Room	2	ГΛ	6	6-10 years	
			2	EΑ	6		la cabinata
	Radiators - Steam	Entire Building	11	EΑ	6	6-10 years	In cabinets
	Unit Heater - Electric	Entire Building	2	EA	6	10+ years	
	Unit Heater - Electric	Entire Building	2	EA	6	10+ years	
	Unit Heater - Electric	Entire Building	2	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	12	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	1	EA	5	1-2 years	Face plate missing
Femnera	ture Control						
empera	Electric Thermostat	Entire Building	17	EA	4	6-10 years	System has malfunctioned, and all
	Electric Monnestat	Entire Ballanig	11	_/\	•	o to youro	control is manual per engineer
	Pneumatic System	Entire Building	41,959	SF	4	1-2 years	System has many links, pneumatic,
	aa eye.e	g	,555	٠.	•	/ 0 0	control, non-functional
	Thermostats - Pneumatic	Entire Building	24	EA	5	6-10 years	oomioi, non ranouonai
		g			· ·	o .o you.o	
√entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	Electrical vault exhaust fan
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EΑ	7	10+ years	That ducted exhaust fan in closet N
		3				, , , , ,	included in previous assessment
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	10+ years	Quantity segregated to reflect
	CFM	Entire Ballating		L/\	O	101 years	observed conditions/capacity
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	7	10 L Vooro	Serves single stall toilet room,
		Entire Building	'	EA	1	10+ years	
	CFM						category, updated to reflect observe
			_		_		conditions, capacity
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	10+ years	Capacity updated to reflect observe
	CFM						conditions
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	10+ years	Quantity updated to reflect observed
	CFM						conditions/capacity
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate		D 11 D				0.10	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EΑ	6	6-10 years	

Campus Name: Chase Page : 6 of 41 Assessment Date: 02/29/2024



Catego	ry : Plumbing	В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	41,959	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	41,959	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	41,959	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	41,959	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	41,959	SF	6	10+ years	
	Sanitary Piping	Entire Building	41,959	SF	6	10+ years	
	Storm Piping	Entire Building	41,959	SF	6	10+ years	
	Vent Piping	Entire Building	41,959	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	10+ years	In elevator pit, not accessible at time of assessment

Category : Room **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	104 Community School Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	104 Community School Office	334	SF	6	6-10 years	
	Ceiling - Lay-in	104 Community School Office	6	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	104 Community School Office	1	EΑ	6	10+ years	· ·
	Floor - Tile	104 Community School Office	340	SF	6	10+ years	
	Lighting - Pendent/Surface	104 Community School Office	4	EA	6	6-10 years	
	Power Distribution	104 Community School Office	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	104 Community School Office	909	SF	6	10+ years	
	Work SInk	104 Community School Office	1	EA	7	10+ years	
	AC Unit	105 Nurse's Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	105 Nurse's Office	350	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Nurse's Office	1	EA	6	10+ years	
	Floor - Tile	105 Nurse's Office	350	SF	7	10+ years	
	Lighting - Lay-in	105 Nurse's Office	5	EA	7	10+ years	
	Power Distribution	105 Nurse's Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	105 Nurse's Office	936	SF	6	10+ years	
_Gymnas	ia						
-	Ceiling - Plaster/Drywall	305	3,684	SF	6	10+ years	No max occupancy sign

Campus Name: Chase Page : 7 of 41 Assessment Date: 02/29/2024



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	305	8	EA	7	10+ years	
	Floor - Tile	305	3,640	SF	6	10+ years	
	Floor - Tile	305	44	SF	4	0-1 year	Cracking tiles
	Lighting - Pendent/Surface	305	42	EA	7	10+ years	
	Sound System	305	1	EA	7	6-10 years	
	Stage	305	1,062	SF	7	10+ years	
	Stage Curtain	305	· 1	EA	7	10+ years	
	Stage Lift	305	1	EΑ	7	10+ years	
	Stage-Stairs - Wood	305	32	LF	7	10+ years	Updated quantity
	Storage/ Closet	305	6	SF	7	10+ years	opacioa quantity
	Walls - Plaster/Drywall	305	4,435	SF	6	10+ years	
	Walls - Flaster/Drywall	303	4,433	OI.	O	10+ years	
1DF_ID	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	154	SF	5	10+ years	Water damage to walls and ceiling
							tile broken and peeling up, subfloo
							exposed
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
echani	ical/ Service Rooms						
	Janitor's Closet	2nd Floor	7	SF	5	6-10 years	Relamp
	Janitor's Closet	3rd Floor	10	SF	7	10+ years	Maintenance 303
	Air Intake Plenums	Basement	250	SF	7	10+ years	Waintenance 505
	Air Tunnel	Basement	150	SF	7	10+ years	
	Boiler Room		832	SF	7	10+ years	
		Basement		SF		-	
	Coal Room	Basement	240	SF SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	225		7	10+ years	
	Mechanical/ Service Rooms	Basement	75	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	200	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	315	SF	7	10+ years	
	Storage Room	Basement	42	SF	7	10+ years	
	Storage Room	Basement	70	SF	7	10+ years	
estroor	n						
	Accessories	014A	60	SF	7	6-10 years	
	Ceiling - Exposed	014A	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	014A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	014A	60	SF	7	10+ years	
	Floor Drain	014A	1	ĒΑ	7	10+ years	
	Lavatory	014A	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	014A	1	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	014A	320	SF	7	10+ years	
	Water Closet	014A	1	EA	7	10+ years	
	Water Gloset	017/	Į.		,	10+ years	

Campus Name: Chase Page : 8 of 41 Assessment Date: 02/29/2024



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	2nd Floor	302	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	302	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	302	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	7	6-10 years			
	Lavatory	2nd Floor	5	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years			
	Partitions	2nd Floor	8	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	180	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	10+ years	Water damage at windowsill		
	Walls - Structural Glazed Tile	2nd Floor	740	SF	7	10+ years			
	Water Closet	2nd Floor	8	EA	7	10+ years			
	Accessories	2nd Floor	274	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	274	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	274	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	5	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years			
	Partitions	2nd Floor	4	EA	7	10+ years			
	Urinals	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	454	SF	7	10+ years			
	Water Closet	2nd Floor	4	EA	7	10+ years			
	Accessories	2nd Floor Unisex	57	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor Unisex	57	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor Unisex	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex	57	SF	6	10+ years			
	Floor Drain	2nd Floor Unisex	1	EA	7	10+ years			
	Hand Dryer	2nd Floor Unisex	1	EA	7	10+ years			
	Lavatory	2nd Floor Unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor Unisex	1	EΑ	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor Unisex	151	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor Unisex	172	SF	7	10+ years			
	Water Closet	2nd Floor Unisex	1	ĒΑ	7	10+ years			
	Accessories	Basement	434	SF	7	6-10 years			
	Ceiling - Exposed	Basement	434	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement	431	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Basement	3	SF	4	0-1 year	Missing and cracked tiles		
	Floor Drain	Basement	1	EA	7	10+ years			
	Hand Dryer	Basement	1	EA	7	6-10 years			
	Lavatory	Basement	5	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years			
	Lighting Foliacity outland	Dascinoni	O	L/\	,	o to yours			

Campus Name: Chase Page : 9 of 41 Assessment Date: 02/29/2024



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	Basement	6	EA	7	10+ years	
	Urinals	Basement	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	Basement	772	SF	7	10+ years	
	Water Closet	Basement	6	EA	7	10+ years	
	Accessories	Basement	625	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	625	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	625	SF	7	10+ years	
	Floor Drain	Basement	2	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	5	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	9	EA	7	6-10 years	
	Partitions	Basement	12	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Basement	1,260	SF	7	10+ years	
	Water Closet	Basement	12	EA	7	10+ years	
	Accessories	Basement Floor Unisex	59	SF	7	6-10 years	
	Ceiling - Exposed	Basement Floor Unisex	59	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Floor Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Floor Unisex	59	SF	7	10+ years	
	Floor Drain	Basement Floor Unisex	1	EΑ	7	10+ years	
	Hand Dryer	Basement Floor Unisex	1	EΑ	7	6-10 years	
	Lavatory	Basement Floor Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Floor Unisex	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Basement Floor Unisex	272	SF	7	10+ years	
	Water Closet	Basement Floor Unisex	1	EA	7	10+ years	

Category : Classroom **Building: Main** 

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #010 (Pre School)						
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	5	LF	6	10+ years	Corrected quantity
	Ceiling - Plaster/Drywall	Basement	774	SF	6	10+ years	
	Chalk Board	Basement	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	766	SF	7	10+ years	
	Floor - Tile	Basement	8	SF	4	0-1 year	Chipped tiles. Quantity updated to match current observations
	Lighting - Pendent/Surface	Basement	17	EA	7	10+ years	
	Marker Board	Basement	20	LF	7	6-10 years	Not previously assessed
	Storage/ Closet	Basement	125	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,072	SF	6	10+ years	
	Work Sink	Basement	. 1	EA	7	10+ years	

Classroom #013 (Kindergarten)



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	529	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Carpet	Basement	529	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement	11	EA	7	6-10 years	
	Storage/ Closet	Basement	63	SF	7	10+ years	
	Walls - Concrete Block	Basement	450	SF	7	10+ years	
	Walls - Plaster/Drywall		450	SF		-	
		Basement			7	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroc	om #014 (Kindergarten)						
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	955	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	Corrected quantity
	Floor - Tile	Basement	955	SF	6	10+ years	Corrocted quartity
	Lighting - Pendent/Surface	Basement	10	EA	7	10+ years	Quantity updated to match current
	Lighting - Fendent/Surface	Dasement	10	LA	′	10+ years	observations
	Marker Board	Basement	5	LF	7	6-10 years	observations
	Storage/ Closet	Basement	12	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,120	SF	6		
	Work Sink		1,120	EA	7	10+ years	
	WOIK SIIIK	Basement	ı	EA	,	10+ years	
Classroc	om #016 (Office)						
	AC Units	Basement	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	783	SF	6	10+ years	
	Chalk Board	Basement	22	LF	4	2-5 years	
	Doors - Steel Doors incl hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	783	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	10+ years	
	Storage/ Closet	Basement	100	SF	7	-	
	Walls - Plaster/Drywall	Basement	1,294	SF	6	10+ years	Recombined quantities
				SF SF		10+ years	
	Walls - Plaster/Drywall	Basement	25	SF	5	10+ years	Cracking where ceiling meets the wa
Classroc	om #021 (Faculty Lounge)						
	AC Units	Basement	2	EA	7	6-10 years	Quantity updated to match current observations
	Casework	Basement	8	LF	7	10+ years	
	Ceiling - Splined	Basement	486	SF	6	10+ years	
	Ceiling - Splined	Basement	4	SF	4	0-1 year	Damaged tiles
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	7	10+ years	<b>3</b> · · · · ·

Campus Name: Chase Page : 11 of 41 Assessment Date: 02/29/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement	486	SF	6	10+ years	
	Floor - Tile	Basement	4	SF	4	0-1 year	Cracked
	Lighting - Pendent/Surface	Basement	6	EA	6	10+ years	
	Marker Board	Basement	5	LF	7	6-10 years	
	Storage/ Closet	Basement	50	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	704	SF	7	10+ years	
Classroc	om #101 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	726	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	726	SF	6	,	Corrected quantity
						10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,256	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9	SF	5	10+ years	Cracking where ceiling meets wall
Classroc	om #102 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	Not previously assessed
	Ceiling - Plaster/Drywall	1st Floor	726	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	726	SF	6	6-10 years	. ,
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,225	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #103 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	804	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	SF EA		-	Corrected quantity
					6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	804	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	1st Floor	8	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	5	6-10 years	Light switch does not work
	Marker Board	1st Floor	6	LF	7	6-10 years	

Campus Name: Chase Page : 12 of 41 Assessment Date: 02/29/2024



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,319	SF	6	10+ years	
Classroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	756	SF	6	10+ years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	744	SF	6	10+ years	
	Floor - Tile	1st Floor	12	SF	4	0-1 year	Cracked by entrance
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	738	SF	6	10+ years	Quantity updated to match current observations
lassroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	2	EΑ	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	740	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	6	6-10 years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	742	SF	6	10+ years	Corrected quartity
	Floor - Tile	1st Floor	8	SF	4	0-1 year	Cracking near entrance
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	Grading ridar distraction
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,225	SF	6	10+ years	Recombined quantities
Classroo	m #108 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	740	SF	7	10+ years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,210	SF	7	10+ years	

Campus Name: Chase Page : 13 of 41 Assessment Date: 02/29/2024



Catego	ry : Classroom		В	uilding	: Main	·	
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
·	Walls - Plaster/Drywall	1st Floor	45	SF	6	10+ years	Cracking, peeling paint where wal and ceiling meet
Classroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	82	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,274	SF	6	10+ years	
lassroc	om #202 (Art Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,294	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
lassroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	865	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,365	SF	6	10+ years	
lassroc	nm #206 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	

Campus Name: Chase Page : 14 of 41 Assessment Date: 02/29/2024



Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	838	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	724	SF	7	10+ years	
	Floor - Tile	2nd Floor	114	SF	4	0-1 vear	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	aranamag maa
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,314	SF	7	10+ years	
	Work Sink	2nd Floor	1,514	EA	7	10+ years	
			·			, , , , , , , , , , , , , , , , , , , ,	
lassro	om #207 (Regular Classroom)						
	AC Units	2nd Floor	_2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	778	SF	7	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	759	SF	7	10+ years	
	Floor - Tile	2nd Floor	19	SF	4	0-1 year	Broken and missing tiles
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	7	10+ years	3
	Marker Board	2nd Floor	18	LF	7	10+ years	
	Storage/ Closet	2nd Floor	112	SF	7	10+ years	Corrected quantity
	Walls - Plaster/Drywall	2nd Floor	896	SF	7	10+ years	Corrected quartity
lassro	om #208 (Regular Classroom)					·	
//assior	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	774	SF	7	10+ years	
	Doors - Transom Window	2nd Floor		SF	6	-	
			9			10+ years	On the standard second title
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	2nd Floor	762	SF	6	10+ years	
	Floor - Tile	2nd Floor	12	SF	4	0-1 year	Tiles cracking and broken edges
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	17	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,265	SF	6	10+ years	
:lassro	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	732	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	•	
	Floor - Tile			SF		10+ years	Corrected quantity
	FIOOL - THE	3rd Floor	732	2L	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	

Campus Name: Chase Page : 15 of 41 Assessment Date: 02/29/2024



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	71	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	6	10+ years	
lassroc	om #302 (Music Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	732	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	15	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	26	LF	4	2-5 years	ŭ
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	Corrected quantity
	Floor - Carpet	3rd Floor	747	SF	6	6-10 years	Conscion quantity
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	Not previously assessed
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	Not providuoly accepted
	Walls - Plaster/Drywall	3rd Floor	1,198	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Water damage
	walls - Flastel/Diywall	314 1 1001	3	O.	3	0-1 year	vvater damage
lassroc	om #307 (Store Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	506	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	Corrected quantity
	Floor - Tile	3rd Floor	506	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EΑ	7	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
lassroc	om #308 (Vacant)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Carpet	3rd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	6	6-10 years	Relamp
	Marker Board	3rd Floor	7	LF	6	6-10 years	Relatify
	Storage/ Closet	3rd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,214	SF	6	-	
	vvalis - Flastel/Diywali	31U F1001	1,214	SF	O	10+ years	



Recommend

**Building: Main** Category : Classroom

Group Item - Type Location Quantity UOM Rank Replacement Comments

Category : Interior **Building** · Main

Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Plaster/Drywall	1st Floor	2,060	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Wood	1st Floor	2,060	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	67	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,926	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,796	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Wood	2nd Floor	1,796	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	67	EA	7	10+ years	Not previously assessed
	Walls - Plaster/Drywall	2nd Floor	3,049	SF	6	10+ years	•
	Ceiling - Plaster/Drywall	2nd Floor - Exit Hallway	169	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor - Exit Hallway	2	EA	6	10+ years	
	Floor - Wood	2nd Floor - Exit Hallway	169	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Exit Hallway	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Exit Hallway	844	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,253	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	, 1	ĒΑ	6	10+ years	
	Doors - Transom Window	3rd Floor	24	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	2	ĒΑ	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	4	ΕA	7	10+ years	
	Floor - Wood	3rd Floor	1,253	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,846	SF	6	10+ years	
	Ceiling - Exposed	Basement	2,291	SF	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	4	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	2,291	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	23	EΑ	7	6-10 years	
	Stairs - Concrete Stairs	Basement	66	LF	7	10+ years	
	Walls - Masonry	Basement	3,492	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	2,328	SF	7	10+ years	
			2,020	<u> </u>	•	,	
Safety							
	Camera Viewing Station	Entire building	1	EA	7	6-10 years	
	Security Cameras	Entire building	2	EA	7	6-10 years	
Stairs							
Sidiis							

Campus Name: Chase Page : 17 of 41 Assessment Date: 02/29/2024



Catego	ry : Interior		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	East (Stair 1)	480	SF	7	10+ years	
	Floor - Tile	East (Stair 1)	480	SF	6	10+ years	
	Handrails	East (Stair 1)	140	LF	7	10+ years	
	Lighting - Pendent/Surface	East (Stair 1)	8	EA	7	10+ years	
	Stairs - Rubber	East (Stair 1)	434	LF	6	6-10 years	
	Walls - Plaster/Drywall	East (Stair 1)	3,016	SF	7	10+ years	
	Walls - Plaster/Drywall	East (Stair 1)	30	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	North (Stair 2)	355	SF	7	10+ years	
	Floor - Tile	North (Stair 2)	360	SF	6	10+ years	
	Handrails	North (Stair 2)	136	LF	7	10+ years	
	Lighting - Pendent/Surface	North (Stair 2)	8	EA	7	10+ years	
	Stairs - Rubber	North (Stair 2)	497	LF	6	6-10 years	
	Walls - Plaster/Drywall	North (Stair 2)	3,665	SF	6	10+ years	
_Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	

Campus Name: Chase Page : 18 of 41 Assessment Date: 02/29/2024



Category : Exterior Building : Linked Addition

Catego	ry : Exterior		Building : Linked Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Entrance	9									
	Exterior Doors - Exterior FRP Door	1	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	1	1	EA	6	6-10 years				
	Exterior Doors - Exterior Steel Door	10	2	ĒΑ	7	10+ years				
	Entrance Control - Audio and Video	11	1	EA	6	10+ years				
	Exterior Doors - Exterior Steel Door	11	1	EA	6	10+ years				
	Exterior Doors - Exterior Steel Door	12-Yard Storage	1	EA	6	1-2 years	Corroded frame			
	Exterior Doors - Exterior Steel Door	13	2	ĒΑ	6	6-10 years				
	Exterior Doors - Exterior Steel Door	14	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	14	1	EA	6	6-10 years				
	Exterior Doors - Store Front	15	1	EA	6	6-10 years				
	Exterior Doors - Transom Lite	15	1	EA	6	10+ years				
	Exterior Doors - Store Front	16	1	EA	6	6-10 years				
	Exterior Doors - Transom Lite	16	1	EA	6	6-10 years				
	Exterior Doors - Exterior Steel Door	17-Roof	2	EA	6	10+ years				
	Entrance Control - Audio and Video	2	2	EΑ	7	10+ years				
	Exterior Doors - Exterior FRP Door	2	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	2	1	EΑ	6	6-10 years				
	Extend Boole Transom Exe	_	·	_, \	Ŭ	o to youro				
Foundati	on									
T Odridati	Foundation - Concrete	Entire Building	592	LF	7	10+ years				
	Superstructure - Metal Deck/ Concrete	Entire Building	42,756	SF	7	10+ years				
	Topping	Littile Building	72,730	Oi	,	10+ years				
	Торринд									
Lighting										
Ligiting	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	10+ years				
	Exterior Lighting Wall Woulded	Entire Ballating	11	L/\	O	101 years				
Roof Sys	stem									
	Coping - Metal	F - link	64	LF	6	6-10 years				
	Downspouts - Interior Downspouts	F - link	15	LF	6	10+ years				
	Parapet - Parapet < 16" Height	F - link	64	LF	6	10+ years				
	Roof - Modified Bitumen	F - link	880	SF	5	0-1 year	Worn roof with several patched areas			
	Roof Structure - Steel / Metal Deck/	F - link	880	SF	7	10+ years	Trom roof war ooveral pateriou areas			
	Concrete Topping		000	٥.	•	io. youro				
	Coping - Metal	G	424	LF	6	10+ years				
	Coping - Stone	G	39	LF	6	10+ years				
	Downspouts - Interior Downspouts	G	172	LF	6	10+ years				
	Parapet - Parapet < 16" Height	G	385	LF	6	10+ years				
	Parapet - Parapet > 30"	G	39	LF	6	10+ years				
	Roof - Modified Bitumen	G	9,316	SF	4	0-1 year	Worn surface, cracks, blistering, soft			
	11001 Modified Dituffier	3	3,310	Oi.	7	o-i yeai	spots, open seams			
	Roof Hatch - Metal	G	1	EA	7	6-10 years	opoto, opoti oddino			
		-	•	_, .	•	5 .5 Jours				

Campus Name: Chase Page : 19 of 41 Assessment Date: 02/29/2024



Catego	ry : Exterior		В	uilding	: Linked	d Addition	
					_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Roof Structure - Steel / Metal Deck/	G	9,316	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Н	1	EA	7	6-10 years	
	Chimney - Metal Flue	Н	40	LF	7	10+ years	
	Coping - Metal	Н	140	LF	6	10+ years	
	Downspouts - Interior Downspouts	Н	116	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Н	140	LF	6	10+ years	
	Roof - Modified Bitumen	Н	1,221	SF	4	0-1 year	Worn surfaces, soft spots, blistering,
							large areas of previous patches,
	Poof Structure Stool / Motel Dook/	ш	1,221	SF	7	10 L VOORO	deteriorated sealants, older roof
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Н	1,221	SF	7	10+ years	
	Access Ladder - Metal	1	1	EA	4	0-1 year	Loose ladder, unattached CMU
	Coping - Metal	i	126	LF	6	10+ years	Loose ladder, driattached Civio
	Downspouts - Interior Downspouts	1	28	LF	6	10+ years	
	Parapet - 16" - 30" Height		126	LF	6	10+ years	
	Roof - Modified Bitumen	1	3,344	SF	4	0-1 year	Distressed roof, open seams,
	Rooi - Modified Bitumen	ı	3,344	SF	4	0-1 year	blistering throughout, worn surface
	Roof Hatch - Metal	1	1	EA	7	10+ years	bilotoring timoagnoat, worm barrage
	Roof Structure - Steel / Metal Deck/	i	3,344	SF	7	10+ years	
	Concrete Topping	•	0,044	O.	,	101 years	
	Access Ladder - Metal	J	1	EA	7	10+ years	
	Coping - Metal	J	100	LF	6	10+ years	
	Downspouts - Interior Downspouts	.J	27	LF	6	10+ years	
	Parapet - 16" - 30" Height	J	100	LF	6	10+ years	
	Roof - Modified Bitumen	J	1,178	SF	5	0-1 year	Blistering throughout, growing
	Noor Woulded Blamon	· ·	1,170	O.	O	o i youi	vegetation, very distressed roof
							surface
	Roof Structure - Steel / Metal Deck/	J	1.178	SF	7	10+ years	dirace
	Concrete Topping	ŭ	1,170	Oi.	'	101 years	
	Controller Topping						
Walls							
	Exterior Walls - Brick	Entire Building	17,385	SF	6	2-5 years	
	Exterior Walls - Brick	Entire Building	1,000	SF	5	10+ years	Deteriorated mortar, deteriorated
							sealant at control joints, very few
							open joints. Verified that mortar at
							exterior and interior of penthouse is
							mostly in good to fair condition.
	Exterior Walls - Prefabricated Metal Panel	Entire Building	195	SF	6	10+ years	
	Wall						
	Exterior Walls - Terra Cotta	Entire Building	2,100	SF	6	10+ years	
VA/Com 1	_						
Windows		F (					
	Guard - Guards perforated	Entire Building	1,172	SF	6	10+ years	

Campus Name: Chase Page : 20 of 41 Assessment Date: 02/29/2024



Group

Category : Exterior

Item - Type

#### Salmon P Chase Elementary School 2021 N Point STREET, Chicago, IL 60647

**Building: Linked Addition** 

Rank

UOM

Quantity

Recommend

Replacement Comments

Group	item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
	Guard - Guards wire guard	Entire Building	268	SF	6	10+ years	
	Lintels - Steel	Entire Building	502	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	838	SF	6	10+ years	
	pane	Entire Banding	555	O.	Ŭ	ioi youro	
	Windows - Decorative	Entire Building	1,871	SF	6	6-10 years	
	Windows - Insulated Panel	Entire Building	90	SF	6	10+ years	
	Windows - Louver	Entire Building	62	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	81	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•			a.a	00		rio più comoni	
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	7,314	SF	6	10+ years	
	Stairs						
	Emergency A/C Power - Lunchrooms	Entire Building	2,250	SF	6	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	10	EA	6	6-10 years	
	Stairs	g			•	,	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	2	0-10 years	No battery or back up generator
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	No battery or back up generator
	Security System - CCTV	Entire Building	2	SF	5	6-10 years	Not included in previous assessment
							At main entrance and lunch room
	Security System - Intrusion Detection	Entire Building	84,715	SF	5	6-10 years	
Main Sei	vice						
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
		Liectrical Room	'	LA	,	10+ years	
	emergency power	Fating Duilding	04.745	0.5	4	0.40	On the state of the state of the state of
	PA System	Entire Building	84,715	SF	4	6-10 years	Serves addition and main building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EΑ	7	6-10 years	L2A PP-2 L-4
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel ELP is live front in
	Lighting and Fower Farioto Foots	Ermi o Bananig	·	_, .	•	o i you	electrical room Quiz segregated to
							reflect observed live front condition
	Lighting and Dawer Danala Above 100 A	Fating Divilations	7	Ε.	7	C 10	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	6-10 years	H-1 L-1 L-2 AC-2 L-3 MDF H-Z
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	0-1 year	Unlabeled panel outside of engineers
							office is live front
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	4	1-2 years	Surface rust all over panel
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	7	10+ years	LDP CP-2 Quantity segregated to
		5				,	reflect, observed capacities
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	MSB is 800A Quantity segregated to
	Main Biothbutton 1 and 5 Greater than 600	Entire Daliding	•	L/\	,	101 yours	mob is 50071 Qualitity sogregated to

Location

Campus Name: Chase Page : 21 of 41 Assessment Date: 02/29/2024



Catedo	ry : Electrical		В	uildina	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	amp  Transformers - 277/480 - 120/208	Entire Building	3	EA	6	10+ years	reflect observed conditions, capacity Previously categorized as main deal front or less than 600 amp distribution panel
	Transformers - 277/480 - 120/208	Entire Building	1	EA	4	6-10 years	Transformer is extremely loud and appears older than the switchgear in the room Quantity segregated to reflect observed conditions
Catego	ry : Fire Protection		В	uildina	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	m						
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	Serves main and addition
	Fire Alarm Strobe Lights	Entire Building	42,756	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	42,756	SF	6	6-10 years	
^-t	n Machanical		В	:   a  : a.	.   :	I A alalitia	
Catego	ry : Mechanical		В	ullaing	: Linked	I Addition Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	· •	Locution	Quantity	COM	IXAIIX	Replacement	Comments
All Colla	Chiller-Water Cooled- Cetrifugal - 100-200 tons	Penthouse	1	EA	5	6-10 years	Recently, tuned, functional Insulation has degraded on refrigerant piping and needs to be replaced Chiller uni compressors, and controls separate from condensers on rooftop
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	4	1-2 years	Original, outdated, corroded, damaged fins
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	4	1-2 years	Original, outdated, corroded, damaged fins
Air Hand	ling Systems						
	Make Up Air Unit- Roof Mounted- Electric Coils - Less than 6000 cfm	Lower Roof	1	EA	5	1-2 years	Significant corrosion on exterior housing, beyond service life
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Lower Roof	1	EA	5	1-2 years	Age equipment, likely end of service
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons	Lower Roof	1	EA	5	10+ years	Condensate pools around unit, additional condensate pipe to roof drain required Capacity updated based on model number

Campus Name: Chase Page : 22 of 41 Assessment Date: 02/29/2024



Catego	ry : Mechanical		В	uilding	: Linked	d Addition		
_				_	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	2	EA	6	6-10 years		
	Chemical Pot Feeder	Boiler Room	1	EA	6	2-5 years		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years		
	Hot Water Pump	Boiler Room	1	EA	6	10+ years		
	Hot Water Pump	Boiler Room	1	EA	6	10+ years		
	Non Condensing- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	2	EA	6	6-10 years		
	Water Fill System	Boiler Room	1	EA	6	6-10 years		
Heating								
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	6-10 years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	5	2-5 years	Older unit showing signs of age, corrosion, near back of house door, 11 Quantity separated to reflect observed conditions	
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	5	6-10 years	No leaks to report, functional at main entrance, and both vestibules	
	Fin Tube - Hot Water	Entire Building	54	LF	6	10+ years	Serves main offices and support rooms	
	Unit Heater - Hot Water	Entire Building	3	EA	6	10+ years		
	Wall Heater - Electric	Entire Building	1	EA	6	10+ years	Not included in previous assessment	
Mechani	cal Plumbing							
	Hydronic Supply and Return - Steel	Entire Building	450	LF	6	10+ years		
	Dual Temperature Pump - Less than 10	Penthouse	1	EΑ	6	6-10 years		
	Dual Temperature Pump - Less than 10	Penthouse	1	EA	6	6-10 years		
Tempera	ature Control							
	Electric Thermostat	Entire Building	2	EA	6	10+ years	Serve exhaust fans and unit heaters	
	Pneumatic System	Entire Building	42,756	SF	4	1-2 years	Outdated, many leaks, compressor runs very frequently	
	Thermostats - Pneumatic	Entire Building	25	EA	5	6-10 years	Serves unit ventilators	
Unit Ven	tilation							
	Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water	3rd Floor	1	EA	4	2-5 years	Room A308: Ceiling mounted, cover missing	
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	4	EA	6	10+ years	Room A304	
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	21	EA	4	2-5 years	Original to the building, many issues.	
Ventilatio	on .							

Campus Name: Chase Page : 23 of 41 Assessment Date: 02/29/2024



Catego	ry : Mechanical		Building : Linked Addition					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years		
	Roof Mounted Duct Work	Entire Building	30	LF	6	6-10 years		
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years		
atego	ry : Plumbing		В	uilding	: Linked	I Addition		
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lot Wate			-					
	Gas Heater - 150000 - 300000 BTU/HR	Penthouse	1	EA	6	10+ years	Serves addition	
	Hot Water Storage Tank_Gas - 201 - 500	Penthouse	1	EA	6	10+ years	Hot water storage tank appears	
	Gallons	1 Chinouse	•	L/ \	U	101 years	uninsulated	
	Calloris						umsuated	
iping								
	Domestic Piping-Hot Water Return Lines	Entire Building	42,756	SF	7	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	42,756	SF	7	10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,756	SF	7	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,756	SF	7	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,756	SF	7	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	42,756	SF	7	10+ years		
	Sanitary Piping	Entire Building	42,756	SF	7	10+ years		
	Storm Piping	Entire Building	42,756	SF	7	10+ years		
	Vent Piping	Entire Building	42,756	SF	7	10+ years		
	. 0	C				•		
umps	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	6	6-10 years		
`otogo	ry : Room		D	uildina	. Linkoo	l Addition		
alego	y . Room		O Company	unung	. LIIIKEC	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminist	rative Suites/Offices							
	Ceiling - Lay-in	A101 Principal's Office	280	SF	7	10+ years		
	Doors - Side-lite	A101 Principal's Office	206	SF	7	10+ years		
	Doors - Transom Window	A101 Principal's Office	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	A101 Principal's Office	4	EA	7	10+ years		
	20010 WOOD DOOLD HOW HW	7.1311 Illiopara Ollioc			,	ioi youis		

Campus Name: Chase Page : 24 of 41 Assessment Date: 02/29/2024



Catego	Category : Room		Building : Linked Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	A101 Principal's Office	280	SF	7	10+ years			
	Lighting - Lay-in	A101 Principal's Office	6	EA	7	6-10 years			
	Power Distribution	A101 Principal's Office	8	EA	7	6-10 years			
	Walls - Concrete Block	A101 Principal's Office	455	SF	7	10+ years			
	Ceiling - Lay-in	A105 Assistant Principal's Office	160	SF	7	10+ years			
	Doors - Wood Doors inclu hw	A105 Assistant Principal's Office	1	EA	7	10+ years			
	Floor - Tile	A105 Assistant Principal's Office	160	SF	7	10+ years			
	Lighting - Lay-in	A105 Assistant Principal's Office	4	EA	7	6-10 years			
	Power Distribution	A105 Assistant Principal's Office	8	EA	7	6-10 years			
	Walls - Concrete Block	A105 Assistant Principal's Office	400	SF	7	10+ years			
	Ceiling - Lay-in	A106 Counselor Office	154	SF	7	10+ years			
	Doors - Wood Doors inclu hw	A106 Counselor Office	1	EA	7	10+ years			
	Floor - Tile	A106 Counselor Office	154	SF	7	10+ years			
	Lighting - Lay-in	A106 Counselor Office	4	EA	7	6-10 years			
	Power Distribution	A106 Counselor Office	10	EA	7	6-10 years			
	Walls - Concrete Block	A106 Counselor Office	422	SF	6	10+ years			
	Ceiling - Lay-in	A107 Faculty Lounge	454	SF	7	10+ years			
	Doors - Wood Doors inclu hw	A107 Faculty Lounge	1	EA	7	10+ years			
	Floor - Tile	A107 Faculty Lounge	454	SF	6	10+ years			
	Lighting - Lay-in	A107 Faculty Lounge	5	EA	7	6-10 years			
	Power Distribution	A107 Faculty Lounge	14	EA	7	6-10 years			
	Walls - Concrete Block	A107 Faculty Lounge	520	SF	7	10+ years			
	Walls - Plaster/Drywall	A107 Faculty Lounge	200	SF	6	10+ years			
	Work Sink	A107 Faculty Lounge	1	EA	7	10+ years			
	Ceiling - Lay-in	A115 Engineer's Office	100	SF	7	10+ years			
	Ceiling - Lay-in	A115 Engineer's Office	8	SF	5	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	A115 Engineer's Office	1	EA	6	10+ years			
	Floor - Tile	A115 Engineer's Office	108	SF	6	10+ years			
	Lighting - Lay-in	A115 Engineer's Office	2	EA	5	2-5 years	Missing cover		
	Power Distribution	A115 Engineer's Office	6	EA	7	10+ years	•		
	Walls - Concrete Block	A115 Engineer's Office	340	SF	6	10+ years			
	Ceiling - Lay-in	A203 Seminar Room	422	SF	7	10+ years			
	Doors - Side-lite	A203 Seminar Room	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	A203 Seminar Room	1	EA	7	10+ years			
	Floor - Tile	A203 Seminar Room	422	SF	7	10+ years			
	Lighting - Lay-in	A203 Seminar Room	6	EA	7	10+ years			
	Storage/ Closet	A203 Seminar Room	50	SF	7	10+ years			
	Walls - Concrete Block	A203 Seminar Room	600	SF	6	10+ years			
	Ceiling - Lay-in	Kitchen Office	70	SF	7	10+ years			
	Doors - Side-lite	Kitchen Office	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Kitchen Office	1	ĒΑ	6	10+ years			
	Floor - Tile	Kitchen Office	70	SF	6	10+ years			
	Lighting - Lay-in	Kitchen Office	2	ĒΑ	7	6-10 years			
	Power Distribution	Kitchen Office	4	EA	7	6-10 years			
			·		•	3 .0 ,00.0			

Campus Name: Chase Page : 25 of 41 Assessment Date: 02/29/2024



Second   S		
Walls - Concrete Block   Kitchen Office   254   SF   6   10+ years		
Ceiling - Lay-in		
Doors - Side-lite		
Doors - Transom Window   Main Office   6   SF   6   10+ 'years		
Doors - Wood Doors inclu hw   Main Office   1		
Floor - Tile		
Floor - Tile		
Lighting - Lay-in Main Office 14 EA 6 6-10 years Storage/ Closet Main Office 170 SF 7 10+ years Walls - Concrete Block Main Office 170 SF 7 10+ years Walls - Concrete Block Main Office 170 SF 6 10+ years Walls - Concrete Block Main Office 170 SF 6 10+ years Water damage Ceiling - Lay-in A125K 8 SF 6 10+ years Water damage Doors - Wood Doors inclu hw A125K 8 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw A125K 2 EA 6 10+ years Floor - Tile Quarry A125K 8 EA 7 6-10 years Storage/ Closet A125K 8 EA 7 6-10 years Storage/ Closet A125K 64 SF 7 10+ years Storage/ Closet A125K 64 SF 7 10+ years Walls - Concrete Block A125K 570 SF 6 10+ years Doors - Wood Doors inclu hw Serving Area 487 SF 7 10+ years Doors - Wood Doors inclu hw Serving Area 487 SF 7 10+ years Lighting - Lay-in Serving Area 487 SF 7 10+ years Elighting - Lay-in Serving Area 487 SF 7 10+ years Serving Area 6 EA 7 6-10 years Walls - Concrete Block Serving Area 6 EA 7 6-10 years Walls - Concrete Block Serving Area 782 SF 7 10+ years Doors - Wood Doors inclu hw Serving Area 6 EA 7 6-10 years Walls - Concrete Block Serving Area 782 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 2,250 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 3 EA 6 10+ years Poors - Side-lite 1st Floor 2,250 SF 7 10+ years Serving Lighting - Lay-in 1st Floor 3 EA 6 10+ years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Serving Lighting - Lay-in 1st Floor 3 EA 7 6-10 years Se		
Power Distribution		
Storage/ Closet   Main Office   170   SF   7   10+ years		
Walls - Concrete Block   Main Office   485   SF   6   10+ years		
Ceiling - Lay-in		
Ceiling - Lay-in		
Ceiling - Lay-in		
Doors - Wood Doors inclu hw		
Floor - Tile Quarry		
Lighting - Lay-in       A125K       8       EA       7       6-10 years         Storage/ Closet       A125K       64       SF       7       10+ years         Walls - Concrete Block       A125K       570       SF       6       10+ years         Ceiling - Lay-in       Serving Area       487       SF       7       10+ years         Doors - Wood Doors inclu hw       Serving Area       1       EA       6       10+ years         Floor - Tile Quarry       Serving Area       487       SF       7       10+ years         Lighting - Lay-in       Serving Area       6       EA       7       6-10 years         Walls - Concrete Block       Serving Area       782       SF       7       10+ years         Lunch & Multipurpose Room       2,250       SF       7       10+ years         Lunch & Multipurpose Room       2,250       SF       7       10+ years         Doors - Wood Doors inclu hw       1st Floor       28       SF       6       10+ years         Floor - Tile       1st Floor       3       EA       6       10+ years         Lighting - Lay-in       1st Floor       30       EA       7       6-10 years <t< td=""><td></td></t<>		
Storage   Closet   A125K   64   SF   7   10+ years		
Walls - Concrete Block       A125K       570       SF       6       10+ years         Ceiling - Lay-in       Serving Area       487       SF       7       10+ years         Doors - Wood Doors inclu hw       Serving Area       1       EA       6       10+ years         Floor - Tile Quarry       Serving Area       487       SF       7       10+ years         Lighting - Lay-in       Serving Area       6       EA       7       6-10 years         Walls - Concrete Block       Serving Area       782       SF       7       10+ years         Lunch & Multipurpose Room       2,250       SF       7       10+ years         Doors - Side-lite       1st Floor       28       SF       6       10+ years         Doors - Wood Doors inclu hw       1st Floor       3       EA       6       10+ years         Floor - Tile       1st Floor       2,250       SF       7       10+ years         Lighting - Lay-in       1st Floor       30       EA       7       6-10 years         Serving Line       1st Floor       30       EA       7       6-10 years         Walls - Concrete Block       1st Floor       1,286       SF       6       10+ years </td <td></td>		
Ceiling - Lay-in Serving Area 487 SF 7 10+ years Doors - Wood Doors inclu hw Serving Area 1 EA 6 10+ years Floor - Tile Quarry Serving Area 487 SF 7 10+ years Lighting - Lay-in Serving Area 6 EA 7 6-10 years Walls - Concrete Block Serving Area 782 SF 7 10+ years Serving Area 1 St Floor 1 S		
Doors - Wood Doors inclu hw Floor - Tile Quarry Lighting - Lay-in Walls - Concrete Block  Serving Area  Ceiling - Lay-in Doors - Wood Doors inclu hw Serving Area		
Floor - Tile Quarry		
Lighting - Lay-in       Serving Area       6 EA 7 6-10 years         Walls - Concrete Block       Serving Area       782 SF 7 10+ years         Lunch & Multipurpose Room       Ceiling - Lay-in       1st Floor       2,250 SF 7 10+ years         Doors - Side-lite       1st Floor       28 SF 6 10+ years         Doors - Wood Doors inclu hw       1st Floor       3 EA 6 10+ years         Floor - Tile       1st Floor       2,250 SF 7 10+ years         Lighting - Lay-in       1st Floor       30 EA 7 6-10 years         Serving Line       1st Floor       30 LF 7 10+ years         Walls - Concrete Block       1st Floor       1,286 SF 6 10+ years		
Walls - Concrete Block         Serving Area         782         SF         7         10+ years           Lunch & Multipurpose Room         Ceiling - Lay-in         1st Floor         2,250         SF         7         10+ years           Doors - Side-lite         1st Floor         28         SF         6         10+ years           Doors - Wood Doors inclu hw         1st Floor         3         EA         6         10+ years           Floor - Tile         1st Floor         2,250         SF         7         10+ years           Lighting - Lay-in         1st Floor         30         EA         7         6-10 years           Serving Line         1st Floor         30         LF         7         10+ years           Walls - Concrete Block         1st Floor         1,286         SF         6         10+ years		
Ceiling - Lay-in       1st Floor       2,250       SF       7       10+ years         Doors - Side-lite       1st Floor       28       SF       6       10+ years         Doors - Wood Doors inclu hw       1st Floor       3       EA       6       10+ years         Floor - Tile       1st Floor       2,250       SF       7       10+ years         Lighting - Lay-in       1st Floor       30       EA       7       6-10 years         Serving Line       1st Floor       30       LF       7       10+ years         Walls - Concrete Block       1st Floor       1,286       SF       6       10+ years		
Ceiling - Lay-in       1st Floor       2,250       SF       7       10+ years         Doors - Side-lite       1st Floor       28       SF       6       10+ years         Doors - Wood Doors inclu hw       1st Floor       3       EA       6       10+ years         Floor - Tile       1st Floor       2,250       SF       7       10+ years         Lighting - Lay-in       1st Floor       30       EA       7       6-10 years         Serving Line       1st Floor       30       LF       7       10+ years         Walls - Concrete Block       1st Floor       1,286       SF       6       10+ years		
Doors - Side-lite         1st Floor         28 SF 6 10+ years           Doors - Wood Doors inclu hw         1st Floor         3 EA 6 10+ years           Floor - Tile         1st Floor         2,250 SF 7 10+ years           Lighting - Lay-in         1st Floor         30 EA 7 6-10 years           Serving Line         1st Floor         30 LF 7 10+ years           Walls - Concrete Block         1st Floor         1,286 SF 6 10+ years		
Doors - Wood Doors inclu hw1st Floor3EA610+ yearsFloor - Tile1st Floor2,250SF710+ yearsLighting - Lay-in1st Floor30EA76-10 yearsServing Line1st Floor30LF710+ yearsWalls - Concrete Block1st Floor1,286SF610+ years		
Floor - Tile         1st Floor         2,250         SF         7         10+ years           Lighting - Lay-in         1st Floor         30         EA         7         6-10 years           Serving Line         1st Floor         30         LF         7         10+ years           Walls - Concrete Block         1st Floor         1,286         SF         6         10+ years		
Lighting - Lay-in1st Floor30EA76-10 yearsServing Line1st Floor30LF710+ yearsWalls - Concrete Block1st Floor1,286SF610+ years		
Serving Line1st Floor30LF710+ yearsWalls - Concrete Block1st Floor1,286SF610+ years		
Walls - Concrete Block 1st Floor 1,286 SF 6 10+ years		
MDF_IDF		
Doors - Steel Doors incl hw In faculty lounge 1 EA 7 10+ years		
Finishes In faculty lounge 55 SF 7 10+ years		
Window AC Unit In faculty lounge 1 EA 7 6-10 years		
Mechanical/ Service Rooms		
Janitor's Closet 1st Floor 25 SF 7 10+ years	<u></u>	
Mechanical/ Service Rooms 1st Floor 80 SF 7 10+ years		
Mechanical/ Service Rooms 1st Floor 238 SF 7 10+ years		
Modifical Colvide Rooms 13t 1001 200 Of 1 10+ years		

Campus Name: Chase Page : 26 of 41 Assessment Date: 02/29/2024



Catego	ry : Room		В	uilding	d Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	44	SF	7	10+ years	
	Storage Room	1st Floor	150	SF	7	10+ years	
	Vaults	1st Floor	110	SF	7	10+ years	
	Janitor's Closet	2nd Floor	42	SF	5	6-10 years	Missing and water damaged ceiling
							tile
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Janitor's Closet	3rd Floor	42	SF	5	6-10 years	Water damage to ceiling tiles, missing
						-	floor tiles
	Mechanical/ Service Rooms	3rd Floor	50	SF	7	10+ years	
	Boiler Room	Penthouse	1,050	SF	7	10+ years	
						Ţ	
Restroo							
	Accessories	102A	84	SF	7	6-10 years	
	Ceiling - Lay-in	102A	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102A	1	EA	7	10+ years	
	Floor - Tile	102A	84	SF	7	10+ years	
	Floor Drain	102A	1	EA	7	10+ years	
	Lavatory	102A	1	EA	7	10+ years	
	Lighting - Lay-in	102A	1	EA	7	6-10 years	
	Walls - Concrete Block	102A	272	SF	7	10+ years	
	Water Closet	102A	1	EA	7	10+ years	
	Accessories	106A	40	SF	7	6-10 years	
	Ceiling - Lay-in	106A	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106A	1	ĒΑ	7	10+ years	
	Floor - Tile	106A	40	SF	7	10+ years	
	Floor Drain	106A	1	ĒΑ	7	10+ years	
	Lavatory	106A	1	EΑ	6	10+ years	
	Lighting - Lay-in	106A	1	EΑ	7	6-10 years	
	Walls - Concrete Block	106A	184	SF	7	10+ years	
	Water Closet	106A	1	EA	7	10+ years	
	Accessories	108A	40	SF	7	6-10 years	
	Ceiling - Lay-in	108A	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108A	1	EA	6	10+ years	
	Floor - Tile	108A	40	SF	6	10+ years	
	Floor Drain	108A	1	EA	7	10+ years	
			1	EA	6		
	Lavatory Lighting - Pendent/Surface	108A	•	EA	6	10+ years	
		108A	1			6-10 years	
	Walls - Concrete Block	108A	184	SF	7	10+ years	
	Water Closet	108A	1	EA	7	10+ years	
	Accessories	1st Floor	208	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	208	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	208	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	

Campus Name: Chase Page : 27 of 41 Assessment Date: 02/29/2024



Catego	ry : Room	Building : Linked Addition  Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	4	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	585	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	
	Accessories	1st Floor	230	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	230	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	2	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	2	ΕA	7	10+ years	
	Walls - Concrete Block	1st Floor	618	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor Unisex	43	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Unisex	39	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor Unisex	4	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor Unisex	1	EA	7	10+ years	Water damage
	Floor - Tile	1st Floor Unisex	43	SF	7	10+ years	
	Floor Drain	1st Floor Unisex	1	EA	7	•	
			1	EA	7	10+ years	
	Lavatory	1st Floor Unisex	•			10+ years	
	Lighting - Lay-in	1st Floor Unisex	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Unisex	190	SF	7	10+ years	
	Water Closet	1st Floor Unisex	1	EA	7	10+ years	
	Accessories	2nd Floor	230	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	230	SF	7	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	618	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	208	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	208	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	208	SF	7	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor		EA	7		
	•	2nd Floor	3	EA	7		
	Lavatory Lighting - Lay-in		2		7	10+ years 10+ years	

Campus Name: Chase Page : 28 of 41 Assessment Date: 02/29/2024



atego	ry : Room		В	uilding	: Linked		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	585	SF	7	10+ years	
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	2nd Floor Men	40	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Men	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Men	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Men	35	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor Men	5	SF	5	1-2 years	Tile cracking around floor drain
	Floor Drain	2nd Floor Men	1	ĒΑ	7	6-10 years	3
	Lavatory	2nd Floor Men	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor Men	1	ΕA	7	10+ years	
	Walls - Concrete Block	2nd Floor Men	180	SF	7	10+ years	
	Water Closet	2nd Floor Men	1	EA	7	10+ years	
	Accessories	2nd Floor Women	40	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Women	34	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Women	6	SF	5		Water damage
	Doors - Wood Doors inclu hw	2nd Floor Women	1	EA	7	1-2 years	Water damage
	Floor - Tile	2nd Floor Women	40	SF	6	10+ years	
			_			10+ years	
	Floor Drain	2nd Floor Women	1	EΑ	7	10+ years	
	Lavatory	2nd Floor Women	1	EΑ	6	10+ years	
	Lighting - Lay-in	2nd Floor Women	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Women	180	SF	7	10+ years	
	Water Closet	2nd Floor Women	1	EA	7	10+ years	
	Accessories	3rd Floor	208	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	208	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	208	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	10+ years	
	Partitions	3rd Floor	4	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	585	SF	7	10+ years	
	Water Closet	3rd Floor	3	EA	7	10+ years	
	Water Closet	3rd Floor	1	EA	4	1-2 years	Out of order
	Accessories	3rd Floor	230	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	230	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	230	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	2	EΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	10+ years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	2	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	618	SF	6	10+ years	
	VVAIIS - OUTICIELE DIOUN	310 1 1001	010	31	U	TOT years	

Campus Name: Chase Page : 29 of 41 Assessment Date: 02/29/2024



Category: Room			В	uilding	: Linked		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Accessories	3rd Floor Unisex	84	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor Unisex	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Unisex	1	EA	7	10+ years	
	Floor - Tile	3rd Floor Unisex	84	SF	6	10+ years	
	Floor Drain	3rd Floor Unisex	2	EA	7	10+ years	
	Lavatory	3rd Floor Unisex	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor Unisex	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor Unisex	276	SF	7	10+ years	
	Water Closet	3rd Floor Unisex	1	ĒΑ	7	10+ years	
	Accessories	A117 Men's Locker Room (Service)	72	SF	7	6-10 years	
	Ceiling - Lay-in	A117 Men's Locker Room (Service)	64	SF	7	10+ years	
	Ceiling - Lay-in	A117 Men's Locker Room (Service)	8	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	A117 Men's Locker Room (Service)	2	EA	7	10+ years	water damage
	Floor - Tile	A117 Men's Locker Room (Service)	72	SF	6	,	
	Floor - Tile Floor Drain			Sr EA		10+ years	
		A117 Men's Locker Room (Service)	1		7	10+ years	
	Lavatory	A117 Men's Locker Room (Service)	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	A117 Men's Locker Room (Service)	1	EA	6	10+ years	
	Student Lockers - One Tier	A117 Men's Locker Room (Service)	6	EA	7	10+ years	
	Walls - Concrete Block	A117 Men's Locker Room (Service)	314	SF	6	10+ years	
	Water Closet	A117 Men's Locker Room (Service)	1	EA	7	10+ years	
	Accessories	A119 Women's Locker Room (Service)	72	SF	7	6-10 years	
	Ceiling - Lay-in	A119 Women's Locker Room (Service)	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	A119 Women's Locker Room (Service)	2	EA	7	10+ years	
	Floor - Tile	A119 Women's Locker Room (Service)	72	SF	6	10+ years	
	Floor Drain	A119 Women's Locker Room (Service)	1	EA	7	10+ years	
	Lavatory	A119 Women's Locker Room (Service)	1	EA	6	10+ years	
	Lighting - Lay-in	A119 Women's Locker Room (Service)	2	EA	6	6-10 years	
	Student Lockers - One Tier	A119 Women's Locker Room (Service)	6	EA	7	10+ years	
	Walls - Concrete Block	A119 Women's Locker Room (Service)	314	SF	6	10+ years	
	Water Closet	A119 Women's Locker Room (Service)	1	EA	7	10+ years	
	Accessories	Main Office Unisex	40	SF	7	6-10 years	
	Ceiling - Lay-in	Main Office Unisex	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Unisex	1	EA	7	10+ years	

Campus Name: Chase Page : 30 of 41 Assessment Date: 02/29/2024



0-1			_			I A .I.1'4'	2021 N FOIR STREET, Chicago, IL 80047
Catego	ry : Room		В	uilding	: Linked	d Addition	
	_				_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Main Office Unisex	40	SF	6	10+ years	
	Floor Drain	Main Office Unisex	1	EA	7	10+ years	
	Lavatory	Main Office Unisex	1	EA	6	10+ years	
	Lighting - Lay-in	Main Office Unisex	1	EA	7	6-10 years	
	Walls - Concrete Block	Main Office Unisex	200	SF	6	10+ years	
	Water Closet	Main Office Unisex	1	EA	7	10+ years	
Catego	ry : Classroom		В	uildina	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #A102 (Pre School)					rtopiacomoni	
Classioc	,	4-4 Fl ::		1.5		40	
	Casework	1st Floor	23	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,076	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,076	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	66	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,120	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #A106 (Pre School)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,142	SF	7	10+ years	
	Doors - Side-lite	1st Floor	<sup>'</sup> 6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,142	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	42	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,090	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #A108 (Pre School)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,126	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,126	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1,120	EA	7	6-10 years	
	Storage/ Closet	1st Floor	26	SF	7		
	Walls - Concrete Block	1st Floor		SF	7	10+ years	
	Work Sink	1st Floor 1st Floor	1,150 2	SF EA	7 7	10+ years 10+ years	
	ANDIK PILIK	TST FIGOR	.)	<b>-</b> Δ	,	THE VACE	



Classroom #A2D1 (Office)   Classroom #A2D1 (Of	Catego	ry : Classroom		В	uilding	: Linked	d Addition	2021 NT OIR OTREET, Officago, IE 00047
Classroom #A201 (Office)							Recommend	
Casework	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Celling - Lay-in   2nd Floor   489 SF 7   10 - Years   Celling - Lay-in   2nd Floor   6 SF 4   1 - 2 years   Water stains	Classroo	m #A201 (Office)						
Caling - Lay-in		Casework	2nd Floor	5		7	10+ years	
Chaik Board 2nd Floor 8 LF 4 2-5 years Doors - Side-life 2nd Floor 6 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Floor - Tile 2nd Floor 95 SF 6 10+ years Storage/ Closes 2nd Floor 6 EA 7 10+ years Storage/ Closes 2nd Floor 60 EA 7 10+ years Walls - Concrete Block 2nd Floor 60 SF 7 10+ years Walls - Concrete Block 2nd Floor 60 SF 7 10+ years Walls - Concrete Block 2nd Floor 80 SF 7 10+ years Walls - Concrete Block 2nd Floor 80 SF 7 10+ years Walls - Concrete Block 2nd Floor 80 SF 7 10+ years Walls - Concrete Block 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Research 2nd Floor 1 EA 6 10+ years Place Research 2nd Floor 1 EA 6 10+ years Place Research 2nd Floor 80 SF 6 10+ years Place Research 2nd Floor 80 SF 6 10+ years Place Research 2nd Floor 80 SF 6 10+ years Place Research 2nd Floor 80 SF 6 10+ years Place Research 2nd Floor 80 SF 6 10+ years Place Research 2nd Floor 80 SF 7 10+ years Place Resear		Ceiling - Lay-in	2nd Floor	489	SF	7	10+ years	
Doors - Side-lite		Ceiling - Lay-in	2nd Floor	6	SF	4	1-2 years	Water stains
Doors - Wood Doors inclu hw   Znd Floor		Chalk Board	2nd Floor	8		4	2-5 years	
Floor - Tile				6				
Lighting - Lay-in   2nd Floor   50   SF   7   10+ years						' <del>-</del> '		
Sióragie Closet   2nd Floor   600   SF   7   10+ years   Walls - Concrete Block   2nd Floor   600   SF   7   10+ years   Work Sink   2nd Floor   1   EA   7   10+ years   Work Sink   2nd Floor   1   EA   7   10+ years   Work Sink   2nd Floor   1   EA   7   10+ years   Work Sink   2nd Floor   850   SF   7   10+ years   Work Sink   2nd Floor   850   SF   7   10+ years   Work Sink   2nd Floor   24   LF   4   2-5 years   Work Sink   2nd Floor   24   LF   4   2-5 years   Work Sink   2nd Floor   1   EA   6   10+ years   Work Sink   2nd Floor   1   EA   6   10+ years   Work Sink   2nd Floor   1   EA   6   10+ years   Work Sink Sink Sink Sink Sink Sink Sink Sin					_	_	•	
Walls - Concrete Block   2nd Floor   600   SF   7   10+ years								
Classroom #A202 (Kindergarten)								
Classroom #A202 (Kindergarten)   Casework   2nd Floor   818   LF   6   10+ years   Ceiling - Lay-in   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   6   SF   7   10+ years   Chalk Board   2nd Floor   6   SF   7   10+ years   Chalk Board   2nd Floor   1   EA   6   10+ years   Chalk Board   2nd Floor   1   EA   6   10+ years   Chalk Board   2nd Floor   1   EA   6   10+ years   Chalk Board   2nd Floor   1   EA   7   10+ years   Chalk Board   2nd Floor   12   EA   7   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   844   SF   7   10+ years   Chalk Board   2nd Floor   6   SF   5   1-2 years   Water stains   Chalk Board   2nd Floor   6   SF   5   1-2 years   Chalk Board   2nd Floor   6   SF   7   10+ years   Chalk Board   2nd Floor   6   SF   7   10+ years   Chalk Board   2nd Floor   6   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   6   10+ years   Chalk Board   2nd Floor   850   SF   6   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   820   SF   6   10+ years   Chalk Board   2nd Floor   820   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Chalk Board   2nd Floor   850   SF   7   10+ years   Cha								
Casework		Work Sink	2nd Floor	1	EA	7	10+ years	
Casework	_Classroc	om #A202 (Kindergarten)						
Ceiling - Lay-in		, , ,	2nd Floor	18	LF	6	10+ vears	
Chalk Board		Ceiling - Lay-in						
Doors - Side-lite								
Floor - Tile						7	•	
Lighting - Lay-in Marker Board       2nd Floor       12 EA 7 10+ years         Marker Board       2nd Floor       8 LF 7 6-10 years         Storage/ Closet       2nd Floor       820 SF 6 10+ years         Walls - Concrete Block         Classroom #A204 (Regular Classroom)         Casework       2nd Floor       18 LF 7 10+ years         Ceiling - Lay-in       2nd Floor       844 SF 7 10+ years         Ceiling - Lay-in       2nd Floor       6 SF 5 1-2 years       Water stains         Chalk Board       2nd Floor       36 LF 4 2-5 years       Water stains         Doors - Side-lite       2nd Floor       6 SF 7 10+ years       Water stains         Floor - Tile       2nd Floor       850 SF 6 10+ years       Description of the years         Floor - Tile       2nd Floor       850 SF 6 10+ years       Storage/ Closet       2nd Floor       12 EA 7 10+ years         Storage/ Closet       2nd Floor       820 SF 6 10+ years       Storage/ Closet       2nd Floor       820 SF 6 10+ years         Walls - Concrete Block       2nd Floor       820 SF 6 10+ years       Storage/ Closet       Storage/ Close		Doors - Wood Doors inclu hw		1		6	10+ years	
Marker Board         2nd Floor         8         LF         7         6-10 years           Storage/ Closet         2nd Floor         60         SF         7         10+ years           Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A204 (Regular Classroom)           Casework         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         6         SF         5         1-2 years         Water stains           Colling - Lay-in         2nd Floor         36         LF         4         2-5 years         Vater stains           Chalk Board         2nd Floor         36         LF         4         2-5 years         Vater stains           Doors - Side-lite         2nd Floor         6         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         850         SF         6         10+ years           Floor - Tile         2nd Floor         850         SF         6         10+ years           Storage/ Closet         2nd Floor         820         SF         6         10+ years           Walls - Concre		Floor - Tile	2nd Floor	850	SF	6	•	
Storage   Closet   2nd Floor   80   SF   7   10+ years		Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
Classroom #A204 (Regular Classroom)         2nd Floor         820         SF         6         10+ years           Casework Ceiling - Lay-in         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         6         SF         5         1-2 years         Water stains           Chalk Board         2nd Floor         36         LF         4         2-5 years         Water stains           Doors - Side-lite         2nd Floor         6         SF         7         10+ years         4         2-5 ye		Marker Board	2nd Floor	8		7	6-10 years	
Classroom #A204 (Regular Classroom)		Storage/ Closet	2nd Floor	60		7	10+ years	
Casework         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         844         SF         7         10+ years           Ceiling - Lay-in         2nd Floor         6         SF         5         1-2 years         Water stains           Chalk Board         2nd Floor         36         LF         4         2-5 years         Water stains           Doors - Side-lite         2nd Floor         6         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         850         SF         6         10+ years           Lighting - Lay-in         2nd Floor         12         EA         7         10+ years           Storage/ Closet         2nd Floor         60         SF         7         10+ years           Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         18         LF         7         10+ years           Chalk Board         2nd Floor         8         LF         4         2-5		Walls - Concrete Block	2nd Floor	820	SF	6	10+ years	
Casework         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         844         SF         7         10+ years           Ceiling - Lay-in         2nd Floor         6         SF         5         1-2 years         Water stains           Chalk Board         2nd Floor         36         LF         4         2-5 years         Water stains           Doors - Side-lite         2nd Floor         6         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         850         SF         6         10+ years           Lighting - Lay-in         2nd Floor         12         EA         7         10+ years           Storage/ Closet         2nd Floor         60         SF         7         10+ years           Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         18         LF         7         10+ years           Chalk Board         2nd Floor         8         LF         4         2-5	Classroo	om #A204 (Regular Classroom)						
Ceiling - Lay-in         2nd Floor         844         SF         7         10+ years           Ceiling - Lay-in         2nd Floor         6         SF         5         1-2 years         Water stains           Chalk Board         2nd Floor         36         LF         4         2-5 years         Water stains           Doors - Side-lite         2nd Floor         6         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         850         SF         6         10+ years           Lighting - Lay-in         2nd Floor         60         SF         7         10+ years           Storage/ Closet         2nd Floor         820         SF         6         10+ years           Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         850         SF         7         10+ years           Ceiling - Lay-in         2nd Floor         850         SF         7         10+ years           Chalk Board         2nd Floor         8         LF         4		, ,	2nd Floor	18	LF	7	10+ vears	
Ceiling - Lay-in       2nd Floor       6 SF       5 1-2 years       Water stains         Chalk Board       2nd Floor       36 LF       4 2-5 years       Water stains         Doors - Side-lite       2nd Floor       6 SF       7 10+ years         Doors - Wood Doors inclu hw       2nd Floor       1 EA       7 10+ years         Floor - Tile       2nd Floor       850 SF       6 10+ years         Lighting - Lay-in       2nd Floor       12 EA       7 10+ years         Storage/ Closet       2nd Floor       60 SF       7 10+ years         Walls - Concrete Block       2nd Floor       820 SF       6 10+ years         Classroom #A206 (Regular Classroom)         Casework       2nd Floor       18 LF       7 10+ years         Ceiling - Lay-in       2nd Floor       850 SF       7 10+ years         Chalk Board       2nd Floor       8 LF       4 2-5 years         Doors - Side-lite       2nd Floor       6 SF       7 10+ years								
Chalk Board         2nd Floor         36         LF         4         2-5 years           Doors - Side-lite         2nd Floor         6         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         850         SF         6         10+ years           Lighting - Lay-in         2nd Floor         12         EA         7         10+ years           Storage/ Closet         2nd Floor         60         SF         7         10+ years           Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         850         SF         7         10+ years           Chalk Board         2nd Floor         8         LF         4         2-5 years           Doors - Side-lite         2nd Floor         6         SF         7         10+ years								Water stains
Doors - Side-lite         2nd Floor         6 SF 7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1 EA 7         10+ years           Floor - Tile         2nd Floor         850 SF 6         10+ years           Lighting - Lay-in         2nd Floor         12 EA 7         10+ years           Storage/ Closet         2nd Floor         60 SF 7         10+ years           Walls - Concrete Block         2nd Floor         820 SF 6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         18 LF 7         10+ years           Ceiling - Lay-in         2nd Floor         850 SF 7         10+ years           Chalk Board         2nd Floor         8 LF 4         2-5 years           Doors - Side-lite         2nd Floor         6 SF 7         10+ years					LF			
Doors - Wood Doors inclu hw   2nd Floor   1   EA   7   10+ years   Floor - Tile   2nd Floor   850   SF   6   10+ years   Lighting - Lay-in   2nd Floor   12   EA   7   10+ years   Storage/ Closet   2nd Floor   60   SF   7   10+ years   Walls - Concrete Block   2nd Floor   820   SF   6   10+ years   Eastroom #A206 (Regular Classroom)		Doors - Side-lite	2nd Floor	6	SF	7	-	
Floor - Tile		Doors - Wood Doors inclu hw		1	EA	7	,	
Storage/ Closet Walls - Concrete Block         2nd Floor         60 SF 7 10+ years           Classroom #A206 (Regular Classroom)         820 SF 6 10+ years           Casework Ceiling - Lay-in Chalk Board Doors - Side-lite         2nd Floor 2nd Floor         18 LF 7 10+ years 850 SF 7 10+ years           But F 4 2-5 years F 7 10+ years         2nd Floor 8 LF 4 2-5 years 9 10+ years				850	SF	6	•	
Storage/ Closet         2nd Floor         60 SF 7         10+ years           Walls - Concrete Block         2nd Floor         820 SF 6         10+ years           Classroom #A206 (Regular Classroom)         2nd Floor         18 LF 7 10+ years           Ceiling - Lay-in         2nd Floor         850 SF 7 10+ years           Chalk Board         2nd Floor         8 LF 4 2-5 years           Doors - Side-lite         2nd Floor         6 SF 7 10+ years		Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
Walls - Concrete Block         2nd Floor         820         SF         6         10+ years           Classroom #A206 (Regular Classroom)         Casework         2nd Floor         18         LF         7         10+ years           Ceiling - Lay-in         2nd Floor         850         SF         7         10+ years           Chalk Board         2nd Floor         8         LF         4         2-5 years           Doors - Side-lite         2nd Floor         6         SF         7         10+ years			2nd Floor		SF	7		
Casework2nd Floor18LF710+ yearsCeiling - Lay-in2nd Floor850SF710+ yearsChalk Board2nd Floor8LF42-5 yearsDoors - Side-lite2nd Floor6SF710+ years			2nd Floor	820	SF	6	-	
Casework2nd Floor18LF710+ yearsCeiling - Lay-in2nd Floor850SF710+ yearsChalk Board2nd Floor8LF42-5 yearsDoors - Side-lite2nd Floor6SF710+ years	Classroo	om #A206 (Regular Classroom)						
Ceiling - Lay-in2nd Floor850SF710+ yearsChalk Board2nd Floor8LF42-5 yearsDoors - Side-lite2nd Floor6SF710+ years		` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	2nd Floor	18	LF	7	10+ vears	
Chalk Board2nd Floor8LF42-5 yearsDoors - Side-lite2nd Floor6SF710+ years							,	
Doors - Side-lite 2nd Floor 6 SF 7 10+ years								
·								
=							•	
							,	

Campus Name: Chase Page : 32 of 41 Assessment Date: 02/29/2024



Catego	ry : Classroom		В	uilding	: Linked	l Addition	
						Recommend	
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	820	SF	6	10+ years	
lassroo	m #A208 (Regular Classroom)						
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	790	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor 2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
		2nd Floor 2nd Floor	60	SF	7		
	Storage/ Closet					10+ years	
	Walls - Concrete Block	2nd Floor	820	SF	6	10+ years	
lassroo	m #A209 (Laboratory/Shop)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	Not previously assessed
	Ceiling - Lay-in	2nd Floor	2,030	SF	7	6-10 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	2,030	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	2,436	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #A210 (Regular Classroom)						
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor 2nd Floor	8	LF	7		
			-	SF		6-10 years	
	Storage/ Closet	2nd Floor	60		7	10+ years	
	Walls - Concrete Block	2nd Floor	820	SF	6	10+ years	
	m #A302 (Regular Classroom)						

Campus Name: Chase Page : 33 of 41 Assessment Date: 02/29/2024



Category : Classroom			В	-			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	780	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	780	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	46	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	836	SF	6	10+ years	
Classroo	om #A303 (Office)						
	Casework	3rd Floor	21	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	874	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	874	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	100	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	918	SF	7	10+ years	
	Walls Collecte Block	314 1 1001	310	O.	,	101 years	
Classroo	om #A304 (Regular Classroom)						
	Casework	3rd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	790	SF	7	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	790	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	820	SF	6	10+ years	
Classroo	om #A306 (Regular Classroom)						
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	790	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	790	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	manor board	01011001	17	_1	,	o io youis	

Campus Name: Chase Page : 34 of 41 Assessment Date: 02/29/2024



Category : Classroom			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	820	SF	6	10+ years	
Classroc	om #A307 (Regular Classroom)						
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	726	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	726	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	820	SF	6	10+ years	
Classroo	om #A308 (Regular Classroom)						
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	790	SF	7	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	790	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	820	SF	6	10+ years	
Classroo	om #A309 (Regular Classroom)						
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Carpet	3rd Floor	690	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	10+ years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	810	SF	6	10+ years	
Classroo	om #A310 (Regular Classroom)						
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	790	SF	7	10+ years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	DOGS - VVOOG DOGIS IIIOIG IIW	Sid i looi	ľ		,	TOT years	



Catego	ry : Classroom	В	Building : Linked Addition						
			•			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	3rd Floor	790	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years			
	Marker Board	3rd Floor	8	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	64	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	820	SF	6	10+ years			
						•			

**Building: Linked Addition** Category : Interior

	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	· ·		•			•	
	Ceiling - Lay-in	1st Floor	1,500	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	ĒΑ	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Carpet	1st Floor	200	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,300	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	2,400	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,200	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	4	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,200	SF	7	10+ years	Updated to match current
						•	observations
	Lighting - Lay-in	2nd Floor	11	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	2,200	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,170	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,170	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	2,150	SF	7	10+ years	
	Ceiling - Lay-in	Link	820	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Link	150	SF	7	10+ years	
	Floor - Tile Quarry	Link	970	SF	7	10+ years	
	Lighting - Lay-in	Link	7	EA	7	10+ years	
	Lighting - Lay-in	Link	3	EA	6	10+ years	
	Walls - Concrete Block	Link	700	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Link	200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Vestibule at Link	136	SF	7	10+ years	
	Doors - Store Front	Vestibule at Link	4	EA	6	10+ years	
	Doors - Transom Window	Vestibule at Link	26	SF	6	10+ years	
	Floor - Tile Quarry	Vestibule at Link	136	SF	7	10+ years	
	Lighting - Lay-in	Vestibule at Link	3	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Vestibule at Link	180	SF	7	10+ years	
	Ceiling - Lay-in	at Main Office	188	SF	7	10+ years	

Campus Name: Chase Page : 36 of 41 Assessment Date: 02/29/2024



Category : Interior			В	-					
Recommend									
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors include hw	at Main Office	1	EΑ	6	10+ years			
	Floor - Tile/Sheet	at Main Office	188	SF	7	10+ years			
	Lighting - Lay-in	at Main Office	4	EA	7	6-10 years			
	Walls - Concrete Block	at Main Office	670	SF	6	10+ years			
Safety									
•	Security Cameras	N/A	3	EA	7	6-10 years	Not previously assessed		
Stairs									
	Ceiling - Lay-in	South A1	450	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South A1	600	SF	6	10+ years			
	Floor - Rubber Floor	South A1	280	SF	6	6-10 years			
	Floor - Tile	South A1	610	SF	6	10+ years			
	Handrails	South A1	124	LF	7	10+ years			
	Lighting - Lay-in	South A1	6	EΑ	7	10+ years			
	Stairs - Rubber	South A1	265	LF	7	10+ years			
	Walls - Concrete Block	South A1	2,000	SF	6	10+ years			
	Ceiling - Lay-in	South A2	350	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South A2	900	SF	7	10+ years			
	Floor - Tile	South A2	820	SF	6	10+ years			
	Handrails	South A2	124	LF	7	10+ years			
	Lighting - Lay-in	South A2	9	EA	7	10+ years			
	Stairs - Rubber	South A2	265	LF	7	10+ years			
	Walls - Concrete Block	South A2	2,000	SF	6	10+ years			
Vertical (	Conveyance								
	Elevator - Hydraulic Elevator	Entire building	1	EA	7	10+ years			

Campus Name: Chase Page : 37 of 41 Assessment Date: 02/29/2024



Category : Site Building : Site

Category : Site			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	13	EA	6	10+ years	
_Fencing_							
	Fencing - Chain Link	Entire Site	679	LF	7	10+ years	Recombined quantities
	Fencing - New Standard Ornamental	Entire Site	286	LF	7	10+ years	
_Landsca	De .						
	Benches	Entire Site	8	EA	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,307	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	500	SF	4	0-1 year	Broken, cracked concrete
	Landscape - Hardscape- Pavers	Entire Site	720	SF	6	10+ years	
	Parkway trees	Entire Site	11	EA	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	1,940	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	4,876	SF	7	10+ years	
	Trash Receptacles	Entire Site	7	EA	6	10+ years	
Parking	ot						
	Surface - Asphalt	North	2,562	SF	4	0-1 year	Disintegrated surface, potholes. The alley is also used to access parking. This alley is full of potholes.
	Trash Enclosure - Chain Links	North	740	SF	6	10+ years	,
_Playgrou	nd						
	Equipment - Pre K 3-5	Entire Site	1	EA	7	10+ years	
	Equipment - School Age 5-12	Entire Site	1	EA	7	10+ years	
	Surface - Poured Surface	Entire Site	1,900	SF	7	10+ years	
	Surface - Poured Surface	Entire Site	900	SF	7	10+ years	
Sidewalk	9						
Oldewall	Sidewalks - Perimeter Sidewalks	Entire Site	6,031	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,000	SF	4	0-1 year	Upheaved, cracked, broken
Signage							
Longituge	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	



1 It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Chase Page: 39 of 41 Assessment Date: 02/29/2024





Classroom Summary			•	•	1	•		•	
				Floor Plan		Glazed	Operable		_
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	202	203	745	160	56	N	Υ
Faculty Lounge	Store Room	Basement	021		490	36	18	N	N
Kindergarten	Faculty Lounge	Basement	013		529	24	12	N	N
Kindergarten	Kindergarten	Basement	014		955	68	18	N	N
Music Room	Regular Classroom	3rd Floor	302	302	747	200	84	N	Υ
Office	Regular Classroom	Basement	016		783	195	25	N	N
Pre School	Regular Classroom	Basement	010		774	48	24	N	N
Regular Classroom	Library	1st Floor	103		804	160	56	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101		726	160	56	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102		726	200	70	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106		756	200	84	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107		750	200	84	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108		740	160	56	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	204	750	160	56	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	205	865	160	56	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	206	778	200	84	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	201	774	200	84	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	303	732	160	56	N	Υ
Science Classroom	Regular Classroom	2nd Floor	206	202	838	200	84	N	Υ
Store Room	Regular Classroom	3rd Floor	307	304	506	160	56	N	N
Vacant	Regular Classroom	3rd Floor	308	308	750	200	84	N	N
	<u> </u>	•	•	•		•		•	
<b>Building: Linked Addition</b>									
Kindergarten	Regular Classroom	2nd Floor	A202	202	850	120	32	N	Υ
Laboratory/Shop	Library	2nd Floor	A209	210	2,030	90	8	N	Υ
Office	Regular Classroom	2nd Floor	A201	201	495	60	16	N	N
Office	Special Program	3rd Floor	A303	317	874	120	32	N	N
Pre School	Kindergarten	1st Floor	A106	106	1,142	150	40	N	N
Pre School	Kindergarten	1st Floor	A108	103	1,126	150	40	N	N
Pre School	Regular Classroom	1st Floor	A102	148 & 151	1,076	120	32	N	N
Regular Classroom	Regular Classroom	2nd Floor	A204	203	850	120	32	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	A206	204	850	120	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	A208	205	790	120	32	N	Y
Regular Classroom	Regular Classroom	2nd Floor	A210	206	850	120	32	N	Y
Regular Classroom	Regular Classroom	3rd Floor	A302	302	780	120	32	N	Y
Regular Classroom	Regular Classroom	3rd Floor	A304	303	790	120	32	N	Y
Regular Classroom	Regular Classroom	3rd Floor	A306	304	790	120	32	N	Y
Regular Classroom	Regular Classroom	3rd Floor	A307	309	726	120	32	N	Y



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	A308	305	790	120	32	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	A309	309	690	120	32	N	Y
Regular Classroom	Regular Classroom	3rd Floor	A310	306	790	120	32	N	Y

Campus Name: Chase Page : 41 of 41 Assessment Date: 02/29/2024