

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	3	59,069
Annex	2023	1	9,910
Modular 1 (4-Classroom)	2001	1	4,188
Campus Total			73,167

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1- Main- SW	1	EA	7	6-10 years	
	Exterior Doors - Exterior AMP Door	#1- Main- SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- Main- SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1- Main- SW	140	LF	6	10+ years	
	Exterior Stairs - Stone	#1- Main- SW	6	LF	6	10+ years	Quantity changed to match current observations
	Stair Handrail - Steel_Stair Handrail	#1- Main- SW	24	LF	6	6-10 years	
	Entrance Control - Audio and Video	#13 -SW	1	EA	7	6-10 years	Added to match current observations
	Exterior Doors - Exterior Steel Door	#13 -SW	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#13 -SW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#13 -SW	4	LF	6	10+ years	Quantity changed to match current observations
	Exterior Doors - Exterior AMP Door	#3 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 - NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - NW	66	LF	7	10+ years	
	Exterior Stairs - Stone	#3 - NW	110	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#3 - NW	100	LF	7	10+ years	
	Ramps - Concrete	#3 - NW	100	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - NW	70	LF	7	10+ years	
	Exterior Doors - Exterior AMP Door	#4 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4 - NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 - NW	20	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	#4 - NW	10	LF	4	1-2 years	Cracking/potholes
	Exterior Stairs - Stone	#4 - NW	56	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4 - NW	18	LF	6	6-10 years	
	Entrance Control - Audio and Video	#5- NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#5- NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5- NE	2	EA	7	10+ years	
	Power Door Operator and Controls	#5- NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#5.1- Boiler Room- NE	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5.2- SE	2	EA	6	6-10 years	
	Entrance Control - Audio and Video	#6 - SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior AMP Door	#6 - SE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 - SE	12	LF	6	10+ years	
	Exterior Stairs - Stone	#6 - SE	46	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	#6 - SE	20	LF	6	6-10 years	
	Exterior Doors - Exterior AMP Door	#7 - SW	2	ĒΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#7 - SW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#7 - SW	80	LF	6	10+ years	
	Exterior Stairs - Stone	#7 - SW	76	LF	6	10+ years	
	Exterior Stairs - Stone	#7 - SW	12	LF	4	0-1 year	Sinking
	Stair Handrail - Steel_Stair Handrail	#7 - SW	50	LF	6	6-10 years	•g
						•	
_Foundati		E B	0.50	. –			
	Foundation - Concrete	Entire Building	952	LF	7	10+ years	144
	Foundation - Concrete	Entire Building	20	LF	5	0-1 year	Water damage
	Superstructure - Concrete	Entire Building	59,069	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	8	SF	5	0-1 year	Cracking/separating floor In auditorium
Lighting							
- 5- 5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	13	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	6-10 years	
Roof Sys	stem						
	Coping - Terra Cotta	Boiler roof	120	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler roof	38	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Boiler roof	120	LF	6	10+ years	
	Roof - Modified Bitumen	Boiler roof	1,650	SF	4	1-2 years	Cracking throughout
	Roof Structure - Concrete	Boiler roof	1,650	SF	6	10+ years	C. Soming an oughout
	Coping - Terra Cotta	Low NW roof	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low NW roof	17	LF	5	2-5 years	Missing
	Parapet - 16" - 30" Height	Low NW roof	38	LF	6	10+ years	55.119
	Roof - Metal	Low NW roof	177	SF	5	2-5 years	
					J	_ 0 ,00.0	

Campus Name: Clissold Page : 2 of 42 Assessment Date: 11/21/2023



Category : Exterior		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel with Clay Tile Arch	Low NW roof	177	SF	7	10+ years	
	Coping - Metal	Low SE courtyard roof	29	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	Low SE courtyard roof	8	LF	6	6-10 years	
	Roof - Modified Bitumen	Low SE courtyard roof	286	SF	4	0-1 year	Soft spots/ponding stains
	Roof Structure - Concrete	Low SE courtyard roof	286	SF	7	10+ years	
	Coping - Terra Cotta	Low SW entrance	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low SW entrance	17	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Low SW entrance	38	LF	6	10+ years	
	Roof - Metal	Low SW entrance	177	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Low SW entrance	177	SF	7	10+ years	
	Access Ladder - Wood	Main Roof	2	EA	4	0-1 year	Not secured/not stable
	Chimney - Brick Chimney- Stainless Steel Liner	Main Roof	70	LF	3	0-1 year	Displaced/Cracking/open joints
	Coping - Terra Cotta	Main Roof	465	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	50	LF	7	10+ years	Quantity changed to match current observations
	Downspouts - Interior Downspouts	Main Roof	200	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	319	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	146	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	524	SF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	11,566	SF	4	0-1 year	Soft spots/bubbling/Cracking throughout
	Roof Hatch - Metal	Main Roof	2	EA	4	1-2 years	Corroded
	Roof Structure - Steel with Clay Tile Arch	Main Roof	12,090	SF	7	10+ years	
	Coping - Terra Cotta	Mid N roof	202	LF	6	10+ years	
	Downspouts - Interior Downspouts	Mid N roof	68	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Mid N roof	127	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Mid N roof	40	LF	6	10+ years	
	Parapet - Parapet > 30"	Mid N roof	35	LF	6	10+ years	
	Roof - Modified Bitumen	Mid N roof	3,514	SF	4	0-1 year	Cracking/bubbling
	Roof Structure - Steel with Clay Tile Arch	Mid N roof	3,514	SF	7	10+ years	3
	Coping - Terra Cotta	Mid S roof	374	LF	6	10+ years	
	Downspouts - Interior Downspouts	Mid S roof	186	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Mid S roof	85	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Mid S roof	289	LF	6	10+ years	
	Roof - Modified Bitumen	Mid S roof	7,740	SF	4	0-1 year	Bubbling/cracking
	Roof Structure - Steel with Clay Tile Arch	Mid S roof	7,740	SF	7	10+ years	0 0
_Walls							
	Cheek-Wall - Concrete	Entire Building	216	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	56	SF	5	0-1 year	Cracking
	Cheek-Wall - Stone	Entire Building	100	SF	6	10+ years	-
	Cornice - Terra Cotta	Entire Building	972	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,224	SF	7	10+ years	
		-				-	

Campus Name: Clissold Page : 3 of 42 Assessment Date: 11/21/2023



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	35,775	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	4	1-2 years	Cracking/open joints. Quantity changed to match current observations
	Exterior Walls - Stone-Cast	Entire Building	1,072	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,487	SF	6	10+ years	
_Windows	3						
	Curtain wall - Louver	Entire Building	12	SF	5	2-5 years	
	Lintels - Steel	Entire Building	49	LF	6	10+ years	
	Lintels - Stone	Entire Building	40	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	292	LF	6	6-10 years	
	Lintels - Terra Cotta	Entire Building	30	LF	5	0-1 year	Cracking
	Skylite - Glass Single-Pane	Entire Building	50	SF	4	0-1 year	Cracking
	Skylite - Lexan	Entire Building	40	SF	6	6-10 years	-
	Windows - Sash Aluminum Double-pane	Entire Building	3,454	SF	4	1-2 years	Bad balancers. Window wouldn't stay open.

Category : Electrical **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System		quantity			Портисотноги	
	Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
	Emergency A/C Power - Auditoium and	Entire Building	3,936	SF	6	10+ years	
	Aisle Lighting						
	Emergency A/C Power - Corridors and	Entire Building	6,684	SF	6	10+ years	
	Stairs	E 4 B 9 P	0.400	0=		4.0	
	Emergency A/C Power - Gym	Entire Building	2,403	SF	6	10+ years	
	Exit Signs - Auditoium	Entire Building	5	EA	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	5	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	5	6-10 years	
	Security System - CCTV	Entire Building	59,069	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	59,069	SF	5	6-10 years	
	Emergency Battery Packs - Auditoium and	Entire Building	4	EA	6	6-10 years	
	Aisle Lighting						
	Emergency Battery Packs - Corridors and	Entire Building	6	EA	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Generator- Outdoor- Natural	Site - East	1	EA	6	6-10 years	
	Gas - 60 - 100 KW						
_Main Se	rvice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years	
						-	



Catego	ry : Electrical		В	uilding	: Main		•
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	120/240/3PH Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power		·			•	
	PA System	Entire Building	59,069	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	2	EA	6	6-10 years	In good condition
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	4	EA	6	10+ years	
	Lighting and Power Panels - 100 A	1st floor, basement, Electrical Room, Entire building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	1st floor, basement, Electrical Room, Entire building	3	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st floor, basement, Electrical Room, Entire building	4	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	1st floor, basement, Electrical Room, Entire building	1	EA	6	10+ years	
	·	Noom, Entire building	_				
Catego	ry : Fire Protection		В	uilding	: Main	Decemberd	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar		20041011	Quantity	OOIII	Rank	Ropidocinont	Comments
nc / dai	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	
	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	Annunciator.
	Fire Alarm Strobe Lights	Electrical Room	59,069	SF	6	10+ years	
	Fire Alarm_System	Electrical Room	59,069	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond	itioning						
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
	Condensing Unit- Ground Mounted - Less	Roof	1	EA	7	10+ years	



Category : Mechanical			В	uilding	: Main		
0	Ham. Towa	Laadian	0	LIOM	D I-	Recommend	0
Group	Item - Type than 5 tons	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	Serves MDF room.
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves MDF room.
	Condensing Unit- Ground Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves MDF room.
_Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	3	EA	5	6-10 years	Serves elevator, mechanical room, and library, 203, 205, main office.
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	3	EA	5	6-10 years	Serves elevator, mechanical room, and library, 203, 205, main office.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	Gymnasium
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	Auditorium
	Air Intake	Mechanical Room	2	EA	5	6-10 years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	2	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	11	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	200	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	33	EA	5	6-10 years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	3	0-1 year	Inoperable
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room	1	EA	5	6-10 years	North
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 4000 - 8000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	10+ years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	South
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	6-10 years	
	Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling Coil - 10,001 - 20,000 cfm	Roof	1	EA	7	10+ years	Gas heating with remote condensing unit.

Campus Name: Clissold Page : 6 of 42 Assessment Date: 11/21/2023



Catego	ry : Mechanical		В	Building : Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	ystems						
·	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	2	ĒΑ	5	6-10 years	
	Condensate Pump	Boiler Room	_ 1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	0-1 year	Cracked casing on low-water cut off.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	10+ years	
	Steam Traps	Boiler Room	65	EA	5	6-10 years	
Heating							
	Cabinet Heaters - With Electric Coil	1st Floor	1	EA	6	10+ years	
	Unit Heater - Electric	Boiler Room	1	EA	6	6-10 years	
	Unit Heater - Steam	Boiler Room	2	EA	5	6-10 years	
	Radiators - Steam	Entire Building	20	EA	5	6-10 years	
	Radiators - Steam	Entire Building	2	EA	4	0-1 year	Corroded.
	Fin Tube - Steam	Entire Building	12	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years	Good condition
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Pneumatic System	Entire Building	59,065	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	26	EA	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	6	EA	4	0-1 year	Leak air
Ventilation							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	10+ years	
Catego	Category : Plumbing		Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate							
TIOL WAL	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	

Campus Name: Clissold Page: 7 of 42 Assessment Date: 11/21/2023



Category : Plumbing							
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	6	6-10 years	
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	59,069	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	59,069	SF	6	6-10 years	Clamps not visible. Repairs made.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	59,069	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	59,069	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	59,069	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	59,069	SF	6	6-10 years	Clamps no longer visible. Repairs made.
	Sanitary Piping	Entire Building	59,069	SF	5	10+ years	
	Storm Piping	Entire Building	59,069	SF	5	6-10 years	
	Vent Piping	Entire Building	59,069	SF	5	10+ years	
ımps							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	6-10 years	
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	10+ years	
atego	ry : Room		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices						
21111111131	AC Unit	1st flr engineer's office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st fir engineer's office	159	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st fir engineer's office	139	EA	6	10+ years	
	Floor - Carpet	1st fir engineer's office	159	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st flr engineer's office	2	EA	7	6-10 years	
	Power Distribution	1st fir engineer's office	6	EA	7		
	Walls - Plaster/Drywall	1st fir engineer's office	304	SF	6	10+ years	point pooling
						2-5 years	paint peeling
	Ceiling - Plaster/Drywall	1st flr helper's office next to engineer's office	80	SF	6	10+ years	Peeling paint
	Ceiling - Plaster/Drywall	1st flr helper's office next to engineer's office	39	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st flr helper's office next to engineer's office	1	EA	6	10+ years 6-10 years	
	Floor - Carpet	1st flr helper's office next to	119	SF	6		



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	1st flr helper's office next to engineer's office	1	EA	5	6-10 years			
	Power Distribution	1st flr helper's office next to engineer's office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	1st flr helper's office next to engineer's office	256	SF	6	10+ years			
	Walls - Plaster/Drywall	1st flr helper's office next to engineer's office	20	SF	5	0-1 year	Water damage		
	Ceiling - Plaster/Drywall	Conference Room inside Main Office- Previous Storage	120	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Conference Room inside Main Office- Previous Storage	2	EA	6	10+ years			
	Floor - Carpet	Conference Room inside Main Office- Previous Storage	118	SF	6	6-10 years			
	Floor - Carpet	Conference Room inside Main Office- Previous Storage	2	SF	4	1-2 years	Carpet torn		
	Lighting - Pendent/Surface	Conference Room inside Main Office- Previous Storage	1	EA	7	10+ years			
	Power Distribution	Conference Room inside Main Office- Previous Storage	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	Conference Room inside Main Office- Previous Storage	270	SF	7	10+ years			
	Walls - Plaster/Drywall	Conference Room inside Main Office- Previous Storage	4	SF	5	1-2 years	Wall damaged		
	Ceiling - Plaster/Drywall	Floor 2 Teachers Room	64	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Floor 2 Teachers Room	8	SF	5	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	Floor 2 Teachers Room	1	ĒΑ	7	10+ years	Transfer daminage		
	Floor - Tile	Floor 2 Teachers Room	62	SF	6	10+ years			
	Floor - Tile	Floor 2 Teachers Room	10	SF	4	1-2 years	Damaged tiles		
	Lighting - Pendent/Surface	Floor 2 Teachers Room	1	EA	7	10+ years	zamagoa moo		
	Power Distribution	Floor 2 Teachers Room	1	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	Floor 2 Teachers Room	186	SF	6	2-5 years	Cracks forming		
	Walls - Plaster/Drywall	Floor 2 Teachers Room	12	SF	5	0-1 year	Water damage		
	AC Unit	Main Office	1	EA	7	6-10 years	Water damage		
	Ceiling - Plaster/Drywall	Main Office	455	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years			
	Floor - Carpet	Main Office	333	SF	6	6-10 years			
	Floor - Carpet	Main Office	8	SF	4	0-10 years 0-1 year	Torn carpet		
	Floor - Tile	Main Office	114	SF	6	10+ years	Tom carper		
	Lighting - Pendent/Surface	Main Office	4	EA	7	6-10 years			
				EA					
	Power Distribution	Main Office Main Office	8	SF	7	10+ years			
	Storage/ Closet	Main Office	96 586	SF SF	7	10+ years			
	Walls - Plaster/Drywall Ceiling - Plaster/Drywall	Nurses Office 107	586 80	SF SF	6 6	10+ years			
	Ceiling - Plaster/Drywall	Nuises Office 107	80	3 F	ю	10+ years			



Catego	ry : Room		Building : Main						
3	,					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_	Doors - Wood Doors inclu hw	Nurses Office 107	1	EΑ	6	10+ years			
	Floor - Tile	Nurses Office 107	20	SF	6	10+ years			
	Floor - Tile	Nurses Office 107	60	SF	4	0-1 year	Damaged tiles		
	Lighting - Pendent/Surface	Nurses Office 107	1	EA	6	6-10 years	ů		
	Walls - Plaster/Drywall	Nurses Office 107	150	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Office in former Women's room off	136	SF	6	10+ years			
	g	the Auditorium		-	-	, , , , , , , , , , , , , , , , , , , ,			
	Doors - Wood Doors inclu hw	Office in former Women's room off	1	EA	6	10+ years			
		the Auditorium				, , , , , ,			
	Floor - Tile Ceramic/ Porcelain	Office in former Women's room off	136	SF	6	10+ years			
		the Auditorium			-	, , , , , ,			
	Lighting - Pendent/Surface	Office in former Women's room off	1	EA	7	6-10 years			
	0 0	the Auditorium				,			
	Power Distribution	Office in former Women's room off	4	EA	7	10+ years			
		the Auditorium				, , , , , ,			
	Walls - Plaster/Drywall	Office in former Women's room off	214	SF	6	10+ years			
	, .	the Auditorium			-	, , , , , ,			
	AC Unit	Principal's Office	1	EA	7	6-10 years	Not accessible engineer doesn't have		
						, , , , , , , , , , , , , , , , , , ,	key		
	Ceiling - Plaster/Drywall	Principal's Office	140	SF	6	10+ years	-,		
	Ceiling - Plaster/Drywall	Principal's Office	5	SF	5	6-10 years			
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years			
	Floor - Carpet	Principal's Office	145	SF	6	6-10 years			
	Lighting - Pendent/Surface	Principal's Office	2	ĒΑ	7	6-10 years			
	Power Distribution	Principal's Office	6	EA	7	10+ years			
	Storage/ Closet	Principal's Office	26	SF	7	10+ years			
	Walls - Plaster/Drywall	Principal's Office	304	SF	6	10+ years			
	Walls - Plaster/Drywall	Principal's Office	15	SF	5	6-10 years			
	AC Unit	Room 301A Teachers Lounge	1	ĒΑ	7	6-10 years			
	Ceiling - Plaster/Drywall	Room 301A Teachers Lounge	343	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Room 301A Teachers Lounge	5	SF	5	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	Room 301A Teachers Lounge	1	ĒΑ	6	10+ years			
	Floor - Tile	Room 301A Teachers Lounge	338	SF	6	10+ years			
	Floor - Tile	Room 301A Teachers Lounge	10	SF	4	0-1 year	Cracks		
	Lighting - Pendent/Surface	Room 301A Teachers Lounge	6	ĒΑ	7	6-10 years			
	Power Distribution	Room 301A Teachers Lounge	6	EA	7	10+ years			
	Walls - Plaster/Drywall	Room 301A Teachers Lounge	498	SF	6	10+ years			
	Walls - Plaster/Drywall	Room 301A Teachers Lounge	10	SF	5	0-1 year	Water damage		
	Work Sink	Room 301A Teachers Lounge	1	ĒΑ	7	6-10 years			
Auditorii	um & Theater								
7 totalion	Balcony Seating	1st Floor	80	EA	7	10+ years			
	Ceiling - Splined	1st Floor	3,936	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years			
	200.0 Wood 20010 Hold Hw	1001	7	_/\	J	101 years			

Campus Name: Clissold Page : 10 of 42 Assessment Date: 11/21/2023



Category :	: Room		В	uilding	: Main		
				_		Recommend	
	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	loor - Concrete Epoxy/ Painted	1st Floor	916	SF	7	10+ years	
FI	loor - Concrete Epoxy/ Painted	1st Floor	20	SF	5	0-1 year	Cracked epoxy
	loor - Tile	1st Floor	3,000	SF	6	10+ years	. ,
Li	ighting - Pendent/Surface	1st Floor	. 8	EA	7	6-10 years	
	lain Floor Seating	1st Floor	288	EA	7	10+ years	
	ound System	1st Floor	1	EA	7	6-10 years	
	tage	1st Floor	454	SF	6	10+ years	
	tage Curtain	1st Floor	8	ĒΑ	7	6-10 years	
	tage Lift	1st Floor	1	EA	7	10+ years	
	tage Lighting System	1st Floor	1	EΑ	7	6-10 years	
	tage-Stairs - Wood	1st Floor	12	LF	6	10+ years	
	Valls - Plaster/Drywall	1st Floor	4,167	SF	7	10+ years	
	Valls - Plaster/Drywall	1st Floor	50	SF	5	1-2 years	Damaged drywall
VV	valis - i lastei/Drywali	131 1001	30	OI.	3	1-2 years	Damaged drywaii
_Gymnasia							
C	eiling - Plaster/Drywall	1st Floor	2,403	SF	6	10+ years	
D	oors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
FI	loor - Wood	1st Floor	2,403	SF	6	10+ years	
Li	ighting - Metal Halide/Sodium Vapor	1st Floor	12	EA	6	6-10 years	
	Valls - Masonry	1st Floor	1,888	SF	7	10+ years	
	Valls - Masonry	1st Floor	300	SF	6	10+ years	
	·					•	
Kitchen							
	eiling - Plaster/Drywall	104B	336	SF	6	10+ years	
	oors - Wood Doors inclu hw	104B	1	EA	6	10+ years	
	loor - Tile Quarry	104B	336	SF	6	10+ years	
	ighting - Pendent/Surface	104B	4	EA	7	6-10 years	
	erving Line	104B	1	LF	7	10+ years	
W	/alls - Plaster/Drywall	104B	976	SF	6	10+ years	
Library							
	C Unit	2nd fl. room 207	1	EA	7	6-10 years	
	asework	2nd ii. 100m 207 2nd fl. room 207	72	LF	, 6	10+ years	
				SF	7		
	eiling - Lay-in	2nd fl. room 207	726	SF SF		10+ years	Water demage
	eiling - Lay-in	2nd fl. room 207	4		4	0-1 year	Water damage
	oors - Transom Window	2nd fl. room 207	18	SF	6	10+ years	
	loors - Wood Doors inclu hw	2nd fl. room 207	2	EA	6	10+ years	
	loor - Carpet	2nd fl. room 207	730	SF	6	6-10 years	
	ighting - Pendent/Surface	2nd fl. room 207	14	EA	7	6-10 years	
	Valls - Plaster/Drywall	2nd fl. room 207	1,080	SF	6	10+ years	
W	/alls - Plaster/Drywall	2nd fl. room 207	10	SF	5	0-1 year	Water damage.
Lunch & Mu	Iltipurpose Room						

Campus Name: Clissold Page : 11 of 42 Assessment Date: 11/21/2023



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	1st floor 102	3	EA	7	6-10 years	
	Ceiling - Lay-in	1st floor 102	1,560	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor 102	3	EA	7	10+ years	
	Floor - Tile	1st floor 102	1,560	SF	7	6-10 years	
	Lighting - Lay-in	1st floor 102	18	EA	7	6-10 years	
	Serving Line	1st floor 102	15	LF	7	6-10 years	
	Storage/ Closet	1st floor 102	12	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor 102	112	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st floor 102	896	SF	7	10+ years	
_MDF_ID	F						
_ _	Doors - Steel Doors incl hw	2nd flr inside Classroom 205	1	EA	6	10+ years	
	Finishes	2nd flr inside Classroom 205	130	SF	5	10+ years	Water damage at wall and ceiling
	Other Cooling Unit	2nd flr inside Classroom 205	1	EA	7	6-10 years	Ductless split system.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Storage Room	1st flr east side	291	SF	7	10+ years	
	Janitor's Closet	2nd Floor	64	SF	7	6-10 years	
	Storage Room	2nd Floor	80	SF	7	6-10 years	
	Janitor's Closet	3rd Floor	33	SF	5	10+ years	
	Air Tunnel	Basement	3,670	SF	5	10+ years	
	Boiler Room	Basement	5,680	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	6,540	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	5,680	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	290	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	10	SF	4	1-2 years	Damaged tiles
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	559	SF	6	10+ years	
	Water Closet	1st Floor	8	EA	6	10+ years	
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	200	SF	6	10+ years	
	coor - the Ceranno Forceian	151 (200)					

Campus Name: Clissold Page : 12 of 42 Assessment Date: 11/21/2023



	ry : Room		Building : Main							
						Recommend	_			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile Ceramic/ Porcelain	1st Floor	20	SF	4	1-2 years	Broken tiles			
	Floor Drain	1st Floor	1	EA	7	10+ years				
	Hand Dryer	1st Floor	1	EA	7	6-10 years				
	Lavatory	1st Floor	2	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years				
	Partitions	1st Floor	4	EA	7	10+ years				
	Urinals	1st Floor	3	EA	6	10+ years				
	Walls - Structural Glazed Tile	1st Floor	407	SF	6	10+ years				
	Walls - Structural Glazed Tile	1st Floor	2	SF	4	1-2 years	Hole in wall			
	Water Closet	1st Floor	4	EA	6	10+ years				
	Accessories	1st flr inside engineer's office	29	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st flr inside engineer's office	29	SF	5	0-1 year	Cracking			
	Doors - Wood Doors inclu hw	1st flr inside engineer's office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st flr inside engineer's office	29	SF	6	10+ years				
	Lavatory	1st flr inside engineer's office	1	EA	6	10+ years				
	Lighting - Pendent/Surface	1st flr inside engineer's office	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st flr inside engineer's office	28	SF	6	10+ years				
	Walls - Plaster/Drywall	1st flr inside engineer's office	30	SF	5	1-2 years	Water damage.			
	Water Closet	1st flr inside engineer's office	1	EA	6	10+ years				
	Accessories	1st flr inside helper's office	29	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st flr inside helper's office	29	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st flr inside helper's office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st flr inside helper's office	29	SF	6	10+ years				
	Lavatory	1st flr inside helper's office	1	EA	6	10+ years				
	Lighting - Pendent/Surface	1st flr inside helper's office	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st flr inside helper's office	98	SF	5	0-1 year	Damaged.			
	Water Closet	1st flr inside helper's office	1	EA	6	10+ years				
	Accessories	2nd Floor	300	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	290	SF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Water damage			
	Doors - Transom Window	2nd Floor	1	SF	5	1-2 years	Missing glass			
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor	300	SF	6	10+ years				
	Floor Drain	2nd Floor	1	EA	7	10+ years				
	Hand Dryer	2nd Floor	1	EA	7	6-10 years				
	Lavatory	2nd Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years				
	Partitions	2nd Floor	10	EA	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor	559	SF	6	10+ years				
	Water Closet	2nd Floor	9	EA	6	10+ years				
	Water Closet	2nd Floor	1	EA	4	1-2 years	Does not work.			
	Accessories	2nd Floor	220	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	220	SF	5	1-2 years	Peeling paint and damage throughout			
	Doors - Transom Window	2nd Floor	1	SF	5	1-2 years	Missing glass			

Campus Name: Clissold Page: 13 of 42 Assessment Date: 11/21/2023



tego	ry : Room	В	uilding				
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	4	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	220	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EΑ	7	10+ years	
	Hand Dryer	2nd Floor	1	EΑ	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	7	ĒΑ	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	409	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	3rd Floor	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	5	0-1 year	Water damage throughout
	Doors - Transom Window	3rd Floor	1	SF	5	0-1 year 0-1 year	Missing glass
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	•	Wissing glass
				SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	295		6	10+ years	Oranica in tiles
	Floor - Tile Ceramic/ Porcelain	3rd Floor	5	SF	4	1-2 years	Cracks in tiles
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Partitions	3rd Floor	7	EA	5	2-5 years	
	Walls - Structural Glazed Tile	3rd Floor	559	SF	6	10+ years	
	Water Closet	3rd Floor	7	EΑ	7	10+ years	
	Accessories	3rd Floor	220	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	220	SF	5	1-2 years	Peeling paint throughout and
	•					-	damaged.
	Doors - Transom Window	3rd Floor	1	SF	5	0-1 year	Missing glass
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	2-5 years	0 0
	Floor - Tile Ceramic/ Porcelain	3rd Floor	220	SF	6	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd Floor	1	EΑ	7	10+ years	
	Lavatory	3rd Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	8	EA	6	10+ years	
	Walls - Structural Glazed Tile		359	SF	6		
		3rd Floor		SF		10+ years	
	Walls - Structural Glazed Tile	3rd Floor	50		5	1-2 years	masonry damage
	Water Closet	3rd Floor	2	EA	6	10+ years	
	Accessories	Floor 2 Unisex	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Floor 2 Unisex	65	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Floor 2 Unisex	5	SF	6	10+ years	Peeling paint
	Doors - Wood Doors inclu hw	Floor 2 Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Floor 2 Unisex	65	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Floor 2 Unisex	5	SF	4	1-2 years	Damaged tiles

Page: 14 of 42 Campus Name: Clissold Assessment Date: 11/21/2023



Doors - Transom Window

Henry R Clissold Elementary School 2350 W 110th PLACE, Chicago, IL 60643

Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	Floor 2 Unisex	1	EA	7	10+ years				
	Hand Dryer	Floor 2 Unisex	1	EA	7	6-10 years				
	Lavatory	Floor 2 Unisex	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Floor 2 Unisex	1	EA	7	10+ years				
	Walls - Plaster/Drywall	Floor 2 Unisex	204	SF	7	10+ years				
	Walls - Plaster/Drywall	Floor 2 Unisex	2	SF	5	0-1 year	Damaged wall			
	Water Closet	Floor 2 Unisex	1	EA	7	10+ years	3			
	Accessories	Restroom Next to Auditorium	80	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Restroom Next to Auditorium	80	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Restroom Next to Auditorium	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Restroom Next to Auditorium	80	SF	6	10+ years				
	Lavatory	Restroom Next to Auditorium	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Restroom Next to Auditorium	1	EA	6	6-10 years				
	Partitions	Restroom Next to Auditorium	1	EA	7	10+ years				
	Walls - Plaster/Drywall	Restroom Next to Auditorium	200	SF	6	10+ years				
	Water Closet	Restroom Next to Additorium	1	EA	6	10+ years				
	Accessories	Restroom inside Principles Office	30	SF	7	6-10 years	Principal office not accessible			
	Accessories	Restroom inside i micipies Office	30	OI .	,	0-10 years	engineer doesn't have key			
	Ceiling - Plaster/Drywall	Restroom inside Principles Office	30	SF	6	10+ years	· ·			
	Doors - Wood Doors inclu hw	Restroom inside Principles Office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Restroom inside Principles Office	30	SF	6	10+ years				
	Lavatory	Restroom inside Principles Office	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Restroom inside Principles Office	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	Restroom inside Principles Office	60	SF	6	10+ years				
	Water Closet	Restroom inside Principles Office	1	EA	6	10+ years				
	Accessories	Women's Room, 1st Floor	89	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor	89	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Women's Room, 1st Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Women's Room, 1st Floor	89	SF	6	10+ years				
	Hand Dryer	Women's Room, 1st Floor	1	EA	7	10+ years				
	Lavatory	Women's Room, 1st Floor	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Women's Room, 1st Floor	1	EΑ	7	6-10 years				
	Partitions	Women's Room, 1st Floor	2	EΑ	7	10+ years				
	Walls - Plaster/Drywall	Women's Room, 1st Floor	152	SF	6	10+ years				
	Water Closet	Women's Room, 1st Floor	2	EA	6	10+ years				
Catego	ry : Classroom		R	uilding	: Main					
24.090	.,			ag		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Classroo	om #101 (Regular Classroom)									
	Casework	1st Floor	16	LF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years				
	Chalk Board	1st Floor	9	LF	4	2-5 years				
	Doors - Transom Window	1st Floor	۵	QE.	6	10± vears				

Campus Name: Clissold Page : 15 of 42 Assessment Date: 11/21/2023

SF

10+ years

1st Floor



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,266	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,253	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #105 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	56	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,253	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	J		_	SF		- ,	



Categor	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,253	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	726	SF	6	10+ years	
	Floor - Wood	1st Floor	4	SF	5	1-2 years	Damaged wood
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Damagea wood
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,462	SF	6	10+ years	
21						•	
Jassioo	m #201 (Regular Classroom)	01 []	4	Ε,	7	0.40	
	AC Units	2nd Floor 2nd Floor	1	EA LF	7	6-10 years	
	Casework		6		7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	Damagad
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Damaged.
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,452	SF	6	10+ years	5
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Damaged.
	Work Sink	2nd Floor	1	EA	7	10+ years	
laceroo	m #202 (Regular Classroom)						



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	725	SF	7	10+ years	
	Floor - Tile	2nd Floor	5	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,457	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Work Sink	2nd Floor	1	EA	5	0-1 year	Not functioning
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Water damage
	Chalk Board	2nd Floor	30	LF	4	2-5 years	S .
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,229	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Water damage and peeling paint
	Wireless System	2nd Floor	1	EA	7	10+ years	Trator damage and poeming paint
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	24	ĹF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,452	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Peeling paint and water damage
							i coming paint and water damage
	Work Sink	2nd Floor	1	EA	7	10+ years	

Campus Name: Clissold Page : 18 of 42 Assessment Date: 11/21/2023



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #205 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	700	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	700	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,166	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	5	1-2 years	Sink not functioning
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Water damage.
	Chalk Board	2nd Floor	8	LF	4	2-5 years	3
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,432	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	4	0-1 year	Water damage
Classroc	om #208 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,462	SF	6	10+ years	
Classroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	2-5 years	
						,	

Campus Name: Clissold Page: 19 of 42 Assessment Date: 11/21/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,216	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracked and peeling paint
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,442	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Large cracks
Classroo	m #214 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	30	LF	4	2-5 years	vvator damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Cracks
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	Ordons
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	5	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,442	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
Classroo	m #300 (Regular Classroom)						
Olassiuc	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	,	
	Floor - Tile			SF		10+ years	
		3rd Floor 3rd Floor	730 14	SF EA	6 7	10+ years	
	Lighting - Pendent/Surface					6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,432	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	30	SF	5	0-1 year	Cracks and water damage

Campus Name: Clissold Page : 20 of 42 Assessment Date: 11/21/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	722	SF	6	10+ years	
	Floor - Tile	3rd Floor	8	SF	4	0-1 year	Cracks
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,175	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	18	SF	4	0-1 year	Water damage
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	8	LF	4	2-5 years	Ğ
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	720	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	· ·
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,442	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Cracks and damage
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	870	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3	SF	5	0-1 year	Water damage
	Chalk Board	3rd Floor	12	LF	4	2-5 years	3
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	798	SF	6	6-10 years	
	Floor - Tile	3rd Floor	75	SF	4	0-1 year	Cracked tiles
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,855	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Hole in wall
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	0-1 year	Cracks
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroc	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Floor - Tile	3rd Floor	30	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	3
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,442	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Cracks in wall
Classroc	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	5	0-1 year	Large areas of water damage
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	_a.go a.oao o. mato. aa.mago
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	730	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,211	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroc	m #306 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	730	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Clorage/ Closel	old I lool	U	SF	,	ioi years	



Catego	Category : Interior			uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,239	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	648	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,561	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Missing or damaged tiles
	Lighting - Pendent/Surface	1st Floor	26	EA	6	6-10 years	
	Student Lockers - One Tier	1st Floor	201	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,517	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,517	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,209	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	5	1-2 years	Cracked and peeling paint
	Drinking Fountains - Single Fountain	2nd Floor	5	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	648	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,561	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	30	SF	4	0-1 year	Cracked and missing tiles
	Lighting - Pendent/Surface	2nd Floor	25	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Does not work.
	Student Lockers - One Tier	2nd Floor	150	EA	6	10+ years	
	Student Lockers - Two Tiers	2nd Floor	50	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,377	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Damaged wall
	Walls - Structural Glazed Tile	2nd Floor	3,387	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,827	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	25	SF	5	0-1 year	Water damage
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	5	0-1 year	Out of order
	Floor - Terrazzo	3rd Floor	375	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,278	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	112	SF	4	0-1 year	Cracks
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	238	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,207	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Water damage
	Walls - Structural Glazed Tile	3rd Floor	2,217	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire building	3	EA	7	6-10 years	
	Security Cameras	Entire building	16	EA	7	6-10 years	
	Security Cameras	Entire building	6	EA	7	6-10 years	
O							
Stairs							

Campus Name: Clissold Page : 23 of 42 Assessment Date: 11/21/2023



Catego	ry : Interior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	East	547	SF	6	10+ years	
	Ceiling - Plaster/Drywall	East	4	SF	5	0-1 year	Damaged
	Floor - Terrazzo	East	442	SF	6	10+ years	
	Handrails	East	64	LF	7	10+ years	
	Lighting - Pendent/Surface	East	6	EA	7	6-10 years	
	Stairs - Terrazzo	East	135	LF	6	10+ years	
	Walls - Plaster/Drywall	East	982	SF	6	10+ years	
	Walls - Plaster/Drywall	East	10	SF	5	0-1 year	Damaged wall
	Walls - Structural Glazed Tile	East	982	SF	6	10+ years	
	Walls - Structural Glazed Tile	East	10	SF	5	1-2 years	Damaged
	Ceiling - Plaster/Drywall	North	823	SF	6	2-5 years	
	Floor - Terrazzo	North	660	SF	6	10+ years	
	Handrails	North	128	LF	7	10+ years	
	Lighting - Pendent/Surface	North	10	EA	7	6-10 years	
	Stairs - Terrazzo	North	270	LF	6	10+ years	
	Walls - Plaster/Drywall	North	1,470	SF	6	10+ years	
	Walls - Plaster/Drywall	North	10	SF	4	0-1 year	Large cracks
	Walls - Structural Glazed Tile	North	1,470	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	10	SF	5	0-1 year	Damaged
	Ceiling - Plaster/Drywall	South	823	SF	6	10+ years	
	Floor - Terrazzo	South	660	SF	6	10+ years	
	Handrails	South	128	LF	7	10+ years	
	Lighting - Pendent/Surface	South	10	EA	6	6-10 years	
	Stairs - Terrazzo	South	60	LF	6	10+ years	
	Walls - Plaster/Drywall	South	1,470	SF	6	10+ years	
	Walls - Plaster/Drywall	South	10	SF	5	1-2 years	Cracks
	Walls - Structural Glazed Tile	South	1,480	SF	6	10+ years	
Vertical 0	Conveyance						
	Elevator - Hydraulic Elevator	Floors 1 to 3	1	EA	7	10+ years	

Campus Name: Clissold Page : 24 of 42 Assessment Date: 11/21/2023



Category : Exterior Building : Annex

Category : Exterior Building : Annex							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance)						
	Entrance Control - Audio and Video	10-East	1	EA	7	6-10 years	
	Exterior Doors - Store Front	10-East	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	10-East	2	EA	7	10+ years	
	Power Door Operator and Controls	10-East	1	EA	7	6-10 years	
	Entrance Control - Audio and Video	11-West	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	11-West	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	11-West	2	EA	7	10+ years	
	Power Door Operator and Controls	11-West	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	11-West	52	LF	7	10+ years	
	Ramps - Concrete	11-West	42	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	12-East	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	13- RTU Enclosure	2	EA	7	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	448	LF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	9,910	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	448	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	64	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	412	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	36	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	9,910	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	9,910	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Metal	Entire Building	80	SF	7	10+ years	
	Cornice - Metal Projecting	Entire Building	448	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	6,380	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	870	SF	7	10+ years	
	Wall						
Windows		E B				4.0	
	Lintels - Steel	Entire Building	151	LF	7	10+ years	



Henry R Clissold Elementary School

XPN S	Schools						2350 W 110th PLACE, Chicago, IL 60643
Catego	ry : Exterior		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Windows - Casement Aluminum Double-	Entire Building	1,088	SF	7	10+ years	
	pane						
Catego	ry : Electrical		B	uilding	· Annex		
Oalcgo	ry . Electrical			unung	. Allica	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System					_	
9	Exit Signs - Corridors and Stairs	1st Floor	5	EA	7	10+ years	
	Security System - CCTV	1st Floor	9,910	SF	7	10+ years	
	Security System - Intrusion Detection	1st Floor	9,910	SF	7	10+ years	
	Emergency Battery Packs - Corridors and	1st Floor	7	EA	7		
	Stairs	ISt Floor	1	EA	,	10+ years	
	Emergency Battery Packs - Students Toilets	1st Floor	6	EA	7	10+ years	
	Emergency A/C Power - Corridors and	1st Floor	9,910	SF	7	10+ years	
	Stairs		2,2.2	-		, , , , , , , , , , , , , , , , , , , ,	
	Emergency A/C Power - Students Toilets	1st Floor	9,910	SF	7	10+ years	
Main Se	rvice						
	Main Electrical Service - 800 A and Less	1st Floor	1	EA	7	10+ years	
	than 277/480/3PH					•	
	PA System	1st Floor	9,910	SF	7	10+ years	PA system is fed into annex building
							through main building.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st Floor	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	1st Floor	1	EA	7	10+ years	
	amp						
Catego	ry : Fire Protection		В	uilding	: Annex		
				. 9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	Annunciator.
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	9,910	SF	7	10+ years	
	Fire Alarm_System	1st Floor	9,910	SF	7	10+ years	No separate category for annunciator
			5,510	J.	,	. o . youro	panel. Cannot create. Picture included.
	Fire Pump Controller	1st Floor	1	EA	7	10+ years	
Sprinkler	System						
•	•						



ALL S							2350 W 110th PLACE, Chicago, IL 6064
Category : Fire Protection			В	uilding	: Annex		
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sprinkler Heads	Mechanical Room	9,910	SF	7	10+ years	
	Sprinkler Piping	Mechanical Room	9,910	SF	7	10+ years	
	Wet Sprinkler System	Mechanical Room	9,910	SF	7	10+ years	
Categor	y : Mechanical		В	uildina	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condi	tioning		Ī				
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	Condenser is in MDF/Electrical Roo
Air Handl	ing Systems						
	Fan Power Box - Fan Power Box with Electric Coil	1st Floor	11	EA	7	10+ years	Units to ceiling underneath ceiling. Throughout building
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 46 - 60 tons	Roof	1	EA	7	10+ years	······································
Heating [Devices						
J	Cabinet Heaters - With Electric Coil	1st Floor	2	EA	7	10+ years	
	Unit Heater - Electric	Mechanical Room	1	EA	7	10+ years	
Tempera	ture Control						
·	DDC System	1st Floor	9,910	SF	7	10+ years	Run from the main building, via engineers office
	Electric Thermostat	1st Floor	13	EA	7	10+ years	engineere emee
√entilatio	n						
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	2	EA	7	10+ years	Janitors closet
	Exhaust Fans- Indoor - Less than 500 CFM	1st Floor	1	EA	7	10+ years	Electrical room
	Exhaust Fans- Indoor - Less than 500 CFM	1st Floor	1	EA	7	10+ years	Mechanical room
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st Floor	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st Floor	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	1st Floor	3	EA	7	10+ years	
Categor	y : Plumbing		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Hot Wate	-	Location	Qualitity	COIVI	IVALIA	Replacement	Comments
	Electric Heater - 20 - 50 KW	Mechanical Room	2	EA	7	10+ years	

Campus Name: Clissold Page : 27 of 42 Assessment Date: 11/21/2023



Catego	Category : Plumbing		В	uilding	: Annex		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping	B C B' H (W (B (I'	4 . 5					
	Domestic Piping-Hot Water Return Lines	1st Floor	9,910	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	1st Floor	9,910	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	1st Floor	9,910	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	1st Floor	9,910	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	1st Floor	9,910	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	1st Floor	9,910	SF	7	10+ years	
	Sanitary Piping	1st Floor	9,910	SF	7	10+ years	
	Storm Piping	1st Floor	9,910	SF	7	10+ years	
	Vent Piping	1st Floor	9,910	SF	7	10+ years	
			3,3.3	О.	-	.o. you.o	
Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor	195	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	195	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Power Distribution	1st Floor	8	EA	7	10+ years	
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	150	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	150	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	2	ĒΑ	7	6-10 years	
	Power Distribution	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years	
	Ceiling - Lay-in	Admin office 500	405	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Admin office 500	1	EA	7	10+ years	
	Floor - Tile	Admin office 500	405	SF	7	10+ years	
	Lighting - Lay-in	Admin office 500	5	EA	7	6-10 years	
	Power Distribution	Admin office 500	24	EA	7	10+ years	
	Walls - Plaster/Drywall	Admin office 500	950	SF	7	10+ years	
	valio i laston biy wall	Admin office ood	930	Oi.	,	ioi yeais	
Kitchen							
	Ceiling - Lay-in	1st Floor	280	SF	7	6-10 years	
						•	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	

Campus Name: Clissold Page : 28 of 42 Assessment Date: 11/21/2023



Category : Room			Building : Annex					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile Quarry	1st Floor	280	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	4	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	280	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	320	SF	7	10+ years		
Mechani	ical/ Service Rooms							
	Janitor's Closet	1st Floor	35	SF	7	6-10 years		
	Mechanical/ Service Rooms	1st Floor	150	SF	7	6-10 years		
	Mechanical/ Service Rooms	1st Floor	150	SF	7	6-10 years		
Restroor	m							
	Accessories	All Gender near Main Office	72	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	All Gender near Main Office	72	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	All Gender near Main Office	1	EΑ	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	All Gender near Main Office	72	SF	7	6-10 years		
	Floor Drain	All Gender near Main Office	1	EΑ	7	10+ years		
	Hand Dryer	All Gender near Main Office	1	EA	7	6-10 years		
	Lavatory	All Gender near Main Office	1	EA	7	6-10 years		
	Lighting - Lay-in	All Gender near Main Office	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	All Gender near Main Office	70	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	All Gender near Main Office	75	SF	7	10+ years		
	Water Closet	All Gender near Main Office	1	ĒΑ	7	6-10 years		
	Accessories	Inside 504	60	SF	7	6-10 years		
	Ceiling - Lay-in	Inside 504	60	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Inside 504	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Inside 504	60	SF	7	6-10 years		
	Floor Drain	Inside 504	1	EA	7	10+ years		
	Lavatory	Inside 504	1	EA	7	6-10 years		
	Lighting - Lay-in	Inside 504	2	EΑ	7	6-10 years		
	Walls - Plaster/Drywall	Inside 504	62	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Inside 504	67	SF	7	6-10 years		
	Water Closet	Inside 504	1	EA	7	6-10 years		
	Accessories	Inside 505	60	SF	7	6-10 years		
	Ceiling - Lay-in	Inside 505	60	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Inside 505 Inside 505	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Inside 505	60	SF	7	6-10 years		
		Inside 505 Inside 505		SF EA	4	0-10 years 0-1 year	Drain is covered	
	Floor Drain	Inside 505 Inside 505	1	EA EA	4 7		Drain is covered	
	Lavatory Lighting - Lay-in		2		7	6-10 years 6-10 years		
	Lignting - Lay-in Walls - Plaster/Drywall	Inside 505		EA SF				
		Inside 505	62		7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Inside 505	67	SF	7	10+ years		
	Water Closet	Inside 505	1	EA	7	6-10 years		
	Accessories	Inside 506	60	SF	7	6-10 years		
	Ceiling - Lay-in	Inside 506	60	SF	7	6-10 years		

Campus Name: Clissold Page : 29 of 42 Assessment Date: 11/21/2023



Catego	ry : Room		R	uildina	: Annex		2330 W TTOUT PLACE, Chicago, IL 60043
Catego	ry . Room			ananig	. Allica	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Inside 506	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Inside 506	60	SF	7	10+ years	
	Floor Drain	Inside 506	1	ĒΑ	7	10+ years	
	Lavatory	Inside 506	1	EΑ	7	6-10 years	
	Lighting - Lay-in	Inside 506	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside 506	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside 506	67	SF	7	10+ years	
	Water Closet	Inside 506	1	ĒΑ	7	6-10 years	
	Accessories	Inside 507	60	SF	7	6-10 years	
	Ceiling - Lay-in	Inside 507	60	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Inside 507	1	ĒΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Inside 507	60	SF	7	6-10 years	
	Floor Drain	Inside 507	1	ĒΑ	7	10+ years	
	Lavatory	Inside 507	1	EA	7	6-10 years	
	Lighting - Lay-in	Inside 507	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Inside 507	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside 507	67	SF	7	10+ years	
	Water Closet	Inside 507	1	EA	7	6-10 years	
	Accessories	Inside 508	60	SF	7	6-10 years	
	Ceiling - Lay-in	Inside 508	60	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Inside 508	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Inside 508	60	SF	7	6-10 years	
	Floor Drain	Inside 508	1	EA	7	10+ years	
	Lavatory	Inside 508	1	EΑ	7	6-10 years	
	Lighting - Lay-in	Inside 508	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Inside 508	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside 508	67	SF	7	10+ years	
	Water Closet	Inside 508	1	EA	7	6-10 years	
	Accessories	Inside 509	60	SF	7	6-10 years	
	Ceiling - Lay-in	Inside 509	60	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Inside 509	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Inside 509	60	SF	7	6-10 years	
	Floor Drain	Inside 509	1	EA	7	10+ years	
	Lavatory	Inside 509	1	EA	7	6-10 years	
	Lighting - Lay-in	Inside 509	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Inside 509	62	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside 509	67	SF	7	10+ years	
	Water Closet	Inside 509	1	EA	7	6-10 years	
_						•	
Catego	ry : Classroom		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	om #504 (Pre School)	Location	Quantity	COIVI	Italik	Replacement	Comments
JIBSSI00	Casework	1st Floor	18	LF	7	6-10 years	
	Casework	1301 1001	10	LI	'	o To years	

Campus Name: Clissold Page : 30 of 42 Assessment Date: 11/21/2023



Catego	Category : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	850	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #505 (Office)						
	Casework	1st Floor	12	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	850	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #506 (Pre School)						
	Casework	1st Floor	12	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	850	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #507 (Pre School)						
	Casework	1st Floor	12	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	850	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classro	om #508 (Pre School)					•	
_Classiot	JIII #300 (FTE SCHOOL)						

Campus Name: Clissold Page : 31 of 42 Assessment Date: 11/21/2023



Category : Classroom			В	Building : Annex				
	•					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	1st Floor	12	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years		
	Floor - Tile	1st Floor	850	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years		
	Marker Board	1st Floor	7	LF	7	6-10 years		
	Storage/ Closet	1st Floor	75	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	990	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	6-10 years		
Classro	om #509 (Pre School)							
Olabbio	Casework	1st Floor	12	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	850	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	6-10 years		
	Floor - Tile	1st Floor	850	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years		
	Marker Board	1st Floor	7	LF	7	6-10 years		
			75	SF	7	6-10 years		
	Storage/ Closet	1st Floor	75	ЭF	1	0-10 years		
	Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor	990	SF SF	7	10+ years		

Category : Interior **Building: Annex**

Group	Itom Type	Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOIVI	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Lay-in	1st Floor	1,050	SF	7	6-10 years	
	Doors - Store Front	1st Floor	4	EA	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,750	SF	7	10+ years	
	Ceiling - Lay-in	North vestibule	50	SF	7	6-10 years	
	Doors - Steel Doors incl hw	North vestibule	2	EA	7	10+ years	
	Doors - Transom Window	North vestibule	10	SF	7	10+ years	
	Floor - Tile/Sheet	North vestibule	50	SF	7	6-10 years	
	Lighting - Lay-in	North vestibule	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	North vestibule	100	SF	7	10+ years	
	Ceiling - Lay-in	South Vestibule	100	SF	7	6-10 years	
	Doors - Store Front	South Vestibule	2	EA	7	10+ years	
	Doors - Transom Window	South Vestibule	10	SF	7	10+ years	
	Floor - Tile/Sheet	South Vestibule	100	SF	7	10+ years	
	Lighting - Lay-in	South Vestibule	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	South Vestibule	200	SF	7	10+ years	

Campus Name: Clissold Page : 32 of 42 Assessment Date: 11/21/2023



Catego	ry : Interior	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Safety							
,	Camera Viewing Station	1st Floor	1	EA	7	10+ years	Camera viewing Software not
	Security Cameras	1st Floor	17	EA	7	10+ years	installed yet

Campus Name: Clissold Page : 33 of 42 Assessment Date: 11/21/2023



Category: Exterior Building: Modular 1 (4-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Rank Group Entrance Entrance Control - Audio and Video #8- South FΑ 6 1 6-10 years Exterior Doors - Exterior FRP Door #8- South 2 FΑ 7 10+ years Changed to match current observations. New doors Power Door Operator and Controls #8- South 1 EΑ 6-10 years Added to match current observations Entrance Control - Audio and Video #9 - North 1 EΑ 6 6-10 years Exterior Doors - Exterior FRP Door 2 7 #9 - North EΑ 10+ years New doors Power Door Operator and Controls #9 - North 1 EΑ 6-10 years Added to match current observations Foundation Foundation - Masonry LF 7 **Entire Building** 258 10+ years Superstructure - Steel 4,188 SF 7 10+ years **Entire Building** Liahtina Exterior Lighting - Wall Mounted **Entire Building** 8 EΑ 7 6-10 years New Roof System LF Downspouts - Exterior Downspouts Main Roof 40 7 6-10 years New Roof - EPDM/ Synthetic Rubber Main Roof SF 7 10+ years 4.188 Replaced SF 7 Roof Structure - Steel / Metal Deck/ Main Roof 4.188 10+ years **Concrete Topping** Walls Canopy - Metal Entire Building 100 SF 7 10+ years New SF Exterior Walls - Brick **Entire Building** 2.440 7 10+ years Newly replaced Exterior Walls - Stucco **Entire Building** 120 SF 0-1 year Gaps Windows SF Guard - Guards perforated **Entire Building** 256 7 10+ years New Windows - Sash Aluminum Double-pane **Entire Building** 256 SF 7 10+ years New Building: Modular 1 (4-Classroom) Category: Electrical Recommend Location **UOM** Rank Replacement Comments Item - Type Quantity Emergency System Emergency A/C Power - Corridors and 1st Floor SF 1 6 6-10 years Stairs Exit Signs - Corridors and Stairs **Entire Building** 5 EΑ 6 6-10 years Exit Signs - Corridors and Stairs **Entire Building** 1 EΑ 6 6-10 years In good condition. Emergency Battery Packs - Corridors and **Entire Building** 2 EΑ 6 6-10 years Stairs

Campus Name: Clissold Page : 34 of 42 Assessment Date: 11/21/2023



Catego	ry : Electrical		Building : Modular 1 (4-Classroom)						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years			
Main Se	rvice								
	PA System	Entire Building	4,188	SF	5	6-10 years			
	Main Electrical Service - 800 A and Less than 120/208/3PH	Exterior wall	1	EA	6	10+ years			
Power D	istribution								
	Lighting and Power Panels - 100 A	1st Floor	1	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	7	10+ years			
	Main Distribution Panels - Greater than 600 amp	1st Floor	1	EA	7	10+ years			
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	oom)		
						Recommend	,		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar									
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Annunciator.		
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years			
	Fire Alarm Strobe Lights	Entire Building	4,188	SF	6	6-10 years			
	Fire Alarm_System	Entire Building	4,188	SF	6	6-10 years			
Sprinkle	r System								
	Sprinkler Heads	Entire Building	4,188	SF	7	10+ years			
	Sprinkler Piping	Entire Building	4,188	SF	6	10+ years			
	Wet Sprinkler System	Entire Building	4,188	SF	6	10+ years			
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	oom)		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Tempera	ature Control								
	Electric Thermostat	Entire Building	4	EA	5	6-10 years			
Unit Ven	itilation								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	exterior wallls	4	EA	7	10+ years			
Ventilation									
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	6	EA	5	6-10 years			

Campus Name: Clissold Page : 35 of 42 Assessment Date: 11/21/2023



Catcge	ory : Plumbing	Building : Modular 1 (4-Classroom)					
	,					Recommend	· •
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er					•	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	6-10 years	
						- · · · · · · · · · · · · · · · · · · ·	
Piping							
. 5	Domestic Piping-Hot Water Return Lines	1st Floor	4,188	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	1st Floor	4,188	SF	6	10+ years	
	(Horizontal Lines)					-	
	Sanitary Piping	1st Floor	4,188	SF	6	10+ years	
	Storm Piping	1st Floor	4,188	SF	6	10+ years	
	Vent Piping	1st Floor	4,188	SF	6	10+ years	
C-1	and Classica and		ь	به ما الدان	. Madul	law 4 /4 Classes	
Catego	ory : Classroom		D	ullaing	· Wodu	ar 1 (4-Classro Recommend	om)
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #401 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	10+ years	
	Floor - Tile	1st Floor	650	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	44	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	731	SF	6	10+ years	
Classro	om #402 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	650	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	44	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	736	SF	6	10+ years	
Classro	om #403 (Regular Classroom)						
CIGSSIU	Ceiling - Lay-in	1st Floor	650	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	650	SF	6	10+ years 10+ years	
		1st Floor	12	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor		LF			
	Marker Board		20		7	6-10 years	
	Marker Board		4.4	C.L	7		
	Storage/ Closet	1st Floor	44	SF	7	10+ years	
			44 736	SF SF	7 6	10+ years 10+ years	
Classro	Storage/ Closet	1st Floor					

Campus Name: Clissold Page : 36 of 42 Assessment Date: 11/21/2023



NY N	Schools						2350 W 110th PLACE, Chicago, IL 60643
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	oom)
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	650	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	44	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	786	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	pom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ical/ Service Rooms	2004	Quantity	00	rtannt	rtopiacomont	
_wechan		4 - t - Flan	F2			10	
	Mechanical/ Service Rooms	1st Floor	53	SF	5	10+ years	
_Restroo	m						
	Accessories	1st Floor	181	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	181	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	181	SF	7	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	_ 1	EA	6	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	374	SF	6	10+ years	
	Water Closet	1st Floor	4	ĒΑ	6	10+ years	
	Accessories	1st Floor	136	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	136	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	136	SF	5	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	_ 1	EA	6	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Urinals	1st Floor	3	EA	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	304	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
Cataca	m Intoviou		.	ده دالمالي	. Mad.:)
Catego	ry : Interior		В	uiiaing	: woaui	ar 1 (4-Classro Recommend	om j
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor	547	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	547	SF	7	10+ years	
						·	



Building : Modular 1 (4-Classroom) Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,217	SF	6	10+ years	

Campus Name: Clissold Page : 38 of 42 Assessment Date: 11/21/2023



Category : Site Building : Site

Fencing - Chain Link	Jaicgo	iy. Oile			unung	. Oile	Decemmend	
Diditional District Distric	- Proup	Itom Type	Location	Quantity	ПОМ	Donk		Comments
Civil/ Drainage - Catch Basin Entire Site 1			Location	Quantity	UOIVI	Kalik	Replacement	Comments
Civil/ Drainage - Catch Basin	Jivil/Dra							
Civil Drainage - Catch Basin Entire Site 1 EA 7 10+ years Replaced								Replaced
Civil/ Drainage - Site Manhole Entire Site 1 EA 7 10+ years Replaced Entire Site 11 EA 7 10+ years Replaced Fencing - Chain Link Fencing - Chain Link Entire Site 1.077 LF 6 6-10 years Fencing - New Standard Ornamental Entire Site 1.077 LF 6 6-10 years Fencing - Wood Fencing w/ Steel Frame Entire Site 1.077 LF 6 6-10 years Fencing - Wood Fencing w/ Steel Frame Entire Site 1.077 LF 6 6-10 years Fencing - Wood Fencing w/ Steel Frame Entire Site 1.077 LF 4 0-1 year Missing Landscape Benches Entire Site 5 EA 6 6-10 years Image of the Site 10 LF 4 0-1 year Missing Landscape - Benches Entire Site 5.2618 SF 6 10+ years Landscape - Hardscape - Asphalt Entire Site 70,779 SF 6 10+ years Landscape - Hardscape - Asphalt Entire Site 9,094 SF 7 10+ years New Landscape - Hardscape - Concrete Entire Site 9,094 SF 7 10+ years New Landscape - Hardscape - Concrete Entire Site 2,291 SF 6 10+ years Landscape - Hardscape - Concrete Entire Site 2,291 SF 6 10+ years Newly added Landscape - Hardscape - Concrete Entire Site 2,291 SF 6 10+ years Newly added Parkwy trees Entire Site 2,341 SF 6 10+ years Newly added Parkwy trees Entire Site 2,342 SF 6 10+ years Newly Added Parkwy trees Entire Site 3,43 EA 6 10+ years Retaining Beds/ Area Entire Site 2,507 SF 6 6-10 years Planting Beds/ Area Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 2,507 SF 6 6-10 years Newly Added National Site 497 LF 7 10+ years Newly Surface - Concrete NE Site 899 SF 7 10+ years New Newly Surface - Concrete NE Site 899 SF 7 10+ years New New Newly Surface - Concrete NE Site 662 SF 7 10+ years New New Newly Surface - Concrete NE Site 662 SF 7 10+ years New New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ years New Newly Surface - Concrete NE Site 662 SF 7 10+ ye				=				
Entire Site 11				4			•	
Fencing				1				Replaced
Fencing - Chain Link		Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
Fencing - Chain Link	Fencing							
Fencing - New Standard Ornamental Entire Site 1.077 LF 6 6-10 years Fencing - Wood Fencing w Steel Frame Entire Site 288 LF 6 2-5 years Fencing - Wood Fencing w Steel Frame Entire Site 288 LF 6 2-5 years Fencing - Wood Fencing w Steel Frame Entire Site 10 LF 4 0-1 year Missing		Fencing - Chain Link	Entire Site	14	LF	4	0-1 year	Rusted/missing pieces
Fencing - Wood Fencing w/ Steel Frame Entire Site 258								3,
Pencing - Wood Fencing w/ Steel Frame								
Benches								Missing
Benches	l andsca	ne						
Irrigation			Entire Site	5	FA	6	6-10 years	
Landscape - Grass								
Landscape - Hardscape- Asphalt Entire Site 9,094 SF 7 0-1 year New Landscape - Hardscape- Asphalt Entire Site 9,094 SF 7 10+ years New Landscape - Hardscape- Concrete Entire Site 2,760 SF 7 10+ years New Newly added Landscape - Hardscape- Concrete Entire Site 2,291 SF 6 10+ years Landscape - Hardscape- Concrete Entire Site 2,291 SF 6 10+ years Landscape - Hardscape- Concrete Entire Site 135 SF 4 0-1 year Cracking Parkway trees Entire Site 43 EA 6 10+ years Planting Beds/ Area Entire Site 23,421 SF 6 6-10 years Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Walking Path - Crushed Stone Entire Site 6 EA 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 497 LF 7 10+ years New Interior Plantings NE site 480 LF 7 10+ years New Interior Plantings NE site 480 LF 7 10+ years New Parking Lot Surface - Asphalt NE site 16,500 SF 7 10+ years New Surface - Concrete NE site 899 SF 7 10+ years New Trash Enclosure - Chain Links NE site 566 SF 7 10+ years New New Playground 1 EA 7 10+ years New Playground 1 EA 7 10+ years New New Playground 1 EA 7 10+ years New New New Playground 1 EA 7 10+ years New								
Landscape - Hardscape - Asphalt								Poplaced
Landscape - Hardscape- Concrete Entire Site 2,760 SF 7 10+ years Newly added Landscape - Hardscape- Concrete Entire Site 2,291 SF 6 10+ years Cracking Parkway trees Entire Site 135 SF 4 0-1 year Cracking Parkway trees Entire Site 43 EA 6 10+ years Planting Beds/ Area Entire Site 23,421 SF 6 6-10 years Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Walking Path - Crushed Stone Entire Site 6 EA 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 7 10+ years New Surface - Asphalt NE site 497 LF 7 10+ years New Parking Lot 16,500 SF 7 10+ years New Parking Lot NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New NE site 566 SF 7 10+ years New New New New New SE ST 56001 Age 5-12 NW - playground 1 EA 7 10+ years New							•	•
Landscape - Hardscape- Concrete Entire Site 2,291 SF 6 10+ years Landscape - Hardscape - Concrete Entire Site 135 SF 4 0-1 year Cracking Parkway trees Entire Site 43 EA 6 10+ years Planting Beds/ Area Entire Site 23,421 SF 6 6-10 years Planting Beds/ Area Entire Site 23,421 SF 6 6-10 years Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Parking Lot Teach Retaining S NE site 497 LF 7 10+ years New Interior Plantings NE site 480 LF 7 10+ years Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 566 SF 7 10+ years New Trash Enclosure - Chain Links NE site 566 SF 7 10+ years New								
Landscape - Hardscape- Concrete Entire Site 135 SF 4 0-1 year Cracking Parkway trees Entire Site 43 EA 6 10+ years Planting Beds/ Area Entire Site 23,421 SF 6 6-10 years Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Walking Path - Crushed Stone Entire Site 6 EA 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Parking Lot Concrete Curbs NE site 497 LF 7 10+ years Interior Plantings NE site 480 LF 7 10+ years Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New New Playground 1 EA 7 10+ years New						-		newly added
Parkway trees				•		_		0 1:
Planting Beds/ Area								Cracking
Play Area - Hardscape- Asphalt Entire Site 2,507 SF 6 6-10 years Retaining Wall - Concrete Entire Site 582 SF 5 10+ years Trash Receptacles Entire Site 6 EA 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Concrete Curbs NE site 497 LF 7 10+ years New Interior Plantings NE site 480 LF 7 10+ years Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground 1 EA 7 10+ years New Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New								
Retaining Wall - Concrete						-		
Trash Receptacles Entire Site 6 EA 6 6-10 years Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years Parking Lot Concrete Curbs NE site 497 LF 7 10+ years New Interior Plantings NE site 480 LF 7 10+ years New Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New		Play Area - Hardscape- Asphalt		2,507		6		
Walking Path - Crushed Stone Entire Site 7,821 SF 6 6-10 years		Retaining Wall - Concrete		582				
Parking Lot		Trash Receptacles	Entire Site	6	EA	6	6-10 years	
Concrete Curbs		Walking Path - Crushed Stone	Entire Site	7,821	SF	6	6-10 years	
Interior Plantings Surface - Asphalt Surface - Asphalt Surface - Concrete Surface - Concrete NE site N	Parking I	Lot						
Interior Plantings NE site 480 LF 7 10+ years Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New. Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New	J	Concrete Curbs	NE site	497	LF	7	10+ years	New
Surface - Asphalt NE site 16,500 SF 7 10+ years New parking lot. Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New. Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New		Interior Plantings	NE site	480	LF	7		
Surface - Concrete NE site 899 SF 7 10+ years New Surface - Concrete NE site 566 SF 7 10+ years New. Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New New NE site 662 SF 7 10+ years New New Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New							•	New parking lot.
Surface - Concrete NE site 566 SF 7 10+ years New Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New								. •
Trash Enclosure - Chain Links NE site 662 SF 7 10+ years New Playground Equipment - Pre K 3-5 Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New 1 EA 7 10+ years New								
Playground Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New							•	
Equipment - Pre K 3-5 NW - playground 1 EA 7 10+ years New Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New		Trasti Etiologuie - Ottalii Elitiks	INE SILO	002	Oi.	,	TOT years	INOW
Equipment - School Age 5-12 NW - playground 1 EA 7 10+ years New	Playgrou							
				1			10+ years	
		Equipment - School Age 5-12	NW - playground	1		7	10+ years	New
Surface - Poured Surface NW - playground 5,386 SF 7 10+ years New		Surface - Poured Surface	NW - playground	5,386	SF	7	10+ years	New
			. , ,	,			•	



Catego	Category : Site				Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	190	LF	7	10+ years	Quantity changed to match current observations
	Sidewalks - Internal Walks	Entire Site	703	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	5	LF	4	0-1 year	Cracking/sinking
	Sidewalks - Perimeter Sidewalks	Entire Site	9,896	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10	SF	4	0-1 year	Cracking/sinking
Signage							
	Flag Pole - Flag Pole	West	2	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	West	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	West	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	West	2	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Clissold Page: 40 of 42 Assessment Date: 11/21/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary			Daam	Floor Plan	Auga	Glazed	Operable	Min daw	Company
0	laterade di Henne	Daniel andian	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		1	101	101	700	100			
Kindergarten	Kindergarten	1st Floor	104	104	720	120	45	N	N
Office	Library	2nd Floor	205		700	200	16		ļ
Office	Regular Classroom	1st Floor	105	105	730	200	60	N	N
Office	Regular Classroom	2nd Floor	214	214	730	120	45	N	N
Other Instructional Use	Regular Classroom	2nd Floor	208	208	730	120	45	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	730	200	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	730	120	45	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	730	200	60	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	730	120	45	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	730	200	60	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	730	120	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	730	120	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	120	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	730	200	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	730	120	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	730	120	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	730	200	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	730	120	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	730	120	45	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	730	200	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	730	120	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	873	240	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	730	120	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	730	200	60	N	N
Special Education	Regular Classroom	3rd Floor	306	306	730	120	45	N	N
Duilding Annov									
Building : Annex Office	Pre School	4 a 4 \(\tau \)	505		050	100	00	1	
		1st Floor	505		850	160	60		
Pre School	Pre School	1st Floor	504		850	160	60		<u> </u>
Pre School	Pre School	1st Floor	506		850	160	60	-	
Pre School	Pre School	1st Floor	507		850	160	60		<u> </u>
Pre School	Pre School	1st Floor	508		850	160	60		
Pre School	Pre School	1st Floor	509		850	160	60		
Building : Modular 1 (4-Cla	assroom)								
Regular Classroom	Regular Classroom	1st Floor	401	NA	650	64	32	N	N
Regular Classroom	Regular Classroom	1st Floor	402	NA	650	64	32	N	N
Regular Classroom	Regular Classroom	1st Floor	403	NA	650	64	32	N	N



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	1st Floor	404	NA	650	64	32	N	Y