8324 S Racine AVENUE, Chicago, IL 60620

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2003	3	82,120
Campus Total			82,120

Category: Exterior **Building: Main** Recommend Replacement Comments Item - Type Location Quantity **UOM** Rank Group Entrance Exterior Doors - Store Front #1 E 3 EΑ 7 10+ years Exterior Doors - Transom Lite #1 E 2 EΑ 7 10+ years Entrance Control - Audio #10 S FΑ 6 6-10 years 1 2 FΑ 5 Exterior Doors - Exterior Steel Door #10 S 2-5 years Entrance Control - Audio and Video #2 E - Main 1 EΑ 6 6-10 years Exterior Doors - Side lite #2 E - Main 2 EΑ 7 10+ years Exterior Doors - Store Front #2 E - Main 4 EΑ 7 10+ years Exterior Doors - Transom Lite #2 E - Main 4 EΑ 7 10+ years Power Door Operator and Controls #2 E - Main 1 EΑ 7 10+ years Exterior Doors - Store Front #3 E 3 FΑ 7 10+ years Exterior Doors - Transom Lite 2 EΑ 7 #3 E 10+ years Exterior Doors - Exterior Steel Door #4 N 4 FΑ 6 6-10 years Entrance Control - Audio and Video #5 N FΑ 7 1 10+ years Exterior Doors - Exterior Steel Door #5 N 1 FΑ 6 10+ years Exterior Doors - Exterior Steel Door #6 W 3 EΑ 6 6-10 years Exterior Doors - Exterior Steel Door 2 EΑ #7 W 6 10+ years Exterior Doors - Exterior Steel Door #8 W 1 EΑ 6 6-10 years Exterior Doors - Exterior Steel Door #9 W 2 EΑ 6 6-10 years Foundation LF Foundation - Concrete **Entire Building** 1,095 7 10+ years **Entire Building** SF 7 Superstructure - Metal Deck/ Concrete 82.000 10+ years Topping



Categor	ategory : Exterior		В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ghting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	19	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	6-10 years			
oof Sys	tem								
-	Coping - Metal	East Low Roof	235	LF	6	6-10 years			
	Downspouts - Interior Downspouts	East Low Roof	120	LF	6	6-10 years			
	Parapet - 16" - 30" Height	East Low Roof	235	LF	6	10+ years			
	Roof - Modified Bitumen	East Low Roof	3,848	SF	4	1-2 years	Bubble, cracking, growth		
	Roof Structure - Steel / Metal Deck/	East Low Roof	3,848	SF	7	10+ years			
	Concrete Topping					•			
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years			
	Coping - Metal	Main Roof	668	LF	6	6-10 years			
	Downspouts - Interior Downspouts	Main Roof	380	LF	6	6-10 years			
	Parapet - 16" - 30" Height	Main Roof	668	LF	6	10+ years			
	Roof - Modified Bitumen	Main Roof	19,319	SF	5	2-5 years			
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Main Roof	19,319	SF	7	10+ years			
	Concrete Topping		,			,			
	Chimney - Metal Flue	North Low Roof	26	LF	6	6-10 years			
	Coping - Metal	North Low Roof	276	LF	6	6-10 years			
	Downspouts - Interior Downspouts	North Low Roof	175	LF	6	6-10 years			
	Parapet - 16" - 30" Height	North Low Roof	175	LF	6	10+ years			
	Roof - Modified Bitumen	North Low Roof	6,938	SF	5	2-5 years			
	Roof - Modified Bitumen	North Low Roof	20	SF	4	0-1 year	Growth, soft spots		
	Roof Structure - Steel / Metal Deck/	North Low Roof	6,958	SF	7	10+ years	, ,		
	Concrete Topping	Courth Law Doof	074	LF	•	C 40			
	Coping - Metal	South Low Roof	274		6	6-10 years			
	Downspouts - Interior Downspouts	South Low Roof	172	LF	6	6-10 years			
	Parapet - 16" - 30" Height	South Low Roof	274	LF CF	6	10+ years			
	Roof - Modified Bitumen	South Low Roof	6,943	SF	5	2-5 years			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	South Low Roof	6,943	SF	7	10+ years			
alls									
	Canopy - Metal	Entire Building	325	SF	6	10+ years			
	Canopy - Metal	Entire Building	40	SF	5	2-5 years	Corroded		
	Exterior Walls - Brick	Entire Building	32,850	SF	6	10+ years			
	Exterior Walls - Precast Panel Wall	Entire Building	440	SF	6	10+ years			
	Exterior Walls - Stone-Cast	Entire Building	585	SF	6	10+ years			
indows									
	Curtain wall - Louver	Entire Building	520	SF	7	10+ years			



Catego	ry : Exterior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM SF	Rank	Replacement	Comments
	Guard - Guards perforated	Entire Building	2,450		6	6-10 years	
	Lintels - Steel	Entire Building	1,245	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,755	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	icy System		·			•	
J	Emergency A/C Power - Corridors and Stairs	Entire Building	17,940	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	862	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	3,307	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	2,236	SF	6	10+ years	
	Security System - CCTV	Entire Building	82,120	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	82,120	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	5	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	12	EΑ	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	Rank, Reason and Priority Rep changed as all exit signs throughout the building have been upgraded and are legible as intended.
	Exit Signs - Lunchroom	Entire Building	5	EA	6	6-10 years	Quantity changed to match current observations.
	Exit Signs - Multipurpose Room	Entire Building	3	EΑ	6	6-10 years	
	Automatic Transfer Switch	Pump Room	1	EA	6	10+ years	Fire pump controller is an ATS serving the fire pump and sprinkler system.
Main Ser	vice						
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	82,120	SF	6	6-10 years	
	Independent Electrical Service for emergency power	Pump Room	1	ĒA	6	10+ years	Location changed for clarification. Fire pump controller is an ATS serving the fire pump and sprinkler system on a second, separate meter/feed.

Campus Name: Cuffe Page : 3 of 32 Assessment Date: 03/18/2024



Catego	ry : Electrical		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	Quantity changed to match current observations as one panel was misidentified in previous assessment. Location changed for clarification.
	Lighting and Power Panels - Above 100 A	Entire Building	22	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as an interior cover is misaligned which exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as an interior cover is misaligned which exposes live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	7	10+ years	Location changed for clarification. Quantity changed to match current observations and as the total has been divided/aggregated.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	Misidentified in previous assessment.
	Transformers - 277/480 - 120/208	Entire Building	3	EA	7	10+ years	Quantity changed to match current observations and as total has been divided/aggregated.
	Transformers - 277/480 - 120/240	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
			<b></b>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present. System is functional and passes annual inspection but Rank, Reason and Priority Rep changed to reflect that it is 20-plus years old, employs antiquated technology, and has reached the end of its anticipated garrier life.
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	service life. Panel is functional and passes annua inspection but Rank, Reason and



Catego	ry : Fire Protection		B	uilding	: Main	-	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	82,120	SF	6	6-10 years	Priority Rep changed to reflect that it is 20-plus years old, employs antiquated technology, and has reached the end of its anticipated service life.  Strobe lights are functional and located as appropriate. The fire alarm system itself is operational and passes annual inspection but Rank, Reason and Priority Rep changed to
	Fire Alarm_System	Entire Building	82,120	SF	6	6-10 years	reflect that the system is 20-plus years old, employs antiquated technology, and has reached the end of its anticipated service life. System is functional and passes annual inspection but Rank, Reason and Priority Rep changed to reflect that it is 20-plus years old, employs antiquated technology, and has reached the end of its anticipated service life.
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	Service life.
Pump R	oom Assembly						
•	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	No CPS Asset Tag present.
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	No CPS Asset Tag present.
Sprinkle	System						
	Sprinkler Heads	Entire Building	82,120	SF	7	10+ years	
	Sprinkler Piping	Entire Building	82,120	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	82,120	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
0	Ham Time	Laastian	Overetite	HOM	Donk	Recommend	Community
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	Chemical Pot Feeder	Roof	1	EA		10	
	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons	Roof	1	EA	6 7	10+ years 10+ years	Rank, Reason and Priority Rep changed as the chiller has been replaced since previous assessment. No CPS Asset Tag present.
	Glycol Feed	Roof	1	EA	6	6-10 years	Si Si Ci lossi rag protonii
	Pipes - Chilled Water Pipe- Galvanized	Roof	800	LF	6	10+ years	
	ripes - Crillied water Pipe- Galvanized	KUUI	800	LF	ь	ru+ years	



atego	ry : Mechanical		В	uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Pressure Fill System Condensing Unit- Roof Mounted - Less than 5 tons	Roof Roof	1	EA EA	6 4	10+ years 2-5 years	Component of a ductless split systes serving MDF Room 205. Unit is functional but is 20-plus years old with visible signs of deterioration at it has reached the end of its anticipated service life. Dataplate accessible. CPS Asset Tag not ab to be scanned.	
<u>r Hand</u>	lling Systems							
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	48	EA	6	6-10 years		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-2, serves 2nd and 3rd floors.	
	Air Intake	Mechanical Room	1	EA	6	10+ years	Location changed for clarification.	
	VAV Box	Mechanical Room	5	EA	6	6-10 years	Location changed for clarification.	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-1, serves 1st floor.	
	Air Intake	Mechanical Room	1	EA	6	10+ years	Location changed for clarification.	
	VAV Box	Mechanical Room	8	EA	6	6-10 years	· ·	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-4, serves Multipurpose Room	
	Air Intake	Mechanical Room	1	EA	6	6-10 years		
	VAV Box	Mechanical Room	3	EA	6	6-10 years		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-3, serves kitchen, lunchroom and associated spaces.	
	Air Intake	Mechanical Room	1	EA	6	6-10 years		
	VAV Box	Mechanical Room	4	EA	6	10+ years		
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-1	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-4	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-3	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-2	
iler Sv	vstems							
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	5	6-10 years	Location changed for clarification.	

Campus Name: Cuffe Page : 6 of 32 Assessment Date: 03/18/2024



Category : Mechanical  Building : Main  Recommend  Group Item - Type  - 2001 - 3000 MBH  Building : Main  Recomment  Quantity UOM Rank Replacement Comments  Located on 2nd flo	
2001 2000 MPH	
	or north.
Chemical Pot Feeder Mechanical Room 1 EA 6 6-10 years Location changed	for clarification.
Located on 2nd flo	or north.
Combustion Dampers Mechanical Room 2 EA 6 10+ years Location changed	
Located on 2nd flo	
mounted above Al-	
Glycol Feed System Mechanical Room 1 EA 5 6-10 years Location changed	
Located on 2nd flo	or north. Manual
system.	
Non Condensing- Water Tube- Flexible Mechanical Room 1 EA 5 6-10 years B-1. Location cha	
Tube- Force Draft- Hot Water Boiler - 2001 clarification. Location and the second seco	ted on 2nd floor
- 3000 MBH	
Non Condensing- Water Tube- Flexible Mechanical Room 1 EA 5 6-10 years B-2. Location cha	
Tube- Force Draft- Hot Water Boiler - 2001 clarification. Locat	ted on 2nd floor
- 3000 MBH  North.  Water Fill System  Mechanical Room  1 FA 6 10+ years   Location changed	for alarification
Water Fill System Mechanical Room 1 EA 6 10+ years Location changed Located on 2nd flo	
Located on 2nd no	or norm.
Heating Devices	
Unit Heater - Electric Electrical Room 1 EA 6 10+ years	
Cabinet Heaters - With Hot Water Coil Entire Building 7 EA 6 10+ years	
Unit Heater - Hot Water Entire Building 1 EA 6 10+ years	
Unit Heater - Hot Water Entire Building 1 EA 6 10+ years Located on 2nd flo	or south.
Unit Heater - Hot Water Entire Building 1 EA 6 10+ years	
Unit Heater - Hot Water Entire Building 1 EA 6 10+ years Located on 2nd flo	or north. Quantity
changed to match	current
observations and a	
been divided/aggre	
Radiator Panels - Hot Water Entire Building 14 EA 6 10+ years Ceiling mounted in	
restrooms, offices	
	Quantity changed
to match current of	bservations.
Machanical Dlumbing	
Mechanical Plumbing Hydronic Supply and Return - Steel Entire Building 800 LF 6 10+ years	
Hot Water Pump - 10 - 20 HP Mechanical Room 1 EA 6 6-10 years Serves boilers. No	CPS Asset Tag
present.	O O O Asset Tay
Hot Water Pump - 10 - 20 HP Mechanical Room 1 EA 6 6-10 years Serves boilers. No	CPS Asset Tag
present.	or or tooot rag
Hot Water Pump - Less than 10 Mechanical Room 1 EA 6 6-10 years Associated with Al	-IU-3.
Hot Water Pump - Less than 10 Mechanical Room 1 EA 6 6-10 years Associated with Al	
Asset Tag present	
Hot Water Pump - Less than 10 Mechanical Room 1 EA 6 6-10 years Associated with Al	
Hot Water Pump - Less than 10 Mechanical Room 1 EA 6 6-10 years Associated with Al	
·	

Campus Name: Cuffe Page: 7 of 32 Assessment Date: 03/18/2024



Catego	ry : Mechanical		В	uilding	: Main		3324 S Racine AVENUE, Chicago, IL 60620
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chilled Water Pump - 10 - 20 HP Chilled Water Pump - 10 - 20 HP	Mechanical Room Mechanical Room	1	EA EA	6 6	10+ years 10+ years	Asset Tag present. No CPS Asset Tag present. No CPS Asset Tag present.
Tempera	ature Control						
	DDC System	Entire Building	82,120	SF	4	2-5 years	The software is outdated.  Communication between temperature sensors and the system is generally questionable and communication between the system and the equipment is unreliable.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Located on 2nd floor south.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations and as the total has been divided/aggregated. Priority Rep adjusted based on current observations and on the age of the equipment. Location changed for clarification.
	Thermostats - DDC	Entire Building	68	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Thermostats are operational but the system itself uses outdated software and communication is unreliable.
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Item Type changed to match current observations. One each located in the north and south mechanical rooms.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification. Not directly accessible at the time of assessment due to lack of climbing means; the standard means of access to the north lower roof is nonfunctional. Unable to view dataplate; unit is operational without undue noise such as from imbalance or vibration.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	One unit has a missing dataplate; units are 2850 cfm restroom exhaust fans.
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years	Location changed for clarification.

Campus Name: Cuffe Page: 8 of 32 Assessment Date: 03/18/2024



Catego	ry : Mechanical			Buildin	g : Main		3324 S Racine AVENUE, Chicago, IL 60620
Catego	i y . iniconamical			Danam	g . Maiii	Recommend	
Group	Item - Type	Location	Quantity	UON	l Rank	Replacement	Comments
	CFM  Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1		5	6-10 years	Not directly accessible at the time of assessment due to lack of climbing means; the standard means of access to the north lower roof is nonfunctional. Unable to view dataplates; units are operational without undue noise such as from imbalance or vibration.  Location changed for clarification.  Not directly accessible at the time of assessment due to lack of climbing means; the standard means of access to the north lower roof is nonfunctional. Unable to view dataplate; unit is operational without undue noise such as from imbalance
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	or vibration.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Location changed for clarification.  Not directly accessible at the time of assessment due to lack of climbing means; the standard means of access to the north lower roof is nonfunctional. Unable to view dataplate; unit is operational without undue noise such as from imbalance or vibration.
	Type I Exhaust Hood- Kitchen	Entire Building	1		6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	2 EA	6	10+ years	Located above ovens and dishwasher.
Catego	ry : Plumbing			Buildin	g : Main		
						Recommend	
Group	Item - Type	Location	Quantity	UON	l Rank	Replacement	Comments
Hot Wat							
	EL .: 11 . 00 E0 10M	4 ( -1		_ ^	_	0.40	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Electric Heater - 20 - 50 KW	1st Floor	1	EA	6	6-10 years	Located in dishwasher room.
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EΑ	6	6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	82,120	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	82,120	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	82,120	SF	7	10+ years	

Campus Name: Cuffe Page : 9 of 32 Assessment Date: 03/18/2024



Catego	ry : Plumbing		В	uilding	: Main		-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	82,120	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	82,120	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	82,120	SF	7	10+ years	
	Sanitary Piping	Entire Building	82,120	SF	7	10+ years	
	Storm Piping	Entire Building	82,120	SF	7	10+ years	
	Vent Piping	Entire Building	82,120	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Inaccessible at the time of assessment. No CPS Asset Tag available. Location changed for clarification.

Category: Room **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	112B Work Room	150	SF	7	10+ years	
	Doors - Steel Doors incl hw	112B Work Room	1	EA	7	10+ years	
	Floor - Tile	112B Work Room	150	SF	6	10+ years	
	Lighting - Lay-in	112B Work Room	4	EA	7	6-10 years	
	Power Distribution	112B Work Room	4	EA	7	10+ years	
	Walls - Concrete Block	112B Work Room	430	SF	7	10+ years	
	Ceiling - Lay-in	113 counselor's office	104	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113 counselor's office	1	EA	7	10+ years	
	Floor - Tile	113 counselor's office	104	SF	7	10+ years	
	Lighting - Lay-in	113 counselor's office	2	EA	7	6-10 years	
	Power Distribution	113 counselor's office	4	EA	7	6-10 years	
	Walls - Concrete Block	113 counselor's office	220	SF	7	10+ years	
	Ceiling - Lay-in	Assitant Principals Office 112C	159	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assitant Principals Office 112C	1	EA	6	10+ years	
	Floor - Carpet	Assitant Principals Office 112C	159	SF	6	6-10 years	
	Lighting - Lay-in	Assitant Principals Office 112C	2	EA	7	10+ years	
	Power Distribution	Assitant Principals Office 112C	6	EA	6	10+ years	
	Walls - Concrete Block	Assitant Principals Office 112C	183	SF	6	10+ years	
	Ceiling - Lay-in	Conference, Room 112D	161	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Conference, Room 112D	1	EA	6	10+ years	
	Floor - Carpet	Conference, Room 112D	161	SF	6	6-10 years	

Campus Name: Cuffe Page : 10 of 32 Assessment Date: 03/18/2024



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Conference, Room 112D	2	EA	7	10+ years	
	Power Distribution	Conference, Room 112D	6	EA	6	10+ years	
	Walls - Concrete Block	Conference, Room 112D	196	SF	6	10+ years	
	Ceiling - Lay-in	Counselor's Office, Room 104	137	SF	6	10+ years	
	Doors - Side-lite	Counselor's Office, Room 104	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office, Room 104	1	EA	6	10+ years	
	Floor - Tile	Counselor's Office, Room 104	137	SF	6	10+ years	
	Lighting - Lay-in	Counselor's Office, Room 104	2	EA	7	10+ years	
	Power Distribution	Counselor's Office, Room 104	6	EA	6	10+ years	
	Walls - Concrete Block	Counselor's Office, Room 104	158	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office 140A	135	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's Office 140A	4	SF	5	1-2 years	Missing tile
	Ceiling - Lay-in	Engineer's Office 140A	3	SF	4	1-2 years	Stained tile
	Doors - Side-lite	Engineer's Office 140A	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office 140A	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office 140A	142	SF	7	10+ years	
	Lighting - Lay-in	Engineer's Office 140A	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office 140A	2	EA	7	6-10 years	
	Walls - Concrete Block	Engineer's Office 140A	173	SF	6	10+ years	
	Ceiling - Lay-in	Gym Office	102	SF	6	10+ years	
	Doors - Side-lite	Gym Office	15	SF	6	10+ years	
	Doors - Steel Doors incl hw	Gym Office	1	EA	6	10+ years	
	Floor - Tile	Gym Office	102	SF	6	10+ years	
	Lighting - Lay-in	Gym Office	2	EA	7	6-10 years	
	Power Distribution	Gym Office	2	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	124	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	446	SF	6	10+ years	
	Doors - Side-lite	Main Office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Carpet	Main Office	334	SF	6	6-10 years	
	Floor - Tile	Main Office	112	SF	6	10+ years	
	Lighting - Lay-in	Main Office	6	EA	7	10+ years	
	Power Distribution	Main Office	12	EA	6	10+ years	
	Storage/ Closet	Main Office	30	SF	7	10+ years	
	Walls - Concrete Block	Main Office	385	SF	6	10+ years	
	Walls - Plaster/Drywall	Main Office	128	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Office 112E	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office 112E	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office 112E	300	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office 112E	4	EA	7	10+ years	
	Power Distribution	Principal's Office 112E	8	EA	6	10+ years	
	Walls - Concrete Block	Principal's Office 112E	366	SF	6	10+ years	
	Ceiling - Lay-in	Room 100G Kitchen Office	97	SF	6	10+ years	
	Doors - Side-lite	Room 100G Kitchen Office	15	SF	6	10+ years	
					-	· ,	



Catego	ry : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	Room 100G Kitchen Office	1	EA	6	10+ years		
	Floor - Tile	Room 100G Kitchen Office	97	SF	7	10+ years		
	Lighting - Lay-in	Room 100G Kitchen Office	1	EA	7	10+ years		
	Power Distribution	Room 100G Kitchen Office	4	EA	6	10+ years		
	Walls - Concrete Block	Room 100G Kitchen Office	134	SF	6	10+ years		
	Ceiling - Lay-in	Student services, 1st floor, next to 116	117	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Student services, 1st floor, next to 116	1	EA	7	10+ years		
	Floor - Tile	Student services, 1st floor, next to 116	117	SF	6	10+ years		
	Lighting - Lay-in	Student services, 1st floor, next to 116	2	EA	7	10+ years		
	Power Distribution	Student services, 1st floor, next to 116	6	EA	7	10+ years		
	Walls - Concrete Block	Student services, 1st floor, next to 116	110	SF	6	10+ years		
	Walls - Plaster/Drywall	Student services, 1st floor, next to 116	296	SF	6	10+ years		
	Work SInk	Student services, 1st floor, next to 116	1	EA	7	10+ years		
	Ceiling - Lay-in	Teacher's Lounge, Room 110	594	SF	6	10+ years		
	Doors - Side-lite	Teacher's Lounge, Room 110	15	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Teacher's Lounge, Room 110	1	EA	6	10+ years		
	Floor - Tile	Teacher's Lounge, Room 110	594	SF	6	10+ years		
	Lighting - Lay-in	Teacher's Lounge, Room 110	9	EA	7	10+ years		
	Power Distribution	Teacher's Lounge, Room 110	30	EA	6	10+ years		
	Walls - Concrete Block	Teacher's Lounge, Room 110	683	SF	6	10+ years		
	Work SInk	Teacher's Lounge, Room 110	1	EA	7	10+ years		
	Ceiling - Lay-in	Workroom 209	230	SF	6	10+ years		
	Doors - Transom Window	Workroom 209	48	SF	6	10+ years		
	Doors - Transom Window	Workroom 209	15	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Workroom 209	1	ĒΑ	6	10+ years		
	Floor - Tile/Sheet	Workroom 209	230	SF	7	10+ years		
	Lighting - Lay-in	Workroom 209	6	EA	7	6-10 years		
	Storage/ Closet	Workroom 209	170	SF	7	10+ years		
	Walls - Concrete Block	Workroom 209	269	SF	6	10+ years		
	Work Sink	Workroom 209	1	EA	7	10+ years		
_Gymnasi	ia							
-	Bleacher Seating	1st Floor	110	EA	6	10+ years		
	Ceiling - Exposed	1st Floor	4,093	SF	7	10+ years		
	Ceiling - Exposed	1st Floor	30	SF	4	1-2 years	Water damaged material	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years		

Campus Name: Cuffe Page : 12 of 32 Assessment Date: 03/18/2024



Coulomb   Item - Type	Category : Room			В	uilding	: Main		· <u> </u>
Floor								
Lighting - Pendent/Surface	Group					Rank	Replacement	Comments
Scoreboards		Floor - Sport Flooring		4,123	SF	7	10+ years	
Storage Closet   1st Floor   180   SF   7   10+ years   Walls - Concrete Block   1st Floor   20   SF   5   1-2 years   Cracked block			1st Floor	16	EA	6	6-10 years	
Walls - Concrete Block			1st Floor	1	EA	7	10+ years	
Walls - Concrete Block		Storage/ Closet	1st Floor	180		7	10+ years	
Ceiling - Lay-in		Walls - Concrete Block	1st Floor	5,010	SF	6	10+ years	
Ceiling - Lay-in		Walls - Concrete Block	1st Floor	20	SF	5	1-2 years	Cracked block
Doors - Steel Doors inclu hw	_Kitchen							
Floor - Concrete Epoxy/ Painted		Ceiling - Lay-in	1st Floor	1,241	SF	6	10+ years	
Floor - Epoxy/ Painted		Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
Floor - Epoxy/ Painted		Floor - Concrete Epoxy/ Painted	1st Floor	1,200	SF	7	6-10 years	
Lighting - Lay-in   1st Floor   16   EA   7   10+ years   Storage/ Closet   1st Floor   134   SF   7   10+ years   Walls - Concrete Block   1st Floor   1,427   SF   6   10+ years   Walls - Concrete Block   1st Floor   2,730   SF   6   10+ years   Water damage   Ceiling - Lay-in   2nd Floor   2,730   SF   6   10+ years   Ceiling - Lay-in   2nd Floor   2,730   SF   6   10+ years   Water damage   Doors - Side-lite   2nd Floor   30   SF   6   10+ years   Water damage   Doors - Wood Doors inclu hw   2nd Floor   2   EA   6   10+ years   Eloor - Carpet   2nd Floor   2,750   SF   6   6-10 years   Eloor - Carpet   2nd Floor   2,750   SF   6   6-10 years   Eloor - Carpet   2nd Floor   2,750   SF   6   6-10 years   Eloor   2,750   EA   7   6-10 years   Eloor   2,750   Eloor   2,		Floor - Epoxy/ Painted	1st Floor		SF	4		Cracked flooring
Storage   Closet   1st Floor   134   SF   7   10+ years			1st Floor	16	EΑ	7		3
Library			1st Floor	134	SF	7		
Casework			1st Floor	1,427		6	•	
Ceiling - Lay-in	Library							
Ceiling - Lay-in		Casework	2nd Floor	200	LF	6	10+ years	
Ceiling - Lay-in		Ceiling - Lay-in	2nd Floor	2,730	SF	6	10+ years	
Doors - Side-lite			2nd Floor	20	SF	4		Water damage
Doors - Wood Doors inclu hw			2nd Floor			6		
Floor - Carpet						_	•	
Lighting - Lay-in Walls - Plaster/Drywall         2nd Floor         24 EA 7 6-10 years           Lunch & Multipurpose Room         4,125 SF 6 10+ years           Ceiling - Exposed Doors - Steel Doors incl hw         1st Floor         3,307 SF 6 10+ years           Floor - Tile Lighting - Metal Halide/Sodium Vapor 1st Floor         12 EA 6 10+ years           Walls - Concrete Block 1st Floor 3,025 SF 6 10+ years         10+ years           Walls - Plaster/Drywall 1st Floor 1,009 SF 6 10+ years         10+ years           Ceiling - Lay-in Servery 856 SF 6 10+ years         10+ years           Ceiling - Lay-in Servery 862 SF 6 10+ years         10+ years           Floor - Tile Servery 862 SF 6 10+ years         10+ years           Lighting - Lay-in Servery 9         2 EA 6 10+ years           Lighting - Lay-in Servery 10 EA 7 10+ years         10 EA 7 10+ years           Serving Line Servery 10 EA 7 10+ years         10 EA 7 10+ years           Walls - Concrete Block Servery 1,051 SF 6 10+ years         10+ years						-		
Lunch & Multipurpose Room						_		
Celling - Exposed 1st Floor 3,307 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 4 EA 6 10+ years Floor - Tile 1st Floor 3,307 SF 6 10+ years Lighting - Metal Halide/Sodium Vapor 1st Floor 12 EA 6 10+ years Walls - Concrete Block 1st Floor 3,025 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 1,009 SF 6 10+ years Celling - Lay-in Servery 856 SF 6 10+ years Ceiling - Lay-in Servery 6 SF 5 1-2 years Missing tile Doors - Steel Doors incl hw Servery 2 EA 6 10+ years Floor - Tile Servery 862 SF 6 10+ years Lighting - Lay-in Servery 10 EA 7 10+ years Serving Line Servery 32 LF 6 10+ years Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years							•	
Doors - Steel Doors incl hw	_Lunch &	Multipurpose Room						
Doors - Steel Doors incl hw		Ceiling - Exposed	1st Floor	3.307	SF	6	10+ years	
Floor - Tile								
Lighting - Metal Halide/Sodium Vapor  Walls - Concrete Block  1st Floor  3,025  SF  6  10+ years  Walls - Plaster/Drywall  1st Floor  1,009  SF  6  10+ years  Walls - Plaster/Drywall  1st Floor  1,009  SF  6  10+ years  Ceiling - Lay-in  Servery  856  SF  6  10+ years  Ceiling - Lay-in  Servery  6  SF  5  1-2 years  Missing tile  Doors - Steel Doors incl hw  Servery  2  EA  6  10+ years  Missing tile  Doors - Tile  Servery  862  SF  6  10+ years  Floor - Tile  Servery  10  EA  7  10+ years  Servery  32  Lighting - Lay-in  Servery  33  Lighting - Lay-in  Servery  34  Lighting - Lay-in  Servery  35  Lighting - Lay-in  Servery  36  Lighting - Lay-in  Servery  37  Lighting - Lay-in  Servery  38  Missing tile  10+ years  10+ years  10+ years  10+ years  10+ years				3,307	SF	6	•	
Walls - Concrete Block Walls - Plaster/Drywall 1st Floor 1,009 SF 6 10+ years Ceiling - Lay-in Servery 856 SF 6 10+ years Ceiling - Lay-in Servery 6 Servery 6 Servery 2 EA 6 10+ years Missing tile Doors - Steel Doors incl hw Servery 862 SF 6 10+ years Floor - Tile Servery 862 SF 6 10+ years Floor - Tile Servery 10 EA 7 10+ years Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years		Lighting - Metal Halide/Sodium Vapor		,		6		
Walls - Plaster/Drywall Ceiling - Lay-in Servery Serve							•	
Ceiling - Lay-in Servery 856 SF 6 10+ years Ceiling - Lay-in Servery 6 SF 5 1-2 years Missing tile Doors - Steel Doors incl hw Servery 2 EA 6 10+ years Floor - Tile Servery 862 SF 6 10+ years Lighting - Lay-in Servery 10 EA 7 10+ years Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years  MDF_IDF						_		
Ceiling - Lay-in Servery 6 SF 5 1-2 years Missing tile Doors - Steel Doors incl hw Servery 2 EA 6 10+ years Floor - Tile Servery 862 SF 6 10+ years Lighting - Lay-in Servery 10 EA 7 10+ years Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years  MDF_IDF				•		_	•	
Doors - Steel Doors incl hw Floor - Tile Servery B62 Floor - Tile Servery B62 Floor - Tile Servery B62 Floor - Tile B10 Floor								Missina tile
Floor - Tile Lighting - Lay-in Servery Serving Line Servery Se						_		· · · <b>3</b> · · · · ·
Lighting - Lay-in Servery 10 EA 7 10+ years Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years  MDF_IDF						_		
Serving Line Servery 32 LF 6 10+ years Walls - Concrete Block Servery 1,051 SF 6 10+ years  MDF_IDF			•		_	_		
Walls - Concrete Block Servery 1,051 SF 6 10+ years  MDF_IDF			•					
	_MDF_ID	E						
			2nd Floor Room 205	1	EA	7	10+ years	

Campus Name: Cuffe Page: 13 of 32 Assessment Date: 03/18/2024



Category : Room			В	uilding	: Main				
	_				_	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Finishes	2nd Floor Room 205	153	SF	7	10+ years			
	Other Cooling Unit	2nd Floor Room 205	1	EA	7	6-10 years			
/lechan	ical/ Service Rooms								
	Janitor's Closet	1st Floor	15	SF	7	10+ years			
	Janitor's Closet	1st Floor	35	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	200	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	120	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	456	SF	5	10+ years			
	Storage Room	1st Floor	1,285	SF	5	10+ years			
	Janitor's Closet	2nd Floor	15	SF	7	10+ years			
	Janitor's Closet	2nd Floor	35	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	4,887	SF	7	10+ years			
	Storage Room	2nd Floor	4,567 80	SF	7	10+ years			
	Janitor's Closet	3rd Floor	15	SF	7	10+ years			
	Janitor's Closet	3rd Floor	30	SF	5	10+ years			
	Mechanical/ Service Rooms	3rd Floor	41	SF	7	10+ years			
	Storage Room	3rd Floor	340	SF	7	10+ years			
	Storage Room	314 1 1001	340	OI.	,	10+ years			
Restroo									
	Accessories	1st Floor	42	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	42	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	38	SF	6	10+ years			
	Floor - Tile/Sheet	1st Floor	4	SF	4	1-2 years	Stained tile		
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	2	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	54	SF	6	10+ years			
	Water Closet	1st Floor	1	EA	6	10+ years			
	Accessories	1st Floor North	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor North	191	SF	6	10+ years			
	Floor - Terrazzo	1st Floor North	191	SF	6	10+ years			
	Floor Drain	1st Floor North	1	ĒΑ	7	10+ years			
	Lavatory	1st Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	1st Floor North	4	ΕA	7	10+ years			
	Partitions	1st Floor North	4	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor North	229	SF	6	10+ years			
	Water Closet	1st Floor North	3	EA	7	10+ years			
	Water Closet	1st Floor North	1	EA	6	1-2 years	Door locked		
	Accessories	1st Floor North	180	SF	7	6-10 years	DOO! IOUNGU		
	Ceiling - Plaster/Drywall	1st Floor North	175	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor North	5	SF SF	5		Stained cailings		
	Floor - Terrazzo	1st Floor North	180	SF SF	5 6	1-2 years	Stained ceilings		
	FIUUI - TEITAZZU	ISL FIOOL MOLLII	180	SF	O	10+ years			

Campus Name: Cuffe Page : 14 of 32 Assessment Date: 03/18/2024



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	1st Floor North	1	EA	7	10+ years			
	Lavatory	1st Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	1st Floor North	4	EA	7	10+ years			
	Partitions	1st Floor North	2	EA	7	10+ years			
	Urinals	1st Floor North	2	EA	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor North	220	SF	6	10+ years			
	Water Closet	1st Floor North	2	EA	7	10+ years			
	Accessories	1st Floor South	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor South	191	SF	6	10+ years			
	Floor - Terrazzo	1st Floor South	191	SF	6	10+ years			
	Floor Drain	1st Floor South	1	ĒΑ	7	10+ years			
	Lavatory	1st Floor South	3	ĒΑ	6	10+ years			
	Lighting - Lay-in	1st Floor South	4	EA	7	6-10 years			
	Partitions	1st Floor South	4	ΕA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor South	229	SF	6	10+ years			
	Water Closet	1st Floor South	4	EA	6	10+ years			
	Accessories	1st Floor South	180	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor South	1	SF	6	1-2 years	Stained ceiling		
	Ceiling - Plaster/Drywall	1st Floor South	179	SF	6	10+ years	Stained Ceiling		
	Floor - Terrazzo	1st Floor South	180	SF	6	10+ years			
	Floor Drain	1st Floor South	1	EA	7	10+ years			
	Lavatory	1st Floor South	3	EA	6	10+ years			
	Lighting - Lay-in	1st Floor South	4	EA	7	6-10 years			
	Partitions	1st Floor South	2	EA	7	10+ years			
	Urinals	1st Floor South	2	EA	6	•			
	Walls - Structural Glazed Tile	1st Floor South	220	SF	6	10+ years			
	Water Closet	1st Floor South	220	EA	6	10+ years 10+ years			
		2nd Floor	42	SF	7				
	Accessories			SF SF		6-10 years			
	Ceiling - Lay-in	2nd Floor	36	SF SF	7	10+ years	Developer.		
	Ceiling - Lay-in	2nd Floor	6		4	0-1 year	Buckling		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	42	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	1	EΑ	7	10+ years			
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	54	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	6	10+ years			
	Accessories	2nd Floor North	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor North	191	SF	7	10+ years			
	Floor - Terrazzo	2nd Floor North	191	SF	6	10+ years			
	Floor Drain	2nd Floor North	1	EA	7	10+ years			
	Lavatory	2nd Floor North	3	EA	6	10+ years			
	Lighting - Lay-in	2nd Floor North	4	EA	7	6-10 years			
	Partitions	2nd Floor North	3	EA	7	10+ years			

Campus Name: Cuffe Page: 15 of 32 Assessment Date: 03/18/2024



Catego	Category : Room		В	uilding	: Main				
J						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2nd Floor North	1	EA	4	0-1 year	Missing door		
	Walls - Structural Glazed Tile	2nd Floor North	229	SF	7	10+ years			
	Water Closet	2nd Floor North	4	EA	6	10+ years			
	Accessories	2nd Floor North	180	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor North	180	SF	7	10+ years			
	Floor - Terrazzo	2nd Floor North	180	SF	6	10+ years			
	Floor Drain	2nd Floor North	1	EA	7	10+ years			
	Lavatory	2nd Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor North	4	EA	7	6-10 years			
	Partitions	2nd Floor North	2	EA	7	10+ years			
	Urinals	2nd Floor North	2	EA	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor North	220	SF	7	10+ years			
	Water Closet	2nd Floor North	2	EA	7	10+ years			
	Accessories	2nd Floor South	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor South	191	SF	7	10+ years			
	Floor - Terrazzo	2nd Floor South	191	SF	7	10+ years			
	Floor Drain	2nd Floor South	1	EA	7	10+ years			
	Lavatory	2nd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor South	4	EA	7	6-10 years			
	Partitions	2nd Floor South	4	EA	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor South	229	SF	7	10+ years			
	Water Closet	2nd Floor South	4	EA	7	10+ years			
	Accessories	2nd Floor South	180	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor South	180	SF	6	10+ years			
	Floor - Terrazzo	2nd Floor South	180	SF	7	10+ years			
	Floor Drain	2nd Floor South	1	EA	7	10+ years			
	Lavatory	2nd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor South	4	EA	7	6-10 years			
	Partitions	2nd Floor South	1	EA	7	10+ years			
	Partitions	2nd Floor South	1	EA	4	1-2 years	Bended		
	Urinals	2nd Floor South	2	EA	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor South	220	SF	6	10+ years			
	Water Closet	2nd Floor South	2	EA	7	10+ years			
	Accessories	3rd Floor	42	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	42	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	34	SF	6	10+ years			
	Floor - Tile	3rd Floor	8	SF	4	0-1 year	Damaged		
	Floor Drain	3rd Floor	1	EA	7	10+ years	•		
	Lavatory	3rd Floor	1	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	2	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	54	SF	6	10+ years			
	Water Closet	3rd Floor	1	ĒΑ	7	10+ years			
	Accessories	3rd Floor North	191	SF	7	6-10 years			
			-			,			

Campus Name: Cuffe Page : 16 of 32 Assessment Date: 03/18/2024



Catego	Category : Room		В	uilding	: Main				
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	3rd Floor North	191	SF	6	10+ years			
	Floor - Terrazzo	3rd Floor North	191	SF	6	10+ years			
	Floor Drain	3rd Floor North	1	EA	7	10+ years			
	Lavatory	3rd Floor North	3	EA	6	10+ years			
	Lighting - Lay-in	3rd Floor North	4	EA	7	10+ years			
	Partitions	3rd Floor North	4	EA	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor North	229	SF	6	10+ years			
	Water Closet	3rd Floor North	4	EA	6	10+ years			
	Accessories	3rd Floor North	180	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor North	180	SF	6	10+ years			
	Floor - Terrazzo	3rd Floor North	180	SF	6	10+ years			
	Floor Drain	3rd Floor North	1	ĒΑ	7	10+ years			
	Lavatory	3rd Floor North	3	EΑ	6	10+ years			
	Lighting - Lay-in	3rd Floor North	4	EA	7	10+ years			
	Partitions	3rd Floor North	2	EA	7	10+ years			
	Urinals	3rd Floor North	2	EA	6	10+ years			
	Walls - Structural Glazed Tile	3rd Floor North	220	SF	6	10+ years			
	Water Closet	3rd Floor North	220	EA	6	10+ years			
	Accessories	3rd Floor South	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor South	191	SF	6				
	Floor - Terrazzo		191	SF	-	10+ years			
		3rd Floor South		Sr EA	6	10+ years			
	Floor Drain	3rd Floor South	1		7	10+ years			
	Lavatory	3rd Floor South	3	EΑ	6	10+ years			
	Lighting - Lay-in	3rd Floor South	4	EΑ	7	10+ years			
	Partitions	3rd Floor South	3	EΑ	7	10+ years	ъ.		
	Partitions	3rd Floor South	1	EA	4	1-2 years	Bent		
	Walls - Structural Glazed Tile	3rd Floor South	229	SF	6	10+ years			
	Water Closet	3rd Floor South	4	EA	6	10+ years			
	Accessories	3rd Floor South	180	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor South	180	SF	6	10+ years			
	Floor - Terrazzo	3rd Floor South	180	SF	6	10+ years			
	Floor Drain	3rd Floor South	1	EA	7	10+ years			
	Lavatory	3rd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor South	4	EA	7	10+ years			
	Partitions	3rd Floor South	1	EA	7	10+ years			
	Partitions	3rd Floor South	1	EA	4	1-2 years	Bended		
	Urinals	3rd Floor South	2	EA	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor South	220	SF	6	10+ years			
	Water Closet	3rd Floor South	1	EA	7	10+ years			
	Water Closet	3rd Floor South	1	EA	4	1-2 years	Out of order		
	Accessories	Classroom 103	48	SF	7	6-10 years			
	Ceiling - Lay-in	Classroom 103	48	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Classroom 103	1	ĒΑ	7	10+ years			
	Floor - Tile	Classroom 103	45	SF	6	10+ years			
			-			,			



Catego	Category : Room			uilding	-		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Classroom 103	3	SF	4	1-2 years	Stained tile
	Lavatory	Classroom 103	1	EA	7	10+ years	
	Lighting - Lay-in	Classroom 103	1	EA	7	6-10 years	
	Walls - Concrete Block	Classroom 103	72	SF	7	10+ years	
	Water Closet	Classroom 103	1	EΑ	7	10+ years	
	Accessories	Classroom 105	48	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 105	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Classroom 105	1	EΑ	6	10+ years	
	Floor - Tile	Classroom 105	46	SF	6	10+ years	
	Floor - Tile	Classroom 105	2	SF	4	1-2 years	Stained tile
	Lavatory	Classroom 105	1	EA	7	10+ years	
	Lighting - Lay-in	Classroom 105	1	EΑ	7	6-10 years	
	Walls - Concrete Block	Classroom 105	72	SF	6	10+ years	
	Water Closet	Classroom 105	1	EA	6	10+ years	
	Accessories	Classroom 107	48	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 107	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Classroom 107	1	EA	6	10+ years	
	Floor - Tile	Classroom 107	46	SF	6	10+ years	
	Floor - Tile	Classroom 107	2	SF	4	1-2 years	Minor cracks
	Lavatory	Classroom 107	1	EA	7	10+ years	
	Lighting - Lay-in	Classroom 107	1	EA	7	6-10 years	
	Walls - Concrete Block	Classroom 107	72	SF	6	10+ years	
	Water Closet	Classroom 107	1	EA	6	10+ years	
	Accessories	In the Main Office	42	SF	7	6-10 years	
	Ceiling - Lay-in	In the Main Office	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In the Main Office	1	EA	6	10+ years	
	Floor - Tile	In the Main Office	38	SF	6	10+ years	
	Floor - Tile	In the Main Office	4	SF	4	1-2 years	Stained tile
	Floor Drain	In the Main Office	1	ĒΑ	7	10+ years	
	Lavatory	In the Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	In the Main Office	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	In the Main Office	54	SF	6	10+ years	
	Water Closet	In the Main Office	1	ĒΑ	7	10+ years	
	Accessories	Kindergarten Room 101	48	SF	7	10+ years	
	Ceiling - Lay-in	Kindergarten Room 101	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kindergarten Room 101	1	ĒΑ	6	10+ years	
	Floor - Tile	Kindergarten Room 101	43	SF	7	10+ years	
	Floor - Tile	Kindergarten Room 101	5	SF	4	1-2 years	Cracked tile
	Lavatory	Kindergarten Room 101	1	ĒΑ	6	10+ years	
	Lighting - Lay-in	Kindergarten Room 101	1	EΑ	7	6-10 years	
	Walls - Concrete Block	Kindergarten Room 101	72	SF	7	10+ years	
	Water Closet	Kindergarten Room 101	1	EA	7	10+ years	
	Accessories	Room 100C, Men's Room in Kitchen	46	SF	7	6-10 years	
	Ceiling - Lay-in	Room 100C, Men's Room in Kitchen	46	SF	6	10+ years	
			10	٥.	J	10. 300.0	



Catego	Category : Room				Building : Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Room 100C, Men's Room in Kitchen	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Room 100C, Men's Room in Kitchen	40	SF	7	6-10 years			
	Floor - Epoxy/ Painted	Room 100C, Men's Room in Kitchen	6	SF	4	1-2 years	Cracked floor		
	Floor Drain	Room 100C, Men's Room in Kitchen	1	EA	7	10+ years			
	Lavatory	Room 100C, Men's Room in Kitchen	1	EA	7	10+ years			
	Lighting - Lay-in	Room 100C, Men's Room in Kitchen	1	EA	7	10+ years			
	Walls - Concrete Block	Room 100C, Men's Room in Kitchen	56	SF	6	10+ years			
	Water Closet	Room 100C, Men's Room in Kitchen	1	EA	7	10+ years			
	Accessories	Room 100D, Women's Room in Kitchen	46	SF	7	6-10 years			
	Ceiling - Lay-in	Room 100D, Women's Room in Kitchen	46	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 100D, Women's Room in Kitchen	1	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	Room 100D, Women's Room in Kitchen	46	SF	7	6-10 years			
	Floor Drain	Room 100D, Women's Room in Kitchen	1	EA	7	10+ years			
	Lavatory	Room 100D, Women's Room in Kitchen	1	EA	7	10+ years			
	Lighting - Lay-in	Room 100D, Women's Room in Kitchen	1	EA	5	1-2 years	Missing cover		
	Walls - Concrete Block	Room 100D, Women's Room in Kitchen	56	SF	6	10+ years			
	Water Closet	Room 100D, Women's Room in Kitchen	1	EA	7	10+ years			

Category: Classroom Building: Main

Calego	Category . Classicolli			Building . Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Classroo	om #101 (Kindergarten)								
	Casework	1st Floor	60	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	900	SF	6	10+ years			
	Doors - Side-lite	1st Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	900	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years			
	Lighting - Lay-in	1st Floor	1	EA	6	1-2 years	Not working		
	Marker Board	1st Floor	28	LF	7	6-10 years			
	Storage/ Closet	1st Floor	126	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	970	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
	Work Sink	1st Floor	2	EA	7	10+ years			

Campus Name: Cuffe Page : 19 of 32 Assessment Date: 03/18/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #102 (Faculty Lounge)						
	Casework	1st Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	551	SF	6	10+ years	
	Doors - Side-lite	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	551	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	633	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #103 (Kindergarten)						
	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	6	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #105 (Kindergarten)						
Olassio	Casework	1st Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	13	EA	6	10+ years	
	Floor - Tile	1st Floor	900	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #106/108 (Regular Classroom)						
VIUSSI (I	Casework	1st Floor	45	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,196	SF	6	10+ years	
	Doors - Side-lite	1st Floor	30	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,196	SF	6	10+ years 10+ years	
	Lighting - Lay-in	1st Floor	1,190	EA	7	10+ years	
	Lighting - Lay-III	151 11001	10	EA	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,375	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	200	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #107 (Kindergarten)						
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	900	SF	6	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	900	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	970	SF	6	10+ years	
			3		7	,	
	Work Sink	1st Floor	3	EA	,	10+ years	
Classroo	m #109/115 (Laboratory/Shop)						
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,792	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Missing tile
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,800	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	1-2 years	Not working
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,940	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	m #116 (Faculty Lounge)						
	Casework	1st Floor	19	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	612	SF	6	10+ years	
	Doors - Side-lite	1st Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	612	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	126	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	703	SF	6	10+ years 10+ years	
	Work Sink	1st Floor	703	SF EA	7		
	VVUIK OIIIK	IST LIOOI	1	EA	1	10+ years	



Category : Classroom			В	Building : Main			Decommend		
			•			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #201 (Computer Lab)								
Oldooroo	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years			
	Chalk Board	2nd Floor	14	LF	4	2-5 years			
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years			
	Floor - Tile	2nd Floor	900	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	14	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	126	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	980	SF	7				
	walls - Concrete Block	2110 F1001	900	SF	,	10+ years			
Classroo	m #202 (Other Instructional Use)								
	Casework	2nd Floor	34	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	850	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	2nd Floor	850	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	126	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	995	SF	6	10+ years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
01	77. //000 (O-77.7.ston   -b)								
Classroc	m #203 (Computer Lab)	0 15	20			40			
	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	1,440	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	1,440	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years			
	Marker Board	2nd Floor	28	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	126	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	1,522	SF	7	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
Classroo	m #204 (Office)								
	Casework	2nd Floor	19	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	620	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years			
	Floor - Tile	2nd Floor	620	SF	7	10+ years			
	I IOOI - I IIG	Z110 1 1001	020	Ji	,	TOT years			



Catego	ry : Classroom		В	uilding	: Main		324 6 Nacine Avenue, Onicago, le 66626
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	713	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	995	SF	7	10+ years	
	Valid Collorete Bleek	2110 1 1001	000	O.	•	101 youro	
_Classroo	om #208 (Store Room)						
	Casework	2nd Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	995	SF	7	10+ years	
Classroo	om #210 (Multi Purpose Room)						
	Casework	2nd Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	995	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	34	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	850	SF	7	10+ years	
	Johning Lay III	ZIIQ I IOOI	000	51	,	ioi yeais	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	995	SF	7	10+ years	
Classro	om #215 (Store Room)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,440	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,440	SF	7	10+ years	
			•			•	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	296	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,522	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	970	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years	
Classro	om #302 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor		SF SF	7	-	
	Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor 3rd Floor	15 1	SF EA		10+ years	
					6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years	

Campus Name: Cuffe Page : 24 of 32 Assessment Date: 03/18/2024



	Category : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #303 (Regular Classroom)						
_Classioo	Casework	3rd Floor	36	LF	6	10 L Vooro	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years 10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	•	
	Doors - Wood Doors inclu hw	3rd Floor	15	EA	6	10+ years 10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	970	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	400	SF	6		
	Walls - Flastel/Drywall	314 F1001	400	SF	b	10+ years	
Classroo	m #304 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	400	SF	6	10+ years	
Classroo	m #305 (Store Room)						
Classioo	Casework	3rd Floor	22	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	600	SF	6	•	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	3rd Floor	15	EA	6	10+ years	
	Floor - Tile	3rd Floor		SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	600 9	EA	7	10+ years	
	Marker Board	3rd Floor	28	LF	7	10+ years 6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	•	
				SF		10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	3rd Floor 3rd Floor	650 400	SF SF	6 6	10+ years	
	walls - Plastel/Drywall	310 F1001	400	SF	б	10+ years	
Classroo	m #306 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	846	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	

Campus Name: Cuffe Page : 25 of 32 Assessment Date: 03/18/2024



Catego	ry : Classroom		В	Building : Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years	
Classroo	m #307 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	890	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	Orackea
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	970	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	•	
	walls - Flastel/Drywall	314 F1001	200	SF	0	10+ years	
Classroo	m #308 (Store Room)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years	
Classroo	m #310 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	400	SF	7	10+ years	
	Trans Tidoton Dry Wall	014 1 1001	400	O.	•	101 yours	

Campus Name: Cuffe Page : 26 of 32 Assessment Date: 03/18/2024



Catego	ry : Classroom		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #311 (Office)						
	Casework	3rd Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	600	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	600	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	10+ years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	650	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	7	10+ years	
Classroo	om #312 (Regular Classroom)						
	Casework	3rd Floor	34	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	850	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	995	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years	
Classros	om #313 (Regular Classroom)						
Classroc	Casework	3rd Floor	20	LF		10	
			36		6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	126	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	970	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	400	SF	6	10+ years	
Classroo	om #315 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	900	SF	6	10+ years	




Categor	y : Classroom		В	Building : Main						
_						Recommend				
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years				
	Marker Board	3rd Floor	36	LF	6	6-10 years				
	Storage/ Closet	3rd Floor	126	SF	7	10+ years				
	Walls - Concrete Block	3rd Floor	970	SF	6	10+ years				
	Walls - Plaster/Drywall	3rd Floor	200	SF	6	10+ years				
ategor	y : Interior		В	uilding	: Main					
,	Ham Time	Location	Overtity	HOM	Donk	Recommend	Comments			
roup orridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
JIIIGOI	Ceiling - Lay-in	1st Floor	4,320	SF	6	10+ years				
	Doors - Side-lite	1st Floor	32	SF	6	10+ years				
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	10+ years				
	Doors - Transom Window	1st Floor	64	SF	6	10+ years				
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years				
	Floor - Terrazzo	1st Floor		SF	6	10+ years				
			4,320	EA	7					
	Lighting - Lay-in	1st Floor	27	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	4,423	SF SF		10+ years				
	Ceiling - Lay-in	2nd Floor	3,960		6	10+ years				
	Doors - Steel Doors incl hw	2nd Floor	4	EΑ	6	10+ years				
	Drinking Fountains - Single Fountain	2nd Floor	1	EΑ	7	10+ years				
	Drinking Fountains - Single Water Cooler	2nd Floor	3	EA	7	10+ years				
	Floor - Terrazzo	2nd Floor	3,960	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	23	EA	7	6-10 years				
	Walls - Concrete Block	2nd Floor	4,013	SF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	3,910	SF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	50	SF	4	0-1 year	Water damage			
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	10+ years				
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years				
	Floor - Terrazzo	3rd Floor	3,960	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	23	EΑ	7	10+ years				
	Student Lockers - One Tier	3rd Floor	220	EA	7	10+ years				
	Walls - Concrete Block	3rd Floor	4,013	SF	6	10+ years				
fety										
*	Camera Viewing Station	Entire Building	4	EA	7	6-10 years				
	Security Cameras	Entire Building	32	EA	7	6-10 years				
airs										
	Ceiling - Lay-in	North	1,900	SF	5	10+ years				
	Floor - Terrazzo	North	1,900	SF	6	10+ years				
	Handrails	North	160	LF	5	10+ years				

Campus Name: Cuffe Page : 28 of 32 Assessment Date: 03/18/2024



Catego	ry : Interior		В	uilding			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	North	5	EA	7	10+ years	
	Stairs - Terrazzo	North	208	LF	6	10+ years	
	Walls - Concrete Block	North	1,961	SF	6	10+ years	
	Ceiling - Lay-in	South	1,900	SF	5	10+ years	
	Floor - Terrazzo	South	1,900	SF	6	10+ years	
	Handrails	South	160	LF	7	10+ years	
	Lighting - Lay-in	South	5	EA	7	10+ years	
	Stairs - Terrazzo	South	208	LF	6	10+ years	
	Walls - Concrete Block	South	1,961	SF	6	10+ years	
	Ceiling - Lay-in	West	1,900	SF	5	10+ years	
	Floor - Terrazzo	West	1,900	SF	6	10+ years	
	Handrails	West	160	LF	5	10+ years	
	Lighting - Lay-in	West	5	EΑ	7	10+ years	
	Stairs - Terrazzo	West	208	LF	6	10+ years	
	Walls - Concrete Block	West	1,961	SF	6	10+ years	
_Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	

Campus Name: Cuffe Page : 29 of 32 Assessment Date: 03/18/2024





Category: Site **Building: Site** 

Jatego	ry : Site	Building: Site							
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ivil/Dra			•			•			
	Civil/ Drainage - Catch Basin	Entire Site	16	ΕΛ	6	10 L VOORO			
				EΑ	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years			
encing									
	Fencing - New Standard Ornamental	Entire Site	1,732	LF	6	6-10 years			
	Fencing - New Standard Ornamental	Entire Site	100	LF	4	0-1 year	Missing, bent		
	· ·					•	<b>C</b> .		
andsca	ne								
aridood	Irrigation	Entire Site	38,150	SF	6	6-10 years			
	Landscape - Grass	Entire Site	30,210	SF	6	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	13,560	SF	6	10+ years			
	Lighting - Pole Mounted	Entire Site	13,300	EA	6	10+ years			
	Lighting - Pole Mounted  Lighting - Pole Mounted	Entire Site Entire Site	1	EA	4	0-1 year	Missing light		
					-		Missing light		
	Parkway trees	Entire Site	23	EA	6	10+ years			
	Planting Beds/ Area	Entire Site	7,940	SF	6	10+ years			
	Play Area - Hardscape- Asphalt	Entire Site	6,050	SF	5	2-5 years			
	Trash Receptacles	Entire Site	3	EA	6	6-10 years			
به منابات م	Lat								
arking	Concrete Curbs	Parking Lot- North	278	LF	6	10			
			3,060	SF	5	10+ years			
	Surface - Asphalt	Parking Lot- North	·			2-5 years	0		
	Trash Compactor	Parking Lot- North	1	EA	5	2-5 years	Corrosion		
	Trash Enclosure - Masonry	Parking Lot- North	2,810	SF	6	10+ years			
	Vehicular Screening	Parking Lot- North	150	LF . –	6	10+ years			
	Concrete Curbs	Parking Lot- South	648	LF	6	10+ years			
	Interior Plantings	Parking Lot- South	80	LF	6	10+ years			
	Lighting - Pole Mounted	Parking Lot- South	2	EA	6	6-10 years			
	Surface - Asphalt	Parking Lot- South	20,644	SF	6	6-10 years			
	Vehicular Screening	Parking Lot- South	546	LF	6	10+ years			
laygrou	und								
ayyıot	Equipment - Pre K 3-5	South	1	EA	6	2-5 years			
	Equipment - School Age 5-12	South	1	EA	5	2-5 years 2-5 years	Damaged netting		
	Surface - Poured Surface	South	2,685	SF	5 5	2-5 years 2-5 years	Damaged Helling		
	Surface - Poured Surface Surface - Poured Surface		1,000	SF SF	5 4		Holog worn ourfood		
	Surface - Poured Surface	South	1,000	SF	4	0-1 year	Holes, worn surface		
dewall	(S								
	Sidewalks - Internal Walks	Entire Site	556	LF	6	10+ years			
	Sidewalks - Perimeter Sidewalks	Entire Site	12,560	SF	6	10+ years			
	c.co r omnotor oldomano		. 2,000	٥.	Ü	10. 300.0			



#### Paul Cuffe Math-Science Technology Academy ES

8324 S Racine AVENUE, Chicago, IL 60620

Catego	ry : Site		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage	• • • • • • • • • • • • • • • • • • •	Location	Qualitity	OOW	Naiik	Replacement	Comments
_оідпаде	Flag Pole - Flag Pole Marquee - Building Mounted Back Lighted Monument - Building Mounted Cut Letter Sign	East East East	1 2 1	EA EA EA	6 6 7	10+ years 10+ years 10+ years	
	Monument - Sign	East	1	EA	7	10+ years	

#### **Definitions**

- · Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Cuffe Page : 31 of 32 Assessment Date: 03/18/2024

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classicom Guilliary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					\ - <i> </i>				
Computer Lab	Art Room	2nd Floor	201	2-16	900	144	75	N	N
Computer Lab	Computer Lab	2nd Floor	203	2-17	1,440	192	100	N	Y
Faculty Lounge	Regular Classroom	1st Floor	102	1-08	551	114	3	N	Υ
Faculty Lounge	Regular Classroom	1st Floor	116	1-20	612	78	2	N	N
Kindergarten	Kindergarten	1st Floor	105	1-43	900	144	75	N	Y
Kindergarten	Kindergarten	1st Floor	107	1-38	900	144	75	N	Υ
Kindergarten	Regular Classroom	1st Floor	101	1-49	900	144	75	N	Υ
Kindergarten	Regular Classroom	1st Floor	103	1-46	900	114	3	N	Υ
Laboratory/Shop	Regular Classroom	1st Floor	109/115	1-34	1,800	144	75	N	Υ
Multi Purpose Room	Regular Classroom	2nd Floor	210	2-09	850	114	3	N	N
Office	Regular Classroom	3rd Floor	311	3-18	600	144	75	N	N
Office	Special Education	2nd Floor	204	2-06	620	76	2	N	N
Other Instructional Use	Regular Classroom	2nd Floor	202	2-05	850	114	3	N	N
Regular Classroom	Regular Classroom	1st Floor	106/108	1-08	1,196	152	4	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	2-07	850	114	3	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	2-10	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	3-23	900	144	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	3-06	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	3-22	900	144	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	3-07	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	3-08	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	3-20	900	144	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	3-10	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	3-11	850	114	3	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	3-17	900	144	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	315	3-16	900	144	75	N	N
Store Room	Regular Classroom	2nd Floor	208	2-08	850	114	3	N	N
Store Room	Regular Classroom	2nd Floor	215	215	1,440	192	100	N	Υ
Store Room	Regular Classroom	3rd Floor	305	3-21	600	95	50	N	N
Store Room	Regular Classroom	3rd Floor	308	3-09	850	114	3	N	N