

the end of this report.

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1971	2	25,927
Campus Total			25,927

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Entrance Entrance Control - Audio and Video #1 - Main - E EΑ 7 1 6-10 years Exterior Doors - Exterior FRP Door #1 - Main - E 2 FΑ 6 6-10 years Exterior Doors - Transom Lite #1 - Main - E FΑ 7 6-10 years 1 Exterior Doors - Exterior Steel Door FΑ 7 10+ years #1.5 - N 1 Entrance Control - Audio and Video #2 - NW EΑ 7 6-10 years 1 Exterior Doors - Exterior Steel Door #2 - NW 2 FΑ 6 6-10 years Exterior Doors - Transom Lite #2 - NW 1 EΑ 6 6-10 years Exterior Doors - Exterior Steel Door #3 - SW 1 EΑ 5 2-5 years #3 - SW 12 1 F Ramps - Concrete 10+ years Foundation Foundation - Concrete **Entire Building** 553 LF 7 10+ years SF Superstructure - Steel **Entire Building** 25,917 7 10+ years \_Liahtina Exterior Lighting - Wall Mounted FΑ 7 **Entire Building** 9 6-10 years 2 Exterior Lighting - Wall Mounted **Entire Building** FΑ 6 6-10 years Roof System 7 Access Ladder - Metal Lower Roofs 1 FΑ 10+ years LF 7 Coping - Metal Lower Roofs 151 10+ years LF **Downspouts - Interior Downspouts** Lower Roofs 7 10+ years 18 Roof - Modified Bitumen Lower Roofs SF 7 2.826 10+ years



#### Countee Cullen Elementary School

XIII S	Schools					106	50 S Eberhart AVENUE, Chicago, IL 606
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	Lower Roofs	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Lower Roofs	2,826	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	455	LF . –	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	80	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	20	LF	4	0-1 year	Leak
	Roof - Modified Bitumen	Main Roof	11,438	SF	7	10+ years	Anti-un Inniu
	Roof - Modified Bitumen	Main Roof	100	SF	2	0-1 year	Active leak
	Roof Structure - Steel / Metal Deck/	Main Roof	11,538	SF	6	10+ years	
	Concrete Topping						
Valls							
	Exterior Walls - Brick	Entire Building	12,653	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	497	SF	7	10+ years	
	Wall						
Vindows							
	Curtain wall - Louver	Entire Building	360	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	32	SF	7	10+ years	
	Lintels - Stone	Entire Building	442	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	2,280	SF	7	10+ years	
	pane	·				•	
atego	ry : Electrical		В	uilding	: Main		
				- J		Recommend	
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	1st Floor	1	EA	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,144	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,758	SF	6	6-10 years	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
•	Automatic Transfer Switch	1st Floor	1	EA	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,144	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,758	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	896	SF	6	6-10 years	Staff toilets have no EM battery packs.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	7	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	7	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EΑ	7	6-10 years	
	Security System - CCTV	Entire Building	25,927	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	25,927	SF	5	6-10 years	

Campus Name: Cullen Page : 2 of 16 Assessment Date: 07/19/2023



ALL A						106	50 S Eberhart AVENUE, Chicago, IL 60628
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2000 A 120/208/3PH	1st Floor	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	25,927	SF	6	2-5 years	
Dower D	istribution						
_Powel_D		Fating Duilding	4			40	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Outdated
	Fire Alarm_System	Entire Building	25,027	SF	4	1-2 years	Outdated.
	The Alam_bystem	Entire Building	20,021	O.	7	1 Z years	Oddatod.
Catego	ry : Mechanical		В	uilding	: Main		
Group	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOW	Kalik	Replacement	Comments
_Air Hand	ling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	7	10+ years	RTU-1
_Heating_	Dovingo						
	PTAC - Electric Heating and Self Contained	1st Floor	1	EA	6	2-5 years	
	Cooling	13(1100)	'	EA	U	2-0 years	
	Fin Tube - Electric	2nd Floor	10	LF	5	1-2 years	Bent, missing cover.
	Wall Heater - Electric	Entire Building	15	EA	7	6-10 years	Bont, missing soven
	Wall Floater Elocato	Entire Ballating	10	_, .	,	o ro youro	
_Tempera	ture Control						
·	Thermostats - DDC	Entire Building	1	EA	4	0-1 year	RTU cool past set points.
		5				·	•
Unit Ven							
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self	Entire Building	20	EA	5	2-5 years	
	Contained Compressor Unit Ventilators- Floor Mounted- Electric	Entire Building	2	EA	4	1-2 years	Drain pan overflowing.

Campus Name: Cullen Page : 3 of 16 Assessment Date: 07/19/2023



chools					106	50 S Eberhart AVENUE, Chicago, IL 60628
y : Mechanical		В	uilding	: Main		
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating & DX Cooling Coil W/ Self Contained Compressor Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	1	EA	4	1-2 years	Leaking TXV valve.
n						
	Poof	3	ΕΛ	7	10+ years	
	Nooi	3	LA	,	10+ years	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	
no a Dhamabia a		<b>.</b>	: 1 - 1 :	. 84 - !		
y : Plumbing		В	ullaing	: wain	December	
Item - Type	Location	Quantity	ПОМ	Pank		Comments
	Location	Quantity	UOIVI	Naiik	Replacement	Comments
	1at Floor	2	ΕΛ		6.10 voore	In kitch on
Electric Heater - Less than 20 KW	1St Floor	2	EA	О	6-10 years	In kitchen
Demostic Dining Het Water Deturn Lines	Entire Duilding	25.027			10	
						Domestic water nining ricers and yent
Domestic Fiping-Hot Water Return Risers	Entire Building			O	10+ years	Domestic water piping risers and vent and drain lines in It readily visible as they are in walls and ceilings
Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	25,927	SF	6	10+ years	Horizontal lines not readily visible as concealed above ceilings.
Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	25,927	SF	6	10+ years	•
Sanitary Piping	Entire Building	25,927	SF	6	10+ years	Not readily visible to be able to take pictures as piping concealed in wall or ceiling.
Storm Piping	Entire Building	25,927	SF	6	10+ years	
Vent Piping	Entire Building	25,927	SF	6	10+ years	Piping not readily visible as piping is behind walls and at ceiling.
y : Room		В	uildina	: Main		
		_			Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rative Suites/Offices		•				
Ceiling - Lay-in	1st Floor	390	SF	7	10+ years	
Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	390	SF	6		
Lighting - Lay-in	1st Floor	4	ĒΑ	7	6-10 years	
Power Distribution	1st Floor	8	EA	7	10+ years	
	Item - Type Heating & DX Cooling Coil W/ Self Contained Compressor Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor  In Exhaust Fans- Roof Mounted - 1501 - 8000 CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM Item - Type If Electric Heater - Less than 20 KW  Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers  Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping  Storm Piping Vent Piping  Item - Type Interest Suites/Offices Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in	Item - Type	tem - Type	Part   Part	Name	Name



Catego	Category : Room			uilding	: Main	-	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	624	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	462	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	347	SF	7	6-10 years	
	Floor - Tile	1st Floor	115	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Power Distribution	1st Floor	10	EA	7	10+ years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	716	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	117	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	117	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Power Distribution	1st Floor	6	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	181	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	177	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	177	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Power Distribution	1st Floor	8	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	240	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Room 210, Office	390	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Room 210, Office	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor Room 210, Office	390	SF	4	0-1 year	Damaged throughout.
	Lighting - Lay-in	2nd Floor Room 210, Office	4	EA	7	6-10 years	
	Power Distribution	2nd Floor Room 210, Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Room 210, Office	604	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor Teachers Lounge next to girl's restroom	289	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Teachers Lounge next to girl's restroom	1	EA	7	6-10 years	
	Floor - Epoxy/ Painted	2nd Floor Teachers Lounge next to girl's restroom	289	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Teachers Lounge next to girl's restroom	3	EA	7	6-10 years	
	Power Distribution	2nd Floor Teachers Lounge next to girl's restroom	6	EA	6	6-10 years	
	Walls - Metal Panel	2nd Floor Teachers Lounge next to girl's restroom	709	SF	7	6-10 years	
	Ceiling - Lay-in	Counselor Office In Library	115	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor Office In Library	1	EA	6	10+ years	
	Floor - Tile	Counselor Office In Library	115	SF	6	10+ years	
	Lighting - Lay-in	Counselor Office In Library	2	ĒΑ	7	10+ years	
	Power Distribution	Counselor Office In Library	4	EA	7	10+ years	
		· ·				,	



Group	ry : Room			uilding			
Group						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Counselor Office In Library	280	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	357	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	347	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	1st Floor	5	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	138	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	414	SF	7	10+ years	
Library							
y	Ceiling - Lay-in	2nd Floor	975	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	975	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,511	SF	7	6-10 years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,758	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	2,758	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	ĒΑ	7	6-10 years	
	Serving Line	1st Floor	8	LF	7	10+ years	
	Storage/ Closet	1st Floor	361	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	4,413	SF	7	10+ years	
MDF IDI	=						
	Doors - Steel Doors incl hw	1st Floor next to girl's restroom	1	EA	7	10+ years	
	Finishes	1st Floor next to girl's restroom	95	SF	7	6-10 years	
	Window AC Unit	1st Floor next to girl's restroom	1	EA	7	6-10 years	Rank changed to match existing observations
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	180	SF	7	10+ years	
	Storage Room	1st Floor	138	SF	7	10+ years	
	Vaults	1st Floor	97	SF	7	10+ years	
	Janitor's Closet	2nd Floor	48	SF	5	0-1 year	Resurface the floor and ceiling tiles show minor cracking.
Restroon	1						



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor Boys	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boys	217	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	217	SF	7	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boys	1	EA	7	6-10 years	
	Lavatory	1st Floor Boys	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Boys	3	EA	7	6-10 years	
	Partitions	1st Floor Boys	2	EA	7	10+ years	
	Urinals	1st Floor Boys	2	EA	7	10+ years	
	Walls - Metal Panel	1st Floor Boys	420	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys	140	SF	7	10+ years	
	Water Closet	1st Floor Boys	2	ĒA	7	10+ years	
	Accessories	1st Floor Girls	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	217	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Girls	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	217	SF	7	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	6-10 years	
	Lavatory	1st Floor Girls	3	ĒΑ	7	10+ years	
	Lighting - Lay-in	1st Floor Girls	3	EΑ	7	6-10 years	
	Partitions	1st Floor Girls	4	EA	7	10+ years	
	Walls - Metal Panel	1st Floor Girls	420	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Girls	140	SF	7	10+ years	
	Water Closet	1st Floor Girls	4	EA	7	10+ years	
	Accessories	1st Floor In Main Office	48	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor In Main Office	48	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor In Main Office	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor In Main Office	48	SF	7	10+ years	
	Hand Dryer	1st Floor In Main Office	1	EA	7	6-10 years	
	Lavatory	1st Floor In Main Office	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor In Main Office	1	EΑ	7	6-10 years	
	Walls - Metal Panel	1st Floor In Main Office	48	SF	7	10+ years	
	Water Closet	1st Floor In Main Office	1	EA	7	10+ years	
	Accessories	1st Floor Unisex	31	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Unisex	31	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Unisex	1	EA	7	10+ years	
	Floor - Wood	1st Floor Unisex	31	SF	7	10+ years	
	Hand Dryer	1st Floor Unisex	1	EA	7	6-10 years	
	Lavatory	1st Floor Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Unisex	98	SF	7	10+ years	
	Water Closet	1st Floor Unisex	1	EA	7	10+ years	
	Accessories	1st Floor onisex  1st Floor inside Kindergarten #101	28	SF	7	6-10 years	
	70069901169	13t 1 1001 III3lue Milluelyaiteil #101	20	3F	,	U-10 years	



Catego	Category : Room			uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor inside Kindergarten #101	28	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor inside Kindergarten #101	1	EA	7	10+ years	
	Floor - Tile	1st Floor inside Kindergarten #101	28	SF	7	10+ years	
	Hand Dryer	1st Floor inside Kindergarten #101	1	EA	7	6-10 years	
	Lavatory	1st Floor inside Kindergarten #101	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor inside Kindergarten #101	1	EA	7	6-10 years	
	Walls - Metal Panel	1st Floor inside Kindergarten #101	90	SF	7	10+ years	
	Water Closet	1st Floor inside Kindergarten #101	1	EA	7	10+ years	
	Accessories	2nd Floor Boys	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	217	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Boys	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	217	SF	6	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Boys	1	EA	7	2-5 years	
	Lavatory	2nd Floor Boys	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor Boys	3	EA	6	6-10 years	
	Partitions	2nd Floor Boys	2	EA	7	2-5 years	
	Urinals	2nd Floor Boys	1	EA	6	6-10 years	
	Walls - Metal Panel	2nd Floor Boys	420	SF	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Boys	140	SF	6	10+ years	
	Water Closet	2nd Floor Boys	2	EA	6	6-10 years	
	Accessories	2nd Floor Girls	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	217	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Girls	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	217	SF	7	10+ years	
	Floor Drain	2nd Floor Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girls	1	EA	7	2-5 years	
	Lavatory	2nd Floor Girls	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor Girls	3	EA	6	6-10 years	
	Partitions	2nd Floor Girls	4	EA	7	10+ years	
	Walls - Metal Panel	2nd Floor Girls	420	SF	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls	140	SF	7	10+ years	
	Water Closet	2nd Floor Girls	4	ĒΑ	6	6-10 years	
	Accessories	2nd Floor Unisex East	20	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Unisex East	20	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Unisex East	1	ĒΑ	7	6-10 years	
	Floor - Wood	2nd Floor Unisex East	20	SF	7	6-10 years	
	Hand Dryer	2nd Floor Unisex East	1	ĒΑ	7	2-5 years	
	Lavatory	2nd Floor Unisex East	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Unisex East	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Unisex East	62	SF	6	10+ years	
	Water Closet	2nd Floor Unisex East	1	EA	6	6-10 years	
	Accessories	2nd Floor Unisex West	20	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Unisex West	20	SF	6	6-10 years	
		a i looi oillook (1700)	20	٥.	·	3 10 ,00.0	



Catego	ory : Room		В	uilding	: Main		30 0 Ebernart Avenoe, Gridago, ie 00020
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	2nd Floor Unisex West	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor Unisex West	20	SF	7	6-10 years	
	Hand Dryer	2nd Floor Unisex West	1	EA	7	2-5 years	
	Lavatory	2nd Floor Unisex West	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Unisex West	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Unisex West	62	SF	7	10+ years	
	Water Closet	2nd Floor Unisex West	1	ĒΑ	6	6-10 years	
Catego	ory : Classroom		В	uilding	: Main		
	<del>.</del>	1	0	11014	<b>.</b>	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classro	om #101 (Kindergarten)	A	0.5			40	
	Casework	1st Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,080	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,080	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	1,674	SF	7	10+ years	
Classro	om #102 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	745	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	1,155	SF	7	10+ years	
_Classro	om #103 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	725	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	725	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Metal Panel	1st Floor	863	SF	7	10+ years	
Classro	om #104 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	745	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Steel Doors little IIW	151 11001	'	EA	,	10+ years	



	ry : Classroom		Б	uilding	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	Rank changed to match current observation
	Walls - Metal Panel	1st Floor	837	SF	7	10+ years	0.000.140.1
	Walls - Plaster/Drywall	1st Floor	279	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	717	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	3.
	Floor - Tile	1st Floor	725	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Metal Panel	1st Floor	863	SF	7	10+ years	
Classror	om #106 (Office)						
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	745	SF	7	10+ years	
	Chalk Board	1st Floor	303	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	745	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	10+ years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	837	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	279	SF	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	725	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	725	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	1st Floor	647	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	216	SF	7	10+ years	
Classroo	om #201 (Science)						
	Casework	2nd Floor	8	LF	6	6-10 years	

Campus Name: Cullen Page : 10 of 16 Assessment Date: 07/19/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	3
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	867	SF	6	6-10 years	
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor		EA	7	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor	1 900	SF	7		
					7 7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA		6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,395	SF	7	6-10 years	
lassroc	m #203 (Other Instructional Use)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Missing tiles
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	S .
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	867	SF	7	6-10 years	
Classroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	745	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	•	
				SF		6-10 years	
	Storage/ Closet	2nd Floor	12		7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,155	SF	7	6-10 years	
lassroc	m #205 (Regular Classroom)						
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	6-10 years	
	Floor - Tile	2nd Floor	725	SF	7	6-10 years	



Category : Classroom		В	uilding	: Main	10030 O ESCHIAIT AVENUE, Onicago, il 00020			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years		
	Marker Board	2nd Floor	18	LF	6	6-10 years		
	Walls - Metal Panel	2nd Floor	858	SF	7	6-10 years		
Classroo	om #206 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile	2nd Floor	740	SF	6	6-10 years		
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Bamagoa	
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years		
	Walls - Metal Panel	2nd Floor	1,145	SF	7	6-10 years		
Classros	om #207 (Science)							
Classion	Casework	2nd Floor	8	LF	6	6.10 vooro		
				SF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	725		7	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile	2nd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	18	LF	6	6-10 years		
	Walls - Metal Panel	2nd Floor	858	SF	7	6-10 years		
Classroo	m #208 (Other Instructional Use)							
	Casework	2nd Floor	6	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile	2nd Floor	745	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	12	SF	5	6-10 years		
	Walls - Metal Panel	2nd Floor	1,145	SF	7	6-10 years		
_Classroo	om #209 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile	2nd Floor	720	SF	7	6-10 years		
	Floor - Tile	2nd Floor	5	SF	4	0-1 year	Damaged	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Walls - Metal Panel	2nd Floor	647	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	216	SF	7	6-10 years		
	Trails Tradition Bry Wall	2110 1 1001	210	J1	•	o io years		



Category : Classroom			В	uilding	: Main		50 S Ebernari AVENDE, Chicago, IL 60626
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0-1	. Intolon		ъ	!! .!!			
Categor	y : Interior		В	Building : Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Corridor	item - Type	Location	Quantity	OCIVI	Italik	Replacement	Comments
Comaoi	Ceiling - Lay-in	1st Floor	1,642	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	1,042	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,642	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	ĒΑ	7	6-10 years	
	Walls - Metal Panel	1st Floor	3,033	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,348	SF	6	6-10 years	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EA	7	2-5 years	
	Floor - Tile/Sheet	2nd Floor	1,348	SF	7	2-5 years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	2,844	SF	7	6-10 years	
_Safetv							
Calety	Camera Viewing Station	Entire Building	4	EA	7	6-10 years	
	Metal Detector	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	5	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
	·	-				-	
_Stairs	- · · · · ·						
	Ceiling - Lay-in	East	136	SF	7	6-10 years	
	Floor - Tile	East	60	SF	5	2-5 years	
	Handrails	East	64 1	LF	7	2-5 years	
	Lighting - Lay-in Stairs - Concrete	East	30	EA LF	7 7	6-10 years	
	Walls - Metal Panel	East East	260	SF	7	6-10 years 6-10 years	
	Ceiling - Lay-in	West	136	SF	6	6-10 years	
	Floor - Tile	West	60	SF	5	2-5 years	
	Handrails	West	64	LF	7	2-5 years	
	Lighting - Lay-in	West	1	EA	6	6-10 years	
	Stairs - Concrete	West	30	LF	6	6-10 years	
	Walls - Metal Panel	West	260	SF	6	6-10 years	



Category : Site		В					
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Athletic							
	Surface - Asphalt	West	2,575	SF	6	6-10 years	
_Civil/Dra	•						
	Civil/ Drainage - Catch Basin	North	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	North	1	EA	6	10+ years	
<b>-</b>							
_Fencing		F :: 0::	700			0.40	
	Fencing - New Standard Ornamental	Entire Site	738	LF	6	6-10 years	Oata dama wad
	Fencing - New Standard Ornamental	Entire Site	10	LF	4	0-1 year	Gate damaged
Landsca	pe						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	1,444	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,296	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	1,135	SF	6	6-10 years	
	Parkway trees	Entire Site	13	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Dead tree
	Planting Beds/ Area	Entire Site	175	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	5,000	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	3,000	SF	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	7	6-10 years	
	Trash Receptacles	Entire Site	2	EA	6	2-5 years	
5							
_Parking_		NI	0.000			40	
	Surface - Asphalt	North	2,000	SF	6	10+ years	
	Surface - Concrete	North	2,200	SF SF	7	10+ years	
	Trash Enclosure - Chain Links	North	100	5F	7	10+ years	
_Playgrou	und						
, ,	Equipment - Combo 3-12	West	1	EA	7	10+ years	
	Surface - Square Rubber Mats	West	2,285	SF	7	10+ years	
O: "	-						
_Sidewall		Frating Cit -		1 -		0.40	
	Sidewalks - Internal Walks	Entire Site	8	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	3,527	SF	6	6-10 years	Draken wasyen
	Sidewalks - Perimeter Sidewalks	Entire Site	400	SF	4	0-1 year	Broken, uneven
Signage							
_ <del></del> 990	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years	
						,	



#### **Countee Cullen Elementary School**

10650 S Eberhart AVENUE, Chicago, IL 60628

Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EΑ	6	2-5 years	
	Monument - Building Mounted Cut Letter	Entire Site	2	EΑ	4	0-1 year	Rusting.
	Sign						

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Cullen Page : 15 of 16 Assessment Date: 07/19/2023

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

Compant Hanna	Intended Heave	Boom Location	Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		1	101						
Computer Lab	Regular Classroom	1st Floor	104	NA	745	94	33	N	Y
Kindergarten	Kindergarten	1st Floor	101	NA	1,080	151	54	N	Υ
Office	Regular Classroom	1st Floor	106	106	745	94	33	N	Υ
Other Instructional Use	Regular Classroom	2nd Floor	203	203	725	94	33	N	N
Other Instructional Use	Regular Classroom	2nd Floor	208	208	745	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	745	94	33	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	725	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	725	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	725	94	33	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	900	94	33	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	745	94	33	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	725	94	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	745	94	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	725	94	33	N	N
Science	Regular Classroom	2nd Floor	201	201	725	94	33	N	Υ
Science	Regular Classroom	2nd Floor	207	207	725	94	33	N	Υ