



7030 N Sacramento AVENUE, Chicago, IL 60645

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1958	1	23,834
Annex	2020	1	18,600
Campus Total			42,434

Category : Exterior Building : Main

Catego	Ty . Exterior	0	unung				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Entrance Control - Audio and Video	#1 - Main - NE	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 - Main - NE	2	EA	6	10+ years	
	Exterior Doors - Side lite	#1 - Main - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - NE	3	EA	6	10+ years	
	Power Door Operator and Controls	#1 - Main - NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 - N	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#10 - N	1	EA	6	10+ years	Quantity changed to match current observations
	Exterior Doors - Exterior FRP Door	#11	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#12	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#12	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#12	5	LF	5	1-2 years	Cracking
	Entrance Control - Audio and Video	#13	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#13	2	EA	6	10+ years	
	Exterior Doors - Side lite	#13	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#13	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#13	10	LF	5	1-2 years	Cracking
	Exterior Doors - Exterior FRP Door	#14-Boiler	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#14-Boiler	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#14-Boiler	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#15	1	EA	6	10+ years	Added to match current observations
	Exterior Doors - Transom Lite	#15	2	EΑ	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main			
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exterior Doors - Exterior FRP Door	#16	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#16	3	LF	5	2-5 years		
	Exterior Doors - Exterior FRP Door	#17 Courtyard	1	EA	6	10+ years		
	Exterior Doors - Exterior FRP Door	#18 Courtyard	1	EA	6	6-10 years		
	Exterior Doors - Transom Lite	#18 Courtyard	1	EA	6	10+ years		
	Exterior Stairs - Concrete	#18 Courtyard	3	LF	6	10+ years		
	Exterior Doors - Exterior FRP Door	#2 - SE	1	EA	6	10+ years		
	Exterior Doors - Transom Lite	#2 - SE	1	EA	6	10+ years		
	Exterior Doors - Exterior FRP Door	#3 - SE	1	EA	6	10+ years		
	Exterior Doors - Transom Lite	#3 - SE	1	EA	6	10+ years		
	Ramps - Concrete	#3 - SE	35	LF	7	10+ years		
_Foundati	on							
	Foundation - Concrete	Entire Building	1,065	LF	7	10+ years		
	Foundation - Concrete	Entire Building	5	LF	5	0-1 year	Cracking/leaking water	
	Foundation - Concrete	Entire Building	100	LF	5	0-1 year	Exposed reinforcement. Quantity	
		, and the second				•	changed to match current observations	
	Superstructure - Concrete	Entire Building	23,829	SF	7	10+ years	Corrected quantity	
Lighting								
Lighting	Exterior Lighting - Wall Mounted	Entire Building	33	EA	7	10+ years	New lightings	
Roof Sys	stem							
	Chimney - Metal Flue	Main Roof	14	LF	7	10+ years	Added to match current observations	
	Coping - Metal	Main Roof	8	LF	6	10+ years	, 14404 10 11141011 04110111 02001 14110110	
	Coping - Metal	Main Roof	843	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	13	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	6	LF	6	10+ years		
	Downspouts - Interior Downspouts	Main Roof	52	LF	6	10+ years		
	Roof - Modified Bitumen	Main Roof	21,587	SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	Main Roof	21,587	SF	6	10+ years		
	Concrete Topping		_ :,00:	•	•	.o. you.o		
	Coping - Metal	NE roof	185	LF	6	10+ years		
	Downspouts - Exterior Downspouts	NE roof	30	LF	6	10+ years		
	Roof - Modified Bitumen	NE roof	1,952	SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	NE roof	1,952	SF	7	10+ years		
	Concrete Topping	142 1001	1,002	O.	,	101 youro		
Walls								
	Canopy - Concrete/ Stucco	Entire Building	80	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	7,269	SF	6	10+ years		
	Exterior Walls Brick		.,	SF	•	io. you.o		

Campus Name: Decatur Page : 2 of 25 Assessment Date: 11/28/2023



Category : Exterior

# Stephen Decatur Classical Elementary School 7030 N Sacramento AVENUE, Chicago, IL 60645

Recommend

**Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Windows							
	Curtain wall - Windows	Entire Building	3,733	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,220	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	10	SF	4	0-1 year	Broken/falling
	Lintels - Steel	Entire Building	9	LF	6	10+ years	
	Windows - Insulated Panel	Entire Building	1,236	SF	6	10+ years	
	Windows - Louver	Entire Building	156	SF	6	10+ years	
	Windows - Louver	Entire Building	12	SF	5	1-2 years	Rusted
Catego	ry : Electrical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Emergency Battery Packs - Corridors and Stairs	1st Floor	7	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	1st Floor	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	7	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	1st Floor	2	EA	6	6-10 years	Exit signs are in existence
	Automatic Transfer Switch	Boiler Room	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,330	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,473	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	561	SF	6	6-10 years	
	Security System - CCTV	Entire Building	23,834	SF	7	10+ years	
	Security System - Intrusion Detection	Entire Building	23,834	SF	6	6-10 years	
Main Se	rvice						
	PA System	1st Floor	23,834	SF	6	6-10 years	
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	6-10 years	
	Main Electrical Service - 800 A and 120/208/3PH	Boiler Room	1	EA	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	1st floor and Boiler Room	1	EA	6	6-10 years	Per engineer, and upon observation, only 1 100A in boiler room
	Lighting and Power Panels - 100 A	1st floor and Boiler Room	3	EA	6	6-10 years	•
	Lighting and Power Panels - Above 100 A	1st floor and Boiler Room	5	EA	6	6-10 years	Per engineer, and upon observation, 5 electrical panels over 100A
Compus	Name: Decatur	Dogo	: 3 of 25				Assessment Date: 11/28/202

Campus Name: Decatur Page: 3 of 25 Assessment Date: 11/28/2023



Catago			ח	uildine	. Main	70001	N Sacramento Avenue, Chicago, il 60645
Catego	ry : Electrical		В	uilding	. wain	December 21	
0	Itama Tuma	Laatian	Overet!tee	LION	Dawl	Recommend	Comments
Group	Item - Type  Main Distribution Danala Creater than 600	Location 1st floor and Boiler Room	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - Greater than 600 amp	1st floor and Boller Room	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Boiler Room	1	EA	6	6-10 years	Main and annex connected
	Fire Alarm Panel	Boiler Room	1	EA	6	6-10 years	Annunciator Panel
	Fire Alarm Strobe Lights	Boiler Room	23,834	SF	6	6-10 years	
	Fire Alarm_System	Boiler Room	23,834	SF	6	6-10 years	
	·					·	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
	than 5 tons	11001	•	L/ \	O	o to years	
	than 5 tons						
Dailar C							
Boiler Sy		D :				0.40	A 11: 1
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	6-10 years	Auxiliaries appear to be in good
	Pressure Boiler - 50 - 75 HP	D :		_ ^	•	0.40	condition upon visual observation
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	Combustion dampers appeared to be
							in good condition. Normal
					_		maintenance required.
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Pumps in good condition, however,
					_		rusty piping
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Pumps in good condition, however,
							rusty piping
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	Tank in good condition, pumps are
							working. Piping rusty.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	Tank in good condition, pumps are
							working. Piping rusty.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	Tank in good condition, pumps are
							working. Piping rusty.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	Tank in good condition, pumps are
							working. Piping rusty.
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	Boiler appears to be in good condition
	Steam- Low Pressure Boiler - 50 - 75 HP						
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	Boiler appears to be in good condition
	Steam- Low Pressure Boiler - 50 - 75 HP						

Campus Name: Decatur Page : 4 of 25 Assessment Date: 11/28/2023



XII A S	chools					7030 N	N Sacramento AVENUE, Chicago, IL 60645
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Boiler Room	250	LF	2	0-1 year	Rusty pipes. Leaking.
	Steam Traps	Boiler Room	3	EA	5	0-1 year	Steam traps under floor, leaking, per building engineer
Heating [	Devices						
	Fin Tube - Steam	1st Floor	84	LF	6	6-10 years	Units appear to be in good condition
	Cabinet Heaters - With Steam Coil	1st Floor	5	EA	6	6-10 years	Cabinet heaters in good condition, per engineer and observation
	Unit Heater - Steam	Boiler Room	1	EA	6	6-10 years	
Mechanio	cal Plumbing						
	Condensate-Steel or Galvanized	Entire Building	250	LF	2	1-2 years	Piping rusty
Tempera	ture Control						
	Pneumatic System	Entire Building	23,834	SF	5	1-2 years	System in fair condition. In need of upgrade and near future.
	Thermostats - Pneumatic	Entire Building	22	EA	5	1-2 years	Thermostats leak air. Some work, some don't can't properly control temperature.
Unit Vent	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	18	EA	5	2-5 years	Motor bearings slipping, actuators, not opening and closing properly
Ventilatio	an .						
Vermane	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Exhaust fans in good working condition
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Exhaust fans in good working condition
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	12	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
3	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	2						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
, 5	Domestic Piping-Hot Water Return Lines	Entire Building	23,834	SF	7	10+ years	Pipes appear to be in good condition. Possibly newly replaced.

Campus Name: Decatur Page : 5 of 25 Assessment Date: 11/28/2023



Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

Floor - Tile

Power Distribution

Walls - Concrete Block

Walls - Concrete Block

Storage/ Closet

Walls - Masonry

#### **Stephen Decatur Classical Elementary School**

7030 N Sacramento AVENUE, Chicago, IL 60645

Catego	Category : Plumbing			uilding	: Main			
	1					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	(Horizontal Lines)		•			•	Possibly newly replaced.	
	Sanitary Piping	Entire Building	23,834	SF	6	6-10 years	Appear to be a good condition	
	Storm Piping	Entire Building	23,834	SF	5	6-10 years	-	
	Vent Piping	Entire Building	23,834	SF	5	6-10 years		
Catego	ry : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Adminis	trative Suites/Offices							
	Ceiling - Plaster/Drywall	113 Counselor Office	220	SF	7	10+ years		
	Doors - Wood Doors inclu hw	113 Counselor Office	2	EA	7	10+ years		
	Floor - Carpet	113 Counselor Office	180	SF	5	2-5 years		
	Floor - Tile	113 Counselor Office	40	SF	6	6-10 years		
	Lighting - Pendent/Surface	113 Counselor Office	4	EΑ	7	6-10 years		
	Power Distribution	113 Counselor Office	4	EΑ	7	10+ years		
	Walls - Concrete Block	113 Counselor Office	440	SF	7	10+ years		
	AC Unit	Engineer's Office	1	EA	5	1-2 years	Unit not functioning	
	Ceiling - Plaster/Drywall	Engineer's Office	313	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Engineer's Office	5	SF	5	10+ years	Water damage	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years		
	Floor - Concrete	Engineer's Office	318	SF	7	10+ years		
	Lighting - Pendent/Surface	Engineer's Office	3	EA	7	6-10 years	Lights in good condition	
	Power Distribution	Engineer's Office	4	EA	6	6-10 years		
	Walls - Concrete Block	Engineer's Office	330	SF	6	10+ years		
	Walls - Masonry	Engineer's Office	320	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Main Office	260	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years		
	Floor - Tile	Main Office	260	SF	7	10+ years		
	Lighting - Pendent/Surface	Main Office	8	EA	7	6-10 years		
	Power Distribution	Main Office	6	EA	7	10+ years		
	Walls - Concrete Block	Main Office	250	SF	7	10+ years		
	Walls - Masonry	Main Office	70	SF	7	10+ years		
	AC Unit	Principal office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Principal office	395	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Principal office	5	SF	5	10+ years	Water damage	
	Doors Wood Doors included	Dringing office	4	_ ∧	7	10		

Campus Name: Decatur Page: 6 of 25 Assessment Date: 11/28/2023

7

6

7

7

7

7

5

7

1

6

8

30

670

10

100

400

EΑ

SF

EΑ

EΑ

SF

SF

SF

SF

10+ years

6-10 years

6-10 years

10+ years

10+ years

10+ years

1-2 years

10+ years

Crack along material change

Principal office



Category: Room		В	Building : Main				
	И Т	l anatinu	0	11014	D	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
IDF_ID							
	Doors - Steel Doors incl hw	In Music Room	1	EA	6	10+ years	
	Finishes	In Music Room	94	SF	5	2-5 years	<b>5</b>
	Other Cooling Unit	In Music Room	1	EA	7	6-10 years	Ductless split
echani	cal/ Service Rooms						
	Boiler Room	1st Floor	856	SF	7	10+ years	
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Storage Room	1st Floor	70	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	21,050	SF	7	10+ years	
estroor	n						
	Accessories	1st Floor	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	256	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	10+ years	crack
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	266	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	2	EA	5	2-5 years	
	Urinals	1st Floor	4	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	400	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	8	SF	5	10+ years	Damaged
	Water Closet	1st Floor	2	EA	7	6-10 years	
	Accessories	1st Floor	262	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	257	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5	SF	5	10+ years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	262	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	6-10 years	Qty 2 observed
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	398	SF	7	10+ years	
	Water Closet	1st Floor	6	EA	7	6-10 years	
	Accessories	1st floor inside principal office	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside principal office	37	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside principal office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside principal office	37	SF	6	10+ years	
	Lavatory	1st floor inside principal office	1	EA	7	6-10 years	Good condition
	Lighting - Pendent/Surface	1st floor inside principal office	1	EA	5	2-5 years	Missing cover
	Walls - Concrete Block	1st floor inside principal office	195	SF	6	10+ years	



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	1st floor inside principal office	1	EA	7	6-10 years	Good condition		
	Accessories	In Classroom 112	24	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In Classroom 112	24	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Classroom 112	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Classroom 112	24	SF	6	10+ years			
	Lavatory	In Classroom 112	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	In Classroom 112	1	EA	7	6-10 years			
	Walls - Concrete Block	In Classroom 112	174	SF	6	10+ years			
	Water Closet	In Classroom 112	1	EA	7	6-10 years	Good condition		
	Accessories	In Kindegarten Room 100	33	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In Kindegarten Room 100	33	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In Kindegarten Room 100	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Kindegarten Room 100	33	SF	6	10+ years			
	Lavatory	In Kindegarten Room 100	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	In Kindegarten Room 100	1	EA	7	10+ years			
	Walls - Concrete Block	In Kindegarten Room 100	185	SF	7	10+ years			
	Water Closet	In Kindegarten Room 100	1	EA	7	6-10 years			
	Accessories	In Music room	37	SF	7	6-10 years	Good condition		
	Ceiling - Plaster/Drywall	In Music room	37	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In Music room	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	In Music room	37	SF	6	6-10 years			
	Lavatory	In Music room	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	In Music room	1	EA	7	2-5 years			
	Walls - Concrete Block	In Music room	190	SF	6	10+ years			
	Walls - Concrete Block	In Music room	5	SF	5	1-2 years	Cracks in masonry		
	Water Closet	In Music room	1	EA	7	10+ years	Good condition		
	Accessories	In the boiler room	54	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In the boiler room	54	SF	6	10+ years			
	Doors - Wood Doors inclu hw	In the boiler room	2	EA	6	10+ years			
	Floor - Concrete	In the boiler room	54	SF	5	2-5 years			
	Lavatory	In the boiler room	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	In the boiler room	1	EA	7	6-10 years			
	Walls - Concrete Block	In the boiler room	225	SF	6	10+ years			
	Water Closet	In the boiler room	1	EA	7	6-10 years			
	Accessories	Inside dance room 101	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Inside dance room 101	45	SF	6	10+ years	Paint cracking		
	Doors - Wood Doors inclu hw	Inside dance room 101	1	EA	6	2-5 years			
	Floor - Tile Ceramic/ Porcelain	Inside dance room 101	45	SF	7	10+ years			
	Lavatory	Inside dance room 101	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	Inside dance room 101	1	EA	7	10+ years			
	Walls - Concrete Block	Inside dance room 101	150	SF	7	10+ years			
	Walls - Masonry	Inside dance room 101	50	SF	7	10+ years			
	Water Closet	Inside dance room 101	1	EA	7	6-10 years			
						•			



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #100 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	32	LF	7	6-10 years	
	Ceiling - Splined	1st Floor	1,214	SF	7	10+ years	
	Ceiling - Splined	1st Floor	10	SF	5	1-2 years	Missing tile and damaged
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,204	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Chipped and cracked
	Lighting - Pendent/Surface	1st Floor	28	EA	7	10+ years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	160	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,897	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #101 (Dance Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	1,294	SF	6	10+ years	
	Ceiling - Splined	1st Floor	5	SF	5	2-5 years	Finish damage
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	ŭ
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,304	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Wall Mirrors	1st Floor	400	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	160	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,630	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years	
Classroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	6-10 years	
	Ceiling - Splined	1st Floor	839	SF	7	10+ years	
	Ceiling - Splined	1st Floor	20	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	rect providuoly accepted
	Floor - Tile	1st Floor	839	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Cracks
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	<b>C.33</b>
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,331	SF	7	10+ years	
	Work Sink	1st Floor	1,001	EA	7	6-10 years	
			·		-	, <b>,</b>	



Catego	y : Classroom		В	uilding	: Main		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	850	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	840	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	882	SF	6	10+ years	
lassroo	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	859	SF	7	10+ years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	Not previously assessed
	Floor - Tile	1st Floor	839	SF	6	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Cracks
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	Clacks
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	24	SF	5	10+ years	Broken door handle
	Walls - Concrete Block	1st Floor	1,331	SF	7	10+ years	Biokeii dooi fiandie
	#405 (D Ol )						
lassroo	m #105 (Regular Classroom)	=				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	846	SF	6	10+ years	
	Ceiling - Splined	1st Floor	4	SF	4	1-2 years	Broken tile
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	882	SF	6	10+ years	
assroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	6-10 years	
	Ceiling - Splined	1st Floor	859	SF	7	10+ years	
	₩ - F - F - F	1st Floor	300	SF	-	- <i>j</i>	

Campus Name: Decatur Page : 10 of 25 Assessment Date: 11/28/2023



		Building : Main				•		
					Recommend			
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		1		7				
Floor - Tile	1st Floor	854		7	10+ years			
Floor - Tile	1st Floor	5	SF	5	1-2 years	Missing tile		
Lighting - Pendent/Surface	1st Floor	18	EA	7		ŭ		
• •			LF					
			SF					
Walls - Concrete Block	1st Floor	1,331	SF	7	10+ years			
m #107 (Regular Classroom)								
	1st Floor	1	FA	7	6-10 years			
					•			
					,			
		· · · · · · · · · · · · · · · · · · ·		-	•			
Walls - Concrete Block	1st Floor	882	SF	6	10+ years			
m #108 (Regular Classroom)								
	1st Floor	2	FΔ	7	6-10 years	Good condition		
			SF			Good Corrainers		
					•	Water damage		
					,	water damage		
				-				
					-	0		
						Cracks		
						Good condition		
						Good condition		
		1,331			10+ years			
Wireless System	1st Floor	1	EA	7	6-10 years			
m #109 (Regular Classroom)								
AC Units	1st Floor	1	EA	7	10+ years			
Casework	1st Floor	8	LF		6-10 years			
		-						
					•			
• •					•			
Marker Board	1St Floor	22	LF	ь	o-10 years			
	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block  m #107 (Regular Classroom)  AC Units Casework Ceiling - Splined Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block  m #108 (Regular Classroom)  AC Units Ceiling - Splined Ceiling - Splined Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block Wireless System	Doors - Wood Doors inclu hw   1st Floor   Floor - Tile   1st Floor   Floor - Tile   1st Floor   Storage   Closet   1st Floor   Ceiling - Splined   1st Floor   Storage   Closet   1st Floor   Ceiling - Splined   1st Floor   Ceiling - Splined   1st Floor   Ceiling - Splined   1st Floor   Storage   Closet   1st Floor   Ceiling - Splined   1st Floor   Ceiling - Splined   1st Floor   Ceiling - Splined   1st Floor   Storage   Closet   1st Floor   Ceiling - Pendent/Surface   1st Floor   Floor - Tile   1st Floor   Storage   Closet   1st Floor   Casework   1st Floor   Casework   1st Floor   Casework   1st Floor   Casework   1st Floor   Caling - Splined   1st Floor   Caling - Spline	Doors - Wood Doors inclu hw					



Catego	ry : Classroom		В	uilding	: Main		V Sacramento AVENOE, Omeago, le 0004
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	20	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	882	SF	6	10+ years	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	849	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	10	SF	4	1-2 years	Water damage
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	849	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Missing tile
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	Good condition
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	10+ years	Good condition
	Walls - Concrete Block	1st Floor	1,331	SF	6	10+ years	
Classroo	m #111 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	74	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	850	SF	7	6-10 years	
	Doors - Side-lite	1st Floor	32	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	The provided by the control of the c
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	882	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	5	6-10 years	
Classroo	m #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Splined	1st Floor	764	SF	7	10+ years	
	Ceiling - Splined	1st Floor	2	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	766	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	541	SF	7	10+ years	
	Walls - Masonry	1st Floor	270	SF	7	10+ years	
Classroo	m #114 (Music Room)					·	

Campus Name: Decatur Page : 12 of 25 Assessment Date: 11/28/2023



Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,473	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,473	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	12	EΑ	7	6-10 years	Good condition
	Sound Panels	1st Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	650	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,841	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	

Category : Interior **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	3,306	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	24	SF	5	10+ years	Water damage
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	-
	Drinking Fountains - Single Fountain	1st Floor	5	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,300	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Cracks
	Lighting - Lay-in	1st Floor	40	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	180	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	3,840	SF	6	10+ years	
	Walls - Masonry	1st Floor	1,280	SF	6	10+ years	
_Safety_							
•	Security Cameras	1st Floor	7	EA	7	10+ years	

Campus Name: Decatur Page : 13 of 25 Assessment Date: 11/28/2023







Category : Exterior **Building: Annex** 

ategor	y . Exterior			unanig		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance	item Type	Location	Quantity	OOM	Italik	Replacement	Comments
папсе	Exterior Doors - Store Front	4	3	EA	7	10+ years	
	Exterior Doors - Store Front  Exterior Doors - Transom Lite	4	3	EA	7	10+ years	
	Entrance Control - Audio and Video	5	1	EA	7	6-10 years	
	Exterior Doors - Side lite	5	4	EA	7	10+ years	
	Exterior Doors - Store Front	5	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	5	3	EA	7	10+ years	
	Power Door Operator and Controls	5	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	6	2	EA	7	10+ years	
	Exterior Stairs - Concrete	6	7	LF	7	10+ years	Added to match current observations
	Entrance Control - Audio and Video	7	1	EA	7	6-10 years	Added to match current observations
	Exterior Doors - Exterior Steel Door	7	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	8	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	8	1	EA	7	10+ years	
	Exterior Doors - Store Front	9	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	9	3	EA	7	10+ years	
	Exterior Boors Transom Elec	3	J	_/\	,	101 years	
undatio							
	Foundation - Concrete	Entire Building	1,100	LF	7	10+ years	
	Superstructure - Steel	Entire Building	18,600	SF	7	10+ years	
ahting							
grining	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
of Syst	em						
	Access Ladder - Metal	Lower Roofs	1	EA	7	10+ years	
	Chimney - Metal Flue	Lower Roofs	28	LF	7	10+ years	Added to match current observations
	Coping - Metal	Lower Roofs	1,000	LF	7	10+ years	
	Downspouts - Interior Downspouts	Lower Roofs	135	LF	6	10+ years	
	Parapet - 16" - 30" Height	Lower Roofs	1,000	LF	7	10+ years	
	Roof - Modified Bitumen	Lower Roofs	14,000	SF	6	10+ years	
	Roof Hatch - Metal	Lower Roofs	1	ĒΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Lower Roofs	14,000	SF	7	10+ years	
	Concrete Topping		,			, , , , ,	
	Access Ladder - Metal	Upper Roof	1	EΑ	7	10+ years	
	Coping - Metal	Upper Roof	393	LF	7	10+ years	
	Downspouts - Interior Downspouts	Upper Roof	90	LF	6	10+ years	
	Parapet - Parapet > 30"	Upper Roof	393	LF	7	10+ years	Changed to match current
						·	observations
	Roof - Modified Bitumen	Upper Roof	4,600	SF	7	10+ years	
				0.5	-	40	
	Roof Structure - Steel / Metal Deck/	Upper Roof	4,600	SF	7	10+ years	

Campus Name: Decatur Page : 14 of 25 Assessment Date: 11/28/2023



Catego	ry : Exterior		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls							
	Exterior Walls - Brick	Entire Building	13,819	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	500	SF	7	10+ years	
Windows							
	Lintels - Steel	Entire Building	204	LF	7	10+ years	
	Storefront Windows	Entire Building	1,412	SF	7	10+ years	
Catego	ry : Electrical		В	uildina	: Annex		
Julego	ry . Electrical			anding	. Aiiiica	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System		•			_	
<b>U</b>	Emergency Battery Packs - Corridors and	1st Floor	8	EA	7	10+ years	
	Stairs						
	Emergency Battery Packs - Gym	1st Floor	8	EA	7	10+ years	
	Emergency Battery Packs - Students Toilets	1st Floor	8	EΑ	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	7	10+ years	
	Exit Signs - Gym	Entire Building	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	18,600	SF	7	10+ years	
	Security System - Intrusion Detection	Entire Building	18,600	SF	7	10+ years	
Main Se	n doo						
Maili Se	Main Electrical Service - 1000 A	Electrical Room	1	EA	7	10+ years	
	277/480/3PH	Liectifical Room	'	LA	,	10+ years	
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power	Liectifical Room	'	LA	'	10+ years	
	PA System	Entire Building	19.600	SF	7	10	
	PA System	Entire building	18,600	SF	,	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Electrical Room	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	3	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Electrical Room	1	EΑ	7	10+ years	
	amp	Liounda Noom	•		•	ioi youis	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	10+ years	
Catoro	ry : Fire Protection		D	uildina	: Annex		
Jaiego			B	anding	. AIIIIEX	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	- J F -		a diamety				

Campus Name: Decatur Page : 15 of 25 Assessment Date: 11/28/2023



Catego	ory : Fire Protection		В	uilding	: Annex		V Cacramento AVENOE, Onicago, 12 00040
<b>.</b>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	18,600	SF	7	10+ years	
	Fire Alarm_System	1st Floor	18,600	SF	7	10+ years	System tied into annunciator panel in main building
	Fire Pump Controller	1st Floor	1	EA	7	10+ years	man banang
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	1st Floor	1	EA	7	10+ years	
	Jockey Pump	1st Floor	1	EA	7	10+ years	
Sprinkle	r System						
-	Sprinkler Heads	Entire Building	18,600	SF	7	10+ years	
	Sprinkler Piping	Entire Building	18,600	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	18,600	SF	7	10+ years	
Catego	ory : Mechanical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	ditionina						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
_Air Hand	dling Systems						
	VAV Box	Entire Building	10	EA	7	10+ years	VAV boxes that serve classrooms underneath ceiling tiles
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof	1	EA	7	10+ years	and the same same grant and the
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof	1	EA	7	10+ years	
Boiler S	vstems						
•	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	7	10+ years	
	Condensing- Hot Water Boiler - 500 - 1000	Boiler Room	2	EA	7	10+ years	
			_			, ,	
	MBH					40	
		Boiler Room	2	EΑ	7	10+ vears	
	мвн Hot Water Pump Water Fill System	Boiler Room Boiler Room	2	EA EA	7 7	10+ years 10+ years	
Heating	Hot Water Pump Water Fill System						

Campus Name: Decatur Page : 16 of 25 Assessment Date: 11/28/2023



Catego	Category : Mechanical			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Electric	Electrical Room	1	EA	7	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	7	10+ years	
_Mechani	ical Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	18,600	SF	7	10+ years	
	Thermostats - DDC	Entire Building	3	EA	7	10+ years	
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	7	10+ years	
	CFM Exhaust Fans- Roof Mounted - 500 - 1500	Roof	3	EA	7	10+ years	
	CFM		· ·	_, .	·	you.o	
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	7	10+ years	
			_		_		

Category : Plumbing **Building: Annex** 

Graup	Itom Tuno	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments
_Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	10+ years	
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	18,600	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	18,600	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	18,600	SF	7	10+ years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	18,600	SF	7	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	18,600	SF	7	10+ years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	18,600	SF	7	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	18,600	SF	7	10+ years	
	Storm Piping	Entire Building	18,600	SF	7	10+ years	
	Vent Piping	Entire Building	18,600	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	1st Floor	2	EA	7	10+ years	
						,	

Campus Name: Decatur Page : 17 of 25 Assessment Date: 11/28/2023



Category : Room			В	uilding	: Annex		V Gaeramento AVENOE, Onicago, le 00040
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	Conference room / Clinicians	127	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Conference room / Clinicians	1	ĒΑ	7	10+ years	
	Floor - Tile	Conference room / Clinicians	127	SF	7	10+ years	
	Lighting - Lay-in	Conference room / Clinicians	2	ĒΑ	7	10+ years	
	Power Distribution	Conference room / Clinicians	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Conference room / Clinicians	450	SF	7	10+ years	
	Ceiling - Lay-in	Gym office	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym office	1	EA	7	10+ years	
	Floor - Tile	Gym office	120	SF	7	10+ years	
	Lighting - Lay-in	Gym office	2	EA	7	10+ years	
	Power Distribution	Gym office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym office	440	SF	7	10+ years	
	Ceiling - Lay-in	Gym storage/copy room	270	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym storage/copy room	2	EA	7	10+ years	
	Floor - Tile	Gym storage/copy room	270	SF	7	10+ years	
	Lighting - Lay-in	Gym storage/copy room	4	EA	7	10+ years	
	Power Distribution	Gym storage/copy room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Gym storage/copy room	800	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	7	10+ years	
	Floor - Tile	Kitchen Office	140	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Office	2	EA	7	10+ years	
	Power Distribution	Kitchen Office	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	800	SF	7	10+ years	
	Ceiling - Lay-in	Staff Lounge	341	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Lounge	1	ĒΑ	7	10+ years	
	Floor - Tile	Staff Lounge	341	SF	7	10+ years	
	Lighting - Lay-in	Staff Lounge	6	ĒΑ	7	10+ years	
	Power Distribution	Staff Lounge	7	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Lounge	750	SF	7	10+ years	
	Work SInk	Staff Lounge	1	ĒΑ	7	10+ years	
			•			- <b>,</b>	
Gvmnas	ia						
	Bleacher Seating	1st Floor	120	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	4,814	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Wood	1st Floor	4,814	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	10+ years	
	Scoreboards	1st Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	8,460	SF	7	10+ years	
			3, 130	٥.	•	, care	

Campus Name: Decatur Page : 18 of 25 Assessment Date: 11/28/2023



Catego	ry : Room		В	uildina	: Annex	Building : Annex						
	.,,		_			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank		Comments					
Kitchen	.,,,,,											
Michen	Ceiling - Lay-in	1st Floor	1,512	SF	7	10+ years						
	Doors - Wood Doors inclu hw	1st Floor	1,512	EA	7	10+ years						
	Floor - Tile		1,512	SF	7							
		1st Floor 1st Floor				10+ years						
	Lighting - Lay-in Serving Line	1st Floor	34 40	EA LF	7 7	10+ years						
		1st Floor		SF		10+ years						
	Storage/ Closet		145		7	10+ years						
	Walls - Plaster/Drywall	1st Floor	522	SF	7	10+ years						
	Walls - Tile	1st Floor	1,218	SF	7	10+ years						
Library	Online Laute	Ant Flans	750	05		40						
	Ceiling - Lay-in	1st Floor	750	SF	7	10+ years						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years						
	Floor - Tile	1st Floor	750	SF	7	10+ years						
	Lighting - Lay-in	1st Floor	7	EA	7	10+ years						
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years						
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	10+ years						
	_											
MDF_IDI												
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	<b>5</b> 1 12					
	Other Cooling Unit	1st Floor	1	EA	7	10+ years	Ductless split					
Maabaai	cal/ Camilias Dagras											
iviecnanii	cal/ Service Rooms	1st Floor	400	SF	7	10						
	Boiler Room	1st Floor	420 56	SF SF	7 7	10+ years						
	Janitor's Closet			SF SF		10+ years						
	Mechanical/ Service Rooms	1st Floor	105	SF SF	7	10+ years						
	Mechanical/ Service Rooms	1st Floor	165	SF SF	7	10+ years						
	Storage Room	1st Floor	319	5F	7	10+ years						
Restroon	n											
TCSTOOL	Accessories	Boy's Toilet	253	SF	7	10+ years						
	Ceiling - Plaster/Drywall	Boy's Toilet	253	SF	7	10+ years						
	Floor - Tile	Boy's Toilet	253	SF	7	10+ years						
	Floor Drain	Boy's Toilet	1	EA	7	10+ years						
	Hand Dryer	Boy's Toilet	2	EA	7	10+ years						
	Lavatory	Boy's Toilet	2	EA	7	10+ years						
	Lighting - Lay-in	Boy's Toilet	7	EA	7	10+ years						
	Partitions	Boy's Toilet	3	EA	7	10+ years						
	Urinals	Boy's Toilet Boy's Toilet	2	EA	7	10+ years						
	Walls - Plaster/Drywall	Boy's Toilet Boy's Toilet	201	SF	7	10+ years						
	Walls - Flaster/Drywall Walls - Tile	Boy's Toilet Boy's Toilet	402	SF	7	10+ years						
	Water Closet	•	3	EA	7	•						
		Boy's Toilet Gender neutral toilet east	60	SF	7	10+ years 10+ years						
	Accessories	Gendei neuliai lonel easi	UØ	OΓ	1	io+ veais						



Category : Room			В	uilding	: Annex		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Gender neutral toilet east	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gender neutral toilet east	1	EA	7	10+ years	
	Floor - Tile	Gender neutral toilet east	60	SF	7	10+ years	
	Floor Drain	Gender neutral toilet east	1	EA	7	10+ years	
	Hand Dryer	Gender neutral toilet east	1	EA	7	10+ years	
	Lavatory	Gender neutral toilet east	1	EA	7	10+ years	
	Lighting - Lay-in	Gender neutral toilet east	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Gender neutral toilet east	93	SF	7	10+ years	
	Walls - Tile	Gender neutral toilet east	186	SF	7	10+ years	
	Water Closet	Gender neutral toilet east	1	EΑ	7	10+ years	
	Accessories	Gender neutral toilet west	60	SF	7	10+ years	
	Ceiling - Lay-in	Gender neutral toilet west	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gender neutral toilet west	1	EA	7	10+ years	
	Floor - Tile	Gender neutral toilet west	60	SF	7	10+ years	
	Floor Drain	Gender neutral toilet west	1	EA	7	10+ years	
	Hand Dryer	Gender neutral toilet west	1	EA	7	10+ years	
	Lavatory	Gender neutral toilet west	1	EA	7	10+ years	
	Lighting - Lay-in	Gender neutral toilet west	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Gender neutral toilet west	93	SF	7	10+ years	
	Walls - Tile	Gender neutral toilet west	186	SF	7	10+ years	
	Water Closet	Gender neutral toilet west	1	ĒΑ	7	10+ years	
	Accessories	Girls toilet	253	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Girls toilet	253	SF	7	10+ years	
	Floor - Tile	Girls toilet	253	SF	7	10+ years	
	Floor Drain	Girls toilet	1	EA	7	10+ years	
	Hand Dryer	Girls toilet	2	ΕA	7	10+ years	
	Lavatory	Girls toilet	3	ΕA	7	10+ years	
	Lighting - Lay-in	Girls toilet	7	EΑ	7	10+ years	
	Partitions	Girls toilet	5	EA	7	10+ years	
	Walls - Plaster/Drywall	Girls toilet	201	SF	7	10+ years	
	Walls - Tile	Girls toilet	402	SF	7	10+ years	
	Water Closet	Girls toilet	5	EA	7	10+ years	
	Accessories	Staff Toilet	60	SF	7	10+ years	
	Ceiling - Lay-in	Staff Toilet	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Toilet	1	EA	7	10+ years	
	Floor - Tile	Staff Toilet	60	SF	7	10+ years	
	Floor Drain	Staff Toilet	1	EA	7	10+ years	
	Hand Dryer	Staff Toilet	1	EA	7	•	
	Lavatory	Staff Toilet	1	EA	7	10+ years 10+ years	
	Lavatory Lighting - Lay-in	Staff Toilet	1	EA	7	-	
				SF		10+ years	
	Walls - Plaster/Drywall Walls - Tile	Staff Toilet Staff Toilet	93 186	SF SF	7 7	10+ years	
	Water Closet			SF EA		10+ years	
		Staff Toilet	1		7	10+ years	
	Accessories	Staff unisex in kitchen	68	SF	7	10+ years	

Campus Name: Decatur Page : 20 of 25 Assessment Date: 11/28/2023



Catego	ry : Room		R	uilding	· Annex		V Cacramento AVEIVOE, Officago, 12 00040
Galogo	.,		_	unung	. , (11110)	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Staff unisex in kitchen	68	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff unisex in kitchen	1	ĒΑ	7	10+ years	
	Floor - Tile	Staff unisex in kitchen	68	SF	7	10+ years	
	Floor Drain	Staff unisex in kitchen	1	EA	7	10+ years	
	Hand Dryer	Staff unisex in kitchen	1	EΑ	7	10+ years	
	Lavatory	Staff unisex in kitchen	1	EΑ	7	10+ years	
	Lighting - Lay-in	Staff unisex in kitchen	1	EA	7	10+ years	
	Student Lockers - One Tier	Staff unisex in kitchen	1	EA	7	10+ years	Not previously assessed
	Walls - Plaster/Drywall	Staff unisex in kitchen	100	SF	7	10+ years	Not previously assessed
	Walls - Tile	Staff unisex in kitchen	215	SF	7	10+ years	
			1	EA	7	•	
	Water Closet	Staff unisex in kitchen	Į	EA	,	10+ years	
Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	om #1011 (Science Classroom)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	735	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	735	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #1012 (Regular Classroom)						
Oldssioc	Ceiling - Lay-in	1st Floor	735	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	735	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
	vvalis - Flastei/Drywali	15t F1001	1,000	SI	,	10+ years	
Classroo	om #1013 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	735	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	735	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
Catego	ry : Interior		R	uilding	· Anney		
	Item - Type	Location	Quantity	UOM	Rank		Comments
Group	nem - Type	Location	Quantity	COIVI	IVALIA	Recommend	Comments



			Replacement					
<u>Corridor</u>								
	Ceiling - Lay-in	1st Floor	2,390	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	815	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	15	EΑ	7	10+ years		
	Doors - Wood Doors include hw	1st Floor	2	EA	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	3,205	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	32	EA	7	10+ years		
	Student Lockers - Two Tiers	1st Floor	116	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	450	SF	7	10+ years		
	Walls - Masonry	1st Floor	120	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	4,340	SF	7	10+ years		
Safety								
,	Security Cameras	Exterior	4	EA	7	6-10 years	Not previously assessed	







Category: Site Building: Site

Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	West	17,940	SF	7	10+ years	
			,			, , , , , ,	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	7	10+ years	
Fencing							
T ending	Fencing - Chain Link	Entire Site	565	LF	7	10+ years	Newly added
	Fencing - Chain Link	Entire Site	286	LF	6	10+ years	. romy dadod
	Fencing - New Standard Ornamental	Entire Site	712	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	650	LF	7	10+ years	
Landsca	pe Benches	Entire Site	5	EA	7	10+ years	Added to match current observations
		Entire Site Entire Site	3,800	SF	6	10+ years	Added to match current observations
	Irrigation Landscape - Grass	Entire Site Entire Site	19,573	SF	7	10+ years	
	Landscape - Grass  Landscape - Hardscape- Concrete	Entire Site Entire Site	12,000	SF	7	10+ years	
					, 6		
	Parkway trees	Entire Site	13	EA	-	10+ years	
	Planting Beds/ Area	Entire Site	3,790	SF	6	10+ years	E d d . l b
	Planting Beds/ Area	Entire Site	10	SF	4	0-1 year	Exposed metal bars
	Trash Receptacles	Entire Site	2	EA	7	10+ years	Added to match current observation
	Walking Path - Crushed Stone	Entire Site	200	SF	7	10+ years	
Parking	Lot						
	Concrete Curbs	Entire site, includes firelanes	2,100	LF	7	10+ years	Added to match current observations
	Interior Plantings	Entire site, includes firelanes	40	LF	7	10+ years	
	Lighting - Pole Mounted	Entire site, includes firelanes	3	EA	7	10+ years	
	Surface - Asphalt	Entire site, includes firelanes	37,000	SF	7	10+ years	
	Surface - Concrete	Entire site, includes firelanes	2,500	SF	7	10+ years	
	Trash Compactor	Entire site, includes firelanes	1	ĒΑ	7	10+ years	
	Trash Enclosure - Masonry	Entire site, includes firelanes	384	SF	7	10+ years	
Playgrou	und						
. idygiot	Equipment - Pre K 3-5	Southeast	1	EA	7	10+ years	
	Surface - Poured Surface	Southeast	1,000	SF	7	6-10 years	
	Equipment - Combo 3-12	Southwest	1	EA	7	10+ years	
	Surface - Poured Surface	Southwest	1,200	SF	7	6-10 years	
0	0						
Service	•	N. d. M. d.					
	Service Garage - Free-Standing	North West	484	SF	7	10+ years	new

Campus Name: Decatur Page : 23 of 25 Assessment Date: 11/28/2023



#### **Stephen Decatur Classical Elementary School**

7030 N Sacramento AVENUE, Chicago, IL 60645

Category : Site			Building : Site				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Sidewalk	KS .						
	Sidewalks - Internal Walks	East	580	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	East	20	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	East	4,298	SF	6	10+ years	
Signage							
	Flag Pole - Flag Pole	East	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	East	2	EA	6	10+ years	
	Monument - Sign	East	1	EA	6	6-10 years	Added to match current observations

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Decatur Page: 24 of 25 Assessment Date: 11/28/2023

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.







**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main						•			
Art Room	Science Classroom	1st Floor	111	111	850	240	60	N	N
Dance Room	Dance Room	1st Floor	101	101	1,304	274	49		
Kindergarten	Kindergarten	1st Floor	100	100	1,224	274	49	N	N
Music Room	Multi Purpose Room	1st Floor	114		1,473	360	80		
Regular Classroom	Office	1st Floor	112	112	766	240	60		
Regular Classroom	Regular Classroom	1st Floor	102	104	859	228	36	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	850	228	36	N	N
Regular Classroom	Regular Classroom	1st Floor	104	106	859	228	36	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	850	240	60	N	N
Regular Classroom	Regular Classroom	1st Floor	106	108	859	228	36	N	Ν
Regular Classroom	Regular Classroom	1st Floor	107	107	850	240	60	N	N
Regular Classroom	Regular Classroom	1st Floor	108	110	859	222	36	N	Ν
Regular Classroom	Regular Classroom	1st Floor	109	109	850	240	60	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	859	228	36	N	N
Building : Annex									
Regular Classroom	Regular Classroom	1st Floor	1012	1012	735	80	16		
Regular Classroom	Regular Classroom	1st Floor	1013	1013	735	80	16		
Science Classroom	Science Classroom	1st Floor	1011	1011	735	80	16		