

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1902	4	68,898
Campus Total			68,898

Catego	ry : Exterior		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	2-West	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	2-West	2	EA	6	6-10 years	
	Exterior Doors - Side lite	2-West	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	2-West	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	2-West	20	LF	6	10+ years	
	Power Door Operator and Controls	2-West	1	EA	7	10+ years	Not previously assessed
	Ramp Handrail - Steel_Ramp Handrail	2-West	45	LF	6	10+ years	
	Ramps - Concrete	2-West	20	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	2-West	20	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	3-NW	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	3-NW	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4-North Boiler Room	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	4-North Boiler Room	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	4-North Boiler Room	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	5-North Yard Storage	1	EA	4	0-1 year	Corroded frame, warped door
	Exterior Doors - Exterior FRP Door	7-East	2	EA	6	6-10 years	•
	Exterior Doors - Side lite	7-East	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7-East	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	7-East	20	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	7-East	45	LF	6	10+ years	
	Ramps - Concrete	7-East	20	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	7-East	20	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	Exit 6-NE	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Exit 6-NE	6	LF	7	6-10 years	



Catego	ry : Exterior		В	uilding	: Main			
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Entrance Control - Audio and Video	Main Entrance 1-South	1	EA	6	6-10 years		
	Exterior Doors - Exterior FRP Door	Main Entrance 1-South	4	EA	6	10+ years		
	Exterior Doors - Transom Lite	Main Entrance 1-South	3	EA	7	10+ years		
	Exterior Stairs - Stone	Main Entrance 1-South	75	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	North fire escape doors	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	North fire escape doors	1	EA	7	6-10 years		
Fire Esc	ape							
	Exterior Doors - Exterior Steel Door	Entire Building	1	EA	6	10+ years	Blocked by storage	
	Exterior Doors - Exterior Steel Door	Entire Building	1	EA	6	10+ years	, ,	
	Fire Escape	Entire Building	161	LF	6	6-10 years		
	Paints	Entire Building	161	LF	3	1-2 years	Corroding steel	
oundati	ion							
oundu	Foundation - Masonry	Entire Building	675	LF	7	10+ years		
	Foundation - Masonry	Entire Building	25	LF	5	2-5 years	Cracked brick, spalled brick	
	i cundation macomy	Entro Dananig	20		Ũ	2 o youro	foundation	
	Superstructure - Heavy Timber	Entire Building	68,898	SF	7	10+ years	Corrected item type	
		Entire Duliang	00,000	01	,	for years		
ighting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	7	10+ years	Replaced	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	7	10+ years	Replaced	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	2-5 years		
Roof Sys								
	Access Ladder - Wood	Roof 1	2	EA	4	0-1 year	Original, unsafe wood ladders. Large ladder bounces, neither is properly attached	
	Coping - Stone	Roof 1	270	LF	6	10+ years		
	Coping - Terra Cotta	Roof 1	390	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 1	330	LF	6	6-10 years		
	Parapet - 16" - 30" Height	Roof 1	525	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Roof 1	35	LF	6	10+ years		
	Parapet - Parapet > 30"	Roof 1	100	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	Roof 1	12,625	SF	4	2-5 years		
	Roof - Asphalt Shingle	Roof 1	125	SF	3	0-1 year	Torn shingles, missing sections	
	Roof Hatch - Metal	Roof 1	1	EA	4	0-1 year	Small, corroded hatch	
	Roof Structure - Concrete	Roof 1	125	SF	6	10+ years		
	Roof Structure - Heavy Timber	Roof 1	12,625	SF	6	10+ years		
	Coping - Clay Tile	Roof 2	130	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 2	90	LF	6	6-10 years		
	Parapet - Parapet < 16" Height	Roof 2	130	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	Roof 2	2,100	SF	6 5	0-1 year	Very old roof with growing vegetation	
	NUUI - ASPITAIL GLAVEL DAIIASL		∠,100	SL	5	0-i year	very old roor with growing vegetation	



8255 S Houston AVENUE, Chicago, IL 60617 **Building : Main Category : Exterior** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments blistering throughout Roof Structure - Heavy Timber SF Roof 2 2.100 6 10+ vears LF Chimney - Brick Chimney- Concrete/ Mortar Roof 3 75 7 10+ years Liner Coping - Clay Tile Roof 3 325 LF 6 10+ years LF **Downspouts - Exterior Downspouts** Roof 3 140 6 6-10 years Parapet - 16" - 30" Height 25 LF 6 10+ years Roof 3 Parapet - Parapet < 16" Height LF Roof 3 300 6 10+ years SF Roof - Asphalt Gravel Ballast Roof 3 2,680 5 0-1 year Very old roof with growing vegetation, blistering throughout Roof - Asphalt Gravel Ballast Roof 3 1.000 SF 4 Very old roof with arowing vegetation. 0-1 year blistering throughout SF 7 Roof Structure - Heavy Timber Roof 3 3,680 10+ years Walls Cornice - Metal Projecting Entire Building 420 LF 6 10+ years Exterior Walls - Brick Entire Building SF 41.417 6 10+ years **Recombined** quantities Exterior Walls - Stone-Cast Entire Building 1,702 SF 6 10+ years SF Exterior Walls - Terra Cotta Entire Building 249 6 10+ years Windows SF **Clerestory - Glass Double-Pane** Entire Building 54 6 10+ years SF Guard - Guards perforated Entire Building 2,626 6 6-10 years Guard - Guards wire guard Entire Building SF 6-10 years 140 6 Lintels - Brick Entire Building 393 LF 7 10+ years LF 55 7 Lintels - Steel Entire Building 10+ years LF Lintels - Stone Entire Building 237 7 10+ years LF 7 Lintels - Terra Cotta Entire Building 131 10+ years Skylite - Glass Single-Pane Entire Building 50 SF 4 0-1 vear Broken glass SF Windows - Louver Entire Building 140 6 6-10 years SF 6 Windows - Sash Aluminum Double-pane Entire Building 5,954 2-5 years SF Windows - Wood- Single-pane Entire Building 126 4 2-5 years Obsolete, original single pane **Building : Main Category : Electrical** Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
C C	Automatic Transfer Switch	Electrical Room	1	EA	2	0-1 year	Failed/removed. Cabinet remains.
	Security System - CCTV	Entire Building	68,898	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	68,898	SF	6	6-10 years	Only maintenance covered by intrusion detection
	Emergency Battery Packs - Corridors and Stairs	Entire Building	45	EA	7	10+ years	



atego	ry : Electrical		B	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Gym	Entire Building	1	EA	7	10+ years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	6	10+ years	
	Exit Signs - Lunchroom	Entire Building	1	EA	4	0-1 year	Lettering on sign is scratching off, frame of unit is cracked.
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,591	SF	7	10+ years	Not previously assessed
lain Se							
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	Two older switchboard panels, one newer. Older equipment is showing signs of age with corrosion. New service added for air-conditioning upgrade.
	Independent Electrical Service for emergency power	Electrical Room, Fire Pump Room.	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room, Fire Pump Room.	1	EA	6	10+ years	
	PA System	Entire Building	68,898	SF	5	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Vintage panel in third-floor north locked closet
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	10+ years	Lab prep (1), unlabeled panel in loading dock, LP-A in boiler room, vintage panel in kitchen, KP in kitchen,
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	EM panels in mech room outside of building operators office.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	unlabeled 100A panel in building operators office with live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	CP-1 & CP-MDF
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	BC in Mech room, DP revised, AC AC-2 & AC-3 inaccessible (locked keys available fit the locks) Quanti separated to document live front condition in unlabeled panel in
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	10+ years	building operators office Vintage panels near East and wes stair towers. Quantity updated to reflect existing conditions.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Tenect existing conditions.



EPIC Academy Charter High School 8255 S Houston AVENUE, Chicago, IL 60617

Catego	egory : Electrical Building : Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	amp Transformers - 120/240 - 120/208	Entire Building	1	EA	2	0-1 year	Single phase Transformer located in building operators office.

Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Ala	m						
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Installed new 2021
	Fire Alarm Strobe Lights	Entire Building	68,898	SF	7	10+ years	
	Fire Alarm_System	Entire Building	68,898	SF	7	10+ years	
	Fire Pump Controller	Entire Building	1	EA	4	1-2 years	Original
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	4	0-1 year	Corroded
Sprinkle	r System						
•	Dry Sprinkler System	Entire Building	68,898	SF	6	10+ years	
	Sprinkler Heads	Entire Building	68,898	SF	7	10+ years	
	Sprinkler Piping	Entire Building	68,898	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Fan Coil Unit- Celing Mounted - Steam	Entire Building	1	EA	4	10+ years	Girls toilet, functional, but deteriorating
	Fan Coil Unit- Celing Mounted - Steam	Entire Building	1	EA	2	10+ years	Boys toilet leaking steam condensate
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 45001 - 60000 cfm	Mechanical Room	1	EA	4	6-10 years	Temperature control from east to west side of building are not consistent.

Boiler Systems

Air Intake

Auxiliaries - 45001 - 60000 cfm

Missing or Existing Shaft

Zone Dampers

Return Duct Work - Masonry and Ducts-

ΕA

ΕA

LF

ΕA

4

6

6

6

1

1

200

39

10+ years

10+ years

10+ years

10+ years

Mechanical Room

Mechanical Room

Mechanical Room

Mechanical Room

OA dampers are significantly closed,

causing return air to keep doors open

Quantity updated to reflect current

and front main vestibule.

observations.



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Feed System	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	Combustion air damper actuator for
						- ,	boiler one does not look functional.
	Condensate Pump	Boiler Room	2	EA	5	1-2 years	Pump seals have been replaced and are no longer leaking profusely. Sma leak detected from south pump petcock and from return tank water level gauge. Quantity aggregated.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	1-2 years	Pumps 1; 2, and four are functional. Pump three needs to be replaced.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	1-2 years	Boiler two is in good working condition per building operator.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	1-2 years	Boiler one cannot maintain water level and will not keep up.
	Piping - Condensate Pipe- Steel	Boiler Room	560	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	560	LF	6	10+ years	
	Steam Traps	Boiler Room	11	EA	5	10+ years	
				_,,	Ũ	io: youro	
Gas Boo	oster						
	Gas Booster	Boiler Room	2	EA	7	10+ years	
Heating	Devices						
	Fin Tube - Electric	Basement	40	LF	6	10+ years	
	Wall Heater - Electric	Basement	3	EA	7	10+ years	Functional new piece of equipment, interior office in basement and fire pump assembly room.
	Wall Heater - Electric	Basement	2	EA	2	10+ years	Vintage, electric wall heater, non- functional, cover missing.
	Unit Heater - Electric	Entire Building	3	EA	6	10+ years	Electric unit heaters found in third- floor north locked closets
	Unit Heater - Steam	Entire Building	1	EA	7	10+ years	Quantity separated to reflect current conditions.
	Unit Heater - Steam	Entire Building	1	EA	2	10+ years	Fan is non-functional, leaking steam condensate.
Tempera	ature Control						
-	Electric Thermostat	Entire Building	3	EA	7	10+ years	Thermostatic control is performed by line voltage switches.
	Hybrid Pneumatic/DDC System	Entire Building	68,898	SF	4	1-2 years	System does not function properly. Well duct temperatures are sensed through DC system pneumatic



Category : Mechanical **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments controls are not functional. ΕA 6 Thermostats - DDC 40 10+ years Entire Building Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 ΕA 7 Entire Building 1 10+ years CFM Exhaust Fans- Roof Mounted - 500 - 1500 2 FΑ Entire Building 6 10+ years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 5 EΑ 6 10+ years 500 CFM **Category : Plumbing Building : Main** Recommend Location Quantity UOM Rank Replacement Comments Group Item - Type Hot Water Gas Heater - 150000 - 300000 BTU/HR Mechanical Room 1 ΕA 6 6-10 years Pipina Domestic Piping-Hot Water Return Lines SF 7 Entire Building 68.898 10+ vears Domestic Piping-Hot Water Return Risers SF Entire Building 68,898 4 6-10 years Domestic water, iron and galvanized pipe is showing age and corrosion. Domestic Piping-Hot Water from Risers to Entire Building 68.898 SF 6 10+ years Fixtures Domestic Piping-Hot/Cold Water Supply Entire Building 68,898 SF 7 10+ years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 68.898 SF 6 6-10 vears (Risers) Domestic Piping-Hot/Cold Water Supply 68,898 SF 7 Entire Building 10+ years (from Risers to Fixtures) Sanitary Piping SF 6 Entire Building 68,898 6-10 years Storm Piping Entire Building 68.898 SF 5 10+ years Vent Piping Entire Building 68.898 SF 6 10+ years Pumps Pumps - Ejector-Simplex Mechanical Room ΕA 6 6-10 years 1 Pumps - Sump-Duplex Mechanical Room 1 EΑ 7 10+ years Not accessible **Building : Main** Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Administrative Suites/Offices AC Unit 1st Floor Main Office 1 ΕA 7 6-10 years



Catego	ry : Room		B	uilding	• Main	02	55 S Houston AVENUE, Chicago, IL 60617
Guicgo				unung	· Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor Main Office	562	SF	7	10+ years	
	Doors - Transom Window	1st Floor Main Office	10	SF	6	10+ years	Corrected quantity
	Doors - Wood Doors inclu hw	1st Floor Main Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor Main Office	562	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Main Office	7	EA	7	6-10 years	
	Power Distribution	1st Floor Main Office	24	EA	7	10+ years	
	Storage/ Closet	1st Floor Main Office	44	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Main Office	1,497	SF	7	10+ years	
	Ceiling - Lay-in	B-3 food services room	625	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B-3 food services room	1	EA	6	10+ years	
	Floor - Tile	B-3 food services room	625	SF	6	10+ years	
	Lighting - Pendent/Surface	B-3 food services room	10	EA	6	6-10 years	
	Power Distribution	B-3 food services room	10	EA	7	10+ years	
	Walls - Masonry	B-3 food services room	520	SF	6	10+ years	
	Walls - Plaster/Drywall	B-3 food services room	203	SF	6	10+ years	
	AC Unit	B-5 teachers work room	1	EA	7	6-10 years	
	Ceiling - Lay-in	B-5 teachers work room	805	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B-5 teachers work room	1	EA	6	10+ years	
	Floor - Tile	B-5 teachers work room	805	SF	7	10+ years	
	Lighting - Pendent/Surface	B-5 teachers work room	15	EA EA	7	6-10 years	
	Power Distribution	B-5 teachers work room	20		7	10+ years	
	Walls - Masonry Walls - Plaster/Drywall	B-5 teachers work room	767 260	SF SF	6 6	10+ years	
	Work Sink	B-5 teachers work room B-5 teachers work room	200	EA	7	10+ years 10+ years	Not previously assessed
	Ceiling - Lay-in	B-7 social work office	1,073	SF	6	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	B-7 social work office	1,073	EA	6	10+ years	
	Floor - Tile	B-7 social work office	1,073	SF	7	10+ years	
	Lighting - Pendent/Surface	B-7 social work office	18	EA	7	6-10 years	
	Power Distribution	B-7 social work office	42	EA	7	10+ years	
	Walls - Plaster/Drywall	B-7 social work office	1,876	SF	6	10+ years	
	Ceiling - Lay-in	Basement Principals Office	107	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Principals Office	1	EA	6	10+ years	
	Floor - Wood	Basement Principals Office	107	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Principals Office	1	EA	7	6-10 years	
	Power Distribution	Basement Principals Office	12	EA	7	6-10 years	
	Walls - Masonry	Basement Principals Office	209	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement Principals Office	209	SF	6	10+ years	
	AC Unit	Chief of operations office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Chief of operations office	95	SF	7	10+ years	
	Doors - Steel Doors incl hw	Chief of operations office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Chief of operations office	1	EA	7	10+ years	
	Floor - Wood	Chief of operations office	95	SF	7	10+ years	
	Lighting - Pendent/Surface	Chief of operations office	2	EA	7	6-10 years	
	Power Distribution	Chief of operations office	10	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Chief of operations office	517	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counseling office #1	98	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Counseling office #1	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Counseling office #1	98	SF	5	10+ years	
	Lighting - Pendent/Surface	Counseling office #1	1	EA	7	6-10 years	
	Power Distribution	Counseling office #1	10	EA	7	10+ years	
	Walls - Masonry	Counseling office #1	198	SF	6	6-10 years	
	Walls - Plaster/Drywall	Counseling office #1	181	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Counseling office #2	79	SF	6	10+ years	
	Doors - Steel Doors incl hw	Counseling office #2	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Counseling office #2	79	SF	7	10+ years	
	Lighting - Pendent/Surface	Counseling office #2	1	EA	7	6-10 years	
	Power Distribution	Counseling office #2	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Counseling office #2	362	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Counseling office #3	60	SF	6	10+ years	
	Doors - Steel Doors incl hw	Counseling office #3	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Counseling office #3	60	SF	5	10+ years	
	Lighting - Pendent/Surface	Counseling office #3	1	EA	7	6-10 years	
	Power Distribution	Counseling office #3	6	EA	6	10+ years	
	Walls - Masonry	Counseling office #3	163	SF	7	10+ years	
	Walls - Masonry	Counseling office #3	163	SF	7	10+ years	
	Walls - Plaster/Drywall	Counseling office #3	150	SF	7	10+ years	
	Ceiling - Lay-in	Dean/asst principal's offices	884	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Dean/asst principal's offices	2	EA	6	10+ years	
	Floor - Tile	Dean/asst principal's offices	884	SF	7	10+ years	
	Lighting - Pendent/Surface	Dean/asst principal's offices	14	EA	7	6-10 years	
	Power Distribution	Dean/asst principal's offices	32	EA	7	10+ years	
	Walls - Concrete Block	Dean/asst principal's offices	342	SF	6	10+ years	
	Walls - Masonry	Dean/asst principal's offices	885	SF	6	10+ years	
	Walls - Plaster/Drywall	Dean/asst principal's offices	293	SF	6	10+ years	
	AC Unit	Engineers office	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	Engineers office	110	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineers office	1	EA	6	10+ years	
	Floor - Concrete	Engineers office	110	SF	5	6-10 years	
	Lighting - Pendent/Surface	Engineers office	1	EA	7	6-10 years	
	Power Distribution	Engineers office	6	EA	7	10+ years	
	Walls - Masonry	Engineers office	109	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineers office	397	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Managers Office	135	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Managers Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Managers Office	135	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Managers Office	2	EA	6	6-10 years	
	Power Distribution	Kitchen Managers Office	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Kitchen Managers Office	358	SF	6	10+ years	
		- 0			-	,	



Catego	ry : Room		В	uilding	: Main		
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Office B-8	127	SF	6	10+ years	
	Doors - Steel Doors incl hw	Office B-8	1	EA	6	10+ years	
	Floor - Tile	Office B-8	127	SF	7	10+ years	New flooring
	Lighting - Pendent/Surface	Office B-8	2	EA	7	6-10 years	-
	Power Distribution	Office B-8	20	EA	7	10+ years	
	Walls - Masonry	Office B-8	118	SF	6	10+ years	
	Walls - Plaster/Drywall	Office B-8	330	SF	6	10+ years	
	Ceiling - Lay-in	Office in main office	103	SF	7	10+ years	
	Ceiling - Lay-in	Office in main office	4	SF	5	0-1 year	Broken tile
	Doors - Wood Doors inclu hw	Office in main office	1	EA	7	10+ years	
	Floor - Carpet	Office in main office	6	SF	7	6-10 years	
	Floor - Wood	Office in main office	101	SF	6	10+ years	
	Lighting - Pendent/Surface	Office in main office	2	EA	7	6-10 years	
	Power Distribution	Office in main office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Office in main office	533	SF	7	10+ years	
	Ceiling - Lay-in	Teachers room	185	SF	7	10+ years	
	Ceiling - Lay-in	Teachers room	9	SF	5	0-1 year	Cracked tile
	Doors - Transom Window	Teachers room	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teachers room	, 1	EA	7	10+ years	
	Floor - Wood	Teachers room	194	SF	5	10+ years	Priority changed to match current
			104	01	0	Tor years	observations
	Lighting - Pendent/Surface	Teachers room	2	EA	7	6-10 years	
	Power Distribution	Teachers room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Teachers room	927	SF	7	10+ years	
litchen							
	Ceiling - Exposed	Basement	445	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	445	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	10	ĒA	7	6-10 years	
	Serving Line	Basement	10	LF	6	10+ years	
	Walls - Masonry	Basement	400	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	302	SF	6	10+ years	
ocker/S	Shower Room						
	Accessories	3rd Fl Boys Changing Room	163	SF	7	6-10 years	
	Benches, ped mounted	3rd Fl Boys Changing Room	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Fl Boys Changing Room	163	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Fl Boys Changing Room	2	EA	7	10+ years	
	Floor - Wood	3rd Fl Boys Changing Room	163	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Fl Boys Changing Room	4	EA	7	6-10 years	
	Student Lockers - Three Tiers	3rd Fl Boys Changing Room	30	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Fl Boys Changing Room	675	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Fl Boys Changing Room	7	SF	5	10+ years	Molding damage, crack
	wans - Flastel/DiyWall	Sid Fi boys changing Room	/	ЗГ	5	ior years	wording damage, clack



Catoria			D	uilding	Main	02	55 S Houston AVENUE, Chicago, IL 606
Catego	ry : Room		В	unaing	: Main	Decemmend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Accessories	3rd Fl Girls Changing Room	163	SF	7	6-10 years	Comments
	Benches, ped mounted	3rd Fl Girls Changing Room	103	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Fl Girls Changing Room	163	SF	7		
						10+ years	
	Doors - Steel Doors incl hw	3rd Fl Girls Changing Room	2	EA	7	10+ years	
	Floor - Wood	3rd FI Girls Changing Room	163	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd FI Girls Changing Room	4	EA	7	6-10 years	
	Student Lockers - Three Tiers	3rd FI Girls Changing Room	30	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd FI Girls Changing Room	675	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd FI Girls Changing Room	12	SF	5	10+ years	Damaged plaster
unch &	Multipurpose Room						
	AC Unit	B-1 lunchroom	1	EA	4	0-1 year	Out of order
	Ceiling - Lay-in	B-1 lunchroom	1,136	SF	6	10+ years	
	Doors - Side-lite	B-1 lunchroom	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B-1 lunchroom	1	EA	6	10+ years	
	Floor - Tile	B-1 lunchroom	1,136	SF	6	10+ years	
	Lighting - Pendent/Surface	B-1 lunchroom	18	EA	7	6-10 years	
	Walls - Masonry	B-1 lunchroom	1,361	SF	6	10+ years	
	Walls - Plaster/Drywall	B-1 lunchroom	40	SF	6	10+ years	
	Ceiling - Lay-in	Basement	895	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	665	SF	6	10+ years	
	Doors - Steel Doors incl hw		1	EA	-		
	Floor - Tile	Basement		SF	6 6	10+ years	
		Basement	1,545	SF	-	10+ years	Currier fleer median
	Floor - Tile	Basement	15		4	0-1 year	Sunken floor, cracking
	Lighting - Pendent/Surface	Basement	17	EA	7	6-10 years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement	264	SF	7	10+ years	
	Walls - Masonry	Basement	1,188	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	106	SF	7	10+ years	
IDF_ID	F						
	Doors - Steel Doors incl hw	MDF_IDF in room 205	1	EA	6	10+ years	
	Finishes	MDF_IDF in room 205	81	SF	7	10+ years	
	Finishes	MDF_IDF in room 205	15	SF	5	1-2 years	Paint falling
	Window AC Unit	MDF_IDF in room 205	1	EA	7	6-10 years	5
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	6	SF	5	10+ years	Needs to be painted, surface level
						-	damage to door
	Storage Room	1st Floor	87	SF	5	10+ years	
	Janitor's Closet	2nd Floor	20	SF	5	10+ years	Water damage to walls
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	
	Storage Room	3rd Floor	96	SF	7	10+ years	



8255 S Houston AVENUE, Chicago, IL 60617 **Building : Main** Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments SF Storage Room 3rd Floor 96 7 10+ vears Updated quantity to match current observations Storage Room 3rd Floor 454 SF 7 10+ years Storage room on fire escape Air Intake Plenums 140 SF 5 **Basement** 10+ years 5 SF Air Intake Plenums **Basement** 140 10+ years SF 5 Air Intake Plenums Basement 173 10+ years Air Intake Plenums SF 5 10+ years Basement 173 SF Boiler Room Basement 1.229 5 10+ years Coal Room Basement 443 SF 5 10+ years SF 7 Janitor's Closet 75 6-10 years Basement Mechanical/ Service Rooms SF Basement 95 5 10+ vears Mechanical/ Service Rooms **Basement** 627 SF 5 10+ years Mechanical/ Service Rooms 387 SF 5 Basement 10+ years SF 5 Mechanical/ Service Rooms Basement 184 10+ years SF 5 Storage Room Basement 208 10+ years Storage Room SF 5 Basement 183 10+ years SF 5 Storage Room Basement 120 10+ years Prep Room Casework 203 Lab Prep Room LF 7 10+ years 30 SF Ceiling - Lav-in 203 Lab Prep Room 285 6 10+ years Doors - Wood Doors inclu hw 203 Lab Prep Room 1 EΑ 6 10+ vears SF Floor - Tile 203 Lab Prep Room 285 7 10+ vears 203 Lab Prep Room ΕA 6-10 vears Lighting - Lav-in 4 6 Walls - Plaster/Drywall 203 Lab Prep Room 780 SF 6 10+ years Work SInk 203 Lab Prep Room ΕA 7 1 10+ years Restroom Accessories 1st Fl next to Main Office 101 SF 7 6-10 vears 1st FI next to Main Office SF Ceiling - Lay-in 101 7 10+ years Doors - Transom Window SF 7 1st FI next to Main Office 7 10+ years 7 Doors - Wood Doors inclu hw 1st FI next to Main Office 1 EΑ 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st FI next to Main Office 101 10+ years Lavatory 1st FI next to Main Office 2 EΑ 7 10+ years Lighting - Pendent/Surface 1st FI next to Main Office 1 ΕA 7 6-10 years Partitions 1st Fl next to Main Office 2 EΑ 7 10+ years 535 SF 7 Walls - Plaster/Drvwall 1st FI next to Main Office 10+ vears Water Closet 1st FI next to Main Office 2 FΑ 7 10+ years 2nd FI Boys 132 SF 7 Accessories 6-10 years SF Ceiling - Plaster/Drywall 2nd FI Boys 132 6 10+ years 2nd FI Boys ΕA Doors - Wood Doors inclu hw 1 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd FI Boys 132 SF 6 10+ years 2nd FI Boys Floor Drain 1 ΕA 7 10+ years Hand Dryer 2nd FI Boys 1 EΑ 7 6-10 years



Catego	ry : Room		B	uilding	• Main	02	55 S Houston AVENUE, Chicago, il 60617
Galego				anang	· Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd FI Boys	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Fl Boys	3	EA	6	6-10 years	
	Partitions	2nd FI Boys	1	EA	7	10+ years	
	Urinals	2nd FI Boys	1	EA	6	10+ years	
	Walls - Concrete Block	2nd FI Boys	428	SF	6	10+ years	
	Water Closet	2nd FI Boys	1	EA	6	10+ years	
	Accessories	2nd FI Girls	132	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl Girls	132	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Fl Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Fl Girls	132	SF	6	10+ years	
	Floor Drain	2nd Fl Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Fl Girls	1	EA	7	6-10 years	
	Lavatory	2nd Fl Girls	1	EA EA	6	10+ years	Delemen
	Lighting - Pendent/Surface Partitions	2nd Fl Girls	3 2	EA EA	5 7	1-2 years	Relamp
	Walls - Concrete Block	2nd Fl Girls 2nd Fl Girls	428	SF	6	10+ years 10+ years	
	Walls - Concrete Block	2nd Fl Girls	420	EA	6	10+ years	
	Accessories	2nd Floor East	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor East	46	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor East	-0	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor East	46	SF	7	10+ years	
	Lavatory	2nd Floor East	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor East	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor East	69	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor East	175	SF	7	10+ years	
	Water Closet	2nd Floor East	1	EA	7	10+ years	
	Accessories	2nd Floor West	46	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor West	46	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor West	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor West	46	SF	7	10+ years	
	Lavatory	2nd Floor West	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor West	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor West	61	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor West	175	SF	7	10+ years	
	Water Closet	2nd Floor West	1	EA	6	10+ years	
	Accessories	Boys restroom, basement	689	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall Floor - Tile Ceramic/ Porcelain	Boys restroom, basement	689 689	SF	7 7	10+ years	Demodeled new finishes
	Floor Drain	Boys restroom, basement Boys restroom, basement	2	EA	7	10+ years 10+ years	Remodeled, new finishes
	Hand Dryer	Boys restroom, basement	2	EA	7	10+ years	
	Lavatory	Boys restroom, basement	5	EA	7	10+ years	Reconfigured
	Lighting - Pendent/Surface	Boys restroom, basement	8	EA	7	10+ years	Reconfigured
	Partitions	Boys restroom, basement	6	EA	7	10+ years	Reconfigured
	Urinals	Boys restroom, basement	4	EA	7	10+ years	Reconfigured
		20,010000000000000000000000000000000000		_/ `	•	, youro	



Building : Main Category : Room Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments Walls - Plaster/Drywall Remodeled, new finishes Boys restroom, basement 477 SF 10+ years 7 Walls - Plaster/Drywall Boys restroom, basement 5 SF 5 10+ years Water damage Walls - Tile Ceramic/ Porcelain Boys restroom, basement 965 SF 7 10+ years Remodeled, new finishes Water Closet Boys restroom, basement 6 ΕA 7 Reconfigured 10+ years SF 7 Accessories Girls restroom, basement 738 6-10 years SF Ceiling - Plaster/Drywall 7 Girls restroom, basement 738 10+ years Floor - Concrete Epoxy/ Painted Girls restroom, basement 738 SF 7 10+ years Floor Drain Girls restroom, basement 2 ΕA 7 10+ years Hand Dryer Girls restroom, basement 3 ΕA 7 10+ years Girls restroom, basement 5 7 Lavatory ΕA 10+ years Replaced Lighting - Pendent/Surface 10+ vears Reconfigured Girls restroom. basement 8 ΕA 7 Partitions Girls restroom, basement 11 ΕA 7 10+ years Reconfigured Walls - Plaster/Drywall Girls restroom, basement 506 SF 7 10+ years Remodeled, new finishes Walls - Tile Ceramic/ Porcelain Girls restroom, basement SF 7 1,012 10+ years Remodeled, new finishes Water Closet ΕA 7 All replaced Girls restroom, basement 11 10+ years

Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #101 (Music Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,191	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,191	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	74	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,525	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	5	2-5 years	
	Work Sink	1st Floor	1	EA	5	2-5 years	
Classroc	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,191	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,191	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	44	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	5	10+ years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drywall 1st Floor 1.612 SF 6 10+ years Work Sink 1st Floor ΕA 7 1 10+ years Classroom #103 (Regular Classroom) AC Units 1st Floor ΕA 7 1 6-10 years Casework 1st Floor 8 LF 7 10+ years Ceiling - Lav-in 1st Floor 929 SF 7 6-10 years Doors - Transom Window SF 1st Floor 80 6 10+ years ΕA 7 Doors - Wood Doors inclu hw 1st Floor 2 10+ years SF Floor - Wood 1st Floor 929 6 6-10 years 12 ΕA 7 6-10 years Lighting - Lay-in 1st Floor Lighting - Lay-in 1st Floor 3 EΑ 7 6-10 years Marker Board 1st Floor 8 LF 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 1.193 7 10+ years Classroom #104 (Regular Classroom) AC Units 1st Floor ΕA 7 1 10+ years Casework 8 LF 7 10+ years 1st Floor 1,203 SF 7 Ceiling - Lay-in 1st Floor 10+ years Ceiling - Lay-in 1st Floor 16 SF 5 0-1 year Cracked tiles LF Chalk Board 1st Floor 12 4 2-5 years Doors - Transom Window SF 1st Floor 7 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 7 10+ years Floor - Wood 1.219 SF 5 6-10 years 1st Floor Lighting - Pendent/Surface 1st Floor 15 EΑ 7 6-10 years Marker Board 1st Floor 44 LF 7 6-10 years SF Storage/ Closet 1st Floor 75 7 10+ years Walls - Plaster/Drywall SF 1st Floor 1.540 6 10+ years Classroom #106 (Regular Classroom) AC Units 1st Floor 7 1 EA 6-10 years 8 LF 7 Casework 1st Floor 10+ years Ceiling - Lay-in 1st Floor 1.217 SF 7 10+ years SF Doors - Transom Window 1st Floor 7 6 10+ years 7 Doors - Wood Doors inclu hw 1st Floor EΑ 10+ years 1 Floor - Wood 1st Floor 1.217 SF 6 10+ vears Lighting - Pendent/Surface ΕA 7 6-10 years 1st Floor 15 Marker Board 1st Floor 44 LF 7 6-10 years Storage/ Closet 1st Floor 75 SF 7 10+ years Locked Walls - Plaster/Drywall 1,649 SF 6 10+ years 1st Floor Classroom #107 (Regular Classroom) AC Units 1st Floor 7 1 ΕA 6-10 years



Floor - Wood

Marker Board

Storage/ Closet

Classroom #202 (Regular Classroom) AC Units

Lighting - Pendent/Surface

Walls - Plaster/Drywall

Catego	ry : Classroom		B	uilding	: Main		
J	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	879	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	5	0-1 year	Damaged tiles
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	C
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	893	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	44	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,396	SF	6	10+ years	
Classroo	m #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,191	SF	7	10+ years	
	Doors - Transom Window	1st Floor	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,191	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	44	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	5	10+ years	Missing ceiling tiles
	Walls - Plaster/Drywall	1st Floor	1,540	SF	7	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	896	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	

SF

ΕA

LF

SF

SF

ΕA

896

14

44

1

210

1,396

6

6

6

7

7

7

10+ years

10+ years

6-10 years

10+ years

10+ years

6-10 years

Ceiling - Lay-in	2nd Floor	905	SF	6	10+ years
Doors - Transom Window	2nd Floor	8	SF	6	10+ years
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years
Floor - Wood	2nd Floor	905	SF	6	10+ years
Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years
Marker Board	2nd Floor	44	LF	6	6-10 years
Storage/ Closet	2nd Floor	210	SF	7	10+ years
Walls - Plaster/Drywall	2nd Floor	1,407	SF	6	10+ years
mpus Name: Epic HS		Page : 16 of 25			

2nd Floor

2nd Floor

2nd Floor

2nd Floor

2nd Floor

2nd Floor

Not previously assessed



Category : Classroom

Classroom #203 (Science Lab Level 1) AC Units Casework Ceiling - Lay-in

> Eye Wash Station Floor - Tile Floor - Tile Gas Line Lighting - Lay-in Marker Board

Doors - Transom Window Doors - Wood Doors inclu hw

Science Lab Fume Hood

Science Lab Shower

Work Sink

Walls - Plaster/Drywall

Group Item - Type

	B	uilding	: Main		
Location	Quantity	UOM	Rank	Recommend Replacement	Comments
2nd Floor	2	EA	7	6-10 years	
2nd Floor	70	LF	7	10+ years	
2nd Floor	1,388	SF	7	10+ years	
2nd Floor	16	SF	7	10+ years	
2nd Floor	2	EA	7	10+ years	
2nd Floor	1	EA	7	10+ years	
2nd Floor	1,382	SF	7	10+ years	
2nd Floor	6	SF	5	1-2 years	Cracking
2nd Floor	1	EA	7	10+ years	č
2nd Floor	20	EA	7	6-10 years	
2nd Floor	24	LF	7	6-10 years	
2nd Floor	1	EA	7	10+ years	

7

7

7

10+ years

10+ years

10+ years

ΕA

SF

ΕA

1

8

1,414

Classroom #204 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Ceiling - Lay-in	2nd Floor	905	SF	6	10+ years	
Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	905	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	44	LF	6	6-10 years	
Walls - Plaster/Drywall	2nd Floor	1,407	SF	6	10+ years	
<u>Classroom #205 (Regular Classroom)</u>						
AC Units	2nd Floor	2	EA	7	6-10 years	
Casework	2nd Floor	5	LF	6	10+ years	
Ceiling - Lay-in	2nd Floor	936	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	936	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
Marker Board	2nd Floor	55	LF	6	6-10 years	
Storage/ Closet	2nd Floor	116	SF	7	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,458	SF	6	10+ years	

2nd Floor

2nd Floor

2nd Floor

Classroom #206 (Regular Classroom)						
AC Units	2nd Floor	2	EA	7	6-10 years	
Ceiling - Lay-in	2nd Floor	873	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	32	SF	5	1-2 years	Water damage



Catago	ry : Classroom		D	uilding	Main	01	55 S Houston AVENUE, Chicago, IL 60617
Catego	ry : Classroom		В	unaing	: main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Doors - Transom Window	2nd Floor	euantity 8	SF	6	10+ years	Comments
	Doors - Wood Doors inclu hw	2nd Floor	o 1	EA	6	10+ years	
	Floor - Wood Doors Inclu nw	2nd Floor	905	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	905 14	EA	6	6-10 years	
	Marker Board	2nd Floor	44		6	6-10 years	
	Storage/ Closet	2nd Floor	116	SF	4		Strong mold smell, water damage to
			-			1-2 years	ceiling tiles
	Walls - Plaster/Drywall	2nd Floor	1,405	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	10+ years	Small hole in plaster
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,458	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,458	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,572	SF	6	10+ years	
Classroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	905	SF	6	10+ years	
	Floor - Wood	2nd Floor	10	SF	5	10+ years	Finish damaged
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	5
	Marker Board	2nd Floor	44	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,407	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	44	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	210	SF	7	10+ years	Locked



)	Schools					82	55 S Houston AVENUE, Chicago, IL 60617
Catego	ry : Classroom		В	uilding	: Main	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #302 (Regular Classroom)						
Chubbrot	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	500	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Floor - Wood	3rd Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	44	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	210	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	1,435	SF	7	10+ years	EUCKEU
			1,+55	01	'	TOF years	
Classroo	om #303 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	800	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	800	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	5	10+ years	Water damage to ceiling tile, missing,
	-					-	light cover
	Walls - Plaster/Drywall	3rd Floor	1,542	SF	7	10+ years	
Classroo	om #304 (Regular Classroom)						
Chaobha	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	600	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	600	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,148	SF	7	10+ years	
	Wallo Flaster/Drywall		1,140	01	'	ior years	

Marker Board Walls - Plaster/Drywall

Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

Classroom #305 (Regular Classroom) AC Units

Ceiling - Lay-in

Floor - Wood

Classroom #306 (Other Instructional Use) AC Units

1

1

600

600

18

40

1

1,148

ΕA

SF

ΕA

SF

ΕA

LF

SF

ΕA

7

7

7

6

7

7

7

5

6-10 years

10+ years

10+ years

10+ years

6-10 years

6-10 years

10+ years

1-2 years

3rd Floor

Damaged air conditioner cover



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	788	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	5	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	800	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	72	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,542	SF	7	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	905	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	905	SF	5	10+ years	Seal damaged
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	5
	Marker Board	3rd Floor	44	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,407	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Floor - Wood	2nd Floor	900	SF	6	10+ years	
	Floor - Wood	2nd Floor	15	SF	5	10+ years	Seal damaged
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	3
	Marker Board	2nd Floor	44	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,435	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
C	Komo Turno	Leastien	Quantitu		Dault	Devices	Commente

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor						•	
	Ceiling - Lay-in	1st Floor	2,824	SF	7	10+ years	Recombined quantities
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	2,739	SF	7	10+ years	
	Floor - Wood	1st Floor	85	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years	Recombined quantities
	Student Lockers - Two Tiers	1st Floor	208	EA	7	10+ years	-
	Walls - Plaster/Drywall	1st Floor	4,758	SF	7	10+ years	



Category : Interior **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Ceiling - Lay-in 2nd Floor 2.420 SF 10+ vears 6 Drinking Fountains - Single Fountain 2nd Floor ΕA 7 2 10+ years Floor - Asphalt Floor 2nd Floor 2.323 SF 6 10+ years Floor - Wood SF 6 2nd Floor 97 10+ years Lighting - Pendent/Surface 2nd Floor 24 EΑ 6 10+ years Student Lockers - Two Tiers 2nd Floor 200 EΑ 6 10+ years Walls - Concrete Block 2nd Floor 967 SF 6 10+ years SF Walls - Plaster/Drywall 2nd Floor 3.529 6 10+ years Ceiling - Lav-in 3rd Floor 2,210 SF 6 10+ years Drinking Fountains - Single Fountain 3rd Floor 2 EΑ 7 10+ years Floor - Asphalt Floor 3rd Floor 505 SF 7 10+ vears Floor - Wood 3rd Floor 1.705 SF 6 10+ years Lighting - Chandelier, Incandescent ΕA 7 6-10 years 3rd Floor 4 ΕA Lighting - Lay-in 3rd Floor 2 6 6-10 years Lighting - Lay-in 8 3rd Floor ΕA 6 6-10 years Lighting - Pendent/Surface 8 FΑ 7 3rd Floor 6-10 years Student Lockers - Two Tiers 3rd Floor 200 ΕA 7 10+ years SF Walls - Plaster/Drvwall 3rd Floor 7.434 7 10+ years SF Walls - Plaster/Drvwall 3rd Floor 10 5 10+ vears Damaged plaster Ceiling - Plaster/Drywall SF **Basement** 3,375 6 10+ years Doors - Side-lite Basement 66 SF 6 10+ years Doors - Steel Doors incl hw 2 6 Basement EΑ 10+ years 42 SF 6 Doors - Transom Window **Basement** 10+ years Doors - Wood Doors include hw Basement 9 FΑ 6 10+ years 3 ΕA 7 Quantity updated to match current Drinking Fountains - Single Fountain Basement 10+ years observations 5 Drinking Fountains - Single Water Cooler Basement EΑ 1-2 years Out of order 1 Floor - Asphalt Floor 3,375 SF 5 6-10 years Basement Floor - Tile Quarry SF Basement 231 6 10+ years Lighting - Lay-in **Basement** 2 ΕA 6 10+ years Lighting - Pendent/Surface 32 FΑ 6 10+ vears Basement Lighting - Wall Mounted Basement 1 EΑ 6 6-10 years Stairs - Concrete Stairs LF 8 6 Basement 10+ years Student Lockers - One Tier 32 FΑ 6 10+ years Basement Walls - Concrete Block Basement 1,462 SF 6 10+ years SF 6 Walls - Concrete Block Basement 273 10+ years SF Walls - Masonry **Basement** 1,369 6 10+ years SF Walls - Plaster/Drywall 3,061 6 10+ years Basement Safetv **Camera Viewing Station** Entire Building 2 ΕA 7 6-10 years Metal Detector Entire Building 1 ΕA 7 6-10 years Security Cameras **Entire Building** 19 ΕA 7 6-10 years



EPIC Academy Charter High School 8255 S Houston AVENUE, Chicago, IL 60617

Catego	ry : Interior		В	uilding	: Main					
_	-		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Stairs										
	Ceiling - Plaster/Drywall	East (Stairwell # 1)	381	SF	6	10+ years				
	Floor - Asphalt	East (Stairwell # 1)	1,107	SF	6	10+ years				
	Handrails	East (Stairwell # 1)	160	LF	7	10+ years				
	Lighting - Wall Mounted	East (Stairwell # 1)	10	EA	6	6-10 years				
	Stairs - Asphalt	East (Stairwell # 1)	476	LF	6	10+ years				
	Walls - Plaster/Drywall	East (Stairwell # 1)	3,551	SF	6	10+ years				
	Ceiling - Plaster/Drywall	West (Stairwell # 2)	381	SF	6	10+ years				
	Floor - Asphalt	West (Stairwell # 2)	1,107	SF	6	10+ years				
	Handrails	West (Stairwell # 2)	160	LF	7	10+ years				
	Lighting - Wall Mounted	West (Stairwell # 2)	8	EA	7	6-10 years				
	Lighting - Wall Mounted	West (Stairwell # 2)	2	EA	5	6-10 years	Missing cover			
	Stairs - Asphalt	West (Stairwell # 2)	476	LF	6	10+ years	-			
	Walls - Plaster/Drywall	West (Stairwell # 2)	3,551	SF	6	10+ years				
ertical (Conveyance									
	Elevator - Hydraulic Elevator	West	1	EA	6	10+ years				



Category : Site Building : Site Recommend Item - Type Location Quantity UOM Replacement **Comments** Group Rank Civil/Drainage 2 FΑ 7 Civil/ Drainage - Catch Basin Entire Site 10+ years Repaired ΕA Civil/ Drainage - Catch Basin **Entire Site** 1 6 10+ years Civil/ Drainage - Site Drain Entire Site 2 ΕA 6 10+ years Civil/ Drainage - Site Manhole Entire Site 4 EΑ 6 10+ years Civil/ Drainage - Site Manhole Entire Site 1 EΑ 6 10+ years Fencina Fencing - Chain Link Entire Site LF 30 6 6-10 years Fencing - Old Standard Ornamental Entire Site 600 LF 6 10+ years LF Fencing - Old Standard Ornamental Entire Site 25 4 0-1 year Bent posts and fence Fencing - Wood Fencing w/ Steel Frame **Entire Site** 267 LF 6 6-10 years Landscape Landscape - Grass Entire Site 2,300 SF 6 10+ years Entire Site SF 7 Landscape - Hardscape- Asphalt 600 10+ years New Landscape - Hardscape- Concrete Entire Site 290 SF 6 10+ years Parkway trees Entire Site 29 ΕA 6 10+ years SF Planting Beds/ Area **Entire Site** 300 6 2-5 years **Trash Receptacles** 2 FΑ 6 6-10 years Entire Site Parking Lot Surface - Asphalt Entire Site 22,535 SF 4 0-1 year Alligatored surface, large cracks, potholes SF Surface - Concrete **Entire Site** 2.745 0-1 year Large cracks, shattered concrete 4 Trash Enclosure - Chain Links **Entire Site** 357 SF 6 10+ vears Recombined quantities Sidewalks LF Sidewalks - Internal Walks Entire Site 250 6 10+ years **Recombined** quantities Sidewalks - Perimeter Sidewalks Entire Site 10,825 SF 6 10+ years Signage Flag Pole - Flag Pole Entire Site ΕA 6 1 10+ years Entire Site Marquee - Free Standing Back Lighted 1 EΑ 6 6-10 years Monument - Sign Entire Site EA 6 6-10 years 1 Repaired

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Music Room	Regular Classroom	1st Floor	101	101	1,191	156	24	Y	N
Office	Gymnasium	3rd Floor	303	N/A	800	53	7	Y	N
Other Instructional Use	Gymnasium	3rd Floor	306	N/A	800	53	7	Y	N
Regular Classroom	Gymnasium	3rd Floor	304	N/A	600	53	7	Y	N
Regular Classroom	Gymnasium	3rd Floor	305	N/A	600	53	7	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	102	1,191	104	16	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	929	130	20	Y	N
Regular Classroom	Regular Classroom	1st Floor	104	104	1,219	164	28	Y	N
Regular Classroom	Regular Classroom	1st Floor	106	106	1,217	104	16	Y	N
Regular Classroom	Regular Classroom	1st Floor	107	107	893	104	16	Y	N
Regular Classroom	Regular Classroom	1st Floor	108	108	1,191	164	28	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	896	130	25	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	905	95	12	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	905	130	25	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	936	59	5	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	905	95	12	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	1,458	95	12	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	915	130	17	Y	N
Regular Classroom	Regular Classroom	2nd Floor	308	308	915	139	25	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	301	301	900	139	25	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	900	139	25	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	307	307	905	95	12	Y	N
Science Lab Level 1	Regular Classroom	2nd Floor	203	203	1,388	145	21	Y	N